

4/3/2023
10:03:51 AM

Palm Beach County Fleet Management Asset Maintenance History
10202392 2016 VERMEER SC802 Stump Cutter/Trailer Mounted

Total Hours: 121.50 Labor: 8,569.50 Parts: 12,084.45 Comm: 376.36 Charged: 21030.31

Work Order: 1606721 **Meter:** 1 **In Date:** 07/01/2016 **Closed:** 07/01/2016
Problem: 1061 - Pre Delivery Inspection

Work Completed

- Pre Delivery Inspection

Hours: 3.00 Comm: 0.00 Labor: 180.00 Parts: 0.00 Total: 180.00

Work Order: 1609914 **Meter:** 4 **In Date:** 09/16/2016 **Closed:** 09/22/2016
Problem: transported with truck

Work Completed

- Tow From: 6th ave and congress To: fleet wpb

Hours: 0.00 Comm: 96.00 Labor: 0.00 Parts: 0.00 Total: 96.00

Work Order: 1611635 **Meter:** 7 **In Date:** 11/14/2016 **Closed:** 11/21/2016
Problem: tail lights

Work Completed

- Ck lighting-replace both tail lights

- Shop Supplies

Hours: 1.00 Comm: 0.00 Labor: 60.00 Parts: 43.82 Total: 103.82

Parts Issued

Quantity

4 Led S T T Lamp 2.00

Shop Supplies 1.00

4/3/2023
10:03:51 AM

Palm Beach County Fleet Management Asset Maintenance History
10202392 2016 VERMEER SC802 Stump Cutter/Trailer Mounted

Work Order: 1708402 **Meter:** 26 **In Date:** 08/25/2017 **Closed:** 08/31/2017
Problem: pm service

Work Completed

- Pm
- Hyd service
- Wash Eqpt
- Trailer Service
- Shop Supplies

Parts Issued **Quantity**

Fuel Filter	1.00
Fuel Filter Main	1.00
Hyd Filter	1.00
Napagold Oil Filter	1.00
15-40 Oil	9.00
Napagold Air Filter	1.00
Napagold Air Filter	1.00
Aw68 Hydro Fluid Hydr	6.00
Shop Supplies	1.00

Hours: 9.00

Comm: 0.00

Labor: 540.00 Parts: 381.13 Total: 921.13

Work Order: 1710451 **Meter:** 28 **In Date:** 10/24/2017 **Closed:** 10/27/2017
Problem: straighten window frame & install glass

Work Completed

- Straighten window frame and reinstall windshield
- Shop Supplies

Parts Issued **Quantity**

Shop Supplies	1.00
---------------	------

Hours: 3.00

Comm: 0.00

Labor: 180.00 Parts: 2.00 Total: 182.00

Work Order: 1711547 **Meter:** 38 **In Date:** 11/27/2017 **Closed:** 11/30/2017
Problem: needs 2 spare yeys

Work Completed

- secure key for dept

Parts Issued **Quantity**

Ignition Key	1.00
--------------	------

Hours: 0.50

Comm: 0.00

Labor: 30.00 Parts: 19.31 Total: 49.31

4/3/2023
10:03:51 AM

Palm Beach County Fleet Management Asset Maintenance History
10202392 2016 VERMEER SC802 Stump Cutter/Trailer Mounted

Work Order: 1810260

Meter: 72

In Date: 10/03/2018 **Closed:** 10/22/2018

Problem: pm service

Work Completed

- pm service
- hydraulic service
- service trailer
- r/r brake backing plates and adjust
- replace 1 tire
- Shop Supplies

Parts Issued

Quantity

15-40 Oil	9.00
Napagold Oil Filter	1.00
Napagold Air Filter	1.00
Napagold Air Filter	1.00
Fuel Filter Main	1.00
Fuel Filter	1.00
Hyd Filter	1.00
Aw68 Hydro Fluid Hydr	10.00
Seal 2.250x3.371x.375	2.00
Backing Plate Assm	1.00
Backing Plate Assm	1.00
Lt10/16.5	1.00
Shop Supplies	1.00
Tire Disposal Fee	1.00

Hours: 11.00

Comm: 0.00

Labor: 737.00

Parts: 1,016.02

Total: 1,753.02

4/3/2023
10:03:51 AM

Palm Beach County Fleet Management Asset Maintenance History
10202392 2016 VERMEER SC802 Stump Cutter/Trailer Mounted

Work Order: 2000027

Meter: 92

In Date: 01/02/2020 **Closed:** 01/27/2020

Problem: pm service/ new blades

Work Completed

- pm service
- replace cutter teeth
- hydraulic service
- service trailer
- replace 2 tires
- Shop Supplies

Parts Issued

Quantity

Napagold Air Filter	1.00
Napagold Air Filter	1.00
Napagold Oil Filter	1.00
Napagold Fuel Filter	1.00
15-40 Oil	9.00
Cutter Teeth	42.00
Napa Hydraulic Filtr	1.00
Aw68 Hydro Fluid Hydr	4.00
Seal 2.250x3.371x.375	2.00
10-16.5/8 Car Trac Chief	1.00
Fuel Filter	1.00
Fuel Filter Main	1.00
9.50-16.5 Power King Super Hwy li 10ply	2.00
9.50-16.5 Power King Super Hwy li 10ply	2.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 11.50

Comm: 0.00

Labor: 839.50

Parts: 2,150.38

Total: 2,989.88

4/3/2023
10:03:51 AM

Palm Beach County Fleet Management Asset Maintenance History
10202392 2016 VERMEER SC802 Stump Cutter/Trailer Mounted

Work Order: 2004962 **Meter:** 100 **In Date:** 05/18/2020 **Closed:** 06/08/2020

Problem: pm service, cant read hours from guage, wheel stops while running from side to side, handles cracked

Work Completed

- pm service
- service trailer
- check charging system and replace failed battert
- restore hour meter gauge
- diagnose cutter wheel stopping while running. replace control handles
- replace trailer plug and amber marker light
- replace 2 missing cutter teeh nuts
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
15-40 Oil	9.00
Napagold Air Filter	1.00
Napagold Air Filter	1.00
Fuel Filter Main	1.00
Fuel Filter	1.00
Seal 2.250x3.371x.375	2.00
Non-chlor Brake Clnr	1.00
Grease Cap W/plug	2.00
Group 31 Post	1.00
Cutter Teeth	2.00
Lamp	1.00
Male Trailer Connector	1.00
Grease Cap W Plug 1.77	2.00
Operator Handle	3.00
Shop Supplies	1.00
Freight Charge	1.00

Hours: 21.00

Comm: 0.00

Labor: 1,533.00 Parts: 1,524.74 Total: 3,057.74

4/3/2023
10:03:51 AM

Palm Beach County Fleet Management Asset Maintenance History
10202392 2016 VERMEER SC802 Stump Cutter/Trailer Mounted

Work Order: 2010576 **Meter:** 108 **In Date:** 10/21/2020 **Closed:** 11/19/2020
Problem: pm/ idle/ hour meter/ teeth/ fender rubber missing/ see coments

Work Completed

Parts Issued

Quantity

- Pm Service	Napagold Oil Filter	1.00	
- Service trailer	15-40 Oil	9.00	
- Replace hour meter/combo gauge	Napagold Air Filter	1.00	
- Replace cutter teeth	Napagold Air Filter	1.00	
- Replace missing fender rubber curtain mat	Fuel Filter	1.00	
- Hydro service	Napagold Fuel Filter	1.00	
- Repair trailer jack	Non-chlor Brake Clnr	2.00	
- Replace brake assemblies and drums,adjust	Grease Cap W Plug 1.77	2.00	
- Replace tire and nitro fill	Seal 2.250x3.371x.375	2.00	
- Shop Supplies	Aw68 Hydro Fluid Hydr	4.00	
	Napa Hydraulic Filtr	1.00	
	Plug	1.00	
	Guage	1.00	
	Cutter Teeth	42.00	
	Curtain Fender	1.00	
	Backing Plate Assm	1.00	
	Backing Plate Assm	1.00	
	Hub Assembly W/bearing	2.00	
	9.50-16.5 Power King Super Hwy li 10ply	1.00	
	Rear Curtain	1.00	
	Shop Supplies	1.00	
	Tire Disposal Fee	1.00	
	Freight Charge	1.00	
Hours: 18.00	Labor: 1,314.00	Parts: 2,304.57	Total: 3,618.57
Comm: 0.00			

4/3/2023
10:03:51 AM

Palm Beach County Fleet Management Asset Maintenance History
10202392 2016 VERMEER SC802 Stump Cutter/Trailer Mounted

Work Order: 2100840 **Meter:** 117 **In Date:** 01/25/2021 **Closed:** 02/04/2021

Problem: key broke off in ignition, starter issues and fuel cap replacement. jack

Work Completed

- key broken off in switch, replaced ignition switch
- starter grinding while cranking, replaced starter
- replaced broken fuel cap with gauge
- trailer jack hard to crank, lube & free up jack
- Shop Supplies

Parts Issued

	Quantity
Key Switch W/key	1.00
16.5 Oz Aero Kroil	1.00
Fuel Cap With Gauge	1.00
Starter	1.00
Shop Supplies	1.00
Freight Charge	1.00

Hours: 3.50

Comm: 0.00

Labor: 255.50

Parts: 1,457.68

Total: 1,713.18

Work Order: 2106548 **Meter:** 128 **In Date:** 06/16/2021 **Closed:** 06/21/2021

Problem: Need a couple bottles of antifreeze please.

Work Completed

- Secure 2 Gallons Of Antifreeze For Dept.
- Shop Supplies

Parts Issued

	Quantity
1gal Rtu Antifreeze	2.00
Shop Supplies	1.00

Hours: 0.50

Comm: 0.00

Labor: 36.50

Parts: 25.39

Total: 61.89

Work Order: 2106840 **Meter:** 131 **In Date:** 06/23/2021 **Closed:** 07/16/2021

Problem: Knocking noise from transmission and when you start grinding, the throttle decreases, wheel stops spinning.

Work Completed

- Check Noise From Transmission, Greased Pinion Bearing, Greased Shaft Splines, Service Upper And Lower Gear Cases
- Check Throttle Decreases, Take Fuel Sample, Drain Contaminated Fuel, Replace Fuel Filters, Repair Fuel Line Leak At Low Pressure Fuel Pump, Remove Fuel Tank For Inspection
- Test Run Equipment
- Degrease Equipment To Inspect For Fuel Or Hydraulic Oil Leak
- Fuel Asset After Draining And Cleaning Fuel System
- Shop Supplies

Parts Issued

	Quantity
1qt Syngear Oil 75-90	4.00
Hose Clamp	1.00
Napa Fuel Filter	1.00
Napagold Fuel Filter	1.00
Shop Supplies	1.00

Hours: 11.00

Comm: 0.00

Labor: 803.00

Parts: 96.43

Total: 899.43

4/3/2023
10:03:51 AM

Palm Beach County Fleet Management Asset Maintenance History
10202392 2016 VERMEER SC802 Stump Cutter/Trailer Mounted

Work Order: 2111222 **Meter:** 139 **In Date:** 10/19/2021 **Closed:** 12/20/2021

Problem: flat tire. Also still losing power under load. Staff think it may be sensor for the handles?

Work Completed

Parts Issued

Quantity

- Pm Service	15-40 Oil	9.00	
- Service Trailer	Napagold Air Filter	1.00	
- Replaced 1 Tire, Swapped Other Tire Over To New Rim	Napagold Air Filter	1.00	
- Replaced Corroded Trailer Plug	Fuel Filter	1.00	
- Replaced 2 Damaged Wheels	Seal 2.250x3.371x.375	2.00	
- Check Engine Looses Power, Engine Fault Code Spn= 523009 Fmi= 9	Non-chlor Brake Clnr	1.00	
Need To Contact Vermeer For Reset Instructions	Male Trailer Connector	1.00	
- Replaced Faulty Trailer Break Away Switch	Napagold Oil Filter	1.00	
- to Vermeer for pressure sensor replacement	9.50-16.5 Power King Super Hwy li 10ply	1.00	
- Shop Supplies	Rim	2.00	
	Stud 1/2-20 X 1.84 Gr8	1.00	
	Tr416 Valve Stem	2.00	
	Napagold Fuel Filter	1.00	
	1cart Palladium 2 Grs	1.00	
	Breakaway Switch	1.00	
	Pressure Sensor Replacement	1.00	
	Shop Supplies	1.00	
	Tire Disposal Fee	1.00	
	Freight Charge	1.00	
Hours: 13.50	Labor: 985.50	Parts: 2,309.70	Total: 3,295.20
Comm: 0.00			

Work Order: 2111437 **Meter:** 135 **In Date:** 10/18/2021 **Closed:** 10/25/2021

Problem: Flat tire, boulevard didnt have a tire had to tow

Work Completed

- Tow From: Clintmoore/jog Valero station To: vista

Hours: 0.00 Comm: 90.40 Labor: 0.00 Parts: 0.00 Total: 90.40

4/3/2023
10:03:51 AM

Palm Beach County Fleet Management Asset Maintenance History
10202392 2016 VERMEER SC802 Stump Cutter/Trailer Mounted

Work Order: 2112389 **Meter:** 135 **In Date:** 11/19/2021 **Closed:**
Problem: transport to vermeer for repair

Work Completed

- Drive To Dealer

Hours: 0.00 Comm: 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00

Work Order: 2112564 **Meter:** 135 **In Date:** 11/19/2021 **Closed:** 11/29/2021
Problem: transport to vermeer for repair

Work Completed

- Tow From: 2601 vista To: vermeer se 1060 W Industrial Ave #3016,
Boynton Be

Hours: 0.00 Comm: 90.40 Labor: 0.00 Parts: 0.00 Total: 90.40

Work Order: 2201145 **Meter:** 143 **In Date:** 02/01/2022 **Closed:** 02/16/2022
Problem: Can you please get us 3 keys made for this stump cutter? Courtney will pick up

Work Completed

	Parts Issued	Quantity
- secure extra keys for dept	key 10	3.00
- Shop Supplies	Key	3.00
	Shop Supplies	1.00
Hours: 0.50	Labor: 36.50	Parts: 33.67
	Comm: 0.00	Total: 70.17

4/3/2023
10:03:51 AM

Palm Beach County Fleet Management Asset Maintenance History
10202392 2016 VERMEER SC802 Stump Cutter/Trailer Mounted

Work Order: 2300301 **Meter:** 166 **In Date:** 01/11/2023 **Closed:** 02/27/2023

Problem: PM Service. Please check muffler and install new blade teeth. Thank you!

Work Completed

- Preventive Maint. Service
- Service Trailer
- Rotate Cutter Teeth
- Replaced Corroded Trailer Plug, Replaced 2 Red Led Tail Lights
- Shop Supplies

Parts Issued

Quantity

15-40 Oil	9.00
Napagold Oil Filter	1.00
Napagold Fuel Filter	1.00
Napagold Air Filter	1.00
Napagold Air Filter	1.00
Seal 2.250x3.371x.375	2.00
Non-chlor Brake Clnr	1.00
Male Trailer Connector	1.00
Led Sup Mdl 44 42 Dio	2.00
Fuel Filter	1.00
Shop Supplies	1.00

Hours: 11.00

Comm: 0.00

Labor: 803.00

Parts: 320.81

Total: 1,123.81

Work Order: 2301906 **Meter:** 161 **In Date:** 02/27/2023 **Closed:** 02/28/2023

Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
---------------	------

Hours: 2.00

Comm: 0.00

Labor: 146.00

Parts: 2.65

Total: 148.65

Total Hours: 121.50

Total Labor: 8,569.50

Total Comm: 376.36

Total Parts: 12,084.45