Palm Beach County Fleet Management Asset Maintenance History 10155238 2004 YALE GLP060TG Forklift 6000 Lb, Lp Gas, W/Jib

Total Hours: 232.25 Labor: 14,415.75 Parts: 9,203.51 Comm: 202.30 Charged: 23821.56

Work Order: 436116 Meter: 0 In Date: 02/26/2004 Closed: 02/26/2004

Problem: PRE-DELIVERY INSPECTION

Work Completed

- Pre-delivery Inspection

Hours: 3.00 Comm: 0.00 Labor: 150.00 Parts: 0.00 Total: 150.00

Work Order: 436768 Meter: 0 In Date: 03/03/2004 Closed: 03/03/2004

Problem: 1 800 AUTO TOW FLORIDA INC 40226024

Work Completed

- 1 800 Auto Tow Florida Inc 40226024 Tow From New Fork Lift From Belv. -

Tow To Sr Shop

Hours: 0.00 Comm: 78.00 Labor: 0.00 Parts: 0.00 Total: 78.00

Work Order: 543774 Meter: 30 In Date: 05/03/2005 Closed: 05/09/2005

Problem: P.M SERVICE

 Work Completed
 Parts Issued
 Quantity

 - Pm
 10w30 Motor Oil
 5.00

 1066 White Lithium (crc 05037)
 1.00

 1347 Oil Filter
 1.00

 Hours: 4.00
 Comm: 0.00
 Labor: 200.00
 Parts: 17.20
 Total: 217.20

Work Order: 555378 Meter: 74 In Date: 09/20/2005 Closed: 09/20/2005

Problem: INSTALL PLEXY GLASS ON ROOF

 Work Completed
 Parts Issued
 Quantity

 - Install Plexy Glass On Roof
 765-1589 Black Silicone
 1.00

 Hours: 0.50
 Comm: 0.00
 Labor: 25.00
 Parts: 5.76
 Total: 30.76

Palm Beach County Fleet Management Asset Maintenance History 10155238 2004 YALE GLP060TG Forklift 6000 Lb, Lp Gas, W/Jib

| Work Order: Problem: | 637565 P.M SERVICE | Meter: | 98 | | In Date: | 04/17/2006 | Closed: | 04/20/2006 |
|-------------------------|----------------------------------|-------------------|------------|--------------------------------------|--------------|--------------|---------|------------|
| Work Com | pleted | | | Parts Issued | | | Qı | uantity |
| - Pm Servi | ce | | | Shop Supplies | | | | 1.00 |
| - Shop Sup | oplies | | | 513334 Filters | | | | 1.00 |
| | | | | 10w30 Motor Oil | | | | 5.00 |
| | | | | L0135-063 Lubriplat Lube,03050crc | te Chain&cal | ole | | 2.00 |
| | Hours: 4.00 | | Comm: 0.00 | Labor: 200.00 | Parts: 44. | 05 | Total: | 244.05 |
| Work Order: Problem: | 736524 P.M.SERVICE | Meter: | 98 | | In Date: | 04/03/2007 | Closed: | 04/05/2007 |
| Work Com | pleted | | | Parts Issued | | | Qı | uantity |
| - Pm Servi | ce | | | 93-9162 Air Filter Us | se Frm Ca92 | 46 Wix 46489 | | 1.00 |
| | | | | Oil Filter 51334 | | | | 1.00 |
| | | | | 10w30 Motor Oil | | | | 5.00 |
| | Hours: 3.00 | | Comm: 0.00 | Labor: 165.00 | Parts: 42. | 32 | Total: | 207.32 |
| Work Order: Problem: | 835937 P.M.SERVICE | Meter: | 213 | | In Date: | 03/24/2008 | Closed: | 03/31/2008 |
| Work Com | pleted | | | Parts Issued | | | Qı | uantity |
| - Pm Servi | ce | | | 93-9162 Air Filter Us | se Frm Ca92 | 46 Wix 46489 | | 1.00 |
| - R&r Tran | smission Filter | | | Ph3593a Oil Filter Lb | of Ph2808 W | ix 51334 | | 1.00 |
| - Remove | & Clean Fittings; Reinstall | | | Filter | | | | 1.00 |
| | - | | | 10w30 Motor Oil | | | | 5.00 |
| | | | | L0135-063 Lubriplat Lube,03050crc | te Chain&cal | ole | | 1.00 |
| | Hours: 6.00 | | Comm: 0.00 | Labor: 360.00 | Parts: 59. | 44 | Total: | 419.44 |
| Work Order: Problem: | 836938 NO START | Meter: | 218 | | In Date: | 04/14/2008 | Closed: | 04/14/2008 |
| Work Com | pleted | | | Parts Issued | | | Qı | uantity |
| - Ck Charg | ing System; Clean Battery Tray & | પ્ર Replace Batte | ery | 24-60 Battery Group | 24 | | | 1.00 |
| J | Hours: 1.00 | • | Comm: 0.00 | Labor: 60.00 | Parts: 74. | 00 | Total: | 134.00 |

Palm Beach County Fleet Management Asset Maintenance History 10155238 2004 YALE GLP060TG Forklift 6000 Lb, Lp Gas, W/Jib

Work Order: 942585 Meter: 269 In Date: 08/26/2009 Closed: 08/31/2009

Problem: P.M.SERVICE

| Work Completed | | Parts Issued | | Quantity |
|---------------------|------------|------------------------------------|----------------------|---------------|
| - Pm Service | | Ca9246 Air Filter L | 1.00 | |
| - Tighten Belt | | Ph3593a Oil Filter | Lbf Ph2808 Wix 51334 | 1.00 |
| - Tighten Rear Assy | | L0135-063 Lubripl Lube,03050crc | ate Chain&cable | 1.00 |
| | | 6y648 Graphite Lu | be (imperial 6590) | 1.00 |
| | | 10w30 Motor Oil | | 5.00 |
| Hours: 5.50 | Comm: 0.00 | Labor: 330.00 | Parts: 56.52 | Total: 386.52 |

Work Order: 1008265 Meter: 294 In Date: 08/03/2010 Closed: 08/09/2010

Problem: P. M. SERVICE

| Work Completed | | Parts Issued | | Quantity |
|---|------------|---------------------|----------------------|---------------|
| - P. M. | | Ph3593a Oil Filter | Lbf Ph2808 Wix 51334 | 1.00 |
| - readjusted belt. | | Ca9246 Air Filter L | bf Laf8143 Wix 46489 | 1.00 |
| - Repaired connection for work lamp. | | 10w30 Motor Oil | | 5.00 |
| - Installed new o-ring on boss fitting for tilt cyl. | | 1066 White Lithiu | m (crc 05037) | 1.00 |
| - Installed new pin & straightened clevin for seat panel. | | 6y648 Graphite Lu | be (imperial 6590) | 2.00 |
| Hours: 7.50 | Comm: 0.00 | Labor: 450.00 | Parts: 54.82 | Total: 504.82 |

Work Order: 1103575 Meter: 311 In Date: 04/01/2011 Closed: 04/11/2011

Problem: P.M.SERVICE

| Work Completed | | Parts Issued | | Qι | ıantity |
|---|---------------|---------------------|----------------------|--------|---------|
| - Performed P.m. | | Ph3593a Oil Filter | Lbf Ph2808 Wix 51334 | | 1.00 |
| - R&r bulb for brake light. | | Ca9246 Air Filter L | bf Laf8143 Wix 46489 | | 1.00 |
| - Readjust belt. | | 10w30 Motor Oil | | | 5.00 |
| - Removed fittings & cleaned out & reinstalled fittings | to lube pins. | 6y648 Graphite Lu | be (imperial 6590) | | 1.00 |
| Hours: 6.00 | Comm: 0.00 | Labor: 360.00 | Parts: 38.50 | Total: | 398.50 |

Palm Beach County Fleet Management Asset Maintenance History 2004 YALE GLP060TG Forklift 6000 Lb, Lp Gas, W/Jib 10155238

| Work Order: | 1203320 | Meter: | 340 | | In Date: | 04/09/2012 | Closed: | 04/13/2012 |
|-------------------------|---------------------------------------|-------------------|--------------------|---------------------|----------------|------------|---------|------------|
| Problem: | p.m.service | | | | | | | |
| Work Com | pleted | | | Parts Issued | | | Qı | uantity |
| - pm | | | | Ph3593a Oil Filter | Lbf Ph2808 W | ix 51334 | | 1.00 |
| - repair wi | ring for brake lights | | | Ca9246 Air Filter L | .bf Laf8143 Wi | x 46489 | | 1.00 |
| - adj belt | | | | 10w30 Motor Oil | | | | 5.00 |
| - remove o | grease fittings for pins clean c s | out and back out | slightly and gease | | | | | |
| | Hours: 8.00 | | Comm: 0.00 | Labor: 480.00 | Parts: 24. | 93 | Total: | 504.93 |
| Work Order: Problem: | 1206865 battery bad | Meter: | 347 | | In Date: | 07/24/2012 | Closed: | 07/26/2012 |
| Work Com | pleted | | | Parts Issued | | | Qı | uantity |
| - ck bad b | attery verify battery tested ba | d replace battery | ck charging sys | Group 24 Battery | (acd 24ps) | | | 1.00 |
| | Hours: 0.75 | | Comm: 0.00 | Labor: 45.00 | Parts: 92. | 48 | Total: | 137.48 |
| Work Order: Problem: | 1303105 P.M.SERVICE | Meter: | 361 | | In Date: | 03/29/2013 | Closed: | 04/09/2013 |
| Work Com | pleted | | | Parts Issued | | | Qı | uantity |
| | | | | 0.11 = 11. | | | | 4.00 |

| Work Completed | Parts Issued | Quantity |
|---|---------------------|----------|
| - pm | Oil Filter | 1.00 |
| - repaired connection at tail light | Napagold Air Filter | 1.00 |
| - adj fan belt | 10w30 Bulk Sr | 5.00 |
| - removed fittings at tilt cylinder to clean pulleys to accept grease | | |

- cleaned off rust and debris and lubed track assy for shift operation to work

Hours: 8.00 Comm: 0.00 Parts: 41.13 Total: 521.13 Labor: 480.00

Hours: 7.00

Palm Beach County Fleet Management Asset Maintenance History 10155238 2004 YALE GLP060TG Forklift 6000 Lb, Lp Gas, W/Jib

| ork Order: Problem: | | Meter: | 383 | | In Date: | 03/13/2014 | Closed: | 04/25/2014 |
|---|--|--|----------------------|---|------------|------------------|---------|--|
| Work Com | pleted | | | Parts Issued | | | Qı | ıantity |
| - pm | | | | Napagold Oil Filter | | | | 1.00 |
| - rr strobe | light | | | Napagold Air Filter | | | | 1.00 |
| - removed | lower ip cover and steering pa | anesl for column | rr brake switches | 10w30 Bulk Sr | | | | 5.00 |
| - tightened | d belt | | | Strobe Light | | | | 1.00 |
| - fittings w | ont take grease removed fititr | ngs and cleaned | galley and installed | E Brake Magnetic Swi | tch | | | 1.00 |
| new fittings | 5 | | | E Brake Lower Switch | | | | 1.00 |
| | | | | Freight Charge | | | | 1.00 |
| | Hours: 9.00 | | Comm: 0.00 | Labor: 540.00 | Parts: 307 | 7.47 | Total: | 847.47 |
| Problem: | ck back up light | | | | | | | |
| Work Com | ck back up light | | | Parts Issued | | | Qı | ıantity |
| Work Com - ck back u trace tire ha | , - | , , | • | Parts Issued Relay | | | Qı | 3.00 |
| Work Com - ck back u trace tire ha | pleted up light stays on and dead batt arness and found damaged wi | re harnes and ba | nd relays replace | | | | Qı | • |
| Work Com - ck back u trace tire ha | pleted Ip light stays on and dead batt arness and found damaged wire repair wire harness | re harnes and ba | nd relays replace | | Parts: 34. | 74 | | • |
| Work Com - ck back u trace tire ha relays and r - recharge | ipleted ip light stays on and dead batter arness and found damaged witer repair wire harness battery and ck charging sys battery and ck charging sys battery | re harnes and ba | s time Comm: 0.00 | Relay | Parts: 34. | 74 06/03/2015 | Total: | 3.00 |
| Work Com - ck back u trace tire ha relays and r - recharge | ipleted ip light stays on and dead batterness and found damaged with repair wire harness battery and ck charging sys battery and ck charging s | re harnes and ba | s time Comm: 0.00 | Relay | | | Total: | 3.00 |
| Work Com - ck back u trace tire ha relays and r - recharge /ork Order: Problem: | ipleted ip light stays on and dead batterness and found damaged with repair wire harness battery and ck charging sys battery and ck charging s | re harnes and ba | s time Comm: 0.00 | Relay Labor: 300.00 | | | Total: | 3.00 334.74 06/09/2015 |
| Work Com - ck back us trace tire had relays and r - recharge Vork Order: Problem: Work Com - pm | ipleted ip light stays on and dead batterness and found damaged with repair wire harness battery and ck charging sys battery and ck charging s | re harnes and ba | s time Comm: 0.00 | Relay Labor: 300.00 Parts Issued | | | Total: | 3.00 334.74 06/09/2019 |
| Work Com - ck back us trace tire has relays and r - recharge Vork Order: Problem: Work Com - pm | apleted up light stays on and dead batter arness and found damaged wire repair wire harness battery and ck charging sys battery and ck charging sys batters: 5.00 1505577 P.M.SERVICE | re harnes and ba | s time Comm: 0.00 | Relay Labor: 300.00 Parts Issued Napagold Air Filter | | | Total: | 3.00 334.74 06/09/2015 antity 1.00 |
| Work Com - ck back user trace tire had relays and reserved and reserved with the company of the | apleted up light stays on and dead batter arness and found damaged wire repair wire harness battery and ck charging sys battery and ck charging sys batters: 5.00 1505577 P.M.SERVICE | re harnes and ba attery is ok at thi Meter: | s time Comm: 0.00 | Relay Labor: 300.00 Parts Issued Napagold Air Filter Napagold Oil Filter | In Date: | | Total: | 3.00 334.74 06/09/2019 1.00 1.00 |
| Work Com - ck back user trace tire had relays and reserved recharge /ork Order: Problem: Work Com - pm - repaired reserved. | apleted up light stays on and dead batter arness and found damaged wire repair wire harness battery and ck charging sys battery Hours: 5.00 1505577 P.M.SERVICE upleted wiring to rear light | re harnes and ba attery is ok at thi Meter: | s time Comm: 0.00 | Relay Labor: 300.00 Parts Issued Napagold Air Filter Napagold Oil Filter 10w30 Bulk Sr | In Date: | | Total: | 3.00 334.74 06/09/2015 1.00 1.00 5.00 |

Comm: 0.00

Labor: 420.00

Parts: 57.00

Total: 477.00

Palm Beach County Fleet Management Asset Maintenance History 10155238 2004 YALE GLP060TG Forklift 6000 Lb, Lp Gas, W/Jib

Work Order: 1506821 Meter: 422 In Date: 07/08/2015 Closed: 08/18/2015

Problem: LEAKING HYD. FLUID

| Work Completed | | Parts Issued | | Quantity |
|---|---------------------|---------------------------------------|-----------------|-----------------|
| - remove frt section of fork lift rr 3 cyl reassemble | Repair Hyd Cylinder | | 2.00 | |
| - rr hyd filter | | Repair Hyd Cylinder | | 1.00 |
| • | | Napa Trans Filter Hydraulic Cylinder | | 1.00 |
| | | | | 2.00 |
| | | Hydraulic Cylinder | | 1.00 |
| Hours: 44.50 | Comm: 0.00 | Labor: 2,670.00 | Parts: 2,086.83 | Total: 4,756.83 |

Work Order: 1606300 Meter: 452 In Date: 06/20/2016 Closed: 06/29/2016

Problem: Pm service

| Work Completed | Parts Issued | Quantity |
|---|------------------------------|----------|
| - Pm service. | Napagold Oil Filter | 1.00 |
| - Repaired wiring to light. | 10w30 Bulk Sr | 5.00 |
| - Adjust belt. | Fork Lift Tire & Damp; Labor | 1.00 |
| - Removed fittings and cleaned gallery.reinstalled fittings and lubed | Tire Disposal Fee | 1.00 |
| - Installed rear tires. | | |

Work Order: 1610804 Meter: 457 In Date: 10/19/2016 Closed: 11/14/2016

Labor: 510.00

Parts: 323.75

Total: 833.75

Comm: 0.00

Problem: WONT START INTERMITTENTLY, CYLINDER LEAKING.

Hours: 8.50

| Work Completed | | Parts Issued | | Quantity |
|---|--------------|-------------------|---------------|-----------------|
| - C/c starting intermittently.replace all micro switc | hes | Mirco Switch V7-1 | lb17b8-022 | 4.00 |
| - Cylinders leaking.verify lean foward and backwa | rd cylinders | Hyd Cylinders | | 1.00 |
| leaking.remove cylinders.have rebuilt.reinstall. | | | | |
| Hours: 11.50 | Comm: 0.00 | Labor: 690.00 | Parts: 461.06 | Total: 1,151.06 |

Work Order: 1702335 Meter: 461 In Date: 03/08/2017 Closed: 03/13/2017

Problem: WONT START

Work Completed

- Verify wont start.remove all panels to acess ingition system.found chafed wire to starter solenoid.repair and reasemble.

Hours: 2.00 Comm: 0.00 Labor: 120.00 Parts: 0.00 Total: 120.00

Palm Beach County Fleet Management Asset Maintenance History 10155238 2004 YALE GLP060TG Forklift 6000 Lb, Lp Gas, W/Jib

Work Order: 1706215 Meter: 469 In Date: 06/23/2017 Closed: 06/30/2017

Problem: P.M.SERVICE

| Work Completed | | Parts Issued | | Quantity |
|-----------------------------------|------------|--------------------|--------------|---------------|
| - Pm Service | | Napagold Oil Filte | r | 1.00 |
| - Service and inspect Hyd.system. | | 10w30 Bulk Sr | | 5.00 |
| - Wash equipment | | Wd40 Spr | | 1.00 |
| | | Macs Chain Cable | Lube | 1.00 |
| Hours: 6.25 | Comm: 0.00 | Labor: 375.00 | Parts: 33.56 | Total: 408.56 |

Work Order: 1803353 Meter: 469 In Date: 03/30/2018 Closed: 03/30/2018

Problem: Fork lift will not go into reverse gear.

Work Completed

- Diagnose for transmission not going into reverse gear.pinpoint test and repair harness for reverse solenoid.adjust steering column and micro switches.test drive.

Hours: 4.00 Comm: 0.00 Labor: 240.00 Parts: 0.00 Total: 240.00

Palm Beach County Fleet Management Asset Maintenance History 2004 YALE GLP060TG Forklift 6000 Lb, Lp Gas, W/Jib 10155238

| Parts Issued Quantity Aw68 Bulk Sr 20.00 |
|---|
| |
| V. I. D. I. |
| ewire Valve Bank 2.00 |
| Clevis Pin 3.00 |
| eplace Cotter Pin 3.00 |
| control boot 3.00 |
| control boot 1.00 |
| 10w30 Bulk Sr 5.00 |
| ehicle. Napagold Oil Filter 1.00 |
| Macs Chain Cable Lube 1.00 |
| Micro Switch 4.00 |
| Oring 8.00 |
| Oring 2.00 |
| Freight Charge 1.00 |
| Labor: 1,560.00 Parts: 3,937.38 Total: 5,497.38 |
| |

Problem: Has to jump start.Bad battery.

| Work Completed | | Parts Issued | | Quantity |
|---|---------------------------|---------------|---------------|---------------|
| - Recharged and tested battery Failed.replace ba | ttery and recharged and | Battery | | 1.00 |
| tested new battery.clean battery tray and hold do | wn hardware.service cable | S. | | |
| Hours: 2.00 | Comm: 0.00 | Labor: 134.00 | Parts: 110.42 | Total: 244.42 |

Palm Beach County Fleet Management Asset Maintenance History 10155238 2004 YALE GLP060TG Forklift 6000 Lb, Lp Gas, W/Jib

 Work Order:
 1902202
 Meter:
 513
 In Date:
 02/27/2019
 Closed:
 05/13/2019

Problem: dead battery

| Parts Issued | Quantity |
|---------------|----------|
| Battery | 1.00 |
| Reman Starter | 1.00 |
| | Battery |

- Fabricate and make up wiring for starter solenoid circuit from steering colum to starter motor.

Hours: 7.25 Comm: 0.00 Labor: 485.75 Parts: 278.57 Total: 764.32

Work Order: 1910163 Meter: 529 In Date: 10/01/2019 Closed: 10/07/2019

Problem: PM Service

| Work Completed | | Parts Issued | | Quantity |
|---|------------|-----------------------|--------------|---------------|
| - Pm Service.- Repair wire harness and replace blown fuse. | | Napagold Oil Filte | 1.00 | |
| | | 10w30 Bulk Sr | 5.00 | |
| - Service and inspect hyd. system. | | Macs Chain Cable Lube | | 1.00 |
| | | Napagold Air Filt | er | 1.00 |
| | | Atc-10 Fuse Pac | | 5.00 |
| | | Aw68 Bulk Sr | | 5.00 |
| Hours: 8.50 | Comm: 0.00 | Labor: 620.50 | Parts: 55.98 | Total: 676.48 |
| | | | | |

Work Order: 2003526 Meter: 541 In Date: 04/08/2020 Closed: 04/30/2020

Problem: LEAKING HYD. FLUID

| Work Completed | | Parts Issued | | Quantity |
|--|------------|--------------------|---------------|---------------|
| - C/c leaking Hyd fluid.remove steering cylinder.sen | d out for | Rebuilt Steering C | yl | 1.00 |
| rebuild.reinstall.top off fluid. | | Aw68 Bulk Sr | | 5.00 |
| - Wash off to determine where unit is leaking from. | | | | |
| Hours: 5.75 | Comm: 0.00 | Labor: 419.75 | Parts: 450.86 | Total: 870.61 |

Palm Beach County Fleet Management Asset Maintenance History 2004 YALE GLP060TG Forklift 6000 Lb, Lp Gas, W/Jib 10155238

| Work Order: 2007500 | Meter: | 548 | | In Date: | 07/30/2020 | Closed: | 07/31/2020 |
|---|--------------|------------|------------------------|------------|------------|---------|------------|
| Problem: Hydraulic oil leakOverheating | | | | | | | |
| Work Completed | | | Parts Issued | | | Qı | uantity |
| - Repaired oil leak. | | | Aw68 Bulk Sr | | | | 5.00 |
| - Wash equipnent to diagnose leak. | | | 1gal Rtu Antifreeze | | | | 2.00 |
| - Repaired leaking coolant hose.correct fluid I | evel and te | st run. | | | | | |
| Hours: 3.25 | | Comm: 0.00 | Labor: 237.25 | Parts: 31. | .35 | Total: | 268.60 |
| Work Order: 2007814 Problem: Seat metal exposed .Lights inop. | Meter: | 548 | | In Date: | 08/07/2020 | Closed: | 08/25/2020 |
| Work Completed | | | Parts Issued | | | Qı | uantity |
| - Replace seat. | | | Forklift Seat Universa | al | | | 1.00 |
| - Trace and repair wiring harness for lights. | | | | | | | |
| Hours: 3.50 | | Comm: 0.00 | Labor: 255.50 | Parts: 37 | 1.25 | Total: | 626.75 |
| Work Order: 2010357 Problem: p.m.service | Meter: | 553 | | In Date: | 10/15/2020 | Closed: | 10/30/2020 |
| Work Completed | | | Parts Issued | | | Qı | uantity |
| - pm service | | | 10w30 Bulk Sr | | | | 5.00 |
| - repair wiring to head lamps and replaced bl | ow fuse | | Napagold Oil Filter | | | | 1.00 |
| - replaced worn faded pbc decals on both sid | es of vehicl | e | Aw68 Bulk Sr | | | | 5.00 |
| - wash vehicle | | | Atc-10 Fuse Pac | | | | 1.00 |
| - diagnose transmission selector switches wo | nt go into g | ear | | | | | |
| Hours: 9.00 | | Comm: 0.00 | Labor: 657.00 | Parts: 28. | .82 | Total: | 685.82 |
| Work Order: 2111613 Problem: PM | Meter: | 578 | | In Date: | 10/27/2021 | Closed: | 10/29/2021 |
| Work Completed | | | Parts Issued | | | Qı | uantity |
| - Preventive Maint. Service | | | 10w30 Bulk Sr | | | | 5.00 |
| | | | Napagold Oil Filter | | | | 1.00 |
| | | | Macs Chain Cable Lu | ıbe | | | 1.00 |
| Hours: 4.00 | | | Labor: 292.00 | | .18 | Total: | |

Palm Beach County Fleet Management Asset Maintenance History 10155238 2004 YALE GLP060TG Forklift 6000 Lb, Lp Gas, W/Jib

Work Order: 2207067 Meter: 681 In Date: 07/06/2022 Closed: 07/08/2022

Problem: Will not go into reverse

Work Completed

- Verify connections on proximity switch are loose, tighten connectors and zip tie at a angle. test run multiple times, unit is working properly at this

time.

Hours: 1.00 Comm: 0.00 Labor: 73.00 Parts: 0.00 Total: 73.00

In Date: 01/13/2023 **Closed:** 01/27/2023

Work Order: 2300421 **Meter:** 695

Problem: PM

| Work Completed | Parts Issued | Quantity |
|--|--------------------------|---------------|
| - Preventive Maint. Service | Napagold Air Filter | 1.00 |
| - Service hydraulic system, replace filters and correct fluid level. | 10w30 Bulk Sr | 5.00 |
| | Napagold Oil Filter | 1.00 |
| | Macs Chain Cable Lube | 1.00 |
| | Napa Trans Filter | 1.00 |
| | Aw68 Bulk Sr | 5.00 |
| Hours: 5.00 Comm: 0.00 | Labor: 365.00 Parts: 66. | Total: 431.18 |

Work Order: 2301992 Meter: 695 In Date: 02/28/2023 Closed: 02/28/2023

Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 0.00 Total: 146.00

Work Order: 2302861 Meter: 695 In Date: 02/22/2023 Closed: 03/21/2023

Problem: Transport from 13026 S Jog road to 2601 vista parkway for surplus

Work Completed

- Tow From: 13026 S. Jog Road To: 2601 Vista Pkwy, West Palm Beach 33411

Hours: 0.00 Comm: 124.30 Labor: 0.00 Parts: 0.00 Total: 124.30

Total Hours: 232.25 Total Labor: 14,415.75 Total Comm: 202.30 Total Parts: 9,203.51