

4/3/2023
10:42:00 AM

Palm Beach County Fleet Management Asset Maintenance History
10198116 2015 CLUB CAR CARRYALL 1500 Utility Cart, All Terrain, 4X4, Diesel

Total Hours: 62.50 Labor: 4,254.50 Parts: 2,210.11 Comm: 0.00 Charged: 6464.61

Work Order: 1503534 **Meter:** 1 **In Date:** 04/06/2015 **Closed:** 04/15/2015
Problem: install hitch ext

Work Completed

- Parts Only
- Shop Supplies

Hours: 0.00 Comm: 0.00

Parts Issued

Quantity

Ball Mount 3/4"	2.00
Pin W/clip 5/8 For Hitch	2.00
Receiver Extension	1.00
Shop Supplies	1.00
Labor: 0.00 Parts: 113.24 Total: 113.24	

Work Order: 1503656 **Meter:** 1 **In Date:** 04/09/2015 **Closed:** 04/09/2015
Problem: 1061 - Pre Delivery Inspection

Work Completed

- Pre Delivery Inspection

Hours: 2.00 Comm: 0.00

Labor: 120.00 Parts: 0.00 Total: 120.00

Work Order: 1602715 **Meter:** 10 **In Date:** 03/15/2016 **Closed:** 03/28/2016
Problem: pm service

Work Completed

- Pm
- Replace windshield
- Undercoat frame
- Shop Supplies

Hours: 7.00 Comm: 0.00

Parts Issued

Quantity

Fuel Filter	1.00
Napagold Oil Filter	1.00
Mobil 424 Fluid	4.00
15-40 Oil	3.00
Brake Cleaner	2.00
Rubberized Undercoat	3.00
Windshield Kit	1.00
Shop Supplies	1.00
Labor: 420.00 Parts: 433.93 Total: 853.93	

4/3/2023
10:42:00 AM

10198116 Palm Beach County Fleet Management Asset Maintenance History
2015 CLUB CAR CARRYALL 1500 Utility Cart, All Terrain, 4X4, Diesel

Work Order: 1702645 **Meter:** 45 **In Date:** 03/15/2017 **Closed:** 03/24/2017
Problem: pm service

Work Completed

Parts Issued

Quantity

- Pm	Fuel Filter	2.00
- Shop Supplies	Napagold Oil Filter	2.00
	15-40 Oil	6.00
	Mobil 424 Fluid	8.00
	Napagold Air Filter	2.00
	Shop Supplies	1.00

Hours: 5.00 Comm: 0.00 Labor: 300.00 Parts: 178.76 Total: 478.76

Work Order: 1802908 **Meter:** 70 **In Date:** 03/19/2018 **Closed:** 03/28/2018
Problem: pm service

Work Completed

Parts Issued

Quantity

- pm service	Fuel Filter	1.00
- Shop Supplies	Napagold Oil Filter	1.00
	Napagold Air Filter	1.00
	Mobil 424 Fluid	4.00
	15-40 Oil	3.00
	Shop Supplies	1.00

Hours: 5.00 Comm: 0.00 Labor: 300.00 Parts: 76.82 Total: 376.82

Work Order: 1806870 **Meter:** 88 **In Date:** 07/05/2018 **Closed:** 07/06/2018
Problem: flat tire

Work Completed

Parts Issued

Quantity

- repair tire	Shop Supplies	1.00
---------------	---------------	------

Hours: 1.00 Comm: 0.00 Labor: 60.00 Parts: 2.00 Total: 62.00

4/3/2023
10:42:00 AM

10198116

Palm Beach County Fleet Management Asset Maintenance History
2015 CLUB CAR CARRYALL 1500 Utility Cart, All Terrain, 4X4, Diesel

Work Order: 1903210 **Meter:** 144 **In Date:** 03/25/2019 **Closed:** 03/29/2019
Problem: pm/ right tail light out

Work Completed

Parts Issued

Quantity

- Pm Service	Napa 20w50 Qt	3.00	
- Repl. right rear tail light bulb	Napagold Oil Filter	1.00	
- Wash equipment	Fuel Filter	1.00	
- Repl. rear asset number	Non-chlor Brake Clnr	1.00	
- Shop Supplies	Mobil 424 Fluid	4.00	
	Napagold Air Filter	1.00	
	Boxed Miniatures	1.00	
	Shop Supplies	1.00	
Hours: 7.00	Labor: 469.00	Parts: 84.65	Total: 553.65
Comm: 0.00			

Work Order: 1907901 **Meter:** 181 **In Date:** 07/31/2019 **Closed:** 08/05/2019
Problem: had to jump start

Work Completed

Parts Issued

Quantity

- check charging system and replace battery	Battery	1.00	
- Shop Supplies	Shop Supplies	1.00	
Hours: 1.00	Labor: 67.00	Parts: 96.87	Total: 163.87
Comm: 0.00			

Work Order: 2003225 **Meter:** 259 **In Date:** 03/31/2020 **Closed:**

Problem: pm/ check lights

Work Completed

-

Hours: 0.00 Comm: 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00

4/3/2023
10:42:00 AM

Palm Beach County Fleet Management Asset Maintenance History
2015 CLUB CAR CARRYALL 1500 Utility Cart, All Terrain, 4X4, Diesel

Work Order: 2003492 **Meter:** 270 **In Date:** 04/07/2020 **Closed:** 04/16/2020
Problem: install strob light

Work Completed

- pm service
- install strob lite
- Shop Supplies

Parts Issued

Quantity

Napagold Air Filter	1.00
Napagold Oil Filter	1.00
Fuel Filter	1.00
15-40 Oil	3.00
Mobil 424 Fluid	4.00
Led 12volt Strobe	1.00
Shop Supplies	1.00

Hours: 6.50

Comm: 0.00

Labor: 474.50 Parts: 198.45 Total: 672.95

Work Order: 2104196 **Meter:** 371 **In Date:** 04/14/2021 **Closed:** 04/30/2021
Problem: Do for PM service and right side rear light cover missing please check also lights

Work Completed

- Preventive Maint. Service
- Replace 2 front tires
- Replace alternator belt
- Replace outer cv axle boots
- Replace taillight bulb and missing hardware for covers
- Replace rear suspension bushings
- Replace parking brake caliper assembly and adjust
- Wash equipment
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Napa Qt 15w40	3.00
Napagold Air Filter	1.00
Non-chlor Brake Clnr	1.00
Mobil 424 Fluid	4.00
Fuel Filter	1.00
25 X 11.00 X 12 Tire Kenda	2.00
Cv Boot	2.00
Boxed Miniatures	1.00
Arm Bushing	4.00
Inner Sleeve	2.00
Caliper Mech Park Brake	1.00
V-belt	1.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 14.50

Comm: 0.00

Labor: 1,058.50 Parts: 880.70 Total: 1,939.20

4/3/2023
10:42:00 AM

Palm Beach County Fleet Management Asset Maintenance History
10198116 2015 CLUB CAR CARRYALL 1500 Utility Cart, All Terrain, 4X4, Diesel

Work Order: 2205447 **Meter:** 464 **In Date:** 05/24/2022 **Closed:** 05/27/2022

Problem: PM Service. Please check steering & ball joints ,Right rear tail light is out.. Thank you

Work Completed

- Preventive Maint. Service, Driveline Service
- Check Suspension, Replaced All Front/rear Suspension Bushings And Hardware
- Replaced Blown Tail Light Bulbs
- Shop Supplies

Parts Issued

Quantity

15-40 Oil	3.00
Napagold Oil Filter	1.00
Fuel Filter	1.00
Napagold Air Filter	1.00
Mobil 424 Fluid	4.00
bushing	8.00
Lower Arm Bushing	4.00
Arm Bushing	16.00
Boxed Miniatures	2.00
Shop Supplies	1.00

Hours: 11.50

Comm: 0.00

Labor: 839.50

Parts: 144.70

Total: 984.20

Work Order: 2302190

Meter: 609

In Date: 03/02/2023 **Closed:** 03/02/2023

Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00

Comm: 0.00

Labor: 146.00

Parts: 0.00

Total: 146.00

Total Hours: 62.50

Total Labor: 4,254.50

Total Comm: 0.00

Total Parts: 2,210.11