



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 12



WorkOrder: 56195715
Invoice Number: 55345-56195715

Client Department:

MRC:	55345M	Equipment:	4839
WO Desc:			GRAND CARAVAN SE
55345-MEDIUM DUTY PMA		VIN:	2C7WDGBG0ER476573
Requested By:	SPACE	Status:	32
Created By:	SPACE	Priority:	3
Class:	WO	Driver:	
Arrangement:	Unassigned	Phone:	
Potential Warranty:	No	ETA:	

Chronology

Reported	Jan 2, 2023	12:00 AM
Started	Jan 4, 2023	
Completed	Jan 5, 2023	12:35 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	265,454	DH

WorkOrder Notes

Line	Comment
10	Complaint: PM A service. Cause: Due by Mileage. Correction: LOF engine oil and filter. Performed tire and brakes inspection.

Activity: 5 **999/999/999 TOTAL VEHICLE**

Activity Note: Personal Risk Assessment
Reason for Repair: SW - Shop Work Order
Work Accomplished: 06 - Inspect
Part Failure: 00 - No Failure

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
04-Jan-23	P9600	FILTER, OIL	1.00	3.61	3.61

Labor Posted

Date	Technician	Hours	Rate	Extended
04-Jan-23	Earl Johnson	0.22	0.00	0.00

Activity 5 Sub Total

Parts:	3.61
Labor:	0.00
Labor Hours: 0.22	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	3.61

Activity: 10 **999/999/999 TOTAL VEHICLE**

Activity Note: Medium Duty PM Inspection
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 2 of 12



WorkOrder: 56195715
Invoice Number: 55345-56195715

Client Department:

MRC: 55345M
WO Desc: 55345-MEDIUM DUTY PMA
Requested By: SPACE
Created By: SPACE
Class: WO
Arrangement: Unassigned
Potential Warranty: No


Equipment: 4839
GRAND CARAVAN SE
2C7WDGBG0ER476573
VIN:
Status: 32
Priority: 3
Driver:
Phone:
ETA:

Labor Posted

Date	Technician	Hours	Rate	Extended
04-Jan-23	Earl Johnson	4.25	0.00	0.00

Activity 10 Sub Total

Parts: 0.00
Labor: 0.00
Labor Hours: 4.25
Sublet Parts: 0.00
Sublet Labor: 0.00
Activity Sub Total 0.00

Activity: 20  **999/999/999 TOTAL VEHICLE**
Activity Note: Medium Duty PMA Service
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
04-Jan-23	Earl Johnson	0.02	0.00	0.00

Activity 20 Sub Total

Parts: 0.00
Labor: 0.00
Labor Hours: 0.02
Sublet Parts: 0.00
Sublet Labor: 0.00
Activity Sub Total 0.00

WorkOrder 56195715 Grand Total

Parts: 3.61
Labor: 0.00
Labor Hours: 4.49
Sublet Parts: 0.00
Sublet Labor: 0.00
WorkOrder Grand Total 3.61

Recent Repair History

WorkOrder	Date Completed	Life Meter	Class	Description
56195715	5-Jan-23	265,454	WO	55345-MEDIUM DUTY PMA

Scheduled Preventative Maintenance



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 3 of 12



WorkOrder: 56195715
Invoice Number: 55345-56195715

Client Department:

MRC: 55345M
WO Desc: 55345-MEDIUM DUTY PMA
Requested By: SPACE
Created By: SPACE
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 4839
VIN: GRAND CARAVAN SE
Status: 2C7WDGBG0ER476573
Priority: 32
Driver: 3
Phone:
ETA:

Nest	PM	WorkOrder	Due Date	Due Life Meter	Due Meter Reading	Due Life Meter 2	Due Meter Reading 2
------	----	-----------	----------	----------------	-------------------	------------------	---------------------

Other Open Repairs

WorkOrder8	Date Reported	Life Meter	Class	Description
------------	---------------	------------	-------	-------------

PH: Work Order: 56195715 Desc: 55345-MEDIUM DUTY PMA
Equip: 4839 Desc: GRAND CARAVAN SE VIN: 2C7WDGBG0ER476573

LH: 10 Desc: Medium Duty PM Inspection

Task: First Transit North America Medium Duty PM Inspection Sheet Performed by: EARJOHNSON
Performed on: 05-JAN-23

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10,000	SECTION 1 - Preparation Inspection	Done		EARJOHNSON	Jan 4, 2023 7:56:03 PM	No	
10,100	INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		EARJOHNSON	Jan 4, 2023 7:56:08 PM	No	
10,200	!FRA!INSPECT_Starter Operation	Done		EARJOHNSON	Jan 4, 2023 7:56:19 PM	No	
10,300	!FRA!INSPECT_Warning Lights and Alarms	Done		EARJOHNSON	Jan 4, 2023 7:56:24 PM	No	
10,400	!FRA!INSPECT_Back Up Alarm	Done		EARJOHNSON	Jan 4, 2023 7:56:28 PM	No	
10,500	!FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		EARJOHNSON	Jan 4, 2023 7:56:33 PM	No	
10,600	Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		EARJOHNSON	Jan 4, 2023 7:57:30 PM	No	
10,700	INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		EARJOHNSON	Jan 4, 2023 7:57:34 PM	No	
10,800	CHECK_All Destination Signage	Done		EARJOHNSON	Jan 4, 2023 7:57:39 PM	No	
10,900	*RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		EARJOHNSON	Jan 4, 2023 7:57:44 PM	No	
11,000	INSPECT_Fuel Tank Cap, and Doors	Done		EARJOHNSON	Jan 4, 2023 7:57:48 PM	No	
11,200	INSPECT_License Plate, Bracket, Bumpers	Done		EARJOHNSON	Jan 4, 2023 7:57:53 PM	No	
20,000	SECTION 2 - Test Drive and Operator Area Inspection	Done		EARJOHNSON	Jan 4, 2023 7:57:58 PM	No	
20,100	INSPECT_Driver Seat condition/operation/seatbelt	Done		EARJOHNSON	Jan 4, 2023 7:58:02 PM	No	
20,200	CHECK_Public Address System	Done		EARJOHNSON	Jan 4, 2023 7:58:07 PM	No	
20,300	TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		EARJOHNSON	Jan 4, 2023 7:58:12 PM	No	
20,400	*RPT*INSPECT_Steering Wheel for Play,Bind; Horn Op; Turn Signal Cancelation	Done		EARJOHNSON	Jan 4, 2023 7:58:20 PM	No	
20,500	PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		EARJOHNSON	Jan 4, 2023 7:58:40 PM	No	
20,600	RECORD_Brake Performance Test E.T.	Second*	NA	EARJOHNSON	Jan 4, 2023 7:58:49 PM	No	
20,700	RECORD_Brake Performance Test Speed	Miles per Hour	NA	EARJOHNSON	Jan 4, 2023 7:58:56 PM	No	
20,800	RECORD_Brake Performance Test Distance	FEET	NA	EARJOHNSON	Jan 4, 2023 7:59:04 PM	No	
20,900	RECORD_Brake Performance Test Adj Distance (20mph)	FEET	NA	EARJOHNSON	Jan 4, 2023 7:59:12 PM	No	
21,000	RECORD_Brake Performance Test Ave GX	Gravitational Force	NA	EARJOHNSON	Jan 4, 2023 7:59:20 PM	No	
21,100	ADD_Image of Brake Test Results to PM Work Order	-	NA	EARJOHNSON	Jan 4, 2023 7:59:30 PM	No	
21,200	*RPT*FRA INSPECT_Lighting/Operation of	Done		EARJOHNSON	Jan 4, 2023	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
	all Gauges				7:59:41 PM		
21,300	*RPT*INSPECT_Windshields, Sun Visors	Done		EARJOHNSON	Jan 4, 2023 7:59:48 PM	No	
21,400	INSPECT_Wiper/Washer Operation, Condition	Done		EARJOHNSON	Jan 4, 2023 7:59:55 PM	No	
21,600	*RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		EARJOHNSON	Jan 4, 2023 7:59:59 PM	No	
21,700	*RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		EARJOHNSON	Jan 4, 2023 8:00:06 PM	No	
21,800	INSPECT_Parking Brake Operation	Done		EARJOHNSON	Jan 4, 2023 8:00:27 PM	No	
21,900	!FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	-	NA	EARJOHNSON	Jan 4, 2023 8:00:38 PM	No	
22,000	INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		EARJOHNSON	Jan 4, 2023 8:01:38 PM	No	
22,100	*RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		EARJOHNSON	Jan 4, 2023 8:02:15 PM	No	
22,200	!FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		EARJOHNSON	Jan 4, 2023 8:02:26 PM	No	
22,250	INSPECT_Driver Floor Area for Water Leaks	Done		EARJOHNSON	Jan 4, 2023 8:08:07 PM	No	
22,300	*RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		EARJOHNSON	Jan 4, 2023 8:08:12 PM	No	
22,400	INSPECT_Engine Fault Codes	Done		EARJOHNSON	Jan 4, 2023 8:08:20 PM	No	
30,000	SECTION 3 - EXTERIOR INSPECTION	Done		EARJOHNSON	Jan 4, 2023 8:08:24 PM	No	
31,000	SSF (Street Side Front)	Done		EARJOHNSON	Jan 4, 2023 8:08:29 PM	No	
31,010	*RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		EARJOHNSON	Jan 4, 2023 8:08:34 PM	No	
31,020	*RPT*INSPECT_FRONT Springs, Shocks, Spring Shackles	Done		EARJOHNSON	Jan 4, 2023 8:08:38 PM	No	
31,030	INSPECT_Mud Flaps, Brackets	Done		EARJOHNSON	Jan 4, 2023 8:08:43 PM	No	
31,040	INSPECT_Wiper Blades, Arms	Done		EARJOHNSON	Jan 4, 2023 8:08:48 PM	No	
32,000	Engine Inspection	Done		EARJOHNSON	Jan 4, 2023 8:08:53 PM	No	
32,010	INSPECT_Hood, Springs and Props	Done		EARJOHNSON	Jan 4, 2023 8:08:57 PM	No	
32,020	!FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		EARJOHNSON	Jan 4, 2023 8:09:12 PM	No	
32,030	!FRA!INSPECT_for Fluid Leaks, Levels	Done		EARJOHNSON	Jan 4, 2023 8:09:17 PM	No	
32,040	!FRA!INSPECT_Hyd_Brake Fluid with Test Strips	-	NA	EARJOHNSON	Jan 4, 2023 8:09:27 PM	No	
32,050	!FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	Degree Fahrenheit	NA	EARJOHNSON	Jan 4, 2023 8:09:35 PM	No	
32,060	PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		EARJOHNSON	Jan 4, 2023 8:09:45 PM	No	
32,070	*RPT*INSPECT_Radiator and Mountings, Cores	Done		EARJOHNSON	Jan 4, 2023 8:10:00 PM	No	
32,080	*RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt	Done		EARJOHNSON	Jan 4, 2023 8:10:04 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
	Driven Components						
32,090	*RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		EARJOHNSON	Jan 4, 2023 8:10:21 PM	No	
32,100	INSPECT_Intake System	Done		EARJOHNSON	Jan 4, 2023 8:10:25 PM	No	
32,140	*RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	13.8 Volt*	At idle, with loads	EARJOHNSON	Jan 4, 2023 8:11:47 PM	No	
33,000	CSF (Curb Side Front)	Done		EARJOHNSON	Jan 4, 2023 8:11:52 PM	No	
33,010	*RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		EARJOHNSON	Jan 4, 2023 8:11:58 PM	No	
33,020	*RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		EARJOHNSON	Jan 4, 2023 8:12:03 PM	No	
33,030	INSPECT_Mud Flaps, Brackets	Done		EARJOHNSON	Jan 4, 2023 8:12:12 PM	No	
33,040	INSPECT_Wiper Blades, Arms	Done		EARJOHNSON	Jan 4, 2023 8:12:18 PM	No	
33,070	INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		EARJOHNSON	Jan 4, 2023 8:12:34 PM	No	
40,000	SECTION 4 - Interior Inspection	Done		EARJOHNSON	Jan 4, 2023 8:12:39 PM	No	
40,100	*RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		EARJOHNSON	Jan 4, 2023 8:12:47 PM	No	
40,200	INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		EARJOHNSON	Jan 4, 2023 8:12:51 PM	No	
40,250	INSPECT_Overhead Compartment for Water Leaks	Done		EARJOHNSON	Jan 4, 2023 8:13:05 PM	No	
40,300	INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		EARJOHNSON	Jan 4, 2023 8:13:10 PM	No	
40,400	INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		EARJOHNSON	Jan 4, 2023 8:13:15 PM	No	
40,600	!FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		EARJOHNSON	Jan 4, 2023 8:13:56 PM	No	
40,700	CHECK_Passenger Stop Request System	-	NA	EARJOHNSON	Jan 4, 2023 8:14:06 PM	No	
40,800	*RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		EARJOHNSON	Jan 4, 2023 8:14:13 PM	No	
40,900	*RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		EARJOHNSON	Jan 4, 2023 8:14:18 PM	No	
41,000	!FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		EARJOHNSON	Jan 4, 2023 8:14:22 PM	No	
41,100	INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		EARJOHNSON	Jan 4, 2023 8:14:53 PM	No	
41,200	INSPECT_CLEAN_AC Filter	Done		EARJOHNSON	Jan 4, 2023 8:14:58 PM	No	
41,300	INSPECT_ Emergency Windows, Hatches, Doors, Associated Alarms and Lights	-	NA	EARJOHNSON	Jan 4, 2023 8:15:20 PM	No	
41,400	*RPT*INSPECT_Interior Body, Floor, Stanchions	Done	Worn near drivers feet area.	EARJOHNSON	Jan 4, 2023 8:15:47 PM	No	
41,500	*RPT*INSPECT_Passenger Doors, Glass, Seal	Done		EARJOHNSON	Jan 4, 2023 8:15:52 PM	No	
50,000	SECTION 5 - UNDER VEHICLE INSPECTION	Done		EARJOHNSON	Jan 4, 2023 8:15:57 PM	No	
50,100	*RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		EARJOHNSON	Jan 4, 2023 8:16:21 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
50,200	INSPECT_Ball Joint Play	Done		EARJOHNSON	Jan 4, 2023 8:16:30 PM	No	
50,300	!FRA!INSPECT_Front Wheel Bearings for Play	Done		EARJOHNSON	Jan 4, 2023 10:48:05 PM	No	
50,400	LUBE_All Chassis Components	Done		EARJOHNSON	Jan 4, 2023 10:48:09 PM	No	
50,500	!FRA!CHANGE_Engine oil, filters	Done		EARJOHNSON	Jan 4, 2023 10:48:34 PM	No	
50,700	INSPECT_Tire Condition	Done	Both front tires below spec. Need replacing.	EARJOHNSON	Jan 4, 2023 11:05:37 PM	Yes	56277691
50,800	INSPECT_Tire Valve Stems, Double Check Caps	Done		EARJOHNSON	Jan 4, 2023 10:50:50 PM	No	
50,900	!FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		EARJOHNSON	Jan 4, 2023 10:50:56 PM	No	
51,000	RECORD_LF-Tire Tread Depth (32nds)	3 32nds of an inch		EARJOHNSON	Jan 4, 2023 10:51:07 PM	No	
51,100	RECORD_LF-Tire Air Pressure (psi)	36 Pounds per Square Inch		EARJOHNSON	Jan 4, 2023 10:51:16 PM	No	
51,200	RECORD_RF-Tire Tread Depth (32nds)	2 32nds of an inch		EARJOHNSON	Jan 4, 2023 10:51:21 PM	No	
51,300	RECORD_RF-Air Pressure (psi)	36 Pounds per Square Inch		EARJOHNSON	Jan 4, 2023 10:51:28 PM	No	
51,400	!FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		EARJOHNSON	Jan 4, 2023 10:51:33 PM	No	
51,500	!FRA!INSPECT_Wheel Seals for Leaks	Done		EARJOHNSON	Jan 4, 2023 10:51:38 PM	No	
51,600	!FRA!INSPECT_Front Brake Assemblies	Done		EARJOHNSON	Jan 4, 2023 10:51:43 PM	No	
51,700	MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	11 32nds of an inch		EARJOHNSON	Jan 4, 2023 10:51:54 PM	No	
51,800	MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	12 32nds of an inch		EARJOHNSON	Jan 4, 2023 10:52:11 PM	No	
51,900	INSPECT VISUALLY_RECORD_LF Rotor Condition (inches)	1.14 Inch		EARJOHNSON	Jan 4, 2023 10:52:32 PM	No	
52,000	INSPECT VISUALLY_RECORD_RF Rotor Condition (inches)	1.139 Inch		EARJOHNSON	Jan 4, 2023 10:52:44 PM	No	
52,100	INSPECT_Vibration Damper	Done		EARJOHNSON	Jan 4, 2023 10:52:48 PM	No	
52,200	!FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		EARJOHNSON	Jan 4, 2023 10:52:53 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
52,400	!FRA!INSPECT_ Starter Mounting	Done		EARJOHNSON	Jan 4, 2023 10:52:58 PM	No	
52,500	!FRA!INSPECT_Engine Exhaust System	Done		EARJOHNSON	Jan 4, 2023 10:53:03 PM	No	
52,700	INSPECT_ Engine, Transmission Mounts	Done	Slightly worn.	EARJOHNSON	Jan 4, 2023 10:53:37 PM	No	
52,800	!FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		EARJOHNSON	Jan 4, 2023 10:53:41 PM	No	
52,900	INSPECT_ Shift Cable Adjustment - All Transmissions	Done		EARJOHNSON	Jan 4, 2023 10:53:46 PM	No	
53,000	!FRA!INSPECT_ Transmission Breather and Clean	Done		EARJOHNSON	Jan 4, 2023 10:53:51 PM	No	
53,100	*RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		EARJOHNSON	Jan 4, 2023 10:54:01 PM	No	
53,200	*RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		EARJOHNSON	Jan 4, 2023 10:54:07 PM	No	
53,300	*RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	-	NA	EARJOHNSON	Jan 4, 2023 10:54:19 PM	No	
53,400	*RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		EARJOHNSON	Jan 4, 2023 10:54:25 PM	No	
53,500	!FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		EARJOHNSON	Jan 4, 2023 10:54:34 PM	No	
53,600	INSPECT_Tire Condition	Done		EARJOHNSON	Jan 4, 2023 10:54:52 PM	No	
53,700	INSPECT_Tire Valve Stems, Double Check Caps	Done		EARJOHNSON	Jan 4, 2023 10:54:57 PM	No	
53,800	INSPECT_ Mismatched Tire Tread, Casing Design	Done		EARJOHNSON	Jan 4, 2023 10:55:07 PM	No	
53,900	INSPECT_Dual Mating Tires w/Square	-	NA	EARJOHNSON	Jan 4, 2023 10:55:29 PM	No	
54,000	!FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		EARJOHNSON	Jan 4, 2023 10:55:34 PM	No	
54,100	INSPECT_Mud Flaps, Brackets	-	NA	EARJOHNSON	Jan 4, 2023 10:55:44 PM	No	
54,200	RECORD_RRO-Tire Tread Depth (32nds)	9 32nds of an inch		EARJOHNSON	Jan 4, 2023 10:56:07 PM	No	
54,400	RECORD_RRO-Air Pressure (psi)	36 Pounds per Square Inch		EARJOHNSON	Jan 4, 2023 10:56:17 PM	No	
54,600	RECORD_LRO-Tire Tread Depth (32nds)	8 32nds of an inch		EARJOHNSON	Jan 4, 2023 10:56:29	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					PM		
54,800	RECORD_LRO-Air Pressure (psi)	36 Pounds per Square Inch		EARJOHNSON	Jan 4, 2023 10:56:43 PM	No	
55,000	!FRA!INSPECT_ REAR Brake Assemblies	Done		EARJOHNSON	Jan 4, 2023 10:56:48 PM	No	
55,100	!FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		EARJOHNSON	Jan 4, 2023 10:56:52 PM	No	
55,200	!FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		EARJOHNSON	Jan 4, 2023 10:56:57 PM	No	
55,300	MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		EARJOHNSON	Jan 4, 2023 10:57:05 PM	No	
55,400	MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		EARJOHNSON	Jan 4, 2023 10:57:14 PM	No	
55,500	INSPECT VISUALLY_MEASURE_RECORD_LR Drum, Rotor Condition (inches)	.483 Inch		EARJOHNSON	Jan 4, 2023 10:57:30 PM	No	
55,600	INSPECT VISUALLY_MEASURE_RECORD_RR Drum, Rotor Condition (inches)	.489 Inch		EARJOHNSON	Jan 4, 2023 10:57:39 PM	No	
55,700	CHECK_Spring Brake Inversion Valve	-	NA	EARJOHNSON	Jan 4, 2023 10:57:56 PM	No	
55,800	CHECK_Double Check Valve - Primary, Secondary	-	NA	EARJOHNSON	Jan 4, 2023 10:58:04 PM	No	
55,900	!FRA!INSPECT_ Under Body Exhaust System	Done		EARJOHNSON	Jan 4, 2023 10:58:08 PM	No	
56,000	*RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	-	NA	EARJOHNSON	Jan 4, 2023 10:58:36 PM	No	
56,100	*RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		EARJOHNSON	Jan 4, 2023 11:09:12 PM	No	
56,100	*RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		EARJOHNSON	Jan 4, 2023 11:09:18 PM	No	
60,000	SECTION 6 - Wheelchair Inspection	Done		EARJOHNSON	Jan 4, 2023 10:59:07 PM	No	
60,100	RECORD_Wheelchair Cycle Count	Cycles	NA	EARJOHNSON	Jan 4, 2023 10:59:16 PM	No	
60,200	CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		EARJOHNSON	Jan 4, 2023 10:59:24 PM	No	
60,300	CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		EARJOHNSON	Jan 4, 2023 10:59:38 PM	No	
60,400	OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	-	NA	EARJOHNSON	Jan 4, 2023 10:59:45 PM	No	
60,500	INSPECT_ Bridgeplate Operation	-	NA	EARJOHNSON	Jan 4, 2023	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					10:59:56 PM		
60,600	INSPECT_All Pivot Points for Wear and Looseness	Done		EARJOHNSON	Jan 4, 2023 11:00:04 PM	No	
60,700	INSPECT_Rollers for Wear and Smooth Rotation	Done		EARJOHNSON	Jan 4, 2023 11:00:14 PM	No	
60,800	INSPECT_Operation of Platform Barrier Mechanism	Done		EARJOHNSON	Jan 4, 2023 11:00:21 PM	No	
60,900	INSPECT_Cam Slots for Wear and Proper Alignment	Done		EARJOHNSON	Jan 4, 2023 11:00:38 PM	No	
61,000	INSPECT_Cable Condition (If Applicable)	-	NA	EARJOHNSON	Jan 4, 2023 11:00:45 PM	No	
61,100	INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	-	NA	EARJOHNSON	Jan 4, 2023 11:00:52 PM	No	
61,200	INSPECT_Electrical Connections and Routing of Wires and Cables	-	NA	EARJOHNSON	Jan 4, 2023 11:01:01 PM	No	
61,300	INSPECT_Operation and Adjustment of All Safety Switches	-	NA	EARJOHNSON	Jan 4, 2023 11:01:34 PM	No	
61,400	INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		EARJOHNSON	Jan 4, 2023 11:01:43 PM	No	
61,500	INSPECT_Manual Back-up Raise/Lower System (If Applicable)	-	NA	EARJOHNSON	Jan 4, 2023 11:01:53 PM	No	
61,600	INSPECT_HydrPump Reservoir Oil Level. Consult SvcManual for Fluid to Use.	-	NA	EARJOHNSON	Jan 4, 2023 11:02:04 PM	No	
61,700	CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	-	NA	EARJOHNSON	Jan 4, 2023 11:02:13 PM	No	
61,800	CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		EARJOHNSON	Jan 4, 2023 11:02:19 PM	No	
61,900	CLEAN_Linkages and Mechanisms	Done		EARJOHNSON	Jan 4, 2023 11:02:42 PM	No	
62,000	LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		EARJOHNSON	Jan 4, 2023 11:02:52 PM	No	
62,100	INSPECT_Emergency Platform Release Mechanism	-	NA	EARJOHNSON	Jan 4, 2023 11:03:18 PM	No	
62,200	INSPECT_Platform Barrier Latch Mechanism	Done		EARJOHNSON	Jan 4, 2023 11:03:36 PM	No	
62,300	INSPECT_Bridgeplate Hinge	Done		EARJOHNSON	Jan 4, 2023 11:03:43 PM	No	
62,400	INSPECT_All Pivot Points	Done		EARJOHNSON	Jan 4, 2023 11:03:48 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
62,500	INSPECT_Cams and Slots	Done		EARJOHNSON	Jan 4, 2023 11:03:54 PM	No	
62,600	INSPECT_Rollers	Done		EARJOHNSON	Jan 4, 2023 11:04:13 PM	No	
62,700	INSPECT_All Linkages	Done		EARJOHNSON	Jan 4, 2023 11:04:28 PM	No	
80,000	SECTION 8 - PMI Report Completion	Done		EARJOHNSON	Jan 4, 2023 11:04:36 PM	No	
80,100	COMPLETE_PM Report; Follow-ups	Done		EARJOHNSON	Jan 4, 2023 11:04:41 PM	No	
80,200	RETURN_Vehicle to Predetermined Location	Done		EARJOHNSON	Jan 4, 2023 11:04:46 PM	No	

LH: 20 Desc: Medium Duty PMA Service

Task: 55345-Medium Duty PMA Inspection Performed by: EARJOHNSON Performed on: 05-JAN-23

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
100,000	"A" PMI SERVICING ITEMS	Done		EARJOHNSON	Jan 4, 2023 11:10:16 PM	No	
101,000	FRA Change Oil Filters	Yes		EARJOHNSON	Jan 4, 2023 11:10:22 PM	No	
102,000	FRA Drain Engine Oil	Yes		EARJOHNSON	Jan 4, 2023 11:10:26 PM	No	
103,000	FRA Check Transmission Fluid	Done		EARJOHNSON	Jan 4, 2023 11:10:31 PM	No	
104,000	Lubricate Chassis	Done		EARJOHNSON	Jan 4, 2023 11:10:35 PM	No	
105,000	Replace or Clean A/C Filters	-	NA	EARJOHNSON	Jan 4, 2023 11:10:46 PM	No	
106,000	Drain Water from Fuel Water Separator (where applicable)	-	NA	EARJOHNSON	Jan 4, 2023 11:10:53 PM	No	
107,000	FRA Change Primary Fuel Filter	No		EARJOHNSON	Jan 4, 2023 11:11:00 PM	No	
108,000	Lube all pivoting Mechanisms	Done		EARJOHNSON	Jan 4, 2023 11:11:07 PM	No	

LH: 5 Desc: Personal Risk Assessment

Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 05-JAN-23

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
1	Are you properly trained to perform the task?	Done		EARJOHNSON	Jan 4, 2023 11:12:25 PM	No	
2	If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Jan 4, 2023 11:12:25 PM	No	
4	Are you wearing the appropriate PPE?	Done		EARJOHNSON	Jan 4, 2023 11:12:26 PM	No	
7	Have you performed the proper LOTO?	Done		EARJOHNSON	Jan 4, 2023 11:12:26 PM	No	
10	Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Jan 4, 2023 11:12:27 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
11	Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Jan 4, 2023 11:12:27 PM	No	



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 10



WorkOrder: 56009779
Invoice Number: 55345-56009779

Client Department:

MRC:	55345M	Equipment:	4839
WO Desc:		VIN:	GRAND CARAVAN SE
55345-LIGHT DUTY PMB		Status:	2C7WDGBG0ER476573
Requested By:	RGASPARD	Priority:	40
Created By:	RGASPARD	Driver:	3
Class:	WO	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No		

Chronology		
Reported	Nov 17, 2022	12:00 AM
Started	Nov 21, 2022	
Completed	Nov 21, 2022	10:00 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	260,563	DH
System	260,357	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT:
	CAUSE:
	CORRECTION:

Activity: 5 **999/999/999 TOTAL VEHICLE**
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW - Shop Work Order
Work Accomplished: 06 - Inspect
Part Failure: 00 - No Failure

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
------	------------	-------	------	----------

Activity 5 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 10
Activity Note: Light Duty PMI
Reason for Repair: -
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
21-Nov-22	68144163AF	PADS, BRAKE, DISC, FRONT, CARAVAN	1.00	90.59	90.59
21-Nov-22	P9600	FILTER, OIL	1.00	3.49	3.49



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 2 of 10



WorkOrder: 56009779
Invoice Number: 55345-56009779

Client Department:

MRC: 55345M
WO Desc: 55345-LIGHT DUTY PMB
Requested By: RGASPARD
Created By: RGASPARD
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 4839
VIN: GRAND CARAVAN SE
Status: 2C7WDGBG0ER476573
Priority: 40
Driver: 3
Phone:
ETA:

Labor Posted

Date	Technician	Hours	Rate	Extended
21-Nov-22	Junior Hurst	3.03	0.00	0.00

Activity 10 Sub Total

Parts: 94.08
Labor: 0.00
Labor Hours: 3.03
Sublet Parts: 0.00
Sublet Labor: 0.00
Activity Sub Total 94.08

Activity: 20 999 TOTAL VEHICLE

Activity Note: PM B
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: B - PM Level B
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
21-Nov-22	Junior Hurst	0.13	0.00	0.00

Activity 20 Sub Total

Parts: 0.00
Labor: 0.00
Labor Hours: 0.13
Sublet Parts: 0.00
Sublet Labor: 0.00
Activity Sub Total 0.00

WorkOrder 56009779 Grand Total

Parts: 94.08
Labor: 0.00
Labor Hours: 3.16
Sublet Parts: 0.00
Sublet Labor: 0.00
WorkOrder Grand Total 94.08

Recent Repair History

WorkOrder	Date Completed	Life Meter	Class	Description
56009779	21-Nov-22	260,563	WO	55345-LIGHT DUTY PMB
56109216	7-Nov-22	259,157	WO	check Battery and chargingsystem



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 3 of 10



WorkOrder: 56009779
Invoice Number: 55345-56009779

Client Department:

MRC: 55345M
WO Desc: 55345-LIGHT DUTY PMB
Requested By: RGASPARD
Created By: RGASPARD
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 4839
VIN: GRAND CARAVAN SE
2C7WDGBG0ER476573
Status: 40
Priority: 3
Driver:
Phone:
ETA:

Scheduled Preventative Maintenance

Nest	PM	WorkOrder	Due Date	Due Life Meter	Due Meter Reading	Due Life Meter 2	Due Meter Reading 2
------	----	-----------	----------	----------------	-------------------	------------------	---------------------

Other Open Repairs

WorkOrder8	Date Reported	Life Meter	Class	Description
56109216	7-Nov-22	259,157	WO	check Battery and chargingsystem
56040465	14-Oct-22	256,604	WO	Windshield Washer

PH: Work Order: 56009779 Desc: 55345-LIGHT DUTY PMB
Equip: 4839 Desc: GRAND CARAVAN SE VIN: 2C7WDGBG0ER476573

LH: 10 Desc: Light Duty PMI

Task: First Transit North America Light Duty PM Inspection Sheet Performed by: JUHURST Performed on: 21-NOV-22

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10,000	SECTION 1 - Preparation Inspection	Done		JUHURST	Nov 21, 2022 6:53:01 PM	No	
10,100	INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		JUHURST	Nov 21, 2022 6:53:06 PM	No	
10,200	!FRA!INSPECT_Starter Operation	Done		JUHURST	Nov 21, 2022 9:26:26 PM	No	
10,300	!FRA!INSPECT_Warning Lights and Alarms	Done		JUHURST	Nov 21, 2022 9:26:31 PM	No	
10,400	!FRA!INSPECT_Back Up Alarm	Done		JUHURST	Nov 21, 2022 9:26:35 PM	No	
10,500	!FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		JUHURST	Nov 21, 2022 9:26:42 PM	No	
10,600	Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		JUHURST	Nov 21, 2022 9:26:47 PM	No	
10,700	INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		JUHURST	Nov 21, 2022 9:26:55 PM	No	
10,800	*RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		JUHURST	Nov 21, 2022 9:27:01 PM	No	
10,900	INSPECT_Fuel Tank Cap, and Doors	Done		JUHURST	Nov 21, 2022 9:27:07 PM	No	
11,100	INSPECT_License Plate, Bracket, Bumpers	Done		JUHURST	Nov 21, 2022 9:27:24 PM	No	
20,000	SECTION 2 - Test Drive and Operator Area Inspection	Done		JUHURST	Nov 21, 2022 9:27:41 PM	No	
20,100	INSPECT_Driver Seat condition/operation/seatbelt	Done		JUHURST	Nov 21, 2022 9:27:50 PM	No	
20,200	TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		JUHURST	Nov 21, 2022 9:28:02 PM	No	
20,300	*RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		JUHURST	Nov 21, 2022 9:53:35 PM	No	
20,300	*RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		JUHURST	Nov 21, 2022 9:53:44 PM	No	
20,400	PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		JUHURST	Nov 21, 2022 9:28:14 PM	No	
20,500	*RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		JUHURST	Nov 21, 2022 9:28:19 PM	No	
20,600	*RPT*INSPECT_Windshields, Sun Visors	Done		JUHURST	Nov 21, 2022 9:28:34 PM	No	
20,700	INSPECT_Wiper/Washer Operation, Condition	Done		JUHURST	Nov 21, 2022 9:28:39 PM	No	
20,900	*RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		JUHURST	Nov 21, 2022 9:28:43 PM	No	
21,000	*RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		JUHURST	Nov 21, 2022 9:28:48 PM	No	
21,100	INSPECT_Parking Brake Operation	Done		JUHURST	Nov 21, 2022 9:29:04 PM	No	
21,200	!FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		JUHURST	Nov 21, 2022 9:29:10 PM	No	
21,300	INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		JUHURST	Nov 21, 2022	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					9:29:15 PM		
21,400	*RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		JUHURST	Nov 21, 2022 9:29:21 PM	No	
21,500	!FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		JUHURST	Nov 21, 2022 9:29:25 PM	No	
21,550	INSPECT_Driver Floor Area for Rust/Water Leaks	Done		JUHURST	Nov 21, 2022 9:29:30 PM	No	
21,600	*RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		JUHURST	Nov 21, 2022 9:29:34 PM	No	
21,700	INSPECT_Engine Fault Codes	Done		JUHURST	Nov 21, 2022 9:29:39 PM	No	
30,000	SECTION 3 - EXTERIOR INSPECTION - Front	Done		JUHURST	Nov 21, 2022 9:29:44 PM	No	
31,000	SSF (Street Side Front)	Done		JUHURST	Nov 21, 2022 9:29:49 PM	No	
31,010	*RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		JUHURST	Nov 21, 2022 9:29:53 PM	No	
31,020	*RPT*INSPECT_FRONT Springs, Shocks, Spring Shackles	Done		JUHURST	Nov 21, 2022 9:29:58 PM	No	
31,030	INSPECT_Mud Flaps, Brackets	Done		JUHURST	Nov 21, 2022 9:30:03 PM	No	
31,040	INSPECT_Wiper Blades, Arms	Done		JUHURST	Nov 21, 2022 9:30:08 PM	No	
32,000	Engine Inspection	Done		JUHURST	Nov 21, 2022 9:30:21 PM	No	
32,010	INSPECT_Hood, Springs and Props	Done		JUHURST	Nov 21, 2022 9:30:16 PM	No	
32,020	!FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		JUHURST	Nov 21, 2022 9:30:28 PM	No	
32,030	!FRA!INSPECT_for Fluid Leaks, Levels	Done		JUHURST	Nov 21, 2022 9:30:36 PM	No	
32,040	!FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		JUHURST	Nov 21, 2022 9:30:52 PM	No	
32,050	!FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	26 Degree Fahrenheit		JUHURST	Nov 21, 2022 9:31:01 PM	No	
32,060	PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		JUHURST	Nov 21, 2022 9:31:06 PM	No	
32,070	*RPT*INSPECT_Radiator and Mountings, Cores	Done		JUHURST	Nov 21, 2022 9:31:14 PM	No	
32,080	*RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		JUHURST	Nov 21, 2022 9:31:22 PM	No	
32,090	*RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		JUHURST	Nov 21, 2022 9:31:39 PM	No	
32,100	INSPECT_Intake System	Done		JUHURST	Nov 21, 2022 9:31:47 PM	No	
32,140	*RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	14 Volt*		JUHURST	Nov 21, 2022 9:31:58 PM	No	
33,010	CSF (Curb Side Front)	Done		JUHURST	Nov 21, 2022 9:32:03 PM	No	
33,020	*RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		JUHURST	Nov 21, 2022 9:32:12 PM	No	
33,030	*RPT*INSPECT_FRONT Springs, Shocks, Spring Shackles	Done		JUHURST	Nov 21, 2022 9:32:19 PM	No	
33,040	INSPECT_Mud Flaps, Brackets	Done		JUHURST	Nov 21, 2022	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					9:32:23 PM		
33,050	INSPECT_Wiper Blades, Arms	Done		JUHURST	Nov 21, 2022 9:32:28 PM	No	
33,080	INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		JUHURST	Nov 21, 2022 9:32:33 PM	No	
40,000	SECTION 4 - Interior Inspection	Done		JUHURST	Nov 21, 2022 9:32:38 PM	No	
40,100	*RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		JUHURST	Nov 21, 2022 9:32:42 PM	No	
40,200	INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		JUHURST	Nov 21, 2022 9:32:47 PM	No	
40,250	INSPECT_Overhead Compartment for Water Leaks	Done		JUHURST	Nov 21, 2022 9:32:55 PM	No	
40,300	INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		JUHURST	Nov 21, 2022 9:33:06 PM	No	
40,400	INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		JUHURST	Nov 21, 2022 9:33:12 PM	No	
40,600	!FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		JUHURST	Nov 21, 2022 9:33:18 PM	No	
40,700	*RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		JUHURST	Nov 21, 2022 9:33:25 PM	No	
40,800	*RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		JUHURST	Nov 21, 2022 9:33:32 PM	No	
40,900	!FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		JUHURST	Nov 21, 2022 9:33:45 PM	No	
41,000	INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		JUHURST	Nov 21, 2022 9:33:40 PM	No	
41,100	INSPECT_CLEAN_AC Filter	Done		JUHURST	Nov 21, 2022 9:33:51 PM	No	
41,200	INSPECT_Emergency Windows,Hatches,Doors,Alarms/Lights;CHECK_for Leaks	Done		JUHURST	Nov 21, 2022 9:33:57 PM	No	
41,300	*RPT*INSPECT_Interior Body, Floor, Stanchions	Done		JUHURST	Nov 21, 2022 9:34:04 PM	No	
41,400	*RPT*INSPECT_Passenger Doors, Glass, Seal	Done		JUHURST	Nov 21, 2022 9:34:10 PM	No	
50,000	SECTION 5 - UNDER VEHICLE INSPECTION	Done	sway bar broken	JUHURST	Nov 21, 2022 9:36:30 PM	Yes	56157554
50,100	*RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		JUHURST	Nov 21, 2022 9:36:41 PM	No	
50,200	INSPECT_Ball Joint Play	Done		JUHURST	Nov 21, 2022 9:36:48 PM	No	
50,300	!FRA!INSPECT_Front Wheel Bearings for Play	Done		JUHURST	Nov 21, 2022 9:36:53 PM	No	
50,400	LUBE_All Chassis Components	Done		JUHURST	Nov 21, 2022 9:36:58 PM	No	
50,500	!FRA!CHANGE_Engine oil,filters	Done		JUHURST	Nov 21, 2022 9:37:02 PM	No	
50,700	INSPECT_Tire Condition	Done		JUHURST	Nov 21, 2022 9:37:07 PM	No	
50,800	INSPECT_Tire Valve Stems, Double Check Caps	Done		JUHURST	Nov 21, 2022 9:37:13 PM	No	
50,900	!FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		JUHURST	Nov 21, 2022 9:37:17 PM	No	
51,000	RECORD_LF-Tire Tread Depth (32nds)	6 32nds of an		JUHURST	Nov 21, 2022	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
		inch			9:37:36 PM		
51,100	RECORD_LF-Tire Air Pressure (psi)	35 Pounds per Square Inch		JUHURST	Nov 21, 2022 9:38:12 PM	No	
51,200	RECORD_RF-Tire Tread Depth (32nds)	6 32nds of an inch		JUHURST	Nov 21, 2022 9:38:23 PM	No	
51,300	RECORD_RF-Air Pressure (psi)	35 Pounds per Square Inch		JUHURST	Nov 21, 2022 9:38:35 PM	No	
51,400	!FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		JUHURST	Nov 21, 2022 9:38:42 PM	No	
51,500	!FRA!INSPECT_Wheel Seals for Leaks	Done		JUHURST	Nov 21, 2022 9:38:47 PM	No	
51,600	!FRA!INSPECT_ Front Brake Assemblies	Done		JUHURST	Nov 21, 2022 9:38:52 PM	No	
51,700	MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	4 32nds of an inch	front brakes too low need replace	JUHURST	Nov 21, 2022 9:40:36 PM	Yes	56157554
51,800	MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	4 32nds of an inch		JUHURST	Nov 21, 2022 9:41:07 PM	No	
51,900	INSPECT VISUALLY_ RECORD_LF Rotor Condition (inches)	1.2699 Inch		JUHURST	Nov 21, 2022 9:41:18 PM	No	
52,000	INSPECT VISUALLY_ RECORD_RF Rotor Condition (inches)	1.2699 Inch		JUHURST	Nov 21, 2022 9:41:31 PM	No	
52,100	INSPECT_Vibration Damper	Done		JUHURST	Nov 21, 2022 9:41:36 PM	No	
52,200	!FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		JUHURST	Nov 21, 2022 9:41:44 PM	No	
52,400	!FRA!INSPECT_ Starter Mounting	Done		JUHURST	Nov 21, 2022 9:41:48 PM	No	
52,500	!FRA!INSPECT_Engine Exhaust System	Done		JUHURST	Nov 21, 2022 9:41:53 PM	No	
52,700	INSPECT_ Engine, Transmission Mounts	Done		JUHURST	Nov 21, 2022 9:41:58 PM	No	
52,800	!FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		JUHURST	Nov 21, 2022 9:42:03 PM	No	
52,900	INSPECT_ Shift Cable Adjustment - All Transmissions	Done		JUHURST	Nov 21, 2022 9:42:08 PM	No	
53,000	!FRA!INSPECT_ Transmission Breather and Clean	Done		JUHURST	Nov 21, 2022 9:42:12 PM	No	
53,100	*RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		JUHURST	Nov 21, 2022 9:42:17 PM	No	
53,200	*RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		JUHURST	Nov 21, 2022 9:42:25 PM	No	
53,300	*RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		JUHURST	Nov 21, 2022 9:42:30 PM	No	
53,400	*RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		JUHURST	Nov 21, 2022 9:42:36 PM	No	
53,500	!FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		JUHURST	Nov 21, 2022 9:42:41 PM	No	
53,600	INSPECT_Tire Condition	Done		JUHURST	Nov 21, 2022 9:42:48 PM	No	
53,700	INSPECT_Tire Valve Stems, Double Check Caps	Done		JUHURST	Nov 21, 2022 9:42:53 PM	No	
53,800	INSPECT_ Mismatched Tire Tread, Casing Design	Done		JUHURST	Nov 21, 2022 9:42:57 PM	No	
53,900	INSPECT_Dual Mating Tires w/Square	Done		JUHURST	Nov 21, 2022 9:43:03 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
54,000	!FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		JUHURST	Nov 21, 2022 9:43:10 PM	No	
54,100	INSPECT_Mud Flaps, Brackets	Done		JUHURST	Nov 21, 2022 9:43:14 PM	No	
54,200	RECORD_RRO-Tire Tread Depth (32nds)	8 32nds of an inch		JUHURST	Nov 21, 2022 9:43:31 PM	No	
54,400	RECORD_RRO-Air Pressure (psi)	35 Pounds per Square Inch		JUHURST	Nov 21, 2022 9:43:39 PM	No	
54,600	RECORD_LRO-Tire Tread Depth (32nds)	6 32nds of an inch		JUHURST	Nov 21, 2022 9:43:59 PM	No	
54,800	RECORD_LRO-Air Pressure (psi)	35 Pounds per Square Inch		JUHURST	Nov 21, 2022 9:44:08 PM	No	
55,000	!FRA!INSPECT_ REAR Brake Assemblies	Done		JUHURST	Nov 21, 2022 9:44:13 PM	No	
55,100	!FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		JUHURST	Nov 21, 2022 9:44:24 PM	No	
55,200	!FRA!INSPECT_ REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		JUHURST	Nov 21, 2022 9:50:41 PM	No	56157554
55,300	MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		JUHURST	Nov 21, 2022 9:44:41 PM	No	
55,400	MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		JUHURST	Nov 21, 2022 9:44:47 PM	No	
55,500	INSPECT VISUALLY_MEASURE_RECORD_LR Drum, Rotor Condition (inches)	.5 Inch		JUHURST	Nov 21, 2022 9:45:00 PM	No	
55,600	INSPECT VISUALLY_MEASURE_RECORD_RR Drum, Rotor Condition (inches)	.5 Inch		JUHURST	Nov 21, 2022 9:45:08 PM	No	
55,700	!FRA!INSPECT_ Under Body Exhaust System	Done		JUHURST	Nov 21, 2022 9:45:13 PM	No	
55,800	*RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		JUHURST	Nov 21, 2022 9:45:24 PM	No	
55,900	*RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		JUHURST	Nov 21, 2022 9:45:30 PM	No	
60,000	SECTION 6 - Wheelchair Inspection	Done		JUHURST	Nov 21, 2022 9:45:35 PM	No	
60,100	RECORD_Wheelchair Cycle Count	0 Cycles		JUHURST	Nov 21, 2022 9:45:47 PM	No	
60,200	CHECK_Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		JUHURST	Nov 21, 2022 9:45:51 PM	No	
60,300	CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		JUHURST	Nov 21, 2022 9:45:56 PM	No	
60,400	OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		JUHURST	Nov 21, 2022 9:46:00 PM	No	
60,500	INSPECT_ Bridgeplate Operation	Done		JUHURST	Nov 21, 2022 9:46:05 PM	No	
60,600	INSPECT_All Pivot Points for Wear and Looseness	Done		JUHURST	Nov 21, 2022 9:46:10 PM	No	
60,700	INSPECT_Rollers for Wear and Smooth Rotation	Done		JUHURST	Nov 21, 2022 9:46:20 PM	No	
60,800	INSPECT_Operation of Platform Barrier Mechanism	Done		JUHURST	Nov 21, 2022 9:46:15 PM	No	
60,900	INSPECT_Cam Slots for Wear and Proper Alignment	Done		JUHURST	Nov 21, 2022 9:46:26 PM	No	
61,000	INSPECT_Cable Condition (If Applicable)	Done		JUHURST	Nov 21, 2022 9:46:31 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
61,100	INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		JUHURST	Nov 21, 2022 9:46:41 PM	No	
61,200	INSPECT_Electrical Connections and Routing of Wires and Cables	Done		JUHURST	Nov 21, 2022 9:46:36 PM	No	
61,300	INSPECT_Operation and Adjustment of All Safety Switches	Done		JUHURST	Nov 21, 2022 9:46:47 PM	No	
61,400	INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		JUHURST	Nov 21, 2022 9:46:52 PM	No	
61,500	INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		JUHURST	Nov 21, 2022 9:46:57 PM	No	
61,600	INSPECT_HydrPump Reservoir Oil Level. Consult SrvManual for Fluid to Use.	Done		JUHURST	Nov 21, 2022 9:47:01 PM	No	
61,700	CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		JUHURST	Nov 21, 2022 9:47:06 PM	No	
61,800	CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		JUHURST	Nov 21, 2022 9:47:11 PM	No	
61,900	CLEAN_Linkages and Mechanisms	Done		JUHURST	Nov 21, 2022 9:47:16 PM	No	
62,000	LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		JUHURST	Nov 21, 2022 9:47:21 PM	No	
62,100	INSPECT_Emergency Platform Release Mechanism	Done		JUHURST	Nov 21, 2022 9:47:25 PM	No	
62,200	INSPECT_Platform Barrier Latch Mechanism	Done		JUHURST	Nov 21, 2022 9:47:30 PM	No	
62,300	INSPECT_Bridgeplate Hinge	Done		JUHURST	Nov 21, 2022 9:47:34 PM	No	
62,400	INSPECT_All Pivot Points	Done		JUHURST	Nov 21, 2022 9:47:46 PM	No	
62,500	INSPECT_Cams and Slots	Done		JUHURST	Nov 21, 2022 9:47:41 PM	No	
62,600	INSPECT_Rollers	Done		JUHURST	Nov 21, 2022 9:47:58 PM	No	
62,700	INSPECT_All Linkages	Done		JUHURST	Nov 21, 2022 9:47:53 PM	No	
80,000	SECTION 8 - PMI Report Completion	Done		JUHURST	Nov 21, 2022 9:48:03 PM	No	
80,100	COMPLETE_PM Report; Follow-ups	Done		JUHURST	Nov 21, 2022 9:48:08 PM	No	
80,200	RETURN_Vehicle to Predetermined Location	Done		JUHURST	Nov 21, 2022 9:48:12 PM	No	

LH: 20 Desc: PM B

Task: PM B SERVICE Performed by: JUHURST Performed on: 21-NOV-22

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
100,000	"A" PMI SERVICING ITEMS	Done		JUHURST	Nov 21, 2022 6:43:47 PM	No	
101,000	FRA Change Oil Filters	Yes		JUHURST	Nov 21, 2022 6:43:52 PM	No	
102,000	FRA Drain Engine Oil	Yes		JUHURST	Nov 21, 2022 6:44:02 PM	No	
103,000	FRA Check Transmission Fluid	Done		JUHURST	Nov 21, 2022 6:44:15 PM	No	
104,000	Lubricate Chassis	Done		JUHURST	Nov 21, 2022 6:44:11 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
105,000	Replace or Clean A/C Filters	Done		JUHURST	Nov 21, 2022 6:44:20 PM	No	
107,000	FRA Change Primary Fuel Filter	Yes		JUHURST	Nov 21, 2022 6:44:33 PM	No	
108,000	Lube all pivoting Mechanisms	Done		JUHURST	Nov 21, 2022 6:44:29 PM	No	
200,000	"B" PMI SERVICING ITEMS (12 MONTH)	Done		JUHURST	Nov 21, 2022 6:44:38 PM	No	
201,000	Service Crankcase Breather	Done		JUHURST	Nov 21, 2022 6:44:44 PM	No	
203,000	FRA Change Automatic Transmission Fluid	No		JUHURST	Nov 21, 2022 6:44:55 PM	No	
204,000	FRA Change Power Steering Fluid and Filter	Yes		JUHURST	Nov 21, 2022 6:45:00 PM	No	
205,000	Complete Engine Diagnostics and Clear Codes when Completed	Done		JUHURST	Nov 21, 2022 6:45:05 PM	No	

LH: 5 Desc: PERSONAL RISK ASSESSMENT

Task: PRA and Meter Readings Performed by: JUHURST Performed on: 21-NOV-22

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
1	Are you properly trained to perform the task?	Done		JUHURST	Nov 21, 2022 6:41:58 PM	No	
2	If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JUHURST	Nov 21, 2022 6:41:53 PM	No	
4	Are you wearing the appropriate PPE?	Done		JUHURST	Nov 21, 2022 6:42:11 PM	No	
7	Have you performed the proper LOTO?	Done		JUHURST	Nov 21, 2022 6:42:06 PM	No	
10	Are you aware of the potential risks of performing this repair?	Done		JUHURST	Nov 21, 2022 6:42:24 PM	No	
11	Have you successfully completed the Personal Risk Assessment?	Done		JUHURST	Nov 21, 2022 6:42:19 PM	No	



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 10



WorkOrder: 55056108
Invoice Number: 55345-55056108

Client Department:

MRC: 55345M
WO Desc: 55345-LIGHT DUTY PMA
Requested By: NPIERRE-LOUIS
Created By: NPIERRE-LOUIS
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 4839
VIN: GRAND CARAVAN SE
2C7WDGBG0ER476573
Status: 40
Priority: 3
Driver:
Phone:
ETA:

Chronology		
Reported	Sep 27, 2022	12:00 AM
Started	Oct 4, 2022	
Completed	Oct 4, 2022	8:51 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	255,837	DH
System	255,484	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT:PMA CAUSE:Service CORRECTION: perform PMA Service oil filter P9600 qty1 engine oil 10w30 qty 6qts add washer fluid check inflate tires to spec

Activity: 5 **999/999/999 TOTAL VEHICLE**
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW - Shop Work Order
Work Accomplished: 06 - Inspect
Part Failure: 00 - No Failure

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
------	------------	-------	------	----------

Activity 5 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 10 **079 DEVICES, SAFETY/STABILITY, TRAILER**
Activity Note: Light Duty PMI
Reason for Repair: 05 - Inspection, Routine
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 2 of 10



WorkOrder: 55056108
Invoice Number: 55345-55056108

Client Department:

MRC: 55345M
WO Desc: 55345-LIGHT DUTY PMA
Requested By: NPIERRE-LOUIS
Created By: NPIERRE-LOUIS
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 4839
GRAND CARAVAN SE
2C7WDGBG0ER476573
VIN:
Status: 40
Priority: 3
Driver:
Phone:
ETA:

Date	Part Number	Description	Qty.	Each	Extended
04-Oct-22	P9600	FILTER, OIL	1.00	3.49	3.49

Labor Posted

Date	Technician	Hours	Rate	Extended
04-Oct-22	Gaspard,Ronald	1.23	0.00	0.00

Activity 10 Sub Total

Parts: 3.49
Labor: 0.00
Labor Hours: 1.23
Sublet Parts: 0.00
Sublet Labor: 0.00
Activity Sub Total 3.49

Activity: 20 **999 TOTAL VEHICLE**

Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
04-Oct-22	Gaspard,Ronald	0.53	0.00	0.00

Activity 20 Sub Total

Parts: 0.00
Labor: 0.00
Labor Hours: 0.53
Sublet Parts: 0.00
Sublet Labor: 0.00
Activity Sub Total 0.00

WorkOrder 55056108 Grand Total

Parts: 3.49
Labor: 0.00
Labor Hours: 1.76
Sublet Parts: 0.00
Sublet Labor: 0.00
WorkOrder Grand Total 3.49

Recent Repair History



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 3 of 10



WorkOrder: 55056108
Invoice Number: 55345-55056108

Client Department:

MRC: 55345M
WO Desc: 55345-LIGHT DUTY PMA
Requested By: NPIERRE-LOUIS
Created By: NPIERRE-LOUIS
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 4839
GRAND CARAVAN SE
VIN: 2C7WDGBG0ER476573
Status: 40
Priority: 3
Driver:
Phone:
ETA:

WorkOrder	Date Completed	Life Meter	Class	Description
55056108	4-Oct-22	255,837	WO	55345-LIGHT DUTY PMA

Scheduled Preventative Maintenance

Nest	PM	WorkOrder	Due Date	Due Life Meter	Due Meter Reading	Due Life Meter 2	Due Meter Reading 2
------	----	-----------	----------	----------------	-------------------	------------------	---------------------

Other Open Repairs

WorkOrder8	Date Reported	Life Meter	Class	Description
------------	---------------	------------	-------	-------------

PH: Work Order: 55056108 Desc: 55345-LIGHT DUTY PMA
Equip: 4839 Desc: GRAND CARAVAN SE VIN: 2C7WDGBG0ER476573

LH: 10 Desc: Light Duty PMI

Task: First Transit North America Light Duty PM Inspection Sheet Performed by: RGASPARD Performed on: 04-OCT-22

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10,000	SECTION 1 - Preparation Inspection	Done		RGASPARD	Oct 4, 2022 7:26:26 PM	No	
10,100	INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		RGASPARD	Oct 4, 2022 7:26:34 PM	No	
10,200	!FRA!INSPECT_Starter Operation	Done		RGASPARD	Oct 4, 2022 7:26:44 PM	No	
10,300	!FRA!INSPECT_Warning Lights and Alarms	Done		RGASPARD	Oct 4, 2022 7:26:49 PM	No	
10,400	!FRA!INSPECT_Back Up Alarm	Done		RGASPARD	Oct 4, 2022 7:26:54 PM	No	
10,500	!FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		RGASPARD	Oct 4, 2022 7:27:00 PM	No	
10,600	Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Oct 4, 2022 7:28:04 PM	No	
10,700	INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		RGASPARD	Oct 4, 2022 7:28:09 PM	No	
10,800	*RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		RGASPARD	Oct 4, 2022 7:28:14 PM	No	
10,900	INSPECT_Fuel Tank Cap, and Doors	Done		RGASPARD	Oct 4, 2022 7:28:19 PM	No	
11,100	INSPECT_License Plate, Bracket, Bumpers	Done		RGASPARD	Oct 4, 2022 7:28:23 PM	No	
20,000	SECTION 2 - Test Drive and Operator Area Inspection	Done		RGASPARD	Oct 4, 2022 7:28:28 PM	No	
20,100	INSPECT_Driver Seat condition/operation/seatbelt	Done		RGASPARD	Oct 4, 2022 7:28:37 PM	No	
20,200	TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		RGASPARD	Oct 4, 2022 7:28:47 PM	No	
20,300	*RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		RGASPARD	Oct 4, 2022 7:28:51 PM	No	
20,400	PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		RGASPARD	Oct 4, 2022 7:28:56 PM	No	
20,500	*RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		RGASPARD	Oct 4, 2022 7:29:14 PM	No	
20,600	*RPT*INSPECT_Windshields, Sun Visors	Done		RGASPARD	Oct 4, 2022 7:29:20 PM	No	
20,700	INSPECT_Wiper/Washer Operation, Condition	Done		RGASPARD	Oct 4, 2022 7:29:47 PM	No	
20,900	*RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		RGASPARD	Oct 4, 2022 7:29:52 PM	No	
21,000	*RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		RGASPARD	Oct 4, 2022 7:29:58 PM	No	
21,100	INSPECT_Parking Brake Operation	Done		RGASPARD	Oct 4, 2022 7:30:03 PM	No	
21,200	!FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		RGASPARD	Oct 4, 2022 7:30:07 PM	No	
21,300	INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		RGASPARD	Oct 4, 2022 7:30:12 PM	No	
21,400	*RPT*INSPECT_Drivers Door Hinges, Handles, Controls	Done		RGASPARD	Oct 4, 2022	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
	and Panels				7:30:25 PM		
21,500	!FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		RGASPARD	Oct 4, 2022 7:30:30 PM	No	
21,550	INSPECT_Driver Floor Area for Rust/Water Leaks	Done		RGASPARD	Oct 4, 2022 7:30:52 PM	No	
21,600	*RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		RGASPARD	Oct 4, 2022 7:31:05 PM	No	
21,700	INSPECT_Engine Fault Codes	Done		RGASPARD	Oct 4, 2022 7:31:10 PM	No	
30,000	SECTION 3 - EXTERIOR INSPECTION - Front	Done		RGASPARD	Oct 4, 2022 7:31:15 PM	No	
31,000	SSF (Street Side Front)	Done		RGASPARD	Oct 4, 2022 7:31:20 PM	No	
31,010	*RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RGASPARD	Oct 4, 2022 7:31:27 PM	No	
31,020	*RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		RGASPARD	Oct 4, 2022 7:31:34 PM	No	
31,030	INSPECT_Mud Flaps, Brackets	Done	na	RGASPARD	Oct 4, 2022 7:31:46 PM	No	
31,040	INSPECT_Wiper Blades, Arms	Done		RGASPARD	Oct 4, 2022 7:32:58 PM	No	
32,000	Engine Inspection	Done		RGASPARD	Oct 4, 2022 7:33:07 PM	No	
32,010	INSPECT_Hood, Springs and Props	Done		RGASPARD	Oct 4, 2022 7:33:27 PM	No	
32,020	!FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		RGASPARD	Oct 4, 2022 7:33:45 PM	No	
32,030	!FRA!INSPECT_for Fluid Leaks, Levels	Done		RGASPARD	Oct 4, 2022 7:33:50 PM	No	
32,040	!FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done	na	RGASPARD	Oct 4, 2022 7:34:00 PM	No	
32,050	!FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	Degree Fahrenheit	na	RGASPARD	Oct 4, 2022 7:34:09 PM	No	
32,060	PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		RGASPARD	Oct 4, 2022 7:34:13 PM	No	
32,070	*RPT*INSPECT_Radiator and Mountings, Cores	Done		RGASPARD	Oct 4, 2022 7:34:22 PM	No	
32,080	*RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		RGASPARD	Oct 4, 2022 7:34:39 PM	No	
32,090	*RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		RGASPARD	Oct 4, 2022 7:35:01 PM	No	
32,100	INSPECT_Intake System	Done		RGASPARD	Oct 4, 2022 7:35:06 PM	No	
32,140	*RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	14.1 Volt*		RGASPARD	Oct 4, 2022 7:35:15 PM	No	
33,010	CSF (Curb Side Front)	Done		RGASPARD	Oct 4, 2022 7:35:25 PM	No	
33,020	*RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RGASPARD	Oct 4, 2022 7:35:38 PM	No	
33,030	*RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		RGASPARD	Oct 4, 2022 7:35:43 PM	No	
33,040	INSPECT_Mud Flaps, Brackets	Done	na	RGASPARD	Oct 4, 2022 7:36:00 PM	No	
33,050	INSPECT_Wiper Blades, Arms	Done		RGASPARD	Oct 4, 2022 7:36:23 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
33,080	INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		RGASPARD	Oct 4, 2022 7:36:43 PM	No	
40,000	SECTION 4 - Interior Inspection	Done		RGASPARD	Oct 4, 2022 7:36:48 PM	No	
40,100	*RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		RGASPARD	Oct 4, 2022 7:36:58 PM	No	
40,200	INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		RGASPARD	Oct 4, 2022 7:37:03 PM	No	
40,250	INSPECT_Overhead Compartment for Water Leaks	Done		RGASPARD	Oct 4, 2022 7:37:09 PM	No	
40,300	INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		RGASPARD	Oct 4, 2022 7:37:14 PM	No	
40,400	INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		RGASPARD	Oct 4, 2022 7:37:22 PM	No	
40,600	!FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done	na	RGASPARD	Oct 4, 2022 7:37:32 PM	No	
40,700	*RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		RGASPARD	Oct 4, 2022 7:37:37 PM	No	
40,800	*RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		RGASPARD	Oct 4, 2022 7:37:43 PM	No	
40,900	!FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		RGASPARD	Oct 4, 2022 7:37:49 PM	No	
41,000	INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		RGASPARD	Oct 4, 2022 7:37:59 PM	No	
41,100	INSPECT_CLEAN_AC Filter	Done		RGASPARD	Oct 4, 2022 7:38:04 PM	No	
41,200	INSPECT_Emergency Windows,Hatches,Doors,Alarms/Lights;CHECK_for Leaks	Done		RGASPARD	Oct 4, 2022 7:38:09 PM	No	
41,300	*RPT*INSPECT_Interior Body, Floor, Stanchions	Done		RGASPARD	Oct 4, 2022 7:38:15 PM	No	
41,400	*RPT*INSPECT_Passenger Doors, Glass, Seal	Done		RGASPARD	Oct 4, 2022 7:38:23 PM	No	
50,000	SECTION 5 - UNDER VEHICLE INSPECTION	Done		RGASPARD	Oct 4, 2022 7:38:28 PM	No	
50,100	*RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		RGASPARD	Oct 4, 2022 7:38:37 PM	No	
50,200	INSPECT_Ball Joint Play	Done		RGASPARD	Oct 4, 2022 7:38:42 PM	No	
50,300	!FRA!INSPECT_Front Wheel Bearings for Play	Done		RGASPARD	Oct 4, 2022 7:38:46 PM	No	
50,400	LUBE_All Chassis Components	Done	na	RGASPARD	Oct 4, 2022 7:38:54 PM	No	
50,500	!FRA!CHANGE_Engine oil,filters	Done		RGASPARD	Oct 4, 2022 7:39:58 PM	No	
50,700	INSPECT_Tire Condition	Done		RGASPARD	Oct 4, 2022 7:40:12 PM	No	
50,800	INSPECT_Tire Valve Stems, Double Check Caps	Done		RGASPARD	Oct 4, 2022 7:40:36 PM	No	
50,900	!FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RGASPARD	Oct 4, 2022 7:40:43 PM	No	
51,000	RECORD_LF-Tire Tread Depth (32nds)	5 32nds of an inch		RGASPARD	Oct 4, 2022 7:42:15 PM	No	
51,100	RECORD_LF-Tire Air Pressure (psi)	40 Pounds per Square Inch		RGASPARD	Oct 4, 2022 7:42:37 PM	No	
51,200	RECORD_RF-Tire Tread Depth (32nds)	5 32nds of an		RGASPARD	Oct 4, 2022	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
		inch			7:42:52 PM		
51,300	RECORD_RF-Air Pressure (psi)	40 Pounds per Square Inch		RGASPARD	Oct 4, 2022 7:43:00 PM	No	
51,400	!FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		RGASPARD	Oct 4, 2022 7:43:06 PM	No	
51,500	!FRA!INSPECT_Wheel Seals for Leaks	Done		RGASPARD	Oct 4, 2022 7:43:17 PM	No	
51,600	!FRA!INSPECT_Front Brake Assemblies	Done		RGASPARD	Oct 4, 2022 7:43:29 PM	No	
51,700	MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		RGASPARD	Oct 4, 2022 7:43:48 PM	No	
51,800	MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		RGASPARD	Oct 4, 2022 7:44:11 PM	No	
51,900	INSPECT VISUALLY_RECORD_LF Rotor Condition (inches)	22 Inch		RGASPARD	Oct 4, 2022 7:44:24 PM	No	
52,000	INSPECT VISUALLY_RECORD_RF Rotor Condition (inches)	22 Inch		RGASPARD	Oct 4, 2022 7:44:29 PM	No	
52,100	INSPECT_Vibration Damper	Done	na	RGASPARD	Oct 4, 2022 7:44:41 PM	No	
52,200	!FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		RGASPARD	Oct 4, 2022 7:44:51 PM	No	
52,400	!FRA!INSPECT_Starter Mounting	Done		RGASPARD	Oct 4, 2022 7:45:04 PM	No	
52,500	!FRA!INSPECT_Engine Exhaust System	Done		RGASPARD	Oct 4, 2022 7:45:10 PM	No	
52,700	INSPECT_Engine, Transmission Mounts	Done		RGASPARD	Oct 4, 2022 7:45:17 PM	No	
52,800	!FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		RGASPARD	Oct 4, 2022 7:46:06 PM	No	
52,900	INSPECT_Shift Cable Adjustment - All Transmissions	Done		RGASPARD	Oct 4, 2022 7:46:20 PM	No	
53,000	!FRA!INSPECT_Transmission Breather and Clean	Done	na	RGASPARD	Oct 4, 2022 7:46:28 PM	No	
53,100	*RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		RGASPARD	Oct 4, 2022 7:46:33 PM	No	
53,200	*RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		RGASPARD	Oct 4, 2022 7:57:27 PM	No	
53,300	*RPT*INSPECT_Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done	na	RGASPARD	Oct 4, 2022 7:57:38 PM	No	
53,400	*RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		RGASPARD	Oct 4, 2022 7:57:46 PM	No	
53,500	!FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		RGASPARD	Oct 4, 2022 7:57:50 PM	No	
53,600	INSPECT_Tire Condition	Done		RGASPARD	Oct 4, 2022 7:57:55 PM	No	
53,700	INSPECT_Tire Valve Stems, Double Check Caps	Done		RGASPARD	Oct 4, 2022 7:58:00 PM	No	
53,800	INSPECT_Mismatched Tire Tread, Casing Design	Done		RGASPARD	Oct 4, 2022 7:58:05 PM	No	
53,900	INSPECT_Dual Mating Tires w/Square	Done	na	RGASPARD	Oct 4, 2022 7:58:12 PM	No	
54,000	!FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RGASPARD	Oct 4, 2022 7:58:19 PM	No	
54,100	INSPECT_Mud Flaps, Brackets	Done	na	RGASPARD	Oct 4, 2022 7:58:26 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
54,200	RECORD_RRO-Tire Tread Depth (32nds)	5 32nds of an inch		RGASPARD	Oct 4, 2022 7:58:31 PM	No	
54,400	RECORD_RRO-Air Pressure (psi)	40 Pounds per Square Inch		RGASPARD	Oct 4, 2022 7:58:35 PM	No	
54,600	RECORD_LRO-Tire Tread Depth (32nds)	5 32nds of an inch		RGASPARD	Oct 4, 2022 7:58:40 PM	No	
54,800	RECORD_LRO-Air Pressure (psi)	40 Pounds per Square Inch		RGASPARD	Oct 4, 2022 7:58:46 PM	No	
55,000	!FRA!INSPECT_ REAR Brake Assemblies	Done		RGASPARD	Oct 4, 2022 7:58:50 PM	No	
55,100	!FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done	na	RGASPARD	Oct 4, 2022 7:58:58 PM	No	
55,200	!FRA!INSPECT_ REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		RGASPARD	Oct 4, 2022 7:59:02 PM	No	
55,300	MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	5 32nds of an inch		RGASPARD	Oct 4, 2022 7:59:08 PM	No	
55,400	MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	5 32nds of an inch		RGASPARD	Oct 4, 2022 7:59:13 PM	No	
55,500	INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	11 Inch		RGASPARD	Oct 4, 2022 8:00:20 PM	No	
55,600	INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	11 Inch		RGASPARD	Oct 4, 2022 8:00:25 PM	No	
55,700	!FRA!INSPECT_ Under Body Exhaust System	Done		RGASPARD	Oct 4, 2022 8:00:30 PM	No	
55,800	*RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done	na	RGASPARD	Oct 4, 2022 8:00:39 PM	No	
55,900	*RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		RGASPARD	Oct 4, 2022 8:00:45 PM	No	
60,000	SECTION 6 - Wheelchair Inspection	-	na	RGASPARD	Oct 4, 2022 8:00:59 PM	No	
60,100	RECORD_Wheelchair Cycle Count	Cycles	na	RGASPARD	Oct 4, 2022 8:01:05 PM	No	
60,200	CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	-	na	RGASPARD	Oct 4, 2022 8:01:13 PM	No	
60,300	CHECK_Platform Emergency Release Mechanism for Ease of Operation	-	na	RGASPARD	Oct 4, 2022 8:01:19 PM	No	
60,400	OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	-	na	RGASPARD	Oct 4, 2022 8:01:24 PM	No	
60,500	INSPECT_ Bridgeplate Operation	-	na	RGASPARD	Oct 4, 2022 8:01:29 PM	No	
60,600	INSPECT_All Pivot Points for Wear and Looseness	-	na	RGASPARD	Oct 4, 2022 8:01:35 PM	No	
60,700	INSPECT_Rollers for Wear and Smooth Rotation	-	na	RGASPARD	Oct 4, 2022 8:01:40 PM	No	
60,800	INSPECT_Operation of Platform Barrier Mechanism	-	na	RGASPARD	Oct 4, 2022 8:01:46 PM	No	
60,900	INSPECT_Cam Slots for Wear and Proper Alignment	-	na	RGASPARD	Oct 4, 2022 8:01:53 PM	No	
61,000	INSPECT_Cable Condition (If Applicable)	-	na	RGASPARD	Oct 4, 2022 8:01:58 PM	No	
61,100	INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	-	na	RGASPARD	Oct 4, 2022 8:02:04 PM	No	
61,200	INSPECT_Electrical Connections and Routing of Wires and Cables	-	na	RGASPARD	Oct 4, 2022 8:02:09 PM	No	
61,300	INSPECT_Operation and Adjustment of All Safety	-	na	RGASPARD	Oct 4, 2022	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
	Switches				8:02:14 PM		
61,400	INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	-	na	RGASPARD	Oct 4, 2022 8:02:20 PM	No	
61,500	INSPECT_Manual Back-up Raise/Lower System (If Applicable)	-	na	RGASPARD	Oct 4, 2022 8:02:26 PM	No	
61,600	INSPECT_HydrPump Reservoir Oil Level. Consult SrvManual for Fluid to Use.	-	na	RGASPARD	Oct 4, 2022 8:02:34 PM	No	
61,700	CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	-	na	RGASPARD	Oct 4, 2022 8:02:40 PM	No	
61,800	CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	-	na	RGASPARD	Oct 4, 2022 8:02:47 PM	No	
61,900	CLEAN_Linkages and Mechanisms	-	na	RGASPARD	Oct 4, 2022 8:02:52 PM	No	
62,000	LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	-	na	RGASPARD	Oct 4, 2022 8:03:03 PM	No	
62,100	INSPECT_Emergency Platform Release Mechanism	-	na	RGASPARD	Oct 4, 2022 8:03:09 PM	No	
62,200	INSPECT_Platform Barrier Latch Mechanism	-	na	RGASPARD	Oct 4, 2022 8:03:16 PM	No	
62,300	INSPECT_Bridgeplate Hinge	-	na	RGASPARD	Oct 4, 2022 8:03:23 PM	No	
62,400	INSPECT_All Pivot Points	-	na	RGASPARD	Oct 4, 2022 8:03:29 PM	No	
62,500	INSPECT_Cams and Slots	-	na	RGASPARD	Oct 4, 2022 8:03:35 PM	No	
62,600	INSPECT_Rollers	-	na	RGASPARD	Oct 4, 2022 8:03:41 PM	No	
62,700	INSPECT_All Linkages	-	na	RGASPARD	Oct 4, 2022 8:03:48 PM	No	
80,000	SECTION 8 - PMI Report Completion	Done		RGASPARD	Oct 4, 2022 8:03:53 PM	No	
80,100	COMPLETE_PM Report; Follow-ups	Done		RGASPARD	Oct 4, 2022 8:03:57 PM	No	
80,200	RETURN_Vehicle to Predetermined Location	Done		RGASPARD	Oct 4, 2022 8:04:02 PM	No	

LH: 20 Desc: PM A

Task: PM A SERVICE Performed by: RGASPARD Performed on: 04-OCT-22

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
100,000	"A" PMI SERVICING ITEMS	Done		RGASPARD	Oct 4, 2022 8:48:43 PM	No	
101,000	FRA Change Oil Filters	Yes		RGASPARD	Oct 4, 2022 8:48:48 PM	No	
102,000	FRA Drain Engine Oil	Yes		RGASPARD	Oct 4, 2022 8:48:53 PM	No	
103,000	FRA Check Transmission Fluid	-	na	RGASPARD	Oct 4, 2022 8:49:03 PM	No	
104,000	Lubricate Chassis	-	na	RGASPARD	Oct 4, 2022 8:49:08 PM	No	
105,000	Replace or Clean A/C Filters	Done		RGASPARD	Oct 4, 2022 8:49:13 PM	No	
107,000	FRA Change Primary Fuel Filter	No	na	RGASPARD	Oct 4, 2022 8:49:26 PM	No	
108,000	Lube all pivoting Mechanisms	-	na	RGASPARD	Oct 4, 2022 8:51:01 PM	No	

LH: 5 Desc: PERSONAL RISK ASSESSMENT

Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 04-OCT-22

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
1	Are you properly trained to perform the task?	Done		RGASPARD	Oct 4, 2022	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					6:55:59 PM		
2	If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Oct 4, 2022 6:56:04 PM	No	
4	Are you wearing the appropriate PPE?	Done		RGASPARD	Oct 4, 2022 6:56:09 PM	No	
7	Have you performed the proper LOTO?	Done		RGASPARD	Oct 4, 2022 6:56:13 PM	No	
10	Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Oct 4, 2022 6:56:18 PM	No	
11	Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Oct 4, 2022 6:56:22 PM	No	



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 10



WorkOrder: 54922976
Invoice Number: 55345-54922976

Client Department:

MRC: 55345M
WO Desc:
55345-LIGHT DUTY PMA
Requested By: NPIERRE-LOUIS
Created By: NPIERRE-LOUIS
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 4839
GRAND CARAVAN SE
2C7WDGBG0ER476573
VIN:
Status: 40
Priority: 3
Driver:
Phone:
ETA:

Chronology		
Reported	Nov 3, 2021	7:30 AM
Started	Nov 3, 2021	
Completed	Nov 3, 2021	10:00 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	251,084	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: pmA Service CAUSE: preventive maintenance CORRECTION:Perform pmA Service And Lube all Pivoting Points

Activity: 5 **999/999/999 TOTAL VEHICLE**

Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW - Shop Work Order
Work Accomplished: 06 - Inspect
Part Failure: 00 - No Failure

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
------	-------------	--	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
------	------------	-------	------	----------

Activity 5 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 10 **999 TOTAL VEHICLE**

Activity Note: Light Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
------	-------------	--	-------------	------	------	----------

Labor Posted



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 10



WorkOrder: 54822884
Invoice Number: 55345-54822884

Client Department:

MRC: 55345M
WO Desc: 55345-LIGHT DUTY PMC
Requested By: JUHURST
Created By: JUHURST
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 4839
VIN: GRAND CARAVAN SE
2C7WDGBG0ER476573
Status: 40
Priority: 3
Driver:
Phone:
ETA:

Chronology

Reported	Sep 22, 2021	8:38 AM
Started	Sep 22, 2021	
Completed	Sep 22, 2021	12:28 PM

Down Time

Meter	Reading	UOM
WO		DH
Life	247,067	DH

WorkOrder Notes

Line	Comment
10	Complaint: PMC service Cause: preventive maintenance Correction: perform PMC service and Lube all Pivoting Points

Activity: 5 **999/999/999 TOTAL VEHICLE**

Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW - Shop Work Order
Work Accomplished: 06 - Inspect
Part Failure: 00 - No Failure

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
------	-------------	--	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
------	------------	-------	------	----------

Activity 5 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 10 **999 TOTAL VEHICLE**

Activity Note: Light Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
------	-------------	--	-------------	------	------	----------

Labor Posted



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 10



WorkOrder: 54704679
Invoice Number: 55345-54704679

Client Department:

MRC: 55345M
WO Desc: 55345-LIGHT DUTY PMA
Requested By: DKNOTT
Created By: DKNOTT
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 4839
VIN: GRAND CARAVAN SE
2C7WDGBG0ER476573
Status: 40
Priority: 3
Driver:
Phone:
ETA:

Chronology		
Reported	Aug 18, 2021	8:53 AM
Started	Aug 18, 2021	
Completed	Aug 18, 2021	1:21 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	243,017	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: Vehicle came in for service CAUSE: Service by miles CORRECTION: Job complete also change oil filter part # p9600 return unit back to work

Activity: 5 **999/999/999 TOTAL VEHICLE**

Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW - Shop Work Order
Work Accomplished: 06 - Inspect
Part Failure: 00 - No Failure

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
18-Aug-21	Junior Hurst	0.07	0.00	0.00

Activity 5 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.07	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 10

Activity Note: Light Duty PMI
Reason for Repair: -
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 10



WorkOrder: 54493089
Invoice Number: 55345-54493089

Client Department:

MRC:	55345M	Equipment:	4839
WO Desc:		VIN:	GRAND CARAVAN SE
55345-LIGHT DUTY PMA		Status:	2C7WDGBG0ER476573
Requested By:	DARTHURS	Priority:	40
Created By:	DARTHURS	Driver:	3
Class:	WO	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No		

Chronology		
Reported	Jul 1, 2021	12:45 PM
Started	Jul 2, 2021	
Completed	Jul 6, 2021	8:45 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	238,770	DH
System	238,621	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: pmA CAUSE:Service CORRECTION:Perform pmA Service Oil filter P9600 qty1 Engine oil 10w30 qty 5 1/2 qts Patched right rear tire mount and balance Torque wheel 100 lbs second torque 100 lbs

Activity: 5 **999/999/999 TOTAL VEHICLE**
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW - Shop Work Order
Work Accomplished: 06 - Inspect
Part Failure: 00 - No Failure

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
------	------------	-------	------	----------

Activity 5 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 10 **079 DEVICES, SAFETY/STABILITY, TRAILER**
Activity Note: Light Duty PMI
Reason for Repair: 05 - Inspection, Routine
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 10



WorkOrder: 54327669
Invoice Number: 55345-54327669

Client Department:

MRC: 55345M
WO Desc: 55345-LIGHT DUTY PMB
Requested By: JUHURST
Created By: JUHURST
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 4839
VIN: GRAND CARAVAN SE
Status: 2C7WDGBG0ER476573
Priority: 40
Driver: 3
Phone:
ETA:

Chronology		
Reported	Apr 22, 2021	12:00 AM
Started	Apr 22, 2021	
Completed	Apr 22, 2021	10:10 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	234,309	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: Perform PMB Service. CAUSE: Service Due by Mileage. CORRECTION: Change Oil & Filter. Lube all Pivoting Points. Check brakes. Check cabin air filter. Parts # P9600 Qty (1) Oil 10W30 Qty (5.5) Qt

Activity: 5 **999/999/999 TOTAL VEHICLE**

Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW - Shop Work Order
Work Accomplished: 06 - Inspect
Part Failure: 00 - No Failure

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
------	------------	-------	------	----------

Activity 5 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 10 **079 DEVICES, SAFETY/STABILITY, TRAILER**

Activity Note: Light Duty PMI
Reason for Repair: 05 - Inspection, Routine
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 10



WorkOrder: 54173490
Invoice Number: 55345-54173490

Client Department:

MRC: 55345M
WO Desc: 55345-LIGHT DUTY PMA
Requested By: DARTHURS
Created By: DARTHURS
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 4839
VIN: GRAND CARAVAN SE
2C7WDGBG0ER476573
Status: 40
Priority: 3
Driver:
Phone:
ETA:

Chronology		
Reported	Feb 24, 2021	12:00 AM
Started	Feb 24, 2021	
Completed	Feb 24, 2021	7:23 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	229,976	DH
System	229,976	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: Vehicle came in for service CAUSE: Time for service CORRECTION: Service job complete

Activity: 5 **999/999/999 TOTAL VEHICLE**

Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW - Shop Work Order
Work Accomplished: 06 - Inspect
Part Failure: 00 - No Failure

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
24-Feb-21	Junior Hurst	0.02	0.00	0.00
24-Feb-21	Junior Hurst	0.12	0.00	0.00

Activity 5 Sub Total

Parts: 0.00
Labor: 0.00
Labor Hours: 0.14
Sublet Parts: 0.00
Sublet Labor: 0.00
Activity Sub Total 0.00

Activity: 10

Activity Note: Light Duty PMI
Reason for Repair: -
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 10



WorkOrder: 54018927
Invoice Number: 55345-54018927

Client Department:

MRC: 55345M
WO Desc: 55345-LIGHT DUTY PMA
Requested By: EARJOHNSON
Created By: EARJOHNSON
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 4839
VIN: GRAND CARAVAN SE
2C7WDGBG0ER476573
Status: 40
Priority: 3
Driver:
Phone:
ETA:

Chronology		
Reported	Dec 31, 2020	8:58 AM
Started	Dec 31, 2020	
Completed	Dec 31, 2020	7:17 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	225,489	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: Perform PMA Service CAUSE: Service Due by Mileage. CORRECTION: Change Oil & Filter. Lube all Pivoting Points.check Brakes. Swap L/F Tire. Parts # P9600 Qty (1) Oil 10W30 Qty (5.5) Qt

Activity: 5 **999/999/999 TOTAL VEHICLE**

Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW - Shop Work Order
Work Accomplished: 06 - Inspect
Part Failure: 00 - No Failure

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
------	-------------	--	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
------	------------	-------	------	----------

Activity 5 Sub Total

Parts: 0.00
Labor: 0.00
Labor Hours: 0.00
Sublet Parts: 0.00
Sublet Labor: 0.00
Activity Sub Total 0.00

Activity: 10 **079 DEVICES, SAFETY/STABILITY, TRAILER**

Activity Note: Light Duty PMI
Reason for Repair: 05 - Inspection, Routine
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
------	-------------	--	-------------	------	------	----------

Labor Posted



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 10



WorkOrder: 53883946
Invoice Number: 55345-53883946

Client Department:

MRC: 55345M
WO Desc: 55345-LIGHT DUTY PMC
Requested By: RGASPARD
Created By: RGASPARD
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 4839
VIN: GRAND CARAVAN SE
2C7WDGBG0ER476573
Status: 40
Priority: 3
Driver:
Phone:
ETA:

Chronology

Reported	Nov 2, 2020	12:00 AM
Started	Nov 2, 2020	
Completed	Nov 2, 2020	10:20 PM

Down Time

Meter	Reading	UOM
WO		DH
Life	221,345	DH

WorkOrder Notes

Line	Comment
10	PM C service Due by mileage. LOF engine oil and filter. Performed tire and brake inspection.

Activity: 5 **999/999/999 TOTAL VEHICLE**

Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW - Shop Work Order
Work Accomplished: 06 - Inspect
Part Failure: 00 - No Failure

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
02-Nov-20	Earl Johnson	0.13	0.00	0.00

Activity 5 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.13	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 10 **999/999/999 TOTAL VEHICLE**

Activity Note: Light Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 11



WorkOrder: 53722474
Invoice Number: 55345-53722474

Client Department:

MRC: 55345M
WO Desc: 55345-LIGHT DUTY PMA
Requested By: DARTHURS
Created By: DARTHURS
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 4839
VIN: GRAND CARAVAN SE
2C7WDGBG0ER476573
Status: 40
Priority: 3
Driver:
Phone:
ETA:

Chronology

Reported	Sep 17, 2020	12:00 AM
Started	Sep 17, 2020	
Completed	Sep 18, 2020	12:29 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	217,074	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PmA CAUSE: Service CORRECTION: perform PmA Service Oil filter P9600 Qty1 Engine oil 10w30 qty 5 qts

Activity: 5 **999/999/999 TOTAL VEHICLE**

Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW - Shop Work Order
Work Accomplished: 06 - Inspect
Part Failure: 00 - No Failure

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
------	------------	-------	------	----------

Activity 5 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 10 **999/999/999 TOTAL VEHICLE**

Activity Note: Light Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 10



WorkOrder: 53576124
Invoice Number: 55345-53576124

Client Department:

MRC: 55345M
WO Desc: 55345-LIGHT DUTY PMA
Requested By: DARTHURS
Created By: DARTHURS
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 4839
VIN: GRAND CARAVAN SE
2C7WDGBG0ER476573
Status: 40
Priority: 3
Driver:
Phone:
ETA:

Chronology		
Reported	Jul 20, 2020	12:00 AM
Started	Jul 22, 2020	
Completed	Jul 22, 2020	5:52 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	212,752	DH
System	212,505	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PMA Service CAUSE: Service Due by Mileage. CORRECTION: Change Oil & Filter. Lube all Pivoting Points. Check brakes. Check batteries. Parts #P9600 Qty (1) Oil 10W20 Qty (5.5) Qt

Activity: 5 **999/999/999 TOTAL VEHICLE**

Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW - Shop Work Order
Work Accomplished: 06 - Inspect
Part Failure: 00 - No Failure

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
------	-------------	--	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
------	------------	-------	------	----------

Activity 5 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 10 **999/999/999 TOTAL VEHICLE**

Activity Note: Light Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: -
Part Failure: -

Activity Comments


Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
------	-------------	--	-------------	------	------	----------

Labor Posted



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 9



WorkOrder: 53558528
Invoice Number: 55345-53558528

Client Department:

MRC: 55345M
WO Desc: 55345-LIGHT DUTY PMB
Requested By: NSTOLFO
Created By: NSTOLFO
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 4839
GRAND CARAVAN SE
2C7WDGBG0ER476573
VIN:
Status: 40
Priority: 3
Driver:
Phone:
ETA:

Chronology		
Reported	May 26, 2020	12:11 PM
Started	May 26, 2020	
Completed	May 26, 2020	8:31 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	208,075	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: Perform PMB Service CAUSE: Service Due by Mileage CORRECTION: Change Oil & Filter .Lube all Pivoting Points. Check brakes. Replace cabin air filter. Parts # P9600 Qty (1) Parts # PA 10030 Qty (1) Oil 10W30 Qty (5.5) Qt

Activity: 5 **999/999/999 TOTAL VEHICLE**
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW - Shop Work Order
Work Accomplished: 06 - Inspect
Part Failure: 00 - No Failure

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
------	------------	-------	------	----------

Activity 5 Sub Total

Parts: 0.00
Labor: 0.00
Labor Hours: 0.00
Sublet Parts: 0.00
Sublet Labor: 0.00
Activity Sub Total 0.00

Activity: 10 **999/999/999 TOTAL VEHICLE**
Activity Note: Light Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued


Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------



WorkOrder

55345 Palm Tran Connection
v 2.2

Page 1 of 9



WorkOrder: 53293413

Invoice Number: 55345-53293413

Client Department:

MRC:

55345M

Equipment:

4839

WO Desc:

GRAND CARAVAN SE

PM A

VIN:

2C7WDGBG0ER476573

Requested By:

JUHURST

Status:

40

Created By:

JUHURST

Priority:

1

Class:

WO

Driver:

Arrangement:

Unassigned

Phone:

Potential Warranty:

No

ETA:

Chronology

Reported	Mar 17, 2020	11:04 AM
Started	Mar 17, 2020	
Completed	Mar 18, 2020	12:21 AM

Down Time

Meter	Reading	UOM
WO		DH
Life	204,056	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PMA CAUSE: service CORRECTION: perform PMA service Oil filter P9600 qty1 Engine oil 10w30 qty 6 qts

Activity: 10



999/999/999 TOTAL VEHICLE

Activity Note:

Light Duty PMI

Reason for Repair:

08 - Preventive Maintenance

Work Accomplished: -

Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
17-Mar-20	Gaspard, Ronald	0.83	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.83	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 20



999 TOTAL VEHICLE

Activity Note:

PM A

Reason for Repair:

08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure: -

Activity Comments


Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
17-Mar-20	P9600	FILTER, OIL	1.00	3.45	3.45



WorkOrder

55345 Palm Tran Connection
v 2.2
Page 1 of 9



WorkOrder: 53186021
Invoice Number: 55345-53186021

Client Department:

MRC:	55345M	Equipment:	4839
WO Desc:			GRAND CARAVAN SE
PM A		VIN:	2C7WDGBG0ER476573
Requested By:	DARTHURS	Status:	40
Created By:	DARTHURS	Priority:	1
Class:	WO	Driver:	
Arrangement:	Unassigned	Phone:	
Potential Warranty:	No	ETA:	

Chronology

Reported	Feb 17, 2020	3:11 PM
Started	Feb 17, 2020	
Completed	Feb 17, 2020	9:17 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	200,141	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: Vehicle came in for service CAUSE: time for service CORRECTION: Service complete. 6 quarts. Oil to engine on filter. Part# 9600

Activity: 10



999/999/999 TOTAL VEHICLE

Activity Note: Light Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
17-Feb-20	P9600	FILTER, OIL	1.00	3.45	3.45

Labor Posted

Date	Technician	Hours	Rate	Extended
17-Feb-20	Junior Hurst	1.62	0.00	0.00

Activity 10 Sub Total

Parts:	3.45
Labor:	0.00
Labor Hours: 1.62	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	3.45

Activity: 20



999 TOTAL VEHICLE

Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued


Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------



WorkOrder

55345 Palm Tran Connection
v 2.2

Page 1 of 9



WorkOrder: 53087484

Invoice Number: 55345-53087484

Client Department:

MRC:

55345M

Equipment:

4839

WO Desc:

GRAND CARAVAN SE

PM C

VIN:

2C7WDGBG0ER476573

Requested By:

DARTHURS

Status:

40

Created By:

DARTHURS

Priority:

1

Class:

WO

Driver:

Phone:

Arrangement:

Unassigned

ETA:

Potential Warranty:

No

Chronology

Reported	Jan 15, 2020	10:34 AM
Started	Jan 15, 2020	
Completed	Jan 15, 2020	9:17 PM

Down Time

Meter	Reading	UOM
WO		DH
Life	195,789	DH

WorkOrder Notes

Line	Comment
10	Perform PMC Service. Change Oil & Filter .lube all Pivoting Points . Check brakes Parts # P9600 Qty (1) Oil 5W20QTY (5.5) Qt

Activity: 10



999/999/999 TOTAL VEHICLE

Activity Note:

Light Duty PMI

Reason for Repair:

08 - Preventive Maintenance

Work Accomplished:

-

Part Failure:

-

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
15-Jan-20	Arthurs,Durvin	1.35	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 1.35	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 20



999 TOTAL VEHICLE

Activity Note:

PM C

Reason for Repair:

08 - Preventive Maintenance

Work Accomplished:

C - PM Level C

Part Failure:

-

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
15-Jan-20	P9600	FILTER, OIL SAME AS 68191349AA	1.00	3.45	3.45

Labor Posted



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 9



WorkOrder: 52698348
Invoice Number: 55345-52698348

Client Department:

MRC: 55345M
WO Desc: PM A
Requested By: DARTHURS
Created By: DARTHURS
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 4839
VIN: GRAND CARAVAN SE
2C7WDGBG0ER476573
Status: 40
Priority: 1
Driver:
Phone:
ETA:

Chronology		
Reported	Oct 4, 2019	12:00 AM
Started	Oct 6, 2019	
Completed	Oct 6, 2019	7:00 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	187,046	DH
System	187,302	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PMA Service CAUSE: Service due by Mileage. CORRECTION: Change Oil & Filter Lube all Pivoting Points . Check brakes. Parts# P9600 Qty (1) Oil 5W20 Qty (5.5) Qt

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
06-Oct-19	Arthurs,Durvin	1.00	65.00	65.00

Activity 10 Sub Total

Parts: 0.00
Labor: 65.00
Labor Hours: 1.00
Sublet Parts: 0.00
Sublet Labor: 0.00
Activity Sub Total 65.00

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
06-Oct-19	P9600	FILTER, OIL SAME AS 68191349AA	1.00	3.45	3.45

**WorkOrder**55345 Palm Tran Connection
v 2.2

Page 1 of 9

**WorkOrder: 52866734****Invoice Number: 55345-52866734****Client Department:****MRC:**

55345M

Equipment:

4839

WO Desc:

GRAND CARAVAN SE

PM A

2C7WDGBG0ER476573

Requested By:

DARTHURS

VIN:

40

Created By:

DARTHURS

Status:

1

Class:

WO

Driver:**Arrangement:**

Unassigned

Phone:**Potential Warranty:**

No

ETA:**Chronology**

Reported	Dec 11, 2019	2:26 PM
Started	Dec 11, 2019	
Completed	Dec 11, 2019	8:09 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	191,435	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PMA Service. CAUSE: Service Due by Mileage. CORRECTION: Change Oil & Filter, Lube All Pivoting Points. Check Brakes. Replace cabin air filter. Parts # P9600 Qty (1) Parts #PA10030 Qty (1)

Activity: 10**999/999/999 TOTAL VEHICLE****Activity Note:**

Light Duty PMI

Reason for Repair:

08 - Preventive Maintenance

Work Accomplished:

-

Part Failure:

-

Activity Comments**Parts Issued**

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
11-Dec-19	Arthurs,Durvin	1.45	65.00	94.25

Activity 10 Sub Total

Parts:	0.00
Labor:	94.25
Labor Hours: 1.45	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	94.25

Activity: 20**999 TOTAL VEHICLE****Activity Note:**

PM A

Reason for Repair:

08 - Preventive Maintenance

Work Accomplished:

A - PM Level A

Part Failure:

-

Activity Comments**Parts Issued**

Date	Part Number	Description	Qty.	Each	Extended
11-Dec-19	P9600	FILTER, OIL SAME AS 68191349AA	1.00	3.45	3.45

**WorkOrder**55345 Palm Tran Connection
v 2.2

Page 1 of 9

**WorkOrder: 52615809****Invoice Number: 55345-52615809****Client Department:****MRC:** 55345M**WO Desc:**

PM B

Requested By:

DARTHURS

Created By:

DARTHURS

Class:

WO

Arrangement:

Unassigned

Potential Warranty:

No

Equipment:

4839

VIN:GRAND CARAVAN SE
2C7WDGBG0ER476573**Status:**

40

Priority:

1

Driver:**Phone:****ETA:**

Chronology		
Reported	Aug 16, 2019	12:52 PM
Started	Aug 16, 2019	
Completed	Aug 16, 2019	11:44 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	182,477	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: Perform PMB Service CAUSE: Service due by Mileage. CORRECTION: Change Oil & Filter .Lube all Pivoting Points. Check Brakes . Parts# P9600 Qty (1) Oil 5W20 Qty (5.5) Qt

Activity: 10**999 TOTAL VEHICLE****Activity Note:**

Light Medium Duty PMI

Reason for Repair:

08 - Preventive Maintenance

Work Accomplished:

06 - Inspect

Part Failure:

-

Activity Comments**Parts Issued**

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
16-Aug-19	Arthurs,Durvin	2.00	65.00	130.00

Activity 10 Sub Total

Parts:	0.00
Labor:	130.00
Labor Hours: 2.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	130.00

Activity: 20**999 TOTAL VEHICLE****Activity Note:**

PM B

Reason for Repair:

08 - Preventive Maintenance

Work Accomplished:

B - PM Level B

Part Failure:

-

Activity Comments**Parts Issued**

Date	Part Number	Description	Qty.	Each	Extended
16-Aug-19	P9600	FILTER, OIL SAME AS 68191349AA	1.00	3.45	3.45



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 9



WorkOrder: 52454999
Invoice Number: 55345-52454999

Client Department:

MRC: 55345M
WO Desc: PM A
Requested By: RGASPARD
Created By: RGASPARD
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 4839
VIN: GRAND CARAVAN SE
2C7WDGBG0ER476573
Status: 40
Priority: 1
Driver:
Phone:
ETA:

Chronology		
Reported	Jul 17, 2019	9:48 AM
Started	Jul 18, 2019	
Completed	Jul 18, 2019	4:51 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	178,444	DH
System	178,444	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: Perform PMA Service CAUSE: Service due by Mileage CORRECTION: Change Oil & Filter. Lube all Pivoting Points . Check brakes Parts # P9600 Qty. (1) Oil 5W20 Qty (5.5) Qt

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
18-Jul-19	Arthurs,Durvin	1.00	65.00	65.00

Activity 10 Sub Total

Parts: 0.00
Labor: 65.00
Labor Hours: 1.00
Sublet Parts: 0.00
Sublet Labor: 0.00
Activity Sub Total 65.00

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
18-Jul-19	P9600	FILTER, OIL SAME AS 68191349AA	1.00	3.45	3.45

**WorkOrder**55345 Palm Tran Connection
v 2.2

Page 1 of 9

**WorkOrder: 52305772****Invoice Number: 55345-52305772****Client Department:**

MRC: 55345M
WO Desc: PM A
Requested By: RRENE
Created By: RRENE
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 4839
VIN: GRAND CARAVAN SE
2C7WDGBG0ER476573
Status: 40
Priority: 1
Driver:
Phone:
ETA:

Chronology		
Reported	May 22, 2019	11:05 AM
Started	May 22, 2019	
Completed	May 23, 2019	12:04 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	173,826	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT:pmA CAUSE: Service CORRECTION:Perform pmA Service Oil filter P9600 Qty1 Engine oil 5 Qts

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments**Parts Issued**

Date	Part Number	Description	Qty.	Each	Extended
------	-------------	-------------	------	------	----------

Labor Posted

Date	Technician	Hours	Rate	Extended
22-May-19	Gaspard,Ronald	1.00	65.00	65.00

Activity 10 Sub Total

Parts: 0.00
Labor: 65.00
Labor Hours: 1.00
Sublet Parts: 0.00
Sublet Labor: 0.00
Activity Sub Total 65.00

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments**Parts Issued**

Date	Part Number	Description	Qty.	Each	Extended
22-May-19	P9600	FILTER, OIL SAME AS 68191349AA	1.00	3.45	3.45