Palm Beach County Fleet Management Asset Maintenance History 10207077 2018 HONDA TRX420FA Atv, 4X4

Total Hours: 66.00 Labor: 4,534.00	Parts: 1,085.17	Comm: 0.00		Charged	d: 5619.17	
Work Order: 1800785 Me Problem: pre delivery inspection	eter: 0		In Date:	01/23/2018	Closed:	02/01/2018
Work Completed		Parts Issued			Qı	uantity
- pre delivery inspection		Shop Supplies				1.00
- Shop Supplies						
Hours: 2.00	Comm: 0.00	Labor: 120.00	Parts: 2.0	0	Total:	122.00
Work Order: 1802025 Me Problem: add switch and harness for	eter: 1 or drip torch		In Date:	02/22/2018	Closed:	03/07/2018
Work Completed		Parts Issued			Qı	uantity
- fab and install wiring harness for sw	itch and drip torch	Trailer Connect Kit				1.00
- fab and install mounting plate for 12	2 volt accessories	Toggle Switch				1.00
- Shop Supplies		Fuse Holder				1.00
		Fab Loom-split Poly				8.00
		Shop Supplies				1.00
Hours: 14.00	Comm: 0.00	Labor: 840.00	Parts: 21.	40	Total:	861.40
Work Order: 1808885 Me Problem: pm service	eter: 16		In Date:	08/28/2018	Closed:	09/10/2018
Work Completed		Parts Issued			Qı	uantity
- pm service		10-30 Synthetic Mcy	/cl			4.00
- Shop Supplies		oil filter				1.00
		Shop Supplies				1.00
Hours: 4.00	Comm: 0.00	Labor: 240.00	Parts: 68.	92	Total:	308.92

- service rear differential

Hours: 6.00

- wash atv

- Shop Supplies

Palm Beach County Fleet Management Asset Maintenance History 10207077 2018 HONDA TRX420FA Atv, 4X4

Work Order: 1903596 Problem: pm service	Meter: 31		In Date:	04/02/2019	Closed:	04/08/2019
Work Completed		Parts Issued			Qı	uantity
- Pm Service		Oil Filter				1.00
- Shop Supplies		10w30 4stroke Gn4				4.00
		Spark Plug				1.00
		Shop Supplies				1.00
Hours: 4.00	Comm: 0.00	Labor: 268.00	Parts: 53.	55	Total:	321.55
Work Order: 2000158 Problem: pm service	Meter: 48		In Date:	01/07/2020	Closed:	01/29/2020
Work Completed		Parts Issued			Qı	uantity
- pm service		Oil Filter				1.00
- service winch		10w30 4stroke Gn4				4.00
- replace right front axle boot		Spark Plug				1.00
- Shop Supplies		Boot Set				1.00
		Boot Set				1.00
		Shop Supplies				1.00
Hours: 6.00	Comm: 0.00	Labor: 438.00	Parts: 334	1.63	Total:	772.63
Work Order: 2008323 Problem: pm service	Meter: 93		In Date:	08/20/2020	Closed:	09/01/2020
Work Completed		Parts Issued			Qı	uantity
- pm service		Oil Filter				1.00

10w30 4stroke Gn4

Parts: 63.91

Gear Oil

Comm: 0.00

Shop Supplies

Labor: 438.00

4.00

1.00

1.00

Total: 501.91

Palm Beach County Fleet Management Asset Maintenance History 10207077 2018 HONDA TRX420FA Atv, 4X4

Work Order: 2010263 Meter: 93 In Date: 10/13/2020 Closed: 10/21/2020

Problem: needs fuel cap

 Work Completed
 Parts Issued
 Quantity

 - secure fuel cap
 Fuel Cap
 1.00

 - Shop Supplies
 Shop Supplies
 1.00

 Hours: 0.50
 Comm: 0.00
 Labor: 36.50
 Parts: 19.39
 Total: 55.89

Work Order: 2103688 Meter: 112 In Date: 03/31/2021 Closed: 04/23/2021

Problem: PM Service - Thank you.

Quantity **Work Completed Parts Issued** 4.00 10w30 4stroke Gn4 - Preventive Maint. Service Oil Filter 1.00 - Shop Supplies 1.00 Spark Plug **Shop Supplies** 1.00 Hours: 4.00 Comm: 0.00 Labor: 292.00 Total: 348.23 Parts: 56.23

Work Order: 2110980 Meter: 115 In Date: 10/12/2021 Closed: 11/12/2021

Problem: PM Service./ see comments

Work Completed		Parts Issued		Quantity
- Preventive Maint. Service		10w30 4stroke Gn	4	4.00
- wash n under coat		Oil Filter		1.00
- service - check over transmission		Rubberized Under	rcoat	2.00
- Shop Supplies		Raptor 2k Aero Bla	ack	2.00
		Shop Supplies		1.00
Hours: 6.00	Comm: 0.00	Labor: 438.00	Parts: 123.22	Total: 561.22

Palm Beach County Fleet Management Asset Maintenance History 10207077 2018 HONDA TRX420FA Atv, 4X4

Work Order: 2200988 Meter: 119 In Date: 01/27/2022 Closed: 03/10/2022

Problem: Transmission is not shifting properly.

Work Completed	Parts Issued	Quantity
- Check Transmission Not Shifting Properly, Remove Shift Motor, Free Up	O2 Sensor	1.00
Brushes, Clean Armeture And Lube Bearings. Re-install And Test Run	Shop Supplies	1.00
Equipment	Freight Charge	1.00

- Free Up Rear Brake Pedal
- Repaired Pull Cord
- Chech Engine Light Is On, Code 23 Is Stored, Test And Replaced Faulty O2 Sensor
- Shop Supplies

Hours: 6.50 Comm: 0.00 Labor: 474.50 Parts: 62.98 Total: 537.48

Work Order: 2207329 Meter: 134 In Date: 07/13/2022 Closed: 08/25/2022

Problem: PM Service.

Work Completed		Parts Issued		Quantity	
- Preventive Maint. Service		10w30 4stroke Gn	4	4.00	
- Service Winch, Replace Clevis Hook		Oil Filter		1.00	
- Replace Nutserts For Drip Tiurch Mount		Spark Plug		1.00	
- Shop Supplies		High Gloss Coatin	g	1.00	
		Clevis Slip Hk W L	tch	1.00	
		Shop Supplies		1.00	
Hours: 5.00	Comm: 0.00	Labor: 365.00	Parts: 70.21	Total: 435.21	
	N. 4 400		L D 4 00/40/00	200 01 1 10/04/00	

Work Order: 2209480 Meter: 138 In Date: 09/12/2022 Closed: 10/31/2022

Problem: ATV WOULD NOT SHIFT INTO DRIVE.

Work Completed		Parts Issued		Quantity
- found atv in manual mode - switched to auto a	and test drove - no	Shop Supplies		1.00
problems found				
- Shop Supplies				
Hours: 1.00	Comm: 0.00	Labor: 73.00	Parts: 2.65	Total: 75.65

Palm Beach County Fleet Management Asset Maintenance History 10207077 2018 HONDA TRX420FA Atv, 4X4

Work Order: 2301375 Meter: 142 In Date: 02/10/2023 Closed: 02/21/2023

Problem: HONDA ATV REPORTED DEAD BATTERY/ PM

Work Completed			Parts Issued		Quantity
- Pm service			Spark Plug		1.00
- test and replace batter	ry		High Gloss Coating	J	1.00
- Shop Supplies			Oil Filter		1.00
			10w30 4stroke Gn4	1	4.00
			Battery		1.00
			Shop Supplies		1.00
Нос	urs: 5.00	Comm: 0.00	Labor: 365.00	Parts: 206.10	Total: 571.10

Work Order: 2304044 Meter: 142 In Date: 04/25/2023 Closed: 04/25/2023

Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 0.00 Total: 146.00

Total Hours: 66.00 Total Labor: 4,534.00 Total Comm: 0.00 Total Parts: 1,085.17