

6/9/2023
5:17:02 PM

Palm Beach County Fleet Management Asset Maintenance History
L00733 2009 FORD F350 Utility Body, 1 Ton, Crewcab

Total Hours: 395.00 Labor: 25,463.95 Parts: 28,938.39 Comm: 5,784.36 Charged: 60186.70

Work Order: 941044 **Meter:** 0 **In Date:** 07/21/2009 **Closed:** 07/21/2009
Problem: Pre Delivery Inspection

Work Completed

- Pre Delivery Inspection

Hours: 4.00 Comm: 0.00 Labor: 240.00 Parts: 0.00 Total: 240.00

Work Order: 1000927 **Meter:** 4322 **In Date:** 01/26/2010 **Closed:** 02/04/2010
Problem: P.M service.

Work Completed

- P.m service.
- Replace missing fire extinguisher bracket.
- Replace missing front lower air spoiler.
- Repair R/r outer tire, nitro service all six tires.
- Alignment.
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
7312 Oil Filterfrm Ch9549 Wix 57312	1.00
Cs10263 Fuel Filter (use Cs10263a)	1.00
15/40 Oil	15.00
Air Deflector	1.00
31-20 Wiper Blades 20" Blade	2.00
Used Firex Refurbed Fire Extingshers	1.00
Custom5lb Bracket Firex Stock #340060300	1.00
Floor Mats / 001382r01	2.00

Hours: 10.00 Comm: 0.00 Labor: 600.00 Parts: 376.91 Total: 976.91

Work Order: 1004567 **Meter:** 5575 **In Date:** 05/03/2010 **Closed:** 05/03/2010
Problem: NO START

Work Completed

- From: 3700 Belvedere Rd-bldg E To: Lv Shop

Hours: 0.00 Comm: 78.00 Labor: 0.00 Parts: 0.00 Total: 78.00

6/9/2023
5:17:02 PM

Palm Beach County Fleet Management Asset Maintenance History
L00733 2009 FORD F350 Utility Body, 1 Ton, Crewcab

Work Order: 1105903 **Meter:** 12981 **In Date:** 06/03/2011 **Closed:** 06/23/2011

Problem: Pm service and install Inverter see notes.

Work Completed

- P.m. Service.
- Test battery and charging system.charge and retest batteries, one failed load test.replace defective battery.
- Replace two tires,rotate and balance all six.
- Install costomer supplied inverter.fabricate and install bracket and wiring.
- Diagnose and repair center brake light circuit.
- Shop Supplies

Parts Issued

Quantity

Pm-22-a Additive Diesel Fuel (m/craft)	1.00
Shop Supplies	1.00
7312 Oil Filterfrm Ch9549 Wix 57312	1.00
Cs10263 Fuel Filter (use Cs10263a)	1.00
15/40 Oil	15.00
31-20 Wiper Blades 20" Blade	2.00
Group 65 Battery (mtc Bxt-65-850)	1.00
Cs2rv Red Cable 2 Gauge	30.00
Cs2l Black Cable 2 Gauge	10.00
Circuit Breaker	2.00
179636492 Lt245/75r17 Wrangler Sr-a E	2.00
Tire Disposal Fee	2.00

Hours: 13.50

Comm: 0.00

Labor: 810.00

Parts: 981.55

Total: 1,791.55

Work Order: 1109519 **Meter:** 14361 **In Date:** 08/16/2011 **Closed:** 09/06/2011

Problem: damage to lft rear bin door, rear bumper, rgt frt bin door & rgt fender

Work Completed

- damage to lft rear bin door, rear bumper, rgt frt bin door & rgt fender

Hours: 0.00

Comm: 1,903.20

Labor: 0.00

Parts: 0.00

Total: 1,903.20

6/9/2023
5:17:02 PM

Palm Beach County Fleet Management Asset Maintenance History
L00733 2009 FORD F350 Utility Body, 1 Ton, Crewcab

Work Order: 1300407 **Meter:** 25647 **In Date:** 01/11/2013 **Closed:** 01/24/2013
Problem: P.M. service.

Work Completed

- P.m. Service.
- Replace missing pintle pin.
- Test batteries and charging system.recharge and retest batteries,both failed.replace defective batteries.
- Replace and balance six new tires.
- Install adjustable cam/caster bushings.perform wheel alignment and test drive.
- Shop Supplies

Parts Issued

Quantity

15-40 Oil	15.00
Oil Filter	1.00
Napagold Fuel Filter	1.00
Pm-22-a Additive Dies	1.00
8c3z9a343a Seal Kit	1.00
31-20 Wiper Blades 20	2.00
Used Firex Refurbed F	1.00
18410 Pintle Pin	1.00
Battery 65	2.00
179636492 Lt245-75r17	6.00
Tr416 Valve Stem	6.00
Caster-camber Bushing	1.00
Shop Supplies	1.00
Tire Disposal Fee	6.00

Hours: 12.75

Comm: 0.00

Labor: 765.00 Parts: 2,001.46 Total: 2,766.46

Work Order: 1307884 **Meter:** 29795 **In Date:** 08/07/2013 **Closed:** 08/21/2013
Problem: Pm service

Work Completed

- P.m. Service.
- Diagnose check engine light.p1178,p2084,p20e3.replace three exhaust temp sensors.clear codes and test drive.
- Rotate and balance all six tires.
- Shop Supplies

Parts Issued

Quantity

15-40 Oil	15.00
Napagold Oil Filter	1.00
Napagold Fuel Filter	1.00
31-20 Wiper Blades 20	2.00
exhaust sensor	3.00
Shop Supplies	1.00

Hours: 9.50

Comm: 0.00

Labor: 570.00 Parts: 298.69 Total: 868.69

6/9/2023
5:17:02 PM

Palm Beach County Fleet Management Asset Maintenance History
L00733 2009 FORD F350 Utility Body, 1 Ton, Crewcab

Work Order: 1311441 **Meter:** 31464 **In Date:** 11/13/2013 **Closed:** 11/25/2013
Problem: Right rear tire flat.

Work Completed

- Repair and balance right rear tire.
- Shop Supplies

Parts Issued

Quantity

Shop Supplies 1.00

Hours: 1.00 Comm: 0.00 Labor: 60.00 Parts: 2.00 Total: 62.00

Work Order: 1402761 **Meter:** 33880 **In Date:** 03/21/2014 **Closed:** 03/28/2014
Problem: Pm service and check belt.

Work Completed

- Perform pm service.
- Inspect and replace failed serpentine belt and tensioner with new..pressure test cooling system.replace failed upper and lower radiator hoses with new.reverse flush and renew engine coolant.
- Test and replace failed left Led brake lamp and both interior dome lamp bulbs with new.
- Replace missing hitch pintle pin with new and secure.
- Rotate and balance all six tires.
- Shop Supplies

Parts Issued

Quantity

15-40 Oil 15.00
Napagold Oil Filter 1.00
Fuel Filter Ford Only 1.00
Wiper Blade 2.00
Napagold Air Filter 1.00
Curved Radiator Hose 1.00
Curved Radiator Hose 1.00
Radiator Hose 1.00
Coolant Ford Gold 3.00
44202r Tail Light 4in 1.00
Bulb 1.00
Pintle Pin W/chain 1.00
Used Fire X Refurbished 1.00
Curved Radiator Hose 1.00
Drive Belt 1.00
Belt Tensioner 1.00
Shop Supplies 1.00

Hours: 11.30 Comm: 0.00 Labor: 678.00 Parts: 740.29 Total: 1,418.29

6/9/2023
5:17:02 PM

Palm Beach County Fleet Management Asset Maintenance History
L00733 2009 FORD F350 Utility Body, 1 Ton, Crewcab

Work Order: 1405999 **Meter:** 35315 **In Date:** 06/18/2014 **Closed:** 06/25/2014
Problem: Right front tire flat.Side wall damage.

Work Completed

- Replace damage right front tire with tire from fleet storage rack.nitrogen fill and balance same.
- Shop Supplies

Parts Issued

	Quantity
Shop Supplies	1.00
Lt245/75r17 Tire	1.00

Hours: 0.50 Comm: 0.00 Labor: 30.00 Parts: 150.50 Total: 180.50

Work Order: 1411387 **Meter:** 37458 **In Date:** 11/14/2014 **Closed:** 12/10/2014
Problem: Pm service.Check AC and strobe lights inop.

Work Completed

- Pm service.
- Replace defective one side marker lamp and left front strobe lamp bulb.
- Ac performance and leak test.evacuate system.replace leaking ac evaporator,accumulator and orifice tube.also replace blower resistor.vacuum and recharge system to specs.
- Rotate and balance all six tires.
- Shop Supplies

Parts Issued

	Quantity
15-40 Oil	15.00
Napagold Oil Filter	1.00
Fuel Filter Ford Only	1.00
Stg Wheel Cov - Ford	1.00
Wiper Blade	2.00
Led M C Lamp	1.00
Hide Away Strob	1.00
Blower Resistor	1.00
Evaporator Core	1.00
Accumulator	1.00
Orifice Tube	1.00
R134a Lv Shop 2	2.00
E8 A/c Oil Univ W Dye	1.00
Rapid Seal Kit	1.00
Shop Supplies	1.00

Hours: 18.75 Comm: 0.00 Labor: 1,125.00 Parts: 491.09 Total: 1,616.09

6/9/2023
5:17:02 PM

Palm Beach County Fleet Management Asset Maintenance History
L00733 2009 FORD F350 Utility Body, 1 Ton, Crewcab

Work Order: 1505818 **Meter:** 39974 **In Date:** 06/10/2015 **Closed:** 06/18/2015
Problem: P.M. Service

Work Completed

- Pm service.
- Replace broken cup holder on center of dash panel.
- Replace and balance all six tires.
- Replace burnt out left rear Led brake lamp and strobe lamp bulbs.
- Replace both front body mounts.
- Complete front end alignment and road test.
- Shop Supplies

Parts Issued

Quantity

15-40 Oil	15.00
Napagold Oil Filter	1.00
Fuel Filter Ford Only	1.00
Wiper Blade	2.00
Used Fire X Refurbished	1.00
179636492 Lt245-75r17	6.00
Led Sup Mdl 44 42 Dio	1.00
Body Mount Kit	2.00
Holder	1.00
Hide Away Strob	1.00
Shop Supplies	1.00
Tire Disposal Fee	6.00

Hours: 13.25

Comm: 0.00

Labor: 795.00

Parts: 2,100.49

Total: 2,895.49

Work Order: 1508316 **Meter:** 41022 **In Date:** 08/19/2015 **Closed:** 08/25/2015
Problem: Dead battery

Work Completed

- Charge batteries fully.test batteries and charging system.replace both defective batteries.
- Shop Supplies

Parts Issued

Quantity

Battery	4.00
Battery 65	2.00
Shop Supplies	1.00

Hours: 2.00

Comm: 0.00

Labor: 120.00

Parts: 768.32

Total: 888.32

Work Order: 1510357 **Meter:** 41698 **In Date:** 10/13/2015 **Closed:** 10/20/2015
Problem: Cleaning exhaust filter warning light on dash.

Work Completed

- Computer diagnose cleaning exhaust filter message on dash.perform force regen.and reset diesel particulate settings.reprogram Pcm with updated calibration.test drive.
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
---------------	------

Hours: 3.00

Comm: 0.00

Labor: 180.00

Parts: 2.00

Total: 182.00

6/9/2023
5:17:02 PM

Palm Beach County Fleet Management Asset Maintenance History
L00733 2009 FORD F350 Utility Body, 1 Ton, Crewcab

Work Order: 1512574 **Meter:** 42626 **In Date:** 12/14/2015 **Closed:** 12/30/2015
Problem: Pm service.

Work Completed

- Pm service.
- Rotate and balance all six tires.
- Shop Supplies

Parts Issued

Quantity

15-40 Oil	15.00
Napagold Oil Filter	1.00
Fuel Filter Ford Only	1.00
20" Wiper Blade	2.00
Shop Supplies	1.00

Hours: 5.50

Comm: 0.00

Labor: 330.00

Parts: 145.63

Total: 475.63

Work Order: 1605259 **Meter:** 44801 **In Date:** 05/20/2016 **Closed:** 05/24/2016
Problem: wont fuel

Work Completed

- Test and Remove Canceiver issue fuel card
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
---------------	------

Hours: 1.00

Comm: 0.00

Labor: 60.00

Parts: 2.00

Total: 62.00

6/9/2023
5:17:02 PM

Palm Beach County Fleet Management Asset Maintenance History
L00733 2009 FORD F350 Utility Body, 1 Ton, Crewcab

Work Order: 1605399

Meter: 45464

In Date: 05/25/2016 **Closed:** 07/12/2016

Problem: P.M. service and check lights and check idle and brakes.see list.

Work Completed

- P.m. Service.
- Replace rear marker light bar on utility body.replace right rear marker light,right brake lamp and tag lamp.
- Replace upper and lower ball joints on both sides.
- Scan for codes.egr codes present.clean injectors and induction and Egr system.clear codes.
- Replace left front camber caster adjuster bushing.complete wheel alignment.test drive.
- R&r Dpf filter and power clean.perform forced regen.
- Straighten locking rods on left rear bin.lube locks and hinges.
- Rotate and balance all six tires.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
15-40 Oil	15.00
Fuel Filter Ford Only	1.00
20" Wiper Blade	2.00
Led Id Bar 6 Ctrs	1.00
Led Sup Mdl 44 42 Dio	1.00
M C Base Mount Kit	1.00
License Bracket W/light	1.00
Rpl Bulb	1.00
Upper Ball Joint	2.00
Lower Ball Joint	2.00
Wheel Seal - Front Wheel	2.00
Injector Cleaner	1.00
Intake Cleaner Kit	1.00
Exha	1.00
Dpkq7 Egr Service Kit	1.00
Kq22932df Diesel Inje	1.00
Caster-camber Bushing	1.00
Exha	1.00
Shop Supplies	1.00

Hours: 29.00

Comm: 0.00

Labor: 1,740.00

Parts: 1,079.74

Total: 2,819.74

6/9/2023
5:17:02 PM

Palm Beach County Fleet Management Asset Maintenance History
L00733 2009 FORD F350 Utility Body, 1 Ton, Crewcab

Work Order: 1612822 **Meter:** 48044 **In Date:** 12/14/2016 **Closed:** 12/30/2016

Problem: P.M. service and check lights and tires and washers and check front end.

Work Completed

- P.m. Service.
- Replace two tires,rotate and balance all four.install steering wheel cover.
- Replace left brake lamp.repair left utility bedmarker light ground.
- Resurface front brake rotors,replace calipers and pads.flush and bleed system.
- Complete wheel alignment.test drive.
- Shop Supplies

Parts Issued

Quantity

15-40 Oil	15.00
Napagold Oil Filter	1.00
Fuel Filter Ford Only	1.00
Napagold Air Filter	1.00
20" Wiper Blade	2.00
Washer Fluid Concentr	1.00
Stg Wheel Cov - Ford	1.00
Used Fire X Refurbished	1.00
179636492 Lt245-75r17	2.00
4 Led S T T Lamp	1.00
Brake Pads	1.00
Reman Brake Caliper	1.00
Reman Brake Caliper	1.00
Non-chlor Brake Clnr	1.00
B Fluid Dot 3-32oz	1.00
Washer Nozzle	2.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 14.50

Comm: 0.00

Labor: 870.00

Parts: 1,015.46

Total: 1,885.46

Work Order: 1703658 **Meter:** 49631 **In Date:** 04/11/2017 **Closed:** 04/11/2017

Problem: 1 - Key(s) issued

Work Completed

- 1 - Key(s) issued

Hours: 0.30

Comm: 0.00

Parts Issued

Quantity

Duplicate Vehicle Keys	1.00
------------------------	------

Labor: 18.00

Parts: 3.00

Total: 21.00

6/9/2023
5:17:02 PM

Palm Beach County Fleet Management Asset Maintenance History
L00733 2009 FORD F350 Utility Body, 1 Ton, Crewcab

Work Order: 1703680 **Meter:** 49631 **In Date:** 04/11/2017 **Closed:** 04/11/2017
Problem: 1 - Key(s) issued

Work Completed

Parts Issued

Quantity

- 1 - Key(s) issued

Duplicate Vehicle Keys

1.00

Hours: 0.30

Comm: 0.00

Labor: 18.00

Parts: 3.00

Total: 21.00

6/9/2023
5:17:02 PM

Palm Beach County Fleet Management Asset Maintenance History
L00733 2009 FORD F350 Utility Body, 1 Ton, Crewcab

Work Order: 1704456

Meter: 50140

In Date: 05/03/2017 **Closed:** 05/24/2017

Problem: P.M. service and A/C. blows warm and check tires.

Work Completed

- P.m. service.
- Left front headlight inop,r&r sealed beam and install new.left front strobe light inop,r&r with new.right Led tail lamp inop ,r&r with new.
- Rear brakes new pads, service calipers, resurface rear rotors.flush and bleedbrake system.test drive.
- Four new tires mount on front and both resr inner.nitrogen fill and high speed balance all six tires.
- Inspect and service rear differential Both rear axle seals failed .r&r with new.
- Left front lower and upper ball joints failed .r&r with new.replace right side grease cap.
- A/c performance test .evacuate and recharge system. Clean condensor,check for leaks.no leaks found at this time.a?c vlower inop.diagnoise blower motor failed R&r& with new.
- Complete front end alignment .
- Shop Supplies

Parts Issued

Quantity

15-40 Oil	15.00
Napagold Oil Filter	1.00
Fuel Filter Ford Only	1.00
20" Wiper Blade	2.00
Pedal Pad	1.00
Washer Fluid Concentr	1.00
4 Led S T T Lamp	1.00
Halogen Lamp	1.00
Brake Pad	1.00
Non-chlor Brake Clnr	1.00
179636492 Lt245-75r17	4.00
Napa Oil Seal	2.00
75w140 Ford Axle Lube	4.00
Ptex Ultra Grey 3oz	1.00
Friction Modifier	2.00
Upper Ball Joint	1.00
Lower Ball Joint	1.00
Hide Away Strob	1.00
Freon Lv Shop 1	1.00
4 Led S T T Lamp	1.00
Cap	1.00
Fan And Motor	1.00
Shop Supplies	1.00
Tire Disposal Fee	4.00

Hours: 25.20

Comm: 0.00

Labor: 1,512.00

Parts: 1,758.81

Total: 3,270.81

6/9/2023
5:17:02 PM

Palm Beach County Fleet Management Asset Maintenance History
L00733 2009 FORD F350 Utility Body, 1 Ton, Crewcab

Work Order: 1710065 **Meter:** 53308 **In Date:** 10/13/2017 **Closed:** 10/17/2017
Problem: Had to jump start.

Work Completed

- Charge batteries.test batteries and charging system.batteries failed load test.r&r both defective batteries.
- Shop Supplies

Parts Issued

Quantity

Battery	2.00
Shop Supplies	1.00

Hours: 2.00 Comm: 0.00 Labor: 120.00 Parts: 259.28 Total: 379.28

Work Order: 1801792 **Meter:** 56451 **In Date:** 02/15/2018 **Closed:** 02/27/2018
Problem: P.M. service.

Work Completed

- P.m. service.
- Check and replace six defective body mounts.replace front and rear bump stops.
- Pressure test and inspect cooling system .perform engine coolant flush and refill.
- Check .replace transmission filter .flush and refill fluid.
- Check and replace trailer plug connector and fabricate wire as needed.test and replace left side marker light and high mount brake light bulb and tag light assembly.
- Check and replace missing pintle pin with chain.
- Balance and rotate all six tires.
- Shop Supplies

Parts Issued

Quantity

15-40 Oil	15.00
Napagold Oil Filter	1.00
Used Fire X Refurbished	1.00
20" Wiper Blade	2.00
Body Mount Kit	4.00
Body Monuts	2.00
Body Mount	2.00
bumper	2.00
Bumper	2.00
Peak Global Antifrz	2.00
Syn-atf Trans Fluid S	20.00
trailer plug	1.00
M C Base Mount Kit	1.00
Bulb	1.00
License Bracket W/light	1.00
Atp Filter	1.00
Pintle Pin W/clip	1.00
Ford Triton Pvc Swc	1.00
Fuel Filter Ford Only	1.00
Shop Supplies	1.00

Hours: 19.30 Comm: 0.00 Labor: 1,158.00 Parts: 1,014.46 Total: 2,172.46

6/9/2023
5:17:02 PM

Palm Beach County Fleet Management Asset Maintenance History
L00733 2009 FORD F350 Utility Body, 1 Ton, Crewcab

Work Order: 1808790

Meter: 61008

In Date: 08/24/2018 **Closed:** 09/04/2018

Problem: PM Service.

Work Completed

- P.m. service.
- Test and replace right strobe light . Replace defective trailer plug connector and wire as needed. Replace right headlight bulb and tag light .
- Check for squeaking noise while driving.remove rear drive shaft to replace all three u-joints and rear flange. Test drive.
- Replace all six worn tires and balance . Nitrofill all.
- Computer diagnose Abs light , code C1233 . Perform pinpoint test. Replace left front Abs wheel speed sensor . Clear code and retest.
- Complete front end alignment and road test.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
15-40 Oil	15.00
Fuel Filter Ford Only	1.00
20" Wiper Blade	2.00
Blaster Penetrant	1.00
License Bracket W/light	1.00
Hide Away Strob	1.00
Halogen Sealed Beams	1.00
trailer plug	1.00
Tr416 Valve Stem	6.00
179636492 Lt245-75r17	6.00
U Joint	3.00
Sensor Asy	1.00
Flange	1.00
Shop Supplies	1.00
Tire Disposal Fee	6.00

Hours: 18.10

Comm: 0.00

Labor: 1,086.00

Parts: 1,906.07

Total: 2,992.07

6/9/2023
5:17:02 PM

Palm Beach County Fleet Management Asset Maintenance History
L00733 2009 FORD F350 Utility Body, 1 Ton, Crewcab

Work Order: 1903880 **Meter:** 66721 **In Date:** 04/10/2019 **Closed:** 04/16/2019
Problem: P.M. service.

Work Completed

- P.m. service.
- Check and replace front and rear shock absorbers
- Balance and rotate all six tires . Nitrofill all.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
15-40 Oil	15.00
Seal Kit	1.00
Fuel Filter Ford Only	1.00
Used Fire X Refurbished	1.00
20" Wiper Blade	2.00
Napagold Air Filter	1.00
Gas Grande Shock	2.00
Gas Grande Fleet Shoc	2.00
Shop Supplies	1.00

Hours: 7.30

Comm: 0.00

Labor: 489.10

Parts: 475.77

Total: 964.87

Work Order: 1906001 **Meter:** 68410 **In Date:** 06/06/2019 **Closed:** 06/24/2019
Problem: Towed in for stalled then crank and no start.

Work Completed

- Diagnose no start . Remove rear fuel tank to replace sending unit for broken pick up tube . Replace tank slector valve . Bleed fuel system and add fuel to front tank . Test drive .
- Pressure test and inspect cooling system for leaks . R&r leaking radiator , thermostats ,upper radiator hose and both lowwer radiator hoses . Flush and refill cooling system . Test drive .
- Shop Supplies

Parts Issued

Quantity

Selector Valve	1.00
Sender Assembly	1.00
lower hose	1.00
Radiator Hose	1.00
Top Radiator Hose	1.00
Peak Global Antifrz	3.00
Radiator	1.00
Thermostat Kit	1.00
Shop Supplies	1.00

Hours: 14.50

Comm: 0.00

Labor: 971.50

Parts: 2,229.14

Total: 3,200.64

6/9/2023
5:17:02 PM

Palm Beach County Fleet Management Asset Maintenance History
L00733 2009 FORD F350 Utility Body, 1 Ton, Crewcab

Work Order: 1906005 **Meter:** 67994 **In Date:** 06/06/2019 **Closed:** 06/06/2019
Problem: Near fuel pumps, meet Jose there and he will bring driver to vehicle. Vehicle will not start (may be out of diesel fuel)

Work Completed

- Tow From: Pbia Maintenance Compound To: Vista

Hours: 0.00 Comm: 96.00 Labor: 0.00 Parts: 0.00 Total: 96.00

Work Order: 1912797 **Meter:** 72913 **In Date:** 12/13/2019 **Closed:** 12/27/2019
Problem: PM Service

Work Completed

- P.m. service.
- Charge batteries fully . Test batteries . R&r both failed batteries . Retest charging system .
- Test and replace right side marker light assembly .
- Replace and balance all six tires . Nitrofill all.
- Remove cab to raise engine to replace leaking oil pan gasket and pick up seal . Clean excess oil . Top off fluids .
- A/c performance test . Recover system and leak test . Replace leaking high side shrader valve . Evacuate system and complete recharge to factory spec . Retest operation .
- Perform complete front end alignment and road test .
- Shop Supplies

Parts Issued

Quantity

15-40 Oil	15.00
Napagold Oil Filter	1.00
Fuel Filter Ford Only	1.00
20" Wiper Blade	2.00
Ford Triton Pvc Swc	1.00
Battery	2.00
Led M C Lamp	1.00
Lt245/75r17 Mich Defend Ltx	6.00
Gasket	1.00
Gasket	1.00
Big G Degreaser 1 Gal	1.00
Coolant Ford Gold	1.00
Ac Valve Core High	1.00
Freon Lv Shop 1	2.00
Shop Supplies	1.00
Tire Disposal Fee	6.00

Hours: 35.80 Comm: 0.00 Labor: 2,613.40 Parts: 2,076.24 Total: 4,689.64

6/9/2023
5:17:02 PM

Palm Beach County Fleet Management Asset Maintenance History
L00733 2009 FORD F350 Utility Body, 1 Ton, Crewcab

Work Order: 2005131 **Meter:** 78535 **In Date:** 05/21/2020 **Closed:** 09/08/2020
Problem: P.M. service ,check engine light , LED lights inop and headlight inop .

Work Completed

Parts Issued

Quantity

- P.m. Service.
- Test battery and charging system.replace defective alternator and drive belt.retest system.
- Diagnose inop strobe light.trace and repair open circuit.left seal beam has water.replace headlight.
- Replace corroded trailer plug and rewire.replace missing pintle pin.
- Rotate and and balance all six tires.
- Transport vehicle to dealer for high pressure pump replacement.
- Excessivde play in steering linkage.replace center link and pittmam arm.
- Complete wheel alignment.test drive.
- Shop Supplies

Napagold Oil Filter	1.00
15-40 Oil	15.00
Napagold Air Filter	1.00
Fuel Filter Ford Only	1.00
22" Wiper Blade	2.00
Washer Fluid Concentr	1.00
Used Fire X Refurbished	1.00
Halogen Sealed Beams	1.00
Pintle Pin W/clip	1.00
Drive Belt	1.00
Alternator	1.00
trailer plug	1.00
Tir Rod Assy	1.00
Arm	1.00
Shop Supplies	1.00

Hours: 18.15

Comm: 3,170.46

Labor: 1,324.95

Parts: 1,042.15

Total: 5,537.56

Work Order: 2101399 **Meter:** 82180 **In Date:** 02/05/2021 **Closed:** 02/16/2021
Problem: PM Service

Work Completed

Parts Issued

Quantity

- Preventive Maint. Service
- Rotate and balance all six wheels and tires. Nitrogen fill all tires to 65 psi.
- D.s. headlight full of water. Remove and replace both front headlights with new. Reinstall both lights. install new supporting rings around lights.
- Shop Supplies

15-40 Oil	15.00
Napagold Oil Filter	1.00
Washer Fluid Concentr	1.00
20" Wiper Blade	2.00
Fuel Filter Ford Only	1.00
H.I. Ret. Ring Kit	2.00
Halogen Sealed Beams	2.00
Shop Supplies	1.00

Hours: 6.50

Comm: 0.00

Labor: 474.50

Parts: 211.89

Total: 686.39

6/9/2023
5:17:02 PM

Palm Beach County Fleet Management Asset Maintenance History
L00733 2009 FORD F350 Utility Body, 1 Ton, Crewcab

Work Order: 2101676 **Meter:** 83122 **In Date:** 02/12/2021 **Closed:** 05/06/2021
Problem: replace bumper & vise mount

Work Completed

- Replace Rear Bumpr, Fabricate & Install Vise Mount And New Vise, Apply Nonskid Coating To Rear Bumper And Vise Mount.
- Shop Supplies

Parts Issued

Quantity

Ridgid Vise 6"	1.00
Glos Blk	1.00
Raptor 2k Aero Black	3.00
Bumper	1.00
Shop Supplies	1.00
Freight Charge	1.00

Hours: 10.00

Comm: 0.00

Labor: 730.00 Parts: 1,573.40 Total: 2,303.40

Work Order: 2104220 **Meter:** 83200 **In Date:** 04/14/2021 **Closed:** 05/06/2021
Problem: oil leak

Work Completed

- Remove drive shaft, transmission and flex plate, Replace engine rear main seal. Clean bottom of truck and top of fluid levels . Engine has several oil leaks also needs engine replacement , department declined repair .
- Shop Supplies

Parts Issued

Quantity

Non-chlor Brake Clnr	4.00
Nut	8.00
Gasket	1.00
Seal	1.00
Shop Supplies	1.00

Hours: 6.30

Comm: 0.00

Labor: 459.90 Parts: 118.50 Total: 578.40

Work Order: 2104353 **Meter:** 83151 **In Date:** 04/14/2021 **Closed:** 04/19/2021
Problem: oil leak

Work Completed

- Tow From: airport maint comp To: vista

Hours: 0.00

Comm: 96.00

Labor: 0.00 Parts: 0.00 Total: 96.00

6/9/2023
5:17:02 PM

Palm Beach County Fleet Management Asset Maintenance History
L00733 2009 FORD F350 Utility Body, 1 Ton, Crewcab

Problem: P.M. service and towed in for cranks but NO START

Work Completed

- Preventive Maint. Service Road test
- R & I two new on front, Rotate and speed balance nitro fill all six tires
- Check and R & I Front and Rear brakes, R & I Front and rear rotors, R & I Front & Rear rotor bearing seals, R & I Front and Rear Calipers, R & I, R & I two front Caliper brake hoses, Repack bearings, R & I Front & rear Rotors at minimum Bleed brak
- Perform Ids diagnostic fuel sys Crank no start, Add fuel to Front tank, Bleed air from fuel system. They ran front tank out of fuel before switching .
- Rear body Marker light inop, R & I new lamp
- Perform diagnostic, A / c blower inop, at low speeds, check and r & I new resister and blower motor assembly . Retest
- Shop Supplies

Parts Issued

Quantity

Fuel Filter Ford Only	1.00
Napagold Oil Filter	1.00
15-40 Oil	15.00
Washer Fluid Concentr	1.00
20" Wiper Blade	2.00
Napagold Air Filter	1.00
Lt245/75r17 Mich Defend Ltx	2.00
Brake Pad	1.00
Non-chlor Brake Clnr	1.00
B Fluid Dot 3-32oz	1.00
Brk Fluid Dot 4-32oz	1.00
Fuel Filter	1.00
Rear Brake Caliper	1.00
Rear Brake Caliper	1.00
R /f Caliper	1.00
L /f Caliper	1.00
Brake Hose	1.00
Rear Pads	1.00
Seal	2.00
Brake Hose	1.00
Seal	2.00
Led Id Bar 6 Ctrs	1.00
Rotor Hub Assembly	2.00
Rotor	2.00
Blower Motor Resistor	1.00
Blwer Mtr Assy Flan	1.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 20.20

Comm: 0.00

Labor: 1,474.60

Parts: 2,118.44

Total: 3,593.04

6/9/2023
5:17:02 PM

Palm Beach County Fleet Management Asset Maintenance History
L00733 2009 FORD F350 Utility Body, 1 Ton, Crewcab

Work Order: 2204671 **Meter:** 89441 **In Date:** 04/07/2022 **Closed:** 04/29/2022
Problem: NO START (KEYS IN IGN)

Work Completed

- Tow From: North Of Austrailian Ave Left Turn Right After 95 To: Lv Shop

Hours: 0.00 Comm: 113.00 Labor: 0.00 Parts: 0.00 Total: 113.00

Work Order: 2209894 **Meter:** 92835 **In Date:** 09/22/2022 **Closed:** 10/06/2022
Problem: Bad Oil Leak . P.M. service.

Work Completed

- check,verify oil leak from breather hose,sop,r&r the defective hose by r&i all necessary parts,clean under the car due to oil leakl residue and verify normal operation

- pm service completed

- rotate and balance all tires . Nitro fill all.

- check,replaced both headlight due water condensation

- Shop Supplies

Parts Issued

Quantity

Crank Vent Hose 1.00

Prem Blue 15w40 1 Gal 3.00

20" Wiper Blade 2.00

Napagold Fuel Filter 1.00

Napagold Oil Filter 1.00

Used Fire X Refurbished 1.00

Halogen Sealed Beams 2.00

Big G Degreaser 1 Gal 1.00

Shop Supplies 1.00

Hours: 16.50 Comm: 0.00 Labor: 1,204.50 Parts: 195.02 Total: 1,399.52

Work Order: 2209935 **Meter:** 92727 **In Date:** 09/21/2022 **Closed:** 09/26/2022
Problem: Bad Oil Leak

Work Completed

- Tow From: 3700 Belvedere Rd, Wpb (next to bldg 'e') To: 2601 Vista Pkwy, West Palm Beach 33411(lv Shop)

Hours: 0.00 Comm: 113.00 Labor: 0.00 Parts: 0.00 Total: 113.00

Work Order: 2301950 **Meter:** 95077 **In Date:** 02/28/2023 **Closed:** 03/02/2023
Problem: Batteries keep dying employee coming this morning inspect and replace please.

Work Completed

- Charge batteries fully . Test batteries and charging system . Batteries failed load test . R&r defective batteries and retest .

- Shop Supplies

Parts Issued

Quantity

Battery 2.00

Shop Supplies 1.00

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 333.46 Total: 479.46

6/9/2023
5:17:02 PM

Palm Beach County Fleet Management Asset Maintenance History
L00733 2009 FORD F350 Utility Body, 1 Ton, Crewcab

Work Order: 2302336 **Meter:** 95077 **In Date:** 03/07/2023 **Closed:**
Problem: dead and coolant leak

Work Completed

- Cooling System

Hours: 0.00 Comm: 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00

Work Order: 2302940 **Meter:** 95210 **In Date:** 03/07/2023 **Closed:** 03/22/2023
Problem: dead and coolant leak

Work Completed

- Tow From: Pbia, maintenance compound To: vista

Hours: 0.00 Comm: 124.30 Labor: 0.00 Parts: 0.00 Total: 124.30

Total Hours: 395.00 Total Labor: 25,463.95 Total Comm: 5,784.36 Total Parts: 28,938.39