

6/9/2023
5:19:45 PM

10196043

Palm Beach County Fleet Management Asset Maintenance History
2014 INTERNATIONAL 7400 Dump Truck, 12Yd, 62,000 Gvwr, Steel Body

Total Hours: 451.50 Labor: 29,545.00 Parts: 27,814.77 Comm: 30,619.12 Charged: 87978.90

Work Order: 1411284 **Meter:** 535 **In Date:** 11/12/2014 **Closed:** 11/12/2014
Problem: 1061 - Pre Delivery Inspection

Work Completed

- Pre Delivery Inspection

Hours: 5.00 Comm: 0.00 Labor: 300.00 Parts: 0.00 Total: 300.00

Work Order: 1504237 **Meter:** 7081 **In Date:** 04/24/2015 **Closed:** 04/24/2015
Problem: Mirror bracket

Work Completed

- Repair Mirror

Hours: 0.50 Comm: 0.00 Labor: 30.00 Parts: 0.00 Total: 30.00

Work Order: 1505663 **Meter:** 8509 **In Date:** 06/05/2015 **Closed:** 06/09/2015
Problem: PM

Work Completed

- pm
- replace tag light bracket and light
- Shop Supplies

Parts Issued

Quantity

15-40 Oil	30.00
Napagold Oil Filter	1.00
Napagold Air Filter	1.00
Fuel Fil	1.00
Wiper Blade	2.00
License Lamp	1.00
License Plate Brkt	1.00
Shop Supplies	1.00

Hours: 8.00 Comm: 0.00 Labor: 480.00 Parts: 215.78 Total: 695.78

Work Order: 1505959 **Meter:** 9181 **In Date:** 06/16/2015 **Closed:** 06/16/2015
Problem: Hyd. Oil

Work Completed

- Test dump bed and ck hyd. oil
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
---------------	------

Hours: 1.00 Comm: 0.00 Labor: 60.00 Parts: 2.00 Total: 62.00

6/9/2023
5:19:46 PM

10196043

Palm Beach County Fleet Management Asset Maintenance History
2014 INTERNATIONAL 7400 Dump Truck, 12Yd, 62,000 Gvwr, Steel Body

- repair air leak at fan clutch
- road test
- Shop Supplies

Parts Issued	Quantity
coolent assy tube	1.00
disf rotella	7.00
coolent fiting	1.00
cooling tube	1.00
Ad Ip Dryer Cart	1.00
Bushing	4.00
Snap Ring	1.00
sfty pin	1.00
Brake Drum	2.00
Brake Shoe Kits- New	2.00
Hd Truck Scotseal	2.00
Non-chlor Brake Clnr	4.00
wheel bearing	2.00
axle gasket	2.00
Qt Hp Gear Oil 85-140	3.00
85-140 Gear Oil Gear	40.00
coolent pipe	1.00
Shop Supplies	1.00
Freight Charge	1.00

Hours: 65.00

Comm: 0.00

Labor: 3,900.00

Parts: 2,047.84

Total: 5,947.84

Work Order: 1703825

Meter: 32864

In Date: 04/14/2017 **Closed:** 04/17/2017

Problem: RFIO tires

Work Completed

- Rfio tires

Hours: 0.00

Comm: 1,988.80

Labor: 0.00

Parts: 0.00

Total: 1,988.80

6/9/2023
5:19:46 PM

10196043

Palm Beach County Fleet Management Asset Maintenance History
2014 INTERNATIONAL 7400 Dump Truck, 12Yd, 62,000 Gvwr, Steel Body

Work Order: 1705217 **Meter:** 33600 **In Date:** 05/26/2017 **Closed:** 06/06/2017
Problem: Power steering fluid

Work Completed

Parts Issued

Quantity

- add p/s fluid

Psf Qt

1.00

Hours: 0.50

Comm: 0.00

Labor: 30.00

Parts: 6.84

Total: 36.84

Work Order: 1706609 **Meter:** 34487 **In Date:** 07/06/2017 **Closed:** 07/10/2017
Problem: check coolant

Work Completed

Parts Issued

Quantity

- add coolant

disf rotella

1.00

Hours: 0.50

Comm: 0.00

Labor: 30.00

Parts: 15.68

Total: 45.68

Work Order: 1707091 **Meter:** 34714 **In Date:** 07/20/2017 **Closed:** 07/25/2017
Problem: hard start

Work Completed

Parts Issued

Quantity

- hard start. found lcp low. replace injector seals and ipr valve. replace valve cover gasket

15-40 Oil

2.00

- drain cooling system and flush/bleed

ipr valve kit

1.00

- test run

lcp Sensor

1.00

- Shop Supplies

Seal Kit

1.00

Gasket

1.00

disf rotella

8.00

Cap

1.00

Shop Supplies

1.00

Hours: 26.50

Comm: 0.00

Labor: 1,590.00

Parts: 1,736.53

Total: 3,326.53

6/9/2023
5:19:46 PM

10196043

Palm Beach County Fleet Management Asset Maintenance History
2014 INTERNATIONAL 7400 Dump Truck, 12Yd, 62,000 Gvwr, Steel Body

Work Order: 1708554
Problem: tarp/hitch

Meter: 36300

In Date: 08/30/2017 **Closed:** 09/26/2017

Work Completed

- replace tarp arms and bushings and tarp
- check hitch bolts
- mud flap
- Shop Supplies

Parts Issued

Quantity

Mud Flap - Chevron De	1.00
Trp NI M C 7-6 X 18	1.00
Connect Arm Kit	1.00
Hose Clm	4.00
Tarp Bar	1.00
Cable Tie	1.00
Bushing	2.00
Shop Supplies	1.00

Hours: 5.50

Comm: 0.00

Labor: 330.00

Parts: 338.12

Total: 668.12

Work Order: 1710500
Problem: Wipers

Meter: 37859

In Date: 10/25/2017 **Closed:** 10/31/2017

Work Completed

- replace wiper blades

Parts Issued

Quantity

Wiper Blade	2.00
-------------	------

Hours: 0.50

Comm: 0.00

Labor: 30.00

Parts: 9.42

Total: 39.42

Work Order: 1711702
Problem: trailer hitch pin

Meter: 38847

In Date: 11/30/2017 **Closed:** 12/08/2017

Work Completed

- Replace hitch pin

Parts Issued

Quantity

hitch pin 1/4x3	1.00
-----------------	------

Hours: 0.50

Comm: 0.00

Labor: 30.00

Parts: 1.20

Total: 31.20

Work Order: 1712205
Problem: Coolent

Meter: 39003

In Date: 12/13/2017 **Closed:** 12/22/2017

Work Completed

- Add Coolent
- Shop Supplies

Parts Issued

Quantity

Rotell Elc Antifeerze	2.00
Shop Supplies	1.00

Hours: 0.50

Comm: 0.00

Labor: 30.00

Parts: 32.66

Total: 62.66

6/9/2023
5:19:46 PM

10196043

Palm Beach County Fleet Management Asset Maintenance History
2014 INTERNATIONAL 7400 Dump Truck, 12Yd, 62,000 Gvwr, Steel Body

Work Order: 1809174
Problem: pm

Meter: 46707

In Date: 09/06/2018 **Closed:** 10/02/2018

Work Completed

- Pm
- Service Ac
- Service Air Dryer
- Repair tag light bracket and hitch pin
- Complete tandom brake renew
- Repair Pto leak
- Test run
- Shop Supplies

Parts Issued

Quantity

15-40 Oil	30.00
Napagold Oil Filter	1.00
Napagold Air Filter	1.00
Filter	1.00
Used Fire X Refurbished	1.00
Wiper Blade	2.00
Rotell Elc Antifeerze	2.00
Cabin Air Filter	1.00
Napa Cabin Air Filter	1.00
Ad Ip Dryer Cart	1.00
Pintle Pin W/clip	1.00
License Plate Brkt	1.00
Led Tag Light	1.00
Gfil Gasket	2.00
Hd Truck Scotseal	2.00
Brake Shoe Kits- New	4.00
Brake Drum	4.00
Shop Supplies	1.00

Hours: 27.50

Comm: 0.00

Labor: 1,842.50

Parts: 1,607.21

Total: 3,449.71

Work Order: 1809467
Problem: RFO flat repair

Meter: 46706

In Date: 09/13/2018 **Closed:** 09/19/2018

Work Completed

- Rfo flat repairs

Hours: 0.00

Comm: 78.97

Labor: 0.00

Parts: 0.00

Total: 78.97

6/9/2023
5:19:46 PM

10196043

Palm Beach County Fleet Management Asset Maintenance History
2014 INTERNATIONAL 7400 Dump Truck, 12Yd, 62,000 Gvwr, Steel Body

Work Order: 1909672
Problem: PM

Meter: 50722

In Date: 09/19/2019 **Closed:** 09/26/2019

Work Completed

- Pm
- Service Trans
- Service Ac
- Ps Service
- Replace lights
- Tighten loose drive shaft bolts
- Weld tailgate chain
- Test drive
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
15-40 Oil	30.00
Filter	1.00
Napagold Air Filter	1.00
Washer Fluid Concentr	1.00
Wiper Blade	2.00
Non-chlor Brake Clnr	2.00
Used Fire X Refurbished	1.00
Rotell Elc Antifeerze	2.00
Syn-atf Trans Fluid S	22.00
Napa Trans Filter	1.00
Cabin Air Filter	1.00
Napa Cabin Air Filter	1.00
Psf Qt	1.00
Power Steering Filter	1.00
Led Red Tail Light	2.00
2 Inch M C Lamp	1.00
Shop Supplies	1.00

Hours: 16.50

Comm: 0.00

Labor: 1,105.50

Parts: 588.44

Total: 1,693.94

Work Order: 2001120
Problem: Running hot

Meter: 51113

In Date: 01/31/2020 **Closed:** 02/07/2020

Work Completed

- Add coolant
- Tested for leaks and pulled codes for low coolant
- Test drive
- Shop Supplies

Parts Issued

Quantity

Rotell Elc Antifeerze	2.00
Shop Supplies	1.00

Hours: 3.50

Comm: 0.00

Labor: 255.50

Parts: 34.66

Total: 290.16

6/9/2023
5:19:46 PM

10196043

Palm Beach County Fleet Management Asset Maintenance History
2014 INTERNATIONAL 7400 Dump Truck, 12Yd, 62,000 Gvwr, Steel Body

Work Order: 2004122
Problem: PM

Meter: 51596

In Date: 04/24/2020 **Closed:** 05/07/2020

Work Completed

- Pm
- Service Ac
- Rebuild tarp
- Replace tail light assembly
- Replace batteries
- Repair air leaks
- Test run
- Shop Supplies

Parts Issued

Quantity

15-40 Oil	30.00
Napagold Oil Filter	1.00
Napagold Air Filter	1.00
Filter	1.00
Wiper Blade	2.00
Washer Fluid Concentr	1.00
Non-chlor Brake Clnr	2.00
Used Fire X Refurbished	1.00
Napa Cabin Air Filter	1.00
Cabin Air Filter	1.00
air dryer housing	1.00
Hose Clamp	6.00
Multicolor Pvc Mesh	1.00
Hose Clamp	2.00
Connect Arm Kit	1.00
Swing Arm	2.00
Tarp Bar	1.00
Led Red Tail Light	1.00
Group 31 Stud Delco	2.00
Shop Supplies	1.00

Hours: 19.50

Comm: 0.00

Labor: 1,423.50

Parts: 2,191.81

Total: 3,615.31

Work Order: 2008096
Problem: Tarp chain

Meter: 52526

In Date: 08/14/2020 **Closed:** 08/14/2020

Work Completed

- adjust tarp chain
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
---------------	------

Hours: 1.50

Comm: 0.00

Labor: 109.50

Parts: 4.00

Total: 113.50

6/9/2023
5:19:46 PM

Palm Beach County Fleet Management Asset Maintenance History
10196043 2014 INTERNATIONAL 7400 Dump Truck, 12Yd, 62,000 Gvwr, Steel Body

Work Order: 2101139 **Meter:** 55175 **In Date:** 01/29/2021 **Closed:** 06/16/2021
Problem: There is a picture on the dash of a Motor, Water in the fuel, also When the truck is turned off you can hear air leaking

Work Completed

- Check engine light, Scan for codes, found codes related to major power surge. Located shorted / burned main wiring harness at frame rail. Send to dealer for repair
- Air leaks at tank fill line. Repaired leak at tank fill line and fittings.
- Travel time to International and back.
- Pm Service.
- Service Ac, change cabin air filters, clean evaporator drains.
- Test run.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
15-40 Oil	30.00
Filter	1.00
Napagold Air Filter	1.00
Washer Fluid Concentr	1.00
Wiper Blade	2.00
Used Fire X Refurbished	1.00
Cabin Air Filter	1.00
Napa Cabin Air Filter	1.00
Shop Supplies	1.00

Hours: 16.50

Comm: 0.00

Labor: 1,204.50

Parts: 349.15

Total: 1,553.65

Work Order: 2106510 **Meter:** 55175 **In Date:** 06/15/2021 **Closed:** 06/16/2021
Problem: Replace Wiring harness and repair AC

Work Completed

- Accessories - Electrical

Hours: 0.00

Comm: 14,947.85 Labor: 0.00

Parts: 0.00

Total: 14,947.85

6/9/2023
5:19:46 PM

Palm Beach County Fleet Management Asset Maintenance History
10196043 2014 INTERNATIONAL 7400 Dump Truck, 12Yd, 62,000 Gvwr, Steel Body

Work Order: 2107225 **Meter:** 56050 **In Date:** 07/01/2021 **Closed:** 07/21/2021

Problem: Dist.4 Armando, truck will not start, it is in Roads Yard.

Work Completed

- No start / Check Engine light. Scan for codes. Low lcp while cranking, Spn 3659 Injector close coil open circuit. Spn 3936 Dpf regen occurring too frequently. All injector coils burned. R+r all 6 injectors, lcp sensor and lpr valve. and all O-rings.
- Remove heat exchanger to access valve cover. Drain and refill cooling system.
- Air leak at rear of engine for exhaust actuator. Remove dog house, seat, shifter, floor liner for access. Replace fittings. check for leaks, Ok.
- Spn 3242 Dpfit / Spn 3246 Dpfot out of range high. Remove and replace temp sensors. Check for proper operation with live data. Ok at this time.
- Spn 3719 Fmi 16 Dpf Soot Load Moderate. Preform parked Regeneration. Clear codes. Ok at this time.
- Test run.
- Shop Supplies

Hours: 46.50

Comm: 0.00

Parts Issued

Quantity

injector	6.00
lcp Sensor	1.00
lpr valve kit	1.00
Seal Kit	1.00
Gasket	1.00
New Pig	1.00
Cable Tie	1.00
Rotell Elc Antifeerze	1.00
Rotell Elc Antifeerze	4.00
Sensor Exhaust Temp	1.00
Exhaust Temp Sensor	1.00
16 Pb Ds Penetrant	1.00
Shop Supplies	1.00

Labor: 3,394.50

Parts: 5,734.11

Total: 9,128.61

6/9/2023
5:19:46 PM

Palm Beach County Fleet Management Asset Maintenance History
10196043 2014 INTERNATIONAL 7400 Dump Truck, 12Yd, 62,000 Gvwr, Steel Body

Work Order: 2202738 **Meter:** 58318 **In Date:** 03/11/2022 **Closed:** 04/12/2022

Problem: PM Service. will turn in tomorrow

Work Completed

- Preventive Maint. Service
- a/c service
- air dryer service drop driveshaft carrier bearing for access to remove air dryer
- test run
- power steering service
- replace washer fluid reservoir and pump
- to international
- pull codes , dpf codes turbo underboost , coolant level
- repair by Rechtien. replace boost control solenoid
- Shop Supplies

Parts Issued

Quantity

Napagold Air Filter	1.00
15-40 Oil	30.00
Napagold Oil Filter	1.00
Filter	1.00
Washer Fluid Concentr	1.00
Wiper Blade	2.00
Used Fire X Refurbished	1.00
Non-chlor Brake Clnr	6.00
Rotell Elc Antifeerze	2.00
Cabin Air Filter	1.00
Napa Cabin Air Filter	1.00
Ad Ip Dryer Cart	1.00
Power Steering Filter	1.00
Psf Qt	1.00
Tank	1.00
Shop Supplies	1.00

Hours: 21.00

Comm: 0.00

Labor: 1,533.00

Parts: 552.93

Total: 2,085.93

Work Order: 2203715 **Meter:** 58318 **In Date:** 04/05/2022 **Closed:** 04/12/2022

Problem: Boost solenoid/repair by rechtien/reference WO2202738

Work Completed

- Engine,other

Hours: 0.00

Comm: 717.78

Labor: 0.00

Parts: 0.00

Total: 717.78

6/9/2023
5:19:46 PM

Palm Beach County Fleet Management Asset Maintenance History
10196043 2014 INTERNATIONAL 7400 Dump Truck, 12Yd, 62,000 Gvwr, Steel Body

Work Order: 2206250 **Meter:** 58739 **In Date:** 06/14/2022 **Closed:** 06/16/2022
Problem: Dist.4 Armando, truck needs coolant .

Work Completed

- add 2.5 gallons of coolant
- Shop Supplies

Hours: 1.00

Comm: 0.00

Parts Issued

Rotell Elc Antifeerze	3.00
Shop Supplies	1.00

Labor: 73.00 Parts: 42.15 Total: 115.15

Work Order: 2207575 **Meter:** 59329 **In Date:** 07/20/2022 **Closed:** 08/01/2022
Problem: Dist.4 Armando, truck bed will not raise up

Work Completed

- pto inop when truck brought in . after fuel system repair and engine operating normal pto functioned properly . run multiple bed cycles
- fuel filter light on dash, pulled fuel filter replaced . fuel pressure still at 60psi. R&r fuel filter housing. after repair fuel pressure sensor was inop. swapped fuel pressure sensor and pressure reading returned
- test run
- pull codes 3471-1 , 3556-7 ,1322-31 ,94-0
- Shop Supplies

Hours: 11.00

Comm: 0.00

Parts Issued

Fuel Filter Housing	1.00
Sensor	1.00
Shop Supplies	1.00

Labor: 803.00 Parts: 1,922.99 Total: 2,725.99

Work Order: 2208385 **Meter:** 59806 **In Date:** 08/12/2022 **Closed:** 08/17/2022
Problem: Coolant

Work Completed

- Topped off cooling system
- Shop Supplies

Hours: 1.00

Comm: 0.00

Parts Issued

Shop Supplies	1.00
---------------	------

Labor: 73.00 Parts: 2.65 Total: 75.65

Work Order: 2211159 **Meter:** 62557 **In Date:** 10/31/2022 **Closed:** 11/01/2022
Problem: Needs Engine oil. Thank you

Work Completed

- Add Oil (only)
- Shop Supplies

Hours: 1.00

Comm: 0.00

Parts Issued

Washer Fluid Concentr	1.00
Prem Blue 15w40 1 Gal	2.00
Shop Supplies	1.00

Labor: 73.00 Parts: 57.63 Total: 130.63

6/9/2023
5:19:46 PM

10196043

Palm Beach County Fleet Management Asset Maintenance History
2014 INTERNATIONAL 7400 Dump Truck, 12Yd, 62,000 Gvwr, Steel Body

Work Order: 2211401 **Meter:** 62557 **In Date:** 11/07/2022 **Closed:** 03/01/2023
Problem: Dist.4 Armando, A/C not working can you look at this tomorrow need for weekend truck Haul

Work Completed

- Preventive Maint. Service

Hours: 0.00 Comm: 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00

Work Order: 2302028 **Meter:** 64136 **In Date:** 03/01/2023 **Closed:** 03/02/2023
Problem: Coolant

Work Completed

- top off cooling system and pressure test
- Napa parts issue.
- Shop Supplies

Parts Issued

Quantity

Rotell Elc Antifeerze	2.00
Shop Supplies	1.00

Hours: 1.50 Comm: 0.00 Labor: 109.50 Parts: 28.98 Total: 138.48

Work Order: 2302200 **Meter:** 64321 **In Date:** 03/03/2023 **Closed:** 03/06/2023
Problem: low coolant

Work Completed

- Top off cooling system, check for leaks, and verify stays above line while running
- Shop Supplies

Parts Issued

Quantity

Rotell Elc Antifeerze	3.00
Shop Supplies	1.00

Hours: 1.50 Comm: 0.00 Labor: 109.50 Parts: 42.15 Total: 151.65

6/9/2023
5:19:46 PM

10196043 Palm Beach County Fleet Management Asset Maintenance History
2014 INTERNATIONAL 7400 Dump Truck, 12Yd, 62,000 Gvwr, Steel Body

Work Order: 2302346 **Meter:** 65132 **In Date:** 03/07/2023 **Closed:** 05/17/2023

Problem: PM/engine light, truck is leaking air

Work Completed

- Operator states air leaking with brake depressed. Inspect unit and found faulty relay valve. Replace relay valve.
- Check engine light on. Connect scan tool and retrieved engine codes. Dpf clogged and sensor codes present. Due to burning coolant from leaking Egr cooler. Unit to dealer.
- A/c inop. Connect a/c machine and check freon pressures. Pressures 100/100. Perform electrical diag. Found no power to compressor clutch. Perform electrical diag. No power out of Bcm. Unit to dealer for repair.
- To International
- Pm Service.
- Service A/c system
- Add Coolant.
- Test Run
- Shop Supplies

Parts Issued

Quantity

Relay Valve	1.00
15-40 Oil	30.00
Napagold Oil Filter	1.00
Napagold Air Filter	1.00
Filter	1.00
Wiper Blade	2.00
Washer Fluid Concentr	1.00
Used Fire X Refurbished	1.00
Non-chlor Brake Clnr	4.00
Napa Cabin Air Filter	1.00
Cabin Air Filter	1.00
Rotell Elc Antifeerze	2.00
Control Crank Kit	1.00
Multicolor Pvc Mesh	1.00
Swing Arm	2.00
Tarp Bar	1.00
Connect Arm Kit	1.00
Shop Supplies	1.00

Hours: 14.00

Comm: 0.00

Labor: 1,022.00

Parts: 1,441.07

Total: 2,463.07

Work Order: 2302826 **Meter:** 65132 **In Date:** 03/09/2023 **Closed:** 03/21/2023

Problem: Tires: LRAO;LRAl;RRAO;RRAl;LFAO;LFAl;RFAO;RFAl; Wear. Replace Tire

Work Completed

- Tire Service: He Problem: Tires: Lrao;lrai;rrao;rrai;lfao;lfai;rfao;rfai; Wear. Replace Tire

Hours: 0.00

Comm: 3,991.48

Labor: 0.00

Parts: 0.00

Total: 3,991.48

6/9/2023
5:19:46 PM

10196043

Palm Beach County Fleet Management Asset Maintenance History
2014 INTERNATIONAL 7400 Dump Truck, 12Yd, 62,000 Gvwr, Steel Body

Work Order: 2305136

Meter: 65132

In Date: 05/24/2023 **Closed:** 05/24/2023

Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00

Comm: 0.00

Labor: 146.00

Parts: 0.00

Total: 146.00

Total Hours: 451.50

Total Labor: 29,545.00

Total Comm: 30,619.12

Total Parts: 27,814.77