Palm Beach County Fleet Management Asset Maintenance History 10198052 2015 TOYOTA PRIUS Car, Mid Size, Hybrid

Total Hours: 64.30 Labor: 4,295.40	Parts: 2,583.02	Comm: 288.00	Charge	ed: 7166.42
Work Order: 1503421 Me Problem: 1061 - Pre Delivery Inspec	eter: 116		In Date: 04/01/2015	5 Closed: 04/01/2015
Work Completed				
- Pre Delivery Inspection				
Hours: 2.00	Comm: 0.00	Labor: 120.00	Parts: 0.00	Total: 120.00
Work Order: 1508321 Me Problem: Right rear tire flat.	eter: 1827		In Date: 08/19/2018	5 Closed: 08/19/2015
Work Completed		Parts Issued		Quantity
- Repair and balance right rear tire.		Shop Supplies		1.00
- Shop Supplies				
Hours: 1.00	Comm: 0.00	Labor: 60.00	Parts: 2.00	Total: 62.00
Work Order: 1509854 Me Problem: Pm service.	eter: 2246		In Date: 09/29/2018	5 Closed: 10/13/2015
Work Completed		Parts Issued		Quantity
- Pm service.		Syn0w20		5.00
- Rotate and balance all four tires.		Napagold Oil Filter		1.00
- Shop Supplies		Shop Supplies		1.00
Hours: 3.00	Comm: 0.00	Labor: 180.00	Parts: 31.82	Total: 211.82
Work Order: 1601784 Me Problem: Right front tire flat.	eter: 4523		In Date: 02/22/2016	6 Closed: 02/24/2016
Work Completed		Parts Issued		Quantity
- Replace and balance two tires.		738274571 195-65r1	15 A	2.00
- Shop Supplies		Shop Supplies		1.00
		Tire Disposal Fee		2.00
Hours: 1.00	Comm: 0.00	Labor: 60.00	Parts: 232.98	Total: 292.98

Hours: 3.00

Palm Beach County Fleet Management Asset Maintenance History 10198052 2015 TOYOTA PRIUS Car, Mid Size, Hybrid

Work Order: 1603503 Problem: P.;M. service.	Meter:	4640		In Date:	04/04/2016	Closed:	04/15/2016
Work Completed			Parts Issued			Q	uantity
- P.m. Service.			Syn0w20				5.00
- Rotate and balance all tires.			Napagold Oil Filter				1.00
- Shop Supplies			Shop Supplies				1.00
Hours: 3.00		Comm: 0.00	Labor: 180.00	Parts: 31.	.21	Total:	211.21
Work Order: 1610319 Problem: P.M. Service.	Meter:	6823		In Date:	09/30/2016	Closed:	10/20/2016
Work Completed			Parts Issued			Q	uantity
- P.m. Service.			Syn0w20				4.00
- Rotate and balance all tires.			Napagold Oil Filter				1.00
- Shop Supplies			Wiper Bleade Anco				1.00
			Wiper Blade Anco				1.00
			Accufit Rear				1.00
			Washer Fluid Concer	ntr			1.00
			Shop Supplies				1.00
Hours: 3.00		Comm: 0.00	Labor: 180.00	Parts: 43.	.67	Total:	223.67
Work Order: 1703689 Problem: P.M. Service	Meter:	9504		In Date:	04/11/2017	Closed:	04/18/2017
Work Completed			Parts Issued			Q	uantity
- P.m. Service.			Napa Syn 5w30 Qt				4.00
- Rotate and balance tires.			Napagold Oil Filter				1.00
- Shop Supplies			Washer Fluid Concer	ntr			1.00
			Wd40 Spr				1.00
			Shop Supplies				1.00

Comm: 0.00

Labor: 180.00

Parts: 36.79

Total: 216.79

Palm Beach County Fleet Management Asset Maintenance History 10198052 2015 TOYOTA PRIUS Car, Mid Size, Hybrid

Work Order: 1710321 Problem: PM Service	Meter:	13804		In Date:	10/20/2017	Closed:	10/31/2017
Work Completed			Parts Issued			Qı	uantity
- P.m. service.			Syn0w20				5.00
- Balance and rotate all four tires.			Napagold Oil Filter				1.00
- Shop Supplies			Accufit Hybrid				1.00
			Accufit Hybrid				1.00
			Accufit Rear				1.00
			Shop Supplies				1.00
Hours: 3.00		Comm: 0.00	Labor: 180.00	Parts: 73.	70	Total:	253.70
Work Order: 1712790 Problem: Towed in for no start.	Meter:	15436		In Date:	12/29/2017	Closed:	01/04/2018
Work Completed			Parts Issued			Qı	uantity
- Check battery and charging system.failed	load test afte	r recharge.replace	Battery				1.00
defective battery.		3 .	Shop Supplies				1.00
- Shop Supplies							
Hours: 1.00		Comm: 0.00	Labor: 60.00	Parts: 278	3.50	Total:	338.50
Work Order: 1800053 Problem: no start	Meter:	15358		In Date:	12/28/2017	Closed:	01/03/2018
Work Completed							
- Tow From: 5th floor of vista garage To: lv	sho						

Comm: 96.00

Hours: 0.00

Labor: 0.00

Parts: 0.00

Total: 96.00

Palm Beach County Fleet Management Asset Maintenance History 10198052 2015 TOYOTA PRIUS Car, Mid Size, Hybrid

Work Order: 1803372 Meter: 18953 In Date: 03/30/2018 Closed: 04/05/2018

Problem: PM Service

Work Completed		Parts Issued		Quantity
P.m. service.Replace and balance four new tires. Nitrogen fill tires.		Syn0w20		5.00
		Napagold Oil Filte	Napagold Oil Filter	
- Complete alignment and road test.		Napa Cabin Air Fil	ter	1.00
- Shop Supplies		Wiper Bleade Anco)	1.00
		Wiper Blade Anco		1.00
		14in Exactfit-rear		1.00
		738274571 195-65	ir15 A	4.00
		Shop Supplies		1.00
		Tire Disposal Fee		4.00
Hours: 6.50	Comm: 0.00	Labor: 390.00	Parts: 545.28	Total: 935.28

Work Order: 1809951 Meter: 22018 In Date: 09/26/2018 Closed: 10/04/2018

Problem: P.M. Service.

Work Completed		Parts Issued		Quantity
- P.m. service.		Napagold Oil Filte	er	1.00
- Balance and rotate all four tires.		Syn0w20		4.00
- Shop Supplies		14in Exactfit-rear		1.00
		Wiper Blade Anco		1.00
		Wiper Bleade And	0	1.00
		Shop Supplies		1.00
Hours: 3.00	Comm: 0.00	Labor: 201.00	Parts: 45.11	Total: 246.11

Palm Beach County Fleet Management Asset Maintenance History 10198052 2015 TOYOTA PRIUS Car, Mid Size, Hybrid

Work Order: 1903339 Meter: 22586 In Date: 03/27/2019 Closed: 04/03/2019

Problem: P.M. service.

Work Completed		Parts Issued		Quantity
- P.m. service.		Napagold Oil Filte	1.00	
- Rotate and high speed bal;ance all four tires . Nitrofi	Syn0w20		4.00	
- Shop Supplies		14in Exactfit-rear		1.00
		Wiper Blade Anco		1.00
		Wiper Bleade Anco	0	1.00
		Shop Supplies		1.00
Hours: 3.00	Comm: 0.00	Labor: 201.00	Parts: 45.78	Total: 246.78

Work Order: 1909701 Meter: 24150 In Date: 09/20/2019 Closed: 10/02/2019

Problem: PM Service

Work Completed		Parts Issued		Quantity
P.m. service.Rotate and high speed balance all four tires . Nitrofill all.		Napagold Oil Filter		1.00
		Syn0w20	5.00	
- Shop Supplies		Wiper Bleade Anc	0	1.00
		Wiper Blade Anco 14in Exactfit-rear Washer Fluid Concentr		1.00
				1.00
				1.00
		Shop Supplies		1.00
Hours: 3.00	Comm: 0.00	Labor: 201.00	Parts: 54.91	Total: 255.91

Work Order: 1912857 Meter: 24789 In Date: 12/17/2019 Closed: 12/26/2019

Problem: Towed in for no start.

Work Completed		Parts Issued		Quantity
- Battery failed charge analysis . Replace battery . Test	charging system and	Agm Battery		1.00
draw test . Dome light left on .		Shop Supplies		1.00
- Shop Supplies				
Hours: 1.00	Comm: 0.00	Labor: 73.00	Parts: 226.45	Total: 299.45

Palm Beach County Fleet Management Asset Maintenance History 10198052 2015 TOYOTA PRIUS Car, Mid Size, Hybrid

Work Order: 1912911 Meter: 24418 In Date: 12/16/2019 Closed: 12/17/2019

Problem: no start

sched to be towed on AM of 12/17/2019

Work Completed

- Tow From: Vista Garage Top Floor To: lv shop

Hours: 0.00 Comm: 96.00 Labor: 0.00 Parts: 0.00 Total: 96.00

Work Order: 2003849 Meter: 26776 In Date: 04/17/2020 Closed: 04/23/2020

Problem: PM Service

Work Completed		Parts Issued		Quantity
P.m. service.Rotate and balance all four tires . Nitrofill all.		Syn0w20		5.00
		Napagold Oil Filter		1.00
- Shop Supplies		14in Exactfit-rear		1.00
		Wiper Blade Anco		1.00
		Wiper Bleade Anco Cabin Air Filter		1.00
				1.00
		Shop Supplies		1.00
Hours: 3.00	Comm: 0.00	Labor: 219.00	Parts: 60.72	Total: 279.72

Work Order: 2011130 Meter: 29908 In Date: 11/03/2020 Closed: 11/24/2020

Problem: PM Service and recall20-369

Work Completed	Parts Issued	Quantity
- performed pm service	Napagold Oil Filter	1.00
- balance and rotate all 4 tires. Nitro fill all.	Syn0w20	5.00
- Transport to and from dealer for recall 20ta10 and replace brake booste	r 14in Exactfit-rear	1.00
assembly .	Wiper Blade Anco	1.00
- Shop Supplies	Wiper Bleade Anco	1.00
	Shop Supplies	1.00
Hours: 5.00 Comm: 0.00	Labor: 365.00 Parts: 53.56	Total: 418.56

Palm Beach County Fleet Management Asset Maintenance History 10198052 2015 TOYOTA PRIUS Car, Mid Size, Hybrid

Work Order: 2012972 Meter: 30181 In Date: 12/30/2020 Closed: 12/31/2020

Problem: front right flat

Work Completed		Parts Issued		Quantity
- Replace both front tires for side wall damage and c	dry rot .	Tire Mic 195/65/1	5	2.00
- Shop Supplies		Shop Supplies		1.00
		Tire Disposal Fee		2.00
Hours: 1.00	Comm: 0.00	Labor: 73.00	Parts: 255.26	Total: 328.26

Work Order: 2013009 Meter: 29929 In Date: 12/30/2020 Closed: 12/31/2020

Problem: front right flat

Work Completed

- Tow From: 2300 jog 5th floor spot c16 To: 2601 vista

Hours: 0.00 Comm: 96.00 Labor: 0.00 Parts: 0.00 Total: 96.00

Work Order: 2105278 Meter: 32164 In Date: 05/11/2021 Closed: 05/19/2021

Problem: PM Service. Thank you.

Work Completed		Parts Issued		Quantity
- Preventive Maint. Service- check ,replace cabin a/c filter and refresh intake air		Wiper Blade Anco Wiper Bleade Anco		1.00
				1.00
- replace two tires,balance and rotate all 4		14in Exactfit-rear		1.00
- Shop Supplies		Napagold Oil Filte	r	1.00
		Syn0w20		5.00
		Cabin Air Filter		1.00
		Tire Mic 195/65/15	Tire Mic 195/65/15	
		Shop Supplies		1.00
		Tire Disposal Fee		2.00
Hours: 4.50 Co	mm: 0.00	Labor: 328.50	Parts: 340.63	Total: 669.13

Palm Beach County Fleet Management Asset Maintenance History 10198052 2015 TOYOTA PRIUS Car, Mid Size, Hybrid

Work Order: 2112001 Problem: PM Service .	Meter:	34034		In Date:	11/08/2021	Closed:	11/16/2021
Work Completed			Parts Issued			Qı	uantity
- Preventive Maint. Service			Syn0w20				4.00
- Rotate And Balance Four Tires. Nitro Fill All .			Napagold Oil Filter				1.00
- Shop Supplies			14in Exactfit-rear				1.00
			Wiper Blade Anco				1.00
			Wiper Bleade Anco				1.00
			Shop Supplies				1.00
Hours: 3.00		Comm: 0.00	Labor: 219.00	Parts: 39.	16	Total:	258.16
Work Order: 2205129 Problem: PM Service.	Meter:	37703		In Date:	05/12/2022	Closed:	05/18/2022
Work Completed		Parts Issued			Qı	uantity	
- Preventive Maint. Service			Napagold Oil Filter				1.00
- Rotated and balanced all 4 tires. Nitrogen filled all tires.			Syn0w20				5.00
- Shop Supplies			Washer Fluid Conce	entr			1.00
			14in Exactfit-rear				1.00
			19in Exactfitblade				1.00
			26in Exactfitblade				1.00
			Shop Supplies				1.00
Hours: 3.00		Comm: 0.00	Labor: 219.00	Parts: 59.	.39	Total:	278.39
Work Order: 2209373 Problem: Maintenance Light on Dash. Char	Meter: nge key FOI			In Date:	09/08/2022	Closed:	09/14/2022
Work Completed			Parts Issued			Qı	uantity
- Pm Canceled			Lithium Coin Cell				1.00
- Replace Key Fob battery, Reset maintenance	e light						
Hours: 0.30	-	Comm: 0.00	Labor: 21.90	Parts: 5.2	20	Total:	27.10

Palm Beach County Fleet Management Asset Maintenance History 10198052 2015 TOYOTA PRIUS Car, Mid Size, Hybrid

Work Order: 2211520 Meter: 41094 In Date: 11/15/2022 Closed: 11/23/2022

Problem: PM Service.

Work Completed		Parts Issued		Quantity
- Preventive Maint. Service		Napagold Oil Filter	1.00	
- rotate and balance all 4 tires nitro fill		Syn0w20		5.00
- Shop Supplies		Washer Fluid Conc	entr	1.00
		19in Exactfitblade		1.00
		26in Exactfitblade		1.00
		Shop Supplies		1.00
Hours: 3.00	Comm: 0.00	Labor: 219.00	Parts: 54.24	Total: 273.24

Work Order: 2304603 Meter: 43525 In Date: 05/09/2023 Closed: 05/17/2023

Problem: PM Services.

Work Completed	Parts Issued	Quantity	
- Preventive Maint. Service	Napagold Oil Filter	1.00	
- Rotate and speed balance, nitro fill	Syn0w20	5.00	
- Shop Supplies	Washer Fluid Concentr	1.00	
	14in Exactfit-rear	1.00	
	19in Exactfitblade	1.00	
	26in Exactfitblade	1.00	
	Silicone Spray 10oz	1.00	
	Shop Supplies	1.00	
Hours: 3.00 Comm: 0.00	Labor: 219.00 Parts: 66.69	Total: 285.69	

Work Order: 2309848 Meter: 44485 In Date: 09/27/2023 Closed: 09/27/2023

Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 0.00 Total: 146.00

Total Hours: 64.30 Total Labor: 4,295.40 Total Comm: 288.00 Total Parts: 2,583.02