

1/8/2024
6:50:40 PM

Palm Beach County Fleet Management Asset Maintenance History
10203148 2017 CLUB CAR CARRYALL 500 Utility Cart, Gas

Total Hours: 58.00 Labor: 4,036.00 Parts: 2,031.45 Comm: 384.00 Charged: 6451.44

Work Order: 1704184 **Meter:** 1 **In Date:** 04/26/2017 **Closed:** 04/26/2017
Problem: 1061 - Pre Delivery Inspection

Work Completed

- Pre Delivery Inspection

Hours: 2.00 Comm: 0.00 Labor: 120.00 Parts: 0.00 Total: 120.00

Work Order: 1802741 **Meter:** 292 **In Date:** 03/13/2018 **Closed:** 03/30/2018
Problem: pm service, check right rear bed bracket

Work Completed

- pm service
- replace right side hinge for dump bed
- clean and adjust brakes
- Shop Supplies

Parts Issued

Quantity

Napa 10w30 Qt	2.00
Spark Plug	1.00
Non-chlor Brake Clnr	2.00
Brkt Hinge Bed	1.00
Shop Supplies	1.00
Labor: 360.00 Parts: 26.78 Total: 386.78	

Work Order: 1806859 **Meter:** 351 **In Date:** 07/03/2018 **Closed:** 07/16/2018
Problem: belt broke

Work Completed

- replace starter drive belt
- Shop Supplies

Parts Issued

Quantity

Starter Belt	1.00
Shop Supplies	1.00
Hours: 1.00 Comm: 0.00 Labor: 60.00 Parts: 18.49 Total: 78.49	

1/8/2024
6:50:40 PM

Palm Beach County Fleet Management Asset Maintenance History
10203148 2017 CLUB CAR CARRYALL 500 Utility Cart, Gas

Work Order: 1912999 **Meter:** 787 **In Date:** 12/19/2019 **Closed:** 01/02/2020
Problem: pm/ possitive battery cable corroded

Work Completed

- pm service
- r/r cale to replace cable end
- Shop Supplies

Parts Issued

Quantity

Spark Plug	1.00
Napagold Air Filter	1.00
Napa 10w30 Qt	2.00
Shop Supplies	1.00

Hours: 5.00

Comm: 0.00

Labor: 365.00

Parts: 25.83

Total: 390.83

Work Order: 1913002 **Meter:** 592 **In Date:** 12/19/2019 **Closed:** 12/19/2019
Problem: Positive Battery Cable Broken (Corroted)

Work Completed

- Tow From: Mounts Bldg-559 N Military Trail

Hours: 0.00

Comm: 96.00

Labor: 0.00

Parts: 0.00

Total: 96.00

1/8/2024
6:50:40 PM

Palm Beach County Fleet Management Asset Maintenance History
10203148 2017 CLUB CAR CARRYALL 500 Utility Cart, Gas

Work Order: 2012400 **Meter:** 787 **In Date:** 12/15/2020 **Closed:** 01/12/2021
Problem: pm/ pos battery cable/ dump bed bracket/ see notes

Work Completed

- Preventive Maint. Service
- remove dump bed - replace damage bed hitches ben back frame n replace lr splash shield - custom mount lr taillight in rewire
- test and replace battery - replace pos & neg cables n terminals make new cables
- wash - clean out rust and undercoat battery tray
- clean and readjust brakes + shoes
- replace drive belt + starter belt
- repair lf tire nitro fill all 4
- Shop Supplies

Parts Issued

Quantity

Non-chlor Brake Clnr	2.00
Napa 10w30 Qt	2.00
Startron 8oz Fuel Trt	1.00
Napagold Air Filter	1.00
Spark Plug	1.00
Battery	1.00
Batt Cable Terminal	2.00
Bulk Battery Cable	3.00
Bulk Battery Cable	3.00
Rear Lh Fender	1.00
Brkt Hinge Bed	2.00
Lamp Stop/trn/tail	1.00
Rubberized Undercoat	1.00
Starter Belt	1.00
Belt	1.00
Tire Rep Brown String	1.00
Shop Supplies	1.00

Hours: 12.50

Comm: 0.00

Labor: 912.50

Parts: 388.03

Total: 1,300.53

Work Order: 2201321 **Meter:** 1409 **In Date:** 02/04/2022 **Closed:** 03/11/2022
Problem: PM Service.

Work Completed

- Preventive Maint. Service
- Clean And Adjust All Brakes
- Shop Supplies

Parts Issued

Quantity

Napa 10w30 Qt	2.00
Spark Plug	1.00
Napagold Air Filter	1.00
Non-chlor Brake Clnr	1.00
Shop Supplies	1.00

Hours: 5.00

Comm: 0.00

Labor: 365.00

Parts: 24.69

Total: 389.69

1/8/2024
6:50:40 PM

Palm Beach County Fleet Management Asset Maintenance History
10203148 2017 CLUB CAR CARRYALL 500 Utility Cart, Gas

Work Order: 2303336 **Meter:** 1409 **In Date:** 04/04/2023 **Closed:** 04/05/2023
Problem: Tire popped need new tire

Work Completed

- Tire Replacement
- Shop Supplies

Hours: 1.00 Comm: 0.00

Parts Issued

	Quantity
Tire 20x10-10 6 Ply Kenda	1.00
Shop Supplies	1.00
Tire Disposal Fee	1.00
Labor: 73.00	Parts: 120.59
Total: 193.59	

Work Order: 2303506 **Meter:** 1842 **In Date:** 04/06/2023 **Closed:** 04/24/2023
Problem: PM Service.

Work Completed

- Preventive Maint. Service
- Replace Passenger Side Dump Body Hinge
- Replace Three Tires
- Replace Upper And Lower Front Suspension Bushings
- Repair Tailgate Both Brackets
- Shop Supplies

Hours: 10.00 Comm: 0.00

Parts Issued

	Quantity
Napa 10w30 Qt	2.00
Spark Plug	1.00
Napagold Air Filter	1.00
Non-chlor Brake Clnr	1.00
Spring Bushing	4.00
Urethane Bushing	12.00
Brkt Hinge Bed	1.00
Tire 20x10-10 6 Ply Kenda	3.00
Shop Supplies	1.00
Tire Disposal Fee	3.00
Freight Charge	1.00
Labor: 730.00	Parts: 512.88
Total: 1,242.88	

Work Order: 2309360 **Meter:** 1842 **In Date:** 09/14/2023 **Closed:** 09/14/2023
Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00 Comm: 0.00

Labor: 146.00 Parts: 0.00 Total: 146.00

Total Hours: 58.00

Total Labor: 4,036.00

Total Comm: 384.00

Total Parts: 2,031.45