Palm Beach County Fleet Management Asset Maintenance History 10198281 2015 FORD TRANSIT T250 Van, 3/4 Ton, Cargo

Total Hours: 129.00 Labor: 8,821.00 Parts: 5,496.20 Comm: 96.00 Charged: 14413.20

Work Order: 1509338 Meter: 333 In Date: 09/16/2015 Closed: 09/16/2015

Problem: 1061 - Pre Delivery Inspection

Work Completed

- Pre Delivery Inspection

Hours: 2.00 Comm: 0.00 Labor: 120.00 Parts: 0.00 Total: 120.00

Work Order: 1512432 Meter: 2405

Problem: need extended upper for van ergo rack for 12 inch ladder

Work Completed Quantity **Parts Issued** extended uppers b2 version 1.00 - install ladder rack rear extented upper extension for 12' a frame ladder **Shop Supplies** 1.00 - Shop Supplies Freight Charge 1.00 Hours: 2.00 Comm: 0.00 Labor: 120.00 Parts: 190.92 Total: 310.92

In Date: 12/09/2015 **Closed:** 01/15/2016

Work Order: 1602262 Meter: 3935 In Date: 03/03/2016 Closed: 03/08/2016

Problem: pm, ck door having problems to lock

Work Completed			Parts Issued		Quantity
- pm			Napagold Oil Filte	er	1.00
- svc ladder rack			5w20 Syn Blend		6.00
- fab and adj rear d	loor lock		Washer Fluid Con	centr	1.00
- Shop Supplies			Shop Supplies		1.00
	Hours: 6.00	Comm: 0.00	Labor: 360.00	Parts: 31.75	Total: 391.75

Work Order: 1610350 Meter: 9179 In Date: 10/03/2016 Closed: 10/17/2016

Problem: PM service

Work Completed			Parts Issued	Quantity
- Pm service.			Napagold Oil Filter	1.00
- Service ladder rad	ck.		Napa Quart 5w20	6.00
- Shop Supplies			Washer Fluid Concentr	1.00
			Shop Supplies	1.00
	Hours: 5.00	Comm: 0.00	Labor: 300.00 Parts: 28.90	Total: 328.90

Palm Beach County Fleet Management Asset Maintenance History 10198281 2015 FORD TRANSIT T250 Van, 3/4 Ton, Cargo

Work Order: 1703632 Problem: P.M.SERVICE	Meter:	13055		In Date:	04/11/2017	Closed:	04/24/2017
Work Completed			Parts Issued			Qı	uantity
- Pm Service			Wiper Blade				1.00
- Service ladder rack.			Wiper Blade				1.00
- Rotate and balance tires.			Napagold Oil Filter				1.00
- Shop Supplies			Oil Filter				1.00
			Napa Quart 5w20				6.00
			Washer Fluid Concen	tr			1.00
			Wiper Blade - Accufit	: - Passenge	er's Side		1.00
			Accufit Beam				1.00
			Shop Supplies				1.00
Hours: 5.75		Comm: 0.00	Labor: 345.00	Parts: 98.	39	Total:	443.39
Work Order: 1709706 Problem: p.m.service	Meter:	16359		In Date:	10/04/2017	Closed:	10/18/2017
Work Completed			Parts Issued			Qı	uantity
- Pm Service			Napagold Oil Filter				1.00
- Service ladder rack.			Napa Quart 5w20				6.00
- Repair right rear tire.			Washer Fluid Concen	tr			1.00
- Shop Supplies			Shop Supplies				1.00
Hours: 6.00		Comm: 0.00	Labor: 360.00	Parts: 30.	13	Total:	390.13
Work Order: 1802251 Problem: ball mount	Meter:	18481		In Date:	02/28/2018	Closed:	03/12/2018
Work Completed			Parts Issued			Qı	uantity
- ball mount			adjustable drop hitch	1			1.00
- Shop Supplies			Trailer Ball				1.00
			Pin W/clip 5/8 For Hi	tch			1.00
			Shop Supplies				1.00
Hours: 0.00		Comm: 0.00	Labor: 0.00	Parts: 152	2.03	Total:	152.03

Palm Beach County Fleet Management Asset Maintenance History 10198281 2015 FORD TRANSIT T250 Van, 3/4 Ton, Cargo

Work Order: 1804532 Meter: 19609 In Date: 05/01/2018 Closed: 05/14/2018

Problem: PM Service. Safety recalls.

Work Completed		Parts Issued		Quantity
- Pm Service.		Napagold Oil Filte	1.00	
- Rotate and balance four tires.		Napa Quart 5w20		6.00
- Service ladder rack.		Napa Air Filter		1.00
- Vacume debris from air cowl,air filter housing	Wiper Blade		1.00	
- Transport vehicle to and from dealer for safet	y recalls #17s15d and	Wiper Blade		1.00
#17s34c complete.	,	Washer Fluid Con-	centr	1.00
- Shop Supplies		Shop Supplies		1.00
Hours: 9.75	Comm: 0.00	Labor: 585.00	Parts: 77.18	Total: 662.18

Work Order: 1813018 Meter: 24373 In Date: 12/26/2018 Closed: 01/14/2019

Problem: P.M.SERVICE,TIRE LIGHT ON, GAS DOOR HINGE BROKEN(TOP)

Work Completed	Parts Issued		Quantity	
- Pm Service.		Napa Quart 5w20		6.00
- Mount and balance 4 tires.		Napagold Oil Filter		1.00
- Rear brake job.replace pads.service rotors and calipers.lul	Washer Fluid Conce	entr	1.00	
system.		Wiper Blade		1.00
- Replace failed fuel door housing.		Wiper Blade		1.00
- Vacume debris from air cowl and engine compartment.		Tire 235/65/16		4.00
- Service ladder rack.		Non-chlor Brake Cl	nr	1.00
- Shop Supplies		Brake Pad		1.00
		Housing		1.00
		Shop Supplies		1.00
		Tire Disposal Fee		4.00
Hours: 15.25	Comm: 0.00	Labor: 1,021.75	Parts: 1,623.25	Total: 2,645.00

Palm Beach County Fleet Management Asset Maintenance History 10198281 2015 FORD TRANSIT T250 Van, 3/4 Ton, Cargo

Work Order: 1907304 Meter: 28389 In Date: 07/16/2019 Closed: 07/22/2019

Problem: P.M.SERVICE

Work Completed		Parts Issued		Quantity
- Pm Service.		Napagold Oil Filte	1.00	
- Service ladder rack.		Napa Quart 5w20		6.00
- Shop Supplies		Washer Fluid Cond	centr	1.00
		Wd40 Spr		1.00
		Shop Supplies		1.00
Hours: 5.00	Comm: 0.00	Labor: 335.00	Parts: 41.31	Total: 376.31

Work Order: 2001116 Meter: 33553 In Date: 01/31/2020 Closed: 02/18/2020

Problem: PM Service.

Work Completed		Parts Issued	Quantity	
- Pm Service.		Programming Abs	Module	1.00
- Service ladder rack.		Napa Quart 5w20		6.00
- Shop Supplies		Napagold Oil Filte	r	1.00
		Wiper Blade		1.00
		Wiper Blade		1.00
		Washer Fluid Concentr		1.00
		Shop Supplies		1.00
Hours: 5.00	Comm: 0.00	Labor: 365.00	Parts: 322.20	Total: 687.20

Palm Beach County Fleet Management Asset Maintenance History 10198281 2015 FORD TRANSIT T250 Van, 3/4 Ton, Cargo

Work Order: 2007429 Meter: 37922 07/29/2020 **Closed**: 07/31/2020 In Date: Problem: PM Service **Work Completed Parts Issued** Quantity Used Fire X Refurbished 1.00 - Pm Service. Napagold Oil Filter 1.00 - Service ladder rack system. Napa Quart 5w20 6.00 - Rotate and balance four tires. Napa Air Filter 1.00 - Repaired left rear tire. Wiper Blade 1.00 - Clean engine compartment. Wiper Blade 1.00 - Shop Supplies Washer Fluid Concentr 1.00 Wd40 Spr 1.00 **Shop Supplies** 1.00 Hours: 7.50 Comm: 0.00 Labor: 547.50 Parts: 108.18 Total: 655.68 Work Order: 2009214 Meter: 39925 In Date: 09/15/2020 Closed: 09/28/2020 **Problem:** Towed in.Crank no start.

	Work Completed		Parts Issued		Quantity	
	- Computer diagnose for crank no start.p	inpoint test confirm bad fuel pump	Fuel Pump Module	Pump Module		
	driver module.replace fuel pump driver m	odule and test drive.	Shop Supplies		1.00	
	- Shop Supplies					
	Hours: 2.50	Comm: 0.00	Labor: 182.50	Parts: 67.78	Total: 250.28	
Wo	ork Order: 2009328	Meter: 39468		In Date: 09/15/202	0 Closed: 09/17/2020	

Problem: Crank No start.

Work Completed

- Tow From: !0th Ave and Jod Road.wellinton To: 13026 Jog Road Delray.

Hours: 0.00 Comm: 96.00 Labor: 0.00 Parts: 0.00 Total: 96.00

Palm Beach County Fleet Management Asset Maintenance History 10198281 2015 FORD TRANSIT T250 Van, 3/4 Ton, Cargo

Work Order: Problem:	2102246 PM Service.	Meter:	43401		In Date:	02/26/2021	Closed:	03/02/2021
Work Com	ıpleted			Parts Issued			Qı	uantity
- Preventiv	ve Maint. Service			Wiper Blade				1.00
- service la	adder rack			Wiper Blade				1.00
- Rotate a	nd balance tires.			Washer Fluid Conce	ntr			1.00
- Shop Su	pplies			Napagold Oil Filter				1.00
				Napa Quart 5w20				6.00
				Shop Supplies				1.00
	Hours: 6.00		Comm: 0.00	Labor: 438.00	Parts: 71.	83	Total:	509.83
Work Order: Problem:	2106813 Safety Recall #20B53	Meter:	46641		In Date:	06/22/2021	Closed:	06/25/2021
Work Com	npleted			Parts Issued			Qı	uantity
- Safety Re	ecall #20b53. Travel from Sr sho	p to Greico For	d in Delray. Travel	235/65/16 Tire Hank	kook			4.00
from Sr sho	op back to ford to pick up vehic	le after recall p	reformed.	Shop Supplies				1.00
- Mount/b	palanced 4 Tires And Reset Tpm	S		Tire Disposal Fee				4.00
- Shop Տսյ	pplies							
	Hours: 3.00		Comm: 0.00	Labor: 219.00	Parts: 1,1	41.44	Total:	1,360.44
Work Order: Problem:	2107569 Check engine light on and over	Meter: er heating.	46970		In Date:	07/13/2021	Closed:	07/28/2021
Work Com	npleted			Parts Issued			Qı	uantity
- C/s engir	ne overheating & check engine	light on. Scan 8	પ્ર found codes	Relay				1.00
	285 & P1299,perform pinpoint		d cooling fans.	Relay				2.00
•	oling fan assembly, fan relays 8			Fan Assy				1.00
	e after repair to verify repairs a	re complete.		Shop Supplies				1.00
- Shop Su	pplies							
	Hours: 4.50		Comm: 0.00	Labor: 328.50	Parts: 32	1.92	Total:	650.42

Palm Beach County Fleet Management Asset Maintenance History 10198281 2015 FORD TRANSIT T250 Van, 3/4 Ton, Cargo

Work Order: 2109627 Meter: 48188 In Date: 09/02/2021 Closed: 09/22/2021

Problem: PM Service.

Work Completed		Parts Issued		Quantity
- Preventive Maint. Service		Napa Quart 5w20		6.00
- C/s A/c does not work some times. Unable to verify cor	ncern, perform	Napagold Oil Filte	r	1.00
system test, evacuate, add leak detection dye, recharge &	k leak test. system is	Washer Fluid Cond	centr	1.00
ok at this time. Install cabin air filter.		Napa Air Filter		1.00
- Remove both rear axles, hubs & rotors. Replace rotors,	axle seals, rear	Freon Sr Shop		1.00
brake pads, service calipers, flush & bleed brake system.		Cabin Air Filter		1.00
- Service ladder rack.		Rear Brake Pad Se	1.00	
- Fill all tires with nitrogen, balance, rotate & reset Tpms.	ms.	Non-chlor Brake Clnr Frig Oil		1.00
- Shop Supplies				1.00
		E8 A/c Oil Univ W	Dye	1.00
		Rotor Rear Seal		2.00
				2.00
		Seal		2.00
		Shop Supplies		1.00
Hours: 13.00	Comm: 0.00	Labor: 949.00	Parts: 381.13	Total: 1,330.13

Work Order: 2201830 Meter: 51721 In Date: 02/17/2022 Closed: 02/18/2022

Problem: wouldnt start this morning, jumped the battery to get it over to fleet.

Work Completed			Parts Is	ssued		Qı	ıantity
- r&r drivers seat to test battery. Battery failed load test. replace battery and			Battry	Motorcraft			1.00
	clean severely corroded terminal ends . Use \ensuremath{Ids} to reset	Bms	Shop Supplies				1.00
	- Shop Supplies						
	Hours: 1.50	Comm: 0.00	Labor:	109.50	Parts: 144.95	Total:	254.45

Palm Beach County Fleet Management Asset Maintenance History 10198281 2015 FORD TRANSIT T250 Van, 3/4 Ton, Cargo

Work Order: 2202897 Meter: 52105 In Date: 03/16/2022 Closed: 03/25/2022

Problem: PM Service.Check tires.

Work Completed	Pa	arts Issued		Quantity
- Pm Service	Na	apa Quart 5w20		6.00
- R&r Right Rear Axle Seals And Fill Differential Fluid Level. Clear	n Excess Na	apagold Oil Filte	•	1.00
Residue	W	iper Blade		1.00
- Rotate Balanced 4 Tires	W	iper Blade		1.00
- Service Ladder Rack System	Us	sed Fire X Refurb	ished	1.00
- Shop Supplies	Se	al		2.00
	No	on-chlor Brake C	Inr	2.00
	Sh	op Supplies		1.00
Hours: 7.50 Comm	n: 0.00 La	bor: 547.50	Parts: 89.06	Total: 636.56

Work Order: 2209533 Meter: 55763 In Date: 09/13/2022 Closed: 09/22/2022

Problem: PM Service.

Work Completed		Parts Issued		Quantity	
- Preventive Maint. Service- rotate balanced 4 tires- clean air cowl system and replaced cabin filter		Napa Quart 5w20		6.00	
		Napagold Oil Filter		1.00	
		Washer Fluid Concentr		1.00	
- Shop Supplies		Wiper Blade		1.00	
		Wiper Blade		1.00	
		Cabin Filter A/c		1.00	
		Shop Supplies		1.00	
Hours: 5.50	Comm: 0.00	Labor: 401.50	Parts: 81.74	Total: 483.24	

Palm Beach County Fleet Management Asset Maintenance History 10198281 2015 FORD TRANSIT T250 Van, 3/4 Ton, Cargo

Work Order: 2303020 Meter: 59800 In Date: 03/24/2023 Closed: 03/29/2023

Problem: PM Service.

Work Completed	Parts Issued		Quantity	
- Preventive Maint. Service - rotate balanced 4 tires		Napagold Oil Filter		1.00
		Napa Quart 5w20		6.00
- Shop Supplies		Washer Fluid Concentr		1.00
		Wiper Blade		1.00
		Wiper Blade		1.00
		Used Fire X Refurbished		1.00
		Shop Supplies		1.00
Hours: 5.00	Comm: 0.00	Labor: 365.00	Parts: 108.56	Total: 473.56

Work Order: 2310445 Meter: 64466 In Date: 10/17/2023 Closed: 10/31/2023

Problem: PM Service. CEL on.

Work Completed			Parts Issued	
- Preventive Maint. Service				1.00
- Right rear tail light was cracked & fill with water. Replace	Napa Quart 5w20		6.00	
assembly.		Washer Fluid Concentr		1.00
- Diagnose check engine light, scan, found code P1450, p	Wiper Blade		1.00	
test, found bad purge valve, replace purge valve & clear codes.		Wiper Blade		1.00
- Service ladder rack.		Napa Air Filter		1.00
- Fill all tires with nitrogen, balance, rotate & reset Tpms.	Used Fire X Refurbished Lamp Assy		1.00	
- Rest drive To verify all repairs are complete.				
- Shop Supplies	Valve Asm		1.00	
		Shop Supplies		1.00
Hours: 9.25	Comm: 0.00	Labor: 675.25	Parts: 383.59	Total: 1,058.84

Work Order: 2311845 Meter: 64704 In Date: 11/29/2023 Closed: 11/29/2023

Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Palm Beach County Fleet Management Asset Maintenance History 10198281 2015 FORD TRANSIT T250 Van, 3/4 Ton, Cargo

Hours: 2.00

Comm: 0.00

Labor: 146.00

Parts: 0.00

Total: 146.00

Total Hours: 129.00

Total Labor: 8,821.00

Total Comm: 96.00

Total Parts: 5,496.20