

2/1/2024
3:31:31 PM

Palm Beach County Fleet Management Asset Maintenance History
10198297 2015 FORD TRANSIT T350 Van, 1 Ton Cargo

Total Hours: 177.10 Labor: 12,305.00 Parts: 8,767.10 Comm: 756.80 Charged: 21828.90

Work Order: 1511774 **Meter:** 327 **In Date:** 11/18/2015 **Closed:** 11/18/2015
Problem: 1061 - Pre Delivery Inspection

Work Completed

- Pre Delivery Inspection

Hours: 2.00 Comm: 0.00 Labor: 120.00 Parts: 0.00 Total: 120.00

Work Order: 1605138 **Meter:** 3168 **In Date:** 05/17/2016 **Closed:** 05/27/2016
Problem: P.M. Service

Work Completed

- P.m. Service.
- Rotate and balance tires.
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
05074 Silicone Spray	1.00
Used Fire X Refurbished	1.00
Shop Supplies	1.00
Labor: 300.00 Parts: 39.70 Total: 339.70	

Hours: 5.00 Comm: 0.00

Work Order: 1611190 **Meter:** 11447 **In Date:** 10/28/2016 **Closed:** 11/22/2016
Problem: P.M. service.

Work Completed

- P.m. Service.
- Rotate and balance tires.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
22" Wiper Blade	2.00
Washer Fluid Concentr	1.00
5w20 Engine Oil	6.00
Wiper Blade - Accufit - Passenger's Side	1.00
Accufit Beam	1.00
Shop Supplies	1.00
Labor: 300.00 Parts: 60.04 Total: 360.04	

Hours: 5.00 Comm: 0.00

2/1/2024
3:31:31 PM

Palm Beach County Fleet Management Asset Maintenance History
10198297 2015 FORD TRANSIT T350 Van, 1 Ton Cargo

Work Order: 1907255 **Meter:** 42922 **In Date:** 07/15/2019 **Closed:** 07/23/2019
Problem: P.M. service and rear cargo door inop.

Work Completed

Parts Issued

Quantity

- P.m. service.
- Diagnose rear cargo door inop . Test and replace defective latch assembly . Retest .
- Rotate and balance all four tires . Nitrofill all.
- Shop Supplies

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
Wiper Blade	1.00
Wiper Blade	1.00
Used Fire X Refurbished	1.00
Latch Asm	1.00
Shop Supplies	1.00

Hours: 6.80 Comm: 0.00 Labor: 455.60 Parts: 264.56 Total: 720.16

Work Order: 1911993 **Meter:** 48647 **In Date:** 11/19/2019 **Closed:** 11/27/2019
Problem: PM Service, Detail.

Work Completed

Parts Issued

Quantity

- P.m.service.
- Test battery and charging system.recharge and retest battery,fail load test.replace defective battery.
- Rotate and balance all four tires.
- Shop Supplies

Napagold Oil Filter	1.00
5w20 Engine Oil	7.00
Washer Fluid Concentr	1.00
Battry Motorcraft	1.00
Shop Supplies	1.00

Hours: 6.00 Comm: 0.00 Labor: 438.00 Parts: 204.72 Total: 642.72

Work Order: 1912238 **Meter:** 48592 **In Date:** 11/27/2019 **Closed:** 11/27/2019
Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued

Hours: 0.00 Comm: 96.00 Labor: 0.00 Parts: 0.00 Total: 96.00

2/1/2024
3:31:31 PM

Palm Beach County Fleet Management Asset Maintenance History
10198297 2015 FORD TRANSIT T350 Van, 1 Ton Cargo

Work Order: 2005223 **Meter:** 52919 **In Date:** 05/26/2020 **Closed:** 06/02/2020
Problem: P.M. service.

Work Completed

- P.m. service.
- Replace rear rotors and pads . Service calipers . Flush and bleed brake system . Road test .
- Rotate and balance all flour tires . Nitrofill all.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
Napa Air Filter	1.00
Used Fire X Refurbished	1.00
Wiper Blade	1.00
Wiper Blade	1.00
Bolt	10.00
Non-chlor Brake Clnr	1.00
Seal	2.00
Rotor Brake	2.00
Brake Pad	1.00
Shop Supplies	1.00

Hours: 9.00

Comm: 0.00

Labor: 657.00 Parts: 371.89 Total: 1,028.89

Work Order: 2008829 **Meter:** 57253 **In Date:** 09/01/2020 **Closed:** 09/15/2020
Problem: A/C not cooling.

Work Completed

- A/c performance test . Leak test . Recover and vacuum system . R&r leaking evaporator and drier in condenser . Evacuate system and complete charge to factory specs. Retest A/c .
- Shop Supplies

Parts Issued

Quantity

Seal	1.00
Freon Lv Shop 2	2.00
Frig Oil	1.00
A/c Accumulator	1.00
A/c Evaporator	1.00
O Ring Kit A/c	1.00
Kit O	1.00
Hose	1.00
Shop Supplies	1.00

Hours: 14.40

Comm: 0.00

Labor: 1,051.20 Parts: 1,393.98 Total: 2,445.18

2/1/2024
3:31:31 PM

Palm Beach County Fleet Management Asset Maintenance History
10198297 2015 FORD TRANSIT T350 Van, 1 Ton Cargo

Work Order: 2102277 **Meter:** 63810 **In Date:** 03/01/2021 **Closed:** 03/10/2021

Problem: P.M. service and Towed in for No Power , check engine light on .

Work Completed

- P.m. service.
- Diagnose check engine light and lack of power. Found to have codes- p0217, P1285, and P1299. Found to have bad cooling fan assembly causing van to overheat. R and R cooling fan assembly. Cleared codes and test drove.
- Replaced 2 tires. Rotated and balanced all 4 tires. Nitrogen filled all tires.
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
Wiper Blade	1.00
Wiper Blade	1.00
Fan Motor Assy	1.00
235/65/16 Tire Hankook	2.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 9.40

Comm: 0.00

Labor: 686.20

Parts: 908.53

Total: 1,594.73

Work Order: 2102321 **Meter:** 63776 **In Date:** 02/26/2021 **Closed:** 03/01/2021

Problem: No Power

Work Completed

- Tow From: Library (11303 Campus Dr, Pbg) To: Lv shop

Hours: 0.00

Comm: 96.00

Labor: 0.00

Parts: 0.00

Total: 96.00

Work Order: 2108854 **Meter:** 70456 **In Date:** 08/16/2021 **Closed:** 09/15/2021

Problem: PM Service. Recalls 20B53 and 19S38 .

Work Completed

- Preventive Maint. Service
- check,replaced cabin a/c filter and refresh intake air
- balance and rotate al 4 tires
- Transport to and from dealer for recalls 19s38 and 20b53 .
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
Wiper Blade	1.00
Wiper Blade	1.00
Used Fire X Refurbished	1.00
Mesh-gray S Whl Cov	1.00
Cabin Air Filter	1.00
Hose Air	1.00
Shop Supplies	1.00

Hours: 7.50

Comm: 0.00

Labor: 547.50

Parts: 239.41

Total: 786.91

2/1/2024
3:31:31 PM

Palm Beach County Fleet Management Asset Maintenance History
10198297 2015 FORD TRANSIT T350 Van, 1 Ton Cargo

Work Order: 2201301 **Meter:** 76413 **In Date:** 02/04/2022 **Closed:** 02/10/2022

Problem: PM Service. Send for Detail. Remove keys bells keep dinging like lights are on, wont lock

Work Completed

Parts Issued

Quantity

- Preventive Maint. Service
- Rotated and balanced all 4 tires. Nitrogen filled all tires.
- Diagnose key bell beeps and doors wont lock. Lubed sticking ignition switch.
- Replaced rear pads rotors and calipers. Service rear calipers Flushed brake fluid and test drove.
- Replaced cabin filter. Cleaned debris from fresh air intake.
- Shop Supplies

Wiper Blade	1.00
Wiper Blade	1.00
5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
Brk Fluid Dot 4-32oz	1.00
Non-chlor Brake Clnr	2.00
Brake Pad	1.00
Rotor Rear	2.00
Cabin Air Filter	1.00
Rear Caliper	1.00
Caliper	1.00
Seal	2.00
Shop Supplies	1.00

Hours: 10.00

Comm: 0.00

Labor: 730.00

Parts: 518.18

Total: 1,248.18

Work Order: 2201560 **Meter:** 76413 **In Date:** 02/10/2022 **Closed:** 02/11/2022

Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued

Hours: 0.00

Comm: 90.40

Labor: 0.00

Parts: 0.00

Total: 90.40

2/1/2024
3:31:31 PM

Palm Beach County Fleet Management Asset Maintenance History
10198297 2015 FORD TRANSIT T350 Van, 1 Ton Cargo

Work Order: 2206202 **Meter:** 82737 **In Date:** 06/13/2022 **Closed:** 06/16/2022
Problem: PM Service.

Work Completed

- Preventive Maint. Service
- Rotate and speed balance, nitro fill
- Check all brakes, R & L new front brakes, R & L two front rotors, service caliper slide pins, bleed brakes, Road test
- Shop Supplies

Parts Issued

Quantity

Brake Pad	1.00
Brake Rotor	2.00
Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
Used Fire X Refurbished	1.00
Washer Fluid Concentr	1.00
Wiper Blade	1.00
Wiper Blade	1.00
White Lithium Grease	1.00
Shop Supplies	1.00

Hours: 9.00

Comm: 0.00

Labor: 657.00 Parts: 337.30 Total: 994.30

Work Order: 2209294 **Meter:** 89588 **In Date:** 09/06/2022 **Closed:** 09/08/2022
Problem: PM Service. drivers side front tire missing chunk of rubber

Work Completed

- Preventive Maint. Service
- Replaced 2 tires. Rotated and balanced al 4 tires. Nitrogen filled all tires.
- Battery tested bad. Charged battery fully and retested bad. Remove left front seat to replaced bad battery and reset Bms.
- Performed full front end alignment. Road test .
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
Wiper Blade	1.00
Wiper Blade	1.00
Napa Air Filter	1.00
235/65/16 Tire Hankook	2.00
Battry Motorcraft	1.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 10.00

Comm: 0.00

Labor: 730.00 Parts: 704.94 Total: 1,434.94

2/1/2024
3:31:31 PM

Palm Beach County Fleet Management Asset Maintenance History
10198297 2015 FORD TRANSIT T350 Van, 1 Ton Cargo

Work Order: 2212894 **Meter:** 94972 **In Date:** 12/28/2022 **Closed:** 01/09/2023
Problem: PM Service. Send for Detail.

Work Completed

Parts Issued

Quantity

- Preventive Maint. Service
- Balance And Rotate Tires With Nitro Fill
- Inspected Brakes, Rear Brake Pads At Minimum Deapth R&r Rear Pads, Rotors, And Service And Bleed Calipers Test Drive
- Shop Supplies

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
Washer Fluid Concentr	1.00
Wiper Blade	1.00
Wiper Blade	1.00
Fire Ext Mount Strap Style	1.00
Brake Pad	1.00
Seal	2.00
Rotor Brake	2.00
Shop Supplies	1.00

Hours: 9.00

Comm: 0.00

Labor: 657.00

Parts: 334.72

Total: 991.72

Work Order: 2300222 **Meter:** 94972 **In Date:** 01/09/2023 **Closed:** 01/09/2023
Problem: 1 - Detail Vehicle Wash Ticket(s) Issued WO: 2212894 for: carl loomis

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued Wo: 2212894 for: carl loomis

Hours: 0.00

Comm: 90.40

Labor: 0.00

Parts: 0.00

Total: 90.40

2/1/2024
3:31:31 PM

Palm Beach County Fleet Management Asset Maintenance History
10198297 2015 FORD TRANSIT T350 Van, 1 Ton Cargo

Work Order: 2304343 **Meter:** 100472 **In Date:** 05/01/2023 **Closed:** 05/12/2023
Problem: PM Service and A/C quite blowing .

Work Completed

- Performed P.m. Service & Inspection.
- Mount 2 Tires Then Balance & Rotate All 4 Wheels, Add Nitro Fill, Reset Tpms.
- Check Customer Concern, Performed A/c Cooling System Performance Test & Diag, Perform Pids Test Found A/c Blower Motor, Resistor & Relay Defective Removed & Replaced Cabin Air Filter, Blower Motor, Resistor & Relay Then Check. Working As Design.
- Performed Fuel & Induction Cleaning Service, Removed Throttle Body And Clean Then Check.
- Diagnose Engine Misfire .performed Tune-up, Removed & Replaced All 6 Spark Plugs Then Check Working As Design.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
Washer Fluid Concentr	1.00
Wiper Blade	1.00
Wiper Blade	1.00
Used Fire X Refurbished	1.00
235/65/16 Tire Gooyer	2.00
Relay	1.00
A/c Blower Regulator	1.00
A/c Blower	1.00
Cabin Filter	1.00
Throttle Body Cleaner	1.00
Motor Tune-up 16oz	1.00
Intake Cleaner Kit	1.00
Gasket	1.00
Gasket	1.00
Spark Plug	6.00
Pl Epoxy Syringe 25ml	1.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 15.00

Comm: 0.00

Labor: 1,095.00

Parts: 751.99

Total: 1,846.99

2/1/2024
3:31:31 PM

Palm Beach County Fleet Management Asset Maintenance History
10198297 2015 FORD TRANSIT T350 Van, 1 Ton Cargo

Work Order: 2308314 **Meter:** 106279 **In Date:** 08/18/2023 **Closed:** 08/30/2023
Problem: PM Service.

Work Completed

- Preventive Maint. Service
- rotate and balance all 4 tires nitro fill all
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
Washer Fluid Concentr	1.00
Wiper Blade	1.00
Wiper Blade	1.00
Shop Supplies	1.00

Hours: 5.00

Comm: 0.00

Labor: 365.00

Parts: 70.19

Total: 435.19

Work Order: 2400289 **Meter:** 109646 **In Date:** 01/09/2024 **Closed:** 01/09/2024
Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00

Comm: 0.00

Labor: 146.00

Parts: 0.00

Total: 146.00

Total Hours: 177.10

Total Labor: 12,305.00

Total Comm: 756.80

Total Parts: 8,767.10