

2/1/2024
4:04:37 PM

Palm Beach County Fleet Management Asset Maintenance History
10198020 2015 JACOBSON GROOM MASTER II Ballfield Groomer

Total Hours: 94.75 Labor: 6,507.25 Parts: 2,086.85 Comm: 0.00 Charged: 8594.10

Work Order: 1502402 **Meter:** 1 **In Date:** 03/06/2015 **Closed:** 03/06/2015
Problem: 1061 - Pre Delivery Inspection

Work Completed

- Pre Delivery Inspection

Hours: 2.00 Comm: 0.00 Labor: 120.00 Parts: 0.00 Total: 120.00

Work Order: 1602033 **Meter:** 224 **In Date:** 02/26/2016 **Closed:** 03/08/2016
Problem: P.M.SERVICE

Work Completed

- pm
- svc hyd sys rr filter inspect lines hoses etc correct fluid level
- wash eq
- Shop Supplies

Parts Issued

Quantity

Napagold Air Filter	1.00
Napagold Oil Filter	1.00
15w40 Bulk South Reg	4.00
Napagold Fuel Filter	1.00
Napa Trans Filter	1.00
Shop Supplies	1.00

Hours: 6.00 Comm: 0.00 Labor: 360.00 Parts: 37.69 Total: 397.69

Work Order: 1703315 **Meter:** 417 **In Date:** 04/03/2017 **Closed:** 04/17/2017
Problem: PM Service

Work Completed

- Pm Service.
- Service hyd.system.inspect lines,hoses,fittings,etc..replace filter.correct fluid level.
- Wash equipment.
- Shop Supplies

Parts Issued

Quantity

Napagold Air Filter	1.00
Napagold Fuel Filter	1.00
Napagold Oil Filter	1.00
15w40 Bulk South Reg	4.00
Napa Trans Filter	1.00
Aw68 Bulk Sr	1.00
Shop Supplies	1.00

Hours: 6.50 Comm: 0.00 Labor: 390.00 Parts: 40.51 Total: 430.51

2/1/2024
4:04:37 PM

Palm Beach County Fleet Management Asset Maintenance History
10198020 2015 JACOBSON GROOM MASTER II Ballfield Groomer

Work Order: 1704387 **Meter:** 433 **In Date:** 05/01/2017 **Closed:** 05/22/2017

Problem: Hard start.Trottle link binding.

Work Completed

- C/c Hard start.verify fuel shut off solenoid not retracting.r/r Solenoid and linkage.
- Shop Supplies

Parts Issued

Quantity

Solenoid Fuel	1.00
Ball Joint	1.00
Threaded Rod	1.00
Hex Nut 1/4-28	2.00
Nut	1.00
Shop Supplies	1.00

Hours: 3.00

Comm: 0.00

Labor: 180.00 Parts: 315.56 Total: 495.56

Work Order: 1803783 **Meter:** 480 **In Date:** 04/11/2018 **Closed:** 04/23/2018

Problem: pm/ fuel rod/ see notes

Work Completed

- pm service
- hard to start. replace fuel solenoid and rod with ball
- replace asset numbers
- Shop Supplies

Parts Issued

Quantity

Napagold Air Filter	1.00
Napagold Fuel Filter	1.00
15-40 Oil	4.00
Pm-22-a Additive Dies	1.00
Napagold Oil Filter	1.00
Ball Joint	1.00
Solenoid Fuel	1.00
Shop Supplies	1.00

Hours: 6.50

Comm: 0.00

Labor: 390.00 Parts: 299.98 Total: 689.98

Work Order: 1804993 **Meter:** 498 **In Date:** 05/14/2018 **Closed:** 07/19/2018

Problem: fuel solenoid rod

Work Completed

- replace solenoid and bracket
- Shop Supplies

Parts Issued

Quantity

Fuel Solenoid Brkt	1.00
Solenoid Fuel	1.00
Shop Supplies	1.00
Freight Charge	1.00

Hours: 3.00

Comm: 0.00

Labor: 180.00 Parts: 386.16 Total: 566.16

2/1/2024
4:04:37 PM

Palm Beach County Fleet Management Asset Maintenance History
10198020 2015 JACOBSON GROOM MASTER II Ballfield Groomer

Work Order: 1810914 **Meter:** 543 **In Date:** 10/23/2018 **Closed:** 11/13/2018
Problem: Wont start after multiple times then will finally start.

Work Completed

Parts Issued

Quantity

- C/c hard to get started.adjust traction pedal and proximity switch.
- Adjust E-brake
- Shop Supplies

Shop Supplies 1.00

Hours: 2.50 Comm: 0.00 Labor: 167.50 Parts: 3.00 Total: 170.50

Work Order: 1905516 **Meter:** 657 **In Date:** 05/23/2019 **Closed:** 06/26/2019
Problem: P.M.SERVICE

Work Completed

Parts Issued

Quantity

- Pm Service.
- Service hyd.system.inspect all.replace filter.correct fluid level.
- Replace battery.install new terminals on wiring.
- Wash equipment.
- Shop Supplies

Napagold Air Filter 1.00

Napagold Fuel Filter 1.00

15w40 Bulk South Reg 4.00

Napagold Oil Filter 1.00

Napa Trans Filter 1.00

Battery Terminals 1.00

Battery 1.00

Fuel Filter 1.00

Shop Supplies 1.00

Freight Charge 1.00

Hours: 7.25 Comm: 0.00 Labor: 485.75 Parts: 196.30 Total: 682.05

2/1/2024
4:04:37 PM

Palm Beach County Fleet Management Asset Maintenance History
10198020 2015 JACOBSON GROOM MASTER II Ballfield Groomer

Work Order: 2009272 **Meter:** 819 **In Date:** 09/16/2020 **Closed:** 09/28/2020
Problem: PM Service.

Work Completed

- Pm Service.
- Service hyd.system.replace filters.
- Replace engine V-belt.
- Replace fuel cap.
- Wash equipment.
- Shop Supplies

Parts Issued

Quantity

Napagold Air Filter	1.00
Napagold Air Filter	1.00
Napagold Fuel Filter	1.00
15w40 Bulk South Reg	4.00
Napagold Oil Filter	1.00
Aw68 Bulk Sr	2.00
Napa Trans Filter	1.00
Diesel Fuel Cap	1.00
Fuel Element	1.00
V-belt	1.00
Shop Supplies	1.00

Hours: 7.25 Comm: 0.00 Labor: 529.25 Parts: 103.95 Total: 633.20

Work Order: 2100379 **Meter:** 819 **In Date:** 01/12/2021 **Closed:** 01/14/2021
Problem: Cannot switch off engine.

Work Completed

- Customers complaint unit will not turn off. Replace broken ball joint connector for fuel shut off solenoid, adjust linkage and test run.
- Wash unit for diagnosis and repairs.
- Shop Supplies

Parts Issued

Quantity

Ball Joint	1.00
Shop Supplies	1.00

Hours: 3.00 Comm: 0.00 Labor: 219.00 Parts: 49.80 Total: 268.80

2/1/2024
4:04:38 PM

Palm Beach County Fleet Management Asset Maintenance History
10198020 2015 JACOBSON GROOM MASTER II Ballfield Groomer

Work Order: 2106177 **Meter:** 849 **In Date:** 06/07/2021 **Closed:** 06/09/2021

Problem: Will not switch off after start up.

Work Completed

Parts Issued

Quantity

- Customers complaint unit will not turn off. Remove fuel shut off solenoid, repair linkage and injection pump arm. Reinstall solenoid, test drive.

Shop Supplies

1.00

- Found traction pedal out of adjustment unit is creeping, Adjust traction pedal linkage

- Shop Supplies

Hours: 4.00

Comm: 0.00

Labor: 292.00

Parts: 4.00

Total: 296.00

Work Order: 2110126

Meter: 853

In Date: 09/17/2021 **Closed:** 09/24/2021

Problem: PM Service.

Work Completed

Parts Issued

Quantity

- Pm Service

Napagold Air Filter

1.00

- Service hydraulic system, replace filter, correct fluid level

Napagold Air Filter

1.00

- Wash equipment of clay and debris for service and repairs.

Napagold Fuel Filter

1.00

- Verify battery is Dead, recharge and load test battery failed load test.

Fuel Element

1.00

- Shop Supplies

15w40 Bulk South Reg

4.00

Napagold Oil Filter

1.00

Aw68 Bulk Sr

2.00

Napa Trans Filter

1.00

Battery

1.00

Shop Supplies

1.00

Hours: 6.75

Comm: 0.00

Labor: 492.75

Parts: 150.35

Total: 643.10

2/1/2024
4:04:38 PM

Palm Beach County Fleet Management Asset Maintenance History
10198020 2015 JACOBSON GROOM MASTER II Ballfield Groomer

Work Order: 2205812 **Meter:** 853 **In Date:** 06/01/2022 **Closed:** 06/02/2022

Problem: Machine wont start also linkage loose and pin missing for hood.

Work Completed

- C/c wont start. Trouble shoot electrical starting system, found loose terminal connection, repair, battery passed load test.

- C/c wont stay running. Verify broken fuel cap contaminated fuel tank, fuel pump inoperable. Replace fuel cap, fuel pump, fuel filter. Remove and clean out contaminated fuel tank. Reinstall.

- Shop Supplies

Hours: 5.00

Comm: 0.00

Labor: 365.00

Parts: 251.56

Total: 616.56

Parts Issued

Quantity

Fuel Element	1.00
Diesel Fuel Cap	1.00
Pump Assmb;y Fuel	1.00
Shop Supplies	1.00

Work Order: 2210254 **Meter:** 860 **In Date:** 10/05/2022 **Closed:** 10/13/2022

Problem: PM Service.

Work Completed

- Preventive Maint. Service

- Service hydraulic system, replace filter, inspect all , correct fluid level.

- Customers complaint plow wont stay up. Repair and lubricate supporting latch

- Shop Supplies

Hours: 6.00

Comm: 0.00

Labor: 438.00

Parts: 61.96

Total: 499.96

Parts Issued

Quantity

Napagold Air Filter	1.00
Napagold Air Filter	1.00
Fuel Element	1.00
Napagold Fuel Filter	1.00
15w40 Bulk South Reg	4.00
Napagold Oil Filter	1.00
Aw68 Bulk Sr	2.00
Napa Trans Filter	1.00
Shop Supplies	1.00

2/1/2024
4:04:38 PM

Palm Beach County Fleet Management Asset Maintenance History
10198020 2015 JACOBSON GROOM MASTER II Ballfield Groomer

Work Order: 2211555 **Meter:** 868 **In Date:** 11/15/2022 **Closed:** 11/30/2022

Problem: Steering is bad. Needs adjustment.

Work Completed

- Customers complaint steering. Verify after test drive the steering is drifting, cylinder is bypassing internally. Remove and rebuild steering cylinder, reinstall, correct fluid level and test drive.

- Stock Parts entry

- Shop Supplies

Hours: 4.00

Comm: 0.00

Parts Issued

Quantity

Aw68 Bulk Sr	2.00
Seal Kit	1.00
Shop Supplies	1.00
Freight Charge	1.00

Labor: 292.00

Parts: 72.18

Total: 364.18

Work Order: 2302065 **Meter:** 915 **In Date:** 03/01/2023 **Closed:** 03/02/2023

Problem: Wont go full speed. Wont shut off when turn off.

Work Completed

- Customers complaint wont shut off, verify fuel shut off is out of adjustment. Remove and adjust fuel shut off solenoid linkage.

- Customers complaint wont go full speed, verify creeps forward, adjust traction and pump linkage.

- Shop Supplies

Hours: 4.00

Comm: 0.00

Parts Issued

Quantity

Shop Supplies	1.00
---------------	------

Labor: 292.00

Parts: 2.65

Total: 294.65

Work Order: 2304394 **Meter:** 928 **In Date:** 05/02/2023 **Closed:** 05/16/2023

Problem: PM Service. Foot pedal mechanism, throttle cable, steering issue, rear lift frame is bent.

Work Completed

- Pm Service

- Service hydraulic system, replace filter, correct fluid level

- C/c foot pedal mechanism. Repair and adjust traction linkage,

- Verify unit hesitates to shut off. Remove fuel shut off solenoid, clean contacts and magnet, reinstall, adjust linkage and injection pump. test run.

- Shop Supplies

Hours: 8.00

Comm: 0.00

Parts Issued

Quantity

Napagold Air Filter	1.00
Napagold Air Filter	1.00
Fuel Element	1.00
Napagold Fuel Filter	1.00
15w40 Bulk South Reg	4.00
Napagold Oil Filter	1.00
Aw68 Bulk Sr	2.00
Napa Trans Filter	1.00
Shop Supplies	1.00

Labor: 584.00

Parts: 62.39

Total: 646.39

2/1/2024
4:04:38 PM

Palm Beach County Fleet Management Asset Maintenance History
10198020 2015 JACOBSON GROOM MASTER II Ballfield Groomer

Work Order: 2310524 **Meter:** 929 **In Date:** 10/18/2023 **Closed:** 10/19/2023
Problem: Stays in reverse when let off the gas.

Work Completed

Parts Issued

Quantity

- C/c stays in reverse. Verify nut for hydraulic motor backed off, adjust, install lock tight, test drive.

Shop Supplies 1.00

- Shop Supplies

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 2.65 Total: 148.65

Work Order: 2310649 **Meter:** 929 **In Date:** 10/23/2023 **Closed:** 10/25/2023
Problem: PM

Work Completed

Parts Issued

Quantity

- Preventive Maint. Service
- Service hydraulic system, replace filter, correct fluid level.
- Replace missing hardware on rake teeth blades. repair and reassemble.
- Shop Supplies

Napagold Oil Filter 1.00

15w40 Bulk South Reg 4.00

Napagold Fuel Filter 1.00

Fuel Element 1.00

Napagold Air Filter 1.00

Napagold Air Filter 1.00

Shop Supplies 1.00

Hours: 6.00 Comm: 0.00 Labor: 438.00 Parts: 46.20 Total: 484.20

Work Order: 2400268 **Meter:** 929 **In Date:** 01/09/2024 **Closed:** 01/09/2024
Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 0.00 Total: 146.00

Total Hours: 94.75 Total Labor: 6,507.25 Total Comm: 0.00 Total Parts: 2,086.85