2/29/2024 1:08:24 PN			Paln		anagement Asset Maintenar ORD E250 Van, 3/4 Ton, Car				
Total Hours: 1	161.35	Labor: 11,13	8.05	Parts: 6,608.98	Comm: 1,125.30		Charged	: 18872.33	
Work Order: Problem:		4 Pre Delivery Ins	Meter:	349		In Date:	09/11/2014	Closed:	09/11/2014
Work Com	pleted								
- Pre Deliv	ery Inspe	ection							
		Hours: 2.00		Comm: 0.00	Labor: 120.00	Parts: 0.0	0	Total:	120.00
Work Order: Problem:			Meter:	7645		In Date:	04/30/2015	Closed:	05/07/2015
Work Com	pleted				Parts Issued			Qı	antity
- Pm servio	ce.				5w20 Engine Oil				6.00
- Rotate ar	nd balan	ce all four tires.			Napagold Oil Filter				1.00
- Shop Sup	oplies				Used Fire X Refurbis	hed			1.00
					Shop Supplies				1.00
		Hours: 5.00		Comm: 0.00	Labor: 300.00	Parts: 37	.18	Total:	337.18
Work Order: Problem:		3 ont and right re	Meter: ar tires f			In Date:	10/01/2015	Closed:	10/13/2015
Work Com	pleted				Parts Issued			Qı	antity
- Repair ar	nd balan	e right front ar	nd right r	ear tires.	Shop Supplies				1.00
- Shop Sup		0	0						
		Hours: 2.00		Comm: 0.00	Labor: 120.00	Parts: 2.0	0	Total:	122.00
Work Order: Problem:		-	Meter:	14641		In Date:	01/06/2016	Closed:	01/20/2016
Work Com	pleted				Parts Issued			Qı	antity
- Pm servio	ce.				5w20 Engine Oil				6.00
		ce all four whee	ls.		Napagold Oil Filter				1.00
- Shop Sup	oplies				20" Wiper Blade				2.00
					Washer Fluid Conce	ntr			1.00
					Shop Supplies				1.00
		Hours: 5.00		Comm: 0.00	Labor: 300.00	Parts: 26	69	Total:	326.69

# Palm Beach CountyFleet Management Asset Maintenance History101952462014 FORD E250 Van, 3/4 Ton, Cargo

Nork Order: 1612519 Problem: P.M. service.	Meter:	23869		In Date:	12/07/2016	Closed:	12/27/2016
Work Completed			Parts Issued			Qı	uantity
- P.m. Service.			Napagold Oil Filter				1.00
- Rotate and balance tires.			5w20 Engine Oil				7.00
- Shop Supplies			20" Wiper Blade				2.00
			Napagold Air Filter				1.00
			Used Fire X Refurbis	hed			1.00
			Shop Supplies				1.00
Hours: 5.00		Comm: 0.00	Labor: 300.00	Parts: 52.	81	Total:	352.81
Vork Order: 1709271 Problem: P.M. Service. Work Completed	Meter:	30902	Parts Issued	In Date:	09/25/2017		10/05/2017 Jantity
- P.m. service.			5w20 Engine Oil			4	7.00
	ck alactrical a	stom roplace had	Napagold Oil Filter				1.00
- Battery failed load test after recharge.chee battery.	ik electrical sy		20" Wiper Blade				2.00
- Flush and refill transmission fluid.			Washer Fluid Conce	ntr			1.00
- Rotate and balance four tires.nitrofill.			Used Fire X Refurbis				1.00
- Shop Supplies			Battery 65				1.00
			Syn-atf Trans Fluid S	5			14.00
			Shop Supplies				1.00
			Shop Supplies				

2/29/2024 1:08:24 PM

Meter: 34884

## Work Order:1802381Problem:A/C inop after driving awhile.

### In Date: 03/02/2018 Closed: 03/12/2018

Work Compl	eted		Parts Issued			Qı	uantity	
- Perform A/o	c performance test.replace defec	tive condensor	Condenser				1.00	
	orifice tube and seals.evacculate		A/c Accumulato				1.00	
spec.			Orifice Tube Filter Seal Kits			1.00		
- Shop Suppl	ies						2.00	
			Seal				1.00	
			Freon Lv Shop 2				2.00	
			Wire Assy				1.00	
			Shop Supplies		1.00			
	Hours: 5.50	Comm: 0.00	Labor: 330.00	Parts: 554	4.81	Total:	884.81	
Work Order: 18	805434	Meter: 37363		In Date:	05/29/2018	Closed:	06/05/2018	
Problem: P	.M. service and towed in for righ	t rear tire flat.						
Work Compl	eted		Parts Issued			Qu	uantity	
- P.m. service	۱.		Napagold Oil Filter				1.00	
- Mount and	high speed balance four new tir	es. Nitrogen fill tires.	5w20 Engine Oil				7.00	
- Complete fi	ront end alignment.		22" Wiper Blade				2.00	
- Shop Suppl	ies		Used Fire X Refurbis	hed			1.00	
			744395900 245-75r	16			4.00	
			Shop Supplies				1.00	
			Tire Disposal Fee				4.00	
	Hours: 8.50	Comm: 0.00	Labor: 510.00	Parts: 847	7.66	Total:	1,357.66	
Nork Order: 18	805655	Meter: 37204		In Date:	05/11/2018	Closed:	06/04/2018	
Problem: P	assenger Rear Flat / PM Service	9						
Work Compl	eted							
- Tow From: 2	20125 southern blvd To: Lv shop	)						
	Hours: 0.00	Comm: 96.00	Labor: 0.00	Parts: 0.0	0	Total:	96.00	

Vork Order: 1813022 Problem: P.M. service a		41284		In Date:	12/26/2018	Closed:	12/31/2018	
Work Completed			Parts Issued			Qı	antity	
- P.m. service.			Napagold Oil Filter				1.00	
- Test and replace blow fu	ise for power outlet and test fo	r shorts .	Napa Quart 5w20			7.00		
- Rotate and high speed b		22" Wiper Blade			2.00			
- Shop Supplies			Washer Fluid Concentr			1.00		
1 11			Bp Fmx-lp F Mx Fuse				1.00	
			Shop Supplies				1.00	
Hours	s: 5.50	Comm: 0.00	Labor: 368.50	Parts: 48.	69	Total:	417.19	
Nork Order: 1900109 Problem: A/C only blows Work Completed		41288	Parts Issued	In Date:	01/03/2019		01/10/2019 Jantity	
•						QL	antity	
- A/c performance test . Vacuum test . Replace vacuum li			M/M/Vacuum Tubing				6.00	
check valve Retest A/c on	•	ine and canister and	W W Vacuum Tubing				6.00	
check valve . Retest A/c op	•	ine and canister and	Vacuum Resevoir				1.00	
check valve . Retest A/c op - Shop Supplies	•	ne and canister and	Vacuum Resevoir A/c Valve				1.00 1.00	
- Shop Supplies	beration .		Vacuum Resevoir A/c Valve Shop Supplies		27	Total	1.00 1.00 1.00	
- Shop Supplies Hours	s: 4.50 Meter:	Comm: 0.00 45509	Vacuum Resevoir A/c Valve	Parts: 34. In Date:	37 06/10/2019		1.00 1.00	
- Shop Supplies Hours Nork Order: 1906086	s: 4.50 Meter:	Comm: 0.00	Vacuum Resevoir A/c Valve Shop Supplies	Parts: 34.	-	Closed:	1.00 1.00 1.00 335.87	
- Shop Supplies Hours Work Order: 1906086 Problem: make spare ke	s: 4.50 Meter:	Comm: 0.00	Vacuum Resevoir A/c Valve Shop Supplies Labor: 301.50	Parts: 34. In Date:	-	Closed:	1.00 1.00 1.00 335.87 06/17/2019	

Meter: 46022

### Work Order: 1906800 Problem: PM Service

#### 06/28/2019 Closed: 07/16/2019 In Date:

Work Completed		Parts Issued	Quantity		
- P.m. service.		Drain Plug		1.00	
- Pressure test and inspect cooling system . Flus	h and refill .	Napagold Oil Filte	r	1.00	
- Diagnose noise in steering . R&r binding interr	mediate shaft . Retest	5w20 Engine Oil	7.00		
- Balance and rotate all four tires . Nitrofill all.		Used Fire X Refurb	1.00		
- Shop Supplies		22" Wiper Blade		2.00	
		Peak Global Antifr	Z	1.00	
		Shaft Assy		1.00	
		Shop Supplies		1.00	
Hours: 9.00	Comm: 0.00	Labor: 603.00	Parts: 310.04	Total: 913.04	

Work Order: 2000121 Meter: 49746 Problem: PM Service, Auxillary port works for a minute then shuts off.

01/06/2020 Closed: 01/24/2020 In Date:

**Work Completed** Parts Issued 5w20 Engine Oil - P.m. service. Napagold Oil Filter - Test and replace defective auxiliary power outlet . Washer Fluid Concentr - Perform complete tune up . Replace all eight spark plugs . 22" Wiper Blade - Perform complete air intake decarb and cleaning . Flush injectors . Clean throttle body. Napagold Air Filter - Inspect and service rear differential . Drain and refill and reseal . Base Asy - Rotate and balance all four tires . Nitrofill all . Knob And E - Shop Supplies luminous Spark Plug Intake Cleaner Kit Motor Tune-up 16oz Throttle Body Cleaner 75w140 Ford Axle Lube Px Grey Rtv Silicone

Labor: 927.10

Parts: 324.30

Shop Supplies

Total: 1,251.40

Quantity

7.00

1.00

1.00

2.00

1.00

1.00

1.00

1.00

8.00

1.00

1.00

1.00

4.00

1.00

1.00

## Palm Beach CountyFleet Management Asset Maintenance History101952462014 FORD E250 Van, 3/4 Ton, Cargo

Nork Order:	2007262	Meter: 50001		In Date: 07/24/20	20 Closed:
Problem:	Weather stripping came loos	e on windshield, Drivers windo	w scratched by weathe	r stripping.	
Work Com	pleted				
-	Hours: 0.00	Comm: 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
Nork Order: Problem:		Meter: 50277 rter installed as per Chris Cava	lier.	<b>In Date:</b> 08/28/20	020 <b>Closed:</b> 09/30/202
Work Com	pleted		Parts Issued		Quantity
- Pm Servi	ce.		Napagold Oil Filt	er	1.00
- Repaired	l third brake light.		Napa Quart 5w2	0	7.00
- Install ne	ew inverter and circuitbreaker.	abricate and make up power a	nd 22" Wiper Blade		2.00
ground cat	ples to mount inverter on part	ician in van.	Washer Fluid Cor	ncentr	1.00
- Rotate ar	nd balance tires.		Boxed Miniature	5	2.00
- Install ho	ow is my driving decal.		Bulk Battery Cab	le	25.00
- Service la	adder rack.		Cabl/lug		6.00
- Shop Sup	oplies		Vinyl Electrical Ta	аре	1.00
			Power Inverter		1.00
			Used Fire X Refu	rbished	1.00
			Cb185-100 Cir Bi	ŕkr	1.00
			Shop Supplies		1.00
	Hours: 11.50	Comm: 0.00	Labor: 839.50	Parts: 462.70	Total: 1,302.20
Nork Order: Problem:		Meter: 50470 water damage, possibly chang	e mats & liner	In Date: 11/05/20	020 Closed:
Work Com	pleted				
- Cab Misc	•				

Hours: 0.00

Comm: 0.00

Labor: 0.00

Parts: 0.00

Total: 0.00

## Work Order:2011255Meter:50520Problem:check for water damage, rear of van submerged

### **In Date:** 11/10/2020 **Closed:** 12/04/2020

Work Completed		Parts Issued	Quantity		
- Remove inside shelving and seats. remove	rubber floor mate and padding	Oil Rear Axle	2.00		
to dry flooring and prpe to install new floor n		Px Grey Rtv Silicon			
mat.		Napagold Oil Filter		1.00	
- service rear differential, water contaminatic		Napa Quart 5w20		14.00	
- service engine filter and oil , contaminated.		Non-chlor Brake Cl	nr		2.00
- service transmission filter and fluid , contain	minated.	Gasket			1.00
- check all brakes ;repack front bearings	Filter			1.00	
- replace power inverter	oil auto		10.00		
- Shop Supplies		Mat			1.00
		Front Mat			1.00
		Таре			1.00
		Power Inverter			1.00
		Shop Supplies			1.00
Hours: 31.00	Comm: 0.00	Labor: 2,263.00	Parts: 1,533.04	Total:	3,796.04
/ork Order: 2011258	Meter: 50470		In Date: 11/05/2020	Closed:	11/10/2020
Problem: Flooded Undercarriage issues					
Work Completed					
- Tow From: 13026 Jog Rd (sr Shop) To: Se sł	hop				
Hours: 0.00	Comm: 96.00	Labor: 0.00	Parts: 0.00	Total:	96.00
Vork Order: 2012239	Meter: 50520		In Date: 10/23/2020	Closed:	12/09/2020
<b>Problem:</b> Stuck in MudMarla Smith call fo	r winch out 561 740 4588				
Work Completed					
- Tow From: 12751 Hagen Ranch Road Boyn	ton To:				
Hours: 0.00	Comm: 696.00	Labor: 0.00	Parts: 0.00	Total:	696.00

2/29/2024 1:08:24 PM

	2012844 Will not start.	<b>Meter:</b> 50718		In Date:	12/28/2020	Closed:	12/29/2020
Work Com	pleted		Parts Issued			Qı	uantity
- Diagnose	e and replace starter motor assen	nbly.had to go to system #3 and	Starter				1.00
0	n starter to start and drive vehicle	, , ,	Shop Supplies				1.00
- Shop Sup	pplies						
	Hours: 2.00	Comm: 0.00	Labor: 146.00	Parts: 224	1.40	Total:	370.40
Vork Order: Problem:	2100752 Engine misfires and check engi	Meter: 50833 ne light on.		In Date:	01/21/2021	Closed:	02/01/202
Work Com	pleted		Parts Issued			Qı	antity
- c/s check	k engine light is on. scan, found c	ode # P0300, P0307 & P0316,	Ford Ignition Coil				3.00
remove en	gine cover/dog house, perform p	Spark Plug				8.00	
	plugs. Replace 3 coil, 8 spark plug	gs, air filter and clear codes.	Napagold Air Filter				1.00
- test drive	e before and after repair.		Shop Supplies				1.00
- repair an	nd balance right rear tire.						
- Shop Sup							
	Hours: 7.00	Comm: 0.00	Labor: 511.00	Parts: 243	3.28	Total:	754.28
Vork Order: Problem:	2103860 PM Service.Check climate cont	Meter: 51163 rols functions.		In Date:	04/06/2021	Closed:	04/09/202
Work Com	pleted		Parts Issued			Qu	uantity
	<b>pleted</b> ve Maint. Service		<b>Parts Issued</b> Washer Fluid Conce	ntr		Qı	<b>antity</b> 1.00
- Preventiv	ve Maint. Service	r tail light.		ntr		Qı	•
- Preventiv - Right fro	•	-	Washer Fluid Conce	ntr		Qı	1.00
- Preventiv - Right fro - Diagnos	ve Maint. Service ont head light and repair right rea	-	Washer Fluid Conce 22" Wiper Blade	ntr		Qı	1.00 2.00
- Preventiv - Right fro - Diagnos a/c blend c	ve Maint. Service ont head light and repair right rea se climate control and found bad	-	Washer Fluid Conce 22" Wiper Blade Napagold Oil Filter	ntr		Qı	1.00 2.00 1.00
- Preventiv - Right fro - Diagnos a/c blend c	ve Maint. Service ont head light and repair right rea se climate control and found bad door actuator. adder rack.	-	Washer Fluid Conce 22" Wiper Blade Napagold Oil Filter Napa Quart 5w20			Qı	1.00 2.00 1.00 7.00
- Preventiv - Right fro - Diagnos a/c blend c - Service la	ve Maint. Service ont head light and repair right rea se climate control and found bad door actuator. adder rack.	-	Washer Fluid Conce 22" Wiper Blade Napagold Oil Filter Napa Quart 5w20 Napagold Air Filter			Qı	1.00 2.00 1.00 7.00 1.00
- Preventiv - Right fro - Diagnos a/c blend c - Service la	ve Maint. Service ont head light and repair right rea se climate control and found bad door actuator. adder rack.	-	Washer Fluid Conce 22" Wiper Blade Napagold Oil Filter Napa Quart 5w20 Napagold Air Filter Halogen Sealed Bea			Q.	1.00 2.00 1.00 7.00 1.00 1.00

Work Order: 2202819 Meter: 52219 03/15/2022 **Closed:** 03/21/2022 In Date: Problem: NO START, PM Service, Field Action 20L02: Insert for Owner's Manual Quantity **Work Completed** Parts Issued Washer Fluid Concentr 1.00 - Preventive Maint, Service 22" Wiper Blade 2.00 - Perform battery charging and load test analyzing, failed, R & I new batter Napagold Oil Filter 1.00 - Rotate and speed balance all 4 tires, nitro fill 5w20 Engine Oil 7.00 - Check wiring circuit to alarm, inop. R & I new back up alarm Used Fire X Refurbished 1.00 - Shop Supplies Battery 1.00 Alarm 1.00 Shop Supplies 1.00 Hours: 6.80 Comm: 0.00 Parts: 208.97 Labor: 496.40 Total: 705.37 Work Order: 2203446 Meter: 52378 **In Date:** 03/15/2022 **Closed:** 03/29/2022 Problem: NO START **Work Completed** - Tow From: 8100 Forest Hill Blvd, Wpb (croc ) To: Fleet Wpb Lv Shop Hours: 0.00 Comm: 113.00 Labor: 0.00 Parts: 0.00 Total: 113.00 Work Order: 2212109 Meter: 53040 In Date: 12/01/2022 Closed: 12/16/2022 Problem: PM Service. Parts Issued **Work Completed** Quantity Drain Plug 1.00 - Preventive Maint. Service Napagold Oil Filter 1.00 - rotate balanced 4 tires reset tpms Napa Quart 5w30 8.00 - replaced missing how's my driving sticker 22" Wiper Blade 2.00 - Shop Supplies Shop Supplies 1.00 Hours: 5.50 Comm: 0.00 Labor: 401.50 Parts: 50.41 Total: 451.91

Meter: 53150

## Work Order: 2305759

#### 06/09/2023 **Closed:** 06/15/2023 In Date:

1.00

7.00

2.00

1.00

4.00

1.00

1.00

1.00

1.00

1.00

1.00

1.00

1.00

4.00

#### Problem: PM Service. AC NOT WORKING Parts Issued Quantity **Work Completed** - Performed P.m. Service & Inspection. Napagold Oil Filter 5w20 Engine Oil - Mount & Balance 4 New Tires, Add Nitro Fill Reset Tpms. 22" Wiper Blade - Performed Front Wheel Alignment & Test Drove Vehicle. Used Fire X Refurbished - A/c Inop, Performed A/c Cooling System Performance, Diagnosie Vehicle & Perform Pids Point Test, Found A/c Blower Motor And Resistor Defective. Lt245/75r16/10 Mich Agilis Removed & Replaced, Then Check. Blower Motor Resistor - Load Test Battery, Battery Test Recommend Charge. Charged Battery & Non-chlor Brake Clnr Retest Working As Design. Brake Fl-dot 3-4 32oz - Rear Brake Pads Were Below Manufacture Specs, Removed Rear Brake Blower Motor Assy Calipers, Pads And Rotors, Then Resurface Both Rear Brake Rotors, Replaced The Calipers And Pads, Bleed & Flush Entire Brake System. Test Drove Brake Pads Vehicle Burnish Brakes. Brake Caliper - Shop Supplies Brake Caliper Shop Supplies Tire Disposal Fee Hours: 15.60 Comm: 0.00 Labor: 1,138.80 Parts: 1,240.43 Total: 2,379.23 Work Order: 2309490 09/19/2023 Closed: Meter: 56300 In Date: Problem: broken down in middle of road

### **Work Completed**

	Hours: 0.00		Comm: 0.00	Labor: 0.00	Parts: 0.00	)	Total:	0.00
Work Order: Problem:	2309942 broken down in middle of road	Meter:	56300		In Date:	09/19/2023	Closed:	09/28/2023
Work Com	pleted							
- Tow Fror	n: East bound lake worth rd, E of pineł	nurst To:	fleet vista Lv shop					
	Hours: 0.00		Comm: 124.30	Labor: 0.00	Parts: 0.00	)	Total:	124.30

2/29/2024 1:08:24 PM		Palm	Beach County 10195246	leet Management Asset Maintenance 2014 FORD E250 Van, 3/4 Ton, Cargo	History			
Work Order:	2311537	Meter:	56300	In	n Date:	11/17/2023	Closed:	11/17/2023
Problem:	Transition Prep Charg	e						
Work Com	pleted							
- Transitio	n Prep Charge							
	Hours: 2.00		Comm: 0.00	Labor: 146.00 P	arts: 0.00		Total:	146.00
Total Hours:	161.35 Total	Labor: 11	,138.05	Total Comm: 1,125.30		Total Parts:	6,608.98	