2/29/2024 1:16:01 PI		Paln 10198283		anagement Asset Maintena T250 Van, 3/4 Ton, Cargo	nce History					
Total Hours: 133.00 Labor: 9,124.5			Parts: 5,697.92	Comm: 1,007.16		Charged: 15829.57				
Work Order:		Meter:	344		In Date:	09/24/2015	Closed:	09/24/2015		
Problem:	1061 - Pre Delivery	Inspection								
Work Con	npleted									
- Pre Deliv	very Inspection									
	Hours: 2.00	C	Comm: 0.00	Labor: 120.00	Parts: 0.0	00	Total:	120.00		
Work Order: Problem:	1603730 P.M. service.	Meter:	4917		In Date:	04/08/2016	Closed:	04/19/2016		
Work Con	npleted			Parts Issued			Q	uantity		
- P.m. Serv	vice.			Filter				1.00		
- Rotate a	nd balance all tires.			5w20 Engine Oil				6.00		
- Shop Su	pplies			Washer Fluid Conce	entr			1.00		
				Used Fire X Refurbis	shed			1.00		
				Shop Supplies				1.00		
	Hours: 5.00	C	Comm: 0.00	Labor: 300.00	Parts: 39	.55	Total:	339.55		
Work Order: Problem:	1610725 P.M. service and sp	Meter: ray for ants			In Date:	10/18/2016	Closed:	10/31/2016		
Work Com	npleted			Parts Issued			Qı	uantity		
- P.m. Serv	vice.			5w20 Engine Oil				6.00		
- Rotate a	nd balance all tires.			Washer Fluid Conce	entr			1.00		
- Shop Su	pplies			Napagold Oil Filter				1.00		
-				Wiper Blade - Accuf	fit - Passeng	er's Side		1.00		
				Accufit Beam				1.00		
				Shop Supplies				1.00		
	Hours: 5.00	C	Comm: 0.00	Labor: 300.00	Parts: 53	.26	Total:	353.26		

Work Order: Problem:	1610953 1 - Detail Vehicle Wash Ticket(s	Meter:) Issued	10896		In Date:	10/24/2016	Closed:	10/24/2016
Work Com	pleted							
- 1 - Detai	l Vehicle Wash Ticket(s) Issued							
	Hours: 0.00		Comm: 96.00	Labor: 0.00	Parts: 0.0	0	Total:	96.00
Nork Order: Problem:	1704457 P.M. service .	Meter:	15942		In Date:	05/03/2017	Closed:	05/18/2017
Work Com	pleted			Parts Issued			Qı	antity
- P.m. serv	ice.			5w20 Engine Oil				6.00
- Balance a	and rotate all four tires.	Napagold Oil Filter		1.00				
- Transpor	t to and from dealer for rear diffe	rential leak.		Wiper Blade - Accu	ıfit - Passenge	er's Side		1.00
- Shop Suj	oplies			Accufit Beam				1.00
				Stg Wheel Cov - Fo	ord			1.00
				Floor Mat-2pc Rub	Bk			1.00
				Used Fire X Refurb	ished			1.00
				Shop Supplies				1.00
	Hours: 7.00		Comm: 0.00	Labor: 420.00	Parts: 104	4.63	Total:	524.63
Vork Order: Problem:	1711665 PM Service, Wipers, Detail.	Meter:	20605		In Date:	11/29/2017	Closed:	12/07/2017
Work Com	pleted			Parts Issued			Qı	antity
- P.m. serv	ice.			5w20 Engine Oil				6.00
- Rotate a	nd balanced all four tires .nitroger	n fill tires.		Napagold Oil Filter				1.00
- Shop Su	oplies			Washer Fluid Conc	entr			1.00
				Air Filter				1.00
				Used Fire X Refurb	ished			1.00
				Wiper Blade				1.00
				Wiper Blade				1.00
				Shop Supplies				1.00
	Hours: 5.00		Comm: 0.00	Labor: 300.00	Parts: 90.	34	Total:	390.34

Work Order:	1712005	Meter: 20498		In Date:	12/07/2017	Closed	12/07/2017
	1 - Detail Vehicle Wash Ticket(s) Is			in Date.	12/01/2011	Closed.	12/01/2017
Work Com	pleted						
- 1 - Detai	l Vehicle Wash Ticket(s) Issued						
	Hours: 0.00	Comm: 96.00	Labor: 0.00	Parts: 0.0	0	Total:	96.00
Work Order: Problem:	1807238 P.M. Service.Recall 17S34.Detail.	Meter: 26070		In Date:	07/17/2018	Closed:	08/01/2018
Work Com	pleted		Parts Issued			Q	uantity
- P.m. serv	ice.		Napagold Oil Filter				1.00
- Replace 1	four tires and balance . Nitrogen fill	tires.	5w20 Engine Oil				6.00
- Resurface rotors .replace brake pads and service rear calipers . Flush and			Wiper Blade				1.00
bleed brake system . Road test.			Wiper Blade				1.00
- Complete	e front end alignment and road test.	Washer Fluid Concer	ntr			1.00	
- Transpor	t to and from dealer for recall 17s15	235/65/16 Tire Hank	ook			4.00	
- Shop Sup	oplies		Brake Pad				1.00
			Non-chlor Brake Cln	r			1.00
			Brk Fluid Dot 4-12oz	2			1.00
			Shop Supplies				1.00
			Tire Disposal Fee				4.00
	Hours: 14.50	Comm: 0.00	Labor: 870.00	Parts: 1,1	82.27	Total:	2,052.27
Work Order: Problem:	1810177 Towed in for no start.	Meter: 27445		In Date:	10/01/2018	Closed:	10/02/2018
Work Com	pleted	Parts Issued			Q	uantity	
- Compute	er diagnose no start ,codes P0627, P	Control Fuel Pump				1.00	
R&r defect	ive fuel pump driver module . Clear	Battry Motorcraft				1.00	
- Charge battery fully . Test battery and charging system . Battery failed load test . R&r defective battery.			d Shop Supplies				1.00
- Shop Sup	oplies						
	Hours: 3.00	Comm: 0.00	Labor: 201.00	Parts: 21	4.0.4	T . (.)	412.34

2/29/2024 1:16:01 PM	Palm 10198283			ment Asset Maintenar Van, 3/4 Ton, Cargo	nce History			
Work Order: 18		Meter:	27445		In Date:	10/01/2018	Closed:	10/03/2018
Problem: No	o start							
Work Comple	eted							
- Tow From: 8	3130 Jog Rd To: Lv Shop							
	Hours: 0.00		Comm: 96.00	Labor: 0.00	Parts: 0.00)	Total:	96.00
Nork Order: 19 Problem: P	01061 M. service and detail .	Meter:	30254		In Date:	01/29/2019	Closed:	02/07/2019
Work Comple				Parts Issued			Oı	uantity
- P.m. service.				Napagold Oil Filter				1.00
		oc Nitrofill a	1	5w20 Engine Oil				6.00
 Rotate and high speed balance all four tires . Nitrofill all. Shop Supplies 				Wiper Blade				1.00
Shop Suppli				Wiper Blades				1.00
				Mac Wite Lithium Gr	res			1.00
				Used Fire X Refurbis	hed			1.00
				Shop Supplies				1.00
	Hours: 5.00		Comm: 0.00	Labor: 335.00	Parts: 78.4	17	Total:	413.47
Nork Order: 19		Meter:	30254		In Date:	02/06/2019	Closed:	02/12/2019
Problem: re	place scratched windsheild							
Work Comple	eted			Parts Issued			Qı	uantity
- set up repai	rs & reasset			Shop Supplies				1.00
- Shop Suppli	es							
	Hours: 1.00		Comm: 442.36	Labor: 67.00	Parts: 3.00)	Total:	512.36

Palm Beach County Fleet Management Asset Maintenance History 10198283 2015 FORD TRANSIT T250 Van, 3/4 Ton, Cargo

Work Order: Problem:	1907768 PM Service, Detail.	Meter:	35316		In Date:	07/26/2019	Closed:	07/31/2019
Work Com	pleted			Parts Issued			Qu	uantity
- P.m. Serv	vice.			Napagold Oil Filter				1.00
- Rotate a	nd balance tires.			5w20 Engine Oil				6.00
- Shop Sup	oplies			Wiper Blade				1.00
				Wiper Blade				1.00
				Shop Supplies				1.00
	Hours: 5.00		Comm: 0.00	Labor: 335.00	Parts: 63.	05	Total:	398.05
Work Order: Problem:	1908121 1 - Detail Vehicle Wash Ticket(s)	Meter: Issued	35316		In Date:	08/06/2019	Closed:	08/06/2019
Work Com	pleted							
- 1 - Detai	l Vehicle Wash Ticket(s) Issued							
	Hours: 0.00		Comm: 96.00	Labor: 0.00	Parts: 0.0	0	Total:	96.00
Nork Order: Problem:	2000723 P.M. service and key fob inop .	Meter:	38996		In Date:	01/22/2020	Closed:	01/30/2020
Work Com	pleted			Parts Issued			Qı	uantity
- P.m. serv	vice.			Napagold Oil Filter				1.00
- Test and	replace failed remote battery .			5w20 Engine Oil				6.00
- Rotate ar	nd high speed balance all four tire	s . Nitrofill al	Ι.	Wiper Blade				1.00
- Shop Supplies				Wiper Blade				1.00
	•			Used Fire X Refurbis	hed			1.00
				Enr Elect Battery				1.00
				Enr Elect Battery Shop Supplies				1.00 1.00

Palm Beach County Fleet Management Asset Maintenance History 10198283 2015 FORD TRANSIT T250 Van, 3/4 Ton, Cargo

Work Order: 2007030 Meter: 44134 07/20/2020 Closed: 07/27/2020 In Date: Problem: P.m. service and fuel door fell off. **Work Completed** Parts Issued Quantity Napagold Oil Filter 1.00 - P.m. service. 5w20 Engine Oil 6.00 - Replace cabin air filter and clean fresh air intake . Wiper Blade 1.00 - Replace and balance all four tires . Nitrofill all. Wiper Blade 1.00 - Replace rear brake rotors and pads . Service calipers . Flush and bleed brake system . Road test . Cabin Air Filter 1.00 - R&r broken fuel door bezel. Tire 235/65/16 4.00 - Perform complete front end alignment and road test . **Rotor Brake** 2.00 - Shop Supplies Pad 1.00 Housing 1.00 Shop Supplies 1.00 Tire Disposal Fee 4.00 Hours: 13.80 Comm: 0.00 Labor: 1,007.40 Parts: 1,774.16 Total: 2,781.56 Work Order: 2101186 Meter: 49241 In Date: 02/01/2021 **Closed:** 02/09/2021 Problem: P.M. service. Quantity **Work Completed** Parts Issued Used Fire X Refurbished 1.00 - Preventive Maint. Service Napagold Oil Filter 1.00 - check, replace defective trailer plug connector . Rewire as needed . 5w20 Engine Oil 6.00 - balance and rotate all 4tires . Nitro fill all. Wiper Blade 1.00 - Shop Supplies Wiper Blade 1.00 Napa Air Filter 1.00

Bracket Socket Mount

Parts: 94.15

Shop Supplies

Labor: 438.00

1.00

Total: 532.15

Hours: 6.00

Comm: 0.00

Palm Beach County Fleet Management Asset Maintenance History 10198283 2015 FORD TRANSIT T250 Van, 3/4 Ton, Cargo

Work Order: 2108399 Meter: 53174 Problem: PM Service. Recall 19S38 / NHTSA RECALL 19V-767

In Date: 08/03/2021 Closed: 08/11/2021

Work Com	Work Completed					Qı	uantity
- Preventiv	- Preventive Maint. Service						1.00
- Diagnose	e sliding door hard to close. Rea	Wiper Blade				1.00	
- Repaired	d Lf tire. Rotated and balanced a	5w20 Engine Oil				6.00	
- Battery t	ested bad. Charged battery fully	and retested bad. Remove left	Napagold Oil Filter				1.00
front seat t	front seat to Replaced bad battery. Use scan tool to reset Bms. - Transport to and from dealer for recall 20b53 and order parts for recall 19s38						1.00
							1.00
- Shop Suj	pplies						
	Hours: 10.50	Comm: 0.00	Labor: 766.50	Parts: 190	0.00	Total:	956.50
Work Order: Problem:		Meter: 54864 ALL).Recall 19S38(Parts are in at o	dealer)	In Date:	10/18/2021	Closed:	10/19/202
Work Com	npleted		Parts Issued			Qı	uantity
- Repair ri	ght front tire and balance . Nitro	o fill all.	Shop Supplies				1.00
- Transpor	rt to and from dealer for recall 1	9s38 part in .					
- Shop Su	pplies						
	Hours: 3.00	Comm: 0.00	Labor: 219.00	Parts: 2.6	5	Total:	221.65
	FLAT TIRE (DRIVER IS ONCA	Meter: 54973 ALL)		In Date:	10/18/2021	Closed:	10/25/202
Work Com	-						
- Tow Fror	m: Tequesta Library (461 Old Dix			Darta: 0.0	0	Tatal	00.40
	Hours: 0.00	Comm: 90.40	Labor: 0.00	Parts: 0.0			90.40
Work Order: Problem:	2112457 Towed in for OVERHEATING	Meter: 55987		In Date:	11/22/2021	Closed:	11/30/202
Work Com	Work Completed					Qı	uantity
- Diagnose	- Diagnose overheating/fan operation using scan tool, Pin point test proves bad fan motor, Replace fan module. Perform operational checks.						1.00
bad fan mo							1.00
- Shop Su	pplios						

Hours: 3.40

Comm: 0.00

Labor: 248.20 Parts: 264.03

Total: 512.23

2/29/2024 1:16:01 PM				ent Asset Maintenan /an, 3/4 Ton, Cargo	ce History			
Work Order: Problem:	2112565 OVERHEATING	Meter:	55760		In Date:	11/22/2021	Closed:	11/29/2021
Work Com	pleted							
- Tow Fror	n: Indiantown Rd And	Turnpike To: Lv Shop						
	Hours: 0.00		Comm: 90.40	Labor: 0.00	Parts: 0.0	0	Total:	90.40
Work Order: Problem:	2202290 PM Service.	Meter:	57750		In Date:	03/01/2022	Closed:	03/07/2022
Work Com	pleted			Parts Issued			Qı	uantity
- Preventiv	e Maint. Service			Napagold Oil Filter				1.00
- rotate ar	d balance all 4 tire nit	ro fill all		5w20 Engine Oil				6.00
- remove and replace pads , cut rotors , service calipers , flush and bleed			Wiper Blade				1.00	
brake syste	m test drive after com	pletion		Wiper Blade				1.00
- Shop Suj	oplies			Used Fire X Refurbish	ned			1.00
				Non-chlor Brake Cln	ſ			1.00
				Brk Fluid Dot 4-32oz				1.00
				Brake Pad				1.00
				Shop Supplies				1.00
	Hours: 7.00		Comm: 0.00	Labor: 511.00	Parts: 117	7.22	Total:	628.22
Work Order: Problem:		Meter:	59646		In Date:	05/24/2022	Closed:	05/25/2022
Work Com	pleted			Parts Issued			Qı	uantity
- Nail in sidewall on both rear tires removed & replaced both rear tire then			235/65/16 Tire Hank	ook			2.00	
balance . N				Shop Supplies				1.00
- Shop Su	oplies			Tire Disposal Fee				2.00
	Hours: 1.00		Comm: 0.00	Labor: 73.00	Parts: 473	3.38	Total:	546.38

Palm Beach County Fleet Management Asset Maintenance History 2015 FORD TRANSIT T250 Van, 3/4 Ton, Cargo 10198283

Work Order: 2209820 Meter: 62385 09/21/2022 **Closed:** 10/03/2022 In Date: Problem: PM Service. Parts Issued Quantity **Work Completed** Napagold Oil Filter 1.00 - Preventive Maint, Service 5w20 Engine Oil 6.00 - mount 2 rotate and balance all 4 tires nitro fill all Wiper Blade 1.00 - perform front end alignment . Road test . Wiper Blade 1.00 - Shop Supplies Used Fire X Refurbished 1.00 235/65r16c Gy Fortitudte Ht 2.00 Shop Supplies 1.00 2.00 Tire Disposal Fee Hours: 8.50 Comm: 0.00 Labor: 620.50 Parts: 436.20 Total: 1,056.70 Work Order: 2302537 Meter: 66510 In Date: 03/14/2023 Closed: 03/30/2023 Problem: PM Service. VAN CUT OUT RESTRATED AND WENT ON MY WAY Quantity Work Completed Parts Issued Napagold Oil Filter 1.00 - Performed P.m. Service & Inspection. 7.00 Napa Quart 5w20 - Performed Tire Rotation Balance On All 4 Wheels, Add Nitro Fill Reset Tpms. Wd40 Spr 1.00 - Removed & Replaced The Cabin Air Filter, Clean A/c Vent & Check. Wiper Blade 1.00 Working As Design. Wiper Blades 1.00 - Performed Intake Decarb And Fuel Injection Cleaning Service . Cabin Air Filter 1.00 - Performed Tune-up, Removed & Replaced All 6 Spark Plugs. Intake Cleaner Kit 1.00 - Check Engine Light On, Plug In Scan Tool Found Fault Code P2111 & Motor Tune-up 16oz 1.00 Perform Pids Test, Found Throttle Body Defective, Removed And Replaced Gasket 1.00 The Throttle Body Test Drove Vehicle Clear Faults. Spark Plug 6.00 - Shop Supplies Gasket 1.00 1.00 Throttle Body Shop Supplies 1.00 Labor: 1,022.00 Parts: 250.72 Total: 1,272.72

Work Order:2308519Meter:70291Problem:PM Service and gas door and steering wheel cover

In Date: 08/24/2023 Closed: 09/06/2023

Work Completed			Parts Issued	Quantity		
- Preventive Maint. Se	ervice completed		Napagold Oil Filte		1.00	
- check,sop and r&r c		r trim	5w20 Engine Oil			6.00
•	- balance and rotate all 4 tires . Nitro fill all.					1.00
- Shop Supplies			Wiper Blade			1.00
			Used Fire X Refurb	bished		1.00
			Leather S Whl Cov	/		1.00
			Housing			1.00
			Shop Supplies			1.00
ŀ	lours: 6.00	Comm: 0.00	Labor: 438.00	Parts: 183.67	Total:	621.67
Work Order: 2401371 Problem: Transition		ter: 73515		In Date: 02/07/202	24 Closed:	02/07/2024
Work Completed						
- Transition Prep Cha	rge					
F	lours: 2.00	Comm: 0.00	Labor: 146.00	Parts: 0.00	Total:	146.00
Total Hours: 133.00	Total Labo	r: 9,124.50	Total Comm: 1,0	07.16 Total Par	ts: 5,697.92	