2/29/2024 1:17:24 PM				anagement Asset Maintena TRANSIT T250 Van, 3/4 Tor				
Total Hours:	157.80 Labor: 10,89	4.00	Parts: 6,882.16	Comm: 8,234.40		Charged	: 26010.57	,
Work Order: Problem:	1511693 1061 - Pre Delivery In:	Meter: spection	333		In Date:	11/16/2015	Closed:	11/16/2015
Work Com	pleted							
- Pre Deliv	ery Inspection							
	Hours: 2.00		Comm: 0.00	Labor: 120.00	Parts: 0.0	0	Total:	120.00
Work Order: Problem:	1604300 P.M. service.	Meter:	2497		In Date:	04/25/2016	Closed:	04/29/2016
Work Com	pleted			Parts Issued			Q	uantity
- P.m Servi	ice.			5w20 Engine Oil				6.00
- Rotate ar	nd balance all tires.			Napagold Oil Filter				1.00
- Shop Sup	oplies			Washer Fluid Conce	entr			1.00
				Shop Supplies				1.00
	Hours: 5.00		Comm: 0.00	Labor: 300.00	Parts: 19.	78	Total:	319.78
Work Order: Problem:	1611197 P.M. service.	Meter:	8694		In Date:	10/28/2016	Closed:	11/22/2016
Work Com	pleted			Parts Issued			Q	uantity
- P.m. Serv	vice.			5w20 Engine Oil				6.00
- Rotate ar	nd balance tires.			Napagold Oil Filter				1.00
- Diagnose	e and replace defective	Tpms. in	right front.	Washer Fluid Conce	entr			1.00
- Shop Sup	oplies			Tpms12 Sensor Tire	Pr			1.00
				Shop Supplies				1.00

Labor: 360.00

Parts: 101.78

Total: 461.78

Hours: 6.00

Comm: 0.00

Problem: P.M. service.	Meter: 13546		In Date:	04/24/2017	Closed:	04/28/2017
Work Completed		Parts Issued			Qı	antity
- P.m. service.		5w20 Engine Oil				6.00
- Rotate and high speed balance all four tires.		Napagold Oil Filter	r			1.00
- Shop Supplies		Mac Wite Lithium	Gres			1.00
		Accufit Beam				1.00
		Wiper Blade - Accu	ufit - Passenge	er's Side		1.00
		Used Fire X Refurb	oished			1.00
		Shop Supplies				1.00
Hours: 5.00	Comm: 0.00	Labor: 300.00	Parts: 65.	48	Total:	365.48
Work Completed		Parts Issued			Qı	uantity
Work Completed					Qu	antity 6.00
- P.m. service.	ed balance all four	5w20 Engine Oil	r		Qı	•
- P.m. service. - Four new tires,mount and nitrogen fill.high spec	ed balance all four.		r		Qu	6.00
 P.m. service. Four new tires,mount and nitrogen fill.high spec Fuel cap cover broken .r&r with new. 		5w20 Engine Oil Napagold Oil Filter Wiper Blade	r		Qu	6.00 1.00
- P.m. service. - Four new tires,mount and nitrogen fill.high spec		5w20 Engine Oil Napagold Oil Filter Wiper Blade			Qı	6.00 1.00 1.00
 P.m. service. Four new tires,mount and nitrogen fill.high spec Fuel cap cover broken .r&r with new. Replace rear brake pads.service calipers and res 		5w20 Engine Oil Napagold Oil Filter Wiper Blade Wiper Blade	Gres		Qı	6.00 1.00 1.00 1.00
 P.m. service. Four new tires,mount and nitrogen fill.high spect Fuel cap cover broken .r&r with new. Replace rear brake pads.service calipers and rest,ok. 		5w20 Engine Oil Napagold Oil Filter Wiper Blade Wiper Blade Mac Wite Lithium	Gres vished		Qu	6.00 1.00 1.00 1.00 1.00
 P.m. service. Four new tires,mount and nitrogen fill.high spector Fuel cap cover broken .r&r with new. Replace rear brake pads.service calipers and rest,ok. Complete front end alignment. 		5w20 Engine Oil Napagold Oil Filter Wiper Blade Wiper Blade Mac Wite Lithium Used Fire X Refurb	Gres vished		Qı	6.00 1.00 1.00 1.00 1.00 1.00
 P.m. service. Four new tires,mount and nitrogen fill.high spector Fuel cap cover broken .r&r with new. Replace rear brake pads.service calipers and rest,ok. Complete front end alignment. 		5w20 Engine Oil Napagold Oil Filter Wiper Blade Wiper Blade Mac Wite Lithium Used Fire X Refurb 235/65/15c/tire Fir	Gres vished		Qu	6.00 1.00 1.00 1.00 1.00 1.00 4.00
 P.m. service. Four new tires,mount and nitrogen fill.high spector Fuel cap cover broken .r&r with new. Replace rear brake pads.service calipers and rest,ok. Complete front end alignment. 		5w20 Engine Oil Napagold Oil Filter Wiper Blade Wiper Blade Mac Wite Lithium Used Fire X Refurb 235/65/15c/tire Fir Housing	Gres vished		Q.	6.00 1.00 1.00 1.00 1.00 4.00 1.00
 P.m. service. Four new tires,mount and nitrogen fill.high spector Fuel cap cover broken .r&r with new. Replace rear brake pads.service calipers and rest,ok. Complete front end alignment. 		5w20 Engine Oil Napagold Oil Filter Wiper Blade Mac Wite Lithium Used Fire X Refurb 235/65/15c/tire Fir Housing Clip	Gres vished		Qu	6.00 1.00 1.00 1.00 1.00 1.00 4.00 4.00
 P.m. service. Four new tires,mount and nitrogen fill.high spector Fuel cap cover broken .r&r with new. Replace rear brake pads.service calipers and rest,ok. Complete front end alignment. 		5w20 Engine Oil Napagold Oil Filter Wiper Blade Mac Wite Lithium Used Fire X Refurb 235/65/15c/tire Fir Housing Clip Brake Pad	Gres vished		Qu	6.00 1.00 1.00 1.00 1.00 1.00 4.00 1.00 4.00

Vork Order: 1		Meter: 20616		In Date:	11/20/2017	Closed:	11/21/2017
Problem: S	Slow crack and clicking noise						
Work Comp	leted		Parts Issued			Qı	uantity
- Charge bat	ttery fully.test battery and cha	arging system.battery failed load	Battry Motorcraft				1.00
test .remove left front seat assembly to replace defective battery.		Shop Supplies				1.00	
- Shop Supp	blies						
	Hours: 1.00	Comm: 0.00	Labor: 60.00	Parts: 173	3.54	Total:	233.54
Vork Order: 1 Problem: F	1804601 PM Service, Repair ladder rac	Meter: 24920 ck, Recall 17S34		In Date:	05/02/2018	Closed:	06/07/2018
Work Comp	leted		Parts Issued			Qı	uantity
- P.m. servic	e.		Napagold Oil Filter				1.00
- Realign an	d resecure all ladder rack bol	ts . Replace broken l bracket and	5w20 Engine Oil				6.00
adjust. Retes	t.		Washer Fluid Concer	ntr			1.00
•		17s34 and 17s15 and rear main oil	L-bracket				1.00
seal replacen	nent.		Shop Supplies				1.00
- Repair righ Tpms.	nt rear tire .rotate and balance	e all four tires. Nitrofill and reset	Freight Charge				1.00
- Shop Supp	blies						
	Hours: 9.00	Comm: 0.00	Labor: 540.00	Parts: 84.	81	Total:	624.81
Vork Order: 1 Problem: c	1806320 damage to frt bumper	Meter: 25042		In Date:	05/29/2018	Closed:	06/20/2018
Work Comp	leted						
- damage to	o frt bumper						
	Hours: 0.00	Comm: 1,324.39	Labor: 0.00	Parts: 0.0	0	Total:	1,324.39

Work Order: 1811136 Meter: 29734 10/29/2018 Closed: 11/19/2018 In Date: Problem: P.M. service and sliding door ajar switch inop. Parts Issued Quantity **Work Completed** Napagold Oil Filter 1.00 - P.m. service. Napa Quart 5w20 6.00 - Test and replace right sliding door ajar switch and adjust. Retest. Wiper Blade 1.00 - Rotate and balance all four tires. Nitrofill all. Wiper Blade 1.00 - Transport to and from dealer for oil leak. Washer Fluid Concentr 1.00 - Shop Supplies Used Fire X Refurbished 1.00 Switch 1.00 Shop Supplies 1.00 Hours: 6.25 Comm: 0.00 Parts: 93.80 Total: 512.55 Labor: 418.75 Work Order: 1811854 In Date: 11/19/2018 Closed: 11/27/2018 Meter: 29734 Problem: repair chipped winsheild Parts Issued Quantity **Work Completed** Shop Supplies 1.00 - set up repairs & inspect - Shop Supplies Comm: 60.00 Hours: 1.00 Labor: 67.00 Parts: 3.00 Total: 130.00 Work Order: 1811941 Meter: 29883 In Date: 11/26/2018 **Closed:** 11/29/2018 Problem: Power outlet inop. **Work Completed** Parts Issued Quantity Bp Fmx-lp F Mx Fuse 1.00 - Test and replace blown fuse for power outlet. Total: 38.21 Hours: 0.50 Comm: 0.00 Labor: 33.50 Parts: 4.71

Work Order: 1904613 Problem: P.M. service and align headlights .	Meter:	35870		In Date:	04/29/2019	Closed:	07/16/2019
Work Completed			Parts Issued			Qı	antity
- P.m. Service.			Napagold Oil Filter				1.00
- Rotate and balance tires.			5w20 Engine Oil				6.00
- Transport vehicle to dealer for oil leak.			Wiper Blade				1.00
- Shop Supplies			Wiper Blade				1.00
			Washer Fluid Concen	ıtr			1.00
			2pc Hd Mat Set Blk				1.00
			Ford Triton Pvc Swc				1.00
			Shop Supplies				1.00
Hours: 7.00		Comm: 0.00	Labor: 469.00	Parts: 116	6.57	Total:	585.57
Vork Order: 1912259 Problem: No start.	Meter:	39719		In Date:	11/27/2019	Closed:	12/04/2019
Work Completed			Parts Issued			Qı	antity
- Diagnose no start . Computer diagnose ,no co	odes . Perf	orm fuel pressure	Fuel Pump Module				1.00
test . R&r defective fuel pump driver module . R	Retest .	·	Shop Supplies				1.00
- Shop Supplies							
Hours: 2.00		Comm: 0.00	Labor: 146.00	Parts: 67.	78	Total:	213.78
Work Order: 1912337 Problem: NO Start	Meter:	39684		In Date:	11/27/2019	Closed:	12/02/2019
Work Completed							
- Tow From: 8130 Jog Rd, Palm Beach Gardens	To: Lv sh	ор					
		Comm: 96.00			0		

Work Order: 2000025 **Meter:** 40701 01/02/2020 **Closed:** 01/24/2020 In Date: **Problem:** P.M. service. **Work Completed** Parts Issued Quantity Napagold Oil Filter 1.00 - P.m. service. 5w20 Engine Oil 6.00 - Replace both rear brake rotors and pads . Service calipers . Flush and bleed brake system . Road test . Napa Air Filter 1.00 - Replace all four tires and balance . Nitrofill all. Wiper Blade 1.00 - Complete front end alignment and road test . Wiper Blade 1.00 - Shop Supplies Used Fire X Refurbished 1.00 Px Grey Rtv Silicone 1.00 Bolt 10.00 2.00 Seal Brake Pad 1.00 2.00 Rotor Brake 235/65/16 Tire Hankook 4.00 Shop Supplies 1.00 Tire Disposal Fee 4.00 Parts: 1,578.29 Total: 2,490.79 Hours: 12.50 Comm: 0.00 Labor: 912.50

Meter: 45550

Work Order: 2005779

06/10/2020 Closed: 06/18/2020 In Date:

Problem: P.M. service and haspon sliding door hitting door .

Work Completed		Parts Issued		Quantity
- P.m. Service.		Napagold Oil Filter		1.00
- Replace cabin filter.clean fresh air duct.	ce cabin filter.clean fresh air duct.			6.00
- Service and clean c throttle body.flush injector	s and clean combustion	Washer Fluid Conce	entr	1.00
system.		Wiper Blade		1.00
- Perform ignition tune-up.repair harness to coil	Perform ignition tune-up.repair harness to coils chewed up by rodents.			1.00
- Inspect and service leaking rear differential.		Rotell Elc Antifeerze	9	1.00
- Fabricate and repair pad lock hasp on sliding of	Cabin Air Filter		1.00	
door.replace damage fire extinguisher bracket.		Intake Cleaner Kit Motor Tune-up 16oz		1.00
- 'how is my driving ' removed.clean glue from g	glass and install new sticker.			1.00
- Rotate and balance all tires.		Gasket		1.00
- Shop Supplies		Spark Plugs		6.00
		1qt Syngear Oil 75-	90	3.00
		Px Grey Rtv Silicone	9	1.00
		Wiper Blade		1.00
		Non-chlor Brake Cl	nr	1.00
		Shop Supplies		1.00
Hours: 17.00	Comm: 0.00	Labor: 1,241.00	Parts: 283.14	Total: 1,524.14

Work Order:2101044Meter:51364Problem:P.M. service , check battery and power outlets .

In Date: 01/28/2021 **Closed:** 02/10/2021

Work Complet	ed		Par	ts Issued			Qı	antity
- Preventive Ma	aint. Service		Use	Used Fire X Refurbished Wiper Blade Wiper Blade			1.00	
- Check all brks	s. R & I new front brakes, Re	surface both rotors, ser	vice Wip					1.00
calipers bleed b	orakes		Wip					1.00
- Check and tra	ace/ repair open ckt to acce	ssary outlet passenger s	side Was	sher Fluid Conce	entr			1.00
- Shop Supplie	S		5w2	0 Engine Oil				6.00
				agold Oil Filter				1.00
			Brk	Fluid Dot 4-32o	Z			1.00
				n-chlor Brake Clr	٦r			1.00
			Bp I	- mx-lp F Mx Fus	e			1.00
			Bral	ke Pad				1.00
			Sho	p Supplies				1.00
	Hours: 8.50	Comm:	0.00 Lab	or: 620.50	Parts: 172	02	Total:	792.52
ork Order: 210 Problem: Bat		Meter: 52142			In Date:	03/05/2021	Closed:	03/11/202
Work Complet	ed		Par	ts Issued			Qı	antity
	ery draw test215 amps aft	5		ry Motorcraft				1.00
	d charging system . Battery	failed load test Durde	foctivo Cha	C				1 0 0
	or draw . After 10 min 0.008			p Supplies				1.00
battery .retest f	or draw . After 10 min 0.008			p Supplies				1.00
battery .retest fo Bsm .	or draw . After 10 min 0.008		to reset	or: 146.00	Parts: 192	82	Total:	1.00 338.82
battery .retest fo Bsm .	For draw . After 10 min 0.008 es Hours: 2.00	amps Ok .hook up Ids	to reset		Parts: 192 In Date:	.82 03/04/2021		
battery .retest for Bsm . - Shop Supplie	For draw . After 10 min 0.008 es Hours: 2.00	amps Ok .hook up Ids Comm:	to reset					338.82
battery .retest for Bsm . - Shop Supplie	For draw . After 10 min 0.008 Hours: 2.00 02616 start /has been stalling out	amps Ok .hook up Ids Comm:	to reset					338.82
battery .retest for Bsm . - Shop Supplie Fork Order: 210 Problem: no s Work Complet	For draw . After 10 min 0.008 Hours: 2.00 02616 start /has been stalling out	amps Ok .hook up Ids Comm: Meter: 52026	to reset					338.82

Nork Order: Problem:	2106903 rt rear has tire leak	Meter:	54885		In Date:	06/24/2021	Closed:	06/28/202
Work Com	pleted			Parts Issued			Qı	uantity
- Replace l	both rear tire and balance . N	litro fill all.		235/65/16 Tire Hank	ook			2.00
- Shop Sup				Shop Supplies				1.00
				Tire Disposal Fee				2.00
	Hours: 1.00		Comm: 0.00	Labor: 73.00	Parts: 572	2.72	Total:	645.72
Vork Order: Problem:	2108089 PM Service. Recall 19S38,	Meter: CSP20B53	55793		In Date:	07/27/2021	Closed:	08/12/202
Work Com	pleted			Parts Issued			Qı	uantity
- Preventiv	ve Maint. Service			Washer Fluid Concer	ntr			1.00
- Check Fo	or Voltage At Circuit Ok And I	R&r Failed High M	lount Led Stop	Wiper Blade				1.00
Lamp.	-	_		Wiper Blade				1.00
- Rotate A	nd Balance Four Tires.			5w20 Engine Oil				6.00
	t to and from dealer for reca	ll 21b53 fuel pum	o driver module	Napagold Oil Filter				1.00
•	nt . Sop coupler			Yellow Markal Crayo	n			1.00
- Shop Sup	oplies			Silicone Spray 10oz				1.00
				Stop Lamp				1.00
				Shop Supplies				1.00
	Hours: 7.75		Comm: 0.00	Labor: 565.75	Parts: 80.	59	Total:	646.34

Work Order:2201820Meter:60474Problem:PM Service. Recall 19S38 DRIVESHAFT FLEX COUPLING

In Date: 02/17/2022 **Closed:** 03/10/2022

Work Completed	Parts Issued	Quantity
- Preventive Maint. Service	Napagold Oil Filter	1.00
- check,replaced cabin a/c filter and refresh intke air	Napa Quart 5w20	6.00
- replaced two tires, balance and rotate all 4	Wiper Blade	1.00
- completed front end alignment and road test	Wiper Blade	1.00
- check,veify needs rear pads & rotors,replaced both rear brakes	Used Fire X Refurbished	1.00
rotors,pds,2 orings seals and flush ,bleed brakes fluid system then test drive	e Cabin Air Filter	1.00
- Transport to and from dealer for recall 19s38	lube	1.00
- Shop Supplies	Seal	2.00
	Rotor Rear	2.00
	Brake Pad	1.00
	235/65/16 Tire Hankook	2.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours: 15.00 Comm: 0.00	Labor: 1,095.00 Parts: 827.58	Total: 1,922.58

Meter: 63752

Work Order: 2209466 Problem: PM Service. and recall 19S38

In Date: 09/12/2022 **Closed:** 10/03/2022

Work Completed		Parts Issued		Q	uantity	
- Performed P.m. Service & Inspection.		Napagold Oil Filte	r		1.00	
- Performed Tire Rotation Balance On All 4 W	heels, Add Nitro Fill Reset	5w20 Engine Oil	5w20 Engine Oil			
Tpms.		Washer Fluid Concentr			1.00	
- Driver Rear Reflector Missing On Bumper. Ir	stalled Missing Reflector.	Wiper Blade			1.00	
- Pressure Test And Inspect Cooling System . Performed Cooling System		Wiper Blade Napa Air Filter Coolent Reflector			1.00	
Flush. Fill To Spec And Bleed Air .	1.00					
- Squeak Noise Coming From Engine Bay. Ins	2.00 1.00					
Belt And A/c Belt Defective. Removed And Rep						
- Transport to and from dealer for recall 19s3	ŏ	A/c Belt			1.00	
- Shop Supplies		V Belt			1.00	
		Shop Supplies			1.00	
Hours: 10.70	Comm: 0.00	Labor: 781.10	Parts: 170.61	Total:	951.71	
ork Order: 2300487 Problem: NAIL IN RT REAR TIRE	Meter: 65996		In Date: 01/17/202	23 Closed:	01/18/202	
Work Completed		Parts Issued		Q	uantity	
- Repair right rear tire and balance . Nitro fill	all and reset Tpms .	Shop Supplies			1.00	
- Shop Supplies						
Hours: 1.00	Comm: 0.00	Labor: 73.00	Parts: 2.65	Total:	75.65	

Work Order: 2302550 Problem: PM Service.

In Date: 03/14/2023 Closed: 03/21/2023

Work Completed		Parts Issued		Quantity
- Preventive Maint. Service completed		Napagold Oil Filte	r	1.00
- balance and rotate all 4 tires. Nitro fill all.		Napa Quart 5w20		6.00
- check and replaced cabin a/c filter. Clean	fresh air intake	Wiper Blade		1.00
- Shop Supplies		Wiper Blade		1.00
		Used Fire X Refur	bished	1.00
		Cabin Filter		1.00
		Shop Supplies		1.00
Hours: 5.50	Comm: 0.00	Labor: 401.50	Parts: 121.26	Total: 522.76
/ork Order: 2306912	Meter: 69481		In Date: 07/12/2023	Closed: 07/26/202

Work Order:2306912Meter:69481In Date:07/12/20Problem:Towed in for smoke coming out of engine bay, wont run/drive. coolant low , check engine light and tire light .

Meter: 67860

Work Completed		Parts Issued	Quantity	
- Scan diagnose overheating, codes P0217, P12	285, P1299, pinpoint test	Coolent		1.00
cooling fan system. Replace bad cooling fan. Coolant was low due to water pump leak. Replace water pump, belt, thermostat and flush cooling system.		Gasket		1.00
	Thermostat Housing Assembly		1.00	
- Shop Supplies		Water Pump Fan Motor Assy		1.00
				1.00
		Big G Degreaser 1	Gal	1.00
		Washer Bottle Cap		1.00
		Shop Supplies		1.00
Hours: 9.30	Comm: 0.00	Labor: 678.90	Parts: 578.39	Total: 1,257.29
Vork Order: 2307506	Meter: 69481		In Date: 07/12/2023	Closed: 07/27/2023

Comm: 124.30

Problem: smoke coming out of engine bay, wont run/drive. Last week AC was cutting in and out

Work Completed

- Tow From: 8100 Forest Hill Blvd, Wpb 33413 near fuel island To: Fleet Vista

Hours:	0.	00
1100101	۰.	00

Labor: 0.00

Parts: 0.00

Total: 124.30

Total Hours: 157.80

08/22/2023 Closed: 08/31/2023

Total Parts: 6.882.16

In Date:

Work Order: 2308394 Meter: 70169

Problem: PM Service. wont start up just crank. check engine light on, Detail

Total Labor: 10.894.00

Parts Issued **Work Completed** Quantity Napagold Oil Filter 1.00 - Preventive Maint. Service completed 5w20 Engine Oil 6.00 - replaced two tires, balance and rotate all 4. Nitro fill all. Wiper Blade 1.00 - computer diag code p1450 ,p2196 & p2198 ,pin point test, performed test, sop, r&r defective evap purge valve, clear light then road test to verify Wiper Blade 1.00 normal operation 235/65/16 Tire Gooyer 2.00 - Shop Supplies Valve Asm 1.00 Shop Supplies 1.00 2.00 Tire Disposal Fee Comm: 0.00 Hours: 7.50 Labor: 547.50 Parts: 437.49 Total: 984.99 Work Order: 2308918 Meter: 70169 In Date: 08/31/2023 Closed: 09/01/2023 Problem: 1 - Detail Vehicle Wash Ticket(s) Issued WO: 2308394 for: frank foray **Work Completed** - 1 - Detail Vehicle Wash Ticket(s) Issued Wo: 2308394 for: frank foray Parts: 0.00 Hours: 0.00 Comm: 90.40 Labor: 0.00 Total: 90.40 Work Order: 2311228 Meter: 70749 In Date: 09/20/2023 Closed: 11/08/2023 Problem: Damage to left rear fender, rear bumper, left rear light & rear doors **Work Completed** - Damage to left rear fender, rear bumper, left rear light & rear doors Comm: 6,539.31 Parts: 0.00 Hours: 0.00 Labor: 0.00 Total: 6,539.31 In Date: 11/17/2023 Closed: 11/17/2023 Work Order: 2311540 Meter: 70749 **Problem:** Transition Prep Charge **Work Completed** - Transition Prep Charge Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 0.00 Total: 146.00

Total Comm: 8,234.40