

5/3/2024
11:31:17 AM

Palm Beach County Fleet Management Asset Maintenance History
10203955 2017 FORD F150 Pickup, 1/2 Ton, 4X4

Total Hours: 124.60 Labor: 8,878.00 Parts: 4,102.54 Comm: 0.00 Charged: 12980.54

Work Order: 1710658 **Meter:** 0 **In Date:** 10/27/2017 **Closed:** 10/27/2017
Problem: 1061 - Pre Delivery Inspection

Work Completed

- Pre Delivery Inspection

Hours: 2.00 Comm: 0.00 Labor: 120.00 Parts: 0.00 Total: 120.00

Work Order: 1803180 **Meter:** 4446 **In Date:** 03/27/2018 **Closed:** 04/04/2018
Problem: P.M. service and washers inop.

Work Completed

- P.m. service.
- Computer diagnose washer pump inop.r&r defective washer pump .fill washer tank and retest.
- Rotate and high speed balance all four tires.
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
Used Fire X Refurbished	1.00
Floor Mat-2pc Rub Bk	1.00
Ford Triton Pvc Swc	1.00
Mac Wite Lithium Gres	1.00
Washer Pump	1.00
Shop Supplies	1.00

Hours: 4.75 Comm: 0.00 Labor: 285.00 Parts: 114.41 Total: 399.41

Work Order: 1806649 **Meter:** 9773 **In Date:** 06/28/2018 **Closed:** 07/10/2018
Problem: P.M. service.

Work Completed

- P.m. service.
- Balance and rotate all four tires. Nitrofill.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
Shop Supplies	1.00

Hours: 3.75 Comm: 0.00 Labor: 225.00 Parts: 18.43 Total: 243.43

5/3/2024
11:31:17 AM

Palm Beach County Fleet Management Asset Maintenance History
10203955 2017 FORD F150 Pickup, 1/2 Ton, 4X4

Work Order: 2012230 **Meter:** 48813 **In Date:** 12/09/2020 **Closed:** 12/17/2020
Problem: P.M. Service, Jump start twice.

Work Completed

- Performed P.m. Service & Inspection.
- Mount And Balance 4 New Tires, Reset Tpms. Nitro fill all.
- Load Test Battery, Test Recommend Charge. Charged Battery And Retest, Battery Failed, Removed And Replaced Then hook up lds to reset Bsm .
- Clean A/c Vents Then Removed And Replaced A/c Cabin Filter.
- Resurface Both Rear Brake Rotors Install New Brake Pads, Lubricate Caliper Slides And Service Calipers . Bleed And Flush Entire Brake System, Test Drove And Burnish Brakes.
- Performed 2 Wheel Alignment. Road Test .
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
22" Wiper Blade	2.00
Battry Motorcraft	1.00
Cabin Filter	1.00
Brk Fluid Dot 4-32oz	1.00
Non-chlor Brake Clnr	1.00
Brake Pad	1.00
265 70 R17 Tire	4.00
Shop Supplies	1.00
Tire Disposal Fee	4.00

Hours: 13.25

Comm: 0.00

Labor: 967.25 Parts: 1,305.41 Total: 2,272.66

Work Order: 2105310 **Meter:** 55881 **In Date:** 05/12/2021 **Closed:** 05/19/2021
Problem: P.M. Service

Work Completed

- Preventive Maint. Service
- Rotate and speed balance all , nitro fill
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Used Fire X Refurbished	1.00
Shop Supplies	1.00

Hours: 3.75

Comm: 0.00

Labor: 273.75 Parts: 50.01 Total: 323.76

5/3/2024
11:31:17 AM

Palm Beach County Fleet Management Asset Maintenance History
10203955 2017 FORD F150 Pickup, 1/2 Ton, 4X4

Work Order: 2109398 **Meter:** 62345 **In Date:** 08/30/2021 **Closed:** 09/22/2021
Problem: P.M. Service and right front tire going flat .

Work Completed

- Preventive Maint. Service
- check,removed nail.add 65 psi air then submerge under water several times no leak found . Rotate and balance all four tires . Nitro fill all. Reset Tpms .
- Shop Supplies

Hours: 3.75

Comm: 0.00

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
22" Wiper Blade	3.00
Washer Fluid Concentr	1.00
Shop Supplies	1.00

Labor: 273.75

Parts: 30.39

Total: 304.14

Work Order: 2112811 **Meter:** 66991 **In Date:** 12/03/2021 **Closed:** 12/14/2021
Problem: REAR BRAKE LIGHT

Work Completed

- Replace left rear brake light bulb and socket

Hours: 0.50

Comm: 0.00

Parts Issued

Quantity

Stp Trn TI Lgt Socket	1.00
Boxed Miniatures	1.00

Labor: 36.50

Parts: 7.68

Total: 44.18

5/3/2024
11:31:17 AM

Palm Beach County Fleet Management Asset Maintenance History
10203955 2017 FORD F150 Pickup, 1/2 Ton, 4X4

Work Order: 2200106 **Meter:** 68388 **In Date:** 01/05/2022 **Closed:** 01/19/2022
Problem: PM Service.

Work Completed

- Preventive Maint. Service
- check,replaced cabin a/c filter and refresh intake air
- Computer diagnose engine misfire . performed major tune up by replaced all 6 spark plugs,and intake gasket
- performed injector flush and top engine decab
- resurfaced both front brakes rotors,replaced calipers,flush fluid system ,then road test
- inspect and service transfer case
- Shop Supplies

Parts Issued

Quantity

Filter	1.00
5w20 Engine Oil	6.00
22" Wiper Blade	2.00
Napagold Air Filter	1.00
Cabin Filter	1.00
Gasket	1.00
Spark Plugs	6.00
Intake Cleaner Kit	1.00
Motor Tune-up 16oz	1.00
Non-chlor Brake Clnr	1.00
Brk Fluid Dot 4-32oz	1.00
Reman/ca	1.00
Reman/ca	1.00
Brake Pad	1.00
oil auto	3.00
Shop Supplies	1.00

Hours: 14.55

Comm: 0.00

Labor: 1,062.15

Parts: 333.26

Total: 1,395.41

Work Order: 2204645 **Meter:** 74393 **In Date:** 04/29/2022 **Closed:** 05/05/2022
Problem: PM Service.

Work Completed

- Preventive Maint. Service
- rotate and balance all 4 tire nitro fill all
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
22" Wiper Blade	2.00
Used Fire X Refurbished	1.00
Shop Supplies	1.00

Hours: 3.75

Comm: 0.00

Labor: 273.75

Parts: 37.96

Total: 311.71

5/3/2024
11:31:17 AM

Palm Beach County Fleet Management Asset Maintenance History
10203955 2017 FORD F150 Pickup, 1/2 Ton, 4X4

Work Order: 2303779

Meter: 92337

In Date: 04/17/2023 **Closed:** 04/24/2023

Problem: P.M. Service

Work Completed

- Preventive Maint. Service
- Testing Trailer Plug And Found Rusted Out Connector Replace Trailer Plug And Retest
- Load Tested Battery And Checked Charging System, Battery Failed Load Test R&r Battery . Hook Up Ids To Reset Bsm .
- Pressure Tested Cooling System Found Water Pump Leaking, R&r Water Pump, Thermostat Housing, Flush And Bleed System And Test Drive Vehicle
- Rotate And Balance Tires With Nitro Fill
- R&r Cabin Air Filter And Clean Fresh Air Intake
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
22" Wiper Blade	2.00
Used Fire X Refurbished	1.00
trailer plug	1.00
Battry Motorcraft	1.00
Hose Clamp	2.00
Belt	1.00
Gasket	1.00
Thermostat Housing Assembly	1.00
Coolent	1.00
Water Pump	1.00
Cabin Air Filter	1.00
Non-chlor Brake Clnr	2.00
Shop Supplies	1.00

Hours: 12.25

Comm: 0.00

Labor: 894.25

Parts: 549.94

Total: 1,444.19

5/3/2024
11:31:17 AM

Palm Beach County Fleet Management Asset Maintenance History
10203955 2017 FORD F150 Pickup, 1/2 Ton, 4X4

Work Order: 2308764 **Meter:** 98571 **In Date:** 08/30/2023 **Closed:** 09/08/2023
Problem: PM Service and check for nails in tires

Work Completed

Parts Issued

Quantity

- Preventive Maint. Service
- Inspect and R & i two new on front, speed balance, nitro fill
- R&r front brake pads ,machine rotors ,service calipers and flush and bleed brake system . Road test
- Shop Supplies

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
265 / 70 / 17 Sl / Tire Gdy	2.00
Non-chlor Brake Clnr	1.00
Brake Pad	1.00
Brake Fluid Fot 4 Lv	1.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 8.75

Comm: 0.00

Labor: 638.75 Parts: 493.66 Total: 1,132.41

Work Order: 2312552 **Meter:** 103904 **In Date:** 12/21/2023 **Closed:** 01/03/2024
Problem: PM Service

Work Completed

Parts Issued

Quantity

- Performed P.m. Service & Inspection.
- Mount 2 Tires Then Balance & Rotate All 4 Wheels, Add Nitro Fill Reset Tpms.
- Performed Front Wheel Alignment & Test Drove Vehicle.
- Rear Brake Pads Below Manufacture Specs, Removed Rear Brake Pads And Rotors, Then Replaced, Bleed & Flush Brakes. Test Drove Vehicle & Burnish Brakes. Working As Design.
- Shop Supplies

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
Wiper Blade	2.00
265 / 70 / 17 Sl / Tire Gdy	2.00
Brake Pad	1.00
Non-chlor Brake Clnr	1.00
Brk Fluid Dot 4-32oz	1.00
Rear Rotor	2.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 11.25

Comm: 0.00

Labor: 821.25 Parts: 719.20 Total: 1,540.45

5/3/2024
11:31:17 AM

Palm Beach County Fleet Management Asset Maintenance History
10203955 2017 FORD F150 Pickup, 1/2 Ton, 4X4

Work Order: 2403642 **Meter:** 107383 **In Date:** 04/11/2024 **Closed:** 04/19/2024
Problem: Transition Prep Charge

Work Completed

Parts Issued

Quantity

- Transition Prep Charge, remove Gps & remove extra decals
- Shop Supplies

Shop Supplies 1.00

Hours: 4.50 Comm: 0.00 Labor: 328.50 Parts: 2.65 Total: 331.15

Total Hours: 124.60

Total Labor: 8,878.00

Total Comm: 0.00

Total Parts: 4,102.54