5/3/2024						
1:23:57 PM						

Palm Beach County Fleet Management Asset Maintenance History 10207773 2018 SCAG STTII72V-25KBD Mower, Zero Turn Radius (Ztr), 72in

Total Hours: 53.00 Labor: 3,851.00		Parts: 5,993.12	Comm: 0.00		Chargeo	l: 9844.12		
Work Order: Problem:	1812213 pre delivery inspectior	Meter:	1		In Date:	11/30/2018	Closed:	11/30/2018
Work Com	pleted			Parts Issued			Qı	antity
- pre deliv	ery inspection			Shop Supplies				1.00
- Shop Sup	pplies							
	Hours: 2.00		Comm: 0.00	Labor: 134.00	Parts: 3.0	0	Total:	137.00
Work Order: Problem:	1907019 Broken belt	Meter:	75		In Date:	07/08/2019	Closed:	07/31/2019
Work Com	pleted			Parts Issued			Qı	antity
- Replace l	broken drive belt.			Belt				1.00
- Shop Sup	pplies			Shop Supplies				1.00
	Hours: 1.00		Comm: 0.00	Labor: 67.00	Parts: 95.	82	Total:	162.82
Work Order: Problem:		Meter:	132		In Date:	10/02/2019	Closed:	10/15/2019
Work Com	pleted			Parts Issued			Qı	antity
- Replace l	broken pto belt and spr	ing.		Belt				1.00
- Replace l	blades.			Pto Spring				1.00
- Shop Sup	pplies			Mower Blade				3.00
				Hh Bolt				1.00
				Shop Supplies				1.00
	Hours: 3.00		Comm: 0.00	Labor: 219.00	Parts: 232	2.02	Total:	451.02

5/3/2024 1:23:57 PM

Palm Beach County Fleet Management Asset Maintenance History 10207773 2018 SCAG STTII72V-25KBD Mower, Zero Turn Radius (Ztr), 72in

Work Order: 1912223 Problem: Pm service, won't start.	Meter: 155		In Date:	11/26/2019	Closed:	12/05/201
Work Completed		Parts Issued			Qı	uantity
- Pm service.	Napagold Oil Filter				1.00	
- Check starting circuit. Lh lever neutral switch	15w40 Bulk Tank Pa	ahokee			4.00	
- Shop Supplies		Napagold Air Filter	•			1.00
		Fuel Fil				1.00
		Napagold Fuel Filte	r			1.00
		Switch Mount				1.00
		Shop Supplies				1.00
Hours: 5.00	Comm: 0.00	Labor: 365.00	Parts: 51.	84	Total:	416.84
Vork Order: 2009856 Problem: list	Meter: 355		In Date:	09/30/2020	Closed:	11/24/202
Work Completed		Parts Issued			Qı	uantity
- Replace damaged blades and blade bolts.		Mower Blade				3.00
- Replaced damaged mower deck.		Nut				3.00
- Shop Supplies		Hh Bolt				3.00
		Cutter Deck Smt-72	2v			1.00
		Wing Nut				1.00
		Roller Shaft				1.00
		Deck Wheel				3.00
		Shop Supplies				1.00
		Freight Charge				1.00
Hours: 7.50	Comm: 0.00	Labor: 547.50	Parts: 2,8	26 76	Total	3,374.26

Work Order:2100410Meter:374Problem:Staff will deliver this asset to Pahokee Fleet this morning for PM service.

In Date: 01/12/2021 Closed: 01/22/2021

Work Completed		Parts Issued		Quantity
- Preventive Maint. Service	15w40 Bulk Tank F	4.00		
- Replace bent blades and right blade bolt and spacer		Napagold Oil Filte	r	1.00
- Replace damaged pump drive belt and idler pulley		Fuel Fil		1.00
- Repaired damaged Pto clutch wires.		Napagold Fuel Filt	er	1.00
- Shop Supplies		Napagold Air Filte	er	1.00
		Napagold Air Filte	er	1.00
		Spindle Spacer		1.00
		Mower Blade		3.00
		Hh Bolt		1.00
		Belt		1.00
		Pulley		1.00
		Shop Supplies		1.00
Hours: 6.50	Comm: 0.00	Labor: 474.50	Parts: 305.07	Total: 779.57

Palm Beach County Fleet Management Asset Maintenance History 2018 SCAG STTII72V-25KBD Mower, Zero Turn Radius (Ztr), 72in 10207773

Meter: 585

Work Order: 2201964 Problem: PM Service.

In Date: 02/22/2022 Closed: 03/22/2022

Work Completed		Parts Issued		Qu	uantity
- Preventive Maint. Service		15w40 Bulk Tank P		4.00	
- coolant bottle assembly cracked and missing	g top replaced	Napagold Oil Filter			1.00
- parking brake lever broken removed broke o	Napagold Fuel Filter Fuel Fil			1.00	
installed new and adjusted				1.00	
- replaced worn bent blades and blade bolts	Napagold Air Filte	er		1.00	
Shop Supplies		Napagold Air Filte	er		1.00
		Reservoir			1.00
		Hh Bolt			3.00
		Mower Blade			3.00
		Bolt 3/8-16x2-3/4		1.00	
		Spacer	1.00 2.00		
		Nut			
		Nut		1.00	
		Rod End Male 3/8-	-24 Rh		1.00
		Nut			3.00
		Shop Supplies			1.00
		Freight Charge			1.00
Hours: 7.00	Comm: 0.00	Labor: 511.00	Parts: 266.45	Total:	777.45
ork Order: 2203977 Problem: Staff are saying that the deck is re	Meter: 601 ally difficult to raise and take	es the weight of two fe	In Date: 04/13/2022 (et to move the pedal.	Closed:	04/15/202
Work Completed		Parts Issued		Qu	antity
- Wash Deck And Pivot Points		Shop Supplies			1.00

Mechanism.

- Shop Supplies

Hours: 2.00

Comm: 0.00

Labor: 146.00

Parts: 2.65

Total: 148.65

Palm Beach County Fleet Management Asset Maintenance History 10207773 2018 SCAG STTII72V-25KBD Mower, Zero Turn Radius (Ztr), 72in

Nork Order: 2204774 Problem: Interlock-seat switch bro	Meter: 608 oken.		In Date:	05/03/2022	Closed:	05/05/202	
Work Completed		Parts Issued			Q	uantity	
- Replaced damaged left drive hand	Seat Switch				1.00		
Hours: 0.50	Comm: 0.00	Labor: 36.50	Parts: 13.1	5	Total:	49.65	
Nork Order: 2302868 Problem: PM Service.	Meter: 807		In Date:	03/21/2023	Closed:	04/24/202	
Work Completed		Parts Issued			Q	uantity	
- Preventive Maintenance Service		Inner Air Filter Rep	blaces 2845			1.00	
- Replaced damaged blades and bla	ade bolts.	Napagold Air Filte	er			1.00	
- Cut off damaged front deck anti s	calp wheels and replaced wheels and	Napagold Fuel Filt	er			1.00	
	outer scalp wheel and left outer wheel.	Fuel Fil		1.00			
Replaced damaged discharge chute cleaner assembly.	and spring. Replaced damaged air	15w40 Bulk Tank F	Pahokee			4.00	
- Battery failed load test. Installed n	ow batton	Napagold Oil Filte	1.00 3.00 3.00				
- R/r deck drive belt. Replaced worr		Hh Bolt					
tensioner spring.	i/damaged pump drive beit and	Blade					
- Shop Supplies		Chute Spring				1.00	
		Wing Nut				1.00	
		Carriage Bolt				4.00	
		Anti-scalp Wheel				4.00	
		Roller Shaft				1.00	
		Deck Wheel				3.00	
		Battery			1.00		
		Pto Spring				1.00	
		Belt				1.00	
		Discharge Chute				1.00	
		Air Filter Assy				1.00	
		Guide Roller				1.00	
		Shop Supplies				1.00	
Hours: 10.00	Comm: 0.00	Labor: 730.00	Parts: 1,00	5.84	Total:	1,735.84	

Palm Beach County Fleet Management Asset Maintenance History 10207773 2018 SCAG STTII72V-25KBD Mower, Zero Turn Radius (Ztr), 72in

Nork Order:	2310255	Meter: 93	30		In Date:	10/10/2023	Closed:	11/30/2023
Problem:	Broken pully belt.Dead batter	у.						
Work Completed			Parts Issued			Qı	antity	
- drive belt	broke and bent pully replaced	d drive belt and pul	lly deck drive	Belt				1.00
belt			-	Drive Pump Belt				1.00
- test run to check alignment of belts and pullys			Pulley				1.00	
	rt. Charge and load test batter	ry, it failed. Installed	d new battery	Belt				1.00
and checked	d charging system.			Battery				1.00
- Shop Sup	oplies			Shop Supplies				1.00
	Hours: 3.50	Co	omm: 0.00	Labor: 255.50	Parts: 418	3.68	Total:	674.18
Nork Order:	2312093	Meter: 93	34		In Date:	12/05/2023	Closed:	12/28/202
		~~						
Problem:	New Tires and Canopy dama	ge						
Problem: Work Com		ge		Parts Issued			Qı	antity
Work Com		-	rear tires	Parts Issued 26-1200-12 Multi-tr	rac Ca		Qu	antity 2.00
Work Com - Replaced	pleted	alled tire sealant in			rac Ca		Qu	•
Work Com - Replaced - Canopy a	pleted worn/damaged tires and insta	alled tire sealant in		26-1200-12 Multi-tr	rac Ca		Qı	2.00
Work Com - Replaced - Canopy a	pleted worn/damaged tires and insta nd frame damaged, Assemble ing hardware.	alled tire sealant in		26-1200-12 Multi-tr Slime Tire Sealant	rac Ca		Qu	2.00
Work Com - Replaced - Canopy a and mounti	pleted worn/damaged tires and insta nd frame damaged, Assemble ing hardware.	alled tire sealant in		26-1200-12 Multi-tr Slime Tire Sealant Turf Top	rac Ca		Qı	2.00 2.00 1.00
Work Com - Replaced - Canopy a and mounti	pleted worn/damaged tires and insta nd frame damaged, Assemble ing hardware.	alled tire sealant in new roof. Installed		26-1200-12 Multi-tr Slime Tire Sealant Turf Top Shop Supplies	rac Ca Parts: 765	5.49		2.00 2.00 1.00 1.00
Work Com - Replaced - Canopy a and mounti - Shop Sup	pleted worn/damaged tires and instand frame damaged, Assemble ing hardware. oplies Hours: 3.00	alled tire sealant in new roof. Installed	new canopy	26-1200-12 Multi-tr Slime Tire Sealant Turf Top Shop Supplies Tire Disposal Fee		5.49 04/02/2024	Total:	2.00 2.00 1.00 1.00 2.00 984.49
Work Com - Replaced - Canopy a and mounti - Shop Sup Work Order:	pleted worn/damaged tires and instand frame damaged, Assemble ing hardware. oplies Hours: 3.00	alled tire sealant in a new roof. Installed Co	new canopy	26-1200-12 Multi-tr Slime Tire Sealant Turf Top Shop Supplies Tire Disposal Fee	Parts: 765		Total:	2.00 2.00 1.00 1.00 2.00 984.49
Work Com - Replaced - Canopy a and mounti - Shop Sup Work Order:	pleted worn/damaged tires and insta nd frame damaged, Assemble ing hardware. oplies Hours: 3.00 2403247 Need four (4) keys, please.	alled tire sealant in a new roof. Installed Co	new canopy	26-1200-12 Multi-tr Slime Tire Sealant Turf Top Shop Supplies Tire Disposal Fee	Parts: 765		Total: Closed:	2.00 2.00 1.00 1.00 2.00 984.49
Work Com - Replaced - Canopy a and mounti - Shop Sup Work Order: Problem: Work Com	pleted worn/damaged tires and insta nd frame damaged, Assemble ing hardware. oplies Hours: 3.00 2403247 Need four (4) keys, please. pleted	alled tire sealant in a new roof. Installed Co	new canopy	26-1200-12 Multi-tr Slime Tire Sealant Turf Top Shop Supplies Tire Disposal Fee Labor: 219.00	Parts: 765		Total: Closed:	2.00 2.00 1.00 1.00 2.00 984.49 04/03/202
Work Com - Replaced - Canopy a and mounti - Shop Sup Work Order: Problem: Work Com	pleted worn/damaged tires and insta nd frame damaged, Assemble ing hardware. oplies Hours: 3.00 2403247 Need four (4) keys, please.	alled tire sealant in t new roof. Installed Co Meter: 97	new canopy	26-1200-12 Multi-tr Slime Tire Sealant Turf Top Shop Supplies Tire Disposal Fee Labor: 219.00 Parts Issued	Parts: 765	04/02/2024	Total: Closed:	2.00 2.00 1.00 2.00 984.49 04/03/202 hantity 5.00

Work Completed

- Transition Prep Charge

5/3/2024 1:23:57 PM	Palm Beach County Fleet Management Asset Maintenance History 10207773 2018 SCAG STTII72V-25KBD Mower, Zero Turn Radius (Ztr), 72in							
	Hours: 2.00	Comm: 0.00	Labor: 146.00	Parts: 0.00	Total: 146.00			
Total Hours: 53.00	Total Labor:	3,851.00	Total Comm: 0.00	Total Pa	arts: 5,993.12			