Hours: 3.00

Comm: 0.00

Palm Beach County Fleet Management Asset Maintenance History 10195207 2014 TOYOTA PRIUS Car, Mid Size, Hybrid

Total Hours: 69.30 Labor: 4,650.90	oor: 4,650.90 Parts: 3,017.12 Coi		Charged: 9144.17				
Work Order: 1405451 Me Problem: 1061 - Pre Delivery Inspec	ter: 117		In Date:	06/04/2014	Closed:	06/04/2014	
Work Completed							
- Pre Delivery Inspection							
Hours: 2.00	Comm: 0.00	Labor: 120.00	Parts: 0.0	0	Total:	120.00	
Work Order: 1411645 Me Problem: Pm service.	ter: 3040		In Date:	11/18/2014	Closed:	12/04/2014	
Work Completed		Parts Issued			Qı	ıantity	
- Pm service.		Syn0w20				5.00	
- Rotate and balance all four tires.		Napagold Oil Filter				1.00	
- Shop Supplies		Shop Supplies				1.00	
Hours: 3.00	Comm: 0.00	Labor: 180.00	Parts: 36.	32	Total:	216.32	
Work Order: 1504189 Me Problem: left rear tire flat .Tire pressu	ter: 4260 ure warning light on.		In Date:	04/22/2015	Closed:	04/28/2015	
Work Completed		Parts Issued			Qı	ıantity	
- Repair flat and balance left rear tire.		Shop Supplies				1.00	
- Shop Supplies							
Hours: 1.00	Comm: 0.00	Labor: 60.00	Parts: 2.0	0	Total:	62.00	
Work Order: 1512889 Me Problem: Pm service.	ter: 6714		In Date:	12/21/2015	Closed:	01/19/2016	
Work Completed		Parts Issued			Qı	uantity	
- Pm service.		Syn0w20				5.00	
- Rotate and balance all four tires.		Napagold Oil Filter				1.00	
- Shop Supplies		Washer Fluid Conce	ntr			1.00	
		Shop Supplies				1.00	

Labor: 180.00

Parts: 33.61

Total: 213.61

Palm Beach County Fleet Management Asset Maintenance History 10195207 2014 TOYOTA PRIUS Car, Mid Size, Hybrid

Work Order: 1609895 Meter: 8907 In Date: 09/22/2016 Closed: 09/29/2016

Problem: P.M. service and remote battery and tire pressure light on.

Work Completed		Parts Issued		Quantity
- P.m. Service.		Napagold Oil Filte	r	1.00
Rotae and balance all tires.Replace key fob battery.		Syn0w20	5.00	
		Wiper Bleade Anco	1.00	
- Fabricate and replace missing asset #s.		Wiper Blade - Accu	ufit - Rear - Oe Style	1.00
- Shop Supplies		Washer Fluid Cond	1.00	
		Lithium Coin Cell	1.00	
		Wiper Blade Anco	1.00	
		Shop Supplies		1.00
Hours: 4.50	Comm: 0.00	Labor: 270.00	Parts: 54.34	Total: 324.34

Work Order: 1703285 Meter: 9347 In Date: 04/03/2017 Closed: 04/12/2017

Problem: P.M. service.

Work Completed		Parts Issued		Quantity
- P.m. Service.		Syn0w20		5.00
- Rotate and balance tires.		Napagold Oil Filte	er	1.00
- Shop Supplies		Wiper Bleade And	0	1.00
		18" wiper blades		1.00
		Wiper Blade - Acc	ufit - Rear - Oe Style	1.00
		Shop Supplies		1.00
Hours: 3.00	Comm: 0.00	Labor: 180.00	Parts: 47.81	Total: 227.81

Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued

Hours: 0.00 Comm: 90.00 Labor: 0.00 Parts: 0.00 Total: 90.00

Palm Beach County Fleet Management Asset Maintenance History 10195207 2014 TOYOTA PRIUS Car, Mid Size, Hybrid

Work Order: 1712096 Meter: 10814 In Date: 12/11/2017 Closed: 12/18/2017

Problem: P.M. service and tire light on and detail.

Work Completed		Parts Issued		Quantity
- P.m. service.- Balance and rotate all four tires.- Shop Supplies		Syn0w20		5.00
		Napagold Oil Filter		1.00
		Wiper Bleade Anco		1.00
		18" wiper blades		1.00
		16in Exactfit-rear		1.00
		Shop Supplies		1.00
Hours: 3.00	Comm: 0.00	Labor: 180.00	Parts: 47.92	Total: 227.92

Work Order: 1712369 Meter: 10712 In Date: 12/15/2017 Closed: 12/15/2017

Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued

Hours: 0.00 Comm: 90.00 Labor: 0.00 Parts: 0.00 Total: 90.00

Work Order: 1807557 Meter: 12817 In Date: 07/25/2018 Closed: 08/01/2018

Problem: P.M. service.

Work Completed	Parts Issued	Quantity
- P.m. service.	Napagold Oil Filter	1.00
- Check battery and charging system .after fully charging battery ,failed	load Syn0w20	5.00
test . R&r defective battery.	Napa Cabin Air Filter	1.00
- Replace two front tires .balance and rotate all four tires. Nitrofill.	16in Exactfit-rear	1.00
- Complete four wheel alignment. Road test.	Wiper Bleade Anco	1.00
- Shop Supplies	18" wiper blades	1.00
	Agm Battery	1.00
	738274571 195-65r15 A	2.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours: 7.50 Comm: 0.00	Labor: 450.00 Parts:	512.37 Total: 962.37

Palm Beach County Fleet Management Asset Maintenance History 10195207 2014 TOYOTA PRIUS Car, Mid Size, Hybrid

Work Order: 1809973 Meter: 13517 In Date: 09/26/2018 Closed: 09/26/2018

Problem: 10 - Wash ticket(s) issued

Work Completed

- 10 - Wash ticket(s) issued

Hours: 0.00 Comm: 83.40 Labor: 0.00 Parts: 0.00 Total: 83.40

Work Order: 1901059 Meter: 15580 In Date: 01/29/2019 Closed: 02/07/2019

Problem: P.M. service.

Work Completed		Parts Issued		Quantity
- P.m. service.		Napagold Oil Filter	r	1.00
- Replace two tires . Rotate and balance all four tires. Nitrofill all.		Syn0w20		4.00
- Shop Supplies		16in Exactfit-rear		1.00
		18" wiper blades		1.00
		Wiper Bleade Anco)	1.00
		Tire Mic 195/65/15		2.00
		Shop Supplies Tire Disposal Fee		1.00
				2.00
Hours: 4.00	Comm: 0.00	Labor: 268.00	Parts: 299.47	Total: 567.47

Work Order: 1908620 Meter: 17269 In Date: 08/16/2019 Closed: 09/09/2019

Problem: P.M. service and towed in for no start.

Work Completed		Parts Issued		Quantity
- P.m. service.	vice.			1.00
- Charge battery fully . Perform battery analyst test . Battery failed test . F	st . Battery failed test . R&r	Napagold Oil Filte	er	1.00
defective battery .		Syn0w20		5.00
- Remove left front door panel to replace defectiv	e lock cylinder .	18" wiper blades		1.00
- Rotate and high speed balance all four tires . Nit	- Rotate and high speed balance all four tires . Nitrofill all.			1.00
- Shop Supplies		16in Exactfit-rear Washer Fluid Concentr Lock Cylinder Shop Supplies		1.00
				1.00
				1.00
				1.00
Hours: 5.50	Comm: 0.00	Labor: 368.50	Parts: 535.20	Total: 903.70

Palm Beach County Fleet Management Asset Maintenance History 10195207 2014 TOYOTA PRIUS Car, Mid Size, Hybrid

Work Order: 1908654 Meter: 16925 In Date: 08/16/2019 Closed: 08/19/2019

Problem: NO START

Work Completed

- Tow From: 8100 Forest Hill Blvd To: Lv Shop

Hours: 0.00 Comm: 96.00 Labor: 0.00 Parts: 0.00 Total: 96.00

Work Order: 1909027 Meter: 16925 In Date: 08/28/2019 Closed: 08/28/2019

Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued

Hours: 0.00 Comm: 90.00 Labor: 0.00 Parts: 0.00 Total: 90.00

Work Order: 1909963 Meter: 17278 In Date: 09/26/2019 Closed: 09/26/2019

Problem: 5 - Wash ticket(s) issued

Work Completed

- 5 - Wash ticket(s) issued

Hours: 0.00 Comm: 47.70 Labor: 0.00 Parts: 0.00 Total: 47.70

Work Order: 1912933 Meter: 17559 In Date: 12/18/2019 Closed: 12/18/2019

Problem: 10 - Wash ticket(s) issued

Work Completed

- 10 - Wash ticket(s) issued

Hours: 0.00 Comm: 83.40 Labor: 0.00 Parts: 0.00 Total: 83.40

Meter: 17559

Work Order: 1912939
Problem: 10 - Wash ticket(s) issued

Work Completed

- 10 - Wash ticket(s) issued

Hours: 0.00 Comm: 83.40 Labor: 0.00 Parts: 0.00 Total: 83.40

In Date: 12/18/2019 **Closed:** 12/18/2019

Palm Beach County Fleet Management Asset Maintenance History 10195207 2014 TOYOTA PRIUS Car, Mid Size, Hybrid

Work Order: 2005574 Meter: 17682 In Date: 06/03/2020 Closed: 06/11/2020

Problem: P.M. service and towed for dead battery and detail .

Work Completed		Parts Issued		Quantity
- P.m. service.		Napagold Oil Filte	r	1.00
- Clean fresh air intake and replace cabin air filte	Syn0w20		5.00	
- Charge battery fully . Test battery and charging system . Battery failed I		18" wiper blades	1.00	
test . R&r defectivebattery .		Wiper Bleade Anco 16in Exactfit-rear Washer Fluid Concentr Napa Cabin Air Filter		1.00
- Rotate and balance all four tires . Nitrofill all.				1.00
- Shop Supplies				1.00
				1.00
		Agm Battery		1.00
		Shop Supplies		1.00
Hours: 4.50	Comm: 0.00	Labor: 328.50	Parts: 286.80	Total: 615.30
W 1 0 1 0005744	N 4 47004			00 01 1 00/00/0000

Work Order: 2005741 Meter: 17634 In Date: 06/09/2020 Closed: 06/09/2020

Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued

Hours: 0.00 Comm: 90.00 Labor: 0.00 Parts: 0.00 Total: 90.00

Work Order: 2005760 Meter: 17634 In Date: 06/03/2020 Closed: 06/10/2020

Problem: No start/ PM

Work Completed

- Tow From: 8100 Forest Hill Blvd To: Lv shop

Hours: 0.00 Comm: 96.00 Labor: 0.00 Parts: 0.00 Total: 96.00

- Tow From: 8100 Forest Hill Blvd Admin To: Lv Shop Hours: 0.00

Palm Beach County Fleet Management Asset Maintenance History 10195207 2014 TOYOTA PRIUS Car, Mid Size, Hybrid

2.00.101 W	10133207	2014 101017	i itioo oai, iiiia oize,	TIYDITA			
Work Order: 2012374 Problem: P.M. service and recall 20V-3	Meter:	17876		In Date:	12/14/2020	Closed:	12/23/2020
Work Completed			Parts Issued			Qı	uantity
- Preventive Maint. Service			Washer Fluid Cond	centr			1.00
- Rotate and speed balance all four, nitro	o fill all		18in Exactfitblade				1.00
- Transport to and from dealer for recall	20v-369 .		26in Exactfitblade				1.00
- Shop Supplies			16in Exactfit-rear				1.00
			Syn0w20				5.00
			Napagold Oil Filte	r			1.00
			Shop Supplies				1.00
Hours: 5.00		Comm: 0.00	Labor: 365.00	Parts: 68.	89	Total:	433.89
Work Order: 2103392 Problem: NO START	Meter:	17900		In Date:	03/25/2021	Closed:	03/30/2021
Work Completed							
- Charge battery and test, Good battery (Gps draw.						
Hours: 0.50		Comm: 0.00	Labor: 36.50	Parts: 0.0	0	Total:	36.50
Work Order: 2103672 Problem: NO START	Meter:	17900		In Date:	03/25/2021	Closed:	03/30/2021
Work Completed							

Comm: 96.00

Labor: 0.00

Parts: 0.00

Total: 96.00

Hours: 0.00

Palm Beach County Fleet Management Asset Maintenance History 10195207 2014 TOYOTA PRIUS Car, Mid Size, Hybrid

Work Order: 2107600 Meter: 18625 07/13/2021 **Closed:** 07/20/2021 In Date: Problem: PM Service. Tire light on . **Parts Issued** Quantity **Work Completed** Napagold Oil Filter 1.00 - Preventive Maint, Service Syn0w20 5.00 - check, replaced cabin a/c filter and clean fresh air intake. 26in Exactfitblade 1.00 - balance and rotate all 4 tires. Nitro fill all. 18in Exactfitblade 1.00 - Shop Supplies 16in Exactfit-rear 1.00 Napa Cabin Air Filter 1.00 **Shop Supplies** 1.00 Hours: 3.50 Comm: 0.00 Labor: 255.50 Parts: 58.19 Total: 313.69 Work Order: 2110079 Meter: 18635 In Date: 06/14/2021 **Closed:** 09/16/2021 Problem: 15 - Wash ticket(s) issued **Work Completed** - 15 - Wash ticket(s) issued Comm: 117.80 Hours: 0.00 Labor: 0.00 Parts: 0.00 Total: 117.80 Work Order: 2112038 Meter: 18645 In Date: 11/09/2021 Closed: 11/15/2021 Problem: Towed in for wont start, Brittany has keys **Work Completed** - Charge battery fully . Test battery and charging system all ok . Perform draw test .035 from Gps . Vehicle needs to be drive more often with Gps hook up. Hours: 0.50 Comm: 0.00 Labor: 36.50 Total: 36.50 Parts: 0.00 Meter: 18645 Work Order: 2112237 11/08/2021 **Closed:** 11/15/2021 In Date: **Problem:** wont start, Brittany has keys **Work Completed** - Tow From: 8100 Fh Blvd. Croc To: vista

Comm: 90.40

Labor: 0.00

Parts: 0.00

Total: 90.40

Palm Beach County Fleet Management Asset Maintenance History 10195207 2014 TOYOTA PRIUS Car, Mid Size, Hybrid

Work Order: 2200821 Meter: 18645 In Date: 01/25/2022 Closed: 02/02/2022

Problem: PM Service. Key fob battery

Work Completed	Parts Issued		Quantity	
- Preventive Maint. Service	eventive Maint. Service			1.00
- rotate and balance all 4 tire nitro fill all	16in Exactfit-rear		1.00	
- car was found inoperative no power at all bat	18in Exactfitblade		1.00	
·	failed load test battery was replaced and load tested vehicle operating as design at this time key fob battery was also replace since the remote would			1.00
design at this time key fob battery was also replan not function properly				1.00
		Motor Oil		5.00
- Shop Supplies		Lithium Coin Cell Shop Supplies		1.00
				1.00
Hours: 4.30	Comm: 0.00	Labor: 313.90	Parts: 243.83	Total: 557.73

Work Order: 2204479 Meter: 18752 In Date: 04/26/2022 Closed: 04/28/2022

Problem: Towed in for NO START

Work Completed	Parts Issued	Quantity
- Charge battery fully . Test battery and charging system . Perform draw t	est Lift Support	2.00
found .225 amp draw from Gps staying and beeping .goes up to .257 am	ips Shop Supplies	1.00
. Without Pgs .005 amps normal. Remove Gps and put on seat needs rep	air	

- Test and replace both rear hatch struts .

- Shop Supplies

	Hours: 1.00	(Jomm: 0.00	Labor: 73.00	Parts: 51.9)1	i otai:	124.91
Work Order: 2204		Meter: 1	18752		In Date:	04/25/2022 Cld	osed:	04/29/2022

Problem: NO START

Work Completed

- Tow From: 8100 forest Hill Blvd (administration area) To: Lv shop

Hours: 0.00 Comm: 113.00 Labor: 0.00 Parts: 0.00 Total: 113.00

Palm Beach County Fleet Management Asset Maintenance History 10195207 2014 TOYOTA PRIUS Car, Mid Size, Hybrid

Problem: PM Service.

Work Completed		Parts Issued		Quantity
- Preventive Maint. Service completed	Napagold Oil Filter		1.00	
- balance and rotate all 4 tires . Nitro fill all.	Syn0w20		4.00	
- check,replaced cabin a/c filter and clean fresh air in	16in Exactfit-rear		1.00	
- Shop Supplies	18in Exactfitblade		1.00	
		26in Exactfitblade		1.00
		Napa Cabin Air Filter		1.00
		Shop Supplies		1.00
Hours: 3.50	Comm: 0.00	Labor: 255.50	Parts: 61.43	Total: 316.93

Work Order: 2303962 Meter: 18910 In Date: 04/21/2023 Closed: 05/01/2023

Problem: NO START/PM Service

Work Completed		Parts Issued		Quantity
- Perform Pm Service		Syn0w20		4.00
- Battery tested bad, Charge and retest. Failed battery. Replace battery and check for draw. Ok		16in Exactfit-rear		1.00
		18in Exactfitblade		1.00
- Rotate, balance and nitro service tires.	26in Exactfitblade		1.00	
- Shop Supplies	Napagold Oil Filter		1.00	
		Agm Battery		1.00
		Shop Supplies		1.00
Hours: 4.00	Comm: 0.00	Labor: 292.00	Parts: 222.35	Total: 514.35

Work Order: 2304845 Meter: 18910 In Date: 04/20/2023 Closed: 05/15/2023

Problem: NO START

Work Completed

- Tow From: 8100 Forest Hill Blvd, Wpb (administration) To: 2601 Vista Pkwy,

West Palm Beach 33411(lv Shop)

Hours: 0.00 Comm: 124.30 Labor: 0.00 Parts: 0.00 Total: 124.30

Palm Beach County Fleet Management Asset Maintenance History 10195207 2014 TOYOTA PRIUS Car, Mid Size, Hybrid

Work Order: 2309572 Meter: 19501 In Date: 09/20/2023 Closed: 09/20/2023

Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 0.00 Total: 146.00

Work Order: 2309685 Meter: 19501 In Date: 09/21/2023 Closed: 09/22/2023

Problem: 1 - Detail Vehicle Wash Ticket(s) Issued to: Dispatch

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued to: Dispatch

Hours: 0.00 Comm: 84.75 Labor: 0.00 Parts: 0.00 Total: 84.75

Work Order: 2311657 Meter: 19702 In Date: 11/22/2023 Closed: 12/04/2023

Problem: pm service

Parts Issued Work Completed Quantity Napagold Oil Filter 1.00 - Preventive Maint. Service Svn0w20 4.00 18in Exactfitblade 1.00 26in Exactfitblade 1.00 Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 41.81 Total: 187.81

Work Order: 2401234 Meter: 21244 In Date: 02/02/2024 Closed: 02/07/2024

Problem: low tire light

Parts Issued Quantity **Work Completed** Tire Mic 195/65/15 2.00 - Replaced And Programmed 2 Tpms Sensors Sensor 2.00 - Mount And Balance Both Front Tires, (6yr Old And Dryrot) Tire Disposal Fee 2.00 Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 412.89 Total: 558.89

Work Order: 2404716 Meter: 22607 In Date: 05/10/2024 Closed: 05/14/2024

Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Palm Beach County Fleet Management Asset Maintenance History 10195207 2014 TOYOTA PRIUS Car, Mid Size, Hybrid

Hours: 0.00 Comm: 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00

Total Hours: 69.30 Total Labor: 4,650.90 Total Comm: 1,476.15 Total Parts: 3,017.12