3:01:47 PM		102010	2016 FORD ESC	APE Suv, Mid Size	,			
Total Hours: 93.10 Labor: 6,515.30		30	Parts: 6,647.50	Comm: 639.63		Charged	: 13802.43	
Work Order: 16099 Problem: 1061		Meter: pection	354		In Date:	09/23/2016	Closed:	09/23/2016
Work Completed	I							
- Pre Delivery Ins	pection							
	Hours: 2.00		Comm: 0.00	Labor: 120.00	Parts: 0.0	0	Total:	120.00
Work Order: 17027 Problem: P.M. S		Meter:	4754		In Date:	03/20/2017	Closed:	03/29/2017
Work Completed	I			Parts Issued			Qı	uantity
- P.m. Service.				5w20 Engine Oil				6.00
- Rotate and bala	nce tires.			Napagold Oil Filter				1.00
- Shop Supplies				Shop Supplies				1.00
	Hours: 3.00		Comm: 0.00	Labor: 180.00	Parts: 17.	89	Total:	197.89
Nork Order: 17080 Problem: P.M. s		Meter:	9607		In Date:	08/16/2017	Closed:	08/24/2017
Work Completed	I			Parts Issued			Qı	uantity
- P.m. service.				5w20 Engine Oil				6.00
- Rotate and high	n speed balance al	l four ti	res.	Napagold Oil Filter				1.00
- Shop Supplies				Shop Supplies				1.00
	Hours: 3.00		Comm: 0.00	Labor: 180.00	Parts: 18.	05	Total:	198.05

Palm Beach County Fleet Management Asset Maintenance History

6/3/2024

6/3/2024	
3:01:47 PM	

Vork Order: 1800728 Problem: P.M. service.	Meter:	14605		In Date:	01/22/2018	Closed:	01/31/2018
Work Completed			Parts Issued			Qı	antity
- P.m. service.			5w20 Engine Oil				6.00
- Rotate and high speed balance all four tires.			Napagold Oil Filter				1.00
- Shop Supplies			Wiper Blade				1.00
			Wiper Blade				1.00
			Blade				1.00
			Shop Supplies				1.00
Hours: 3.00		Comm: 0.00	Labor: 180.00	Parts: 83.	56	Total:	263.56
ork Order: 1805782 Problem: P.M. service.	Meter:	19626		In Date:	06/06/2018	Closed:	06/12/2018
Work Completed			Parts Issued			Qı	uantity
- P.m. Service.			Napagold Oil Filter				1.00
- Rotate and balance tires.			5w20 Engine Oil				6.00
- Shop Supplies			Blade				1.00
			Wiper Blade				1.00
			Wiper Blade				1.00
			Shop Supplies				1.00
Hours: 3.00		Comm: 0.00	Labor: 180.00	Parts: 74.	35	Total	254.35

6/3/2024	
3:01:47 PM	

	Closed:	10/04/2018
Work Completed Parts Issued	Qı	antity
- P.m. service. Napagold Oil Filter		1.00
- Replace all four tires . Balance and nitrogen fill all tires . 5w20 Engine Oil		6.00
- Perform four wheel alignment. Road test. Blade		1.00
- Shop Supplies Tire235/55/17 Mic		4.00
Washer Fluid Concentr		1.00
Wiper Blade		1.00
Wiper Blade		1.00
Shop Supplies		1.00
Tire Disposal Fee		4.00
Hours: 6.50 Comm: 0.00 Labor: 435.50 Parts: 840.74	Total:	1,276.24
Work Order: 1902231 Meter: 29721 In Date: 02/28/2019 C	Closed:	03/07/2019
Problem: P.M. service.		
Problem: P.M. service. Work Completed Parts Issued	Qı	antity
	Qı	antity 1.00
Work Completed Parts Issued	Qı	-
Work Completed Parts Issued - P.m. service. Napagold Oil Filter	Qı	1.00
Work CompletedParts Issued- P.m. service.Napagold Oil Filter- Rotate and balance all four tires . Nitrofill all.Sw20 Engine Oil	Qu	1.00 6.00
Work CompletedParts Issued- P.m. service.Napagold Oil Filter- Rotate and balance all four tires . Nitrofill all.5w20 Engine Oil- Shop SuppliesWasher Fluid Concentr	Qı	1.00 6.00 1.00
Work CompletedParts Issued- P.m. service.Napagold Oil Filter- Rotate and balance all four tires . Nitrofill all.5w20 Engine Oil- Shop SuppliesWasher Fluid ConcentrNapa Cabin Air Filter	Qı	1.00 6.00 1.00 1.00
Work CompletedParts Issued- P.m. service.Napagold Oil Filter- Rotate and balance all four tires . Nitrofill all.Sw20 Engine Oil- Shop SuppliesWasher Fluid ConcentrNapa Cabin Air FilterFord Triton Pvc Swc		1.00 6.00 1.00 1.00 1.00
Work CompletedParts Issued- P.m. service.Napagold Oil Filter- Rotate and balance all four tires . Nitrofill all.5w20 Engine Oil- Shop SuppliesWasher Fluid Concentr- Napa Cabin Air FilterFord Triton Pvc Swc- Ford Triton Pvc SwcShop Supplies	Total:	1.00 6.00 1.00 1.00 1.00 252.68
Work Completed Parts Issued - P.m. service. Napagold Oil Filter - Rotate and balance all four tires . Nitrofill all. Sw20 Engine Oil - Shop Supplies Washer Fluid Concert Napa Cabin Air Filter Napa Cabin Air Filter Ford Triton Pvc Swc Shop Supplies Hours: 3.00 Comm: 0.00 Labor: 201.00 Parts: 51.68 Work Order: 1906995 Meter: 33550 In Date: 07/08/2019 O	Total: Closed:	1.00 6.00 1.00 1.00 1.00 252.68
Work Completed Parts Issued - P.m. service. Napagold Oil Filter - Rotate and balance all four tires . Nitrofill all. Sw20 Engine Oil - Shop Supplies Washer Fluid Concentr Napa Cabin Air Filter Napa Cabin Air Filter Ford Triton Pvc Swc Shop Supplies Hours: 3.00 Comm: 0.00 Labor: 201.00 Parts: 51.68 Work Order: 1906995 Meter: 33550 In Date: 07/08/2019 Concentr Problem: ABS light on and speedometer inop. In Date: 07/08/2019 Concentr	Total: Closed:	1.00 6.00 1.00 1.00 1.00 252.68 07/18/2019
Work Completed Parts Issued Napagold Oil Filter Napagold Oil Filter - P.m. service. Sw20 Engine Oil Sw20 Engine Oil Napagold Oil Filter - Shop Supplies Sw20 Engine Oil Washer Fluid Concentr Napa Cabin Air Filter - Shop Supplies Ford Triton Pvc Swc Shop Supplies Shop Supplies Hours: 3.00 Corm: 0.00 Labor: 201.00 Parts: 51.68 Work Order: 1906995 Meter: 33550 In Date: 07/08/2019 Of Work Completed - Transport vehicle to dealer for Abs light and speedometer inop.(harness) Parts Issued Shop Supplies	Total: Closed:	1.00 6.00 1.00 1.00 1.00 252.68 07/18/2019

	Palm Beach County Fleet Managem 201093 2016 FORD ESCAPE Su		nce History			
Nork Order: 1907467	Meter: 33639		In Date:	07/19/2019	Closed:	07/23/2019
Problem: Had to jump start.						
Work Completed		Parts Issued			Qı	uantity
- Charge battery fully . Test battery and	l charging system . Battery failed load	Bat Cable				1.00
test . R&r defective battery and corrode	Battery				1.00	
battery monitoring system .		Shop Supplies				1.00
- Shop Supplies Hours: 2.00	Comm: 0.00	Labor: 134.00	Parts: 244	.50	Total:	378.50
Nork Order: 1909214 Problem: PM Service	Meter: 34801		In Date:	09/06/2019	Closed:	09/18/2019
Work Completed		Parts Issued			Qı	uantity
- P.m. service.		Napagold Oil Filter				1.00
- Rotate and balance all four tires . Nitr	ofill all.	5w20 Engine Oil				6.00
- Shop Supplies		Blade				1.00
		Wiper Blade				1.00
		Wiper Blade				1.00
		Washer Fluid Concer	ntr			1.00
		Shop Supplies				1.00
Hours: 3.00	Comm: 0.00	Labor: 201.00	Parts: 84.	78	Total:	285.78

Hours: 3.50

Vork Order: 2002273 Problem: P.M. service.	Meter: 39789		In Date:	03/04/2020 C	losed:	03/12/2020
Work Completed		Parts Issued			Qı	uantity
- P.m. service.		Napagold Oil Filter				1.00
- R&r both leaking rear shocks .		5w20 Engine Oil				6.00
- Replace both rear brake rotors and	pads . Service calipers . Flush and	Napa Air Filter				1.00
bleed brake system .road test .		Blade				1.00
- Rotate and high speed balance all for	Wiper Blade				1.00	
- Shop Supplies	Wiper Blade				1.00	
	Shock Absober				2.00	
		Brk Fluid Dot 4-32oz				1.00
		Non-chlor Brake Clnr				1.00
		Brake Rotor				2.00
		Brake Pad Real				1.00
		Shop Supplies				1.00
Hours: 7.60	Comm: 0.00	Labor: 554.80	Parts: 49	6.21	Total:	1,051.01
Vork Order: 2007092 Problem: PM Service	Meter: 45045		In Date:	07/21/2020 C	losed:	07/27/202
Work Completed		Parts Issued			Q	uantity
- P.m. service.		Napagold Oil Filter				1.00
- Replace cabin air filter and clean fre	sh air intake .	5w20 Engine Oil				6.00
- Rotate and high speed balance all fo		Blade				1.00
- Shop Supplies		Wiper Blade				1.00
· · ·		Wiper Blade				1.00
		•				

Comm: 0.00

Shop Supplies

Labor: 255.50

Parts: 91.87

1.00

Total: 347.37

Work Order: 2100084 Meter: 50901 01/05/2021 **Closed:** 01/14/2021 In Date: Problem: PM Service on Friday, Thank you! **Work Completed** Parts Issued Quantity 5w20 Engine Oil 6.00 - Preventive Maint, Service Napagold Oil Filter 1.00 - Replace two tires .rotate and balance all four wheels and tires. Nitrogen fill tires and reinstall on vehicle. reset Tpms Wiper Blade 1.00 - Cabin A/c filter. Clean outside air pick up vents filled with leaves. Wiper Blade 1.00 - Alignment. Use alignment machine to preform 4 wheel alignment. Use Blade 1.00 alignment machine to adjust rear Toe into spec. Use machine to center Tire235/55/17 Mic 2.00 steering wheel. Test drive vehicle. Cabin A/c Filter 1.00 - Shop Supplies Shop Supplies 1.00 Tire Disposal Fee 2.00 Hours: 7.00 Comm: 0.00 Labor: 511.00 Parts: 648.34 Total: 1,159.34 In Date: 05/27/2021 Closed: 06/08/2021 Meter: 55411

Work Order: 2105883

Problem: PM Service. Coming in for an early PM as there are also some dash lights coming up. Also requesting a detail. Thank you!

Work Completed		Parts Issued		Quantity
- Preventive Maint. Service		5w20 Engine Oil	6.00	
Oil Maintance Light On No Other Lights C	Napagold Oil Filter	1.00		
- Diagnose dash light . Low tire . Dismou	nt And Mount 2 New Tires Rotate	Blade		1.00
And Balance All four With Nitro Fill		Wiper Blade		1.00
- Shop Supplies		Wiper Blade		1.00
		Tire235/55/17 Mic		2.00
		Shop Supplies		1.00
		Tire Disposal Fee		2.00
Hours: 4.00	Comm: 0.00	Labor: 292.00	Parts: 532.64	Total: 824.64
Work Order: 2106200 Problem: 1 - Detail Vehicle Wash Ticke	Meter: 55256 et(s) Issued		In Date: 06/07/2021	1 Closed: 06/07/2021
Work Completed				
- 1 - Detail Vehicle Wash Ticket(s) Issued				
Hours: 0.00	Comm: 96.00	Labor: 0.00	Parts: 0.00	Total: 96.00

Nork Order: Problem:	2109254 Got a brake light bulb out. Man	Meter: 58730	wait for a new bulb in	In Date: stall if that is ok	08/25/2021 ? Thanks!	Closed:	08/30/2021
Work Completed		Parts Issued			Qu	uantity	
 Right rear tail light lens full of water . Leak test . R&r defective leaking right rear tail light lens assembly . Shop Supplies 			L Amp Asy				1.00
			Shop Supplies				1.00
Hours: 0.50 Comm: 0.00		Labor: 36.50	Parts: 370	.07	Total: 406.57		
Vork Order: Problem:	2110614 PM Service. Please detail befor	Meter: 60218 re pick up notice, Thank you!		In Date:	09/30/2021	Closed:	10/13/2021
Work Com	pleted		Parts Issued			Qı	uantity
- Preventiv	e Maint. Service		Napagold Oil Filte	r			1.00
- Inspected Brakes Front Pads Below Minium R&r Front Brakes Pads,			5w20 Engine Oil				6.00
Resurface R	otors And Service Calipers. Blee	d And Flush Brakes . Road Test	Washer Fluid Concentr				1.00
- Rotate Ar	nd Balance All 4 Tires With Nitro	Fill	Wiper Blade				1.00
- Shop Sup	oplies		Wiper Blade				1.00
			Blade				1.00
			Non-chlor Brake C	Clnr			1.00
			Brake Pads				1.00
			Shop Supplies				1.00
	Hours: 6.50	Comm: 0.00	Labor: 474.50	Parts: 123	.34	Total:	597.84
Vork Order: Problem:	2110956 1 - Detail Vehicle Wash Ticket(Meter: 60198 s) Issued		In Date:	10/08/2021	Closed:	10/08/2021
Work Com	pleted						
- 1 - Detail	Vehicle Wash Ticket(s) Issued						
	Hours: 0.00	Comm: 90.40	Labor: 0.00	Parts: 0.00)	Total:	90.40

Work Completed		Parts Issued		Quantity
- Preventive Maint. Service		5w20 Engine Oil		6.00
- Check both tail lamps, water intrusion,oute	Napagold Oil Filte	r	1.00	
& right deck lid lamp leaking		Washer Fluid Cond	centr	1.00
- Rotate and speed balance. nitro fill		Blade		1.00
- Check all, R & I new rear brake, R & I new r	Wiper Blade		1.00	
road test		Wiper Blade	1.00	
- Shop Supplies		Lamp Assy	1.00	
		Lamp Assy		1.00
		Brake Rotor		2.00
		Brk Fluid Dot 4-12	OZ	1.00
		Non-chlor Brake C	Inr	1.00
		Brake Pad		1.00
		Shop Supplies		1.00
Hours: 7.30	Comm: 0.00	Labor: 532.90	Parts: 809.67	Total: 1,342.57
ork Order: 2203403	Meter: 65418		In Date: 03/29/2022	2 Closed: 03/29/202

- 1 - Detail Vehicle Wash Ticket(s) Issued

Hours: 0.00

Comm: 90.40

Labor: 0.00

Parts: 0.00

Total: 90.40

Work Order: Problem:	2209803 PM Service.	Meter:	70805		In Date:	09/21/2022	Closed:	09/30/2022
Work Com	pleted			Parts Issued			Qı	uantity
- Preventiv	ve Maint. Service			Napagold Oil Filter				1.00
- Perform battery analyzing, load and charging sys test, failed. R & I new		5w20 Engine Oil				6.00		
battery . Hook up Ids to reset Bsm .			Washer Fluid Concen	tr			1.00	
- R & I new cabin filter and clean fresh air intake .			Blade				1.00	
- Shop Suj	pplies			Wiper Blade				1.00
				Wiper Blade				1.00
				Battery				1.00
				Napa Cabin Air Filter				1.00
				Shop Supplies				1.00
	Hours: 4.00		Comm: 0.00	Labor: 292.00	Parts: 239).27	Total:	531.27
	Right rear FLAT TIRE TOW IN TO							
Work Com	npleted			Parts Issued			Qı	uantity
	pleted ght rear tire and balance . Nitro fill	all .reset Tp	ms .	Parts Issued Shop Supplies			Qı	uantity 1.00
	ght rear tire and balance . Nitro fill	all .reset Tp	ms .				Qı	-
- Repair ri	ght rear tire and balance . Nitro fill	all .reset Tp	ms . Comm: 0.00		Parts: 2.6	5		-
- Repair rig - Shop Suj Work Order:	ght rear tire and balance . Nitro fill pplies Hours: 1.00	all .reset Tpi Meter:	Comm: 0.00	Shop Supplies	Parts: 2.6	5 11/14/2022	Total:	1.00 75.65
- Repair rig - Shop Suj Work Order:	ght rear tire and balance . Nitro fill pplies Hours: 1.00 2211690 FLAT TIRE TOW IN TO FLEET		Comm: 0.00	Shop Supplies			Total:	1.00 75.65
- Repair rig - Shop Su Work Order: Problem: Work Com	ght rear tire and balance . Nitro fill pplies Hours: 1.00 2211690 FLAT TIRE TOW IN TO FLEET	Meter:	Comm: 0.00 72327	Shop Supplies			Total:	1.00 75.65
- Repair rig - Shop Su Work Order: Problem: Work Com	ght rear tire and balance . Nitro fill pplies Hours: 1.00 2211690 FLAT TIRE TOW IN TO FLEET	Meter:	Comm: 0.00 72327	Shop Supplies		11/14/2022	Total: Closed:	1.00 75.65
- Repair rig - Shop Sup Work Order: Problem: Work Com - Tow Fror Work Order:	ght rear tire and balance . Nitro fill pplies Hours: 1.00 2211690 FLAT TIRE TOW IN TO FLEET pleted m: Okeeheelee Park Maint. Compou Hours: 0.00	Meter: un To: Lv Sho Meter:	Comm: 0.00 72327 op Comm: 113.00 72985	Shop Supplies Labor: 73.00 Labor: 0.00	In Date: Parts: 0.00	11/14/2022	Total: Closed: Total:	1.00 75.65 11/16/2022 113.00
- Repair rig - Shop Sup Work Order: Problem: Work Com - Tow Fror Work Order:	ght rear tire and balance . Nitro fill pplies Hours: 1.00 2211690 FLAT TIRE TOW IN TO FLEET pleted m: Okeeheelee Park Maint. Compou Hours: 0.00 2212617 Passenger side front headlight is	Meter: un To: Lv Sho Meter:	Comm: 0.00 72327 op Comm: 113.00 72985	Shop Supplies Labor: 73.00 Labor: 0.00	In Date: Parts: 0.00	11/14/2022 0	Total: Closed: Total: Closed:	1.00 75.65 11/16/2022 113.00
- Repair rig - Shop Su Work Order: Problem: Work Com - Tow Fror Work Order: Problem: Work Com	ght rear tire and balance . Nitro fill pplies Hours: 1.00 2211690 FLAT TIRE TOW IN TO FLEET pleted m: Okeeheelee Park Maint. Compou Hours: 0.00 2212617 Passenger side front headlight is	Meter: un To: Lv Sho Meter: out. Possibl	Comm: 0.00 72327 op Comm: 113.00 72985	Shop Supplies Labor: 73.00 Labor: 0.00	In Date: Parts: 0.00	11/14/2022 0	Total: Closed: Total: Closed:	1.00 75.65 11/16/2022 113.00 12/19/2022
- Repair rig - Shop Su Work Order: Problem: Work Com - Tow Fror Work Order: Problem: Work Com	ght rear tire and balance . Nitro fill pplies Hours: 1.00 2211690 FLAT TIRE TOW IN TO FLEET pleted m: Okeeheelee Park Maint. Compou Hours: 0.00 2212617 Passenger side front headlight is ppleted	Meter: un To: Lv Sho Meter: out. Possibl	Comm: 0.00 72327 op Comm: 113.00 72985	Shop Supplies Labor: 73.00 Labor: 0.00 his supervisor? Thank ye Parts Issued	In Date: Parts: 0.00	11/14/2022 0 12/15/2022	Total: Closed: Total: Closed: Qu	1.00 75.65 11/16/202 113.00 12/19/202

Work Order:2303023Meter:74618Problem:PM Service. Please detail before pick up. Thank you!

In Date: 03/24/2023 Closed: 03/30/2023

Work Completed		Parts Issued		Quantity
- Preventive Maint. Service		Napagold Oil Filter		1.00
- rotate and balance all 4 tires nitro fill all		Napa Quart 5w20		6.00
- replace both leaking rear shocks .		Wiper Blade		1.00
- Shop Supplies		Wiper Blade		1.00
		Shock Absober		2.00
		Shop Supplies		1.00
Hours: 4.10	Comm: 0.00	Labor: 299.30	Parts: 268.27	Total: 567.57
rk Order: 2303218	Meter: 74617		In Date: 03/30/20	23 Closed: 03/30/202

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued Wo: 2303023 for: Courtney Hanson

 Hours: 0.00
 Comm: 90.40
 Labor: 0.00
 Parts: 0.00
 Total: 90.40

Work Order: 2310415 Meter: 78035 10/16/2023 Closed: 10/26/2023 In Date: Problem: PM Service. Parts Issued Quantity **Work Completed** Napagold Oil Filter 1.00 - Preventive Maint, Service 5w20 Engine Oil 6.00 - Popping Noise While Making Turns. R&r Failed Left Front Axel With Nut. Road Test To Verify Repair Complete. Washer Fluid Concentr 1.00 - R&r Left Rear Hatch Lamp Lens Cracked With Water Inside. Blade 1.00 - Right Rear Seat Belt Buckle Is Broken. Removed Right Rear Seat To R&r Wiper Blade 1.00 Broken Buckle. Wiper Blade 1.00 - Vibration From Engine. R&r Worn Front Engine Mount. Road Test To Verify Leather S Whl Cov 1.00 Repair. Axle Nut 1.00 - R&r Broken Transmission Mount And Torque Arm. Verify Repair Complete. Left Front Axle 1.00 - Mount And Balance Four New Tires. Relearn Tire Sensors. 235/55r17 Mich Def Replaces 69235 4.00 - Complete Front And Rear Alignment. Road Test To Verify Repair. 1.00 Lamp - Shop Supplies 1.00 Housing Housing 1.00 Bracket Engine 1.00 Buckle Asy 1.00 Shop Supplies 1.00 4.00 **Tire Disposal Fee** Comm: 0.00 Hours: 14.60 Labor: 1,065.80 Parts: 1,635.97 Total: 2,701.77 Work Order: 2404702 **Meter:** 81545 05/10/2024 **Closed:** 05/14/2024 In Date: Problem: Transition Prep Charge Work Completed - Transition Prep Charge Comm: 0.00 Hours: 2.00 Labor: 146.00 Parts: 0.00 Total: 146.00 Total Hours: 93.10 Total Labor: 6,515.30 **Total Comm: 639.63** Total Parts: 6,647.50