

7/3/2024
2:32:52 PM

Palm Beach County Fleet Management Asset Maintenance History
10196040 2015 INTERNATIONAL 4300 Flat Bed Dump, 14 Ft, 33,000 Gvwr

Total Hours: 270.50	Labor: 18,909.50	Parts: 16,500.13	Comm: 21,416.21	Charged: 56825.84
----------------------------	-------------------------	-------------------------	------------------------	--------------------------

Work Order: 1409633	Meter: 520	In Date: 09/25/2014	Closed: 10/07/2014
Problem: Check In			

Work Completed

- check in
- test run
- Shop Supplies

Parts Issued

Shop Supplies

Quantity

1.00

Hours: 6.50	Comm: 0.00	Labor: 390.00	Parts: 2.00	Total: 392.00
-------------	------------	---------------	-------------	---------------

Work Order: 1410066	Meter: 520	In Date: 10/07/2014	Closed: 10/07/2014
Problem: 1062 - Make & Apply Decals. Check Fluids, Belts and Operation			

Work Completed

- Make & Apply Decals. Check Fluids, Belts and Operation

Hours: 1.00	Comm: 0.00	Labor: 60.00	Parts: 0.00	Total: 60.00
-------------	------------	--------------	-------------	--------------

Work Order: 1412096	Meter: 1328	In Date: 12/03/2014	Closed: 12/04/2014
Problem: safety hitch oins			

Work Completed

- safety hitch pins

Parts Issued

Pintle Pin W/chain

Quantity

3.00

Hours: 0.00	Comm: 0.00	Labor: 0.00	Parts: 7.83	Total: 7.83
-------------	------------	-------------	-------------	-------------

7/3/2024
2:32:52 PM

Palm Beach County Fleet Management Asset Maintenance History
10196040 2015 INTERNATIONAL 4300 Flat Bed Dump, 14 Ft, 33,000 Gvwr

Work Order: 1509394 **Meter:** 8506 **In Date:** 09/17/2015 **Closed:** 09/28/2015
Problem: PM

Work Completed

- pm
- replace cabin air filter and clean evap box
- test run
- Shop Supplies

Parts Issued

Quantity

15-40 Oil	30.00
Napagold Oil Filter	1.00
Fuel Fil	1.00
Wiper Blade	2.00
2602212c1 Air Filter	1.00
Washer Fl	1.00
Cabin Air Filter	1.00
Used Fire X Refurbished	1.00
Napa Cabin Air Filter	1.00
Shop Supplies	1.00

Hours: 8.50

Comm: 0.00

Labor: 510.00

Parts: 409.00

Total: 919.00

Work Order: 1608398 **Meter:** 18625 **In Date:** 08/15/2016 **Closed:** 09/01/2016
Problem: PM

Work Completed

- pm
- R&r back up alarm
- Ac evap and filter service
- add stickers "hows my driving"
- road test
- Shop Supplies

Parts Issued

Quantity

15-40 Oil	30.00
Napagold Oil Filter	1.00
2602212c1 Air Filter	1.00
Fuel Fil	1.00
Used Fire X Refurbished	1.00
Wiper Blade	2.00
Alarm	1.00
Napa Cabin Air Filter	1.00
Cabin Air Filter	1.00
Shop Supplies	1.00

Hours: 10.00

Comm: 0.00

Labor: 600.00

Parts: 427.73

Total: 1,027.73

7/3/2024
2:32:52 PM

Palm Beach County Fleet Management Asset Maintenance History
10196040 2015 INTERNATIONAL 4300 Flat Bed Dump, 14 Ft, 33,000 Gvwr

Work Order: 1703084
Problem: PM

Meter: 25723

In Date: 03/28/2017 **Closed:** 05/11/2017

Work Completed

- pm
- replace cabin filters and clean evap box
- replace cab light
- road test
- Shop Supplies

Parts Issued

Quantity

15-40 Oil	30.00
Napagold Oil Filter	1.00
2602212c1 Air Filter	1.00
Fuel Fil	1.00
Wiper Blade	2.00
Napa Cabin Air Filter	1.00
Cabin Air Filter	1.00
Bulb	4.00
red paint pin	1.00
Stick-on Rd Reflector	2.00
Ultra Supreme 238 Moly Grease	20.00
Washer Fluid Concentr	2.00
Air Freshener	2.00
Shop Supplies	1.00

Hours: 9.50

Comm: 0.00

Labor: 570.00

Parts: 529.64

Total: 1,099.64

7/3/2024
2:32:52 PM

Palm Beach County Fleet Management Asset Maintenance History
10196040 2015 INTERNATIONAL 4300 Flat Bed Dump, 14 Ft, 33,000 Gvwr

Work Order: 1712709 **Meter:** 32766 **In Date:** 12/27/2017 **Closed:** 01/19/2018
Problem: PM

Work Completed

- pm
- replace fire x and bracket
- repair clearance lights
- test run
- Shop Supplies

Parts Issued

Quantity

15-40 Oil	30.00
Napagold Oil Filter	1.00
Air Filter	1.00
Filter	1.00
Wiper Blade	2.00
Washer Fluid Concentr	1.00
Non-chlor Brake Clnr	3.00
Napa Cabin Air Filter	1.00
Cabin Air Filter	1.00
Used Fire X Refurbished	1.00
Fire Ext Mount Strap Style	1.00
Shop Supplies	1.00

Hours: 8.50

Comm: 0.00

Labor: 510.00

Parts: 411.31

Total: 921.31

Work Order: 1800622 **Meter:** 32645 **In Date:** 01/18/2018 **Closed:** 01/24/2018
Problem: RF tire

Work Completed

- Rf tire

Hours: 0.00

Comm: 527.47

Labor: 0.00

Parts: 0.00

Total: 527.47

Work Order: 1804680 **Meter:** 36616 **In Date:** 05/04/2018 **Closed:** 05/07/2018
Problem: Bad Hitch

Work Completed

- cut off ball and replace
- Shop Supplies

Parts Issued

Quantity

Pin Hook	1.00
Shop Supplies	1.00

Hours: 2.00

Comm: 0.00

Labor: 120.00

Parts: 118.63

Total: 238.63

7/3/2024
2:32:52 PM

Palm Beach County Fleet Management Asset Maintenance History
10196040 2015 INTERNATIONAL 4300 Flat Bed Dump, 14 Ft, 33,000 Gvwr

Work Order: 1808018 **Meter:** 38575 **In Date:** 08/06/2018 **Closed:** 08/14/2018
Problem: pm

Work Completed

- Pm
- Service Ac
- Service Air Dryer
- Replace battery
- Shop Supplies

Parts Issued

Quantity

15-40 Oil	30.00
Air Filter	1.00
Filter	1.00
Napagold Oil Filter	1.00
Washer Fluid Concentr	1.00
Wiper Blade	2.00
Used Fire X Refurbished	1.00
Cabin Air Filter	1.00
Napa Cabin Air Filter	1.00
Ad Ip Dryer Cart	1.00
Group 31 Stud Delco	2.00
Shop Supplies	1.00

Hours: 11.00

Comm: 0.00

Labor: 660.00

Parts: 752.47

Total: 1,412.47

Work Order: 1810021 **Meter:** 39777 **In Date:** 09/27/2018 **Closed:** 09/27/2018
Problem: LRO tire

Work Completed

- Lro tire

Hours: 0.00

Comm: 535.76

Labor: 0.00

Parts: 0.00

Total: 535.76

7/3/2024
2:32:52 PM

Palm Beach County Fleet Management Asset Maintenance History
10196040 2015 INTERNATIONAL 4300 Flat Bed Dump, 14 Ft, 33,000 Gvwr

Work Order: 1904238 **Meter:** 45235 **In Date:** 04/18/2019 **Closed:** 06/28/2019
Problem: pm/list

Work Completed

- Pm
- Service Ac
- R&r pintle pin
- Replace lights and reflectors
- Repair bed switch
- To Rechten 2xs
- Test run
- Shop Supplies

Parts Issued

Quantity

15-40 Oil	17.00
oil filter	1.00
fuel filter	1.00
fuel filter	1.00
Air Filter	1.00
Washer Fluid Concentr	2.00
Wiper Blade	4.00
Cabin Air Filter	1.00
Napa Cabin Air Filter	1.00
Lucas Red-tacky Grs	2.00
Hydraulic Filter	1.00
Blue Df	2.00
Lens	3.00
Napagold Oil Filter	1.00
Filter	1.00
Non-chlor Brake Clnr	1.00
Grime-away	1.00
Used Fire X Refurbished	1.00
Napa Cabin Air Filter	1.00
Cabin Air Filter	1.00
Pintle Pin W/clip	1.00
Stick-on Rd Reflector	1.00
Led Red Tail Light	1.00
Body Up Switch	1.00
1cart Palladium 2 Grs	1.00
15-40 Oil	30.00
Shop Supplies	1.00

Hours: 16.00

Comm: 0.00

Labor: 1,072.00

Parts: 916.07

Total: 1,988.07

7/3/2024
2:32:52 PM

Palm Beach County Fleet Management Asset Maintenance History
10196040 2015 INTERNATIONAL 4300 Flat Bed Dump, 14 Ft, 33,000 Gvwr

Work Order: 1904876 **Meter:** 45197 **In Date:** 05/03/2019 **Closed:** 05/03/2019
Problem: RRIO LRO tires

Work Completed

- Tire Service He - Rrio Lro tires

Hours: 0.00 Comm: 51.56 Labor: 0.00 Parts: 0.00 Total: 51.56

Work Order: 1904877 **Meter:** 45197 **In Date:** 05/03/2019 **Closed:** 05/03/2019
Problem: RRIO LRO

Work Completed

- Tire Service He - Rrio Lro

Hours: 0.00 Comm: 1,439.40 Labor: 0.00 Parts: 0.00 Total: 1,439.40

Work Order: 1905003 **Meter:** 45197 **In Date:** 05/08/2019 **Closed:** 06/26/2019
Problem: Repairs by Rechtien

Work Completed

- Replace Bbcm

Hours: 0.00 Comm: 1,487.05 Labor: 0.00 Parts: 0.00 Total: 1,487.05

7/3/2024
2:32:52 PM

Palm Beach County Fleet Management Asset Maintenance History
10196040 2015 INTERNATIONAL 4300 Flat Bed Dump, 14 Ft, 33,000 Gvwr

Work Order: 1911988 **Meter:** 50459 **In Date:** 11/19/2019 **Closed:** 12/17/2019
Problem: PM/ list

Work Completed

- Pm
- Service Ac
- Service Dryer
- Service trans
- Replace Ls mirror
- Ps service
- Repair tarp
- Treat fuel
- Replaced Bu alarm
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Washer Fluid Concentr	1.00
Wiper Blade	2.00
Air Fltr	1.00
Filter	1.00
Non-chlor Brake Clnr	3.00
Used Fire X Refurbished	1.00
Napa Cabin Air Filter	1.00
Cabin Air Filter	1.00
Ad Ip Dryer Cart	1.00
Syn-atf Trans Fluid S	25.00
Napa Trans Filter	1.00
Driverside Mirror Glass	1.00
Power Steering Filter	1.00
Psf Qt	1.00
Control Crank Kit	1.00
Motor Tune-up 16oz	1.00
Alarm	1.00
15-40 Oil	30.00
Shop Supplies	1.00

Hours: 18.50

Comm: 0.00

Labor: 1,350.50

Parts: 1,162.29

Total: 2,512.79

Work Order: 1912037 **Meter:** 50421 **In Date:** 11/19/2019 **Closed:** 11/20/2019
Problem: Broken Driver mirror

Work Completed

- Tow From: Jpp nursery To: He shop

Hours: 0.00

Comm: 132.00

Labor: 0.00

Parts: 0.00

Total: 132.00

7/3/2024
2:32:52 PM

Palm Beach County Fleet Management Asset Maintenance History
10196040 2015 INTERNATIONAL 4300 Flat Bed Dump, 14 Ft, 33,000 Gvwr

Work Order: 2004184 **Meter:** 53308 **In Date:** 04/22/2020 **Closed:** 04/27/2020
Problem: LF Tire

Work Completed

- Tire Service Jpp - Lf Tire

Hours: 0.00 Comm: 96.56 Labor: 0.00 Parts: 0.00 Total: 96.56

Work Order: 2004376 **Meter:** 53375 **In Date:** 05/01/2020 **Closed:** 05/05/2020
Problem: Tire

Work Completed

- Tire

- Shop Supplies

Parts Issued Quantity

11r22.5bstone 1.00

Shop Supplies 1.00

Tire Disposal Fee 1.00

Hours: 0.00 Comm: 0.00 Labor: 0.00 Parts: 598.35 Total: 598.35

Work Order: 2007095 **Meter:** 55755 **In Date:** 07/21/2020 **Closed:** 08/12/2020
Problem: PM/ door Hinge

Work Completed

- pm

- repair weld rear dump body

- check engine light scan codes. brake switch data eratic

- remove brake switch clean terminal. clear dtc

- road test

- Shop Supplies

Parts Issued Quantity

Napagold Oil Filter 1.00

15-40 Oil 30.00

Filter 1.00

Air Fltr 1.00

Washer Fluid Concentr 1.00

Wiper Blade 2.00

Used Fire X Refurbished 1.00

Non-chlor Brake Clnr 3.00

Shop Supplies 1.00

Hours: 12.50 Comm: 0.00 Labor: 912.50 Parts: 329.70 Total: 1,242.20

7/3/2024
2:32:52 PM

Palm Beach County Fleet Management Asset Maintenance History
10196040 2015 INTERNATIONAL 4300 Flat Bed Dump, 14 Ft, 33,000 Gvwr

Work Order: 2010218 **Meter:** 57214 **In Date:** 10/09/2020 **Closed:** 10/24/2020
Problem: Mirror

Work Completed

- passenfer door mirror assembly
- Shop Supplies

Hours: 4.00

Comm: 0.00

Parts Issued

	Quantity
mirror	1.00
Shop Supplies	1.00
Labor: 292.00	Parts: 703.14
Total: 995.14	

Work Order: 2101054 **Meter:** 59983 **In Date:** 01/28/2021 **Closed:** 02/16/2021
Problem: There is an air leak in two places - One air leak at the chamber for brakes the other at the ignition and fan clutch. Le

Work Completed

- Air leak at engine fan clutch line. Replace line and fitting to fan clutch.
- Air leak at rear of engine, replace leaking fitting at exhaust back pressure control valve, Scan and Clear related code Spn 4752 Fmi 4 Egr cooler efficiency, Ok.
- Air leak at Rf brake chamber hose. Remove and replace hose, check for leaks, ok.
- Road call to Jpp. and back 2x.
- To Mako and back to shop.
- Test run.
- Shop Supplies

Hours: 8.50

Comm: 0.00

Parts Issued

	Quantity
Fittins From Mako	1.00
Dot Push In Swvl Elbow	2.00
Brass Nut	4.00
Fitting	4.00
Fitting	4.00
Bushing	4.00
Tube-nylon-black	12.00
Shop Supplies	1.00
Labor: 620.50	Parts: 191.38
Total: 811.88	

7/3/2024
2:32:52 PM

Palm Beach County Fleet Management Asset Maintenance History
10196040 2015 INTERNATIONAL 4300 Flat Bed Dump, 14 Ft, 33,000 Gvwr

Work Order: 2105057 **Meter:** 62241 **In Date:** 05/05/2021 **Closed:** 05/19/2021
Problem: PM

Work Completed

- Preventive Maint. Service
- Service Ac system clean evaporator core
- Service air dryer brakes
- Service transmission
- Replace bed tarp
- Add Fuel treatment do to water trace on fuel filter.
- Add reflective tape and replace Rr marker.
- Shop Supplies

Parts Issued

Quantity

Air Fltr	1.00
Filter	1.00
Washer Fluid Concentr	1.00
Wiper Blade	2.00
Napagold Oil Filter	1.00
Non-chlor Brake Clnr	3.00
Air Freshener	2.00
Grime-away	1.00
Used Fire X Refurbished	1.00
15-40 Oil	30.00
Cabin Air Filter	1.00
Napa Cabin Air Filter	1.00
Ad Ip Dryer Cart	1.00
Syn-atf Trans Fluid S	25.00
Napa Trans Filter	1.00
76x18 Mesh Tarp	1.00
Motor Tune-up 16oz	1.00
Stick-on Rd Reflector	1.00
2 Inch White Reflective Tape Dot2	1.00
Shop Supplies	1.00

Hours: 17.00

Comm: 0.00

Labor: 1,241.00

Parts: 784.33

Total: 2,025.33

Work Order: 2106339 **Meter:** 63022 **In Date:** 06/10/2021 **Closed:**
Problem: Wiring harness burnt / AC Compressor

Work Completed

- Accessories - Electrical

Hours: 0.00

Comm: 0.00

Labor: 0.00

Parts: 0.00

Total: 0.00

7/3/2024
2:32:52 PM

Palm Beach County Fleet Management Asset Maintenance History
10196040 2015 INTERNATIONAL 4300 Flat Bed Dump, 14 Ft, 33,000 Gvwr

Work Order: 2107419 **Meter:** 63783 **In Date:** 07/09/2021 **Closed:** 07/19/2021

Problem: A/C is not functioning. There is also an air leak when you shut the truck off,.. not sure where, but you can hear it.

Work Completed

Parts Issued

Quantity

- diag no a/c complaint, discover blower motor not functional. diag stuck blower motor replace and test system .

Blower Motor	1.00
--------------	------

Motor	1.00
-------	------

- diag air leak when initial engine start up, diag loose fitting from compressor to air dryer . tighten line and check system for leaks no leaks found.

Shop Supplies	1.00
---------------	------

- test drive road test

- Shop Supplies

Hours: 8.50

Comm: 0.00

Labor: 620.50

Parts: 272.38

Total: 892.88

7/3/2024
2:32:52 PM

Palm Beach County Fleet Management Asset Maintenance History
10196040 2015 INTERNATIONAL 4300 Flat Bed Dump, 14 Ft, 33,000 Gvwr

Work Order: 2109558 **Meter:** 65056 **In Date:** 09/01/2021 **Closed:** 10/18/2021
Problem: Coming in for regeneration issues. Alarm going off.

Work Completed

- Warning lights. Scan for codes. Low fuel delivery pressure Spn94 Fmi17, Low aftertreatment fuel pressure Spn3471 Fmi10, Aftertreatment injector not responding Spn3556 Fmi7, Verified low fuel delivery pressure. Replace fuel pump and housing assembly.
- Dpf soot load too high, clear codes and preform multiple manual regen's after fuel pump repairs. Preform multiple drive cycles to clear permanent Egr codes from Pcm after repairs.
- A/c not cooling well, Check refrigerant charge and pressures, Ok. Mode and blend doors inoperative. Replace all 3 actuators. Check Ok.
- Batteries failed load test. Clean battery tray and cables. Replace 2 batteries. Check charging system, Ok.
- Check engine light, scan for codes, Permanent codes Spn2659 Fmi21 Egr low flow rate detected, Spn4752 Fmi4 Egr cooler efficiency. Replace failed Egr valve and clean throttle valve and housing. Repair broken lines and hoses to wastegate actuators.
- Air leak at compressor governor, replace related air fittings, test Ok.
- Check engine light. Permanent Code Spn639 Fmi14 J1939 Data Link Error due to fuel pump upgrade. Send to International for Pcm Update.
- Travel Time to International and back.
- Test run.
- Shop Supplies

Parts Issued

Quantity

fuel pump with filter housing	1.00
3542606c1 Acuator Doo	2.00
Group 31 Stud Delco	2.00
3542606c1 Acuator Doo	1.00
Inlet Duct Gasket	1.00
Egr Actuator	1.00
Shop Supplies	1.00

Hours: 41.50 Comm: 0.00 Labor: 3,029.50 Parts: 2,263.58 Total: 5,293.08

Work Order: 2110960 **Meter:** 65056 **In Date:** 10/12/2021 **Closed:** 10/14/2021
Problem: reflash

Work Completed

- Engine,other

Hours: 0.00 Comm: 491.55 Labor: 0.00 Parts: 0.00 Total: 491.55

7/3/2024
2:32:53 PM

Palm Beach County Fleet Management Asset Maintenance History
10196040 2015 INTERNATIONAL 4300 Flat Bed Dump, 14 Ft, 33,000 Gvwr

Work Order: 2112421 **Meter:** 66354 **In Date:** 11/22/2021 **Closed:** 01/11/2022
Problem: PM Service. Please also repair drivers side rear brake light. Thank you!

Work Completed

- Preventive Maint. Service
- service a/c system clean all filters.
- add coolant
- replace rear tail light unit
- to international 2xs
- Shop Supplies

Parts Issued

Quantity

15-40 Oil	30.00
Napagold Oil Filter	1.00
Filter	1.00
Air Fltr	1.00
Washer Fluid Concentr	1.00
Hand Wipes	1.00
Non-chlor Brake Clnr	3.00
Cabin Air Filter	1.00
Napa Cabin Air Filter	1.00
weldon 2350 tail light	1.00
Shop Supplies	1.00

Hours: 11.00

Comm: 0.00

Labor: 803.00

Parts: 342.63

Total: 1,145.63

Work Order: 2113707 **Meter:** 66406 **In Date:** 12/30/2021 **Closed:** 02/17/2022
Problem: Oil in coolant

Work Completed

- Engine,other
- To Rechten
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
---------------	------

Hours: 2.00

Comm: 13,283.70

Labor: 146.00

Parts: 2.65

Total: 13,432.35

7/3/2024
2:32:53 PM

Palm Beach County Fleet Management Asset Maintenance History
10196040 2015 INTERNATIONAL 4300 Flat Bed Dump, 14 Ft, 33,000 Gvwr

Work Order: 2207768 **Meter:** 71479 **In Date:** 07/26/2022 **Closed:** 10/03/2022
Problem: possible hose came off

Work Completed

- Cooling System
- Pm
- From Rechten
- Power Steering Service
- Transmission Service
- A/c Service
- Rear Differential Service
- Shop Supplies

Parts Issued

Quantity

15-40 Oil	30.00
Napagold Oil Filter	1.00
Hand Wipes	1.00
Used Fire X Refurbished	1.00
Non-chlor Brake Clnr	3.00
Washer Fluid Concentr	2.00
Wiper Blade	2.00
Air Fltr	1.00
Filter	1.00
Power Steering Filter	1.00
Psf Qt	1.00
Napa Trans Filter	1.00
Syn-atf Trans Fluid S	25.00
Cabin Air Filter	1.00
Napa Cabin Air Filter	1.00
Evap Odor Elinitator	1.00
5gal Hpgearoil85-140	1.00
Lucas 85-140 Gear Oil	2.00
Shop Supplies	1.00

Hours: 17.00

Comm: 909.01

Labor: 1,241.00

Parts: 710.52

Total: 2,860.53

Work Order: 2208409 **Meter:** 71247 **In Date:** 07/25/2022 **Closed:** 08/12/2022
Problem: possible hose came off

Work Completed

- Tow From: I-95 Southbound going on 45th street ramp To: He shop

Hours: 0.00

Comm: 124.30

Labor: 0.00

Parts: 0.00

Total: 124.30

7/3/2024
2:32:53 PM

Palm Beach County Fleet Management Asset Maintenance History
10196040 2015 INTERNATIONAL 4300 Flat Bed Dump, 14 Ft, 33,000 Gvwr

Work Order: 2208410 **Meter:** 71247 **In Date:** 07/26/2022 **Closed:** 08/12/2022
Problem: Transport to Rechten International

Work Completed

- Tow From: He shop To: Rechten International

Hours: 0.00 Comm: 124.30 Labor: 0.00 Parts: 0.00 Total: 124.30

Work Order: 2301167 **Meter:** 75315 **In Date:** 02/03/2023 **Closed:** 02/07/2023
Problem: Lights

Work Completed

- Stop lights out, replace both rear stop lights, Drill old rivets and install new ones

Parts Issued	Quantity
Led Red Tail Light	2.00
Shop Supplies	1.00

- Shop Supplies

Hours: 1.50 Comm: 0.00 Labor: 109.50 Parts: 72.21 Total: 181.71

Work Order: 2302505 **Meter:** 76587 **In Date:** 03/13/2023 **Closed:** 03/14/2023
Problem: headlight out

Work Completed

- Lighting, Remove & replace Lh headlight bulb

- Shop Supplies

Parts Issued	Quantity
Boxed Capsules	1.00
Shop Supplies	1.00

Hours: 1.50 Comm: 0.00 Labor: 109.50 Parts: 10.47 Total: 119.97

Work Order: 2310055 **Meter:** 82685 **In Date:** 10/03/2023 **Closed:** 12/06/2023
Problem: PM Service. Check headlights, Needs new pintle hitch.

Work Completed

- Preventive Maint. Service

- Found cooling system tank to be damaged along with cap removed and replaced. Drain and refilled cooling system and bleed system.

- Power Steering service

- Service air dryer

- Operator states headlights in op tested fuses and inspected wiring.

Checked resistance in wiring found pigtailed to have corrosion causing over heating and melting insulation on connectors. Removed and replaced bulbs and sockets

Parts Issued	Quantity
Pntl Hitch	1.00
Napa Gal 15w40	10.00
Tree Royal Pine 3pk	1.00
Non-chlor Brake Clnr	4.00
Hand Wipes	1.00
Washer Fluid Concentr	2.00
Wiper Blade	2.00
Used Fire X Refurbished	1.00
Napagold Oil Filter	1.00

7/3/2024
2:32:53 PM

Palm Beach County Fleet Management Asset Maintenance History
10196040 2015 INTERNATIONAL 4300 Flat Bed Dump, 14 Ft, 33,000 Gvwr

- Upon inspection found rear brakes to be well worn. Removed and replaced rear drums shoes and hardware.
- Upon inspection found asset to have multiple air leaks. repaired total of 4 leaks at this time.
- Operator States needs new pintle hitch found pintle hitch to have wear removed and replaced pintle hitch and pin after removing siezed bolts and removing welds on each side of hitch
- Travel and wait at mako
- Remove and replace both cab filters for air conditioning
- Found vehicle to have low fuel pressure checked fuel pressure with scan tool. Cleaned screen and replaced fuel filter. with no improvement remove and replaced fuel pump complete assembly
- Upon initial test drive after repairs found vehicle to be leaking from valve on air dryer receiver. Required removal and replacement of air dryer receiver.
- to rechtien 4xs
- repairs by rechtien
- repair by rechtien
- Shop Supplies

Parts Issued	Quantity
Filter	1.00
Air Fltr	1.00
Power Steering Filter	1.00
Psf Qt	3.00
Ad Ip Dryer Cart	1.00
Hi Temp 9004 9007	2.00
Boxed Capsules	2.00
Sensor Coolent Level	1.00
Cap	1.00
Expansion Tank	1.00
Rotell Elc Antifeerze	12.00
Shoes	2.00
Drum Rear	2.00
Stiction Elimint 32oz	1.00
Ad Ip Dryer Cart	1.00
Combo Hitch 2bl 10tn	1.00
Pintle Pin W/clip	1.00
Smokex Odor Elim 2 Oz	1.00
Napa Cabin Air Filter	1.00
Cabin Air Filter	1.00
Fittings From Mako	1.00
Fuel Filter Housing	1.00
Shop Supplies	1.00
Labor: 3,248.50	Parts: 5,339.45
Total: 10,066.99	

Hours: 44.50

Comm: 1,479.03

7/3/2024
2:32:53 PM

Palm Beach County Fleet Management Asset Maintenance History
10196040 2015 INTERNATIONAL 4300 Flat Bed Dump, 14 Ft, 33,000 Gvwr

Work Order: 2400478 **Meter:** 83780 **In Date:** 01/16/2024 **Closed:** 02/05/2024
Problem: Replace hitch bolts

Work Completed

Parts Issued

Quantity

- inspect and remove pintle hitch assy. order new pintle hitch assy.
- to and from ocean cay park
- repair hitch bumper outsourced
- to and from Wpb machine and welding
- Shop Supplies

Pntl Hitch	1.00
Shop Supplies	1.00

Hours: 6.50 Comm: 734.50 Labor: 474.50 Parts: 137.10 Total: 1,346.10

Work Order: 2401724 **Meter:** 84757 **In Date:** 02/14/2024 **Closed:** 04/24/2024
Problem: Driver side, lower blind spot mirror needs to be replaced. Will send photos.

Work Completed

Parts Issued

Quantity

- to jpp
- Shop Supplies

Shop Supplies	1.00
---------------	------

Hours: 1.00 Comm: 0.00 Labor: 73.00 Parts: 2.65 Total: 75.65

Work Order: 2405009 **Meter:** 87122 **In Date:** 05/20/2024 **Closed:** 06/26/2024
Problem: PM/A/C inop/Driver window crank inop.Driver side mirror. Fuel gauge inop.tires. hitch bolts/ new seat

Work Completed

- Preventive Maint. Service

Hours: 0.00 Comm: 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00

Work Order: 2405628 **Meter:** 87122 **In Date:** 06/07/2024 **Closed:** 06/28/2024
Problem: Transition Prep Charge

Work Completed

Parts Issued

Quantity

- Transition Prep Charge
- Shop Supplies

Shop Supplies	1.00
---------------	------

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 2.65 Total: 148.65

Total Hours: 270.50 Total Labor: 18,909.50 Total Comm: 21,416.21 Total Parts: 16,500.13