

1/13/2025
9:46:01 AM

Palm Beach County Fleet Management Asset Maintenance History
10196012 2015 FORD F350 Utility Body, 14,000 Gvwr, Crew Cab, Topper, 4x4

Total Hours: 155.80 Labor: 10,710.10 Parts: 6,525.49 Comm: 3,011.68 Charged: 20247.26

Work Order: 1502237 **Meter:** 345 **In Date:** 03/03/2015 **Closed:** 03/03/2015
Problem: 1061 - Pre Delivery Inspection

Work Completed

- Pre Delivery Inspection

Hours: 4.00 Comm: 0.00 Labor: 240.00 Parts: 0.00 Total: 240.00

Work Order: 1600403 **Meter:** 3383 **In Date:** 01/12/2016 **Closed:** 01/28/2016
Problem: Pm service.Water leaks into utility body,left front.

Work Completed

- Pm service.
- Fabricate and reseal body water leaks at utility body seams and lamps.extensive water testing to verify ok.
- Rotate and balance all six tires.
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	7.00
Napagold Oil Filter	1.00
Washer Fluid Concentr	1.00
Wd40 16oz	1.00
Marine Adh Seal White	1.00
Shop Supplies	1.00

Hours: 7.50 Comm: 0.00 Labor: 450.00 Parts: 46.22 Total: 496.22

Work Order: 1609082 **Meter:** 5237 **In Date:** 08/31/2016 **Closed:** 09/19/2016
Problem: P.M. Service

Work Completed

- P.m. Service.
- Rotate and balance all six tires.
- Inspect and service winch.
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	7.00
Napagold Oil Filter	1.00
22" Wiper Blade	2.00
Wd40 Spr	1.00
Shop Supplies	1.00

Hours: 6.50 Comm: 0.00 Labor: 390.00 Parts: 35.36 Total: 425.36

1/13/2025
9:46:01 AM

Palm Beach County Fleet Management Asset Maintenance History
10196012 2015 FORD F350 Utility Body, 14,000 Gvwr, Crew Cab, Topper, 4x4

Work Order: 1703925 **Meter:** 6976 **In Date:** 04/19/2017 **Closed:** 04/28/2017
Problem: P.M. service.

Work Completed

- P.m. service.
- Replace missing handle for vise.
- Check corner strobes light system and repair broken wire for left rear corner strobe light.
- Rotate and high speed balance all six tires.
- Inspect and service power winch.
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	7.00
Napagold Oil Filter	1.00
Napagold Air Filter	1.00
Used Fire X Refurbished	1.00
Mac Wite Lithium Gres	1.00
Washer Fluid Concentr	1.00
Wd40 Spr	1.00
Stg Wheel Cov - Ford	1.00
22" Wiper Blade	2.00
ridgid vise handle	1.00
Shop Supplies	1.00

Hours: 7.80

Comm: 0.00

Labor: 468.00 Parts: 156.89 Total: 624.89

Work Order: 1704025 **Meter:** 6790 **In Date:** 04/21/2017 **Closed:** 04/24/2017
Problem: weld vise

Work Completed

- weld nuts on vise handle
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
---------------	------

Hours: 1.00

Comm: 0.00

Labor: 60.00 Parts: 2.00 Total: 62.00

1/13/2025
9:46:01 AM

Palm Beach County Fleet Management Asset Maintenance History
10196012 2015 FORD F350 Utility Body, 14,000 Gvwr, Crew Cab, Topper, 4x4

Work Order: 1712708 **Meter:** 8999 **In Date:** 12/27/2017 **Closed:** 01/04/2018
Problem: P.M. service.

Work Completed

- P.m. service.
- Replace left rear failed corner strobe light.
- Replace all six tires .nitrogen fill all and high speed balance all six tires.
- Check starting and charging systems.battery failed load test after recharge.replace battery.
- Perform front end alignment.
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	7.00
Napagold Oil Filter	1.00
22" Wiper Blade	2.00
Used Fire X Refurbished	1.00
Washer Fluid Concentr	1.00
Lighting	1.00
Lt245/75r17 Mich Defend Ltx	6.00
Tr416 Valve Stem	6.00
Battery 65	1.00
Shop Supplies	1.00
Tire Disposal Fee	6.00

Hours: 11.30

Comm: 0.00

Labor: 678.00 Parts: 1,903.30 Total: 2,581.30

Work Order: 1807766 **Meter:** 10893 **In Date:** 07/31/2018 **Closed:** 08/06/2018
Problem: P.M. service.

Work Completed

- P.m. service.
- Diagnose right rear strobe light inop. Replace strobe light and fabricate mount. Test and replace center rear marker light .
- Rotate and high speed balance all six tires .
- Inspect and service winch .
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	7.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Used Fire X Refurbished	1.00
Mnt Conc Led Clear	1.00
Marker Lamp	1.00
Shop Supplies	1.00

Hours: 9.00

Comm: 0.00

Labor: 540.00 Parts: 154.36 Total: 694.36

1/13/2025
9:46:01 AM

Palm Beach County Fleet Management Asset Maintenance History
10196012 2015 FORD F350 Utility Body, 14,000 Gvwr, Crew Cab, Topper, 4x4

Work Order: 1905470 **Meter:** 13427 **In Date:** 05/22/2019 **Closed:** 05/29/2019
Problem: P.M. Service.

Work Completed

- P.m. service.
- Check and replace broken overhead console assembly .
- Test and replace defective trailer plug connector . Rewire as needed.
- Replace missing pintle pin .
- Inspect and service winch .
- Balance and rotate all six tires . Nitrofill all.
- Shop Supplies

Hours: 8.50

Comm: 0.00

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	7.00
Used Fire X Refurbished	1.00
22" Wiper Blade	2.00
Console Assy	1.00
trailer plug	1.00
Pintle Pin W/clip	1.00
Shop Supplies	1.00

Labor: 569.50

Parts: 180.27

Total: 749.77

Work Order: 2002442 **Meter:** 15532 **In Date:** 03/10/2020 **Closed:** 03/19/2020
Problem: P.M. service and install roof vent in utility .

Work Completed

- P.m. service .
- Resurface both rear brake rotors and service calipers . Replace brake pads .
Flush and bleed brake system . Road test .
- Test battery after fully charging battery . Battery failed load test . R&r
defective battery .
- Fabricate and cut hole in walk in to mount vent fan assembly . Wire in
and seal vent fan assembly . Bleach and pressure wash entire walk in bed .
Test fan operation .
- Balance and rotate and all six tires . Nitrofill all.
- Inspect and service winch .
- Shop Supplies

Hours: 20.50

Comm: 0.00

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	8.00
22" Wiper Blade	2.00
Used Fire X Refurbished	1.00
Brake Pad	1.00
Battery	1.00
Roof Vent Fan	1.00
Vinyl Electrical Tape	1.00
Permatex	2.00
Fab Loom-split Poly	30.00
Primary Wire	30.00
Primary Wire	15.00
Real Brake Pad	1.00
Shop Supplies	1.00

Labor: 1,496.50

Parts: 714.58

Total: 2,211.08

1/13/2025
9:46:01 AM

Palm Beach County Fleet Management Asset Maintenance History
10196012 2015 FORD F350 Utility Body, 14,000 Gvwr, Crew Cab, Topper, 4x4

Work Order: 2007390 **Meter:** 16447 **In Date:** 07/28/2020 **Closed:** 08/04/2020
Problem: Power steering leaking.

Work Completed

Parts Issued

Quantity

- Diagnose power steering leak . Replace leaking brake booster . Bleed power steering fluid . Test drive .
- Shop Supplies

Brakr Booster	1.00
Shop Supplies	1.00

Hours: 3.00 Comm: 0.00 Labor: 219.00 Parts: 323.01 Total: 542.01

Work Order: 2009633 **Meter:** 16920 **In Date:** 09/24/2020 **Closed:** 10/05/2020
Problem: P.M. service.

Work Completed

Parts Issued

Quantity

- P.m. service.
- Test and replace rear three tail lights and repair harness.
- Replace peeling front asset number .
- Inspect and service winch .
- Rotate and balance all six tires . Nitrofill all.
- Shop Supplies

Napagold Oil Filter	1.00
5w20 Engine Oil	7.00
22" Wiper Blade	2.00
Washer Fluid Concentr	1.00
Three Light Harness Red	1.00
Shop Supplies	1.00

Hours: 8.00 Comm: 0.00 Labor: 584.00 Parts: 81.94 Total: 665.94

Work Order: 2104251 **Meter:** 17977 **In Date:** 04/15/2021 **Closed:** 04/26/2021
Problem: P.M. service.

Work Completed

Parts Issued

Quantity

- Preventive Maint. Service
- inspect and service winch
- balance and rotate all six tires . Nitro fill all.
- Shop Supplies

5w20 Engine Oil	8.00
Napagold Oil Filter	1.00
Napagold Air Filter	1.00
Wd40 Spr	1.00
Steering Wheel Cover Large	1.00
Used Fire X Refurbished	1.00
22" Wiper Blade	2.00
Shop Supplies	1.00

Hours: 6.50 Comm: 0.00 Labor: 474.50 Parts: 99.16 Total: 573.66

1/13/2025
9:46:01 AM

Palm Beach County Fleet Management Asset Maintenance History
10196012 2015 FORD F350 Utility Body, 14,000 Gvwr, Crew Cab, Topper, 4x4

Work Order: 2111041 **Meter:** 19450 **In Date:** 10/13/2021 **Closed:** 10/20/2021
Problem: PM Service.

Work Completed

- Preventive Maint. Service
- rotate and balance all 6 tires . Nitro fill all.
- Inspect and service winch .lube winch cable and re roll cable
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	8.00
22" Wiper Blade	2.00
Mac Wite Lithium Gres	1.00
Shop Supplies	1.00

Hours: 4.50

Comm: 0.00

Labor: 328.50 Parts: 34.47 Total: 362.97

Work Order: 2203969 **Meter:** 21020 **In Date:** 04/13/2022 **Closed:** 04/18/2022
Problem: PM Service.

Work Completed

- Preventive Maint. Service
- diagnose engine misfire and arcing noise engine area, replaced # 1,5&7 defective coils ,all 16 spark plugs,8 wires
- performed top engine decab ,throttle body clean up,and injector flush
- replaced all six tires and balance . Nitro fill all.
- completed front end alignment and road test
- inspect and service winch
- Shop Supplies

Parts Issued

Quantity

Drain Plug	1.00
Napa Quart 5w20	8.00
Napagold Oil Filter	1.00
22" Wiper Blade	2.00
Used Fire X Refurbished	1.00
Espak Plug Wire	4.00
Espak Plug Wire	4.00
Coil	2.00
Coil	1.00
Spark Plug	16.00
Motor Tune-up 16oz	1.00
Intake Cleaner Kit	1.00
Lt245/75r17 Mich Defend Ltx	6.00
Shop Supplies	1.00
Tire Disposal Fee	6.00

Hours: 18.20

Comm: 0.00

Labor: 1,328.60 Parts: 2,099.27 Total: 3,427.87

1/13/2025
9:46:01 AM

Palm Beach County Fleet Management Asset Maintenance History
10196012 2015 FORD F350 Utility Body, 14,000 Gvwr, Crew Cab, Topper, 4x4

Work Order: 2210835 **Meter:** 22733 **In Date:** 10/24/2022 **Closed:** 10/31/2022
Problem: PM Service.

Work Completed

- Preventive Maint. Service
- Inspect Power Winch Seized Due To Water Intrusion. Dismantle Winch, Cleaned And Lubricated Gears And Reassemble. Retest Winch And Verify Repair Complete.
- Rotate And Balance Six Tires. Nitro Fill All.
- Shop Supplies

Parts Issued

	Quantity
Napagold Oil Filter	1.00
Napa Quart 5w30	7.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Brake Pedal Pad	1.00
5w20 Engine Oil	7.00
Shop Supplies	1.00

Hours: 8.50 Comm: 0.00 Labor: 620.50 Parts: 76.27 Total: 696.77

Work Order: 2304560 **Meter:** 23740 **In Date:** 04/13/2023 **Closed:** 05/09/2023
Problem: Damage to right front door, step & front bumper.

Work Completed

- Damage to right front door, step & front bumper.

Hours: 0.00 Comm: 3,011.68 Labor: 0.00 Parts: 0.00 Total: 3,011.68

Work Order: 2305454 **Meter:** 24102 **In Date:** 06/02/2023 **Closed:** 06/12/2023
Problem: PM Service.

Work Completed

- Preventive Maint. Service
- Load Test Battery, Recharge And Retest. R&r Failed Battery Due To Normal Wear.
- Resurface Front Rotors, Lube Caliper Pins, R&r Worn Brake Pads, Flush And Bleed Brake System. Road Test To Verify Repair.
- Inspect And Service Power Winch.
- Rotate And Balance Six Tires. Nitro Fill All .
- Complete Front End Alignment Due To Steering Wheel Not Centered. Road Test To Verify Repair.
- Shop Supplies

Parts Issued

	Quantity
Napagold Oil Filter	1.00
5w20 Engine Oil	7.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Used Fire X Refurbished	1.00
Battery	1.00
Front Brake Pad	1.00
Non-chlor Brake Clnr	1.00
Brake Fl-dot 3-4 32oz	1.00
Shop Supplies	1.00

Hours: 15.00 Comm: 0.00 Labor: 1,095.00 Parts: 245.19 Total: 1,340.19

1/13/2025
9:46:01 AM

Palm Beach County Fleet Management Asset Maintenance History
10196012 2015 FORD F350 Utility Body, 14,000 Gvwr, Crew Cab, Topper, 4x4

Work Order: 2400098 **Meter:** 25475 **In Date:** 01/04/2024 **Closed:** 01/11/2024
Problem: PM Service.

Work Completed

- Preventive Maint. Service
- Rotate and balance six tires. Relearn tire sensors.
- Inspect and service power winch.
- Shop Supplies

Hours: 6.50 Comm: 0.00

Parts Issued

Quantity

Wiper Blade	2.00	
Washer Fluid Concentr	1.00	
5w20 Engine Oil	7.00	
Napagold Oil Filter	1.00	
Shop Supplies	1.00	
Labor: 474.50	Parts: 37.23	Total: 511.73

Work Order: 2406552 **Meter:** 27539 **In Date:** 07/09/2024 **Closed:** 07/15/2024
Problem: PM Service.

Work Completed

- Preventive Maint., Service No Key For Cab Door
- Diagnose Inoperative Exhaust Fan Tested Power And Ground Going Into Resistor Coming Out Of Switch No Power Replace And Retest.
- Rotate And Balance All 6 Tires With Nitro Fill
- Shop Supplies

Hours: 7.50 Comm: 0.00

Parts Issued

Quantity

Drain Plug	1.00	
Napagold Oil Filter	1.00	
5w20 Engine Oil	7.00	
Wiper Blade	2.00	
Used Fire X Refurbished	1.00	
Roof Vent Fan	1.00	
Shop Supplies	1.00	
Labor: 547.50	Parts: 335.97	Total: 883.47

Work Order: 2411030 **Meter:** 28394 **In Date:** 11/18/2024 **Closed:** 11/19/2024
Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00 Comm: 0.00

Labor: 146.00 Parts: 0.00 Total: 146.00

Total Hours: 155.80

Total Labor: 10,710.10

Total Comm: 3,011.68

Total Parts: 6,525.49