

3/27/2017  
3:46:13PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169549 2007 FORD F150 Pickup, 1/2 Ton, 4X4, Tow Pkg

**Workorder:** 744036                      **Problem:** PRE-DELIVERY INSPECTION

Meter Reading: 0	Labor	Parts
In Date: 09/13/2007	Hours	Description
Close Date: 09/13/2007	Quantity	
- Pre-Delivery Inspection	<b>2.00</b>	
<b>Parts Charge:</b> 0.00	<b>Labor Charge:</b> 110.00	

**Workorder:** 746071                      **Problem:** INSTALL 2 SIDE BOXES

Meter Reading: 1736	Labor	Parts
In Date: 10/23/2007	Hours	Description
Close Date: 10/25/2007	Quantity	
- Fabricate And Install 2 New Side Tool Boxes With Leg Support	<b>2.00</b>	SHOP SUPPLIES 1.00 TBSM36 SIDE MOUNT TOOL BOX 2.00
- Shop Supplies		
<b>Parts Charge:</b> 477.20	<b>Labor Charge:</b> 120.00	

**Workorder:** 833650                      **Problem:** P.M.SERVICE

Meter Reading: 6806	Labor	Parts
In Date: 02/04/2008	Hours	Description
Close Date: 02/12/2008	Quantity	
- Pm Service	<b>3.25</b>	10020 INJECTOR CLEANER DON'T REORDER 1.00
- Test Drive		1372 OIL FILTER FRM PH2 WIX 51372 1.00
- Shop Supplies		USED FIREX REFURBED FIRE EXTINGSHERS 1.00 CA8039 AIR FILTER LBF AF1615 WIX 46418 1.00 5W20 ENGINE OIL 7.00 SHOP SUPPLIES 1.00
<b>Parts Charge:</b> 56.66	<b>Labor Charge:</b> 15.00	

**Workorder:** 837624                      **Problem:** NO POWER,WONT GO OVER 40MPH & STALLS .

Meter Reading: 10500	Labor	Parts
In Date: 04/28/2008	Hours	Description
Close Date: 05/07/2008	Quantity	
- C/S No Power/Stalls/Eng Lt On; Comp Sys Diag-Po191 & Po148; Road Test Monitor Pin Data & F/Press; Fuel Drops On Hard Accel; R&R F/Filter	<b>3.50</b>	G10166 FUEL FILTER MTC FG1083 WIX 33243 1.00 SHOP SUPPLIES 1.00
- Transport & Pick Up At Dealer; Defective Fuel Pump		
- Shop Supplies		
<b>Parts Charge:</b> 19.15	<b>Labor Charge:</b> 60.00	

3/27/2017  
3:46:13PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169549 2007 FORD F150 Pickup, 1/2 Ton, 4X4, Tow Pkg

Workorder: 839283

Problem: P.M.SERVICE

Meter Reading: 11775	Labor	Parts	
In Date: 06/02/2008	Hours	Quantity	
- Pm Service	3.25	CA8039 AIR FILTER LBF AF1615 WIX 46418	1.00
- Road Test		1372 OIL FILTER FRM PH2 WIX 51372	1.00
- Shop Supplies		31-20 WIPER BLADES 20" BLADE	2.00
		5W20 ENGINE OIL	7.00
		SHOP SUPPLIES	1.00
<b>Parts Charge:</b> 53.88		<b>Labor Charge:</b> 30.00	

Workorder: 844531

Problem: NAIL IN TIRE

Meter Reading: 16570	Labor	Parts	
In Date: 09/22/2008	Hours	Quantity	
- C/S Nail In Tire; Verify Nail Punctured Tire; Remove Nail & Dismount Tire; Patch Hole, Mount & Balance; Add Nitrogen	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
<b>Parts Charge:</b> 2.00		<b>Labor Charge:</b> 60.00	

Workorder: 845299

Problem: P.M.SERVICE/NEEDS 4 TIRES

Meter Reading: 17263	Labor	Parts	
In Date: 10/07/2008	Hours	Quantity	
- Pm Service	5.75	31-22 WIPER BLADES 22" WIPER BLADE	2.00
- C/S Needs New Tires; Mount & Balance 4 New Tires; Test Drive		WASTE FEES	4.00
- Add Nitrogen		05023 BATTERY CLEANER	1.00
- Shop Supplies		1066 WHITE LITHIUM (CRC 05037)	1.00
		5W20 ENGINE OIL	7.00
		SHOP SUPPLIES	1.00
		61A P/STEERING FLUID	1.00
		12345841 GEAR OIL SYNTHETIC 75W-90	1.00
		TIRE DISPOSAL FEE	4.00
		TIRES 235/75R17	4.00
		1372 OIL FILTER FRM PH2 WIX 51372	1.00
<b>Parts Charge:</b> 715.69		<b>Labor Charge:</b> 60.00	

3/27/2017  
3:46:13PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169549 2007 FORD F150 Pickup, 1/2 Ton, 4X4, Tow Pkg

**Workorder:** 936284

**Problem:** P.M.SERVICE

Meter Reading: 24867	Labor	Parts	
In Date: 04/09/2009	Hours	Description	Quantity
- Pm Service	3.00	1372 OIL FILTER FRM PH2 WIX 51372	1.00
- Install New Decal		5W20 ENGINE OIL	7.00
- Shop Supplies		SHOP SUPPLIES	1.00
		1066 WHITE LITHIUM (CRC 05037)	1.00
<b>Parts Charge:</b> 43.48		<b>Labor Charge:</b> 180.00	

**Workorder:** 940509

**Problem:** Battery dead

Meter Reading: 28807	Labor	Parts	
In Date: 07/08/2009	Hours	Description	Quantity
- Road Call,Dead Battery.Jump Start Battery At Pink Palace,Check Charging System .Found Defective Battery.	3.00	SHOP SUPPLIES	1.00
- Transport And Pick Up Veh. At Dealer(Batt. Defective)			
- Shop Supplies			
<b>Parts Charge:</b> 2.00		<b>Labor Charge:</b> 120.00	

**Workorder:** 941189

**Problem:** LEFT REAR CHAIN GUARD/SEE REQUEST

Meter Reading: 29213	Labor	Parts	
In Date: 07/24/2009	Hours	Description	Quantity
-			
<b>Parts Charge:</b> 0.00		<b>Labor Charge:</b> 0.00	

3/27/2017  
3:46:13PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169549 2007 FORD F150 Pickup, 1/2 Ton, 4X4, Tow Pkg

**Workorder:** 943791

**Problem:** P.M. SERVICE

<b>Meter Reading:</b> 32641		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 09/28/2009	<b>Close Date:</b> 09/30/2009	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
-	P.M.Service	<b>5.50</b>	G10166 FUEL FILTER MTC FG1083 WIX 33243	1.00	
-	Verify C/K Engine Light On/Run Rough;Diagnose W/lds		31-20 WIPER BLADES 20" BLADE	2.00	
	Cylinder 7 Misfire.Send To Dealer For Warranty Repair		SHOP SUPPLIES	1.00	
-	Repair Nail In L/Front Tire		5W20 ENGINE OIL	7.00	
-	Repair Tool Box.		1066 WHITE LITHIUM (CRC 05037)	1.00	
-	Shop Supplies		CA8039 AIR FILTER LBF AF1615 WIX 46418	1.00	
			1372 OIL FILTER FRM PH2 WIX 51372	1.00	
<b>Parts Charge:</b> 78.73		<b>Labor Charge:</b> 330.00			

**Workorder:** 943919

**Problem:** C/K ENGINE LIGHT STAYS ON/MISFIRE

<b>Meter Reading:</b> 32658		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 09/30/2009	<b>Close Date:</b> 10/09/2009	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
-	Transpot And Pick Up Veh. At Dealer.	<b>2.00</b>	SHOP SUPPLIES	1.00	
-	Shop Supplies				
<b>Parts Charge:</b> 2.00		<b>Labor Charge:</b> 60.00			

**Workorder:** 1001520

**Problem:** P. M.

<b>Meter Reading:</b> 38584		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 02/10/2010	<b>Close Date:</b> 02/22/2010	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
-	P. M. Service.	<b>2.75</b>	G10166 FUEL FILTER MTC FG1083 WIX 33243	1.00	
-	Shop Supplies		5W20 ENGINE OIL	7.00	
			1372 OIL FILTER FRM PH2 WIX 51372	1.00	
			SHOP SUPPLIES	1.00	
<b>Parts Charge:</b> 55.80		<b>Labor Charge:</b> 165.00			

3/27/2017  
3:46:13PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169549 2007 FORD F150 Pickup, 1/2 Ton, 4X4, Tow Pkg

**Workorder:** 1005635

**Problem:** Nail in front left tire

Meter Reading: 43043	Labor	Parts	
In Date: 05/28/2010	Hours	Description	Quantity
- C/C: Nail In Tire. Verify. Nail In F/L Tire. Dismount, Patch, Mount, Balance, Add N2.	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
<b>Parts Charge:</b>	2.00	<b>Labor Charge:</b>	60.00

**Workorder:** 1006460

**Problem:** P. M., & needs 4 new tires

Meter Reading: 44121	Labor	Parts	
In Date: 06/18/2010	Hours	Description	Quantity
- P. M. Service.	5.75	31-20 WIPER BLADES 20" BLADE	2.00
- C/C: Needs 4 Tires. Verify. R&R Four Tires, Mount, Alance, Add 35 Psi Of Nitrogen.		TIRE DISPOSAL FEE	4.00
		WASTE FEE	4.00
- Verify, Fuel Filter Quick Connect Broken. R&R Quick Connect.		FUEL FILTER CLIPS	1.00
- Shop Supplies		SHOP SUPPLIES	1.00
		5W20 ENGINE OIL	7.00
		G10166 FUEL FILTER MTC FG1083 WIX 33243	1.00
		CA8039 AIR FILTER LBF AF1615 WIX 46418	1.00
		1372 OIL FILTER FRM PH2 WIX 51372	1.00
		P235/75R17 108T WRANGLER TIRES	4.00
<b>Parts Charge:</b>	746.31	<b>Labor Charge:</b>	345.00

3/27/2017  
3:46:13PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169549 2007 FORD F150 Pickup, 1/2 Ton, 4X4, Tow Pkg

**Workorder:** 1012781

**Problem:** P.M.SERVICE

Meter Reading: 50035	Labor	Parts	
In Date: 11/16/2010	Hours	Quantity	
Close Date: 11/30/2010	Description		
- P. M.	10.75	1372 OIL FILTER FRM PH2 WIX 51372	1.00
- Verify. Needs Front Brake Pads, Replace Pads. Turn F-Rotors, Lube Calipers, Reassemble & Test Drive.		5W20 ENGINE OIL	7.00
- Service All Tool Boxes. Lube Hinges, Adjust Latches, Tighten & Check Fastening Bolts.		FRONT BRAKE PADS	1.00
- Verify, Strobe Has Moisture. Remove Lens, Dry Out, Reinstall & Seal. Repair Trim On Bumper.		SHOP SUPPLIES	1.00
- Found Nail In F/L Tire. Remove Nail, Found Leaking, Dismount, Patch, Mount, Balance, Add 35 Psi Of Nitrogen, & Rotate To Right Rear.			
- Shop Supplies			
<b>Parts Charge:</b>	77.57	<b>Labor Charge:</b>	645.00

**Workorder:** 1101359

**Problem:** BOLT IN R/REAR TIRE

Meter Reading: 52583	Labor	Parts	
In Date: 02/03/2011	Hours	Quantity	
Close Date: 02/08/2011	Description		
- C/C: Bolt In R/R Tire. Remove Bolt, Verify Hole, Dismount, Patch, Mount, Balance, Add N2.	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
<b>Parts Charge:</b>	2.00	<b>Labor Charge:</b>	60.00

3/27/2017  
3:46:13PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169549 2007 FORD F150 Pickup, 1/2 Ton, 4X4, Tow Pkg

**Workorder:** 1103888

**Problem:** P. M. SERVICE

Meter Reading: 54761	Labor	Parts	
In Date: 04/11/2011	Hours	Description	Quantity
- Performed P.M.	5.25	1372 OIL FILTER FRM PH2 WIX 51372	1.00
- R&R Bulb For Center Brake.		31-20 WIPER BLADES 20" BLADE	2.00
- Disassembled Beacon Light & Repaired & Cleaned One Side Of Light Connection.		5W20 ENGINE OIL	7.00
- Adjusted Tail Gate Strikers & Latch.		1066 WHITE LITHIUM (CRC 05037)	1.00
- Shop Supplies		SHOP SUPPLIES	1.00
		CA8039 AIR FILTER LBF AF1615 WIX 46418	1.00
		USED FIREX REFURBED FIRE EXTINGUISHERS	1.00
		G10166 FUEL FILTER MTC FG1083 WIX 33243	1.00
<b>Parts Charge:</b>	53.56	<b>Labor Charge:</b>	315.00

**Workorder:** 1104282

**Problem:** LIGHT ON TOP OF CAB BROKE.

Meter Reading: 55042	Labor	Parts	
In Date: 04/20/2011	Hours	Description	Quantity
- R&R Strobe & Rewired, Dropped Rear Of Hd Liner To Access Wiring.	3.00	EMERGENCY STROBE LIGHT ASSY.	1.00
- Shop Supplies		765-1589 BLACK SILICONE	2.00
		SHOP SUPPLIES	1.00
<b>Parts Charge:</b>	154.25	<b>Labor Charge:</b>	180.00

**Workorder:** 1108769

**Problem:** P. M. SERVICE

Meter Reading: 59884	Labor	Parts	
In Date: 08/18/2011	Hours	Description	Quantity
- P. M. Service.	4.75	1372 OIL FILTER FRM PH2 WIX 51372	1.00
- Remove Reese Hitch, Wire Brush Rust, Clean Receiver, Lube & Reinstall.		31-20 WIPER BLADES 20" BLADE	2.00
- Found Nail In Left Rear Tire. Dismount, Patch, Mount, Balance, Add N2, Rotate To Front Left.		SHOP SUPPLIES	1.00
- Shop Supplies		5W20 ENGINE OIL	7.00
		2560 HITCH PIN/CLIP	1.00
<b>Parts Charge:</b>	52.66	<b>Labor Charge:</b>	285.00

3/27/2017  
3:46:13PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169549 2007 FORD F150 Pickup, 1/2 Ton, 4X4, Tow Pkg

**Workorder:** 1109049

**Problem:** Re-wire truck for trailer hook-up

Meter Reading: 60129	Labor	Parts	
In Date: 08/26/2011	Hours	Description	Quantity
- C/S: Trailer Lock Up In Reverse. Perform Pinpoint Test & Found Trailer Was Not Wired Correct. Replace Trailer Plug, Rewire, Install Fuse & Wire Aux Battery Charger, Wire Trailer Brake Controller.	6.00	SHOP SUPPLIES	1.00
		4047 BRAKE CONTROLLER (USE 5100)	1.00
		5404 FEMALE CONNECTOR	1.00
- Shop Supplies			
<b>Parts Charge:</b> 73.02		<b>Labor Charge:</b> 360.00	

**Workorder:** 1112096

**Problem:** REPLACE BATTERY

Meter Reading: 62366	Labor	Parts	
In Date: 11/10/2011	Hours	Description	Quantity
- C/C: Replace Battery. Verify Complaint. Test Battery, Bad After Recharge. R&R Battery, Check Charging System.	0.75	GROUP 58 BATTERY (MTC BXT-58)	1.00
		SHOP SUPPLIES	1.00
- Shop Supplies			
<b>Parts Charge:</b> 120.18		<b>Labor Charge:</b> 45.00	

**Workorder:** 1201706

**Problem:** P. M. Service, & Nail in front passenger tire

Meter Reading: 65708	Labor	Parts	
In Date: 02/22/2012	Hours	Description	Quantity
- P. M. Service.	4.25	5W20 ENGINE OIL	7.00
- Replace Both Rear Tires & Rotate To The Front.		WASTE FEE	2.00
- Shop Supplies		31-20 WIPER BLADES 20" BLADE	2.00
		CA8039 AIR FILTER LBF AF1615 WIX 46418	1.00
		P235/75R17-108T WRANGLER SL ARMOR	2.00
		TIRE DISPOSAL FEE	2.00
		1372 OIL FILTER FRM PH2 WIX 51372	1.00
		USED FIREX REFURBED FIRE EXTINGSHERS	1.00
		SHOP SUPPLIES	1.00
<b>Parts Charge:</b> 415.66		<b>Labor Charge:</b> 255.00	

3/27/2017  
3:46:13PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169549 2007 FORD F150 Pickup, 1/2 Ton, 4X4, Tow Pkg

**Workorder:** 1208634

**Problem:** pm , flat tire

<b>Meter Reading: 73125</b>		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 09/11/2012	<b>Close Date:</b> 09/19/2012	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
- Pm		<b>7.25</b>	SHOP SUPPLIES		1.00
- Ck Flat Tire Verify Needs Two Rear Tires Dismount Patch			5W20 ENGINE OIL		7.00
Mount Balance Rotate To Front Add N2 Clear Tpm			P235/75R17-108T SILENT ARMOR		2.00
- Secure Tool Boxes Tighten Bolts			G10166 FUEL FILTER MTC FG1083 WIX 33243		1.00
- Ck Wate On Floor Board Verify Ac Drain Clogged Clean			1372 OIL FILTER FRM PH2 WIX 51372		1.00
Out Drain Disassemble Ps Pannels And Flooring To Dry			31-20 WIPER BLADES 20" BLADE		2.00
Out			WASTE FEE		2.00
- Shop Supplies			TIRE DISPOSAL FEE		2.00
<b>Parts Charge:</b> 441.71		<b>Labor Charge:</b> 435.00			

**Workorder:** 1301784

**Problem:** pm

<b>Meter Reading: 79649</b>		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 02/21/2013	<b>Close Date:</b> 02/27/2013	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
- Pm		<b>2.75</b>	NAPA QUART 5W20		7.00
- Shop Supplies			1372 OIL FILTER		1.00
			SHOP SUPPLIES		1.00
			USED FIREX REFURBED F		1.00
<b>Parts Charge:</b> 48.18		<b>Labor Charge:</b> 165.00			

**Workorder:** 1304158

**Problem:** battery

<b>Meter Reading: 82288</b>		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 04/26/2013	<b>Close Date:</b> 04/30/2013	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
- Ck Battery Test Battery Bad Replace Battery Ck		<b>0.75</b>	SHOP SUPPLIES		1.00
Charging Sys			58 BATTERY		1.00
- Shop Supplies					
<b>Parts Charge:</b> 137.62		<b>Labor Charge:</b> 45.00			

3/27/2017  
3:46:13PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169549 2007 FORD F150 Pickup, 1/2 Ton, 4X4, Tow Pkg

**Workorder:** 1305453      **Problem:** Flat tire, screw in sidewall

Meter Reading: 83538	Labor	Parts
In Date: 06/04/2013	Hours	Description
Close Date: 06/07/2013		Quantity
- C/C: Flat, R&R Tire. Verify, Unable To Repair, Repace, Mount, Balance One Tire.	1.00	758537188 235-75R17
- Shop Supplies		SHOP SUPPLIES
		TIRE DISPOSAL FEE
<b>Parts Charge:</b> 216.89	<b>Labor Charge:</b> 60.00	

**Workorder:** 1307560      **Problem:** tail light out

Meter Reading: 86443	Labor	Parts
In Date: 07/30/2013	Hours	Description
Close Date: 08/08/2013		Quantity
- Ck Tail Light Out Replace Lr Tail Light Bulb Reassemble	0.50	BULB
<b>Parts Charge:</b> 0.99	<b>Labor Charge:</b> 30.00	

**Workorder:** 1308458      **Problem:** pm

Meter Reading: 87417	Labor	Parts
In Date: 08/21/2013	Hours	Description
Close Date: 09/12/2013		Quantity
- Pm	2.75	NAPAGOLD FUEL FILTER
- Shop Supplies		31-20 WIPER BLADES 20
		NAPA QUART 5W20
		NAPAGOLD OIL FILTER
		NAPAGOLD AIR FILTER
		WASHER FL
		SHOP SUPPLIES
<b>Parts Charge:</b> 60.65	<b>Labor Charge:</b> 165.00	

**Workorder:** 1312050      **Problem:** nail in l/front tire

Meter Reading: 90435	Labor	Parts
In Date: 12/03/2013	Hours	Description
Close Date: 12/11/2013		Quantity
- Ck Tire For Leak And Fill All 4 Tires With Air	0.25	
<b>Parts Charge:</b> 0.00	<b>Labor Charge:</b> 15.00	

3/27/2017  
3:46:13PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169549 2007 FORD F150 Pickup, 1/2 Ton, 4X4, Tow Pkg

**Workorder:** 1402550

**Problem:** pm

Meter Reading: 93979	Labor	Parts	
In Date: 03/17/2014	Hours	Description	Quantity
- Pm	6.25	SHOP SUPPLIES	1.00
- Verify Needs 4 Tires Replace 4 Tires Mount Balance Add N2		NAPA QUART 5W20	7.00
		235 75R17 ADVENTURE	4.00
- Verify Brake Light Inop Found Bad Brake Switch On Pedal Rr Switch Ck All Lights		SWITCH - STOPLIGHT	1.00
		NAPAGOLD OIL FILTER	1.00
- Shop Supplies		TIRE DISPOSAL FEE	4.00
		WIPER BLADE	2.00
<b>Parts Charge:</b>	1,024.59	<b>Labor Charge:</b>	375.00

**Workorder:** 1404470

**Problem:** maint. light on, runs rough

Meter Reading: 95796	Labor	Parts	
In Date: 05/07/2014	Hours	Description	Quantity
- Ck Maint Light Is On Scan And Found No Codes Test Drive Vehicle 50 Miles And Was Unable To Verify Customer Concern At This Time Clean Throttle Plate And Clear Codes	5.50	SHOP SUPPLIES	1.00
- Ac Clutch Was Cycling Too Much Ck Sys Pressure Evacuate And Recharge To Proper Level Ck For Leaks And Found No Leaks At This Time			
- Shop Supplies			
<b>Parts Charge:</b>	2.00	<b>Labor Charge:</b>	330.00

**Workorder:** 1405528

**Problem:** CK ENGINE LIGHT IS ON

Meter Reading: 96567	Labor	Parts	
In Date: 06/05/2014	Hours	Description	Quantity
- Ck Engine Light Is On Scan Po61B Perform Pinpoint Test And Found Bad Throttle Octuator Assembly Replace Actuator Assembly And Clear Code	5.00	SHOP SUPPLIES	1.00
		THROTTLE	1.00
		LUBRICANT	1.00
- Test Drive 48 Miles After Repair			
- Shop Supplies			
<b>Parts Charge:</b>	274.04	<b>Labor Charge:</b>	300.00

3/27/2017  
3:46:13PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169549 2007 FORD F150 Pickup, 1/2 Ton, 4X4, Tow Pkg

**Workorder:** 1410457

**Problem:** P.M.SERVICE

<b>Meter Reading:</b> 101421		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 10/20/2014	<b>Close Date:</b> 10/23/2014	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
- Pm		<b>7.75</b>	NAPAGOLD FUEL FILTER		1.00
- Verify Needs Rear Brake Pads Turn Rear Rotors Svc			NAPA QUART 5W20		7.00
- Calipers Rr Pads			DISC BRAKE PADS		1.00
- Shop Supplies			WIPER BLADE		2.00
			NAPAGOLD OIL FILTER		1.00
			SHOP SUPPLIES		1.00
<b>Parts Charge:</b> 101.21		<b>Labor Charge:</b> 465.00			

**Workorder:** 1503911

**Problem:** pm

<b>Meter Reading:</b> 107700		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 04/15/2015	<b>Close Date:</b> 04/23/2015	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
- Pm		<b>3.25</b>	NAPA QUART 5W20		7.00
- Install Steering Wheel Cover			WASHER FL		1.00
- Shop Supplies			SHOP SUPPLIES		1.00
			NAPAGOLD OIL FILTER		1.00
			WIPER BLADE		2.00
			NAPAGOLD AIR FILTER		1.00
			BATTERY CLEANER		1.00
			STG WHEEL COV - FORD		1.00
<b>Parts Charge:</b> 74.58		<b>Labor Charge:</b> 195.00			

**Workorder:** 1504555

**Problem:** NEEDS NEW KEY

<b>Meter Reading:</b> 108243		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 05/05/2015	<b>Close Date:</b> 05/12/2015	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
- Ck Ignition Switch And Found Bad Ign Key Send Driver To Vista For New Key		<b>0.50</b>			
<b>Parts Charge:</b> 0.00		<b>Labor Charge:</b> 30.00			

3/27/2017  
3:46:13PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169549 2007 FORD F150 Pickup, 1/2 Ton, 4X4, Tow Pkg

Workorder: 1504569		Problem: need spare key			
Meter Reading: 108096		Labor	Parts		
In Date: 05/05/2015	Close Date: 05/11/2015	Hours	Description	Quantity	
- Make And Program One Spare Key		1.00	SHOP SUPPLIES		1.00
- Shop Supplies			FORD IGNITION KEY BLANK		1.00
Parts Charge: 28.61		Labor Charge: 60.00			
Workorder: 1505749		Problem: low tire front left			
Meter Reading: 109579		Labor	Parts		
In Date: 06/09/2015	Close Date: 06/16/2015	Hours	Description	Quantity	
- Ck Front Left Tire Flat Repair FI Tire Add N2		1.00	SHOP SUPPLIES		1.00
- Shop Supplies					
Parts Charge: 2.00		Labor Charge: 60.00			
Workorder: 1507542		Problem: battery slow starting			
Meter Reading: 111395		Labor	Parts		
In Date: 07/29/2015	Close Date: 07/31/2015	Hours	Description	Quantity	
- Dead Battery Ck Battery Bed Replace Battery Ck		0.75	BATTERY		1.00
Charging Sys			SHOP SUPPLIES		1.00
- Shop Supplies					
Parts Charge: 99.89		Labor Charge: 45.00			
Workorder: 1509494		Problem: pm, vacuum hose			
Meter Reading: 112947		Labor	Parts		
In Date: 09/21/2015	Close Date: 09/24/2015	Hours	Description	Quantity	
- Pm		9.75	VALVE ASSEMBLY		1.00
- Ck Vacuum Leak Perform Pinpoint Test Found Leaking			SHOP SUPPLIES		1.00
Vacuum Solenoid Replace Solenoid			NAPAGOLD OIL FILTER		1.00
- Repair Left Head Light			NAPA QUART 5W20		7.00
- Replace Both Outer Stabilizer Bar Links			SWAY BAR LINK		2.00
- Shop Supplies			HALOGEN CAPSULE		1.00
			USED FIRE X REFURBISHED		1.00
			WASHER FLUID CONCENTR		1.00
Parts Charge: 227.69		Labor Charge: 585.00			

3/27/2017  
3:46:13PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169549 2007 FORD F150 Pickup, 1/2 Ton, 4X4, Tow Pkg

<b>Workorder:</b> 1512364		<b>Problem:</b> nail in tire			
<b>Meter Reading:</b> 115650		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 12/07/2015	<b>Close Date:</b> 12/09/2015	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
<hr/>					
-	Repair FI Tire Patch Mount Balance Add N2	1.00	SHOP SUPPLIES		1.00
-	Shop Supplies				
	<b>Parts Charge:</b> 2.00	<b>Labor Charge:</b> 60.00			

<b>Workorder:</b> 1601939		<b>Problem:</b> PM			
<b>Meter Reading:</b> 118230		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 02/24/2016	<b>Close Date:</b> 02/29/2016	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
<hr/>					
-	Pm	6.00	NAPAGOLD AIR FILTER		1.00
-	Replace 4 Tires		TIRE DISPOSAL FEE		4.00
-	Fill All Tires With Nitrogen		235 75R17 ADVENTURE		4.00
-	Repair Left Rear Tail Light		20" WIPER BLADE		2.00
-	Shop Supplies		NAPAGOLD OIL FILTER		1.00
			WASHER FLUID CONCENTR		1.00
			SHOP SUPPLIES		1.00
			NAPA QUART 5W20		7.00
			NAPAGOLD FUEL FILTER		1.00
	<b>Parts Charge:</b> 920.47	<b>Labor Charge:</b> 360.00			

<b>Workorder:</b> 1605178		<b>Problem:</b> Left tail light inop.			
<b>Meter Reading:</b> 121479		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 05/18/2016	<b>Close Date:</b> 05/20/2016	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
<hr/>					
-	Replace Left Rear Marker Light Bulb.	0.50	BULB		1.00
	<b>Parts Charge:</b> 0.78	<b>Labor Charge:</b> 30.00			

3/27/2017  
3:46:13PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169549 2007 FORD F150 Pickup, 1/2 Ton, 4X4, Tow Pkg

**Workorder:** 1606441

**Problem:** Pm service

<b>Meter Reading:</b> 123107		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 06/24/2016	<b>Close Date:</b> 06/29/2016	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
- Pm Service.		<b>8.75</b>	NAPAGOLD OIL FILTER		1.00
- Verify Needs Front Brake Pads.And Turn Front Brake Rotors			NAPAGOLD AIR FILTER		1.00
			SHOP SUPPLIES		1.00
- Rotate And Balance All Four Tires.			NAPA QUART 5W20		7.00
- Shop Supplies			DISC BRAKE PADS		1.00
<b>Parts Charge:</b> 78.13		<b>Labor Charge:</b> 525.00			

**Workorder:** 1608774

**Problem:** Fan makes loud noise.

<b>Meter Reading:</b> 125872		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 08/23/2016	<b>Close Date:</b> 08/30/2016	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
- Diagnose For Fan Noise. Pressure Test And Inspect Cooling System. R/R Radiator,Thermostat. Flush & Fill Cooling System,Clear Codes With Scan Tool. Test Drive.		<b>5.25</b>	THERMOSTAT		1.00
			NAPA RADIATOR		1.00
			THERMOSTAT SEAL		1.00
- Shop Supplies			SHOP SUPPLIES		1.00
			THERMOSTAT		1.00
			RADIATOR ASSY		1.00
			PEAK GLOBAL ANTIFRZ		2.00
<b>Parts Charge:</b> 249.01		<b>Labor Charge:</b> 315.00			

**Workorder:** 1701595

**Problem:** Transition Prep Charge

<b>Meter Reading:</b> 132009		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 02/15/2017	<b>Close Date:</b> 02/15/2017	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
- Transition Prep Charge		<b>2.00</b>			
<b>Parts Charge:</b> 0.00		<b>Labor Charge:</b> 0.00			

Total Parts Charges:	<b>7,194.84</b>	Total Labor Charges:	<b>8,510.00</b>	Total Comm. Charges:	<b>0.00</b>
----------------------	-----------------	----------------------	-----------------	----------------------	-------------