Palm Beach County Fleet Management Asset Maintenance History 10198317 2016 FORD F250 Utility Body, 3/4 Ton, 4X4

Total Hours: 100.65 Labor: 7,016.80 Parts: 3,769.21 Comm: 90.40 Charged: 10876.41

Work Order: 1600943 Meter: 321 In Date: 01/27/2016 Closed: 01/27/2016

Problem: 1061 - Pre Delivery Inspection

Work Completed

- Pre Delivery Inspection

Hours: 3.00 Comm: 0.00 Labor: 180.00 Parts: 0.00 Total: 180.00

Work Order: 1612376 Meter: 4032 In Date: 12/02/2016 Closed: 12/27/2016

Problem: P.M. service.

Work Completed		Parts Issued	Parts Issued	
- P.m. Service.		5w20 Engine Oil	5w20 Engine Oil	
- Replace missing pintle pin.		Napagold Oil Filte	Napagold Oil Filter	
- Rotate and balance tires.		Floor Mat-2pc Ruk) Bk	1.00
- Shop Supplies		Stg Wheel Cov - Fo	ord	1.00
		Pintle Pin W/clip		1.00
		Shop Supplies		1.00
Hours: 4.00	Comm: 0.00	Labor: 240.00	Parts: 67.28	Total: 307.28

Work Order: 1705430 Meter: 5819 In Date: 05/31/2017 Closed: 06/06/2017

Problem: P.M. service.

Work Completed		Parts Issued		Qu	ıantity
- P.m. service.		5w20 Engine Oil			7.00
- Rotate and high speed balance all fo	our wheels.nitro fill all.	Napagold Oil Filte	er		1.00
- Shop Supplies		22" Wiper Blade			2.00
,		Washer Fluid Con	centr		1.00
		Used Fire X Refurb	bished		1.00
		Shop Supplies			1.00
Hours: 3.75	Comm: 0.00	Labor: 225.00	Parts: 43.28	Total:	268.28

Hours: 4.55

Palm Beach County Fleet Management Asset Maintenance History 10198317 2016 FORD F250 Utility Body, 3/4 Ton, 4X4

Work Order: 1800033 **Meter:** 8150 01/02/2018 **Closed:** 01/08/2018 In Date: Problem: P.M. service and wiper blades. **Parts Issued** Quantity **Work Completed** 5w20 Engine Oil 7.00 - P.m. service. Napagold Oil Filter 1.00 - Test battery and charging system .battery failed load test after recharge.r&r with new battery. Napagold Air Filter 1.00 - Rotate and high speed balance all four tires. 2.00 22" Wiper Blade - Shop Supplies Used Fire X Refurbished 1.00 **Bat Term Protector** 1.00 Battery 65 1.00 **Shop Supplies** 1.00 Comm: 0.00 Parts: 212.27 Total: 497.27 Hours: 4.75 Labor: 285.00 Work Order: 1806181 Meter: 9840 In Date: 06/18/2018 **Closed**: 06/20/2018 **Problem:** Right rear passenger tire. Quantity **Work Completed Parts Issued Shop Supplies** 1.00 - Repair and balance right rear tire. - Shop Supplies Comm: 0.00 Hours: 1.00 Labor: 60.00 Parts: 2.00 Total: 62.00 Work Order: 1807982 Meter: 10193 In Date: 08/03/2018 **Closed**: 08/09/2018 Problem: PM Service **Work Completed Parts Issued** Quantity Napagold Oil Filter 1.00 - P.m. service. 5w20 Engine Oil 7.00 - R&r both defective rear red brake lights. 2.00 22" Wiper Blade - Rotate and balance all four tires. Nitrogen fill tires. Led Sup Mdl 44 42 Dio 2.00 - Shop Supplies **Shop Supplies** 1.00

Comm: 0.00

Labor: 273.00

Parts: 153.59

Total: 426.59

Palm Beach County Fleet Management Asset Maintenance History 10198317 2016 FORD F250 Utility Body, 3/4 Ton, 4X4

Work Order: 1901364 Meter: 10651 In Date: 02/05/2019 Closed: 02/14/2019

Problem: P.M. service.

Work Completed		Parts Issued		Quantity
- P.m. service.	- P.m. service. Napagold C		er	1.00
- Charge battery fully . Test battery and charging	5w20 Engine Oil		7.00	
		22" Wiper Blade		2.00
 Rotate and high speed balance all four tires . Nitrofill all . Shop Supplies 		Used Fire X Refurbished Ford Triton Pvc Swc Wd40 Spr Battery 65		1.00
				1.00
				1.00
				1.00
		Shop Supplies		1.00
Hours: 4.75	Comm: 0.00	Labor: 318.25	Parts: 247.74	Total: 565.99

Work Order: 1906801 Meter: 11545 In Date: 06/28/2019 Closed: 07/16/2019

Problem: PM Service

Work Completed		Parts Issued		Quantity
- P.m. service.		Napagold Oil Filter 5w20 Engine Oil		1.00
- Repair right front tire . Rotate and high speed balance	7.00			
Nitrofill all.		22" Wiper Blade		2.00
- Shop Supplies		Used Fire X Refurb	oished	1.00
		Shop Supplies		1.00
Hours: 4.75	Comm: 0.00	Labor: 318.25	Parts: 47.36	Total: 365.61

Palm Beach County Fleet Management Asset Maintenance History 10198317 2016 FORD F250 Utility Body, 3/4 Ton, 4X4

Work Order: 2000226 Meter: 12102 In Date: 01/08/2020 Closed: 01/21/2020

Problem: P.M. Service.Battery goes dead.

Work Completed		Parts Issued		Quantity
- P.m. service.	Napagold Oil Filte	r	1.00	
- Charge battery fully . Test battery and charging system . c	5w20 Engine Oil		7.00	
draw test500 Amps draw from inverter . Replace defective	22" Wiper Blade Mac Wite Lithium Gres Ford Triton Pvc Swc Thor Push Button On/off Pwr Inverter 2000w		2.00	
and install remote on/off switch for inverter. Retest .			1.00	
- Rotate and high speed balance all four tire . Nitrofill all.			1.00	
- Shop Supplies			1.00	
			1.00	
		Shop Supplies		1.00
Hours: 8.75	Comm: 0.00	Labor: 638.75	Parts: 486.79	Total: 1,125.54

Work Order: 2007809 Meter: 12559 In Date: 08/07/2020 Closed: 08/12/2020

Problem: PM Service, Check lights.

Work Completed		Parts Issued		Quantity
- P.m. service.		Napagold Oil Filte	r	1.00
- Test and replace both defective brake light bulbs .		5w20 Engine Oil		7.00
- Balance and rotate all four tires . Nitrofill all.		22" Wiper Blade		2.00
- Shop Supplies		Mac Wite Lithium	Gres	1.00
		Wd40 Spr		1.00
		Used Fire X Refurb	ished	1.00
		Led Sup Mdl 44 42	2 Dio	2.00
		Shop Supplies		1.00
Hours: 4.55	Comm: 0.00	Labor: 332.15	Parts: 197.53	Total: 529.68

Palm Beach County Fleet Management Asset Maintenance History 10198317 2016 FORD F250 Utility Body, 3/4 Ton, 4X4

Work Order: 2101781 Meter: 12768 In Date: 02/17/2021 Closed: 02/25/2021

Problem: P.M. service.

Work Completed		Parts Issued		Quantity
 check battery , charging system after fully charge it fails load test r@r the defective battery . balance and rotate all 4 tires . Nitro fill all. 		Drain Plug		1.00
		Napagold Oil Filte	r	1.00
		5w20 Engine Oil		8.00
		22" Wiper Blade		2.00
		Battery 65		1.00
		Shop Supplies		1.00
Hours: 4.75	Comm: 0.00	Labor: 346.75	Parts: 232.80	Total: 579.55

Work Order: 2113380 Meter: 13048 In Date: 12/17/2021 Closed: 12/23/2021

Problem: PM Service.

Work Completed		Parts Issued		Quantity
- Preventive Maint. Service		Napagold Oil Filter		1.00
- Rotate and speed balance all 4 tires, nitro fill		5w20 Engine Oil		8.00
- Replace broken pintle		Washer Fluid Concentr		1.00
- Shop Supplies		22" Wiper Blade		2.00
		Used Fire X Refurbished		1.00
		Pintle Pin W/clip		1.00
		Shop Supplies		1.00
Hours: 3.95	Comm: 0.00	Labor: 288.35	Parts: 43.92	Total: 332.27

Palm Beach County Fleet Management Asset Maintenance History 10198317 2016 FORD F250 Utility Body, 3/4 Ton, 4X4

Work Order: 2208291 Meter: 14197 In Date: 08/09/2022 Closed: 08/24/2022

Problem: PM Service. seat will not recline

Work Completed		Parts Issued		Quantity
- Preventive Maint. Service		Napagold Oil Filte	r	1.00
- Driver Seat Wont Recline, Frame Gear Broken Inside	5w20 Engine Oil		8.00	
Seat Cusion And Replace Seat Back Frame	22" Wiper Blade		2.00	
- Rotate And Balance All Tires With Nitro Fill		Body Mount Kit		4.00
- Frame Mount Bushings Worn Out R&r All 6 Frame N	Mount Bushings	Body Mount Kit		2.00
- Shop Supplies		Hadle		1.00
		Frame Assy		1.00
		Shop Supplies		1.00
Hours: 11.75	Comm: 0.00	Labor: 857.75	Parts: 692.81	Total: 1,550.56

Work Order: 2301959 Meter: 14893 In Date: 02/28/2023 Closed: 03/07/2023

Problem: PM Service.

Work Completed		Parts Issued		Quantity
- Preventive Maint. Service		Napagold Oil Filte	r	1.00
- rotate and balance all 4 tires nitro fill all		Napa Quart 5w20		8.00
- Replace broken key program new key		22" Wiper Blade		2.00
- Rear Differential service . Inspect and service rear	r differential	Used Fire X Refurb	oished	1.00
- Shop Supplies		Non-chlor Brake C	Inr	1.00
		Friction Modifier		2.00
		75w140 Ford Axle	Lube	4.00
		Ford Ignition Key I	Blank	1.00
		Shop Supplies		1.00
Hours: 5.75	Comm: 0.00	Labor: 419.75	Parts: 237.13	Total: 656.88

Palm Beach County Fleet Management Asset Maintenance History 10198317 2016 FORD F250 Utility Body, 3/4 Ton, 4X4

Work Order: 2308405 Meter: 15457 In Date: 08/22/2023 Closed: 09/07/2023

Problem: PM Service. ac not blowing at all

Work Completed	
----------------	--

- Preventive Maint. Service completed
- balance and rotate all 4 tires. Nitro fill all.
- check and r&r defective trailer plug and fabricated wire as needed
- computer diag b10b9,check,pin test by ids,performed a/c performance test,sop ,replaced a/c blower controller by r&i all necessary parts such as dash board,a/c evap case,recover and recharge freon then verify normal operation

- Shop Supplies

Hours: 14.25 Comm: 0.00

Parts Issued	Quantity
Drain Plug	1.00
Napagold Oil Filter	1.00
5w20 Engine Oil	8.00
22" Wiper Blade	2.00
Wd40 Spr	1.00
Steering Wheel Cover Large	1.00
Socket	1.00
A/c Resistor	1.00
Shop Supplies	1.00
Labor: 1,040.25 Parts: 202.52	Total: 1,242.77

Palm Beach County Fleet Management Asset Maintenance History 10198317 2016 FORD F250 Utility Body, 3/4 Ton, 4X4

Work Order: 2402582 Meter: 16253 In Date: 03/12/2024 Closed: 03/21/2024

Problem: PM Service. Send for Detail. wont started in morning

Work Completed		Parts Issued	Quantity
- Performed P.m. Service & Inspection.		Napagold Oil Filter	1.00
- Performed Tire Rotation Balance On All 4 Wheels, Add Nitro Fill Rese		5w20 Engine Oil	8.00
Tpms.		Washer Fluid Concentr	1.00
- Load Test Battery, Battery Test Recommend Ch	,	Wiper Blade	2.00
Retest, Battery Test Recommend Replacment Bad Cell. Removed Then Replaced & Reset To Basic Settings.		Used Fire X Refurbished	1.00
	ivers Dear Light & Chack	Napagold Air Filter	1.00
 Driver Side Rear Turn Signal Inop. Removed Dri Signal, Found Led Light Inop, Removed And Repla 	3	Battery	1.00
- Vehicle Bounce While Driving, Removed & Repl		Led Sup Mdl 44 42 Dio	1.00
Bump Stops.		Gas Grande Shock	2.00
 Performed Engine Decarb & Fuel Injection Flush Then Removed Throttle Body And Clean. Vehicle Running Rough Check Engine Light On, Plug In Scan Tool Found Fault Code P0301 Engine Misfire, Perform Diagnose Found Ignition Coil Defective, Removed & Replaced Then Perform Tune-up Removed & Replaced 8 Ignition Wires, 16 Spark Pugs. 		bumper	2.00
		Intake Cleaner Kit	1.00
		Motor Tune-up 16oz	1.00
		Espak Plug Wire	4.00
		Espak Plug Wire	4.00
- Shop Supplies		Spark Plug	16.00
		Coil	1.00
		Shop Supplies	1.00
Hours: 14.35	Comm: 0.00	Labor: 1,047.55 Pa	rts: 902.20 Total: 1,949.7

Work Order: 2402905 Meter: 16253 In Date: 03/21/2024 Closed: 03/22/2024

Problem: 1 - Detail Vehicle Wash Ticket(s) Issued WO: 2402582 for: terrance

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued Wo: 2402582 for: terrance

Hours: 0.00 Comm: 90.40 Labor: 0.00 Parts: 0.00 Total: 90.40

Palm Beach County Fleet Management Asset Maintenance History 10198317 2016 FORD F250 Utility Body, 3/4 Ton, 4X4

Work Order: 2409382 Meter: 17705 In Date: 09/26/2024 Closed: 09/27/2024

Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 0.00 Total: 146.00

Total Hours: 100.65 Total Labor: 7,016.80 Total Comm: 90.40 Total Parts: 3,769.21