

1/13/2025
9:41:38 AM

Palm Beach County Fleet Management Asset Maintenance History
10178881 2009 FORD F250 Pickup, 3/4 Ton

Total Hours: 195.25 Labor: 12,505.00 Parts: 8,373.57 Comm: 0.00 Charged: 20878.57

Work Order: 938059 **Meter:** 0 **In Date:** 05/21/2009 **Closed:** 05/21/2009
Problem: PRE-DELIVERY INSPECTION

Work Completed

- Pre-delivery Inspection

Hours: 2.00 Comm: 0.00 Labor: 120.00 Parts: 0.00 Total: 120.00

Work Order: 938496 **Meter:** 309 **In Date:** 06/01/2009 **Closed:** 06/04/2009
Problem: DUPLICATE AND PROGRAM KEY

Work Completed

- Duplicate & Program Keys
- Shop Supplies

Parts Issued

Quantity

164-r0475 Ign Key 2010-earlier (don't Reorder) 1.00

164-r0475 Ign Key 2010-earlier (don't Reorder) 1.00

Shop Supplies 1.00

Hours: 1.50 Comm: 0.00 Labor: 90.00 Parts: 44.90 Total: 134.90

Work Order: 946311 **Meter:** 1461 **In Date:** 11/23/2009 **Closed:** 11/30/2009
Problem: P. M. Service

Work Completed

- P. M. Service
- Verify damaged pintle pin. R/r pintle pin.
- Shop Supplies

Parts Issued

Quantity

Shop Supplies 1.00

1372 Oil Filter Frm Ph2 Wix 51372 1.00

5w20 Engine Oil 8.00

1066 White Lithium (crc 05037) 1.00

18410 Pintle Pin 1.00

Hours: 3.25 Comm: 0.00 Labor: 195.00 Parts: 50.28 Total: 245.28

1/13/2025
9:41:38 AM

Palm Beach County Fleet Management Asset Maintenance History
10178881 2009 FORD F250 Pickup, 3/4 Ton

Work Order: 1401198 **Meter:** 7090 **In Date:** 02/05/2014 **Closed:** 02/26/2014
Problem: ac not working, engine lightn running rough

Work Completed

- ck ac performa sys test and found low freon recharte add uv dye and ck for leaks found no leaks at this time
- ck egine light is on scan and found code po607 send to dealer to replace pcm under warranty
- transport and pick up veicle at dealer for warranty repair defective pcm
- Shop Supplies

Parts Issued

Quantity

South Region R134a	2.00
Shop Supplies	1.00

Hours: 4.00 Comm: 0.00 Labor: 240.00 Parts: 11.84 Total: 251.84

Work Order: 1406156 **Meter:** 7624 **In Date:** 06/23/2014 **Closed:** 07/10/2014
Problem: pm, ac warm, flat tire screw front right

Work Completed

- pm
- replace pintle pin
- ck ac not working perform sys test and found low freon evacuate recharge ck for leaks and was unable to find leak at this time
- repair right fornt tire
- trace and repair wire harness for strobe
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Napa Quart 5w20	8.00
Used Fire X Refurbished	1.00
Napagold Fuel Filter	1.00
Wiper Blade	2.00
Pintle Pin W/chain	1.00
South Region R134a	1.00
Shop Supplies	1.00

Hours: 9.50 Comm: 0.00 Labor: 570.00 Parts: 74.21 Total: 644.21

Work Order: 1500391 **Meter:** 8063 **In Date:** 01/12/2015 **Closed:** 01/15/2015
Problem: pm

Work Completed

- pm
- rr pintal pin
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Napa Quart 5w20	8.00
Wiper Blade	2.00
Pintle Pin W/chain	1.00
Shop Supplies	1.00

Hours: 3.00 Comm: 0.00 Labor: 180.00 Parts: 46.94 Total: 226.94

1/13/2025
9:41:38 AM

Palm Beach County Fleet Management Asset Maintenance History
10178881 2009 FORD F250 Pickup, 3/4 Ton

Work Order: 1503660 **Meter:** 8438 **In Date:** 04/09/2015 **Closed:** 04/23/2015
Problem: A/C BLOWS WARM

Work Completed

- ck ac blows warm perform pinpoint test and foind leaking shrader valve ebacuate replace oth shrader valve recharge and leak test
- Shop Supplies

Parts Issued

Quantity

Ac Valve Core High	1.00
Valve Core	1.00
South Region R134a	2.00
Shop Supplies	1.00

Hours: 4.00 Comm: 0.00 Labor: 240.00 Parts: 35.18 Total: 275.18

Work Order: 1506507 **Meter:** 8665 **In Date:** 06/29/2015 **Closed:** 07/14/2015
Problem: pm

Work Completed

- pm
- verify need 2 tires replace two tires
- Shop Supplies

Parts Issued

Quantity

Napagold Fuel Filter	1.00
Napagold Oil Filter	1.00
Napa Quart 5w20	8.00
179636492 Lt245-75r17	2.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 4.25 Comm: 0.00 Labor: 255.00 Parts: 561.41 Total: 816.41

Work Order: 1600993 **Meter:** 9420 **In Date:** 01/28/2016 **Closed:** 02/04/2016
Problem: pm

Work Completed

- pm
- replace 2 tires mount balance add n2
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Napa Quart 5w20	8.00
22" Wiper Blade	2.00
Washer Fluid Concentr	1.00
179636492 Lt245-75r17	2.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 4.25 Comm: 0.00 Labor: 255.00 Parts: 548.94 Total: 803.94

1/13/2025
9:41:39 AM

Palm Beach County Fleet Management Asset Maintenance History
10178881 2009 FORD F250 Pickup, 3/4 Ton

Work Order: 1613069 **Meter:** 10755 **In Date:** 12/27/2016 **Closed:** 12/30/2016
Problem: PM Service.AC inop.

Work Completed

- P.m.service
- C/c A/c Inop. Replace A/c Blower Motor And Resistor, R&r Fuse
- Repair F/left Tire, Rotate And Balance All Tires, Correc N2.
- Clean Interior& Vacuum Debris From Evap.
- Shop Supplies

Parts Issued

Quantity

Napagold Air Filter	1.00
Napagold Fuel Filter	1.00
Napagold Oil Filter	1.00
Napa Quart 5w20	8.00
22" Wiper Blade	2.00
Washer Fluid Concentr	1.00
Used Fire X Refurbished	1.00
Fmx-40 Fuse	1.00
Gl Whit	2.00
Fan Motor	1.00
resistor	1.00
Shop Supplies	1.00

Hours: 9.50

Comm: 0.00

Labor: 570.00

Parts: 243.04

Total: 813.04

Work Order: 1700060 **Meter:** 10755 **In Date:** 01/03/2017 **Closed:** 01/17/2017
Problem: Noise when ac on.

Work Completed

- C/c ac makes noise.verify air not blowing cold.recover freon.found low.found leaking high and low side valves.r&r valves.vacume,add oil.add two lbs freon.verify blowing cold.no leaks.
- Shop Supplies

Parts Issued

Quantity

Ac Valve Core High	1.00
Valve Core	1.00
Freon Sr Shop	2.00
Core	1.00
Shop Supplies	1.00

Hours: 3.75

Comm: 0.00

Labor: 225.00

Parts: 39.10

Total: 264.10

1/13/2025
9:41:39 AM

Palm Beach County Fleet Management Asset Maintenance History
10178881 2009 FORD F250 Pickup, 3/4 Ton

Work Order: 1709876 **Meter:** 12033 **In Date:** 10/10/2017 **Closed:** 10/18/2017
Problem: Dead battery.Has to jump start

Work Completed

Parts Issued

Quantity

- Test starting and charging system.battery failed loadtest.replace bad battery.
- Shop Supplies

Battery	1.00
Shop Supplies	1.00

Hours: 0.75 Comm: 0.00 Labor: 45.00 Parts: 130.64 Total: 175.64

Work Order: 1800695 **Meter:** 12517 **In Date:** 01/19/2018 **Closed:** 01/31/2018
Problem: P.M.SERVICE, REPAI TOOL BOX.

Work Completed

Parts Issued

Quantity

- Pm Service.
- Replace 6 way socket and harness.
- Replace tool box struts.
- Rotate and balance four tires.repaired left rear tire.
- R/r right tail lamp lens drill hole to drain moisture.
- Shop Supplies

Napagold Oil Filter	1.00
Napagold Fuel Filter	1.00
Napa Quart 5w20	8.00
22" Wiper Blade	2.00
Washer Fluid Concentr	1.00
Drain Plug	1.00
Used Fire X Refurbished	1.00
trailer plug	1.00
Wire Term 16-14 Blt	10.00
Dielect Silicone Comp	1.00
Support	2.00
Shop Supplies	1.00

Hours: 9.00 Comm: 0.00 Labor: 540.00 Parts: 145.72 Total: 685.72

1/13/2025
9:41:39 AM

Palm Beach County Fleet Management Asset Maintenance History
10178881 2009 FORD F250 Pickup, 3/4 Ton

Work Order: 1807459 **Meter:** 13178 **In Date:** 07/23/2018 **Closed:** 07/30/2018
Problem: PM Service.

Work Completed

- Pm Service.
- Replace pintle pin.
- Repair right side headlight.
- C/s Ac not cold.verify concern.perform system pressure test and leak test and found leaking schrader valve.evacuate replace both valves.recharge and leak test system.
- Rotate and balance tires.
- Shop Supplies

Parts Issued

Quantity

Napa Quart 5w20	8.00	
Napagold Oil Filter	1.00	
22" Wiper Blade	2.00	
Washer Fluid Concentr	1.00	
Pintle Pin W/clip	1.00	
Halogen Sealed Beams	1.00	
High Side Schrader Valve	1.00	
Non-chlor Brake Clnr	1.00	
Freon Sr Shop	2.00	
E8 A/c Oil Univ W Dye	1.00	
A/c Service Port	1.00	
Shop Supplies	1.00	
Labor: 495.00	Parts: 115.67	Total: 610.67

Hours: 8.25

Comm: 0.00

Work Order: 1902066 **Meter:** 14441 **In Date:** 02/25/2019 **Closed:** 02/28/2019
Problem: PM Service Missing gas cap.

Work Completed

- Pm Service.
- Mount two tires.rotate and balance 4 tires.
- Replace missing gas cap.
- Vacume debris from engine bay.
- Service battery hold down and tray.
- Shop Supplies

Parts Issued

Quantity

Used Fire X Refurbished	1.00	
Napa Quart 5w20	8.00	
Napagold Oil Filter	1.00	
22" Wiper Blade	2.00	
Washer Fluid Concentr	1.00	
179636492 Lt245-75r17	2.00	
Gas Cap Non-locking	1.00	
Shop Supplies	1.00	
Tire Disposal Fee	2.00	
Labor: 435.50	Parts: 587.64	Total: 1,023.14

Hours: 6.50

Comm: 0.00

1/13/2025
9:41:39 AM

Palm Beach County Fleet Management Asset Maintenance History
10178881 2009 FORD F250 Pickup, 3/4 Ton

Work Order: 2404049 **Meter:** 27486 **In Date:** 04/24/2024 **Closed:** 05/28/2024
Problem: PM Service.

Work Completed

- Preventive Maint. Service
- Verify tires are worn. Replace 4 tires, mount, balance, correct Nitrogen levels.
- Verify right hand tail light bulb is out, replace 3157 tail light bulb.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Napa Quart 5w20	8.00
Washer Fluid Concentr	1.00
Wiper Blade	2.00
Napagold Fuel Filter	1.00
Napagold Air Filter	2.00
Tire Lt245/75/17 Mich	4.00
Boxed Miniatures	1.00
Shop Supplies	1.00
Tire Disposal Fee	4.00

Hours: 4.75 Comm: 0.00

Labor: 346.75 Parts: 1,210.20 Total: 1,556.95

Work Order: 2410019 **Meter:** 28274 **In Date:** 10/18/2024 **Closed:** 10/22/2024
Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00 Comm: 0.00

Labor: 146.00 Parts: 0.00 Total: 146.00

Total Hours: 195.25

Total Labor: 12,505.00

Total Comm: 0.00

Total Parts: 8,373.57