Total Hours:	148.80 Labor: 10,42	3.90	Parts: 9,154.24	Comm: 6,192.29		Charged	: 25770.43	
Work Order: Problem:	1700828 1061 - Pre Delivery In	Meter: spection	311		In Date:	01/26/2017	Closed:	01/26/2017
Work Com	npleted							
- Pre Deliv	very Inspection							
	Hours: 2.00		Comm: 0.00	Labor: 120.00	Parts: 0.0	0	Total:	120.00
Work Order: Problem:	1703114 DEAD BATTERY	Meter:	2294		In Date:	03/29/2017	Closed:	03/30/2017
Work Com	npleted			Parts Issued			Qı	uantity
	art vehicle from Wud pa ystem.found no probler	0	Recharge battery Test battery and time	Shop Supplies				1.00
- Shop Su	pplies							
	Hours: 1.00		Comm: 0.00	Labor: 60.00	Parts: 2.0	0	Total:	62.00
Vork Order: Problem:	1705993 Pm Service	Meter:	6465		In Date:	06/16/2017	Closed:	06/26/2017
Work Com	npleted			Parts Issued			Qı	uantity
- Pm Servi	ice			Napa Quart 5w20				7.00
- Rotate a	nd balance tires.			Napagold Oil Filter				1.00
- Shop Su	pplies			Washer Fluid Concer	ntr			1.00
				Shop Supplies				1.00
	Hours: 2.75		Comm: 0.00	Labor: 165.00	Parts: 33.	11	Total	198.44

Work Order: 1709555 Meter: 11760 Problem: P.M.SERVICE,LOW PRESSURE PASSENGER REAR TIRE

In Date: 09/29/2017 Closed: 10/10/2017

Work Com	npleted		Parts Issued			Qı	antity
- Pm Servi	ice		Napagold Oil Filter				1.00
- Mount c	one new tire to the right front.rota	te and balance all four.	Napa Quart 5w20				7.00
- Shop Su	pplies		Napagold Air Filter				1.00
			22" Wiper Blade				2.00
			Washer Fluid Conce	ntr			1.00
			245/70/17 Tire Mich			1.00	
			Napagold Oil Filter		1.00		
			Napagold Air Filter				1.00
			Shop Supplies				1.00
			Tire Disposal Fee				1.00
	Hours: 3.50	Comm: 0.00	Labor: 210.00	Parts: 348	3.46	Total:	558.46
Vork Order: Problem:	1710989 PASSENGER REAR TIRE.	Meter: 13606		In Date:	11/06/2017	Closed:	11/13/201
Work Con	npleted		Parts Issued			Qı	antity
- Repair a	nd balance right rear tire.		Shop Supplies				1.00
- Shop Su	pplies						
	Hours: 1.00	Comm: 0.00	Labor: 60.00	Parts: 2.0	0	Total:	62.00
	1710006	15030		In Date:	12/13/2017	Cleased	12/28/201
Nork Order: Problem:	Bad battery has to jump start.Ri	Meter: 15070 ght side mirror broken.		in Date.	12/10/2011	Closed:	12,20,201
	Bad battery has to jump start.Ri		Parts Issued	in Date.	12,10,2017		antity
Problem: Work Con	Bad battery has to jump start.Ri	ght side mirror broken.	Parts Issued Lamp Asy	in Date.	12,10,2011		
Problem: Work Con - Replace	Bad battery has to jump start.Ri	ght side mirror broken.		in Date.	12,10,2011		antity
Problem: Work Con - Replace	Bad battery has to jump start.Rig npleted broken right side mirror assembly rt vehicle to and from dealer for re	ght side mirror broken.	Lamp Asy	in Date.	12,10,2011		iantity 1.00

1/13/2025 9:40:03 AN			nty Fleet Managem 7 FORD F150 Picku	nent Asset Maintenan up, 1/2 Ton	nce History			
Work Order: Problem:	1801948 PM Service	Meter:	18117		In Date:	02/20/2018	Closed:	02/26/2018
Work Com	pleted			Parts Issued			Qı	uantity
- Pm Servi	ce.			Napagold Oil Filter				1.00
- Replace	both front tires.replace ri	ght rear tire with spar	e tire.put old right	Napa Quart 5w20				7.00
	spare rim.balance all four			Washer Fluid Concer		1.00		
- Shop Su	oplies			Used Fire X Refurbis	1.00			
				183114470 P245-70)r17			2.00
				Shop Supplies				1.00
				Tire Disposal Fee				2.00
	Hours: 4.50		Comm: 0.00	Labor: 270.00	Parts: 463	3.73	Total:	733.73
Work Order: Problem: Work Com	PM Service	Meter:	18117		In Date:	02/20/2018	Closed:	
-	Hours: 0.00		Comm: 0.00	Labor: 0.00	Parts: 0.0	0	Total:	0.00
Nork Order: Problem:	1805643 P M Service.	Meter:	23184		In Date:	06/04/2018	Closed:	06/18/2018
Work Com	pleted			Parts Issued			Qu	uantity
- Pm Servi	се			Napa Quart 5w20				7.00
- Rotate a	nd balance tires.			Napagold Oil Filter				1.00
- Shop Su	oplies			22" Wiper Blade				2.00
				Washer Fluid Concer	ntr			1.00
				Shop Supplies				1.00
	Hours: 2.75		Comm: 0.00	Labor: 165.00	Parts: 42.	13	Total:	207.13

Work Order: 1809750 Meter: Problem: Left front tire flatTrailer plug inop.	27434		In Date:	09/20/2018	Closed:	09/27/2018
Work Completed		Parts Issued			Qı	uantity
- Repair and balance left front tire.		Shop Supplies				1.00
- Diagnose and repair for trailer wiring fault message or	n dash.					
- Shop Supplies						
Hours: 2.50	Comm: 0.00	Labor: 150.00	Parts: 2.0	00	Total:	152.00
Work Order:1810427Meter:Problem:P.M.SERVICE	28296		In Date:	10/10/2018	Closed:	10/22/2018
Work Completed		Parts Issued			Qı	uantity
- Pm Service.		Napagold Oil Filter				1.00
- Resurface rear rotors.service calipers and replace pads.		Napa Quart 5w20				7.00
- Shop Supplies		Washer Fluid Conce	ntr			1.00
		22" Wiper Blade				2.00
		Used Fire X Refurbis	hed			1.00
		Brake Pad				1.00
		Non-chlor Brake Cln	r			1.00
		Shop Supplies				1.00
Hours: 7.00	Comm: 0.00	Labor: 469.00	Parts: 138	8.68	Total:	607.68
Work Order:1901726Meter:Problem:PM Service	34032		In Date:	02/13/2019	Closed:	02/25/2019
Work Completed		Parts Issued			Qı	uantity
- Pm Service.		Napa Quart 5w20				7.00
- Rotate and balance all tires.relearn Tpms.correct N2.		Napagold Oil Filter				1.00
- Shop Supplies		Used Fire X Refurbis	hed			1.00
		Shop Supplies				1.00
Hours: 3.25	Comm: 0.00	Labor: 217.75	Parts: 48.	.99	Total:	266.74

Work Order: 1 Problem: p	1905991 o.m.service, l/rear tire low	Meter: 38323		In Date:	06/06/2019	Closed:	06/26/2019
Work Comp	leted		Parts Issued			Qu	uantity
- Pm Service	2.		Napa Quart 5w20				7.00
- Replace fo	ur tires.		Napagold Oil Filter		1.00		
- Resurface	front rotors.service calipers	and replace brake pads.	22" Wiper Blade		2.00		
- Shop Supp			Washer Fluid Conce	entr			1.00
			Napagold Air Filter	~			1.00
			183114470 P245-7	0r17			4.00
			Brake Pad				1.00
			Shop Supplies				1.00
			Tire Disposal Fee				4.00
	Hours: 8.50	Comm: 0.00	Labor: 569.50	Parts: 930	0.08	Total:	1,499.58
ork Order: 7 Problem: 7	1908842 Ac inop.Radio inop.	Meter: 41241		In Date:	08/23/2019	Closed:	09/27/2019
Work Comp	leted		Parts Issued			Qu	uantity
- Computer	diagnose with Ids.codes U0	256 lost communication with Ficm	Fcim				1.00
and U0164 lost communication with Hvac.pin point test and confirm short internally in Ficm.replace Ficm and reprogram Ok.			Shop Supplies				1.00
- Shop Supp	blies						
	Hours: 4.50	Comm: 0.00	Labor: 301.50	Parts: 452	2.22	Total:	753.72

Work Order:1912923Meter:43615Problem:PM Service.Check tires.TPMS warning light on.

In Date: 12/18/2019 **Closed:** 12/26/2019

Work Completed			Parts Issued			Qı	uantity	
- Pm Service.			Used Fire X Refurbish	ned			1.00	
- Rotate and balance 4 tires.			Napagold Oil Filter				1.00	
- Repaired right rear tire and reset Tpms.			Napa Quart 5w20				7.00	
- Service tool box and adjust latches to close	e properly.		Washer Fluid Concer	ntr			1.00	
- Clean engine compartment.			22" Wiper Blade		2.00			
- Shop Supplies			Macs Battery Cleaner		1.00			
			Shop Supplies			1.00		
Hours: 5.25		Comm: 0.00	Labor: 383.25	Parts: 66.	69	Total:	449.94	
Work Order: 2001424 Problem: Right front tire flat.	Meter:	46680		In Date:	02/10/2020	Closed:	02/18/2020	
Work Completed			Parts Issued			Qı	uantity	
- Repair and balance right front tire.nitrogen fill all and reset Tpms.			Shop Supplies				1.00	
- Shop Supplies								
Hours: 1.00		Comm: 0.00	Labor: 73.00	Parts: 4.0	0	Total:	77.00	
Nork Order: 2003725 Problem: PM Service.Light bar inop.	Meter:	50300		In Date:	04/14/2020	Closed:	04/27/2020	
Work Completed			Parts Issued			Qu	uantity	
- Pm Service.			Napa Quart 5w20				7.00	
- Check and replace light bar controller.			Napagold Oil Filter				1.00	
- Replace leaking rear shocks.			22" Wiper Blade				2.00	
- Shop Supplies			Washer Fluid Concer	ntr			1.00	
			Napagold Air Filter				1.00	
			Lighted Switchbox				1.00	
			Rearshock				2.00	
			Shop Supplies				1.00	
Hours: 4.50		Comm: 0.00	Labor: 328.50	Parts: 366	\$ 75	Total	695.25	

Work Order: Problem:	2004301 Safety recalls # 17S33 and 18S	Meter:	50792		In Date:	04/29/2020	Closed:	05/11/2020
		21					•	
Work Com	pleted			Parts Issued			Qı	uantity
- Transpor	t vehicle to and from dealer for s	afety recalls #	17s33 and 18s27	Shop Supplies				1.00
- Shop Sup	oplies							
	Hours: 2.00		Comm: 0.00	Labor: 146.00	Parts: 4.0	0	Total:	150.00
Nork Order: Problem:	2006631 Has to jump start all the time.Na	Meter: ail in right fron			In Date:	07/06/2020	Closed:	07/17/2020
Work Com	pleted			Parts Issued			Qı	uantity
- Test start	ting and charging system.battery	failed loadtes	t after	Battery				1.00
	place bad battery.			Shop Supplies				1.00
- Repair ar	nd balance right front tire.							
- Shop Sup	oplies							
	Hours: 2.00		Comm: 0.00	Labor: 146.00	Parts: 148	3.86	Total:	294.86
Work Order: Problem:	2007417 Driver front and rear tires flat.Ta	Meter: aillight inop.	55658		In Date:	07/28/2020	Closed:	08/17/2020
Work Com	pleted			Parts Issued			Qı	uantity
- Repair fro	ont and rear feft side tires.balanc	e both.		Shop Supplies				1.00
- Check ov	ver tail lights,clean sockets.							
- Shop Sup	oplies							
	Hours: 3.00		Comm: 0.00	Labor: 219.00	Parts: 4.0	0	Total:	223.00

1/13/2025 9:40:03 AM

Palm Beach County Fleet Management Asset Maintenance History102021482017 FORD F150 Pickup, 1/2 Ton

Work Order: 2008294 Problem: PM Service.	Meter:	55777		In Date:	08/19/2020	Closed:	08/31/2020
Work Completed			Parts Issued			Qı	antity
- Pm Service.			Napagold Oil Filter				1.00
- Replace and balance four tires.			Napa Quart 5w20				7.00
- Install how is my driving decal.			Washer Fluid Concer	ntr			1.00
- Shop Supplies			22" Wiper Blade				2.00
			245/70/17tire Coop				4.00
			Shop Supplies				1.00
			Tire Disposal Fee				4.00
Hours: 4.25		Comm: 0.00	Labor: 310.25	Parts: 948	3.32	Total:	1,258.57
Nork Order: 2012024 Problem: PM Service.	Meter:	61223		In Date:	12/02/2020	Closed:	12/17/202
Work Completed			Parts Issued			Qı	antity
- Preventive Maint. Service			Napa Quart 5w20				7.00
- repair rear brakes.			Napagold Oil Filter				1.00
- replace right front wheel bearings			Washer Fluid Concer	ntr			1.00
- rotate and balance tires.			22" Wiper Blade				2.00
- replace asset number.			Used Fire X Refurbis	hed			1.00
- Shop Supplies			B Fluid Dot 3-32oz				1.00
			Brake Rotor				2.00
			Non-chlor Brake Cln	r			1.00
			Brake Pad				1.00
			Hub Assy Wheel				1.00
			Shop Supplies				1.00
			Shop Supplies				1.00

1/13/2025 9:40:03 AM

Palm Beach County Fleet Management Asset Maintenance History102021482017 FORD F150 Pickup, 1/2 Ton

Work Order: Problem:	2102380 Right rear tire flat.	Meter:	65824		In Date:	03/02/2021	Closed:	03/04/2021
Work Com	npleted			Parts Issued			Qu	antity
- Repair ar	nd balance right rear tire.			Shop Supplies				1.00
- Shop Su	pplies							
	Hours: 1.00		Comm: 0.00	Labor: 73.00	Parts: 4.00	0	Total:	77.00
Work Order: Problem:	2103634 PM SERVICE	Meter:	67585		In Date:	03/30/2021	Closed:	04/02/2021
Work Com	npleted			Parts Issued			Qı	antity
- Preventiv	ve Maint. Service			Napa Quart 5w20				7.00
- Replace	cabin air filter.			Napagold Oil Filter				1.00
- Shop Su	pplies			Washer Fluid Concer	ntr			1.00
				22" Wiper Blade				2.00
				Cabin Air Filter				1.00
				Shop Supplies				1.00
	Hours: 2.50		Comm: 0.00	Labor: 182.50	Parts: 60.6	67	Total:	243.17
Work Order: Problem:	2104965 Brake lights inop.Left rear tire flat.	Meter:	69690		In Date:	05/04/2021	Closed:	05/06/2021
Work Com	npleted			Parts Issued			Qı	antity
- Test and	replace both brake lamp bulbs.			Boxed Miniatures				2.00
- Repair ar	nd balance left rear tire.nitrogen fill a	all.		Shop Supplies				1.00
- Shop Su	pplies							
	Hours: 1.50		Comm: 0.00	Labor: 109.50	Parts: 5.53	3	Total:	115.03
						05/27/2021	Cleased	06/03/2021
	2105900 Ignition key broken.	Meter:	71261		In Date:	05/27/2021	Closed:	00/03/2021
	Ignition key broken.	Meter:	71261	Parts Issued	In Date:	05/27/2021		uantity
Problem: Work Com	Ignition key broken.			Parts Issued ford side key	In Date:	03/27/2021		
Problem: Work Com	Ignition key broken. •pleted and program a new ignition key and				In Date:	03/27/2021		antity
Problem: Work Com - Replace a	Ignition key broken. •pleted and program a new ignition key and			ford side key	In Date:	03/27/2021		iantity 1.00
Work Com - Replace a	Ignition key broken. •pleted and program a new ignition key and			ford side key Tool Box Key	In Date: Parts: 106		Qu	1.00

1/13/2025
9:40:03 AM

Palm Beach County Fleet Management Asset Maintenance History102021482017 FORD F150 Pickup, 1/2 Ton

Work Order: 2106 Problem: PM		Meter: 7	72345		In Date:	06/18/2021	Closed:	06/22/202
Work Complete	ed			Parts Issued			Qı	uantity
- Preventive Ma	int. Service			22" Wiper Blade				2.00
- Rotate/balanc	ed 4 Tires			Washer Fluid Concer	ntr			1.00
- Wash Vehicle	And Clean Debris From Er	ngine Compartme	ent	Napa Quart 5w20				7.00
- Shop Supplies		5		Napagold Oil Filter				1.00
				Napagold Air Filter				1.00
				Shop Supplies				1.00
	Hours: 4.00	(Comm: 0.00	Labor: 292.00	Parts: 58.	35	Total:	350.35
Work Order: 2109 Problem: PM		Meter: 7	77216		In Date:	09/13/2021	Closed:	09/21/202
Work Complete	ed			Parts Issued			Qı	uantity
- Pm Service				22" Wiper Blade				2.00
- replaced cabir	n air filter and clean air co	wl intake system		Washer Fluid Concer	ntr			1.00
- rotate/balance	ed 4 tires			Napagold Oil Filter				1.00
- serviced and a	djusted tool box latches t	to close properly		Napa Quart 5w20				7.00
- Shop Supplies				Cabin Filter				1.00
				Shop Supplies				1.00
	Hours: 4.25	(Comm: 0.00	Labor: 310.25	Parts: 56.	57	Total:	366.82
Work Order: 2113 Problem: Nail	3086 in Right Rear Tire, light b	Meter: 8 par not working	81560		In Date:	12/10/2021	Closed:	12/17/202
Work Complete	ed			Parts Issued			Qı	uantity
- Repair right re	ar tire.nitrogen fill all.rese	et Tpms		Shop Supplies				1.00
- Test for power	r and ground.replace oper	n fuse.test operat	ion ok					
- Shop Supplies								
	Hours: 2.00	(Comm: 0.00	Labor: 146.00	Parts: 2.6	5	Total:	148.65

Palm Beach County Fleet Management Asset Maintenance History102021482017 FORD F150 Pickup, 1/2 Ton

Meter: 82506

Work Order: 2200247 Problem: PM Service.

In Date: 01/07/2022 Closed: 01/31/2022

Total: 526.62

Work Completed		Parts Issued			0	uantity	
- Preventive Maint. Service		Napa Quart 5w20			4	7.00	
		Filter			1.00		
 Verify needs 4 tires. Replace tires, mount, balance a relearn Tpms. 	add 36 PSI of Nitrogen,	Used Fire X Refurbish	ned		1.00		
- Verify right rear tail light is out. Replace tail light b	ulb.	22" Wiper Blade			2.00		
- Verify coolant reservoir is not venting and collapsir						4.00	
coolant reservoir and cap, top off coolant level, evacu		Boxed Miniatures				1.00	
system. Test drive to verify fix.		Rad Cap	1.00				
- Shop Supplies		Rotell Elc Antifeerze				1.00	
	Tank Assy				1.00		
		Shop Supplies				1.00	
		Tire Disposal Fee				4.00	
Hours: 6.50	Comm: 0.00	Labor: 474.50	Parts: 98	3.62	Total:	1,458.12	
ork Order: 2204269 Me	eter: 87164		In Date:	04/22/2022	Closed:	05/26/20	
Problem: PM Service.							
Work Completed		Parts Issued			Q	uantity	
- Preventive Maint. Service		White Lithium Grease	e			1.00	
- Install steering wheel cover & floor mats.		Napagold Oil Filter				1.00	
- Diagnose light bar was not working, perform pinpo	pint test, disassembly	Napa Quart 5w20				7.00	
light bar & found bad Io board, replace Io board.		Washer Fluid Concer	ntr			1.00	
- Replace how's my driving decal.		22" Wiper Blade				2.00	
- Fill all tires with nitrogen, balance, rotate & reset T	pms.	Floor Mats				1.00	
- Shop Supplies		Steering Wheel Cove	er Large			1.00	
		Shop Supplies				1.00	

Hours: 6.00

Comm: 0.00

Labor: 438.00

Parts: 88.62

Palm Beach County Fleet Management Asset Maintenance History 2017 FORD F150 Pickup, 1/2 Ton 10202148

Meter: 88835

Work Order: 2210443 Problem: PM Service. Battery

10/12/2022 **Closed:** 10/27/2022 In Date:

Work Completed		Parts Issued	Quantity	
- Preventive Maint. Service		Napagold Oil Filte	1.00	
 Jump start in Wud lot. Recharged /test battery replaced failed battery rotate balanced 4 tires prep rear bumper to replaced missing how's my driving sticker Shop Supplies 		Motor Oil	7.00	
		Washer Fluid Con		
		22" Wiper Blade	2.00	
		Napagold Air Filter		1.00
		Battery		1.00
		Shop Supplies		1.00
Hours: 4.50	Comm: 0.00	Labor: 328.50	Parts: 197.46	Total: 525.96
ork Order: 2303671	Meter: 93052		In Date: 04/12/2023	Closed: 04/25/20

Work Order: 2303671 Problem: PM Service.

Work Completed

- Preventive Maint. Service
- clean debris from air cowl system and replaced dirty cabin filter
- diagnose wipers won't shut off . replaced wiper switch
- replaced rear brake pads and rotors. serviced calipers and slides
- R&r coolant reservoir and replaced leaking water pump thermostat assy. and heater hoses
- performed coolant system flush
- Shop Supplies

Parts Issued		Quantity		
Used Fire X Refurbished		1.00		
22" Wiper Blade		2.00		
Washer Fluid Cond	centr	1.00		
Napa Quart 5w20		7.00		
Napagold Oil Filte	r	1.00		
Cabin Air Filter		1.00		
Rotor		2.00		
Non-chlor Brake C	Inr	2.00		
Brake Pad		1.00		
Thermostat Housi	ng Assembly	1.00		
Water Pump		1.00		
Coolent		2.00		
Heater Hose		1.00		
Hea Hose		1.00		
Wiper Switch		1.00		
Shop Supplies		1.00		
Labor: 985.50	Parts: 788.84	Total: 1,774.34		

Palm Beach County Fleet Management Asset Maintenance History 10202148 2017 FORD F150 Pickup, 1/2 Ton

Work Order: 2307973 Meter: 97960 08/10/2023 Closed: 08/24/2023 In Date: Problem: PM Service. Parts Issued Quantity **Work Completed** Napagold Oil Filter 1.00 - Preventive Maint, Service Napa Quart 5w20 7.00 - Tpms light was on, test & found bad right rear tmps sensor. Replace sensor, fill all tires with nitrogen, balance, rotate, & reset Tpms. Washer Fluid Concentr 1.00 - Left rear brake light lens was broken & had water in leaking in. Replace 22" Wiper Blade 2.00 lens & reinstall strobe light. **Tpms Sensor** 1.00 - Service front rotors, calipers, replace brake pads & bleed air from system. Brake Pad 1.00 - Test drive after brake repair to "garnish" new pads to rotors. Brake Fl-dot 3-4 32oz 1.00 - Shop Supplies 1.00 Lamp Assy Brake Fluid Cap 1.00 1.00 Shop Supplies Hours: 8.25 Comm: 0.00 Labor: 602.25 Parts: 255.03 Total: 857.28 Work Order: 2309376 Meter: 99158 09/14/2023 **Closed:** 09/14/2023 In Date: Problem: Tire going flat on left rear tire Parts Issued Quantity Work Completed 1.00 - c/c right rear tire flat. Remove nail from tire, dismount and repair right rear Shop Supplies tire Correct all Nitrogen levels to 35 Psi. - Shop Supplies Hours: 1.00 Comm: 0.00 Labor: 73.00 Parts: 2.65 Total: 75.65 Work Order: 2401780 Meter: 101726 In Date: 02/15/2024 **Closed:** 02/26/2024 **Problem:** needs 2 spare keys Parts Issued **Work Completed** Quantity ford side key 2.00 - order and program 2 extra keys Shop Supplies 1.00 - Shop Supplies Hours: 1.00 Comm: 0.00 Labor: 73.00 Parts: 122.24 Total: 195.24

Work Completed		Parts Issued		Qı	Quantity	
- Preventive Maint. Service		Napagold Oil Filter			1.00	
- Inspect & R & i four new tires, speed balance, nitro fill		5w20 Engine Oil			7.00	
- Perform battery analyzing load & charging system test, battery failed, R & i new battery . Reset Bsm with scan tool		Washer Fluid Concentr			1.00	
		Wiper Blade			2.00	
- Check circuit for left rear tail light and strobe R $\&$ i bulb and strobe light		Used Fire X Refurbished			1.00	
switch	245/70/17 Tire Mich			4.00		
- Shop Supplies	Battry Motorcraft			1.00		
	Led Rocker Switch Round			1.00		
		Boxed Miniatures			1.00	
		Shop Supplies			1.00	
		Tire Disposal Fee			4.00	
Hours: 6.00	Comm: 0.00	Labor: 438.00	Parts: 1,018.94	Total:	1,456.94	
ork Order: 2402248 Problem: 1 - Detail Vehicle Wash Ticket(s) I	Meter: 101847 Issued WO: 2401856 for: ashle	y elbers	In Date: 02/29/202	24 Closed:	03/01/202	
Work Completed						
- 1 - Detail Vehicle Wash Ticket(s) Issued Wo:	2401856 for: ashley elbers					
Hours: 0.00	Comm: 90.40	Labor: 0.00	Parts: 0.00	Total	90.40	

Work Order: 2407354 **Meter:** 106723 07/31/2024 Closed: 08/06/2024 In Date: Problem: PM Service and Damage on lower passenger door (accident reproted) :rumbling sound around 45mph? Tire pressure light on Parts Issued Work Completed Quantity Napagold Oil Filter 1.00 - Preventive Maint. Service complete Road test from noise only noise heard was wind noise from damage and light bar 5w20 Engine Oil 6.00 - check tire sensor ,sop r&r two front sensor, nitro fill ,balance and rotate all Wiper Blade 2.00 4 tires 2.00 Tpms Sens Kit - check, sop and r&r defective trailer plug connector and fabricated wires as Trailer Connector Truck Side 1.00 needed Lamp Assy 1.00 - check, sop and r&r crack/damaged r/r tail assembly, drill and reinstalled Shop Supplies 1.00 strobes light and verify normal operation - Shop Supplies Hours: 5.80 Comm: 0.00 Labor: 423.40 Parts: 240.61 Total: 664.01 Work Order: 2408791 **Meter:** 106723 08/06/2024 **Closed:** 09/11/2024 In Date: **Problem:** Damage-to right side of bed, cab, door & step Work Completed - Damage-to right side of bed, cab, door & step Hours: 0.00 Comm: 6,101.89 Labor: 0.00 Parts: 0.00 Total: 6,101.89 Work Order: 2410949 **Meter:** 109313 **In Date:** 11/15/2024 **Closed:** 11/15/2024 **Problem:** Transition Prep Charge **Work Completed** - Transition Prep Charge Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 0.00 Total: 146.00 Total Comm: 6,192.29 Total Hours: 148.80 Total Labor: 10,423.90 Total Parts: 9,154.24