

3/28/2025
12:02:59 PM

Palm Beach County Fleet Management Asset Maintenance History
10214931 2021 FORD EXPLORER Suv, Lg Mid Size, 4X4

Total Hours: 98.40 Labor: 7,183.20 Parts: 4,582.03 Comm: 1,638.32 Charged: 13403.55

Work Order: 2011668 **Meter:** 309 **In Date:** 11/23/2020 **Closed:** 11/24/2020
Problem: pre delivery inspection

Work Completed

Parts Issued

Quantity

- pre delivery inspection
- Shop Supplies

Shop Supplies 1.00

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 4.00 Total: 150.00

Work Order: 2012048 **Meter:** 312 **In Date:** 12/03/2020 **Closed:** 12/09/2020
Problem: Install floor mats, steering wheel cover , window vent visors and supplied computer stand .

Work Completed

Parts Issued

Quantity

- Fabricate and install window vent shades and floor mats and steering wheel cover .
- Shop Supplies

Floormat 1.00

Steering Wheel Cover Large 1.00

Kit Window Vent 1.00

Shop Supplies 1.00

Hours: 1.00 Comm: 0.00 Labor: 73.00 Parts: 195.67 Total: 268.67

Work Order: 2102547 **Meter:** 5390 **In Date:** 03/05/2021 **Closed:** 03/11/2021
Problem: Roads John, vehicle will be turn in for PM, install computer stand, hardwire a power converter and to be detailed.

Work Completed

Parts Issued

Quantity

- Preventive Maint. Service
- Rotate and speed balance all four, nitro fill
- Check and assemble and install computer stand, Hard wire electrical Invertor , restrig wiring to under hood battery
- Shop Supplies

Napagold Oil Filter 1.00

5w20 Engine Oil 6.00

Washer Fluid Concentr 1.00

Used Fire X Refurbished 1.00

Primary Wire 3.00

Shop Supplies 1.00

Hours: 8.75 Comm: 0.00 Labor: 638.75 Parts: 41.74 Total: 680.49

3/28/2025
12:02:59 PM

Palm Beach County Fleet Management Asset Maintenance History
10214931 2021 FORD EXPLORER Suv, Lg Mid Size, 4X4

Work Order: 2102740 **Meter:** 5330 **In Date:** 03/10/2021 **Closed:** 03/10/2021
Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued

Hours: 0.00 Comm: 96.00 Labor: 0.00 Parts: 0.00 Total: 96.00

Work Order: 2107012 **Meter:** 10627 **In Date:** 06/25/2021 **Closed:** 06/29/2021
Problem: PM Service. John , needs to be detail and needs wiper

Work Completed

- Preventive Maint. Service
- Rotate and speed balance all , nitro fill
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
Washer Fluid Concentr	1.00
Wiper Blade	1.00
Wiper Blade	1.00
Wiper Blade	1.00
Shop Supplies	1.00

Hours: 3.75 Comm: 0.00 Labor: 273.75 Parts: 86.53 Total: 360.28

Work Order: 2107115 **Meter:** 10457 **In Date:** 06/28/2021 **Closed:** 06/28/2021
Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued

Hours: 0.00 Comm: 96.00 Labor: 0.00 Parts: 0.00 Total: 96.00

Work Order: 2109312 **Meter:** 13859 **In Date:** 08/20/2021 **Closed:** 08/26/2021
Problem: 2 - Wash ticket(s) issued

Work Completed

- 2 - Wash ticket(s) issued

Hours: 0.00 Comm: 17.97 Labor: 0.00 Parts: 0.00 Total: 17.97

3/28/2025
12:02:59 PM

Palm Beach County Fleet Management Asset Maintenance History
10214931 2021 FORD EXPLORER Suv, Lg Mid Size, 4X4

Work Order: 2109564 **Meter:** 14272 **In Date:** 09/01/2021 **Closed:** 09/01/2021
Problem: Roads, truck rear Rt. tire has a screw in it

Work Completed

Parts Issued

Quantity

- repair drivers rear tire, balance & nitro service
- Shop Supplies

Shop Supplies 1.00

Hours: 1.00 Comm: 0.00 Labor: 73.00 Parts: 2.65 Total: 75.65

Work Order: 2111768 **Meter:** 16828 **In Date:** 10/29/2021 **Closed:** 11/02/2021
Problem: PM Service. Wipers

Work Completed

Parts Issued

Quantity

- Preventive Maint. Service
- Rotate and speed balance, nitro fill
- Shop Supplies

Napagold Oil Filter 1.00

5w20 Engine Oil 6.00

Washer Fluid Concentr 1.00

Wiper Blade 1.00

Wiper Blade 1.00

Wiper Blade 1.00

Shop Supplies 1.00

Hours: 3.75 Comm: 0.00 Labor: 273.75 Parts: 62.00 Total: 335.75

Work Order: 2202294 **Meter:** 20389 **In Date:** 03/01/2022 **Closed:** 03/01/2022
Problem: right rear tire going flat

Work Completed

Parts Issued

Quantity

- Repair right rear tire and balance . Nitro fill all.
- Shop Supplies

Shop Supplies 1.00

Hours: 1.00 Comm: 0.00 Labor: 73.00 Parts: 2.65 Total: 75.65

3/28/2025
12:02:59 PM

Palm Beach County Fleet Management Asset Maintenance History
10214931 2021 FORD EXPLORER Suv, Lg Mid Size, 4X4

Work Order: 2206823 **Meter:** 31048 **In Date:** 06/28/2022 **Closed:** 06/30/2022
Problem: PM Service. Roads John, front windshield has a crack

Work Completed

- Preventive Maint. Service
- balance and rotate all 4 tire . Nitro fill all.
- Shop Supplies

Parts Issued

Quantity

Washer Fluid Concentr	1.00
21in Exactfit-beam	1.00
26in Exactfit-beam	1.00
Oil Filter	1.00
5w20 Engine Oil	6.00
Used Fire X Refurbished	1.00
White Lithium Grease	1.00
Shop Supplies	1.00

Hours: 3.75

Comm: 0.00

Labor: 273.75

Parts: 68.21

Total: 341.96

Work Order: 2206826 **Meter:** 30911 **In Date:** 06/28/2022 **Closed:** 07/07/2022
Problem: replace cracked windshield

Work Completed

- set up repairs, reasset
- Remove and replace Dmi cable
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
---------------	------

Hours: 2.00

Comm: 709.15

Labor: 146.00

Parts: 2.65

Total: 857.80

Work Order: 2207256 **Meter:** 31245 **In Date:** 07/12/2022 **Closed:** 07/13/2022
Problem: Left front seat side panel falling off

Work Completed

- Replace broken left front seat side panel .
- Shop Supplies

Parts Issued

Quantity

Shield Asm	1.00
Shop Supplies	1.00

Hours: 0.50

Comm: 0.00

Labor: 36.50

Parts: 50.89

Total: 87.39

3/28/2025
12:02:59 PM

Palm Beach County Fleet Management Asset Maintenance History
10214931 2021 FORD EXPLORER Suv, Lg Mid Size, 4X4

Work Order: 2210803 **Meter:** 39979 **In Date:** 10/21/2022 **Closed:** 10/25/2022
Problem: PM Service. will turn in today Wipers

Work Completed

- Preventive Maint. Service
- Rotate and speed balance, nitro fill
- Shop Supplies

Parts Issued

Quantity

Whl/cvr	1.00
26in Exactfit-beam	1.00
21in Exactfit-beam	1.00
Washer Fluid Concentr	1.00
11in Exactfit-rear	1.00
Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
Shop Supplies	1.00

Hours: 3.75

Comm: 0.00

Labor: 273.75

Parts: 67.43

Total: 341.18

Work Order: 2211880 **Meter:** 39983 **In Date:** 11/18/2022 **Closed:** 11/28/2022
Problem: 1 - Detail Vehicle Wash Ticket(s) Issued to: Ray Hiskell

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued to: Ray Hiskell

Hours: 0.00

Comm: 90.40

Labor: 0.00

Parts: 0.00

Total: 90.40

Work Order: 2301176 **Meter:** 47169 **In Date:** 02/03/2023 **Closed:** 02/08/2023
Problem: PM Service. and a detail, Check speedometer.

Work Completed

- Performed P.m. Service & Inspection.
- Performed Tire Rotation Balance On All 4 Wheels, Add Nitro Fill Reset Tpms.
- Check Customer Concern, Test Drove Vehicle & Connect Scan Tool Then Check For Faults. Found No Faults And Tech Could Not Duplicate Concern.compaired To Phone Gps .
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
Washer Fluid Concentr	1.00
Shop Supplies	1.00

Hours: 4.75

Comm: 0.00

Labor: 346.75

Parts: 27.36

Total: 374.11

3/28/2025
12:02:59 PM

Palm Beach County Fleet Management Asset Maintenance History
10214931 2021 FORD EXPLORER Suv, Lg Mid Size, 4X4

Work Order: 2310643 **Meter:** 69896 **In Date:** 10/20/2023 **Closed:** 10/24/2023
Problem: PM Service and a detail

Work Completed

Parts Issued

Quantity

- Preventive Maint. Service
- rotate and balance all 4 tires nitro fill all
- Shop Supplies

Oil Filter	1.00
5w20 Engine Oil	6.00
Washer Fluid Concentr	1.00
21in Exactfit-beam	1.00
26in Exactfit-beam	1.00
Shop Supplies	1.00

Hours: 3.75

Comm: 0.00

Labor: 273.75

Parts: 49.66

Total: 323.41

Work Order: 2310751 **Meter:** 69896 **In Date:** 10/25/2023 **Closed:** 10/25/2023
Problem: 1 - Detail Vehicle Wash Ticket(s) Issued WO: 2310643 for: Ray Hiskell

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued Wo: 2310643 for: Ray Hiskell

Hours: 0.00

Comm: 90.40

Labor: 0.00

Parts: 0.00

Total: 90.40

3/28/2025
12:02:59 PM

Palm Beach County Fleet Management Asset Maintenance History
10214931 2021 FORD EXPLORER Suv, Lg Mid Size, 4X4

Work Order: 2403150 **Meter:** 81063 **In Date:** 03/28/2024 **Closed:** 04/04/2024
Problem: PM Service will turn in today and needs a detail

Work Completed

Parts Issued

Quantity

- Performed P.m. Service & Inspection.
- Performed Tire Rotation & balance On All 4 Tires, Add Nitro Fill Reset Tpms.
- Both Front & Rear Brakes Below Manufac Specs, Removed All 4 Brake Pads & Rotors, Resurface Both Front Rotors, Replaced Both Rear Rotors, Install New Pads & Lubricate Caliper Slides. Bleed Entire Brake System, Test Drove Vehicle And Burnish Brakes.
- Shop Supplies

Air Filter	1.00
Brake Rotor	2.00
Brake Pad	1.00
Brake Pad	1.00
5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
Washer Fluid Concentr	1.00
Blade	1.00
21in Exactfit-beam	1.00
26in Exactfit-beam	1.00
Permatex	1.00
Brk Fluid Dot 4-32oz	1.00
Non-chlor Brake Clnr	2.00
Shop Supplies	1.00

Hours: 11.75

Comm: 0.00

Labor: 857.75

Parts: 444.21

Total: 1,301.96

Work Order: 2403315 **Meter:** 80946 **In Date:** 04/03/2024 **Closed:** 04/03/2024
Problem: 1 - Detail Vehicle Wash Ticket(s) Issued WO: 2403150 for: Ray Hiskell

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued Wo: 2403150 for: Ray Hiskell

Hours: 0.00

Comm: 90.40

Labor: 0.00

Parts: 0.00

Total: 90.40

3/28/2025
12:02:59 PM

Palm Beach County Fleet Management Asset Maintenance History
10214931 2021 FORD EXPLORER Suv, Lg Mid Size, 4X4

Work Order: 2405631 **Meter:** 89601 **In Date:** 06/07/2024 **Closed:** 06/12/2024
Problem: PM Service , need a better inverter installed and a detail

Work Completed

Parts Issued

Quantity

- Preventive Maint. Service	5w20 Engine Oil	6.00		
- Rotate and speed balance, nitro fill,	Oil Filter	1.00		
- Remove old Inverter, Fabricate & Install 1500 Watt new inverter, & Install 100 amp circuit breaker and wiring, Install Remote control switch	Washer Fluid Concentr	1.00		
- Check & replace cabin filter and clean fresh air intake duct	11in Exactfit-rear	1.00		
- Shop Supplies	22in Exactfit-beam	1.00		
	26in Exactfit-beam	1.00		
	Bulk Battery Cable	10.00		
	Bulk Battery Cable	10.00		
	Cobra 1500 Watt Power Inverter	1.00		
	Cb185-100 Cir Brkr	1.00		
	Napa Cabin Air Filter	1.00		
	Cobra Inverter Remote	1.00		
	Cabin Air Filter	1.00		
	Shop Supplies	1.00		
Hours: 8.25	Comm: 0.00	Labor: 602.25	Parts: 412.07	Total: 1,014.32

Work Order: 2405826 **Meter:** 89601 **In Date:** 06/12/2024 **Closed:** 06/12/2024
Problem: 1 - Detail Vehicle Wash Ticket(s) Issued WO: 2405631 for: Ray Hiskell

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued Wo: 2405631 for: Ray Hiskell	Hours: 0.00	Comm: 90.40	Labor: 0.00	Parts: 0.00	Total: 90.40
---	-------------	-------------	-------------	-------------	--------------

3/28/2025
12:02:59 PM

Palm Beach County Fleet Management Asset Maintenance History
10214931 2021 FORD EXPLORER Suv, Lg Mid Size, 4X4

Work Order: 2409706 **Meter:** 98793 **In Date:** 10/04/2024 **Closed:** 10/15/2024
Problem: PM Service will turn in tomorrow and needs a detail

Work Completed

- Preventive Maint. Service
- Inspect all, R & i four new tires, speed balance, nitro fill
- Inspect Axles, Left front Cv joint seal leaking, R & i new Axle
- Perform front Alignment, road test
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
Washer Fluid Concentr	1.00
11in Exactfit-rear	1.00
21in Exactfit-beam	1.00
26in Exactfit-beam	3.00
255/65r18 Hankook Kinenergy Gt	4.00
Used Fire X Refurbished	1.00
Shaft	1.00
Retainer	1.00
Shop Supplies	1.00
Tire Disposal Fee	4.00

Hours: 8.85

Comm: 0.00

Labor: 646.05

Parts: 1,220.61

Total: 1,866.66

Work Order: 2411857 **Meter:** 103888 **In Date:** 12/13/2024 **Closed:** 12/31/2024
Problem: PM Service CHASE, AND NEEDS D DEEP DETAIL WILL TURN IN TOMORROW

Work Completed

- Performed P.m. Service & Inspection.
- Performed Tire Rotation Balance On All 4 Tires, Add Nitro Fill Reset Tpms.
- Removed And Replaced Damaged Passenger Side Fender Liner Housing.
- Front Halo Bar Light Inop, Check Power And Ground, Ground & Power Source Ok, Check Signal To Halo Bar Light. No Siganl Found Corrosion Around Relay. Removed Battery Cover And Relay Then Clean Terminals, Replaced Relay Then Check.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
Shield	1.00
Relay	1.00
Shop Supplies	1.00

Hours: 5.55

Comm: 0.00

Labor: 405.15

Parts: 140.86

Total: 546.01

3/28/2025
12:02:59 PM

Palm Beach County Fleet Management Asset Maintenance History
10214931 2021 FORD EXPLORER Suv, Lg Mid Size, 4X4

Work Order: 2500061 **Meter:** 103902 **In Date:** 01/02/2025 **Closed:** 01/06/2025
Problem: 1 - Detail Vehicle Wash Ticket(s) Issued WO: 2411857 for: Ray Hiskell

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued Wo: 2411857 for: Ray Hiskell

Hours: 0.00 Comm: 86.40 Labor: 0.00 Parts: 0.00 Total: 86.40

Work Order: 2502337 **Meter:** 105444 **In Date:** 03/11/2025 **Closed:** 03/26/2025
Problem: Transmission shifting in and out of gear hard.

Work Completed

- Service transmission

- Shop Supplies

Hours: 0.00 Comm: 0.00

Parts Issued

Quantity

Mercon Ulv 1qt 12.00

Tram Filter 1.00

Shop Supplies 1.00

Labor: 0.00 Parts: 124.62 Total: 124.62

Work Order: 2502709 **Meter:** 105444 **In Date:** 03/20/2025 **Closed:** 03/21/2025
Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

- Shop Supplies

Hours: 2.00 Comm: 0.00

Parts Issued

Quantity

Shop Supplies 1.00

Labor: 146.00 Parts: 2.65 Total: 148.65

Total Hours: 98.40 Total Labor: 7,183.20 Total Comm: 1,638.32 Total Parts: 4,582.03