

3/28/2025
1:26:17 PM

Palm Beach County Fleet Management Asset Maintenance History
10201451 2016 FORD F250 Pickup, 3/4 Ton, Ext Cab

Total Hours: 144.80 Labor: 10,090.60 Parts: 8,243.89 Comm: 186.40 Charged: 18520.89

Work Order: 1609923 **Meter:** 345 **In Date:** 09/22/2016 **Closed:** 09/22/2016
Problem: 1061 - Pre Delivery Inspection

Work Completed

- Pre Delivery Inspection

Hours: 4.00 Comm: 0.00 Labor: 240.00 Parts: 0.00 Total: 240.00

Work Order: 1611330 **Meter:** 2230 **In Date:** 11/02/2016 **Closed:** 01/03/2017
Problem: Install ladder rack and floor mats and steering wheel cover.

Work Completed

- Fabricate and install ladder rack.relocate tool box.install floor mats and steering wheel cover.

- Shop Supplies

Hours: 4.50 Comm: 0.00

Parts Issued

Quantity

Ladder Rack Weekender	1.00
Floor Mat-2pc Rub Bk	1.00
Stg Wheel Cov - Ford	1.00
Shop Supplies	1.00
Labor: 270.00 Parts: 673.43 Total: 943.43	

Work Order: 1703380 **Meter:** 5653 **In Date:** 04/05/2017 **Closed:** 04/18/2017
Problem: P.M. service.

Work Completed

- P.m. Service.

- Rotate and balance titres.

- Shop Supplies

Hours: 3.75 Comm: 0.00

Parts Issued

Quantity

5w20 Engine Oil	7.00
Napagold Oil Filter	1.00
Washer Fluid Concentr	1.00
Mac Wite Lithium Gres	1.00
Used Fire X Refurbished	1.00
Shop Supplies	1.00
Labor: 225.00 Parts: 43.18 Total: 268.18	

3/28/2025
1:26:17 PM

Palm Beach County Fleet Management Asset Maintenance History
10201451 2016 FORD F250 Pickup, 3/4 Ton, Ext Cab

Work Order: 1805917 **Meter:** 13312 **In Date:** 06/11/2018 **Closed:** 07/10/2018
Problem: Check engine light..A/C not cold.

Work Completed

- Transport to and from dealer for check engine light P0355 . Tsb 18-2047.
- Fabricate and install toolbox fuel tank combo with pump .install filter kit and wiring harness with switch .
- Shop Supplies

Parts Issued

Quantity

Fab Loom-split Poly	10.00
Primary Wire	12.00
Pri/wire	12.00
Fuse Holder	1.00
Toggle Switch	1.00
2x1	1.00
Adapter	1.00
Napagold Fuel Filter	1.00
Shop Supplies	1.00

Hours: 8.00

Comm: 0.00

Labor: 480.00

Parts: 46.96

Total: 526.96

Work Order: 1807642 **Meter:** 14045 **In Date:** 07/27/2018 **Closed:** 07/30/2018
Problem: Nail in tire, right rear.

Work Completed

- Repair right rear tire and balamce . Nitrofill.
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
---------------	------

Hours: 1.00

Comm: 0.00

Labor: 60.00

Parts: 2.00

Total: 62.00

3/28/2025
1:26:17 PM

Palm Beach County Fleet Management Asset Maintenance History
10201451 2016 FORD F250 Pickup, 3/4 Ton, Ext Cab

Work Order: 1904915 **Meter:** 20650 **In Date:** 05/06/2019 **Closed:** 05/16/2019
Problem: P.M. service, trailer warning on dash and aux fuel pump low volume .

Work Completed

- P.m. service.
- Inspect and service auxiliary fuel tank . Replace filter and retest for low volume.
- Test and replace defective trailer plug connector and rewire as needed .
- Balance and rotate all four tires . Nitrofill all.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Napa Quart 5w30	8.00
Used Fire X Refurbished	1.00
22" Wiper Blade	2.00
Napagold Fuel Filter	1.00
Ford Triton Pvc Swc	1.00
trailer plug	1.00
Shop Supplies	1.00

Hours: 5.75

Comm: 0.00

Labor: 385.25

Parts: 97.55

Total: 482.80

Work Order: 2000269 **Meter:** 24494 **In Date:** 01/09/2020 **Closed:** 01/24/2020
Problem: P.M. Service.Dead battery,brakes noisy.

Work Completed

- P.m. service.
- Charge battery fully . Test battery and charging system . Battery failed load test . R&r defective battery .
- Inspect and service auxiliary fuel tank .
- Computer diagnose Abs light on , code C0034 . Perform pinpoint test . R&r right front Abs wheel speed sensor . Clear codes and test drive . Could not duplicate noise at this time .
- Rotate and high speed balance all four tires . Nitrofill all.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Napa Quart 5w30	8.00
22" Wiper Blade	2.00
Mac Wite Lithium Gres	1.00
Napagold Air Filter	1.00
Used Fire X Refurbished	1.00
Napagold Fuel Filter	1.00
Battery 65	1.00
Sensor	1.00
Shop Supplies	1.00

Hours: 8.25

Comm: 0.00

Labor: 602.25

Parts: 336.75

Total: 939.00

3/28/2025
1:26:17 PM

Palm Beach County Fleet Management Asset Maintenance History
10201451 2016 FORD F250 Pickup, 3/4 Ton, Ext Cab

Work Order: 2100891 **Meter:** 33306 **In Date:** 01/26/2021 **Closed:** 02/03/2021
Problem: P.M. service and vibration over 60 mph .

Work Completed

- Preventive Maint. Service
- Inspect and replace all four tires, speed balance , nitro fill all
- Inspect and service Aps fuel system
- Check circuit to rr tail lamp inop, r & l new bulb
- Perform complete front alignment . Road test .
- Weld Damaged Tool Box Lid
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Napa Quart 5w30	7.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Used Fire X Refurbished	1.00
Napagold Fuel Filter	1.00
Boxed Miniatures	1.00
Lt245/75r17 Mich Defend Ltx	4.00
Shop Supplies	1.00
Tire Disposal Fee	4.00

Hours: 10.25

Comm: 0.00

Labor: 748.25

Parts: 1,273.68

Total: 2,021.93

Work Order: 2105499 **Meter:** 36342 **In Date:** 05/17/2021 **Closed:** 05/18/2021
Problem: hose to disel fuel tank broken

Work Completed

- R&r Cracked Fuel Transfer Hose From Auillary Fuel Tank.
- Shop Supplies

Parts Issued

Quantity

1in X 20ft Hose	1.00
Shop Supplies	1.00

Hours: 1.00

Comm: 0.00

Labor: 73.00

Parts: 92.41

Total: 165.41

3/28/2025
1:26:17 PM

Palm Beach County Fleet Management Asset Maintenance History
10201451 2016 FORD F250 Pickup, 3/4 Ton, Ext Cab

Work Order: 2109171

Meter: 39792

In Date: 08/24/2021 **Closed:** 09/01/2021

Problem: PM Service.

Work Completed

- Preventive Maint. Service
- Load Test Battery And Had To Recharge. Retest Battery Failed, R&r Battery. Check Current Draw, Found Lab Top Charger Cable Plugged In Outlet Staying On. Retest Current Draw At 0.002amps Within Range.
- Diagnose Misfire With Scan Tool, Power Balance Test. R&r Faulty Ignition Coils From Cylinders 1 And 2. R&r Sixteen Spark Plugs And Eight Wires. Retest And Clear Codes.
- Perform Fuel Injector Service; Intake System, And Clean Throttle Body.
- Inspect And Service Auxillary Fuel Tank.
- Rotate And Balance Four Tires. Nitro Fill All.
- Shop Supplies

Parts Issued

Quantity

Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Napagold Oil Filter	1.00
Napa Quart 5w30	7.00
Mac Battery Protect	1.00
Battery	1.00
Espak Plug Wire	4.00
Espak Plug Wire	4.00
Throttle Body Cleaner	1.00
Intake Cleaner Kit	1.00
Motor Tune-up 16oz	1.00
Napagold Fuel Filter	1.00
Spark Plug	16.00
Coil	2.00
Shop Supplies	1.00

Hours: 13.75

Comm: 0.00

Labor: 1,003.75

Parts: 647.79

Total: 1,651.54

3/28/2025
1:26:17 PM

Palm Beach County Fleet Management Asset Maintenance History
10201451 2016 FORD F250 Pickup, 3/4 Ton, Ext Cab

Work Order: 2206149

Meter: 42691

In Date: 06/10/2022 **Closed:** 06/21/2022

Problem: PM Service.

Work Completed

- Preventive Maint. Service
- Rotated and balanced all 4 tires. Nitrogen filled all tires.
- Inspect and serviced aux fuel system
- Diagnose washer fluid leak. Found to have leaking washer pump. Replaced faulty washer pump and topped off fluid
- Replaced broken pintle pin
- Shop Supplies

Parts Issued

Quantity

Napa Quart 5w30	8.00
Napagold Oil Filter	1.00
22" Wiper Blade	2.00
Used Fire X Refurbished	1.00
Napagold Air Filter	1.00
Steering Wheel Cover Large	1.00
White Lithium Grease	1.00
Napagold Fuel Filter	1.00
Washer Fluid Concentr	1.00
Washer Pump	1.00
Washer Fluid Concentr	1.00
Pintle Pin W/clip	1.00
Shop Supplies	1.00

Hours: 5.45

Comm: 0.00

Labor: 397.85

Parts: 118.33

Total: 516.18

3/28/2025
1:26:17 PM

Palm Beach County Fleet Management Asset Maintenance History
10201451 2016 FORD F250 Pickup, 3/4 Ton, Ext Cab

Work Order: 2301969 **Meter:** 47387 **In Date:** 02/28/2023 **Closed:** 03/07/2023
Problem: PM Service. Send for Detail.

Work Completed

Parts Issued

Quantity

- Preventive Maint. Service
- Check and service Aps fuel system
- Rotate and speed balance, nitro fill
- Check circuit to washer pump, R & I fender well, necessary to replace washer pump
- Check all brakes, R & I new front brakes, resurface both front rotors, R & I both front calipers, service caliper slide pins, Bleed brake system, Road test
- Shop Supplies

Napagold Oil Filter	1.00
Napa Quart 5w30	8.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Napagold Fuel Filter	1.00
Washer Pump	1.00
Brake Fl-dot 3-4 32oz	1.00
Non-chlor Brake Clnr	1.00
Front Brake Pad	1.00
Brake Caliper	1.00
Brake Caliper	1.00
Shop Supplies	1.00

Hours: 9.75 Comm: 0.00 Labor: 711.75 Parts: 323.23 Total: 1,034.98

Work Order: 2302303 **Meter:** 47247 **In Date:** 03/06/2023 **Closed:** 03/06/2023
Problem: 1 - Detail Vehicle Wash Ticket(s) Issued WO: 2301969 for: James Riley

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued Wo: 2301969 for: James Riley

Hours: 0.00 Comm: 90.40 Labor: 0.00 Parts: 0.00 Total: 90.40

3/28/2025
1:26:17 PM

Palm Beach County Fleet Management Asset Maintenance History
10201451 2016 FORD F250 Pickup, 3/4 Ton, Ext Cab

Work Order: 2307354 **Meter:** 47426 **In Date:** 07/25/2023 **Closed:** 08/07/2023
Problem: PM Service ,had to jump start and A/C warm .

Work Completed

- Preventive Maint. Service completed
- balance and rotate all 4tires Nitro fill all.
- inspect and service auxiliary fuel system also replaced defective fuel hose
- check,performed a/c system performance test,sop and r&r a/c evaporator,condensor mexpansion valve,orings,shradder valves by removed & all necessary parts,vacuum ,recharge to spec and verify normal operation
- check and replaced defective bar light switch controller
- check battery ,charging system after fully charge it fails load test,r&r defective battery and performed draw test
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Motor Oil Motorcraft	8.00
22" Wiper Blade	2.00
Used Fire X Refurbished	1.00
Hose Wacher	1.00
Washer Jet	2.00
Napagold Fuel Filter	1.00
Condenser	1.00
Evaporator Core	1.00
Valve	1.00
High Side Schrader Valve	1.00
Kit O	1.00
Pag Oil	1.00
Freon Lv Shop 1	2.00
Rapid Seal Kit	1.00
Rocker Switch	2.00
Battery	1.00
1in X 20ft Hose	1.00
Shop Supplies	1.00

Hours: 19.95

Comm: 0.00

Labor: 1,456.35

Parts: 1,072.22

Total: 2,528.57

Work Order: 2307970 **Meter:** 47426 **In Date:** 08/10/2023 **Closed:** 08/11/2023
Problem: cut new key

Work Completed

- Make Duplicate Keys
- Shop Supplies

Parts Issued

Quantity

Ford Ignition Key Blank	1.00
Shop Supplies	1.00

Hours: 0.50

Comm: 0.00

Labor: 36.50

Parts: 43.80

Total: 80.30

3/28/2025
1:26:17 PM

Palm Beach County Fleet Management Asset Maintenance History
10201451 2016 FORD F250 Pickup, 3/4 Ton, Ext Cab

Work Order: 2308447 **Meter:** 47650 **In Date:** 08/23/2023 **Closed:** 08/24/2023
Problem: Left back turn blinker not working and cigarette AC power adapter not working possible blown fuse

Work Completed

- Replace left rear tail lamp bulb
- Replace pass. side power port
- Shop Supplies

Hours: 1.30

Comm: 0.00

Parts Issued

	Quantity
Boxed Miniatures	1.00
Soket Pauer Outlet	1.00
Shop Supplies	1.00

Labor: 94.90

Parts: 14.50

Total: 109.40

Work Order: 2402465 **Meter:** 51118 **In Date:** 03/08/2024 **Closed:** 03/27/2024
Problem: PM Service.

Work Completed

- Preventive Maint. Service
- Service And Inspect Fuel System
- Perform Tune Up 16 Spark Plugs And 8 Wires
- Perofrm Injector Cleaning And Decarb Of Intake, Clean Throttle Body And Reset With Ids
- Body Mounts Worn And Making Noise Replace All 6 Body Mounts
- Replace 4 Tires Mount And Balance With Nitro Fill
- Upper Radiator Hose Leaking While Pressure Testing System, Drain Coolant And Replace Hose Vacuum System And Retest
- Test Drive And Perform Front End Alignment Retest
- Shop Supplies

Hours: 22.35

Comm: 0.00

Parts Issued

	Quantity
Napagold Fuel Filter	1.00
Napa Quart 5w30	7.00
Napagold Oil Filter	1.00
Beam Wiper Blade	2.00
Napagold Fuel Filter	1.00
Spark Plug	16.00
Intake Cleaner Kit	1.00
Motor Tune-up 16oz	1.00
Body Mount Kit	4.00
Body Mount Kit	2.00
Tire Lt245/75/17 Mich	4.00
Espak Plug Wire	4.00
Espak Plug Wire	4.00
Upper Hose	1.00
Coolent	2.00
Shop Supplies	1.00
Tire Disposal Fee	4.00

Labor: 1,631.55

Parts: 2,014.44

Total: 3,645.99

3/28/2025
1:26:17 PM

Palm Beach County Fleet Management Asset Maintenance History
10201451 2016 FORD F250 Pickup, 3/4 Ton, Ext Cab

Work Order: 2405946 **Meter:** 51703 **In Date:** 06/17/2024 **Closed:**
Problem: Left signal light is out

Work Completed

-
Hours: 0.00 Comm: 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00

Work Order: 2405947 **Meter:** 51764 **In Date:** 06/17/2024 **Closed:** 06/25/2024
Problem: Left signal light is out

Work Completed

- Replace left rear turn signal bulb

Parts Issued **Quantity**

Boxed Miniatures 1.00

Hours: 0.50 Comm: 0.00 Labor: 36.50 Parts: 0.58 Total: 37.08

Work Order: 2409904 **Meter:** 54474 **In Date:** 10/16/2024 **Closed:** 10/24/2024
Problem: PM Service.

Work Completed

- Preventive Maint. Service
- Rotate and balance four tires. Nitro fill all .
- Inspect and service auxiliary fuel system.
- R&r broken pintel pin.
- Shop Supplies

Parts Issued **Quantity**

Napagold Oil Filter 1.00

Napa Quart 5w30 7.00

Washer Fluid Concentr 1.00

Wiper Blade 2.00

Used Fire X Refurbished 1.00

Napagold Fuel Filter 1.00

Pintle Pin W/clip 1.00

Shop Supplies 1.00

Hours: 4.95 Comm: 0.00 Labor: 361.35 Parts: 65.29 Total: 426.64

Work Order: 2502490 **Meter:** 56050 **In Date:** 03/14/2025 **Closed:** 03/18/2025
Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 0.00 Total: 146.00

Total Hours: 144.80 Total Labor: 10,090.60 Total Comm: 186.40 Total Parts: 8,243.89