

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: PB1301 to PB1301

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>			Total Line Count for System Code 1100 :	25	<u>Cause-Reason</u>
PB1301	1100	INTERIOR CLEAN					
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>			
1814039	1	07/02/2018	627	INTERIOR CLEAN			OPERATOR COMPLAINT
							SCHEDULED SERVICE
1918020	1	09/30/2019	821	INTERIOR CLEAN----COMPLETED			SCHEDULED SERVICE
1812686	1	06/19/2018	656	INTERIOR CLEAN			OPERATOR COMPLAINT
1902753	3	02/11/2019	619	CLEAN FLOOR & SEALS			SCHEDULED SERVICE
1908063	1	04/30/2019	657	INTERIOR CLEAN-----COMPLETED			SCHEDULED SERVICE
2004247	1	03/10/2020	619	INTERIOR CLEAN----COMPLETED			SCHEDULED SERVICE
1906921	1	04/16/2019	619	INTERIOR CLEAN---COMPLETED			SCHEDULED SERVICE
1912963	1	07/16/2019	862	INTERIOR CLEAN----COMPLETED			OPERATOR COMPLAINT
2129262	3	11/04/2021	29	VENDOR CLEAN			OPERATOR COMPLAINT
1910778	1	06/11/2019	619	INTERIOR CLEAN			OPERATOR COMPLAINT
1902443	1	02/06/2019	619	INTERIOR CLEAN---COMPLETED			SCHEDULED SERVICE
1808775	1	05/01/2018	619	INTERIOR CLEAN---COMPLETED			OPERATOR COMPLAINT
1914740	1	08/13/2019	619	INTERIOR CLEAN---COMPLETED			OPERATOR COMPLAINT
1905806	1	03/27/2019	619	INTERIOR CLEAN---COMPLETED			SCHEDULED SERVICE
1825984	1	12/05/2018	627	INTERIOR CLEAN---COMPLETED			OPERATOR COMPLAINT
1900403	1	01/10/2019	619	INTERRIOR CLEAN			SCHEDULED SERVICE
1904884	1	03/12/2019	812	INTERIOR CLEAN---COMPLETED			SCHEDULED SERVICE
1807592	1	04/17/2018	619	INTERIOR CLEAN			SCHEDULED SERVICE

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: **PB1301** to **PB1301**

BUS#	SYS Code	SYS Code Description		Total Line Count for System Code 1100 :	25	Cause-Reason
PB1301	1100	INTERIOR CLEAN				
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>		<u>SCHEDULED SERVICE</u>
1902779	1	02/12/2019	619	INTERIOR CLEAN---COMPLETED		
1818040	1	08/21/2018	619	INTERIOR CLEAN		OPERATOR COMPLAINT
1910131	1	06/03/2019	619	INTERIOR CLEAN		SCHEDULED SERVICE
1822726	1	10/18/2018	627	INTERIOR CLEAN---COMPLETED		SCHEDULED SERVICE
1819479	1	09/12/2018	619	INTERIOR CLEAN---COMPLETED		SCHEDULED SERVICE
2003084	3	02/29/2020	619	INTERIOR CLEAN		OPERATOR COMPLAINT
1919588	1	10/22/2019	619	IN?TERIOR CLEAN---COMPLETED		OPERATOR COMPLAINT

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: 1100 to 9700

Print Date: 3/25/2025

Asset# Range: PB1301 to PB1301

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>			<u>Cause-Reason</u>
PB1301	1200	COOLING SYSTEM	Total Line Count for System Code 1200 :		19
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	
2015728	4	08/14/2020	841	R/R WATER PUMP BELT	OPERATOR COMPLAINT
1711950	4	07/11/2017	679	LOW COOLANT CODE 0197 STILL PRESENT POSSIBLE BAD SEXNSORS -2 MAJOR	OPERATOR COMPLAINT
2002648	2	02/18/2020	828	TIGHTEN COOLAN FILTER HOUSING BRACKET	COOLANT LEAKS E SCHEDULED SERVICE
1808739	3	05/02/2018	809	TOIP OFF COOLANT LEVEL ON ROAD--CK FOR LEAKS---NONE	OPERATOR COMPLAINT
1915019	9	08/20/2019	828	REPLCD O RING ON EGR COOLER PLUMBING	SCHEDULED SERVICE
1512198	3	08/31/2015	762	CHECKED & TIGHTENED LOOSE HOSE CLAMP ON HOSE TO THERMOSTAT HOUSING. COLD WATER L	SCHEDULED SERVICE
2215435	6	05/16/2022	820	TIGHTEN ALL LOOSE CLAMPS ON THE BYPASS COOLANT HOSE AND ELBOW.	SCHEDULED SERVICE
2215435	6	05/16/2022	833	TIGHTEN ALL LOOSE CLAMPS ON THE BYPASS COOLANT HOSE AND ELBOW.	SCHEDULED SERVICE
2124040	2	09/14/2021	869	MOTOR WASH	SCHEDULED SERVICE
2417030	3	07/19/2024	809	R/R W/P belt	SCHEDULED SERVICE
2133816	3	12/09/2021	833	R/R COOLANT HOSE FROM TOP OF RADIATOR TO SURGE TANK	OPERATOR COMPLAINT
1824617	4	11/15/2018	809	TOP OFF COOLNA LEVEL AND CHECK FOR LEAKS	OPERATOR COMPLAINT
1616879	3	11/29/2016	800	ADDED 1/2 GALLON COOLANT	OPERATOR COMPLAINT
2012856	4	07/08/2020	841	ADD COOLANT BELOW SENSOR	OPERATOR COMPLAINT
2132760	7	12/01/2021	832	PRESSURE TEST COOLANT	SCHEDULED SERVICE
1800959	3	01/22/2018	828	TIGHTEN COOLANT FILTER MOUNTING BRACKET BOLTS	SCHEDULED SERVICE
1602127	3	02/17/2016	773	REOMVED GRAFFITTI	SCHEDULED SERVICE
1602127	4	02/17/2016	773	REPLACED BOLT AT COOLANT FILTER BRACKET	SCHEDULED SERVICE

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: **PB1301** to **PB1301**

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>			<u>Cause-Reason</u>
PB1301	1200	COOLING SYSTEM	Total Line Count for System Code 1200 :		19
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	OPERATOR COMPLAINT
2226703	5	09/05/2022	833	CHECKED FOR COOLANT LEAKS	

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024 System Code Range: 1100 to 9700

Print Date: 3/25/2025

Asset# Range: PB1301 to PB1301

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>			<u>Total Line Count for System Code 1201 :</u>	<u>19</u>	<u>Cause-Reason</u>
PB1301	1201	TROUBLESHOOT COOLING SYS					
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>SCHEDULED SERVICE</u>		
2417030	2	07/19/2024	849	Turn on water valve at marine pump to check to see if heater defroster works and to			OPERATOR COMPLAINT
2021881	3	11/04/2020	778	T/S COOLING SYSTEM BOTH COOLANT LEVEL SENSORS N/R -HARNES RUBBIMG EXHAUST PIPE			OPERATOR COMPLAINT
2021836	1	11/04/2020	832	TROUBLESHOOT COOLING SYSTEM---TOPPED W/COOLANT--PRESSURE TEST--OK---NO LEAK			OPERATOR COMPLAINT
1415646	1	11/06/2014	796	TS COOLING SYS - LEAKING RADIATOR			OPERATOR COMPLAINT
1617140	3	12/07/2016	789	TROUBLESHOOT COOLING SYSTEM--LEAK @HEATER CORE			OPERATOR COMPLAINT
1400820	1	01/21/2014	753	TROUBLESHOOT COOLING SYSTEM-TIGHTEN LOOSE CLAMP			OPERATOR COMPLAINT
1708710	3	05/19/2017	839	TROUBLESHOOT COOLING SYSTEM--REPLCD COOLANT HOSE			OPERATOR COMPLAINT
1815816	1	07/30/2018	828	TROUBLESHOOT COOLING SYSTEM----COOLANT LEVEL SENSORS WERE READING WRONG			OPERATOR COMPLAINT
1904084	4	03/04/2019	779	CK COOLANT--TOP OFF BOTH TANKS			OPERATOR COMPLAINT
1415646	5	11/06/2014	819	TOP OFF COOLANT RUN AND CHECK GOOD TO GO			OPERATOR COMPLAINT
1617333	1	12/13/2016	819	T/S COOLING SYSTEM			OPERATOR COMPLAINT
1719867	3	11/03/2017	822	TROUBLESHOOT COOLANT SYSTEM			OPERATOR COMPLAINT
1723466	3	01/02/2018	818	ADD COOLANT			OPERATOR COMPLAINT
1800412	1	01/08/2018	797	T/S COOLING SYSTEM -PRESSURE TEST SYSTEM COULD NOT DUPLICATE COOLANT LEAK -NONE F			OPERATOR COMPLAINT
1409249	4	07/07/2014	764	CLEAR CODES			OPERATOR COMPLAINT
1723505	1	01/04/2018	832	TROUBLESHOOT COOLING SYSTEM----			OPERATOR COMPLAINT
1617035	1	12/06/2016	773	TROUBLESHOOT COOLING SYSTEM--LOW COOLANT LIGHT ON			OPERATOR COMPLAINT
1907349	3	04/18/2019	795	TROUBLESHOOT COOLING SYSTEM ---HOSE LEAKING--HOSES @COOLANT FILTER CRACKING			OPERATOR COMPLAINT

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: **PB1301** to **PB1301**

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>				
PB1301	1201	TROUBLESHOOT COOLING SYS		Total Line Count for System Code 1201 :	19	<u>Cause-Reason</u>
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>		OPERATOR COMPLAINT
1409249	2	07/07/2014	764	CHECK CODES		
PB1301	1202	WATER PUMP		Total Line Count for System Code 1202 :	2	<u>Cause-Reason</u>
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>		SCHEDULED SERVICE
2008248	10	05/11/2020	756	REPAIR BOLT AT WATER PUMP PRESSURE TEST		
1808615	3	05/01/2018	841	REPLACE WATER PUMP		SCHEDULED SERVICE
PB1301	1206	RADIATOR REPL		Total Line Count for System Code 1206 :	2	<u>Cause-Reason</u>
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>		OPERATOR COMPLAINT
1415646	2	11/06/2014	753	REMOVE/REPLACE RADIATOR NO FINISH ONLY NEED 4 HOSES AND PUT BACK COOLANT WIP		
1415646	2	11/06/2014	820	REMOVE/REPLACE RADIATOR NO FINISH ONLY NEED 4 HOSES AND PUT BACK COOLANT WIP		OPERATOR COMPLAINT

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: PB1301 to PB1301

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>			<u>Cause-Reason</u>
PB1301	1207	COOLING SYS LEAKS REPAIR	Total Line Count for System Code 1207 :		27
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	
1723505	2	01/04/2018	832	REPLCD HOSE	OPERATOR COMPLAINT
2416122	3	07/10/2024	823	R/R HOSES AND CLAMP	OPERATOR COMPLAINT
1408567	3	06/18/2014	789	REPAIR COOLANT LEAK-FILL SYSTEM-NO CODES	OPERATOR COMPLAINT
1800959	5	01/22/2018	832	REPLACE HOSE	SCHEDULED SERVICE
1804075	11	03/05/2018	809	INSTALLED COOLANT OUTLET GASKET/FILLED	SCHEDULED SERVICE
2008248	2	05/11/2020	837	COOLANG SSYTEM LEAKS REPAIR	SCHEDULED SERVICE
1902347	9	02/08/2019	853	REPLCD ELBOW TRANS OIL COOLER	SCHEDULED SERVICE
1902347	9	02/08/2019	832	REPLCD ELBOW TRANS OIL COOLER	SCHEDULED SERVICE
1710659	5	06/20/2017	841	REPLCD COOLANT GASKET	SCHEDULED SERVICE
1909230	3	05/17/2019	753	R/R HEATER VALVE--FILTER & HOSES	OPERATOR COMPLAINT
1617140	4	12/07/2016	789	REPLC HEATER VALVE	OPERATOR COMPLAINT
1706410	2	04/18/2017	809	REPAIRED SEVERAL COOLANT LEAK	SCHEDULED SERVICE
1902347	4	02/08/2019	853	REPLCD HOSE & WATER INLET GASKET	SCHEDULED SERVICE
1902347	4	02/08/2019	832	REPLCD HOSE & WATER INLET GASKET	SCHEDULED SERVICE
2010594	2	06/12/2020	800	REPAIR COOLANT LEAKS	SCHEDULED SERVICE
2002648	6	02/18/2020	837	RR HEATER VALVE	SCHEDULED SERVICE
2008248	5	05/11/2020	781	INSTALLED WATER PUMP SEE DEFECT SHEET	SCHEDULED SERVICE
2305991	1	03/10/2023	859	TIGHTEN HOSE CLAMP. TOP OFF COOLANT	OPERATOR COMPLAINT

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: **PB1301** to **PB1301**

BUS#	SYS Code	SYS Code Description			Total Line Count for System Code		Cause-Reason
PB1301	1207	COOLING SYS LEAKS REPAIR			27		
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>			<u>OPERATOR COMPLAINT</u>
1826733	3	12/19/2018	789	REPAIR COOLANT LAKES			SCHEDULED SERVICE
1804075	8	03/05/2018	832	DRAINED COOLANT--REMVD OUTLET CONNECTION--LOOK FOR PARTS			SCHEDULED SERVICE
2103029	5	03/03/2021	849	REPAIRD 4 LEAKS@ LOWER RADIATOR HOSE, HOSE TO ENGIEN BLOCK & 2 HOSES@REAR OF ENG			SCHEDULED SERVICE
2103029	5	03/03/2021	797	REPAIRD 4 LEAKS@ LOWER RADIATOR HOSE, HOSE TO ENGIEN BLOCK & 2 HOSES@REAR OF ENG			SCHEDULED SERVICE
2418363	13	08/03/2024	909	repair coolant leaks			SCHEDULED SERVICE
2305456	5	03/05/2023	849	t/s coolant sys.. repaired fitting			SCHEDULED SERVICE
2124040	5	09/14/2021	874	R/R FRONT HEATER CORE VALVE			SCHEDULED SERVICE
1921419	8	11/19/2019	795	REPLCD CLAMP ON RADIATOR HOSE			SCHEDULED SERVICE
1921419	8	11/19/2019	789	REPLCD CLAMP ON RADIATOR HOSE			SCHEDULED SERVICE
PB1301	1208	COOLING SYS LINES/HOSES R			8		
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>			<u>OPERATOR COMPLAINT</u>
1717398	3	09/27/2017	825	DRAINED COOLANT. R/R UPPER RADIATOR HOSE, REFILLED COOLING SYSTEM			OPERATOR COMPLAINT
1711950	8	07/11/2017	679	REMOVED REAR SEAT TO ACCESS LEARNING HOSES DRAIN COOLANT			SCHEDULED SERVICE
2021158	16	10/27/2020	871	DRAIN COOLANT--R/R COOLANT HOSE--FILLED COOLANT			OPERATOR COMPLAINT
1907349	5	04/18/2019	795	REPLCD BYPASS HOSE GOING TO EGR COOLER			OPERATOR COMPLAINT
1719867	4	11/03/2017	822	DRAINED COOLANT--R/R COOLANT HOSE			OPERATOR COMPLAINT
1907349	4	04/18/2019	795	REPLCD 2 HOSES GOING TO ENGINE--REPLCD HOSES@COOLANT FILTER---FOUND HOES @EGR CO			SCHEDULED SERVICE
1710659	6	06/20/2017	841	REPLCD HOSE UPPER RADIATOR@THERMOSTAT HOUSING			OPERATOR COMPLAINT
1817291	3	08/14/2018	752	CK COOLANT LEAK--REPLCD EGR COOLER HOSE			

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: 1100 to 9700

Print Date: 3/25/2025

Asset# Range: PB1301 to PB1301

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>			<u>Cause-Reason</u>
PB1301	1209	COOLING SYS PROBES/SENSOR	Total Line Count for System Code 1209 :		8
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
1815816	2	07/30/2018	828	REPLCD COOLANT LEVEL SENSOR--REPAIR PIGTAIL	OPERATOR COMPLAINT
1903696	4	02/25/2019	798	R/R LOW COOLANT SENSOR--REFILL COOLANT--CLEAR CODES	OPERATOR COMPLAINT
2021881	4	11/04/2020	778	RR BOTH COOLANT SENSORS -SEUED SENSOR HARNESS OK	OPERATOR COMPLAINT
2016013	6	08/19/2020	809	R/R COOLANT HOSES/CLAMPS	SCHEDULED SERVICE
1609162	3	06/28/2016	786	REPL 2 LEVEL SENSORS	OPERATOR COMPLAINT
1713883	2	08/04/2017	809	R/R COOLANT LEVEL SENSOR	OPERATOR COMPLAINT
1617035	2	12/06/2016	773	R/R COOLANT LEVEL SENSORS	OPERATOR COMPLAINT
1409249	3	07/07/2014	764	R/R COOLANT SENSOR	OPERATOR COMPLAINT
PB1301	1210	SURGE TANK REPAIR	Total Line Count for System Code 1210 :		1
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
1410267	5	07/22/2014	818	REMOVED BROKEN HOSE FROM TOP COLLANT RESERVOIR TO BOTTOM COOLANT RESERVIOUR AN	SCHEDULED SERVICE
PB1301	1214	Radiator Cap	Total Line Count for System Code 1214 :		3
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
1720113	4	11/07/2017	849	REPLCD RADIATOR CAP	SCHEDULED SERVICE
1403816	3	03/21/2014	819	CK COOLING SYSTEM, FIND RADIATOR CAP LOOSE, RECK COOLING SYSTEM-NO LEAKS	SCHEDULED SERVICE
1617260	3	12/10/2016	822	R/R RADIATOR CAP & BLEED COOLANT SYSTEM	OPERATOR COMPLAINT
PB1301	1216	FAN BLADE REPLACE	Total Line Count for System Code 1216 :		1
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
1713479	6	08/01/2017	822	WATER PUMP BELT DAMAGED--REMVD/REPLCD--IDLE OULLEY MAKING NOISE--NONE IN STOCK	OPERATOR COMPLAINT

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: **PB1301** to **PB1301**

BUS#	SYS Code	SYS Code Description			Total Line Count for System Code 1222 :	38	Cause-Reason
PB1301	1222	Clean Radiator					
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>			
2111333	2	05/15/2021	762	CLEAN RADIATOR			SCHEDULED SERVICE
2004217	2	03/10/2020	762	CLEAN RADIATOR			SCHEDULED SERVICE
1720464	2	11/15/2017	752	CLEAN RADIATOR			SCHEDULED SERVICE
2205301	2	02/14/2022	880	CLEAN RADIATOR.			SCHEDULED SERVICE
1617544	2	12/20/2016	762	WASH RADIATOR			OPERATOR COMPLAINT
1816961	2	08/08/2018	762	CLEAN RADIATOR			SCHEDULED SERVICE
1512198	2	08/31/2015	762	WASHED RADIATOR			SCHEDULED SERVICE
1602314	2	03/02/2016	753	CLEAN RADIATOR			SCHEDULED SERVICE
1611660	2	08/15/2016	809	CLEAN RADIATOR			SCHEDULED SERVICE
2008754	2	05/14/2020	753	CLEAN RAIDATOR			SCHEDULED SERVICE
2015544	2	08/12/2020	762	CLEAN RADIATOR			SCHEDULED SERVICE
1413272	2	09/16/2014	809	CLEAN RADIATOR - COMPLETED			SCHEDULED SERVICE
1911051	2	06/17/2019	762	CLEANED RADIATOR			SCHEDULED SERVICE
2134621	2	12/15/2021	871	RAD CLEAN CCOMPLETED			SCHEDULED SERVICE
2103698	2	05/16/2021	762	CLEAN RADIATOR			SCHEDULED SERVICE
2217064	2	05/29/2022	853	rad clean			SCHEDULED SERVICE
2020190	2	10/12/2020	762	CLEARED RADIATOR			OPERATOR COMPLAINT
2235778	2	12/21/2022	809	CLEAN RADIATOR			SCHEDULED SERVICE

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: **PB1301** to **PB1301**

BUS#	SYS Code	SYS Code Description			Total Line Count for System Code 1222 :	38	Cause-Reason
PB1301	1222	Clean Radiator					
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>			<u>SCHEDULED SERVICE</u>
1904972	2	03/14/2019	762	clean radiator			SCHEDULED SERVICE
1711256	2	06/28/2017	752	CLEAN RADIATOR			SCHEDULED SERVICE
1716054	4	09/03/2017	757	CLEAN RADIATOR			SCHEDULED SERVICE
1515017	2	10/26/2015	820	CLEAN RADIATOR			SCHEDULED SERVICE
1315447	2	12/03/2013	762	CLEAN RADIATOR			SCHEDULED SERVICE
1800826	2	01/20/2018	762	CLEAN RADIATOR			SCHEDULED SERVICE
1810540	2	05/22/2018	764	CLEANA RADIATOR			SCHEDULED SERVICE
1715344	2	08/23/2017	762	CLEAN RADIATOR			SCHEDULED SERVICE
1404016	2	03/24/2014	762	CLEAN RADIATOR			SCHEDULED SERVICE
1918116	2	10/02/2019	762	CLEAN RADIATOR---			SCHEDULED SERVICE
1614776	3	10/20/2016	762	WASHED RADIATOR			SCHEDULED SERVICE
1900520	2	01/11/2019	752	CLEAN RADIATOR			SCHEDULED SERVICE
2000176	2	01/08/2020	762	clean radiator			SCHEDULED SERVICE
1401204	2	01/27/2014	814	CLEAN RADIATOR			SCHEDULED SERVICE
1605267	2	04/19/2016	762	CLEAN RADIATOR			SCHEDULED SERVICE
1823413	2	10/29/2018	762	WASHED RADIATOR			OPERATOR COMPLAINT
1407058	2	05/21/2014	764	CLEAN RADIATOR			SCHEDULED SERVICE
2210023	2	03/27/2022	880	CLEAN RADIATOR.			SCHEDULED SERVICE

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: **PB1301** to **PB1301**

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>			<u>Cause-Reason</u>
PB1301	1222	Clean Radiator	Total Line Count for System Code 1222 :		38
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	
2025439	2	12/21/2020	762	CLEANED RADIATOR	OPERATOR COMPLAINT
2118257	2	07/19/2021	836	CLEAN RADIATOR	SCHEDULED SERVICE

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: **PB1301** to **PB1301**

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>				<u>Cause-Reason</u>
PB1301	1300	AIR COND\HEATING SYSTEM	Total Line Count for System Code 1300 :			18
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>		
1602314	3	03/02/2016	753	A/C COMPARTMENT		SCHEDULED SERVICE
1910738	3	06/11/2019	832	A/C DOOR FIXED		SCHEDULED SERVICE
1820644	3	09/24/2018	679	CLEAN EVAP COIL/FILTER---WASHED RADIATOR--RAN AC---OK		OPERATOR COMPLAINT
2227592	2	09/19/2022	809	r/r reheat valve		OPERATOR COMPLAINT
2132760	4	12/01/2021	832	ADJUST A/C BELT. SECURE WIRING		SCHEDULED SERVICE
2132760	4	12/01/2021	849	ADJUST A/C BELT. SECURE WIRING		SCHEDULED SERVICE
2018797	3	09/23/2020	795	STRAIGHTEN COOLING FANS--PRESSURE WASH EVAP--DRY ALL COMPONENTS		OPERATOR COMPLAINT
2418353	1	08/01/2024	809	clean a/c condenser and evap. run unit for several hours under the sun , unit is cold		OPERATOR COMPLAINT
2013393	11	07/20/2020	781	R/R AC BELT		SCHEDULED SERVICE
2232435	3	11/11/2022	809	sealed uv sys harness		OPERATOR COMPLAINT
1502783	3	02/18/2015	828	REPLACE A/C TENSIONER PULLEY		SCHEDULED SERVICE
2219498	1	06/21/2022	849	AC SYSTEM		OPERATOR COMPLAINT
2232435	2	11/11/2022	809	wash evap coil & filter		OPERATOR COMPLAINT
1921419	5	11/19/2019	795	REPAIR AC FILTER PANEL		SCHEDULED SERVICE
1921419	5	11/19/2019	789	REPAIR AC FILTER PANEL		SCHEDULED SERVICE
2225708	2	08/25/2022	809	top off freon		OPERATOR COMPLAINT
2215435	2	05/16/2022	833	R/R AC BELT		OPERATOR COMPLAINT
2215435	2	05/16/2022	820	R/R AC BELT		OPERATOR COMPLAINT

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: **PB1301** to **PB1301**

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>			<u>Total Line Count for System Code 1301 :</u>	<u>10</u>	<u>Cause-Reason</u>
PB1301	1301	TROUBLESHOOT AC SYSTEM					
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>OTHER MECHANICAL BREAKDOWN</u>		
2227592	1	09/19/2022	871	t/s ac sys	<u>OTHER MECHANICAL BREAKDOWN</u>		
2227592	1	09/19/2022	809	t/s ac sys	<u>SCHEDULED SERVICE</u>		
2000176	3	01/08/2020	762	rr a/c filter drier	<u>OPERATOR COMPLAINT</u>		
2416723	3	07/15/2024	907	Evaporator coil is dirty	<u>SCHEDULED SERVICE</u>		
2018957	7	09/25/2020	798	TROUBLESHOOT AC--NO CODES--AC COLD--OK	<u>OPERATOR COMPLAINT</u>		
2106377	3	03/26/2021	752	ADJ THERMASTAT	<u>OPERATOR COMPLAINT</u>		
2216454	1	05/24/2022	859	DRIVER STATES BOOSTER FAN NOT WORKING CHECK FOR POWER . POWER GOING IN BUT NOT CO	<u>OPERATOR COMPLAINT</u>		
2225708	1	08/25/2022	809	epr has intermittent problem	<u>OPERATOR COMPLAINT</u>		
1820192	4	09/17/2018	795	AC IS WORKING FINE--PRESSURE OK	<u>OPERATOR COMPLAINT</u>		
2232435	1	11/11/2022	809	t/s ac sys. evap valve sticking intermittently	<u>OPERATOR COMPLAINT</u>		

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: PB1301 to PB1301

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>			<u>Total Line Count for System Code 1302 :</u>	<u>54</u>	<u>Cause-Reason</u>
PB1301	1302	AIR CONDITIONING SYS PM					
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>			
1707230	1	04/27/2017	752	AIR CONDITIONING SYSTEM PM---COMPLETED			SCHEDULED SERVICE
2025439	1	12/21/2020	762	A/C SYSTEM PM			OPERATOR COMPLAINT
2210023	1	03/27/2022	880	A/C PM COMPLETE.			SCHEDULED SERVICE
2111333	1	05/15/2021	762	AIR CONDITIONING SYSTEM PM---COMPLETED			SCHEDULED SERVICE
2205301	1	02/14/2022	880	A/C PM COMPLETE.			SCHEDULED SERVICE
2229120	1	10/04/2022	778	A/C PM			SCHEDULED SERVICE
2134621	1	12/15/2021	871	COMPLETE A/C PM			SCHEDULED SERVICE
1715344	1	08/23/2017	762	AIR CONDITINING SYS PM- COMPLETED			SCHEDULED SERVICE
1605267	1	04/19/2016	762	A/C SYSTEM M PM COMPLETED			SCHEDULED SERVICE
1413272	1	09/16/2014	809	AC SYS PM - COMPLETED			SCHEDULED SERVICE
1614776	1	10/20/2016	762	A/C SYSTEM PM			SCHEDULED SERVICE
1404016	1	03/24/2014	762	AIR COND SYSTEM PM			SCHEDULED SERVICE
1611660	1	08/15/2016	809	AIR CONDITIONING SYSTEM PM--			OPERATOR COMPLAINT
2020190	1	10/12/2020	762	A/C SYSTEM PM			SCHEDULED SERVICE
1517733	1	12/29/2015	752	AIR CONDITIONING SYSTEM PM			SCHEDULED SERVICE
1911051	1	06/17/2019	762	AIR CONDITIONING SYSTEM PM			SCHEDULED SERVICE
1315447	1	12/03/2013	762	AC SYS PM - COMPLETED			SCHEDULED SERVICE
2118257	1	07/19/2021	836	AIR CONDITIONING SYSTEM PM---COMPLETED			SCHEDULED SERVICE

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: PB1301 to PB1301

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>				<u>Cause-Reason</u>
PB1301	1302	AIR CONDITIONING SYS PM	Total Line Count for System Code 1302 :			54
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>		
1800826	1	01/20/2018	762	A/C SYSTEM PM	SCHEDULED SERVICE	
1810540	1	05/22/2018	764	A/C SYSTEM PM	SCHEDULED SERVICE	
1410267	2	07/22/2014	818	A/C SYS PM - COMPLETED	SCHEDULED SERVICE	
1900520	1	01/11/2019	752	AIR CONDITIONING SYSTEM PM---COMPLETED	SCHEDULED SERVICE	
2008754	1	05/14/2020	753	AIR CONDITIONING SYSTEM PM---COMPLETED	SCHEDULED SERVICE	
1608516	1	06/15/2016	752	AIR CONDITIONING SYSTEM PM---COMPLETED	SCHEDULED SERVICE	
1602314	1	03/02/2016	753	A/C SYSTEM PM	SCHEDULED SERVICE	
1918116	1	10/02/2019	762	AIR CONDITIONING SYSTEM PM---COMPLETED	SCHEDULED SERVICE	
2015544	1	08/12/2020	762	A/C SYSTEM PM	OPERATOR COMPLAINT	
1515017	1	10/26/2015	820	AIR COND SYSTEM PM	SCHEDULED SERVICE	
1716054	3	09/03/2017	757	A/C PM	SCHEDULED SERVICE	
1711256	1	06/28/2017	752	AIR CONDITIONING SYTEM PM---COMPLETED	SCHEDULED SERVICE	
1501258	1	01/22/2015	764	A/C SYS PM - COMPLETED A/C P.M.	SCHEDULED SERVICE	
1407058	1	05/21/2014	764	AIR CONDITIONING SYSTEM PM	SCHEDULED SERVICE	
1823413	1	10/29/2018	762	A/C SYSTEM PM	OPERATOR COMPLAINT	
1805186	1	03/16/2018	752	A/C SYSTEM PM	SCHEDULED SERVICE	
1416634	1	11/13/2014	764	A/C SYS PM - COMPLETED A/C P.M.	SCHEDULED SERVICE	
2124996	1	09/23/2021	849	AIR CONDITIONING SYSTEM PM---COMPLETED	SCHEDULED SERVICE	

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: **PB1301** to **PB1301**

BUS#	SYS Code	SYS Code Description			Total Line Count for System Code 1302 :	54	Cause-Reason
PB1301	1302	AIR CONDITIONING SYS PM					
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>			<u>SCHEDULED SERVICE</u>
2000176	1	01/08/2020	762	a/c system pm			SCHEDULED SERVICE
2223499	1	07/30/2022	828	A/C PM			SCHEDULED SERVICE
2103698	1	05/16/2021	762	AIR CONDITIONING SYSTEM PM---COMPLETED			SCHEDULED SERVICE
1703379	1	03/02/2017	752	A/C SYSTEM PM			SCHEDULED SERVICE
1617544	1	12/20/2016	762	A/C SYSTEM PM			OPERATOR COMPLAINT
1504834	1	03/24/2015	773	A/C SYS PM - A/C P.M. COMPLETE			SCHEDULED SERVICE
1720464	1	11/15/2017	752	AIR CONDITIONING SYSTEM PM			SCHEDULED SERVICE
2004217	1	03/10/2020	762	AC PM---COMPLETED			SCHEDULED SERVICE
1816961	1	08/08/2018	762	A/C SYSTEM PM			SCHEDULED SERVICE
2304298	1	02/19/2023	849	pm			OPERATOR COMPLAINT
1512198	1	08/31/2015	762	A/C SYS PM - COMPLETED			SCHEDULED SERVICE
1509679	2	07/08/2015	631	a/c system pm			SCHEDULED SERVICE
1401204	1	01/27/2014	814	AIR COND SYSTEM PM			SCHEDULED SERVICE
2235778	1	12/21/2022	809	AC PM DUE			SCHEDULED SERVICE
1904972	1	03/14/2019	762	AC PM----COMPLETED			SCHEDULED SERVICE
1507964	1	05/28/2015	752	a/c system pm			SCHEDULED SERVICE
2217064	1	05/29/2022	853	a/c pm			SCHEDULED SERVICE
2417030	1	07/19/2024	849	PM Complete.			SCHEDULED SERVICE

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: 1100 to 9700

Print Date: 3/25/2025

Asset# Range: PB1301 to PB1301

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>			<u>Cause-Reason</u>
PB1301	1307	BLOWER MOTOR REPL	Total Line Count for System Code 1307 :		3
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
2216454	2	05/24/2022	859	R/R DRIVER FAN MOTOR	OPERATOR COMPLAINT
2219498	2	06/21/2022	849	R/R DRIVERS BLOWER MOTOR	OPERATOR COMPLAINT
2014404	1	07/30/2020	837	BLOWER MOTOR REPLACED	OPERATOR COMPLAINT
PB1301	1311	A/C EVAPORATOR	Total Line Count for System Code 1311 :		1
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
2416723	4	07/15/2024	907	Clean Evaporator coil.	OPERATOR COMPLAINT
PB1301	1316	A/C DRIER REPL	Total Line Count for System Code 1316 :		2
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
1614776	2	10/20/2016	762	R/R A/C FILTER	SCHEDULED SERVICE
1504834	2	03/24/2015	773	REPLACED FILTER DRYER OUT DATED	SCHEDULED SERVICE
PB1301	1318	A/C SYSTEM RE-CHARGE	Total Line Count for System Code 1318 :		2
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
2018797	4	09/23/2020	795	RECHARGE AC SYSTEM	OPERATOR COMPLAINT
2109165	3	04/22/2021	828	TIGHTEN low side hose--pump sys down, recharge--CK FOR LEAKS	OPERATOR COMPLAINT

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: **PB1301** to **PB1301**

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>			<u>Total Line Count for System Code 1319 :</u>	<u>21</u>	<u>Cause-Reason</u>
PB1301	1319	A/C BELT REPLACE					
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>OPERATOR COMPLAINT</u>		
2003851	6	03/12/2020	866	RR A/C BELT	OPERATOR COMPLAINT		
					SCHEDULED SERVICE		
2302250	2	01/28/2023	820	R/R AC BELT & ADJ	SCHEDULED SERVICE		
1816961	3	08/08/2018	762	RR A/C FILTER DRIER RAN A/C SYSTEM	SCHEDULED SERVICE		
1617544	3	12/20/2016	762	ADJUSTED A/C BELT	SCHEDULED SERVICE		
1611309	3	08/09/2016	820	R/R A/C BELT	SCHEDULED SERVICE		
1415202	5	10/20/2014	820	REMOVED/REPLACED A/C BELT	SCHEDULED SERVICE		
1704308	3	03/15/2017	781	R/R AC BELT	SCHEDULED SERVICE		
2127251	2	10/15/2021	869	R/R AC BELT	SCHEDULED SERVICE		
1827559	5	12/28/2018	797	REPLCD AC BELT---ADJUST TENSION	SCHEDULED SERVICE		
1316429	2	12/23/2013	819	REPL A/C BELT	SCHEDULED SERVICE		
2106173	3	03/22/2021	836	R/R AC BELT	SCHEDULED SERVICE		
1804075	2	03/05/2018	809	R/R AC BELT	SCHEDULED SERVICE		
1502783	2	02/18/2015	828	REPLACE A/C BELT	OPERATOR COMPLAINT		
1717004	4	09/21/2017	841	REPLC AC BELT	SCHEDULED SERVICE		
1912904	2	07/15/2019	799	A/C BELT	SCHEDULED SERVICE		
2217064	3	05/29/2022	853	adjust a/c belt	SCHEDULED SERVICE		
1808615	2	05/01/2018	841	REPLACE A/C BELT REFILLED COOLANT	SCHEDULED SERVICE		
2204184	5	02/07/2022	828	REPLACE A/C BELT	SCHEDULED SERVICE		

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024 System Code Range: 1100 to 9700

Print Date: 3/25/2025

Asset# Range: PB1301 to PB1301

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>			<u>Total Line Count for System Code</u>		<u>Cause-Reason</u>
PB1301	1319	A/C BELT REPLACE			Total Line Count for System Code 1319 :	21	<u>Cause-Reason</u>
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>			OPERATOR COMPLAINT
2015728	3	08/14/2020	841	R/R AC BELT			
1919184	4	10/21/2019	800	ADJUST AC BELT			SCHEDULED SERVICE
2223499	2	07/30/2022	828	REPLACE A/C BELT			SCHEDULED SERVICE
PB1301	1337	Heater System Diagnosis			Total Line Count for System Code 1337 :	1	<u>Cause-Reason</u>
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>			OPERATOR COMPLAINT
1418146	1	12/11/2014	791	HEATER SYSTEM DIAGNOSIS - CHECK/RESET PARIMETERS CLEAN FILTER			
PB1301	1341	Heater Valves R/R			Total Line Count for System Code 1341 :	1	<u>Cause-Reason</u>
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>			SCHEDULED SERVICE
1512533	5	09/08/2015	815	R/R DRIVER HEATER VALVE			
PB1301	1345	REPLACE IDLER PULLEY			Total Line Count for System Code 1345 :	1	<u>Cause-Reason</u>
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>			SCHEDULED SERVICE
1508321	2	06/04/2015	828	REPLC AC BELT PULLEY			

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: 1100 to 9700

Print Date: 3/25/2025

Asset# Range: PB1301 to PB1301

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>				<u>Cause-Reason</u>
PB1301	1347	ADJUST A/C BELT	Total Line Count for System Code 1347 :			14
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>	
2000176	4	01/08/2020	762	adj a/c belt tension and secured	SCHEDULED SERVICE	
1904977	3	03/18/2019	781	ADJUSTED AC BELT	SCHEDULED SERVICE	
1310022	3	08/14/2013	798	ADJUST BELT	SCHEDULED SERVICE	
2015544	3	08/12/2020	762	ADJ A/ BELT AND SECURED RAN THE A/C SYSTEM -OK AT THIS TIME	SCHEDULED SERVICE	
2109165	4	04/22/2021	828	WASH AC FILTER--ADJUST AC BELT	OPERATOR COMPLAINT	
2304298	2	02/19/2023	849	adjust a/c belt	OPERATOR COMPLAINT	
1500016	5	01/05/2015	809	ADJUSTED A/C BELT TO SPEC	SCHEDULED SERVICE	
1500016	5	01/05/2015	828	ADJUSTED A/C BELT TO SPEC	SCHEDULED SERVICE	
2229120	2	10/04/2022	778	ADJUST BELT	SCHEDULED SERVICE	
1612957	3	09/13/2016	781	ADJUST A/C BELT	SCHEDULED SERVICE	
2416122	4	07/10/2024	823	A/C BELT	OPERATOR COMPLAINT	
1611660	3	08/15/2016	809	ADJUSTED AC BELT	SCHEDULED SERVICE	
1400775	3	01/21/2014	814	RETORQUE AC BELT	SCHEDULED SERVICE	
2025439	3	12/21/2020	762	ADJ A/C BELT AND SECURED	SCHEDULED SERVICE	
PB1301	1348	REPROGRAM TK ECM	Total Line Count for System Code 1348 :			1
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>	
2105414	3	03/15/2021	795	REPROGRAM NEW THERMO KING ECM---INSTALL	OPERATOR COMPLAINT	

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: **PB1301** to **PB1301**

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>			<u>Total Line Count for System Code 1400 :</u>	<u>20</u>	<u>Cause-Reason</u>
PB1301	1400	ELECTRICAL SYSTEM					
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>			
1509861	3	07/10/2015	751	REPLC WIRING			OPERATOR COMPLAINT
2417561	2	07/24/2024	833	REMOVE PARKING BRAKE TO FIND BRAKE SWITCH PRESSURE SWITCH			OPERATOR COMPLAINT
2021158	12	10/27/2020	797	REPLCD DASH LIGHT BULB			SCHEDULED SERVICE
2311525	1	06/12/2023	778	Electric troubleshooting and check ignition system.			OPERATOR COMPLAINT
2311525	1	06/12/2023	911	Electric troubleshooting and check ignition system.			OPERATOR COMPLAINT
2417561	1	07/24/2024	833	BRAKE INDICATOR FLICKERING			OPERATOR COMPLAINT
2008248	3	05/11/2020	781	RR BACK UP WARNING MODULE			SCHEDULED SERVICE
1605681	3	04/25/2016	809	SECURED WIRING UNDER BODY @EXIT DOOR			SCHEDULED SERVICE
2417482	1	07/23/2024	797	Check and found defected switch for fast idle.			OPERATOR COMPLAINT
2013199	3	07/14/2020	833	REPAIR FAULTY GROUND FOR FANS--WORKING OK			OPERATOR COMPLAINT
1825167	3	11/21/2018	833	REPLCD MARKER LIGHT			SCHEDULED SERVICE
1509679	5	07/08/2015	631	electrical pm			SCHEDULED SERVICE
2417482	2	07/23/2024	797	R/R fast idle switch.			OPERATOR COMPLAINT
2235778	4	12/21/2022	809	TIGHTEN VOLTAGE REGULATOR			SCHEDULED SERVICE
2427748	2	11/12/2024	911	replace inserts			OPERATOR COMPLAINT
1907132	3	04/17/2019	837	jump start			OPERATOR COMPLAINT
2417561	3	07/24/2024	833	REPLACE PARKING BRAKE PRESSURE SWITCH			OPERATOR COMPLAINT
1705185	3	03/27/2017	828	REPLACE GENERATOR AND VOLTAGE REGULATOR			OPERATOR COMPLAINT

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: PB1301 to PB1301

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>			<u>Cause-Reason</u>
PB1301	1400	ELECTRICAL SYSTEM	Total Line Count for System Code 1400 :		20
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
2108590	9	04/18/2021	869	CHECK BACK--UP ALARM--OK	SCHEDULED SERVICE
2108590	9	04/18/2021	849	CHECK BACK--UP ALARM--OK	SCHEDULED SERVICE
PB1301	1401	TROUBLESHOOT ELECTRICAL S	Total Line Count for System Code 1401 :		11
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
1509861	2	07/10/2015	751	TROUBLESHOOT ELECTRICALS	OPERATOR COMPLAINT
1614591	3	10/18/2016	819	HOOK WARNING ALRAM UP	SCHEDULED SERVICE
2105966	1	03/16/2021	853	TROUBLESHOOT ELECTRICALS---REPLC SIDE PANEL	OPERATOR COMPLAINT
1311046	1	09/05/2013	762	TS ELECTRICAL S. CHECKED AND R/R COOLANT SURGE TANK SENSOR. PLUG CONNECTION AND W	WARRANTY
1511967	4	08/26/2015	822	CLEARED ALL ACTIVE/INACTIVE CODES	OPERATOR COMPLAINT
1403547	2	03/15/2014	773	TROUBLESHOOT ENTRANCE & RAMP	OPERATOR COMPLAINT
1403547	2	03/15/2014	760	TROUBLESHOOT ENTRANCE & RAMP	OPERATOR COMPLAINT
2311525	2	06/12/2023	778	Replace D2 module and also replace front dash start switch.	OPERATOR COMPLAINT
2311525	2	06/12/2023	911	Replace D2 module and also replace front dash start switch.	OPERATOR COMPLAINT
1508644	2	06/11/2015	828	TROUBLESHOOT ELECTRICAL-NO CHARGE	OPERATOR COMPLAINT
1513076	3	09/17/2015	783	J1939-TRACED TO Y CONNECTOR-OK	OPERATOR COMPLAINT
PB1301	1402	ALTERNATOR REPL	Total Line Count for System Code 1402 :		2
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
2222897	3	07/23/2022	839	REPLACE ALTERNATOR	OPERATOR COMPLAINT
1917148	4	09/18/2019	756	R/R ALT REGULATOR & TEST SYSTEM---OK	SCHEDULED SERVICE

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: 1100 to 9700

Print Date: 3/25/2025

Asset# Range: PB1301 to PB1301

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>					<u>Cause-Reason</u>
PB1301	1403	ALTERNATOR BELT REPL			Total Line Count for System Code 1403 :	6	
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>			<u>Cause-Reason</u>
1921419	2	11/19/2019	795	REPLCD ALTERNATOR BELT			SCHEDULED SERVICE
1921419	2	11/19/2019	789	REPLCD ALTERNATOR BELT			SCHEDULED SERVICE
2222897	4	07/23/2022	839	INSTALL NEW ALT. BELT			OPERATOR COMPLAINT
1515017	4	10/26/2015	820	R/R ALTERNATOR BELT			SCHEDULED SERVICE
1705185	4	03/27/2017	828	REPLACE GENERATOR BELT			OPERATOR COMPLAINT
2418363	3	08/03/2024	832	alt belt			SCHEDULED SERVICE
PB1301	1405	VOLTAGE REGULATOR REPL			Total Line Count for System Code 1405 :	1	
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>			<u>Cause-Reason</u>
1508644	3	06/11/2015	828	REPLC VOL;TAGE REGULATOR-CLEAN CABLES/PLUGS			OPERATOR COMPLAINT
PB1301	1407	BATTERIES CHECK			Total Line Count for System Code 1407 :	2	
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>			<u>Cause-Reason</u>
1513076	2	09/17/2015	783	R/R BATTERIES			OPERATOR COMPLAINT
2221613	2	07/11/2022	853	charge and test batteries, one bad battery			OPERATOR COMPLAINT

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: **PB1301** to **PB1301**

BUS#	SYS Code	SYS Code Description		Total Line Count for System Code 1408 :	10	Cause-Reason
PB1301	1408	BATTERIES REPLACE				ACCIDENT
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>		
1905688	1	03/25/2019	781	R/R BOTH BATTERIES		
2322153	2	09/13/2023	894	R/R BATTERY & AMEREX BATTERY		SCHEDULED SERVICE
2322153	2	09/13/2023	796	R/R BATTERY & AMEREX BATTERY		SCHEDULED SERVICE
2427386	1	11/07/2024	849	Tested batteries and are good		OPERATOR COMPLAINT
2135785	2	01/06/2022	849	REPLACE BOTH BATTERIES		SCHEDULED SERVICE
2020663	3	10/27/2020	832	BATTERIES REPLCD--TEST DOZER/NO LEAKING--PRESSURE OK -- EGR VALVE NO OK BOLT 1/4		OPERATOR COMPLAINT
2221613	3	07/11/2022	853	replace two batteries		OPERATOR COMPLAINT
1711950	5	07/11/2017	679	RECHARGE LOW BATTERY		OPERATOR COMPLAINT
2132168	1	11/30/2021	836	R/R BATTERIES		OPERATOR COMPLAINT
2305456	6	03/05/2023	849	R/R BATTERIES		SCHEDULED SERVICE

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: 1100 to 9700

Print Date: 3/25/2025

Asset# Range: PB1301 to PB1301

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>			<u>Total Line Count for System Code 1409 :</u>	<u>34</u>	<u>Cause-Reason</u>
PB1301	1409	EXTERIOR LIGHTING					
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>			
2427748	1	11/12/2024	911	replace light			OPERATOR COMPLAINT
2018957	2	09/25/2020	798	R/R REAR & FRONT TURN SIGNAL LIGHTS			SCHEDULED SERVICE
2021158	8	10/27/2020	797	REPLCD REAR LEFT SIDE SIGNAL & MARKER LIGHT			SCHEDULED SERVICE
1923274	2	12/18/2019	781	RR LIGHT ASSEMBLY AT RR WHEEL			SCHEDULED SERVICE
1903794	2	02/26/2019	796	R/R TAIL LIGHTS			OPERATOR COMPLAINT
2418363	5	08/03/2024	832	r/r tag light			SCHEDULED SERVICE
2106173	7	03/22/2021	869	R/R LAMP ASSY MARKER LIGHT			SCHEDULED SERVICE
2106173	7	03/22/2021	832	R/R LAMP ASSY MARKER LIGHT			SCHEDULED SERVICE
2223716	3	08/02/2022	648	RED BRAKE LEDS OUT. PARTS NOT IN STOCK			SCHEDULED SERVICE
1516644	2	11/30/2015	828	REPLC CURBSIDE LOWER BRAKE LIGHT			SCHEDULED SERVICE
2021141	1	10/26/2020	756	lube turn signal switch			OPERATOR COMPLAINT
2302250	9	01/28/2023	823	BRAKE LIGHT X2			SCHEDULED SERVICE
2302250	9	01/28/2023	828	BRAKE LIGHT X2			SCHEDULED SERVICE
1902347	5	02/08/2019	853	REPLCD LIGHT			SCHEDULED SERVICE
1902347	5	02/08/2019	832	REPLCD LIGHT			SCHEDULED SERVICE
2225708	4	08/25/2022	809	replace exsit light			OPERATOR COMPLAINT
2118433	1	07/21/2021	869	EXTERIOR LIGHTING--R/R BOTH UPPER/LOWER AMBER LIGHTS			MECHANIC DEFECT
1316719	2	12/26/2013	789	EXTERIOR LIGHTING			OPERATOR COMPLAINT

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: PB1301 to PB1301

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>				<u>Cause-Reason</u>
PB1301	1409	EXTERIOR LIGHTING	Total Line Count for System Code 1409 :			34
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>		
2010594	4	06/12/2020	800	LOW BEAMS -REPLACED	SCHEDULED SERVICE	
2322153	3	09/13/2023	894	R/R CLEARENCE LIGHT	SCHEDULED SERVICE	
2322153	3	09/13/2023	796	R/R CLEARENCE LIGHT	SCHEDULED SERVICE	
1615503	1	11/08/2016	797	EXTERIOR LIGHTING -R/R SIGNAL LIGHT ASSEMBLY	OPERATOR COMPLAINT	
2216609	1	05/25/2022	874	R/R LEFT SIDE WSTOP LIGHT	OPERATOR COMPLAINT	
2021158	7	10/27/2020	797	REPLCD FRONT/LEFT FRONT MARKER	SCHEDULED SERVICE	
1711950	7	07/11/2017	679	RR RIGHT LIGHT	OPERATOR COMPLAINT	
2208045	5	03/13/2022	828	replace dash lights	SCHEDULED SERVICE	
2127251	3	10/15/2021	859	R/R REAR MARKER LIGHT	SCHEDULED SERVICE	
1509512	1	07/07/2015	791	EXTERIOR LIGHTING-CK HEAD LIGHTS-OK	OPERATOR COMPLAINT	
1715885	1	09/03/2017	751	EXTERIOR -INSTALL FLASHING LIGHT KIT	SCHEDULED SERVICE	
1602127	2	02/17/2016	828	REPLACE STREET SIDE BRAKE LIGHT	SCHEDULED SERVICE	
2016013	3	08/19/2020	756	R/R STOP LAMP	SCHEDULED SERVICE	
2418363	14	08/03/2024	909	r/r marker lights	SCHEDULED SERVICE	
2021158	9	10/27/2020	797	REPLCD REAR RED LIGHT	SCHEDULED SERVICE	
1617704	2	12/23/2016	819	R/R RAMP LIGHT	SCHEDULED SERVICE	

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: PB1301 to PB1301

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>			<u>Cause-Reason</u>
PB1301	1410	INTERIOR LIGHTING	Total Line Count for System Code 1410 :		28
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	
1915019	3	08/20/2019	849	REPLCD FLOOR ISLE LIGHT	SCHEDULED SERVICE
1717579	4	09/29/2017	781	REPLACE DASH LIGHTS	SCHEDULED SERVICE
1605681	4	04/25/2016	809	REPLC DOME BULBS	SCHEDULED SERVICE
1701246	3	01/25/2017	781	R/R BULBS @INSTRUMENT PANELS	SCHEDULED SERVICE
2223716	5	08/02/2022	648	R/R DIFFERENT CONNECTION.	SCHEDULED SERVICE
1612957	2	09/13/2016	781	REPAIR 3 INSTRUMENT CONTROL LIGHTS	SCHEDULED SERVICE
1500016	2	01/05/2015	809	R/R DASH BULBS - R/R IGNITION SWITCH BULB	SCHEDULED SERVICE
1500016	2	01/05/2015	828	R/R DASH BULBS - R/R IGNITION SWITCH BULB	SCHEDULED SERVICE
1715363	4	09/01/2017	781	REPIARED INTERIOR LIGHT OVER WINDSHEILD WASHER TANK	SCHEDULED SERVICE
1822636	3	10/19/2018	837	R/R STEP LAMP	SCHEDULED SERVICE
2021158	4	10/27/2020	797	REPLCD 2 STEP LAMP & DASH LIGHTS	SCHEDULED SERVICE
1512533	2	09/08/2015	773	REPLACED DASH LIGHT BULB	SCHEDULED SERVICE
2013393	3	07/20/2020	781	REPAIRED DASH LIGHTS	SCHEDULED SERVICE
2100874	3	01/17/2021	809	R/R DASH B ULBS, IGNITION BULB	SCHEDULED SERVICE
2223716	4	08/02/2022	648	BLOWN FUSE	SCHEDULED SERVICE
1704308	4	03/15/2017	781	REPAIR INSTRUMENT CONTROL LIGHTS	SCHEDULED SERVICE
2108590	4	04/18/2021	869	R/R BOTH DASH BULBS	SCHEDULED SERVICE
2108590	4	04/18/2021	849	R/R BOTH DASH BULBS	SCHEDULED SERVICE

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: 1100 to 9700

Print Date: 3/25/2025

Asset# Range: PB1301 to PB1301

BUS#	SYS Code	SYS Code Description			Total Line Count for System Code 1410 :	28	Cause-Reason
PB1301	1410	INTERIOR LIGHTING					
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>			<u>SCHEDULED SERVICE</u>
1811403	2	06/01/2018	841	REPLCD LIGHTS ON DASH			SCHEDULED SERVICE
2114518	7	06/13/2021	869	CHECK INTERIOR LIGHTS--OK			SCHEDULED SERVICE
1410267	7	07/22/2014	818	REPLACED BULB IN DRIVERS SIDE PANEL			SCHEDULED SERVICE
1827559	3	12/28/2018	837	REPAIRED DASH LIGHTS			SCHEDULED SERVICE
2211758	2	04/14/2022	871	NO DASH LIGHT BULBS. OUT OF STOCK			SCHEDULED SERVICE
2308083	5	04/02/2023	832	replace dash lights			SCHEDULED SERVICE
1904977	2	03/18/2019	781	REPAIRED DASH LIGHTS			SCHEDULED SERVICE
1921419	3	11/19/2019	795	REPLCD DASH LIGHT--REPAIR DASH DIMMER			SCHEDULED SERVICE
1921419	3	11/19/2019	789	REPLCD DASH LIGHT--REPAIR DASH DIMMER			SCHEDULED SERVICE
2418363	16	08/03/2024	909	dash lights			SCHEDULED SERVICE
PB1301	1411	HORNS			Total Line Count for System Code 1411 :	7	Cause-Reason
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>			<u>SCHEDULED SERVICE</u>
1607566	2	05/31/2016	762	R/R BACK UP WARNING HORN			SCHEDULED SERVICE
2100874	6	01/17/2021	832	REPAIR DOOR ALARM			SCHEDULED SERVICE
2111697	3	05/19/2021	839	REPLCD HORN BUTTON			SCHEDULED SERVICE
1721998	3	12/07/2017	796	REPAIRED HOIRN			OPERATOR COMPLAINT
2305456	2	03/05/2023	778	r/r horn			SCHEDULED SERVICE
1722381	3	12/13/2017	778	REPAIRED HORN WIRE---OK			OPERATOR COMPLAINT
2114518	3	06/13/2021	869	R/R BACK UP HORN			SCHEDULED SERVICE

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024 System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: PB1301 to PB1301

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>			<u>Cause-Reason</u>
PB1301	1412	PASSENGER SIGNALS	Total Line Count for System Code 1412 :		3
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
2001055	3	01/21/2020	800	REGEN PULL CABLE	SCHEDULED SERVICE
1701246	4	01/25/2017	781	REPAIR PULL CORDS	SCHEDULED SERVICE
1605681	2	04/25/2016	809	r/r back up alarm	SCHEDULED SERVICE
PB1301	1413	ELEC.SYS.SWITCHES-BREAKER	Total Line Count for System Code 1413 :		7
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
1504820	2	03/24/2015	773	SECURED FAST IDLE SW	SCHEDULED SERVICE
1502134	2	02/06/2015	797	REPLACE FRONT MICRO DOOR SWITCH	OPERATOR COMPLAINT
1609490	2	07/05/2016	773	RR SENSOR	SCHEDULED SERVICE
1415202	2	10/20/2014	820	REMOVED/REPLACED BACK UP ALARM	SCHEDULED SERVICE
1607566	4	05/31/2016	762	TIGHTENED ALL LOOSE TOGGLE SWITCHES ON DRIVER DASH PANEL	SCHEDULED SERVICE
2304529	1	02/22/2023	648	VERIFIED	OPERATOR COMPLAINT
1403547	3	03/15/2014	773	R/R PROX SWITCH @THE RAMP	OPERATOR COMPLAINT
PB1301	1417	WIRING HARNESES	Total Line Count for System Code 1417 :		6
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
1919184	3	10/21/2019	800	REPAIR OPEN EMP WIRES IN REAR RUN BOX	SCHEDULED SERVICE
1711291	3	06/28/2017	828	CLEAN UP PLUG--CONNECT WITH TIE WRAP	OPERATOR COMPLAINT
2224296	3	08/10/2022	753	TIGHTENED ROUND CONNECTOR @ VOLTAGE REGULAOR, ALT STARTED CHARGE & CONTINUED W/	OPERATOR COMPLAINT
1823022	2	01/16/2019	753	R/R JUMPER SENSOR HARNESS & PARTIC FILTER SENSOR MODULE HARNESS	OPERATOR COMPLAINT
1907132	2	04/17/2019	837	secure alternator wire cable to regulator	OPERATOR COMPLAINT
1609162	4	06/28/2016	786	REPAIRED HARNESS TO BOTTOM SENSOR	OPERATOR COMPLAINT

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: 1100 to 9700

Print Date: 3/25/2025

Asset# Range: PB1301 to PB1301

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>			<u>Cause-Reason</u>
PB1301	1418	INSTRUMENTS & GAUGES	Total Line Count for System Code 1418 :		2
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
1819701	7	09/11/2018	828	REPLCD ENGINE COMP OIL PRESSURE GAUGE	SCHEDULED SERVICE
1808204	1	04/24/2018	753	INSTALL TOGGLE EXTENSION	OPERATOR COMPLAINT
PB1301	1422	DOOR ELECTRICAL SYSTEMS	Total Line Count for System Code 1422 :		1
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
1502210	2	02/10/2015	797	REPLACE FRONT DOOR ELECTRICAL VALVE	OPERATOR COMPLAINT
PB1301	1427	R/R CANCEIVER ANTENNA	Total Line Count for System Code 1427 :		2
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
1614931	1	10/22/2016	773	R/R CANCEIVER ANTENNA	EQUIPMENT CONVERSION
1614931	1	10/22/2016	818	R/R CANCEIVER ANTENNA	EQUIPMENT CONVERSION
PB1301	1428	REPROGRAM CANCEIVER	Total Line Count for System Code 1428 :		1
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
1310022	2	08/14/2013	732	REPROGRAM CANCEIVER	SCHEDULED SERVICE
PB1301	1429	REPAIR DPIM	Total Line Count for System Code 1429 :		1
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
2024770	3	12/16/2020	853	REPLACE LOCK FOR BATTEREY DOOR	SCHEDULED SERVICE

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024 System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: PB1301 to PB1301

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>			<u>Cause-Reason</u>
PB1301	1500	WHEEL CHAIR RAMPS / QUANTUM	Total Line Count for System Code 1500 :		9
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	
2107941	1	04/09/2021	874	TROUBLESHOOT QUANTUM--CKD MOTHERBOARD, MODULE--FOUND RESET BUTTON PUSHED IN/R/	OPERATOR COMPLAINT
1509458	1	07/07/2015	820	WHEEL CHAIR LIFTS/RAMPS - OPEN FOUND DIRTY, CLEANED , CHECK SENSOR , FOUND PROX SWIT	OPERATOR COMPLAINT
2215435	7	05/16/2022	833	W/C RAMP DROP DOWN FEATURE IS NOT WORKING DUE TO BROKEN LATCH AND LOCK SOLINOID H.	SCHEDULED SERVICE
2215435	7	05/16/2022	820	W/C RAMP DROP DOWN FEATURE IS NOT WORKING DUE TO BROKEN LATCH AND LOCK SOLINOID H.	SCHEDULED SERVICE
1706410	4	04/18/2017	809	R/R SIDE SUNVISOR	SCHEDULED SERVICE
2219725	10	06/24/2022	797	INSTALL SUPPORT SWITCH & ADJUST WHEEL CHAIR RAMP LOCKS	SCHEDULED SERVICE
1905169	2	03/19/2019	752	CHEKC W/C RAMP REPLCE MOTOR ON ADJ	OPERATOR COMPLAINT
2215435	8	05/16/2022	874	SWAPPED W/C RAMP FROM PB1303 TO PB1301	SCHEDULED SERVICE
2100874	4	01/17/2021	809	SECURED WHEELCHAIR RAMP TRIM	SCHEDULED SERVICE
PB1301	1501	TS:WHEELCHAIR RAMP / QUANTUM	Total Line Count for System Code 1501 :		9
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	
1814948	1	07/16/2018	752	T*/S W/C LIFT RAMP	OPERATOR COMPLAINT
2112218	1	05/24/2021	874	Adjusted Wheelchair Ramp latch sensors	OPERATOR COMPLAINT
1902875	1	02/12/2019	797	TS:WHEELCHAIR LIFT/RAMP---LUBE/ADJUST RAMP & CHAIN	OPERATOR COMPLAINT
1502436	1	02/11/2015	809	TS: WHEELCHAIR LIFT/RAMP - FOUND DEFECTIVE PROXIMITY SWITCH	OPERATOR COMPLAINT
2132760	5	12/01/2021	832	CLEANED AND LUBE WC RAMP	SCHEDULED SERVICE
2132760	5	12/01/2021	849	CLEANED AND LUBE WC RAMP	SCHEDULED SERVICE
1905169	1	03/19/2019	752	T/S W/C LEFT /RAMP	OPERATOR COMPLAINT
2108333	1	04/14/2021	832	RETIGHTENED BASE OF RAMP	OPERATOR COMPLAINT
2110158	2	05/01/2021	874	TSHOOT WHEELCHAIR RAMP--NO ISSUE FOUND	OPERATOR COMPLAINT

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024 System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: PB1301 to PB1301

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>			<u>Cause-Reason</u>
PB1301	1503	WHEEL CHAIR LIFT/RAMP ADJ	Total Line Count for System Code 1503 :		2
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
2427386	2	11/07/2024	849	Adjusted lock cams to tighten ramp when closed.	OPERATOR COMPLAINT
1911051	3	06/17/2019	762	CKD OPERATION OF W/CHAIR RAMP--CLEAN/RESET	SCHEDULED SERVICE
PB1301	1504	WHEELCHAIR/LIFT/RAMP ELEC	Total Line Count for System Code 1504 :		1
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
1502436	2	02/11/2015	809	R/R PROXIMITY SWITCH AND ADJUSTED SWITCH	OPERATOR COMPLAINT
PB1301	1506	WC LIFT/RAMP MECHANICAL S	Total Line Count for System Code 1506 :		2
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
2001055	2	01/21/2020	800	W/C RAMP ADJ	SCHEDULED SERVICE
1919511	3	10/21/2019	762	CKD/REMV RISER PLATE--LUBED LATCHES & SOLENOID LINAGES--REINSTALLED RISER PLATE	OPERATOR COMPLAINT
PB1301	1509	WHEEL CHAIR RAMP BELT	Total Line Count for System Code 1509 :		1
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
2104937	3	03/08/2021	752	REPLCD PROX SWITCH	OPERATOR COMPLAINT

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: 1100 to 9700

Print Date: 3/25/2025

Asset# Range: PB1301 to PB1301

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>			<u>Cause-Reason</u>
PB1301	1600	AMEREX FIRE SYSTEM	Total Line Count for System Code 1600 :		14
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>SCHEDULED SERVICE</u>
2417030	4	07/19/2024	809	R/R alarm bell.	
1513621	4	10/02/2015	778	reset fire detection	OPERATOR COMPLAINT
1720113	2	11/07/2017	849	INSTALL NEW TAMPER TAG ON FIRE BUTTON	SCHEDULED SERVICE
1819701	6	09/11/2018	828	REPLCD FIRE EXT BOTTLE	SCHEDULED SERVICE
2308083	3	04/02/2023	832	install tamper tag	SCHEDULED SERVICE
2016013	2	08/19/2020	756	REPLCD TAMPER TAG	SCHEDULED SERVICE
2418363	11	08/03/2024	909	r/r amerex nozzle cap	SCHEDULED SERVICE
1902347	6	02/08/2019	853	INSTALLED NEW TAMPER TAG	SCHEDULED SERVICE
1902347	6	02/08/2019	832	INSTALLED NEW TAMPER TAG	SCHEDULED SERVICE
2108590	10	04/18/2021	869	RECONNECTED FIRE WIRE	SCHEDULED SERVICE
2108590	10	04/18/2021	849	RECONNECTED FIRE WIRE	SCHEDULED SERVICE
1816746	3	08/06/2018	781	INSTALLED TAMPER TAG ON AMEREX FIRE CINTROL LEFT OF DRIER	SCHEDULED SERVICE
1706410	5	04/18/2017	809	INSTALLED FIRE PIN TAMPER	SCHEDULED SERVICE
1720113	7	11/07/2017	849	RECONNECT FIRE WIRE HARNESS WAS WAS FOUND LOOSE	SCHEDULED SERVICE
PB1301	1602	BOTTLE REPLACE	Total Line Count for System Code 1602 :		1
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>OPERATOR COMPLAINT</u>
1513785	2	10/06/2015	756	AMEREX SYSTEM	
PB1301	1603	THERMO SENSORS REPLACE	Total Line Count for System Code 1603 :		1
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>SCHEDULED SERVICE</u>
2109458	3	04/25/2021	828	REPLCD FIRE SYSTEM HARNESS & SENSOR	

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024 System Code Range: 1100 to 9700

Print Date: 3/25/2025

Asset# Range: PB1301 to PB1301

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>			<u>Cause-Reason</u>
PB1301	1606	CONTROL HEAD REPLACE	Total Line Count for System Code 1606 :		1
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
1513785	4	10/06/2015	756	replace control	OPERATOR COMPLAINT
PB1301	1608	GILLIG FIRE SYSTEM REPAIR	Total Line Count for System Code 1608 :		1
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
1514753	3	10/23/2015	828	REPLC GILLIG FIRE SUPPRESSION TAMPER SEAL	SCHEDULED SERVICE
PB1301	1609	AMEREX FIRE SYSTEM PM	Total Line Count for System Code 1609 :		1
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
2417027	1	07/18/2024	809	pm	SCHEDULED SERVICE
PB1301	2106	REPAIR ARTIC JOINT CYLINDER	Total Line Count for System Code 2106 :		2
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
2419520	4	08/15/2024	880	ck brake system found leaking r-12 valve	OPERATOR COMPLAINT
2419520	4	08/15/2024	926	ck brake system found leaking r-12 valve	OPERATOR COMPLAINT
PB1301	2200	STEERING SYSTEMS	Total Line Count for System Code 2200 :		2
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
2114518	8	06/13/2021	869	CK POWER STEERING FLUID FOR LEAKS--NO LEAKS JUST DIRTY	SCHEDULED SERVICE
1818671	1	10/11/2018	852	t/s engien-active code for particulated filter temp module burnt harness to temp module	OPERATOR COMPLAINT
PB1301	2201	TROUBLESHOOT STEERING SYS	Total Line Count for System Code 2201 :		3
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
1714895	1	08/17/2017	773	TROUBLESHOOT STEERING SYS - SECURED HARD STEERING	MECHANIC DEFECT
1608815	1	06/22/2016	791	TROUBLESHOOT STEERING SYSTEM--	OPERATOR COMPLAINT
2211758	4	04/14/2022	871	CHECK GEARBOX AND DRAG LINK	SCHEDULED SERVICE
PB1301	2210	STEERING SYS LINES/HOSES	Total Line Count for System Code 2210 :		1
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
1819701	5	09/11/2018	828	REPLCD P/S PUMP HOSE	SCHEDULED SERVICE
PB1301	2220	PWR STEERING PUMP REPLACE	Total Line Count for System Code 2220 :		1
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
2122378	3	08/29/2021	837	INSTALLED P/STEERING PUMP--FILLED ALL FLUIDS--CLEARED CODES--ECM NEEDS UPDATE	OPERATOR COMPLAINT

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: PB1301 to PB1301

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>					
PB1301	2300	SUSPENSION SYSTEM			Total Line Count for System Code 2300 :	3	Cause-Reason
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>			SCHEDULED SERVICE
1825167	2	11/21/2018	833	REPLCD RIGHT REAR BELLOW			SCHEDULED SERVICE
2004459	3	03/16/2020	756	TIGHTEN AIR BELOOW BOLT			SCHEDULED SERVICE
1508321	4	06/04/2015	828	TIGHTEN FRONT SHOCKS			SCHEDULED SERVICE
PB1301	2302	FRONT AIR BELLOWS REPL			Total Line Count for System Code 2302 :	4	Cause-Reason
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>			SCHEDULED SERVICE
1822636	7	10/19/2018	781	R/R CURB/FRONT SIDE BELLOWS			OPERATOR COMPLAINT
2229218	3	10/05/2022	828	REPLACE RT FRONT AIR BAGS			SCHEDULED SERVICE
2305456	7	03/05/2023	849	R/R FRONT LEFT AIR BELLOW			OPERATOR COMPLAINT
1715663	3	08/28/2017	800	RR FRONT ROAD SIDE REAR AIR BAG			
PB1301	2303	LEVELING VALVE ADJ			Total Line Count for System Code 2303 :	1	Cause-Reason
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>			SCHEDULED SERVICE
2100874	11	01/17/2021	832	adjusted leveling valve			
PB1301	2304	LEVELING VALVE REPL			Total Line Count for System Code 2304 :	2	Cause-Reason
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>			SCHEDULED SERVICE
2108590	3	04/18/2021	869	R/R LEVELING VALVE			SCHEDULED SERVICE
2108590	3	04/18/2021	849	R/R LEVELING VALVE			

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: **PB1301** to **PB1301**

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>			<u>Cause-Reason</u>
PB1301	2309	REAR AIR BELLOWS REPLACE	Total Line Count for System Code 2309 :		7
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
1822636	8	10/19/2018	781	FOUND REAR AIR BELLOWS NEED REPLC	SCHEDULED SERVICE
1822636	9	10/19/2018	752	R//R AIR BAG IS NOT LEAKING	SCHEDULED SERVICE
1923274	3	12/18/2019	780	REAIRED ROADSIDE FRONT REAR END AIR BELLOWS	SCHEDULED SERVICE
2132760	2	12/01/2021	832	REPLACE AIR BELLOWS	SCHEDULED SERVICE
2132760	2	12/01/2021	849	REPLACE AIR BELLOWS	SCHEDULED SERVICE
2302250	4	01/28/2023	820	R/R R/R AIR BELLOW	SCHEDULED SERVICE
1815807	1	07/23/2018	824	REAR AIR BELLOWS REPLCD	OPERATOR COMPLAINT
PB1301	2310	RADIUS RODS REPLACE	Total Line Count for System Code 2310 :		1
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
1915019	7	08/20/2019	828	CK TORQUE ROD--ROAD TEST--OK	SCHEDULED SERVICE
PB1301	2400	CHASSIS/HUBS	Total Line Count for System Code 2400 :		6
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
1704087	2	03/10/2017	747	R/R LF HUB COVER & GASKET AND OIL	OPERATOR COMPLAINT
2121073	2	08/17/2021	869	R/R BOTH DIFF PLUGS--TOP OFF FLUID	SCHEDULED SERVICE
1604062	2	03/21/2016	820	RR FRONT HUB CAP	SCHEDULED SERVICE
1502783	4	02/18/2015	828	FILL UP HUBS AND REPLACE PLUGS	SCHEDULED SERVICE
1902659	3	02/08/2019	781	RR FRONT HUBCAP ASSYM	OPERATOR COMPLAINT
2023913	2	12/09/2020	797	REMOVE/CHECK TIRE SIZE--DIFFERENT FROM 2004 STUB--REINSTALL & TAP INSTALL NEW NUT	SCHEDULED SERVICE

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: 1100 to 9700

Print Date: 3/25/2025

Asset# Range: PB1301 to PB1301

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>			<u>Cause-Reason</u>
PB1301	2402	FRONT HUB	Total Line Count for System Code 2402 :		3
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>SCHEDULED SERVICE</u>
2418363	4	08/03/2024	832	r/r front hub cap	SCHEDULED SERVICE
1902347	2	02/08/2019	849	R/R FRONT HUB CAP SCREW	SCHEDULED SERVICE
1410267	3	07/22/2014	818	REMOVED FRONT HUB CAPS/TORQUED BOTH FRONT SPINDLE NUTS LEFT/RIGHT TO SPECS	SCHEDULED SERVICE
PB1301	2404	FRONT HUB SEALS REPL	Total Line Count for System Code 2404 :		1
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>SCHEDULED SERVICE</u>
1704308	5	03/15/2017	819	R/R HUB SEAL, BEARING & RACES	SCHEDULED SERVICE
PB1301	2406	DIFFERENTIAL REPLACE	Total Line Count for System Code 2406 :		1
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>SCHEDULED SERVICE</u>
1923274	6	12/18/2019	781	CLEARED DIFFON WASH RACK	SCHEDULED SERVICE
PB1301	2412	REPL DIFFERENTIAL PINION SEAL	Total Line Count for System Code 2412 :		4
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>SCHEDULED SERVICE</u>
2013393	17	07/20/2020	837	R/R PINION SEAL	SCHEDULED SERVICE
2016013	4	08/19/2020	756	R/R PINION SEAL	SCHEDULED SERVICE
2002648	8	02/18/2020	837	RR PINON SEAL	SCHEDULED SERVICE
2021158	21	10/27/2020	837	R/R DIFF PINION SEAL	SCHEDULED SERVICE

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: PB1301 to PB1301

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>				<u>Cause-Reason</u>
PB1301	2500	BODY	Total Line Count for System Code 2500 :			136
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>		
2125711	3	10/02/2021	869	CHECK/ADJUST SPRINGS--LUBE DOOR	OPERATOR COMPLAINT	
2125711	3	10/02/2021	833	CHECK/ADJUST SPRINGS--LUBE DOOR	OPERATOR COMPLAINT	
1904977	4	03/18/2019	781	REPAIRED HINGES ON ENGINE GUARD	SCHEDULED SERVICE	
2108590	6	04/18/2021	869	REAJUST WIEOR BLADE LF	SCHEDULED SERVICE	
2108590	6	04/18/2021	849	REAJUST WIEOR BLADE LF	SCHEDULED SERVICE	
2302250	3	01/28/2023	820	R/R L/S DRIVERS SHADE	SCHEDULED SERVICE	
1502783	5	02/18/2015	828	FIX DRIVER'S WINDOW SUNVISOR	SCHEDULED SERVICE	
2206892	2	03/01/2022	887	REPAIR PANEL AND REINSTALL	OPERATOR COMPLAINT	
1819701	2	09/11/2018	828	REPLCD DRIVER SUNSHADE	SCHEDULED SERVICE	
2021158	11	10/27/2020	797	REPLCD DRIVER COMP LATCH	SCHEDULED SERVICE	
2021158	6	10/27/2020	797	REPLCD BREAKAWY PLASTIC GLASS	SCHEDULED SERVICE	
2217250	1	05/31/2022	887	REPAIR/ PAINT FRONT BUMPER. PAINT WIPER AND BIKE RACK	OPERATOR COMPLAINT	
2418363	10	08/03/2024	832	repair entrance door trim	SCHEDULED SERVICE	
1715363	2	09/01/2017	781	RR ROAD SIDE SUNVISOR -REPAIR LOOSE WINDOW LATCHES	SCHEDULED SERVICE	
2418363	9	08/03/2024	832	lube seat latch	SCHEDULED SERVICE	
2132760	6	12/01/2021	832	SANITAITION BOTTLE- REFILL AND REPLACE BATTERIES	SCHEDULED SERVICE	
1806209	2	04/03/2018	828	REPLCD DRIVER WINDOW SHADE	SCHEDULED SERVICE	
1717579	2	09/29/2017	781	REPLACED ROADSIDE SUNVISOR	SCHEDULED SERVICE	

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: 1100 to 9700

Print Date: 3/25/2025

Asset# Range: PB1301 to PB1301

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>				<u>Cause-Reason</u>
PB1301	2500	BODY	Total Line Count for System Code 2500 :			136
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>		
1712977	2	07/21/2017	828	REPAIR DRIVERS WINDOW SUNSHADE		OPERATOR COMPLAINT
2018029	3	09/14/2020	747	TROUBLESHOOT & REPAIRED DOORS/ADJUSTED & LUBED--CLEANED		OPERATOR COMPLAINT
2427748	3	11/12/2024	911	parts charge		OPERATOR COMPLAINT
2418353	2	08/01/2024	809	parts charge		OPERATOR COMPLAINT
2418363	6	08/03/2024	832	sunvisor		SCHEDULED SERVICE
2118274	9	07/20/2021	869	ADJUST WIPERS		SCHEDULED SERVICE
1416992	3	11/20/2014	820	REMOVED/REPLACED LEFTSIDE SUNVISOR		SCHEDULED SERVICE
2100602	1	01/12/2021	853	REPLCD SUN SHADE		OPERATOR COMPLAINT
2418363	8	08/03/2024	832	repair w/c ratchet		SCHEDULED SERVICE
2226971	3	09/08/2022	820	repair sunvisor		SCHEDULED SERVICE
2226971	3	09/08/2022	833	repair sunvisor		SCHEDULED SERVICE
1502472	1	02/12/2015	819	BODY - FIND WINDOW LATCH MISSING SPRING (DRIVERS REAR WINDOW)		OPERATOR COMPLAINT
2208045	6	03/13/2022	828	replace batteries on hand sanitizer, still not working, dispenser no part in stock		SCHEDULED SERVICE
1915019	4	08/20/2019	849	LUBED C/SIDE EMERGENCY WINDOW LATCH		SCHEDULED SERVICE
1915019	6	08/20/2019	828	NO HARDWARE IN STOCK FOR SEAT BOTTOM		SCHEDULED SERVICE
1702007	1	02/03/2017	841	BODY---REPLC MISSING ROD---ADJUSTED SUNVISOR		OPERATOR COMPLAINT
1516644	9	11/30/2015	809	R/R REAR REFLECTOR		SCHEDULED SERVICE
2206042	1	02/20/2022	887	REPAIR WATER LEAK IN FRONT THE QUANTUM AND EXIT DOOR		OPERATOR COMPLAINT

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: PB1301 to PB1301

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>				<u>Cause-Reason</u>
PB1301	2500	BODY	Total Line Count for System Code 2500 :			136
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>		
1508954	1	06/19/2015	631	BODY - RAIL @ ENTRANCE DOOR SECURED	OPERATOR COMPLAINT	
					SCHEDULED SERVICE	
2121073	4	08/17/2021	869	REFILL HAND SANITIZER	OPERATOR COMPLAINT	
1818056	3	08/21/2018	644	MOP FLOOR	ACCIDENT	
2105797	1	03/16/2021	780	REPLCD DESTINATION SIGN---GLASS-- R/R DESTINATION GLASS & CLEAN/REMOVE BROKEN GLAS	ACCIDENT	
2105797	1	03/16/2021	837	REPLCD DESTINATION SIGN---GLASS-- R/R DESTINATION GLASS & CLEAN/REMOVE BROKEN GLAS	SCHEDULED SERVICE	
1704308	2	03/15/2017	781	R/R ROAD SIDE SUN VISOR	SCHEDULED SERVICE	
1921419	11	11/19/2019	795	CLEAN GRAFFIT ON SEAT	OPERATOR COMPLAINT	
1502307	2	02/11/2015	643	TROUBLESHOOT THE DOOR	SCHEDULED SERVICE	
1800959	4	01/22/2018	832	REPLACE WASHER NOZZLE	SCHEDULED SERVICE	
2219725	3	06/24/2022	839	LUBE LATCH ON R/R ENGINE DOOR	OPERATOR COMPLAINT	
1409240	1	07/06/2014	791	BODY- R/R ROADSIDE VISOR	SCHEDULED SERVICE	
1800959	2	01/22/2018	825	REPAIR DRIVERS WINDOW SHADE	SCHEDULED SERVICE	
1717579	5	09/29/2017	781	REPAIR CURBSIDE ENGINE DOOR	SCHEDULED SERVICE	
2228486	1	09/25/2022	887	REPAIR CENTER POLE BETWEEN WINDSHIELD	OPERATOR COMPLAINT	
2016958	6	09/02/2020	820	R/R DRIVER SUNVISOR	SCHEDULED SERVICE	
1504820	3	03/24/2015	773	REPLACED SUN VISOR	OPERATOR COMPLAINT	
1516609	1	11/29/2015	756	INSTALL BOOK HOLDER	SCHEDULED SERVICE	
2100874	9	01/17/2021	832	REPAIRED VENT TUBE--installed enw clamp		

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: **PB1301** to **PB1301**

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>				<u>Cause-Reason</u>
PB1301	2500	BODY	Total Line Count for System Code 2500 :			136
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>		
1600223	3	01/11/2016	820	REMOPVED GRAFFITTI	SCHEDULED SERVICE	
2121073	3	08/17/2021	869	CLEAN SEATS/GRAFITTI	SCHEDULED SERVICE	
2011654	1	06/24/2020	853	BODY----REPAIR	OPERATOR COMPLAINT	
2013393	9	07/20/2020	781	REMOVE GRAFITTI FROM REAR SEATS	SCHEDULED SERVICE	
1804075	3	03/05/2018	809	R/R SIDE SUNSCREEN	SCHEDULED SERVICE	
1720113	6	11/07/2017	849	GRAFFITI ON REAR SEAT CLEARED OFF	SCHEDULED SERVICE	
2124040	4	09/14/2021	874	R/R DRIVER SUNSHADE	SCHEDULED SERVICE	
1400775	4	01/21/2014	814	WD40 WINDOWS,CABLES,LATCHES, VACUUM/WASH OUT RAMP	SCHEDULED SERVICE	
2228659	3	09/27/2022	887	REPAIR A HOLE IN THE ROOF ABOVE THE DRIVER SEAT WITH FIBER GLASS.	OPERATOR COMPLAINT	
2222423	1	07/18/2022	887	body	OPERATOR COMPLAINT	
1611309	4	08/09/2016	820	REMPVED GRAFFITIFROM SEAT	SCHEDULED SERVICE	
2103029	6	03/03/2021	849	TIGHTEN LOOSE INTERIOR MIRRORS	SCHEDULED SERVICE	
2103029	6	03/03/2021	797	TIGHTEN LOOSE INTERIOR MIRRORS	SCHEDULED SERVICE	
1612957	5	09/13/2016	781	REMOVED GRAFFITTI 3 CURBSIDE SEATS	SCHEDULED SERVICE	
1414678	1	10/08/2014	781	BODY - REMOVE GRAFFITTI FROM ROADSIDE SEAT	OPERATOR COMPLAINT	
1508321	3	06/04/2015	828	REPLC GUIDE BOOK HOLDER	SCHEDULED SERVICE	
1912904	3	07/15/2019	799	REPAIR SUNVISOR	SCHEDULED SERVICE	
1415369	1	10/21/2014	760	BODY -SECURE BRACKET AT PASS WINDOW	OPERATOR COMPLAINT	

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: PB1301 to PB1301

BUS#	SYS Code	SYS Code Description			Total Line Count for System Code 2500 :	136	Cause-Reason
PB1301	2500	BODY					
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>			
2100874	2	01/17/2021	809	INSTALLED REAR REFLECTOR	SCHEDULED SERVICE		
2021158	2	10/27/2020	780	ADJUST SIGNAL WIRING--SCREW FRONT WHEEL WELL PANELS IN PLACE	SCHEDULED SERVICE		
2013891	3	07/27/2020	797	CK/LUBRICATE DOOR LOCK & HINGES	OPERATOR COMPLAINT		
1923274	4	12/18/2019	781	SECURED MIRROR AT WINDSHIELD	SCHEDULED SERVICE		
2103029	7	03/03/2021	849	REPAIR WINDOW FRAME	SCHEDULED SERVICE		
2103029	7	03/03/2021	797	REPAIR WINDOW FRAME	SCHEDULED SERVICE		
1415202	9	10/20/2014	820	REMOVED GRAFFITI ON 4 SEATS	SCHEDULED SERVICE		
1827559	4	12/28/2018	837	REPAIRED WINDOW SHADE	SCHEDULED SERVICE		
1913761	3	07/29/2019	752	CLOSED PANNEL	OPERATOR COMPLAINT		
1408616	2	06/19/2014	796	R/R SUN VISOR	SCHEDULED SERVICE		
2103029	3	03/03/2021	849	INSTALL TAMPER TAG	SCHEDULED SERVICE		
2103029	3	03/03/2021	797	INSTALL TAMPER TAG	SCHEDULED SERVICE		
2114518	5	06/13/2021	869	R/R BOTH WIPER SADDLES	SCHEDULED SERVICE		
1804075	4	03/05/2018	809	INSTALLED AC FILTER HOLDER CLIP	OPERATOR COMPLAINT		
1315025	2	11/21/2013	813	ADJUSTED DOORS	SCHEDULED SERVICE		
2118274	3	07/20/2021	869	INSTALL NEW SIDE ROD FOR FRONT SHADE	SCHEDULED SERVICE		
2204184	3	02/07/2022	828	REPLACE LATCH	SCHEDULED SERVICE		
2125711	2	10/02/2021	887	POLISH WINDSHIELD AT WINDSIELD	OPERATOR COMPLAINT		

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: **PB1301** to **PB1301**

BUS#	SYS Code	SYS Code Description				Total Line Count for System Code 2500 :	136	Cause-Reason
PB1301	2500	BODY						
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>				<u>Cause-Reason</u>
1414594	1	10/07/2014	791	BODY - INSTALL TRAINAGLES				OPERATOR COMPLAINT
1315639	2	12/03/2013	759	CHECK BIKE RACK				OPERATOR COMPLAINT
1607566	3	05/31/2016	762	R/R DRIVER SUNSHADE				SCHEDULED SERVICE
2013393	8	07/20/2020	781	R/R EXHAUST BELLOW & CLAMPS				SCHEDULED SERVICE
1816746	6	08/06/2018	781	REMOVED GRAFFITTI				SCHEDULED SERVICE
1316028	1	12/12/2013	814	BODY - DRILL OUT HOLES AND RE-BOLT 1 NEW ROCKER LATCH				OPERATOR COMPLAINT
2021158	10	10/27/2020	797	REPLCD DRIVER SHADE				SCHEDULED SERVICE
1516644	5	11/30/2015	828	R/R DRIVER WINDOW SHADE-REPLC WCHAIR RAMP BAR				SCHEDULED SERVICE
2325773	1	10/24/2023	887	REPAIR THE FLOOR IN THE LAST TWO ROWS.				OPERATOR COMPLAINT
1710659	2	06/20/2017	809	R/R ACESS DOIOR HANDLE				SCHEDULED SERVICE
2219725	6	06/24/2022	797	R/R RIGHT REAR ENGINE DOOR SPRING				SCHEDULED SERVICE
1516101	2	11/16/2015	756	R/R BOOK HOLDER				OPERATOR COMPLAINT
2106173	9	03/22/2021	869	R/R NEW BULB FOR AC SWITCH ON DASH				SCHEDULED SERVICE
2106173	9	03/22/2021	832	R/R NEW BULB FOR AC SWITCH ON DASH				SCHEDULED SERVICE
2114518	4	06/13/2021	869	R/R SUNSHADE				SCHEDULED SERVICE
1804075	5	03/05/2018	809	R/R ENGINE ACCESS DOOR HANDLE--TIGHTEN BATTERY HOLD-DOWN				SCHEDULED SERVICE
1607566	5	05/31/2016	762	TIGHTENED DRIVER/PSGR WINDOW				SCHEDULED SERVICE
1507948	1	05/27/2015	760	ADJUST SIDE SHADES				OPERATOR COMPLAINT

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: **PB1301** to **PB1301**

BUS#	SYS Code	SYS Code Description				Total Line Count for System Code 2500 :	136	Cause-Reason
PB1301	2500	BODY						
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>				<u>SCHEDULED SERVICE</u>
2008248	4	05/11/2020	781	RR ROADSIDE SUNVISOR				
2227813	1	09/17/2022	887	REPAIR WATER LEAK				OPERATOR COMPLAINT
2118274	4	07/20/2021	869	INSTALL CORD ON L/S SHADE				SCHEDULED SERVICE
1915019	10	08/20/2019	780	R/R LEFT REAR RUBBER FENDER				SCHEDULED SERVICE
2308083	4	04/02/2023	832	repair drivers sunvisor				SCHEDULED SERVICE
2204184	2	02/07/2022	828	REPLACE SIDE SCREEN				SCHEDULED SERVICE
1602127	5	02/17/2016	773	SECURED DRIVER SUNVISOR				SCHEDULED SERVICE
1921419	10	11/19/2019	795	REPLCD SUNSHADE				SCHEDULED SERVICE
1921419	10	11/19/2019	789	REPLCD SUNSHADE				SCHEDULED SERVICE
2302250	5	01/28/2023	820	R/R HAND SANITIZER DISPENSER				SCHEDULED SERVICE
1915019	8	08/20/2019	828	REPLCD ENGINE DOOR RINGS				SCHEDULED SERVICE
1710659	3	06/20/2017	809	SECURED DASH PANELS--REMVD GRAFITTI FROM SEAT				SCHEDULED SERVICE
1415202	7	10/20/2014	773	INSTALLED DRIVER SIDE SUNVISOR				SCHEDULED SERVICE
2106173	5	03/22/2021	869	CLEAN WASHER HOSES---REPLC R/F HOSE & NOZZLE				SCHEDULED SERVICE
2106173	5	03/22/2021	832	CLEAN WASHER HOSES---REPLC R/F HOSE & NOZZLE				SCHEDULED SERVICE
2106173	6	03/22/2021	869	R/R SIDE SCREEN				SCHEDULED SERVICE
2106173	6	03/22/2021	832	R/R SIDE SCREEN				SCHEDULED SERVICE
2231100	4	10/26/2022	778	refil sanitizer				SCHEDULED SERVICE

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: 1100 to 9700

Print Date: 3/25/2025

Asset# Range: PB1301 to PB1301

BUS#	SYS Code	SYS Code Description		Total Line Count for System Code 2500 :	136	Cause-Reason
PB1301	2500	BODY				
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>		<u>Cause-Reason</u>
2008248	8	05/11/2020	781	RR FRONT SUNVISOR		SCHEDULED SERVICE
2002648	4	02/18/2020	837	RR DRIBERS WINDOW SHADE		SCHEDULED SERVICE
2114518	6	06/13/2021	869	ADJUST REAR DOOR HANDLE		SCHEDULED SERVICE
1722193	2	12/12/2017	849	REPAIRED ROAD SIDE WINDOW SHADE		SCHEDULED SERVICE
2216977	2	06/02/2022	839	INSTALL NEW KNOB & E-CLIP		SCHEDULED SERVICE
1416992	2	11/20/2014	820	REMOVED/REPLACED MANUAL DOOR RELEASE WINDOW (FOUND BROKEN)		SCHEDULED SERVICE
2013393	4	07/20/2020	781	REPAIRED WHEELCHAIR RAMP TRIM		SCHEDULED SERVICE
2118274	5	07/20/2021	869	ADJUST TRIANGLE BOX		SCHEDULED SERVICE
1814112	3	07/05/2018	841	REPAIRED DRIVER SUNVISOR		SCHEDULED SERVICE
1816746	4	08/06/2018	781	REPAIRED ROAD SIDE SUNVISOR		SCHEDULED SERVICE
PB1301	2501	ACCIDENT DAMAGE REPAIR		Total Line Count for System Code 2501 :	8	Cause-Reason
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>		<u>Cause-Reason</u>
1801743	4	02/09/2018	759	ACCIDENT DAMAGE/REPAIRED FRONT/BACK BUMPER		ACCIDENT
1801743	4	02/09/2018	808	ACCIDENT DAMAGE/REPAIRED FRONT/BACK BUMPER		ACCIDENT
1708902	1	05/23/2017	808	ACCIDENT DAMAGE REPAIR--LEFT SIDE REAR PANEL REPLACED & LEFT SIDE BUMPER MODULE		OPERATOR COMPLAINT
1708902	1	05/23/2017	759	ACCIDENT DAMAGE REPAIR--LEFT SIDE REAR PANEL REPLACED & LEFT SIDE BUMPER MODULE		OPERATOR COMPLAINT
1721016	1	11/20/2017	780	ACCIDENT DAMAGE REPAIR--CK PANEL--INSTALL REFLECTOR		ACCIDENT
1721016	2	11/20/2017	780	R/R RADIATOR PANEL--SAND/PAINT LEFT REAR WHEEL-WELL PANEL		ACCIDENT
1704087	1	03/10/2017	780	ACCIDENT DAMAGE REPAIR---R/R BATTERY PANEL--R/R FRONT WHEEL WELL/USED PART		ACCIDENT
1704087	1	03/10/2017	808	ACCIDENT DAMAGE REPAIR---R/R BATTERY PANEL--R/R FRONT WHEEL WELL/USED PART		ACCIDENT

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: **PB1301** to **PB1301**

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>			<u>Total Line Count for System Code 2502 :</u>	<u>9</u>	<u>Cause-Reason</u>
PB1301	2502	BODY REPAIR GENERAL/SCHED					
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>			<u>OPERATOR COMPLAINT</u>
1904502	1	03/06/2019	759	REPAIR WINDSHIELD RAIL			OPERATOR COMPLAINT
1904502	1	03/06/2019	808	REPAIR WINDSHIELD RAIL			SCHEDULED SERVICE
2024770	5	12/16/2020	853	REPAIR DDOOR FOR BATTERY			OPERATOR COMPLAINT
2206892	1	03/01/2022	887	DISASSEMBLE TAIL LIGHT FOR REPAIR			OPERATOR COMPLAINT
1820571	1	09/20/2018	746	REPAIRED DRIVER SHADE			SCHEDULED SERVICE
2013393	16	07/20/2020	837	R/R MUD FLAP			SCHEDULED SERVICE
1921419	13	11/19/2019	808	R/R REAR WHEEL WELL MOLDINGS			OPERATOR COMPLAINT
1502472	2	02/12/2015	819	R/R DRIVER REAR WINDOW LATCH			SCHEDULED SERVICE
2223716	2	08/02/2022	648	SUNSHADE FIXED			

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: PB1301 to PB1301

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>			<u>Total Line Count for System Code 2504 :</u>	<u>13</u>	<u>Cause-Reason</u>
PB1301	2504	BUS DECALS INSTALL					
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>			
1516644	3	11/30/2015	828	REPLC HANDRAIL DECAL	SCHEDULED SERVICE		
1720113	3	11/07/2017	849	REPLCD DECALS----WATCH YOUR STEP	SCHEDULED SERVICE		
1415202	6	10/20/2014	820	REMOVED BAD SIGN AND INSTALLED NEW SIGN WATCH YOUR STEP	SCHEDULED SERVICE		
1915019	2	08/20/2019	849	REPLCD RAILROAD BUMPER DECALS	SCHEDULED SERVICE		
1902347	7	02/08/2019	853	INSTALLED NEW DECAL	SCHEDULED SERVICE		
1902347	7	02/08/2019	832	INSTALLED NEW DECAL	SCHEDULED SERVICE		
1514753	2	10/23/2015	828	REPLC DECALS	SCHEDULED SERVICE		
1500016	3	01/05/2015	809	R/R HANDRAIL DECALS	SCHEDULED SERVICE		
1500016	3	01/05/2015	828	R/R HANDRAIL DECALS	SCHEDULED SERVICE		
2004459	2	03/16/2020	756	REPLCD DECAL	SCHEDULED SERVICE		
1822636	4	10/19/2018	837	R/R DECALS--WYSTEP	SCHEDULED SERVICE		
1816746	2	08/06/2018	781	install watch your step decals in english and spanish	SCHEDULED SERVICE		
2021158	3	10/27/2020	797	R/R DECALS--WYSTEP	SCHEDULED SERVICE		

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: PB1301 to PB1301

BUS#	SYS Code	SYS Code Description				Total Line Count for System Code 2505 :	26	Cause-Reason
PB1301	2505	WIPERS						
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>				<u>SCHEDULED SERVICE</u>
1904977	5	03/18/2019	781	R/R WIPER INSERTS				SCHEDULED SERVICE
1614591	2	10/18/2016	819	R/R WIPER NOZZLE				SCHEDULED SERVICE
2322153	4	09/13/2023	894	R/R WIPER BLADES				SCHEDULED SERVICE
2322153	4	09/13/2023	796	R/R WIPER BLADES				SCHEDULED SERVICE
1710659	4	06/20/2017	841	REPLCD WIPERS				SCHEDULED SERVICE
1921419	4	11/19/2019	795	REPAIR W/WASHER				SCHEDULED SERVICE
1921419	4	11/19/2019	789	REPAIR W/WASHER				SCHEDULED SERVICE
2100874	10	01/17/2021	832	UNCLOGGED C/SIDE WINDSHIELD WASHER				SCHEDULED SERVICE
1915019	5	08/20/2019	849	REPLCD WIPERS---UNCLOGGED WASHER SQUIRTER				SCHEDULED SERVICE
1819701	3	09/11/2018	828	REPLCD BLADES--ADJUST ARMS				SCHEDULED SERVICE
2008248	9	05/11/2020	781	RR BOTH WIPER BLADES				SCHEDULED SERVICE
2002648	3	02/18/2020	828	TIGHTEN DRIVES SIDE WIPER ARM				SCHEDULED SERVICE
2013393	6	07/20/2020	781	R/R WIPER BLADES- WASHER NOZZLE				SCHEDULED SERVICE
1804075	9	03/05/2018	809	R/R WASHER NOZZLE				SCHEDULED SERVICE
1919184	6	10/21/2019	832	REPLCD WIPERS/NOZZLES--CLOGGED				SCHEDULED SERVICE
2100874	7	01/17/2021	832	REPAIRED BAR LATCH ON WINDOW				SCHEDULED SERVICE
1708516	2	05/18/2017	828	R/R BROKEN WASHER FITTINGS				SCHEDULED SERVICE
2124040	6	09/14/2021	874	ADDED NEW HOSE TO WIPER ARM				SCHEDULED SERVICE

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: PB1301 to PB1301

BUS#	SYS Code	SYS Code Description				Total Line Count for System Code 2505 :	26	Cause-Reason
PB1301	2505	WIPERS						
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>				<u>SCHEDULED SERVICE</u>
1822636	2	10/19/2018	837	R/R WIPER BLADES, NOZZLES ON BLADE & WASHER NOZZLES				SCHEDULED SERVICE
2010594	3	06/12/2020	800	WIPER BLADES REPLACED				SCHEDULED SERVICE
1507948	2	05/27/2015	760	TIGHTEND SIDE WIPER ARM				OPERATOR COMPLAINT
2021158	13	10/27/2020	797	REPLCD WIPERS				SCHEDULED SERVICE
1814112	4	07/05/2018	841	TIGHTEN DRIVER WIPER BLADE				SCHEDULED SERVICE
1617704	3	12/23/2016	819	REPAIR WIPER NOZZLE				SCHEDULED SERVICE
2001055	4	01/21/2020	781	INSTALLED WATVH YUR STEP DECAL ON GRAB RAILS				SCHEDULED SERVICE
1827559	2	12/28/2018	837	R/R WIPERS				SCHEDULED SERVICE

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: **PB1301** to **PB1301**

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>				<u>Cause-Reason</u>
PB1301	2506	DOORS	Total Line Count for System Code 2506 :			17
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>		
1403547	4	03/15/2014	760	ADJUSTED ENTRANCE DOOR	OPERATOR COMPLAINT	
1502134	1	02/06/2015	797	DOORS - DIAGNOSE DOOR FOUND - DEFECTED DOOR SWITCH	OPERATOR COMPLAINT	
1501498	2	01/26/2015	731	DOORS-TROUBLESHOT & AFJUST THE FRONT DOOR	OPERATOR COMPLAINT	
1502307	3	02/11/2015	643	REPAIR DOOR	OPERATOR COMPLAINT	
2216977	1	06/02/2022	839	KNOB FOR LOCK & E-CLIP IS MISSING	SCHEDULED SERVICE	
2020332	3	10/14/2020	822	R/R DOOR SOLENOID--ADJUSTED MICRO SWITCH	OPERATOR COMPLAINT	
1514068	2	10/09/2015	809	REMVD REAR DOOR BRACKET-REPAIRED BOLT	OPERATOR COMPLAINT	
1315381	1	12/03/2013	773	DOORS - ADJUSTED OPENING SPEED ON ENTR DOOR	OPERATOR COMPLAINT	
1514068	1	10/09/2015	781	DOORS-CKD REAR DOOR-BOLT SECURING ROD BROKE OFF	OPERATOR COMPLAINT	
1501380	1	01/26/2015	760	DOORS - CAN'T DUBLICATE PROBLEM	OPERATOR COMPLAINT	
1502210	1	02/10/2015	797	DOORS - DIAGNOSE FRONT DOOR SYSTEM - FOUND DETECT	OPERATOR COMPLAINT	
1314513	1	11/15/2013	773	DOORS. ADJUSTED THE CUSHIONING ON THE ENTRANCE DOOR.	OPERATOR COMPLAINT	
1511883	3	08/24/2015	821	DOORS-REPLC DOOR CONTROLLER HANDLE	OPERATOR COMPLAINT	
1403480	2	03/14/2014	773	entrance door jammed opened and closed the entrance door , entrance door is now operating	OPERATOR COMPLAINT	
2100874	8	01/17/2021	832	ADJUST FRONT DOOR	SCHEDULED SERVICE	
1401521	1	02/03/2014	809	DOORS-OK--NPF	OUTSIDE REPAIR	
1410486	1	07/24/2014	791	DOORS - CHECK FRONT DOOR OPERATION CLOSES IN LESS TIME (3) THREE SECONDS	OPERATOR COMPLAINT	

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: 1100 to 9700

Print Date: 3/25/2025

Asset# Range: PB1301 to PB1301

BUS#	SYS Code	SYS Code Description			Total Line Count for System Code		Cause-Reason
PB1301	2507	WINDOWS GLASS REPL			2		
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>			<u>SCHEDULED SERVICE</u>
2108590	5	04/18/2021	869	LUBE ALL EMERGENCY WINDOWS			SCHEDULED SERVICE
2108590	5	04/18/2021	849	LUBE ALL EMERGENCY WINDOWS			SCHEDULED SERVICE
PB1301	2508	DOOR GLASS REPL			3		
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>			<u>OPERATOR COMPLAINT</u>
2126475	1	10/10/2021	887	REPLCD DOOR GLASS@EXIT DOOR			SCHEDULED SERVICE
1505376	1	03/31/2015	759	door glass replace			OPERATOR COMPLAINT
2125711	1	10/02/2021	887	DOOR GLASS REPLC---AT EXIT DOOR			SCHEDULED SERVICE
PB1301	2509	WINDSHIELD REPL			1		
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>			<u>SCHEDULED SERVICE</u>
2024770	2	12/16/2020	853	REPLACED BATTERY HOLD DOWNS			SCHEDULED SERVICE

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: **PB1301** to **PB1301**

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>				<u>Cause-Reason</u>
PB1301	2510	MIRRORS	Total Line Count for System Code 2510 :			24
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>		
1706410	6	04/18/2017	809	TIGHTEN IN ERIOR MIRROR INSTALLED TRIANGLE	SCHEDULED SERVICE	
2231100	3	10/26/2022	778	tighten r/r view mirror	SCHEDULED SERVICE	
1804075	10	03/05/2018	809	RMVD/TIGHTENED MIRROR BASE	SCHEDULED SERVICE	
1715363	3	09/01/2017	781	REPAIR MIRROR OVER WINDSHEILD	SCHEDULED SERVICE	
2231407	1	10/29/2022	832	found bad fuse, replace fuse bus ok	OPERATOR COMPLAINT	
1811403	3	06/01/2018	841	TIGHTEN C/SIDE MIRROR	SCHEDULED SERVICE	
1816746	5	08/06/2018	781	SECURED CURBSIDE OUTSIDE MIRROR TO BUS	SCHEDULED SERVICE	
2118274	6	07/20/2021	859	ADJUST BOTH MIRRORS	SCHEDULED SERVICE	
1806209	3	04/03/2018	828	TIGHTEN R/SIDE MIRROR BRACKET	SCHEDULED SERVICE	
2023465	3	12/03/2020	797	REPLCD MIRROR ---STREETSIDE	OPERATOR COMPLAINT	
2219725	2	06/24/2022	839	TIGHTEN MIDDLE INTERIOR MIRROR	SCHEDULED SERVICE	
1415202	8	10/20/2014	820	RETIGHT/CLEANED 2 INTERIOR MIRRORS	SCHEDULED SERVICE	
2305456	3	03/05/2023	778	tightened mirror	SCHEDULED SERVICE	
1410267	4	07/22/2014	818	TIGHTENED LEFT OUTSIDE MIRROR	SCHEDULED SERVICE	
2021158	5	10/27/2020	797	REPLCD MIRROR & SPOT MIRROR C/SIDE	SCHEDULED SERVICE	
1919184	2	10/21/2019	800	TIGHTEN MIRROR C/SIDE	SCHEDULED SERVICE	
2105059	1	03/13/2021	839	REPLCD MIRROR	OPERATOR COMPLAINT	
2111697	5	05/19/2021	797	REPLCD MIRROR & BRACKET ASSY	SCHEDULED SERVICE	

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: 1100 to 9700

Print Date: 3/25/2025

Asset# Range: PB1301 to PB1301

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>			<u>Cause-Reason</u>
PB1301	2510	MIRRORS	Total Line Count for System Code 2510 :		24
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
1411565	1	08/13/2014	773	MIRRORS - ADJUSTED MIRROR	OPERATOR COMPLAINT
2010006	1	06/03/2020	797	MIRRORS---CHECK WIRING--REPLCD FUSE	OPERATOR COMPLAINT
1310022	4	08/14/2013	798	SECURE EXT MIRROR	SCHEDULED SERVICE
1500016	4	01/05/2015	809	TIGHTEN STREETSIDE MIRROR	SCHEDULED SERVICE
1500016	4	01/05/2015	828	TIGHTEN STREETSIDE MIRROR	SCHEDULED SERVICE
2111697	4	05/19/2021	839	LEFT OUTSIDE MIRROR INOP	SCHEDULED SERVICE
PB1301	2511	DRIVER SEATS	Total Line Count for System Code 2511 :		8
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
1717579	3	09/29/2017	781	REPAIRED DRIVERS SEAT FROM STICKING ON TRACK	SCHEDULED SERVICE
1924219	6	12/30/2019	837	R/R DRIVER SEAT	OPERATOR COMPLAINT
1608409	1	06/14/2016	781	DRIVER SEATS--REPAIR SEAT BELT	OPERATOR COMPLAINT
1917148	2	09/18/2019	800	REMVD SEAT CUSHION--PINCH HOSE & REPLC	SCHEDULED SERVICE
1314075	2	11/05/2013	756	DRIVE SEAT LIFT SWITCH LEAKING, SEAT DROPPING. REPL LIFT SWITCH AIR.	WARRANTY
1616546	1	11/21/2016	781	DRIVER SEATS--CK FOR LEAKS--REPAIR SWITCHS INSTALLED NEW CLAMPS ON HOSES TO SWITCH	OPERATOR COMPLAINT
1911994	3	07/01/2019	798	REMOVED AND REPAIR DRIER SEAT	OPERATOR COMPLAINT
1816346	1	07/31/2018	797	driver seats	OPERATOR COMPLAINT

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024 System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: PB1301 to PB1301

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>			<u>Cause-Reason</u>
PB1301	2512	DRIVER SEAT BELTS	Total Line Count for System Code 2512 :		7
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
2231206	3	10/27/2022	887	r/r driver seatbelt	OPERATOR COMPLAINT
1608393	3	06/14/2016	809	R/R DRIVER SEAT BELT	OPERATOR COMPLAINT
1902347	8	02/08/2019	853	REPLCD D RIVER SEAT BELT	SCHEDULED SERVICE
1902347	8	02/08/2019	832	REPLCD D RIVER SEAT BELT	SCHEDULED SERVICE
1902141	3	02/01/2019	759	REPAIRED DRIVER SEAT BELT	OPERATOR COMPLAINT
1603433	1	03/08/2016	781	DRIVER SEAT BELTS---REPAIRED	OPERATOR COMPLAINT
1826381	3	12/10/2018	759	REPAIRED SEAT BELT/DRIVER	OPERATOR COMPLAINT
PB1301	2513	INTERIOR PANELS	Total Line Count for System Code 2513 :		2
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
1917148	3	09/18/2019	800	INTERIOR PANELS--PUT RIGHT REAR RAIL BACK INTO POSITION	SCHEDULED SERVICE
1410267	6	07/22/2014	818	CLEANED GRAFFITI FROM LEFT REAR SEAR, RIGHT REAR SEAT AND LEFTSIDE FLOORING	SCHEDULED SERVICE
PB1301	2514	HAND RAILS	Total Line Count for System Code 2514 :		2
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
1826105	3	12/05/2018	756	REPLCD RIVOTS @FRONT HAND RAIL	OPERATOR COMPLAINT
1600223	2	01/11/2016	820	R/R WATER PUM P BELT	SCHEDULED SERVICE
PB1301	2515	FLOOR REPAIR	Total Line Count for System Code 2515 :		2
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
2208045	4	03/13/2022	887	repair the floor is pealing in front of last row of seat	SCHEDULED SERVICE
2206042	2	02/20/2022	887	REPAIR DAMAGE IN THE FLOOR	OPERATOR COMPLAINT
PB1301	2517	PASSENGER SEAT REPAIR	Total Line Count for System Code 2517 :		2
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
1500016	6	01/05/2015	819	SWAP HANDICAP SEATS	SCHEDULED SERVICE
1822636	6	10/19/2018	837	SECURE SEATS	SCHEDULED SERVICE

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: **PB1301** to **PB1301**

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>			<u>Cause-Reason</u>
PB1301	2518	WHEEL CHAIR SEAT BELT	Total Line Count for System Code 2518 :		1
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>OPERATOR COMPLAINT</u>
1826490	2	12/11/2018	832	WHEEL CHAIR SEAT BELT	
PB1301	2519	TRIANGLES REPLACE	Total Line Count for System Code 2519 :		3
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>OPERATOR COMPLAINT</u>
2116500	7	07/11/2021	823	BRAKE TEST	
1718148	4	10/09/2017	756	REPLACE TRIANGLES	<u>OPERATOR COMPLAINT</u>
1514753	4	10/23/2015	828	REPLC EMERGENCY TRIANGLE	<u>SCHEDULED SERVICE</u>
PB1301	2522	BIKE RACK	Total Line Count for System Code 2522 :		12
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>OPERATOR COMPLAINT</u>
1311730	1	09/23/2013	791	BIKE RACK - REPAIR BIKE RACK	
1310022	5	08/14/2013	798	REPAIR BIKE RACK	<u>SCHEDULED SERVICE</u>
1612957	4	09/13/2016	781	REPAIRED CURBSIDE BIKE RACK ARM	<u>SCHEDULED SERVICE</u>
2420643	1	08/25/2024	832	REPLACE BUMPER	<u>OPERATOR COMPLAINT</u>
2018491	6	09/22/2020	823	R/R BIKE RACK	<u>OPERATOR COMPLAINT</u>
2124040	3	09/14/2021	874	ADJUSTED BIKE RACK	<u>SCHEDULED SERVICE</u>
2008676	3	05/13/2020	808	R/R BIKE RACK	<u>OPERATOR COMPLAINT</u>
1919184	7	10/21/2019	837	INSTALLED BIKE RACK SWITCH--REPAIRED CABLE TO LIGHT	<u>SCHEDULED SERVICE</u>
1818671	2	10/11/2018	832	bike rack -fixed braket to lock bike rack	<u>OPERATOR COMPLAINT</u>
1706410	8	04/18/2017	809	R/R BIKE RACK STOP BUMPERS	<u>SCHEDULED SERVICE</u>
2010051	1	06/03/2020	797	BIKE RACK---REINSTAL BIKE RACK SHOCK & LOCK PIN	<u>OPERATOR COMPLAINT</u>
1315328	1	12/02/2013	814	BIKE RACK - BEND BACK INTO LOCK UP POSITIN. ADJUST BACK STOPS.	<u>OPERATOR COMPLAINT</u>

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: PB1301 to PB1301

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>			<u>Cause-Reason</u>
PB1301	2523	Bumper Repair	Total Line Count for System Code 2523 :		1
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>SCHEDULED SERVICE</u>
2005845	1	04/01/2020	780	R/R RUBBER WHEEL WELLS--ADJUST FRONT BUMPER	
PB1301	2525	Rain Leak	Total Line Count for System Code 2525 :		2
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>OPERATOR COMPLAINT</u>
2129238	1	11/03/2021	887	RAIN LEAK--REPAIR RAIN LEAK@FRONT	
2227592	3	09/19/2022	887	rear roof hatch seal	<u>OPERATOR COMPLAINT</u>
PB1301	2526	REPLACE DESTINATION SIGN-GLASS	Total Line Count for System Code 2526 :		1
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>SCHEDULED SERVICE</u>
2208045	2	03/13/2022	887	replace destination glass	

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: 1100 to 9700

Print Date: 3/25/2025

Asset# Range: PB1301 to PB1301

BUS#	SYS Code	SYS Code Description		Total Line Count for System Code 2600 :	19	Cause-Reason
PB1301	2600	BRAKES				
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>		<u>OPERATOR COMPLAINT</u>
2305899	3	03/09/2023	809	INSTALLED BRAKE PEDAL RUBBER PAD		SCHEDULED SERVICE
2219725	8	06/24/2022	797	CHECKED FRONT BRAKES		SCHEDULED SERVICE
2226971	4	09/08/2022	820	adjusted slack adjusters inspected front brakes ok		SCHEDULED SERVICE
2226971	4	09/08/2022	833	adjusted slack adjusters inspected front brakes ok		SCHEDULED SERVICE
1602127	6	02/17/2016	773	REMOVED ALL HARDWIRE CLEANED HUBS		SCHEDULED SERVICE
2127251	5	10/15/2021	869	INSPECT/CLEAN FRONT BRAKES--OK		SCHEDULED SERVICE
2018957	4	09/25/2020	798	R/R HUB SEAL--CKEAN BRAKE SYSTEM & DRUM--ADJUST FRONT BRAKES		SCHEDULED SERVICE
2106173	10	03/22/2021	869	ZIP TIE AIR CHAMBER IN THE REAR HOSES		SCHEDULED SERVICE
2106173	10	03/22/2021	832	ZIP TIE AIR CHAMBER IN THE REAR HOSES		OPERATOR COMPLAINT
2215928	1	05/19/2022	883	BRAKES		SCHEDULED SERVICE
2114518	9	06/13/2021	869	CK FRONT BRAKES--OK		OPERATOR COMPLAINT
2215928	2	05/19/2022	883	PERFORMED VISUAL INSPECTION AND NPF		SCHEDULED SERVICE
2004459	4	03/16/2020	756	ADJUST SLACK ADJUSTOR		OPERATOR COMPLAINT
1903794	4	02/26/2019	796	E STROKE LIGHT ON--MULTIPLE CODES--R/R TRANSDUCER		OPERATOR COMPLAINT
2303813	1	02/14/2023	778	BRAKES		SCHEDULED SERVICE
2016013	8	08/19/2020	809	INSTALLED GREASE FITTINGS ON REAR BRAKES BOTH SIDES		SCHEDULED SERVICE
2215435	4	05/16/2022	833	INSPECT FRONT BRAKES AND REAR BRAKES.		SCHEDULED SERVICE
2215435	4	05/16/2022	820	INSPECT FRONT BRAKES AND REAR BRAKES.		SCHEDULED SERVICE

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: **PB1301** to **PB1301**

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>			<u>Cause-Reason</u>
PB1301	2600	BRAKES	Total Line Count for System Code 2600 :		19
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	
1507016	1	05/06/2015	797	BRAKES - ROAD TEST , CHECK & ROAD TEST - OK	OPERATOR COMPLAINT

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: 1100 to 9700

Print Date: 3/25/2025

Asset# Range: PB1301 to PB1301

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>			<u>Total Line Count for System Code 2601 :</u>	<u>19</u>	<u>Cause-Reason</u>
PB1301	2601	TROUBLESHOOT BRAKES					
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>			
2302250	8	01/28/2023	823	DISASSEMBLE DRUMS FOR BRAKE INSPECTION, MEASURE SHOES (11MM) PLENTY OF SHOES LEFT			SCHEDULED SERVICE
2302250	8	01/28/2023	828	DISASSEMBLE DRUMS FOR BRAKE INSPECTION, MEASURE SHOES (11MM) PLENTY OF SHOES LEFT			SCHEDULED SERVICE
1722364	1	12/12/2017	818	T/S BRAKES			OPERATOR COMPLAINT
2223716	6	08/02/2022	648	BRAKES OK			SCHEDULED SERVICE
2305456	8	03/05/2023	849	CHECKED BRAKES OK AT 35%			SCHEDULED SERVICE
1909659	1	05/23/2019	833	TROUBLESHOOT ROAD CALL--INSTALL E STROKE SCANNER--NO CODES FOUND--ROAD TEST--NPF			OPERATOR COMPLAINT
1909659	3	05/23/2019	833	CKD BRAKES--FRONT ARE NEW--REAR ABOUT 70% LEFT ON SHOES			OPERATOR COMPLAINT
2024049	1	12/02/2020	820	TROUBLESHOOT brakes---ckd brake pedal---no problem found			OPERATOR COMPLAINT
2018029	5	09/14/2020	822	TROUBLESHOOT E--STROKE--FOUND REAR LEFT SENSOR SHORTED			OPERATOR COMPLAINT
1505711	1	04/09/2015	791	T/S BRAKES			OPERATOR COMPLAINT
1813186	1	06/21/2018	781	TROUBLESHOOT BRAKES--NO PROBLEM FOUND			OPERATOR COMPLAINT
1517893	1	12/29/2015	818	TROUBLESHOOT BRAKES-NPF-BRAKES STOPPING PROPER			OPERATOR COMPLAINT
2420758	1	09/01/2024	913	t/s brakes			OPERATOR COMPLAINT
1711915	1	07/06/2017	781	TROUBLESHOOT BRAKES--CK BRAKES---CLEANED			OPERATOR COMPLAINT
1813355	1	06/25/2018	781	TROUBLESHOOT BRAKES--ROAD TEST INYARD--CK RAKES--REMVD DEBRIS FROM SHOES			OPERATOR COMPLAINT
2018136	6	09/15/2020	796	E--STROKE LIGHT STAYING ON--CODE FOR REAR LEFT ACTUATOR--UNPLUGGED, CODE WENT INAC			OPERATOR COMPLAINT
1506853	2	05/02/2015	828	TROUBLESHOOT BRAKES-NPF			OPERATOR COMPLAINT
1506853	2	05/02/2015	781	TROUBLESHOOT BRAKES-NPF			OPERATOR COMPLAINT

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024 System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: PB1301 to PB1301

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>			<u>Cause-Reason</u>
PB1301	2601	TROUBLESHOOT BRAKES	Total Line Count for System Code 2601 :		19
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>OPERATOR COMPLAINT</u>
1903794	7	02/26/2019	822	TROUBLESHOOT E STROKE	
PB1301	2602	ADJUST BRAKES	Total Line Count for System Code 2602 :		3
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>OPERATOR COMPLAINT</u>
1505711	2	04/09/2015	791	ADJUST BRAKES	
1924219	3	12/30/2019	837	PRESSURE WASH BRAKES/ADJUST	<u>OPERATOR COMPLAINT</u>
2418363	17	08/03/2024	832	chk and adjusted brakes	<u>SCHEDULED SERVICE</u>
PB1301	2603	FRONT RELINE	Total Line Count for System Code 2603 :		3
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>OPERATOR COMPLAINT</u>
2420758	2	09/01/2024	913	remove front brakes	
2420758	4	09/01/2024	833	install front c/s brakes	<u>OPERATOR COMPLAINT</u>
2420758	3	09/01/2024	913	r/r front road side spider and install brakes & bearings	<u>OPERATOR COMPLAINT</u>
PB1301	2604	REAR RELINE	Total Line Count for System Code 2604 :		9
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>SCHEDULED SERVICE</u>
1516644	7	11/30/2015	773	CK REAR BRAKES	
1602127	7	02/17/2016	753	R/R LEFT REAR BRAKES	<u>SCHEDULED SERVICE</u>
1602127	7	02/17/2016	828	R/R LEFT REAR BRAKES	<u>SCHEDULED SERVICE</u>
2013393	13	07/20/2020	841	REAR BRAKE RELINE---WIP	<u>SCHEDULED SERVICE</u>
1819701	9	09/11/2018	841	REAR BRAKE RELINE	<u>SCHEDULED SERVICE</u>
1819701	9	09/11/2018	837	REAR BRAKE RELINE	<u>SCHEDULED SERVICE</u>
1819701	8	09/11/2018	828	RELINE REAR BRAKES---WIP...	<u>SCHEDULED SERVICE</u>
2013393	14	07/20/2020	837	R/R REAR BRAKES--NEEDS--BRAKE TEST & PINION SEAL DONE	<u>SCHEDULED SERVICE</u>
2013393	14	07/20/2020	841	R/R REAR BRAKES--NEEDS--BRAKE TEST & PINION SEAL DONE	<u>SCHEDULED SERVICE</u>

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024 System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: PB1301 to PB1301

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>			<u>Cause-Reason</u>
PB1301	2607	SLACK ADJUSTERS FRONT	Total Line Count for System Code 2607 :		3
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
2018136	5	09/15/2020	796	INSPECT FRONT SLACK ADJUSTERS--REMOVED/REPLCD	OPERATOR COMPLAINT
1512533	4	09/08/2015	797	R/R FRONT SLACK ADJUSTERS	SCHEDULED SERVICE
2016013	7	08/19/2020	809	ALIGN BOTH FRONT SLACK ADJUSTERS	SCHEDULED SERVICE
PB1301	2609	BRAKE TREADLE VALVE	Total Line Count for System Code 2609 :		2
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
1903794	5	02/26/2019	838	REMVD TREADLE VALVE	OPERATOR COMPLAINT
1903794	6	02/26/2019	778	R/R BRAKE TREADLE VALVE--E STROKE LIGHT STILL ON	OPERATOR COMPLAINT
PB1301	2610	BRAKE RELAY VALVES	Total Line Count for System Code 2610 :		3
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
2419520	6	08/15/2024	832	finish r-12 valve install , ck for leas, adjust brake travel	OPERATOR COMPLAINT
2419520	5	08/15/2024	880	R&R r-12 valve	OPERATOR COMPLAINT
2419520	5	08/15/2024	926	R&R r-12 valve	OPERATOR COMPLAINT
PB1301	2611	BRAKE LINES/HOSES REPL	Total Line Count for System Code 2611 :		1
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
2210458	3	03/31/2022	853	replace both service air hoses	OPERATOR COMPLAINT
PB1301	2615	BRAKE LIGHT SENSOR REPLAC	Total Line Count for System Code 2615 :		1
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
2018029	7	09/14/2020	822	R/R LEFT REAR SENSOR	OPERATOR COMPLAINT
PB1301	2618	ABS MODULE VALVE REPLACE	Total Line Count for System Code 2618 :		2
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
2106173	8	03/22/2021	869	R/R L/SIDE ABS VALVE	SCHEDULED SERVICE
2106173	8	03/22/2021	832	R/R L/SIDE ABS VALVE	SCHEDULED SERVICE

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: PB1301 to PB1301

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>	Total Line Count for System Code 2619 :			25	<u>Cause-Reason</u>
PB1301	2619	BRAKE TEST					
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>			
2223716	7	08/02/2022	648	BRAKE TEST PASS		SCHEDULED SERVICE	
2418363	18	08/03/2024	832	brake test		SCHEDULED SERVICE	
2215928	4	05/19/2022	880	PERFORMED BRAKES TEST		OPERATOR COMPLAINT	
1506853	3	05/02/2015	828	BRAKE TEST-PASSED		OPERATOR COMPLAINT	
1506853	3	05/02/2015	781	BRAKE TEST-PASSED		OPERATOR COMPLAINT	
2302250	10	01/28/2023	823	BRAKE TEST		SCHEDULED SERVICE	
2302250	10	01/28/2023	833	BRAKE TEST		SCHEDULED SERVICE	
2211758	3	04/14/2022	871	BRAKE TEST PASS		SCHEDULED SERVICE	
1813355	2	06/25/2018	781	BRAKE TEST--PASSED		OPERATOR COMPLAINT	
1909659	2	05/23/2019	833	BRAKE TEST---PASSED		OPERATOR COMPLAINT	
1505711	3	04/09/2015	791	BRAKE TEST		OPERATOR COMPLAINT	
2226971	5	09/08/2022	820	brake test performed under wet road and passed		SCHEDULED SERVICE	
2226971	5	09/08/2022	833	brake test performed under wet road and passed		SCHEDULED SERVICE	
1819701	10	09/11/2018	841	BRAKE TEST		SCHEDULED SERVICE	
2303813	2	02/14/2023	778	BRAKE TEST/ SEE PRINTOUT		OPERATOR COMPLAINT	
2215435	3	05/16/2022	833	BRAKE TEST		SCHEDULED SERVICE	
2215435	3	05/16/2022	820	BRAKE TEST		SCHEDULED SERVICE	
1923274	5	12/18/2019	781	ADJ BRAKES AND PERFORMED BRAKE TEST		SCHEDULED SERVICE	

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: **PB1301** to **PB1301**

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>			<u>Total Line Count for System Code</u>		<u>Cause-Reason</u>
PB1301	2619	BRAKE TEST			Total Line Count for System Code 2619 :	25	
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>SCHEDULED SERVICE</u>		
2114518	10	06/13/2021	869	BRAKE TEST	OPERATOR COMPLAINT		
2305899	4	03/09/2023	809	BRAKE TEST. PASSED	OPERATOR COMPLAINT		
1924219	4	12/30/2019	837	BRAKE TEST	OPERATOR COMPLAINT		
1711915	2	07/06/2017	781	PERFORMED BRAKE TEST---PASSED	OPERATOR COMPLAINT		
2419520	3	08/15/2024	823	brake test fail	OPERATOR COMPLAINT		
2215928	3	05/19/2022	833	TRIED PERFORMING BRAKE TEST/ TESTER DIED	OPERATOR COMPLAINT		
2419520	7	08/15/2024	832	brake test passed	OPERATOR COMPLAINT		
PB1301	2700	AIR SYSTEM			Total Line Count for System Code 2700 :	8	
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>SCHEDULED SERVICE</u>		
1720113	8	11/07/2017	849	VALVE ON ACUUMALATOR WAS LOOSE TOOK APART INSTALLED TEFLON TAPE ON THREADS AND RE	OPERATOR COMPLAINT		
2417561	4	07/24/2024	797	CHECK AND REPLACE BRAKE VALUE	SCHEDULED SERVICE		
1919184	5	10/21/2019	800	ACC ABOVE DRIVER SEAT RESEALED@ GOVENOR	OPERATOR COMPLAINT		
2124033	3	09/14/2021	705	REPAIRED ON W/O 2124040	MECHANIC DEFECT		
1822427	8	10/17/2018	797	INSTALL STEERING PUMP, BRACKETS, COOLING LINES	SCHEDULED SERVICE		
1706410	9	04/18/2017	809	TIGHTEN AIR DRAIN AIR LINE	SCHEDULED SERVICE		
2008248	6	05/11/2020	781	RR RADIATOR	SCHEDULED SERVICE		
2008248	7	05/11/2020	781	SERVICE AIR DRIER	SCHEDULED SERVICE		
PB1301	2702	AIR COMPRESSOR REPL			Total Line Count for System Code 2702 :	1	
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>MECHANIC DEFECT</u>		
1822427	7	10/17/2018	797	INSTALL U COMPRESSOR			

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024 System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: PB1301 to PB1301

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>					<u>Cause-Reason</u>
PB1301	2704	AIR GOVERNOR REPL			Total Line Count for System Code 2704 :	1	
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>			SCHEDULED SERVICE
2013393	5	07/20/2020	781	R/R AIR GOVENOR			
PB1301	2705	AIR LINES			Total Line Count for System Code 2705 :	3	
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>			SCHEDULED SERVICE
2118274	2	07/20/2021	869	R/R AIR COMPRESSOR HOSE TO PING TANK--INSTALLED NEW O RING			SCHEDULED SERVICE
1808615	4	05/01/2018	841	REPAIRED AIR LINE BOTTOM OF AIR DRIER			SCHEDULED SERVICE
2418363	12	08/03/2024	909	repair leaking air line fitting			SCHEDULED SERVICE
PB1301	2706	AIR DRIER REPL			Total Line Count for System Code 2706 :	3	
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>			SCHEDULED SERVICE
2219725	4	06/24/2022	797	R/R AIR DRIER ASSEMBLY			OPERATOR COMPLAINT
1723336	3	12/29/2017	781	RTR AIR DRYER ASSEMBLY			SCHEDULED SERVICE
1514753	6	10/23/2015	773	R/R AIR DRYER			
PB1301	2707	TREADLE VALVE ACCELERATOR			Total Line Count for System Code 2707 :	1	
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>			OPERATOR COMPLAINT
1617333	2	12/13/2016	819	R/R COMPRESSOR			
PB1301	2709	AIR PRESSURE SWITCHES			Total Line Count for System Code 2709 :	1	
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>			OPERATOR COMPLAINT
1907856	5	04/26/2019	836	CHANGED E STROKE TRANSDUCER--RESET ECM BEHIND DRIVER--ADJUSTED BRAKES/GREASED			
PB1301	2716	Replace Purge Valve			Total Line Count for System Code 2716 :	1	
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>			SCHEDULED SERVICE
1604062	3	03/21/2016	818	SEVICED UNLOADERT VALVE ON DRIER			

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: PB1301 to PB1301

BUS#	SYS Code	SYS Code Description				Total Line Count for System Code 2800 :	82	Cause-Reason
PB1301	2800	ENGINE						
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>				
1512935	3	09/16/2015	799	r/r dgf hose				OPERATOR COMPLAINT
2308769	2	04/10/2023	833	code 3567 dozer valve				OPERATOR COMPLAINT
1615835	3	11/08/2016	762	RESET FIRE SYSTEM				OPERATOR COMPLAINT
1717004	3	09/21/2017	841	R/R WATER PUMP BELT				OPERATOR COMPLAINT
1612397	2	08/29/2016	828	REPLC VGT ACTUATOR				OPERATOR COMPLAINT
2108590	8	04/18/2021	869	R/R EGR COOLER PIPE O RING				SCHEDULED SERVICE
2108590	8	04/18/2021	849	R/R EGR COOLER PIPE O RING				SCHEDULED SERVICE
2004459	5	03/16/2020	756	INSPECT MOTOR MOUNTS				SCHEDULED SERVICE
1905760	5	04/17/2019	853	INSTALL CLAMP/SHIELD				OPERATOR COMPLAINT
1822427	6	10/17/2018	797	REPLCD OIL DRAIN TUBES				MECHANIC DEFECT
1822427	6	10/17/2018	849	REPLCD OIL DRAIN TUBES				MECHANIC DEFECT
2013393	12	07/20/2020	828	REPLCD ROCKER BOX GASKET,INJECTOR HARNESS, VALVE COVER GASKET & MOUNTING BOTH IN				SCHEDULED SERVICE
2202116	10	02/28/2022	797	diag n repair				OPERATOR COMPLAINT
2022384	14	11/22/2020	869	ROAD TEST				OPERATOR COMPLAINT
2022384	14	11/22/2020	880	ROAD TEST				OPERATOR COMPLAINT
1706410	3	04/18/2017	809	R/R WATER PUMP BELT				SCHEDULED SERVICE
2302059	3	01/28/2023	828	R/R FUEL RAIL PRESSURE SENSOR & REPAIR ENGINE HARNESS				OPERATOR COMPLAINT
1921419	9	11/19/2019	795	REPLCD OIL DRAIN CAP				SCHEDULED SERVICE

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: **PB1301** to **PB1301**

BUS#	SYS Code	SYS Code Description		Total Line Count for System Code 2800 :	82	Cause-Reason
PB1301	2800	ENGINE				
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>		<u>SCHEDULED SERVICE</u>
1921419	9	11/19/2019	789	REPLCD OIL DRAIN CAP		SCHEDULED SERVICE
1710659	8	06/20/2017	841	REINSTALL METAL BRACKET FOR DOSING VALVE		SCHEDULED SERVICE
2421657	3	09/06/2024	833	clean engine		OPERATOR COMPLAINT
2118274	7	07/20/2021	869	ZIP TIE ENGINE HARNESS		SCHEDULED SERVICE
1718433	4	10/16/2017	825	INSTALLED DAMPER		OPERATOR COMPLAINT
2122378	2	08/29/2021	836	remv air comp & p/steering pump--found sensor cracked causing a miss read		OPERATOR COMPLAINT
1820192	3	09/17/2018	854	CHECK ENGINE CODES--2554, 4151, 4163--NEEDS EXH PRESSURE SENSOR-WIP		OPERATOR COMPLAINT
2016013	9	08/19/2020	809	RAN ENGINE TO OPEN THERMOSTAT		SCHEDULED SERVICE
2024956	3	12/15/2020	797	NO BELT TENSIONER @NC OR SC---POO		OPERATOR COMPLAINT
1910738	2	06/11/2019	832	REPLACED NOZZLE		SCHEDULED SERVICE
1701246	2	01/25/2017	781	R/R DEF TANK CAP		SCHEDULED SERVICE
2226971	2	09/08/2022	820	install new chains on plugs		SCHEDULED SERVICE
2226971	2	09/08/2022	833	install new chains on plugs		SCHEDULED SERVICE
2021158	14	10/27/2020	828	REPLCD DOSER INJECTOR, REPLCD DEF HOSE--REPLC DOSER INJECTOR CONNECTOR PLUG		SCHEDULED SERVICE
2124040	8	09/14/2021	869	BUS RUNNING--NO LEAKS DETECTED		SCHEDULED SERVICE
2418363	2	08/03/2024	832	fuel tank cap		OPERATOR COMPLAINT
2024956	4	12/15/2020	752	R/R TENSIONER & ALT BELT		OPERATOR COMPLAINT
2122378	1	08/29/2021	836	ENGINE--ACTIVE CODES 0778, 2322		OPERATOR COMPLAINT

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024 System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: PB1301 to PB1301

BUS#	SYS Code	SYS Code Description				Total Line Count for System Code 2800 :	82	Cause-Reason
PB1301	2800	ENGINE						
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>			
2022384	13	11/22/2020	869	CODE FOR EGR PORT--REMVD SENDER--CLEANED--OK	OPERATOR COMPLAINT			
2022384	13	11/22/2020	880	CODE FOR EGR PORT--REMVD SENDER--CLEANED--OK	OPERATOR COMPLAINT			
2421657	4	09/06/2024	833	let engine run to ck for oil leaks, rear main leaks and front main leaks	OPERATOR COMPLAINT			
2417025	3	07/18/2024	809	R&R fuel level sender	OPERATOR COMPLAINT			
1905760	3	04/17/2019	809	PERFORM SCR TEST--FAILED--NEEDS SCR--WIP...	OPERATOR COMPLAINT			
2101083	2	01/24/2021	849	REMVD TSS--FOUND HARNESS SATURATED W/OIL--CLEANED--REPLCD TSS	OPERATOR COMPLAINT			
1818671	5	10/11/2018	832	cable to dpf temp sensor was modified erased codes	OPERATOR COMPLAINT			
1818671	3	10/11/2018	832	temp module harness not in stcok	OPERATOR COMPLAINT			
1717398	4	09/27/2017	825	R/R IDLER PULLEY, ALTENATOR BELT	OPERATOR COMPLAINT			
1900133	3	01/08/2019	833	EXHAUST LEAK DETECTED INPARTIC FILTER GASKET/LOOSE CLAMPS	OPERATOR COMPLAINT			
1819839	3	09/18/2018	796	NO FUMES /NO REPAIRS NEEDED	OPERATOR COMPLAINT			
2308995	1	04/12/2023	833	T/S ENGINE	SCHEDULED SERVICE			
2016013	5	08/19/2020	809	INSTALLED AIR RESTRICTION INDICATOR	OPERATOR COMPLAINT			
1711950	9	07/11/2017	643	COMPLETE COOLING SYSTEM -REPAIRED COOLING SYSTEM REPAIR AND CLEARED CODE	SCHEDULED SERVICE			
2127251	4	10/15/2021	869	R/R UPPER TORQUE PIPE SUPPORT	SCHEDULED SERVICE			
2418363	7	08/03/2024	832	air dryer	OPERATOR COMPLAINT			
2128844	1	10/25/2021	880	T/S ENGINE-NOX SENSOR N/R	OPERATOR COMPLAINT			
2226703	2	09/05/2022	833	PERFORMED VGT TEST/ FAILED	OPERATOR COMPLAINT			

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: **PB1301** to **PB1301**

BUS#	SYS Code	SYS Code Description		Total Line Count for System Code 2800 :	82	Cause-Reason
PB1301	2800	ENGINE				
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>		<u>Cause-Reason</u>
1512935	5	09/16/2015	643	remove remove dozer injector		OPERATOR COMPLAINT
1826490	3	12/11/2018	832	REPLACE SENSOR		OPERATOR COMPLAINT
2308769	4	04/10/2023	833	replace coolat line nozzles		OPERATOR COMPLAINT
1502783	6	02/18/2015	828	REPLACE FUEL FILTER FILL CAP		SCHEDULED SERVICE
1822427	9	10/17/2018	797	CK SYSTEM & REFILL COOLANT--BURP SYSTEM		MECHANIC DEFECT
2219725	9	06/24/2022	797	WASH, PRESSURE TEST COOLANT SYSTEM		SCHEDULED SERVICE
2418363	19	08/03/2024	832	chk oil leak ok		SCHEDULED SERVICE
1512935	4	09/16/2015	799	p/ test dgf dgk dozer inj		OPERATOR COMPLAINT
1600521	2	01/13/2016	832	REPLCD BRACKET		OPERATOR COMPLAINT
2125401	5	09/26/2021	809	ROAD TEST--NEEDED		OPERATOR COMPLAINT
2022384	3	11/22/2020	839	NO PUMP IN STOCK--CKD FUSE & RELAY--FOUND WATER IN PLUG--CLEANED		OPERATOR COMPLAINT
2226703	3	09/05/2022	833	R/R VGT ASSEMBLY		OPERATOR COMPLAINT
1509679	4	07/08/2015	631	engine pm		SCHEDULED SERVICE
2127251	8	10/15/2021	869	RUN BUS TO CK FOR LEAKS--NONE		SCHEDULED SERVICE
1905760	4	04/17/2019	853	INSTALLED SCR--WAITNG FOR CLAMP & HEAT SHIELD FROM NC		OPERATOR COMPLAINT
1706410	10	04/18/2017	809	LUBE REAR THROTTLE		SCHEDULED SERVICE
1408815	4	06/26/2014	799	repair terminals		OPERATOR COMPLAINT
1516644	8	11/30/2015	773	CLEARED CODES		SCHEDULED SERVICE

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: **PB1301** to **PB1301**

BUS#	SYS Code	SYS Code Description		Total Line Count for System Code 2800 :	82	Cause-Reason
PB1301	2800	ENGINE				
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>		
1516644	8	11/30/2015	809	CLEARED CODES		SCHEDULED SERVICE
2118274	8	07/20/2021	869	ADJUST AC BELT		SCHEDULED SERVICE
1822636	5	10/19/2018	837	R/R ALTERNATOR VENT TUBE		SCHEDULED SERVICE
1900133	4	01/08/2019	833	TIGHTEN CLAMPS--CK FOR LEAKS--NONE--CLEARED OCDES--ROAD TEST		OPERATOR COMPLAINT
2202116	5	02/28/2022	797	Diag n repair		OPERATOR COMPLAINT
1900292	5	01/10/2019	809	NO NEW ECM CALABRATION FOUND -OK AT THIS TIME		OPERATOR COMPLAINT
2215435	5	05/16/2022	833	REMOVES AIR COOLER INLET CLAMP AND ROTATED AWAY FROM COOLANT HOSE		SCHEDULED SERVICE
2215435	5	05/16/2022	820	REMOVES AIR COOLER INLET CLAMP AND ROTATED AWAY FROM COOLANT HOSE		SCHEDULED SERVICE
2308769	3	04/10/2023	833	replace dozer		OPERATOR COMPLAINT
1818671	4	10/11/2018	832	cable need to modify to connect -wip		OPERATOR COMPLAINT

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: **PB1301** to **PB1301**

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>			<u>Total Line Count for System Code 2801 :</u>	<u>109</u>	<u>Cause-Reason</u>
PB1301	2801	TROUBLESHOOT ENGINE					
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>SCHEDULED SERVICE</u>		
1814112	2	07/05/2018	841	MIL LIGHT ON INACTIVE CODE EXHAUST	OPERATOR COMPLAINT		
1417625	1	12/02/2014	752	TS ENGINE - FOUND CODE FOR LOW COOLANT	OPERATOR COMPLAINT		
1506459	2	04/23/2015	789	TROUBLESHOOT ENGINE-NEEDS REGEN	OPERATOR COMPLAINT		
1516359	4	11/23/2015	786	4163 ACTIVE-FILTER SENSOR MODULE	OPERATOR COMPLAINT		
2226278	2	09/01/2022	778	t/s and replaced dpf press sensor harness	SCHEDULED SERVICE		
2004345	1	03/12/2020	797	T/S DIAG ENGINE PARTICULATE FILTER	SCHEDULED SERVICE		
2208045	7	03/13/2022	828	scan ecm needs differensial pressure	OPERATOR COMPLAINT		
1500337	2	01/09/2015	795	TROUBLESHOOT ENGINE-NEEDS REGEN	OPERATOR COMPLAINT		
1826490	1	12/11/2018	832	T/S ENGINE	SCHEDULED SERVICE		
2018957	3	09/25/2020	798	TROUBLESHOOT ENGINE--REGEN -STOPPED --INCOMPLETE	OPERATOR COMPLAINT		
1718433	3	10/16/2017	800	R/R IDLER PULLEY	SUPERVISOR DEFECT		
2417246	2	07/20/2024	797	Diagnose code 0559 for fuel rail pressure erratic and found dirty fuel filters	OPERATOR COMPLAINT		
1612397	1	08/29/2016	828	TROUBLESHOOT ENGINE---VGT ACTUATOR DEFECTIVE--DPF NEEDS REGEN	OPERATOR COMPLAINT		
1600521	1	01/13/2016	832	TROUBLESHOOT ENGINE-	SCHEDULED SERVICE		
2208045	16	03/13/2022	874	T/S mil light, dtc 4153,1883,dpf temp sensor module, module overheat inactive	OPERATOR COMPLAINT		
2018880	3	09/25/2020	778	TROUBLESHOOT ENGINE----NEEDS DPF & DOC--NEEDS TURBO TOP ORANGE HOSE-NONE IN STOCK	OPERATOR COMPLAINT		
1500381	2	01/14/2015	751	TROUBLESHOOT ENGINE	OPERATOR COMPLAINT		
1900292	4	01/10/2019	837	T/S ENGINE /CODE 4151	OPERATOR COMPLAINT		

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024 System Code Range: 1100 to 9700

Print Date: 3/25/2025

Asset# Range: PB1301 to PB1301

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>				<u>Cause-Reason</u>
PB1301	2801	TROUBLESHOOT ENGINE	Total Line Count for System Code 2801 :			109
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>		
1808217	3	04/24/2018	809	TROUBLESHOOT ENGINE---CODES 4163, 4151 ACTIVE CODES	OPERATOR COMPLAINT	
2420186	1	08/20/2024	648	Oil level low. Inspect for major oil leak by running bus.	OPERATOR COMPLAINT	
1900252	1	01/08/2019	779	TROUBLESHOOT ENGINE----ADD COOLANT---REPAIR CLAMPS/HOSES	OPERATOR COMPLAINT	
2017713	5	09/10/2020	836	T/S ACTIVE CODES 1894 5177 VGT ON UNPLUGGED AT VGT CHECK VOLTS THATS FINE -UNPLUGGE	OPERATOR COMPLAINT	
1711950	6	07/11/2017	679	START ENG T/S -NO CODE PRESENT -FOR 2 HOURS NOTICE COOLANT DRIP REAR ENG FROM HOSE	SCHEDULED SERVICE	
2010594	5	06/12/2020	832	T/S ENGINE	SCHEDULED SERVICE	
2021158	19	10/27/2020	871	TSHOOT EGR CODE 3382--FOUND EGR PRESSURE SENSOR TO BE CLOGGED FULL OF CARBON--RI	OPERATOR COMPLAINT	
2019279	1	09/30/2020	800	TROUBLESHOOT ENGINE---CODE FOR REGEN	OPERATOR COMPLAINT	
1511967	2	08/26/2015	751	TROUBLESHOOT ENGINE-VODE 3899 INACTIVE HIGH COUNTS-SENSOR ON ORDER	OPERATOR COMPLAINT	
1717228	1	09/25/2017	832	TROUBLESHOOT ENGINE- CODE 3582 ACTIVE, SCR PROBLEMCLEAR CODE	OPERATOR COMPLAINT	
1820375	3	09/20/2018	789	TROUBLESHOOT ENGINE---REST ECM	SCHEDULED SERVICE	
2418363	15	08/03/2024	909	t/s and cleared egr codes	SCHEDULED SERVICE	
1512533	6	09/08/2015	819	CHECK ENGINE LIGHT IS ON FOR LOW COOLANT. REPAIRED COMPLETED DURING DRIVER HEATER	OPERATOR COMPLAINT	
1804391	1	03/07/2018	809	T/S ENGINE SCAN ECM FOR CODES PRESENT	OPERATOR COMPLAINT	
1903794	1	02/26/2019	796	TROUBLESHOOT ENGINE---INACTIVE CODES WHEN BUS STARTED--DEF LEVEL OK	SCHEDULED SERVICE	
1514753	5	10/23/2015	828	CK ACTIVE 3228,3748,3725 CODES-DEF SYSTEM LEAKING	OPERATOR COMPLAINT	
2022384	4	11/22/2020	838	TROUBLESHOOT ENGINE---CODE 3559--DOSING UNIT SHORTED TO LOW SOURCE	OPERATOR COMPLAINT	
2012856	1	07/08/2020	849	TROUBLESHOOT ENGINE---MIL LIGHT ON FOR NOX CODE--NEED TO REPLC INTAKE NOX SENOSR	OPERATOR COMPLAINT	

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024 System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: PB1301 to PB1301

BUS#	SYS Code	SYS Code Description			Total Line Count for System Code 2801 :	109	Cause-Reason
PB1301	2801	TROUBLESHOOT ENGINE					
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>			
2422317	4	09/15/2024	648	Codes 3342, 3714, 3382, 0143, 0415, 0559			OPERATOR COMPLAINT
2422317	4	09/15/2024	925	Codes 3342, 3714, 3382, 0143, 0415, 0559			OPERATOR COMPLAINT
2422317	8	09/15/2024	648	Tightened oil pan bolts.			OPERATOR COMPLAINT
2422317	8	09/15/2024	925	Tightened oil pan bolts.			OPERATOR COMPLAINT
1816326	1	07/31/2018	797	T/S ENGINE -DIAG ENGINE			SCHEDULED SERVICE
1514753	7	10/23/2015	756	ACTIVE CODE-INTAKE NOX SENSOR HIGH			OPERATOR COMPLAINT
1808217	1	04/24/2018	797	TROUBLESHOOT ENGINE--FOUNDPARTIC FILTER & SENSOR PROBLEM			OPERATOR COMPLAINT
2308769	1	04/10/2023	832	inactive code for def			OPERATOR COMPLAINT
2419520	1	08/15/2024	913	no codes could not duplicate stall issues, after road test found code 559 replace sender and road test			OPERATOR COMPLAINT
2419520	1	08/15/2024	823	no codes could not duplicate stall issues, after road test found code 559 replace sender and road test			SCHEDULED SERVICE
2012150	1	06/30/2020	797	T/S ENGINE			OPERATOR COMPLAINT
2022384	10	11/22/2020	822	TROUBLESHOOT CK ENGINE LIGHT--WRONG DEF SENSOR---POO			SCHEDULED SERVICE
1712596	1	07/17/2017	781	T/S ENGINE			OPERATOR COMPLAINT
1903696	3	02/25/2019	798	TROUBLESHOOT ENGINE			OPERATOR COMPLAINT
2018029	4	09/14/2020	822	TROUBLESHOOT MIL LIGHT-FOUND SOOT LOAD 2.75--NEEDS REGEN			OPERATOR COMPLAINT
1503799	1	03/05/2015	819	TS ENGINE: FIND NO CODE FOR TRANS OR ENGINE			OPERATOR COMPLAINT
2226703	1	09/05/2022	833	T/S ENGINE			SCHEDULED SERVICE
2235778	3	12/21/2022	809	T/S ENGINE/ NO START			SCHEDULED SERVICE

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: 1100 to 9700

Print Date: 3/25/2025

Asset# Range: PB1301 to PB1301

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>			<u>Cause-Reason</u>
PB1301	2801	TROUBLESHOOT ENGINE	Total Line Count for System Code 2801 :		109
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	
1716637	1	09/15/2017	841	TROUBLESHOOT ENGINE- ACTIVE CODE FOR SCR	OPERATOR COMPLAINT
1500337	5	01/09/2015	641	TROUBLESHOOT FUEL FILTERS-NEED TO B REPLACED	OPERATOR COMPLAINT
1806726	1	04/09/2018	832	TROUBLESHOOT ENGINE--ACTIVE CODE FOR SCR--ERASED CODES	OPERATOR COMPLAINT
2100546	1	01/12/2021	797	TROUBLESHOOT ENGINE--CK TO FIND CODE 0687 TURBO ISSUE--RECALIBRATE TURBO SYSTEM	OPERATOR COMPLAINT
2101083	1	01/24/2021	756	TROUBLESHOOT ENGINE---INACTIVE 0687 TURBO SPEED SENSOR	OPERATOR COMPLAINT
2101626	3	01/26/2021	799	T/S ENGINE	OPERATOR COMPLAINT
2018491	3	09/22/2020	823	TROUBLESHOOT ENGINE----CODE 1921 AFTER TREATMENT DIESEL PARTICULATE FILTER DIFF PRES	OPERATOR COMPLAINT
1510717	1	07/28/2015	819	T/S ENGINE - COULDN'T DUPLICATE	OPERATOR COMPLAINT
1905724	1	03/25/2019	797	TROUBLESHOOT ENGINE--FOUND PARTICULATE FILTER	OPERATOR COMPLAINT
1510484	1	07/23/2015	631	T/S ENGINE - FOR EXHAUST LEAK.	SCHEDULED SERVICE
1512783	1	09/11/2015	819	T/S ENGINE - REGEN NEEDED	OPERATOR COMPLAINT
2013891	1	07/27/2020	797	TROUBLESHOOT ENGINE---FOUND PARTICULATE FILTER	OPERATOR COMPLAINT
1408567	2	06/18/2014	789	TROUBLESHOOT ENGINE-LOW COOLANT	OPERATOR COMPLAINT
1806812	1	04/09/2018	797	TROUBLESHOOT ENGINE---PARTIC FILTER & SCR-----NEEDS REGEN	OPERATOR COMPLAINT
1417687	1	12/10/2014	752	TS ENGINE: FOUND ENG CODE FOR VGT	OPERATOR COMPLAINT
2226278	1	09/01/2022	648	t/s code 1881	OPERATOR COMPLAINT
1818120	3	08/21/2018	702	T/S ENGINE -OPERATOR SHUT DOWN BUS BY ACCIDENT	OPERATOR COMPLAINT
2022384	9	11/22/2020	874	TROUBLESHOOT CK ENGINE LIGHTS--CODE 1669 DEF GAUGE TEMP NOT READING	OPERATOR COMPLAINT

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024 System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: PB1301 to PB1301

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>			<u>Total Line Count for System Code 2801 :</u>	<u>109</u>	<u>Cause-Reason</u>
PB1301	2801	TROUBLESHOOT ENGINE					
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>			
2022384	9	11/22/2020	839	TROUBLESHOOT CK ENGINE LIGHTS--CODE 1669 DEF GAUGE TEMP NOT READING	OPERATOR COMPLAINT		
					SCHEDULED SERVICE		
1502783	7	02/18/2015	828	ENGINE LIGHT CAUSED BY INCREASED FUEL PRESSURE DUE TO DIRTY FUEL FILTERS - FILTERS WE	OPERATOR COMPLAINT		
2125401	1	09/26/2021	809	TROUBLESHOOT ENGINE---DIAGNOSE DEFECTIVE DOSER MODULE PUMP---3712, 3714 IN ECM	OPERATOR COMPLAINT		
1516101	1	11/16/2015	756	T/S ENGINE	OPERATOR COMPLAINT		
1903501	1	02/20/2019	820	TROUBLESHOOT ENGINE---FOUND ACTIVE CODE FOR REGEN	OPERATOR COMPLAINT		
2416916	1	07/17/2024	914	Fast idle and hazard switch were both faulty.	OPERATOR COMPLAINT		
1901012	3	01/21/2019	679	T/S ENGINE COOLANT LEVEL -ACT CODE 0197 3366 CLEARED CODE RAN ENG NO CODE AT THIS TIM	OPERATOR COMPLAINT		
1815640	1	07/23/2018	838	TROUBLESHOOT ENGINE--NEED TO RESET FAST IDLE SWITCH	OPERATOR COMPLAINT		
2422317	7	09/15/2024	648	Oil Leaks, Rear main seal, air compressor, & air compressor	OPERATOR COMPLAINT		
2422317	7	09/15/2024	925	Oil Leaks, Rear main seal, air compressor, & air compressor	OPERATOR COMPLAINT		
1516991	1	12/07/2015	819	T/S ENGINE	OPERATOR COMPLAINT		
1512935	2	09/16/2015	799	t/s eng.	OPERATOR COMPLAINT		
1408815	3	06/26/2014	799	t/s eng.	OPERATOR COMPLAINT		
1812914	1	06/19/2018	832	T/S ENGINE -PARTICU;ATED FILTER -NEED REGEN	OPERATOR COMPLAINT		
1510853	2	08/04/2015	648	TROUBLESHOOT ENGINE-NO CODES IN ECM-ENGINE OIL LOW-TOP OFF	OPERATOR COMPLAINT		
2216681	1	05/26/2022	820	found check engine, active code 3725 (intake nox sensor) t/s checked data monitor and had erratic reading , cl	OPERATOR COMPLAINT		
1719351	1	10/26/2017	753	T/S ENGINE	OPERATOR COMPLAINT		
2017713	10	09/10/2020	648	BOTH 1942 AND 4163 CODES WERE INACTIVE CHECKED CRANKCASE PRESS -OM CODE 0286 FLASH	OPERATOR COMPLAINT		

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: PB1301 to PB1301

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>			<u>Cause-Reason</u>
PB1301	2801	TROUBLESHOOT ENGINE	Total Line Count for System Code 2801 :		109
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	
1825492	1	11/27/2018	832	TROUBLESHOOT ENGINE--REGEN NEEDED	OPERATOR COMPLAINT
1417687	2	12/10/2014	668	DROVE BUS TO CUMMINS FOR WARRANTY	WARRANTY
1417687	2	12/10/2014	664	DROVE BUS TO CUMMINS FOR WARRANTY	WARRANTY
2128531	1	10/25/2021	797	T/S ENGINE CODES	OPERATOR COMPLAINT
1823022	1	01/16/2019	753	TROUBLESHOOT ENGINE----FOUND REGEN--FOUND AFTER TREATMENT SENSOR MODULE--FOUND	OPERATOR COMPLAINT
1900292	1	01/10/2019	837	T/S ENGINE	OPERATOR COMPLAINT
1824617	1	11/15/2018	832	T/S ENGINE -ACTIVE CODE 1898 And 5177 VGT ACTUATOR OUT CALIBRATION	SCHEDULED SERVICE
1825916	1	12/05/2018	752	TROUBLESHOOT ENGINE--CK ENGINE SCR	ERASED CODES AND OPERATOR COMPLAINT
1820990	1	09/26/2018	824	TROUBLESHOOT ENGINE---CHECK/CLEAR CODES	OPERATOR COMPLAINT
1716597	1	09/15/2017	818	TROUBLESHOOT ENGINE- CODE 3582 SCR NEEDS REGEN	OPERATOR COMPLAINT
1711950	3	07/11/2017	679	CHECK FUEL SYSTEM ADD FUEL FILTERS -FUEL SYSTEM OK	OPERATOR COMPLAINT
1515730	1	11/09/2015	819	T/S ENGINE - NEED A INTAKE NOX SENSOR.	OPERATOR COMPLAINT
1408815	2	06/26/2014	731	needs coolant level sensors	OPERATOR COMPLAINT
2302250	6	01/28/2023	820	T/S C.E.L ON	SCHEDULED SERVICE
1717123	1	09/25/2017	756	TROUBLESHOOT ENGINE---RESET TRAN OIL LIFE	OPERATOR COMPLAINT
1719576	1	11/02/2017	756	T/S ENGINE	OPERATOR COMPLAINT
1417687	3	12/10/2014	762	PICK BUS @ CUMMINS WARRANTY REPAIR IS COMPLETE	WARRANTY
1417687	3	12/10/2014	753	PICK BUS @ CUMMINS WARRANTY REPAIR IS COMPLETE	WARRANTY

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024 System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: PB1301 to PB1301

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>			<u>Cause-Reason</u>
PB1301	2801	TROUBLESHOOT ENGINE	Total Line Count for System Code 2801 :		109
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>SCHEDULED SERVICE</u>
1917148	5	09/18/2019	756	OIL LEAK--WASH ENGINE--ROAD TEST--FOUND (1)OIL LEAK@FRONT SEAL--NO REPAIR @THIS TIME	
PB1301	2803	NO START	Total Line Count for System Code 2803 :		4
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>OPERATOR COMPLAINT</u>
1907132	1	04/17/2019	837	no start---battery dead--alternator cable not connected to regulator	OPERATOR COMPLAINT
1513076	1	09/17/2015	783	NO START-HARD TO JUMP START	OPERATOR COMPLAINT
2223289	1	08/01/2022	828	replace starter motor and 500 amp fuse	OPERATOR COMPLAINT
2221613	1	07/11/2022	853	jump start and (lights & ignition was left on)	OPERATOR COMPLAINT
PB1301	2805	NO POWER	Total Line Count for System Code 2805 :		2
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>OPERATOR COMPLAINT</u>
2233965	3	01/19/2023	820	removed trans and cleaned old one flushed system and installed new trans	OPERATOR COMPLAINT
2233965	3	01/19/2023	832	removed trans and cleaned old one flushed system and installed new trans	OPERATOR COMPLAINT
PB1301	2808	TURBO REPL	Total Line Count for System Code 2808 :		5
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>OPERATOR COMPLAINT</u>
1824617	3	11/15/2018	756	RR TURBO	OPERATOR COMPLAINT
2017713	7	09/10/2020	809	RR TURBO	OPERATOR COMPLAINT
2017713	7	09/10/2020	778	RR TURBO	OPERATOR COMPLAINT
2017713	6	09/10/2020	836	REMOVEAL OF VGT BUT VGT SHAFT ON TURBO MAY BE DEFECTED MAY NEED TO CHANGE OUT TU	OPERATOR COMPLAINT
1824617	2	11/15/2018	832	COOLANT WAS DRAINED -ENGINE TOO TO REMOVE VGT	OPERATOR COMPLAINT
PB1301	2809	AIR INTAKE SYSTEM REPAIR	Total Line Count for System Code 2809 :		1
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>OPERATOR COMPLAINT</u>
2018880	6	09/25/2020	822	INSTALL INTAKE HOSE	OPERATOR COMPLAINT

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: **PB1301** to **PB1301**

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>			<u>Cause-Reason</u>
PB1301	2811	EXHAUST SYSTEM REP	Total Line Count for System Code 2811 :		3
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
1912904	4	07/15/2019	799	TIGHT EXHAUST CLAMPS	SCHEDULED SERVICE
1712596	2	07/17/2017	781	REPAIRED CLAMPS AT FLEX PIPE	OPERATOR COMPLAINT
1513785	3	10/06/2015	756	repalce flex pipe	OPERATOR COMPLAINT
PB1301	2813	ENGINE OIL LEAK	Total Line Count for System Code 2813 :		9
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
2421657	5	09/06/2024	909	clean engine, found leak at air compressors, tighten bolts ok for service at this time	OPERATOR COMPLAINT
2204184	7	02/07/2022	828	TORQUE OIL COOLER TO MANUFACTURE SPECS	SCHEDULED SERVICE
2420186	2	08/20/2024	648	Add 9 qts to engine. Oil level is ok. No major leaks	OPERATOR COMPLAINT
2422317	9	09/15/2024	787	Tightened air compressor mounting bolts and put extension hose onto breather drain tube.	OPERATOR COMPLAINT
1713479	4	08/01/2017	822	R/R DIPSTICK	OPERATOR COMPLAINT
2021158	22	10/27/2020	837	TSHOOT OIL LEAKS--OIL PRESSURE SWITCH LOOSE--NO LEAK@OIL COOLER	SCHEDULED SERVICE
1901012	8	01/21/2019	800	RR REAR MAIN SEAL	OPERATOR COMPLAINT
2204184	6	02/07/2022	828	TIGHTEN TIMING COVER	SCHEDULED SERVICE
1719351	3	10/26/2017	753	RR DIPSTICK	OPERATOR COMPLAINT

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: 1100 to 9700

Print Date: 3/25/2025

Asset# Range: PB1301 to PB1301

BUS#	SYS Code	SYS Code Description			Total Line Count for System Code 2814 :	13	Cause-Reason
PB1301	2814	ENGINE BELTS REPL					
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>			<u>Cause-Reason</u>
1827559	7	12/28/2018	797	REPLCD ALTERNATOR BELT			SCHEDULED SERVICE
1717398	5	09/27/2017	800	INSTALL BELTS, CLEAR CODES			OPERATOR COMPLAINT
1827559	8	12/28/2018	797	REPLCD WATER PUMP BELT			SCHEDULED SERVICE
2106173	4	03/22/2021	836	R/R BOTH BOLTS			SCHEDULED SERVICE
1403816	2	03/21/2014	819	REPLC ALL BELTS			SCHEDULED SERVICE
1415202	4	10/20/2014	820	REMOVED/REPLACED WATER PUMP BELT			SCHEDULED SERVICE
1611309	2	08/09/2016	820	R/R WATER PUMP BELT			SCHEDULED SERVICE
1720113	5	11/07/2017	849	REPLACEED WATER PUMP BELT			SCHEDULED SERVICE
2308083	2	04/02/2023	832	replace ac belt			SCHEDULED SERVICE
1920816	1	11/11/2019	752	ENGINE BELTS REPLACED			SCHEDULED SERVICE
1718433	6	10/16/2017	825	FINISHED INSTALLING DAMPER AND ALL BELTS			OPERATOR COMPLAINT
1718148	3	10/09/2017	756	CHANGE BELT ON ROAD			OPERATOR COMPLAINT
2204184	4	02/07/2022	828	REPLACE W/P AND ALT. BELT			SCHEDULED SERVICE
PB1301	2816	ENGINE GASKETS/SEALS REPL			Total Line Count for System Code 2816 :	3	Cause-Reason
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>			<u>Cause-Reason</u>
2003851	4	03/12/2020	787	REMOVE FRONT GEAR COVER -RESEALED FRONT GEAR COVER			OPERATOR COMPLAINT
1822427	4	10/17/2018	797	REPLCD ENGINE VALVE COVEER GASKET			MECHANIC DEFECT
1822427	4	10/17/2018	849	REPLCD ENGINE VALVE COVEER GASKET			MECHANIC DEFECT

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: **PB1301** to **PB1301**

BUS#	SYS Code	SYS Code Description			Total Line Count for System Code		Cause-Reason
PB1301	2817	ENGINE PULLEYS/TENSIONERS			8		
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>			<u>SCHEDULED SERVICE</u>
1515017	3	10/26/2015	820	R/R AC TENSIONER BELT			SCHEDULED SERVICE
2013393	15	07/20/2020	837	INSTALL ALTERNATOR BRACKET			SCHEDULED SERVICE
2305456	4	03/05/2023	778	r/r water pump pulley			SCHEDULED SERVICE
2208045	8	03/13/2022	828	replace a/c tensioner			SCHEDULED SERVICE
1827559	6	12/28/2018	797	REPLCD WATER PUMP TENSIONER			SCHEDULED SERVICE
2132760	3	12/01/2021	832	REPLACE TENSIONER WATER PUMP			SCHEDULED SERVICE
2132760	3	12/01/2021	849	REPLACE TENSIONER WATER PUMP			SCHEDULED SERVICE
1415202	3	10/20/2014	820	REMOVED/REPLACED WATER PUMP TENSIONER BELT AND IDLE PULLEY			SCHEDULED SERVICE
PB1301	2818	ENGINE MOUNTS REPL			3		
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>			<u>SCHEDULED SERVICE</u>
1819701	4	09/11/2018	828	REPLCD MOTOR MOUNTS			SCHEDULED SERVICE
2208045	15	03/13/2022	874	R&R front eng mounts			SCHEDULED SERVICE
2021158	15	10/27/2020	871	TIGHTEND LOOSE MOTOR MOUNT BOLTS ON TOP/BOTTOM			SCHEDULED SERVICE

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: **PB1301** to **PB1301**

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>			<u>Cause-Reason</u>
PB1301	2819	ENGINE SWIT/SENS/THERM RE	Total Line Count for System Code 2819 :		29
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	
1417625	2	12/02/2014	752	R/R LOW COOLANT SENSOR	OPERATOR COMPLAINT
					SCHEDULED SERVICE
2021158	23	10/27/2020	837	TIGHTEN OIL PRESSURE SWITCH	OPERATOR COMPLAINT
2012856	2	07/08/2020	841	R/R INLET NOX SENSOR	OPERATOR COMPLAINT
1515730	2	11/09/2015	809	R/R INTAKE NOX SENSOR	OPERATOR COMPLAINT
2018644	3	09/21/2020	787	REPALCED EXHAUST PRESSURE SENSOR	OPERATOR COMPLAINT
1808217	4	04/24/2018	809	R/R PARTIC FILTER TEMP SENSOR	OPERATOR COMPLAINT
2302059	9	01/28/2023	871	INSTALLED COMPRESSOR, P/S PUMP, COOLANT LINES	MECHANIC DEFECT
1822427	3	10/17/2018	797	INSTALL ENGINE WIRING HARNESS	MECHANIC DEFECT
1822427	3	10/17/2018	849	INSTALL ENGINE WIRING HARNESS	SCHEDULED SERVICE
2219725	5	06/24/2022	797	R/R OIL PRESSURE SENSOR	SCHEDULED SERVICE
1710659	7	06/20/2017	841	REPLCD INTAKE PRESSURE SENSOR	MECHANIC DEFECT
1822427	5	10/17/2018	797	REPLCD INTAKE SENSOR HARNESS	MECHANIC DEFECT
1822427	5	10/17/2018	849	REPLCD INTAKE SENSOR HARNESS	OPERATOR COMPLAINT
2016958	3	09/02/2020	828	REPLCD DPF TEMP SENSOR MODULE	SCHEDULED SERVICE
2013393	10	07/20/2020	781	R/R BOTH MOTOR MOUNTS	SCHEDULED SERVICE
1902347	3	02/08/2019	853	REPLCD ENGINE OIL PRESSURE SENSOR	SCHEDULED SERVICE
1902347	3	02/08/2019	832	REPLCD ENGINE OIL PRESSURE SENSOR	OPERATOR COMPLAINT
2419520	2	08/15/2024	823	R&R fuel pressure relief valve and rail sensor	

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: **PB1301** to **PB1301**

BUS#	SYS Code	SYS Code Description			Total Line Count for System Code		Cause-Reason
PB1301	2819	ENGINE SWIT/SENS/THERM RE			29		
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>			<u>Cause-Reason</u>
1907856	3	04/26/2019	836	R/R FUEL PRESSURE ACTUATOR			OPERATOR COMPLAINT
2022384	8	11/22/2020	874	REPLCD LEVEL SENSOR			OPERATOR COMPLAINT
2022384	8	11/22/2020	839	REPLCD LEVEL SENSOR			OPERATOR COMPLAINT
2010594	6	06/12/2020	832	REPLACED DIFF SENSOR RERASE CODE -CLEAN TUBE PROTECT WIRING			SCHEDULED SERVICE
2302059	8	01/28/2023	820	R/R CAMSHFT SENSOR			OPERATOR COMPLAINT
2302059	8	01/28/2023	833	R/R CAMSHFT SENSOR			OPERATOR COMPLAINT
1822427	2	10/17/2018	797	REPLCD (3)INJECTOR HARNESS & WIRE CLIPS			MECHANIC DEFECT
1822427	2	10/17/2018	849	REPLCD (3)INJECTOR HARNESS & WIRE CLIPS			MECHANIC DEFECT
2416916	2	07/17/2024	914	R & R fast idle switch and hazard switch.			OPERATOR COMPLAINT
2101626	4	01/26/2021	799	RR CKP SS			OPERATOR COMPLAINT
1511967	3	08/26/2015	825	R/R SENSOR			OPERATOR COMPLAINT
PB1301	2820	FUEL FILTERS REPL			3		
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>			<u>Cause-Reason</u>
1812914	2	06/19/2018	832	REGEN DONE			OPERATOR COMPLAINT
1500337	6	01/09/2015	641	R/R BOTH FUEL FILTERS			OPERATOR COMPLAINT
2417246	1	07/20/2024	797	Replaced primary and secondary fuel filters			SUPERVISOR DEFECT
PB1301	2821	FUEL PUMPS REPL			2		
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>			<u>Cause-Reason</u>
2003851	3	03/12/2020	787	REMOVE FUEL PUMP			OPERATOR COMPLAINT
2003851	5	03/12/2020	866	INSTALLED FUEL PUMP ALL BELTS ENGINE SAFETY BRAKET-WASH ENGINE			OPERATOR COMPLAINT

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024 System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: PB1301 to PB1301

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>			<u>Total Line Count for System Code</u>		<u>Cause-Reason</u>
PB1301	2824	ENGINE ELEC SWIT/SEN/HARN			Total Line Count for System Code 2824 :	7	
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>			<u>SCHEDULED SERVICE</u>
2208045	9	03/13/2022	828	wait for parts, no parts showed up on stock replace sensors			
1516991	3	12/07/2015	809	REDUCECD OUTLET NOX SENSOR			OPERATOR COMPLAINT
2018222	6	09/17/2020	648	FINISHED REINSTALL DPF			OPERATOR COMPLAINT
1822427	1	10/17/2018	832	REMOVED HARNESS			MECHANIC DEFECT
2216681	2	05/26/2022	820	R&R INTAKE NOX SENSOR			OPERATOR COMPLAINT
1400775	2	01/21/2014	814	REPAIR LOOSE CONNECTION ON REAR FAN SWITCH			SCHEDULED SERVICE
2017713	4	09/10/2020	648	RR ENGINE PRESS SENSOR CODE STILL ACTIVE AND 2 VGT CODES BECOME ACTIVE T/S SENSOR C			OPERATOR COMPLAINT
PB1301	2825	REAR MAIN SEAL			Total Line Count for System Code 2825 :	1	<u>Cause-Reason</u>
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>			<u>OPERATOR COMPLAINT</u>
1801743	3	02/09/2018	787	REPLCD OIL PLUG, CAMSHAFT PLUG & O RING & REAR MAIN SEAL			
PB1301	2826	OUT OF FUEL			Total Line Count for System Code 2826 :	1	<u>Cause-Reason</u>
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>			<u>OPERATOR COMPLAINT</u>
2416717	3	07/15/2024	848	add 24 gallons of fuel			
PB1301	2827	E.C.M. PROGRAM			Total Line Count for System Code 2827 :	4	<u>Cause-Reason</u>
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>			<u>OPERATOR COMPLAINT</u>
2122378	4	08/29/2021	837	UPDATE ECM			
2125401	4	09/26/2021	809	REINSTALLED ECM TEMP			OPERATOR COMPLAINT
1905760	6	04/17/2019	837	UPDATE ECM			OPERATOR COMPLAINT
2012150	3	06/30/2020	828	ACTIVE CODE FOR NOX			OPERATOR COMPLAINT

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: PB1301 to PB1301

BUS#	SYS Code	SYS Code Description			Total Line Count for System Code 2828 :	16	Cause-Reason
PB1301	2828	MOTOR WASH ENGINE					
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>			
2103029	2	03/03/2021	848	MOTOR WASH ENGINE			SCHEDULED SERVICE
2231100	1	10/26/2022	778	motor wash			SCHEDULED SERVICE
2132760	8	12/01/2021	832	CLEAN ENGINE			SCHEDULED SERVICE
2106173	2	03/22/2021	848	MOTOR WASH ENGINE---			SCHEDULED SERVICE
1713479	5	08/01/2017	822	WASHED ENGINE			OPERATOR COMPLAINT
2226792	1	09/06/2022	648	CLEAN ENGINE			OPERATOR COMPLAINT
2111697	2	05/19/2021	848	MOTOR WASH ENGINE			SCHEDULED SERVICE
2219725	7	06/24/2022	797	MOTOR WASH			SCHEDULED SERVICE
2422317	5	09/15/2024	648	Washed engine			OPERATOR COMPLAINT
2422317	5	09/15/2024	925	Washed engine			OPERATOR COMPLAINT
1908788	2	05/10/2019	779	MNOTOR WASH ROAD TEST BRAKE TEST			SCHEDULED SERVICE
2127251	6	10/15/2021	869	WASH MOTOR			SCHEDULED SERVICE
2114518	2	06/13/2021	848	MOTOR WASH ENGINE			SCHEDULED SERVICE
2108590	2	04/18/2021	848	MOTOR WASH ENGINE			SCHEDULED SERVICE
2021158	20	10/27/2020	837	WASH ENGINE			SCHEDULED SERVICE
1919184	8	10/21/2019	832	WASHED ENGINE			SCHEDULED SERVICE

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: **PB1301** to **PB1301**

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>				<u>Cause-Reason</u>
PB1301	2832	PARTICULATE FILTER REGEN	Total Line Count for System Code 2832 :			56
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>		
2018222	7	09/17/2020	648	REGEN BUS		OPERATOR COMPLAINT
1719440	3	11/02/2017	841	PARTICULATE FILTER REGEN		OPERATOR COMPLAINT
1612397	3	08/29/2016	828	REGEN--CLEAR CODES		OPERATOR COMPLAINT
2016958	4	09/02/2020	828	REGEN		OPERATOR COMPLAINT
1512783	2	09/11/2015	819	REGEN- COMPLETED		SCHEDULED SERVICE
2018880	7	09/25/2020	822	REGEN PARTICULATE FILTER		OPERATOR COMPLAINT
1516007	6	11/13/2015	819	regen complete		OPERATOR COMPLAINT
1823613	3	10/31/2018	797	REGEN SYSTEM		OPERATOR COMPLAINT
2018491	4	09/22/2020	823	REGEN		OPERATOR COMPLAINT
1500337	3	01/09/2015	795	REGEN BUS		OPERATOR COMPLAINT
1711291	4	06/28/2017	828	REGEN		OPERATOR COMPLAINT
1719351	2	10/26/2017	753	PERFORMED REGEN		OPERATOR COMPLAINT
1806726	2	04/09/2018	832	REGEN		OPERATOR COMPLAINT
1516359	3	11/23/2015	786	REGEN/RESET		OPERATOR COMPLAINT
2100546	2	01/12/2021	797	REGEN --CK TURBO OPERATION--OK		OPERATOR COMPLAINT
1500337	7	01/09/2015	641	REGEN		OPERATOR COMPLAINT
2012150	2	06/30/2020	797	REGEN SYSTEM		OPERATOR COMPLAINT
1500696	2	01/22/2015	731	REGEN		OPERATOR COMPLAINT

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: **PB1301** to **PB1301**

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>			<u>Total Line Count for System Code 2832 :</u>	<u>56</u>	<u>Cause-Reason</u>
PB1301	2832	PARTICULATE FILTER REGEN					
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>			
2125401	3	09/26/2021	809	REGEN			OPERATOR COMPLAINT
1415646	4	11/06/2014	819	REGEN COMPLETE MIL LIGHT ON FOR LOW COOLANT			OPERATOR COMPLAINT
2017713	9	09/10/2020	869	REGEN NEW HAS 2 ACTIVE CODES 1942 CRANKASE PRESSURE 4163 TAP SENSOR MODULE -WIP			OPERATOR COMPLAINT
2017713	9	09/10/2020	778	REGEN NEW HAS 2 ACTIVE CODES 1942 CRANKASE PRESSURE 4163 TAP SENSOR MODULE -WIP			SCHEDULED SERVICE
1804075	15	03/05/2018	832	REGEN			OPERATOR COMPLAINT
1816326	2	07/31/2018	797	REGEN SYSTEM			OPERATOR COMPLAINT
2017454	1	09/04/2020	853	PARTICULATE FILTER REGEN			SCHEDULED SERVICE
2208045	10	03/13/2022	828	perform regen, code came back up			OPERATOR COMPLAINT
1808217	2	04/24/2018	797	REGEN SYSTEM--REGEN SYSTEM FILTER CLEAR--BUT TEMP SENSOR CODE ACTIVE			OPERATOR COMPLAINT
1512935	8	09/16/2015	787	regen bus			OPERATOR COMPLAINT
1415646	3	11/06/2014	819	COMPLETE RADIATOR INSTALL FILL WITH COOLANT - CHECK CODES NEED REGEN			OPERATOR COMPLAINT
1903940	3	02/28/2019	820	REGEN--RESET MAINT & INSTALLATION FILTER			OPERATOR COMPLAINT
1516991	4	12/07/2015	809	CLEARED CODES			OPERATOR COMPLAINT
1506459	3	04/23/2015	789	REGEN			SCHEDULED SERVICE
2018957	5	09/25/2020	798	REGEN PARTICULATE FILTER			OPERATOR COMPLAINT
1900292	2	01/10/2019	837	T/S ENGINE AND PEFOMED STATIONARY JUST VTO UNRIFE AND REGEN WAS NOT THE PROBLEM PE			OPERATOR COMPLAINT
1500381	3	01/14/2015	751	REGEN			OPERATOR COMPLAINT
2018136	3	09/15/2020	796	REGEN DONE---CODES INACTIVE			OPERATOR COMPLAINT

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: PB1301 to PB1301

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>				<u>Cause-Reason</u>
PB1301	2832	PARTICULATE FILTER REGEN	Total Line Count for System Code 2832 :			56
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>		
1716637	2	09/15/2017	841	REGEN		OPERATOR COMPLAINT
						SCHEDULED SERVICE
1513785	1	10/06/2015	819	T/S ENGINE		SCHEDULED SERVICE
1513785	1	10/06/2015	809	T/S ENGINE		OPERATOR COMPLAINT
1515891	3	11/12/2015	756	REGEN - COMPLETED		OPERATOR COMPLAINT
1717228	2	09/25/2017	832	REGEN DONE		SCHEDULED SERVICE
1514753	8	10/23/2015	756	REGEN-CLEAR CODES		OPERATOR COMPLAINT
2017558	3	09/09/2020	643	PERFORMED STATIONARY REGEN NO CEL ON OKAY NOW		OPERATOR COMPLAINT
2004345	2	03/12/2020	797	REGEN SYSTEM		OPERATOR COMPLAINT
2128531	2	10/25/2021	797	REGEN BUS -OK		SCHEDULED SERVICE
2010594	7	06/12/2020	832	REGEN COMPLETLEY		OPERATOR COMPLAINT
1823022	3	01/16/2019	753	REGEN---CLEAR CODES		OPERATOR COMPLAINT
1903501	2	02/20/2019	820	REGEN--RESET MAINTENANCE & INSTALLATION FILTER--OK		OPERATOR COMPLAINT
1825492	2	11/27/2018	832	REGEN DONE		OPERATOR COMPLAINT
2019279	2	09/30/2020	820	REGEN		OPERATOR COMPLAINT
2226278	3	09/01/2022	778	regen		OPERATOR COMPLAINT
2013891	2	07/27/2020	797	REGEN---RESET SYSTEM --CLEAR CODES		OPERATOR COMPLAINT
1806812	2	04/09/2018	797	REGEN--CLEARED CODES		OPERATOR COMPLAINT
1716597	2	09/15/2017	818	REGEN , CLEAR CODE		OPERATOR COMPLAINT

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: **PB1301** to **PB1301**

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>					<u>Cause-Reason</u>
PB1301	2832	PARTICULATE FILTER REGEN			Total Line Count for System Code 2832 :	56	
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>			OPERATOR COMPLAINT
1905724	2	03/25/2019	797	REGEN SYSTEM			OPERATOR COMPLAINT
1815107	4	07/17/2018	832	REGEN DONE			OPERATOR COMPLAINT
PB1301	2833	PART FILTER ELEMENT CLEAN			Total Line Count for System Code 2833 :	4	
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>			OPERATOR COMPLAINT
1516007	5	11/13/2015	819	r/r particulate filter			OPERATOR COMPLAINT
1516007	4	11/13/2015	809	clean particulate filter incomplete			OPERATOR COMPLAINT
2018222	3	09/17/2020	839	REMOVE AND CLEAN DPF FILER -WIP - BAKE UNTIL 12AM-PART IN STOCK SOUTH COUNTY			OPERATOR COMPLAINT
2018222	4	09/17/2020	839	BAKE DPF FILTER			OPERATOR COMPLAINT
PB1301	2834	PART FILTER R&R			Total Line Count for System Code 2834 :	7	
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>			SCHEDULED SERVICE
1804075	12	03/05/2018	809	REMVD PARTICULATE FILTER--CK COOLANT LEVEL--FILL/INSTALL			OPERATOR COMPLAINT
2018222	5	09/17/2020	839	RE INSTALL DPF FILTER 2 TIMES DPF PRESS SENSOR CLIP			OPERATOR COMPLAINT
1516007	3	11/13/2015	809	removed particulate filter			OPERATOR COMPLAINT
2018880	5	09/25/2020	822	INSTALL DPF FILTERS			SCHEDULED SERVICE
1804075	13	03/05/2018	832	INSTALLED FILTERS			OPERATOR COMPLAINT
1516991	2	12/07/2015	809	NO PARTS IN STOCK			OPERATOR COMPLAINT
2018880	4	09/25/2020	778	REMVD FILTERS, HOSES--NIS--WIP			OPERATOR COMPLAINT

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: **PB1301** to **PB1301**

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>			<u>Total Line Count for System Code</u>		<u>Cause-Reason</u>
PB1301	2835	PART FILTER SENSORS			Total Line Count for System Code 2835 :	5	
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>			<u>Cause-Reason</u>
1516359	5	11/23/2015	786	REPLC PARTIC FILTER TEMP SENSOR MODULE			OPERATOR COMPLAINT
1804075	14	03/05/2018	832	MODULE FOR TEMP SENSOR DAMAGED---REPLACED			SCHEDULED SERVICE
2208045	17	03/13/2022	874	R&Rv pressure module			SCHEDULED SERVICE
1815107	3	07/17/2018	832	RR SENSOR NO INPUT ERASED CODE			OPERATOR COMPLAINT
2128844	2	10/25/2021	880	R&R OUTLET NOX SENSOR			OPERATOR COMPLAINT
PB1301	2836	AFTER-TREATMENT INJECTOR			Total Line Count for System Code 2836 :	2	
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>			<u>Cause-Reason</u>
1512935	7	09/16/2015	787	repalced dozer injector			OPERATOR COMPLAINT
1804075	6	03/05/2018	832	R/R DOZER INJECTOR			SCHEDULED SERVICE
PB1301	2843	R&R ENGINE BREATHER FILTER			Total Line Count for System Code 2843 :	5	
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>			<u>Cause-Reason</u>
1713479	3	08/01/2017	822	REMOVED BREATHER--HAREWARE STRIPPED--REPLCD BREATHER ASSY			OPERATOR COMPLAINT
2108590	7	04/18/2021	869	R/R ENGINE BREATHER FILTER			SCHEDULED SERVICE
2108590	7	04/18/2021	849	R/R ENGINE BREATHER FILTER			SCHEDULED SERVICE
2017713	3	09/10/2020	648	RR ENGINE BREATHER FILTER RR ENGINE OIL -HIGH			OPERATOR COMPLAINT
2013393	2	07/20/2020	837	R//R ENGINE BREATHER ASSEMBLY			SCHEDULED SERVICE

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: **PB1301** to **PB1301**

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>			<u>Total Line Count for System Code</u>		<u>Cause-Reason</u>
PB1301	2846	R/R DEF SENSOR			Total Line Count for System Code 2846 :	8	
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>			<u>OPERATOR COMPLAINT</u>
2022384	2	11/22/2020	789	R.R DEF PUMP			
1516644	6	11/30/2015	773	REPLC INJECTOR DOZER KIT			SCHEDULED SERVICE
1516644	6	11/30/2015	773	REPLC INJECTOR DOZER KIT			SCHEDULED SERVICE
1815481	3	07/19/2018	787	REPLCD OUTLET NOX SENSOR			OPERATOR COMPLAINT
2022384	5	11/22/2020	838	R/R DOSER INJECTOR			OPERATOR COMPLAINT
2022384	11	11/22/2020	869	R/R DEF SESNOR--REWIRE			OPERATOR COMPLAINT
2022384	11	11/22/2020	880	R/R DEF SESNOR--REWIRE			OPERATOR COMPLAINT
2022384	7	11/22/2020	838	NEEDS A DEF SENDING UNIT			OPERATOR COMPLAINT
PB1301	2847	DEF - LEAK			Total Line Count for System Code 2847 :	1	Cause-Reason
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>			<u>SCHEDULED SERVICE</u>
1804075	7	03/05/2018	832	R/R DOZER INJ HOSE--PRESSURE TEST			
PB1301	2849	SELECTIVE CATALYST REDUCTION			Total Line Count for System Code 2849 :	1	Cause-Reason
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>			<u>OPERATOR COMPLAINT</u>
1827651	3	01/03/2019	822	RAN SCR PERFORMANCE TEST AND IT PASSED -CLEARED ALL CODES			
PB1301	2851	DEF PUMP REPLACE			Total Line Count for System Code 2851 :	2	Cause-Reason
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>			<u>OPERATOR COMPLAINT</u>
2022384	6	11/22/2020	838	R/R DEF PUMP			
2125401	2	09/26/2021	809	R/R DOSER PUMP			OPERATOR COMPLAINT

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024 System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: PB1301 to PB1301

BUS#	SYS Code	SYS Code Description		Total Line Count for System Code 2900 :	19	Cause-Reason
PB1301	2900	TRANSMISSION				
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>		<u>SCHEDULED SERVICE</u>
1921419	7	11/19/2019	795	REPAIR TRANS DIPSTICK		SCHEDULED SERVICE
1921419	7	11/19/2019	789	REPAIR TRANS DIPSTICK		SCHEDULED SERVICE
2302059	4	01/28/2023	828	CHECK OIL LEVEL		OPERATOR COMPLAINT
2416916	3	07/17/2024	914	Added 2qts of ATF.		OPERATOR COMPLAINT
2123652	3	09/09/2021	820	T/S TRNS -CHECKED LEVEL -CLEARED INACTIVE CODE		OPERATOR COMPLAINT
2119382	3	07/28/2021	837	RESET OIL LIFE		OPERATOR COMPLAINT
2104540	2	03/02/2021	778	DRAINED (4)QTS OF TRANS FLUID--OK---WASHED TRANS		OPERATOR COMPLAINT
2021825	2	11/02/2020	839	REPLCD SHFT SELECTOR		OPERATOR COMPLAINT
2233965	2	01/19/2023	828	had to cut drive shaft bolts, to start the removal of transmission		OPERATOR COMPLAINT
2233965	1	01/19/2023	820	found codes p088a and p088b ran trans health and found c1 clutch bad		OPERATOR COMPLAINT
1509679	3	07/08/2015	631	transmission pm		SCHEDULED SERVICE
1801743	5	02/09/2018	27	REPAIRED BY ALLISON		SCHEDULED SERVICE
2006427	2	04/14/2020	841	TIGHTEN TRAN HOSE		OPERATOR COMPLAINT
1507016	2	05/06/2015	797	TRANSMISSION - ROAD TEST -OK RETARDER -OK		OPERATOR COMPLAINT
2232215	4	11/08/2022	778	reset trans fluid helth level indicator added two quarts of fluid		OPERATOR COMPLAINT
2213179	3	04/25/2022	786	RESET OIL LIFE		SCHEDULED SERVICE
2013393	7	07/20/2020	820	DRIANED TRAN OIL--REMVD COOLER HOSES--FLASHED SYSTEM--R/R TRANS FILTERS--ADD OIL/FLA		OPERATOR COMPLAINT
2327305	3	11/14/2023	809	RESET TRANS FLUID LIFE		

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: **PB1301** to **PB1301**

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>			<u>Cause-Reason</u>
PB1301	2900	TRANSMISSION	Total Line Count for System Code 2900 :		19
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	
2119423	1	07/28/2021	833	RESET TRANSMISSION OIL LIFE	OPERATOR COMPLAINT

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024 System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: PB1301 to PB1301

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>			<u>Cause-Reason</u>
PB1301	2901	TROUBLESHOOT TRANSMISSION	Total Line Count for System Code 2901 :		21
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>SCHEDULED SERVICE</u>
2208045	3	03/13/2022	828	perform trans health test to ransmission	
2102158	1	02/16/2021	820	TROUBLESHOOT TRANSMISSION--FOUND CK TRANS LIGHT ON, ALARM & ACTIVE	OPERATOR COMPLAINT
2302059	6	01/28/2023	820	T/S ENGINE	CODE P0897 OIL IF OPERATOR COMPLAINT
2302059	6	01/28/2023	833	T/S ENGINE	OPERATOR COMPLAINT
1517972	1	12/28/2015	822	TROUBLESHOOT TRANSMISSION -CKD OIL LEVEL-TRIED TO CONNECT TO ALLISON-WIP...ACTIVE CO	OPERATOR COMPLAINT
1517972	1	12/28/2015	732	TROUBLESHOOT TRANSMISSION -CKD OIL LEVEL-TRIED TO CONNECT TO ALLISON-WIP...ACTIVE CO	OPERATOR COMPLAINT
2106295	2	03/25/2021	752	RESET OIL LIFE	OPERATOR COMPLAINT
1602127	8	02/17/2016	753	START BUS CHECK TRANSLIGHT FOUND AVTIVE CODE P0843	SCHEDULED SERVICE
1602395	1	02/17/2016	753	T/S TRANS	WARRANTY
1825114	1	11/21/2018	838	TROUBLESHOOT TRANSMISSION---CODE 2789 CLUTCH ADAPTIVE LEARNING @LIMIT	OPERATOR COMPLAINT
2024906	1	12/14/2020	820	TROUBLESHOOT TRANSMISSION--FOUND CODE P0897--TRAN FLUID DETERIORATE--RESET--CLEAR!	OPERATOR COMPLAINT
1901012	4	01/21/2019	679	T/S TRANS -CHECK FLUID CONDITION AND LEVEL WHE N YOU PUT IN GEAR THE CLUTCH DOES NC	OPERATOR COMPLAINT
2232215	3	11/08/2022	778	t/s trans active code p0897, oil level low	OPERATOR COMPLAINT
1602127	9	02/17/2016	753	CHECKED WIRES DOUND INACTIVE CODE	SCHEDULED SERVICE
1602127	10	02/17/2016	820	ROAD TEST	SCHEDULED SERVICE
2016958	5	09/02/2020	820	TROUBLESHOOT TRANSMISSION---FOUND CK TRANS LIGHT ON--REPAIRED	OPERATOR COMPLAINT
2110158	1	05/01/2021	874	TROUBLESHOOT TRANSMISSION--CK TRANS LIGHT ON--CODE FOR OIL LIFE--RESET	OPERATOR COMPLAINT
2021825	1	11/02/2020	839	TROUBLESHOOT TRANS---NOT GOING IN DRIVE OR REVERSE---DIAGNOSE & MODE SELECTION WO	OPERATOR COMPLAINT

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: 1100 to 9700

Print Date: 3/25/2025

Asset# Range: PB1301 to PB1301

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>			<u>Cause-Reason</u>
PB1301	2901	TROUBLESHOOT TRANSMISSION	Total Line Count for System Code 2901 :		21
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
2106295	1	03/25/2021	753	T/S TRANS	OPERATOR COMPLAINT
2104540	1	03/02/2021	778	TROUBLESHOOT TRANS ---TRANS OVER FILLED	OPERATOR COMPLAINT
2303813	3	02/14/2023	778	t/s transmission	OPERATOR COMPLAINT
PB1301	2902	TRANSMISSION ECU PROGRAM	Total Line Count for System Code 2902 :		1
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
1517972	2	12/28/2015	732	TRANS ECU PROGRAM-RESET PROGNOSTICS DATA ON LIFE MONITOR @99%	OPERATOR COMPLAINT
PB1301	2904	TRANSMISSION REP	Total Line Count for System Code 2904 :		1
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
2208045	12	03/13/2022	820	pressure washed old trans, accumulator, ring gear. cleaned and installed on good used transmission. installed	SCHEDULED SERVICE
PB1301	2905	TRANSMISSION R & R	Total Line Count for System Code 2905 :		7
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
2208045	13	03/13/2022	820	floshed system , installed used trans, and put back everything, oil ok	SCHEDULED SERVICE
2208045	11	03/13/2022	820	drained oil removed drive shaft hoses harness connedctor bolts etc, removed trans no parts	SCHEDULED SERVICE
2208045	11	03/13/2022	832	drained oil removed drive shaft hoses harness connedctor bolts etc, removed trans no parts	SCHEDULED SERVICE
1901012	6	01/21/2019	796	REMOVE TRANS WHEN BUS STARTED ALOT OF GRINDING NOISE FROM TRANS	OPERATOR COMPLAINT
1901012	6	01/21/2019	859	REMOVE TRANS WHEN BUS STARTED ALOT OF GRINDING NOISE FROM TRANS	OPERATOR COMPLAINT
1901012	11	01/21/2019	823	INSTALL TRANS COMPLETE PRGRAM SHIFTING POINT COMPLETED	OPERATOR COMPLAINT
1901012	10	01/21/2019	823	INSTALL YOKE , RING GEAR AND ACCUMULATOR INSTALL TRANS DONE -NEEDS TI INSTALL STARTE	OPERATOR COMPLAINT
PB1301	2906	TRANSMISSION LEAKS REP	Total Line Count for System Code 2906 :		3
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
1901756	3	01/28/2019	796	REPAIR ATF LEAK--TOP OFF ATF @OPERATING TEMP--ALLISON DOC NEEDS TO BE FIRED	OPERATOR COMPLAINT
2303813	4	02/14/2023	778	R/R TRANS COOLER FITTING	OPERATOR COMPLAINT
2024770	4	12/16/2020	853	TORQUE TRANY LINE LOOSE	SCHEDULED SERVICE

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: 1100 to 9700

Print Date: 3/25/2025

Asset# Range: PB1301 to PB1301

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>			<u>Cause-Reason</u>
PB1301	2910	TRANSMISSION LINES REPL	Total Line Count for System Code 2910 :		2
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
2103029	4	03/03/2021	849	REMVD LEAKING TRANS COOLER LINE--DRAIND OIL FROM COOLER--INSTLLED NEW TRANS COOLE	SCHEDULED SERVICE
2103029	4	03/03/2021	797	REMVD LEAKING TRANS COOLER LINE--DRAIND OIL FROM COOLER--INSTLLED NEW TRANS COOLE	SCHEDULED SERVICE
PB1301	2911	TRANSMISSION FILTERS REPL	Total Line Count for System Code 2911 :		1
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
1901012	5	01/21/2019	679	DRAIN TRAINS FLUID REPLACED FLUID AND FILTER CONDITION STILL THE SAME CLUTCH DOES NC	OPERATOR COMPLAINT
PB1301	2912	DRIVE SHAFT	Total Line Count for System Code 2912 :		1
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
2100874	5	01/17/2021	832	REPLCD DRIVE SHAFT	SCHEDULED SERVICE
PB1301	2913	U JOINTS REPL	Total Line Count for System Code 2913 :		1
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
1901012	7	01/21/2019	796	REMOVED U JOINTS AND CLEANED DRIVE SHAFT MAY WANT TO PUT IN NEW REAR MAIN SEAL	OPERATOR COMPLAINT
PB1301	2914	TRANS.ELEC.SWITCHES/SENSO	Total Line Count for System Code 2914 :		1
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
2002648	7	02/18/2020	837	RR ACCMILATOR VALVE ASSEMBLY	SCHEDULED SERVICE
PB1301	2916	RETARDER REPAIR	Total Line Count for System Code 2916 :		2
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
1706410	7	04/18/2017	809	TIGHTEN RETARDER VALVE	SCHEDULED SERVICE
1516644	4	11/30/2015	828	R/R RETARDER SOLENOID ACTUATOR	SCHEDULED SERVICE
PB1301	3000	OPS -OTHER	Total Line Count for System Code 3000 :		2
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
1511883	2	08/24/2015	702	OPS-OTHER	OPERATOR COMPLAINT
1814112	5	07/05/2018	841	REMOVE GUM FROM DEAT	SCHEDULED SERVICE
PB1301	3002	SPILL-BEER/SODA	Total Line Count for System Code 3002 :		4
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
1312519	2	10/09/2013	668	WASH FLOOR	OPERATOR COMPLAINT
1904598	3	03/07/2019	848	MOP FLOOR & CLEAN SEAT	OPERATOR COMPLAINT
2205244	3	02/13/2022	848	MOP FLOOR AT LOCATION	OPERATOR COMPLAINT
1401037	2	01/23/2014	611	SPILL-BEER/SODA-CLEAN	OPERATOR COMPLAINT

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: 1100 to 9700

Print Date: 3/25/2025

Asset# Range: PB1301 to PB1301

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>			<u>Cause-Reason</u>
PB1301	3003	BODY FLUIDS/WASTE	Total Line Count for System Code 3003 :		5
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
2422232	3	09/12/2024	797	CLEAN BUS	OPERATOR COMPLAINT
2122495	3	08/30/2021	848	CLEAN, DISINFECT/DEODORIZE	OPERATOR COMPLAINT
1511198	2	08/11/2015	808	BODY FLUIDS/WASTE-INTERIOR CLEAN	OPERATOR COMPLAINT
1613987	3	10/01/2016	665	BODY FLUIDS /WASTE -CLEAN UP	OPERATOR COMPLAINT
1710107	3	06/09/2017	642	INTERIOR CLEAN	OPERATOR COMPLAINT
PB1301	3400	FARE BOX SERVICE	Total Line Count for System Code 3400 :		4
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
2234597	1	12/07/2022	752	fb pm	SCHEDULED SERVICE
2224585	3	08/12/2022	752	service fb bill feed	OPERATOR COMPLAINT
1310022	6	08/14/2013	742	INSTALL FAREBOX	SCHEDULED SERVICE
2225005	3	08/17/2022	752	service fb bill feed	OPERATOR COMPLAINT
PB1301	3401	TROUBLESHOOT FAREBOX	Total Line Count for System Code 3401 :		4
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
2222816	3	07/23/2022	752	remove stuck bill	OPERATOR COMPLAINT
2221862	3	07/13/2022	752	RESET FAREBOX	OPERATOR COMPLAINT
2220941	3	07/05/2022	752	Reset Farebox	OPERATOR COMPLAINT
2220723	1	07/02/2022	752	T/S FREBOX	OPERATOR COMPLAINT

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: **PB1301** to **PB1301**

BUS#	SYS Code	SYS Code Description				Total Line Count for System Code 3402 :	31	Cause-Reason
PB1301	3402	FAREBOX PM						
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>				<u>SCHEDULED SERVICE</u>
2001870	1	02/06/2020	751	FAREBOX PM				SCHEDULED SERVICE
1407067	1	05/27/2014	764	FAREBOX PM				SCHEDULED SERVICE
1817566	1	08/15/2018	751	FAREBOX PM				SCHEDULED SERVICE
1714673	1	08/15/2017	764	FAREBOX PM				OPERATOR COMPLAINT
2416354	1	07/11/2024	752	FB PM				SCHEDULED SERVICE
2111698	2	05/20/2021	751	FAREBOX PM --SERVICE THE TRIM				SCHEDULED SERVICE
2111698	2	05/20/2021	731	FAREBOX PM --SERVICE THE TRIM				SCHEDULED SERVICE
1805602	1	03/21/2018	764	FAREBOX PM----COMPLETED				SCHEDULED SERVICE
2125617	2	09/28/2021	751	COMPLETE F/B PM				OPERATOR COMPLAINT
1407067	2	05/27/2014	749	FAREBOX REPLC				SCHEDULED SERVICE
2224069	1	08/06/2022	752	FB PM				SCHEDULED SERVICE
1506892	1	05/02/2015	764	FAREBOX PM-COMPLETED				SCHEDULED SERVICE
2015716	1	08/14/2020	751	FAREBOX PM				SCHEDULED SERVICE
1500311	1	01/09/2015	10	FAREBOX PM - COMPELTED F/B P.M.				SCHEDULED SERVICE
1402470	1	02/21/2014	764	FAREBOX PM				SCHEDULED SERVICE
2100252	1	01/07/2021	751	FAREBOX PM				SCHEDULED SERVICE
2211204	1	04/08/2022	752	FAREBOX PM				SCHEDULED SERVICE
1517234	1	12/09/2015	764	FAREBOX PM-COMPLETED				SCHEDULED SERVICE

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: PB1301 to PB1301

BUS#	SYS Code	SYS Code Description			Total Line Count for System Code		Cause-Reason
PB1301	3402	FAREBOX PM			31		
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>			<u>OPERATOR COMPLAINT</u>
1611335	1	08/09/2016	764	FB PM			SCHEDULED SERVICE
1826810	1	12/20/2018	751	FAREBOX PM			SCHEDULED SERVICE
1908332	1	05/06/2019	751	FAREBOX PM			SCHEDULED SERVICE
1413484	1	09/19/2014	764	FAREBOX PM - COMPLETED F/B P.M.			SCHEDULED SERVICE
1917613	1	09/25/2019	751	FAREBOX PM			SCHEDULED SERVICE
1604866	2	04/08/2016	770	FAREBOX PM			SCHEDULED SERVICE
1511632	1	08/19/2015	764	farebox pm			SCHEDULED SERVICE
1720327	2	11/13/2017	751	FAREBOX PM			SCHEDULED SERVICE
2025834	1	12/27/2020	731	FAREBOX PM			SCHEDULED SERVICE
1705925	2	04/17/2017	749	FAREBOX PM			SCHEDULED SERVICE
1617238	1	12/09/2016	764	FAREBOX PM--COMPLETED			SCHEDULED SERVICE
2236061	1	12/24/2022	752	FB PM DUE			SCHEDULED SERVICE
2010764	1	06/16/2020	751	FAREBOX PM			SCHEDULED SERVICE
PB1301	3403	RESET FAREBOX			1		
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>			<u>OPERATOR COMPLAINT</u>
2221860	3	07/20/2022	752	REMOVE CARD. RESET FAREBOX			

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: 1100 to 9700

Print Date: 3/25/2025

Asset# Range: PB1301 to PB1301

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>				<u>Cause-Reason</u>
PB1301	3404	FAREBOX REPL	Total Line Count for System Code 3404 :			14
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>SCHEDULED SERVICE</u>	
1705925	1	04/17/2017	764	FAREBOX REPLC	SCHEDULED SERVICE	
2100252	2	01/07/2021	731	FAREBOX REPLCD	SCHEDULED SERVICE	
2015716	2	08/14/2020	764	FAREBOX REPLCD	SCHEDULED SERVICE	
2025834	2	12/27/2020	752	FAREBOX REPLACED	SCHEDULED SERVICE	
2125617	1	09/28/2021	752	R&R F/B	SCHEDULED SERVICE	
1908332	2	05/06/2019	764	FAREBOX REPLACED	SCHEDULED SERVICE	
1917613	2	09/25/2019	764	FAREBOX REPLACED	SCHEDULED SERVICE	
1817566	2	08/15/2018	764	FAREBOX REPLACED	SCHEDULED SERVICE	
2010764	2	06/16/2020	764	FAREBOX REPLACE	SCHEDULED SERVICE	
2001870	2	02/06/2020	764	FAREBOX REPLACED	SCHEDULED SERVICE	
1720327	1	11/13/2017	764	FAREBOX REPLACED	SCHEDULED SERVICE	
1604866	1	04/08/2016	764	FAREBOX REPLACE	SCHEDULED SERVICE	
1826810	2	12/20/2018	731	FAEBOX REPALCED	SCHEDULED SERVICE	
2111698	1	05/20/2021	752	FAREBOX REPLCD	SCHEDULED SERVICE	
PB1301	3418	COIN MECH JAMED	Total Line Count for System Code 3418 :			1
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>OPERATOR COMPLAINT</u>	
2214924	3	05/10/2022	731	CLEAR THE COIN MECH. & PUT IT BACK ON NORMAL OPERATION	OPERATOR COMPLAINT	

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: **PB1301** to **PB1301**

BUS#	SYS Code	SYS Code Description			Total Line Count for System Code 3419 :	3	Cause-Reason
PB1301	3419	DOLLAR MECH JAMED					
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>			<u>Cause-Reason</u>
2214138	3	05/04/2022	731	UNJAMMED THE DOLLAR TRANSPORTER			OPERATOR COMPLAINT
2214383	3	05/06/2022	731	REMOVED JAMMED DOLLARS			OPERATOR COMPLAINT
2214383	3	05/06/2022	731	REMOVED JAMMED DOLLARS			OPERATOR COMPLAINT

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: 1100 to 9700

Print Date: 3/25/2025

Asset# Range: PB1301 to PB1301

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>				<u>Cause-Reason</u>
PB1301	4000	TIRES	Total Line Count for System Code 4000 :			19
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>		
2002176	1	02/13/2020	809	TIRES---TORQUE WHEELS 500LB		OPERATOR COMPLAINT
2023913	1	12/09/2020	752	TIRES NEED REPLC--R/R TIRE STUD		SCHEDULED SERVICE
1822636	10	10/19/2018	752	INSTALL FRONT TIRES		SCHEDULED SERVICE
2008552	1	05/13/2020	800	RR RETORQUE TIRES		SCHEDULED SERVICE
2009828	3	06/03/2020	853	TIRES---ADVISE GOODYEAR TECH TO REPLC AS NECESSARY		OPERATOR COMPLAINT
2011096	1	06/16/2020	837	TIRES---REARS & R/S & L/S TIRES		OPERATOR COMPLAINT
2021158	17	10/27/2020	871	R/R ALL 4 TIRES ON REAR AXLE--TORQUED		SCHEDULED SERVICE
1921419	6	11/19/2019	795	REPLCD MISSING LUG NUT INDICATORS		SCHEDULED SERVICE
1921419	6	11/19/2019	789	REPLCD MISSING LUG NUT INDICATORS		SCHEDULED SERVICE
1921419	12	11/19/2019	795	TIRE TECH INSPECTED RF TIRE		SCHEDULED SERVICE
1921419	12	11/19/2019	789	TIRE TECH INSPECTED RF TIRE		SCHEDULED SERVICE
2003209	1	02/29/2020	837	TIRES---		SCHEDULED SERVICE
2213020	3	04/24/2022	833	REPLACE R/R OUTER TIRE.		OPERATOR COMPLAINT
1820571	2	09/20/2018	746	REPLCD FRONT TIRE		OPERATOR COMPLAINT
1512533	3	09/08/2015	815	INSTALLED REAR TIRE		SCHEDULED SERVICE
1905702	1	03/25/2019	837	TIRES---COMPLETED		SCHEDULED SERVICE
1915218	1	08/21/2019	764	TIRES--TORQUE TIRES		SCHEDULED SERVICE
2016528	1	08/24/2020	837	TIRES----CHECK TIRE TORQUE----LEFT REAR		SCHEDULED SERVICE

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024 System Code Range: 1100 to 9700

Print Date: 3/25/2025

Asset# Range: PB1301 to PB1301

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>			<u>Cause-Reason</u>
PB1301	4000	TIRES	Total Line Count for System Code 4000 :		19
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
2020408	3	10/15/2020	27	TIRE CHANGED BY MICHELIN TECH	OPERATOR COMPLAINT
PB1301	4001	TIRE REPAIR	Total Line Count for System Code 4001 :		1
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
2002648	5	02/18/2020	837	RR RRO TIRE -RR RRI TIRE	SCHEDULED SERVICE
PB1301	4007	LUGS MISSING OR LOOSE	Total Line Count for System Code 4007 :		1
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
2023711	1	12/02/2020	29	LUGS MISSING OR LOOSE	PARTS ONLY
PB1301	4008	BROKEN STUDS	Total Line Count for System Code 4008 :		4
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
2021158	18	10/27/2020	871	REPAIRED 1 DAMAGED LUG STUD ON ---R/R HUB	SCHEDULED SERVICE
2116500	4	07/11/2021	799	REMV HUB & WHEEL STUDS--POO---WIP	OPERATOR COMPLAINT
2116500	4	07/11/2021	882	REMV HUB & WHEEL STUDS--POO---WIP	OPERATOR COMPLAINT
2116500	6	07/11/2021	823	INSTALL NEW STUDS R/RIGHT HUB--COMPLETED	OPERATOR COMPLAINT
PB1301	4011	L/F TIRE REPLACEMENT	Total Line Count for System Code 4011 :		2
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
1608815	3	06/22/2016	791	R/R LEFT FRONT TIRE	OPERATOR COMPLAINT
1807676	5	04/17/2018	822	R/R LEFT FRONT TIRE	OPERATOR COMPLAINT
PB1301	4012	R/F TIRE REPLACEMENT	Total Line Count for System Code 4012 :		2
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
1807676	6	04/17/2018	822	R/R RIGHT FRONT TIRE	OPERATOR COMPLAINT
1608815	2	06/22/2016	791	R/R FRONT TIRE	OPERATOR COMPLAINT
PB1301	4013	L/R/O TIRE REPLACEMENT	Total Line Count for System Code 4013 :		3
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
1827559	9	12/28/2018	797	REPLCD LRO TIRE	SCHEDULED SERVICE
1712651	4	07/17/2017	773	REPLACED LEFT REAR OUTSIDE TIRE	OPERATOR COMPLAINT
1807676	3	04/17/2018	822	R/R LRO TIRE	OPERATOR COMPLAINT

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: **PB1301** to **PB1301**

BUS#	SYS Code	SYS Code Description			Total Line Count for System Code	Cause-Reason
PB1301	4014	L/R/I TIRE REPLACEMENT			3	
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>		<u>Cause-Reason</u>
1712651	3	07/17/2017	773	REPLACED LEFT REAR INSIDE TIRES		OPERATOR COMPLAINT
1827559	10	12/28/2018	797	REPLCD LRI TIRE		SCHEDULED SERVICE
1807676	4	04/17/2018	822	R/R LRI TIRE		OPERATOR COMPLAINT
PB1301	4015	R/R/O TIRE REPLACEMENT			3	
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>		<u>Cause-Reason</u>
2306560	3	03/16/2023	828	R/R R/R/O TIRE		OPERATOR COMPLAINT
2116500	5	07/11/2021	799	R/R RRO TIRE		OPERATOR COMPLAINT
2116500	5	07/11/2021	882	R/R RRO TIRE		OPERATOR COMPLAINT
PB1301	4016	R/R/I TIRE REPLACEMENT			3	
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>		<u>Cause-Reason</u>
1722609	1	12/18/2017	828	RRI TIRE REPLACEMENT		OPERATOR COMPLAINT
2116500	3	07/11/2021	799	R/R RRI TIRE		OPERATOR COMPLAINT
2116500	3	07/11/2021	882	R/R RRI TIRE		OPERATOR COMPLAINT

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024 System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: PB1301 to PB1301

BUS#	SYS Code	SYS Code Description			Total Line Count for System Code 5001 :	10	Cause-Reason
PB1301	5001	CAMERAS					
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>			<u>Cause-Reason</u>
1814330	1	07/06/2018	29	CAMERAS PCO			OPERATOR COMPLAINT
1404045	1	03/24/2014	710	CAMERAS-CHARGE OUT PART ONLY			OPERATOR COMPLAINT
2303348	1	02/09/2023	901	PM AVIL SYS. REPLACE DRIVER CAM W/DECOM PARTS. ALL SYS GOOD			OPERATOR COMPLAINT
2412219	1	05/31/2024	896	REPLACED CURBSIDE CAMERA			OPERATOR COMPLAINT
2215743	1	05/21/2022	895	replaced camera 7,2,5 and reset dvr			SCHEDULED SERVICE
2215743	1	05/21/2022	892	replaced camera 7,2,5 and reset dvr			SCHEDULED SERVICE
1824874	1	11/15/2018	27	CAMERAS---PART CHARGE OUT			SCHEDULED SERVICE
1611983	1	08/23/2016	27	CAMERAS---PART CHARGE OUT			SCHEDULED SERVICE
2009840	1	06/01/2020	27	CAMERAS			SCHEDULED SERVICE
1608176	1	06/09/2016	29	CAMERAS			OPERATOR COMPLAINT
PB1301	5002	RADIOS			Total Line Count for System Code 5002 :	6	Cause-Reason
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>			<u>Cause-Reason</u>
2010684	3	06/12/2020	762	RADIOS -CHECKED AND REPOSITIONED			OPERATOR COMPLAINT
2224201	1	08/08/2022	892	RADIO			OPERATOR COMPLAINT
2412335	2	06/01/2024	901	REPROGRAM RADIO			OPERATOR COMPLAINT
2412335	1	06/01/2024	896	RADIOS			OPERATOR COMPLAINT
1310150	1	08/21/2013	705	radio ser#10186908 p.c.o			SCHEDULED SERVICE
2214506	1	05/06/2022	828	CHECKED CONNECTIONS FOUND RUSTY PINS AND BENT ON THE INTERFACE BETWEEN SPEAKER A			OPERATOR COMPLAINT

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: **PB1301** to **PB1301**

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>			<u>Cause-Reason</u>
PB1301	5003	SIGNS	Total Line Count for System Code 5003 :		2
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	
2100297	1	01/06/2021	27	SIGNS----PART CHARGE OUT	SCHEDULED SERVICE
2020650	1	10/20/2020	27	SIGNS	OPERATOR COMPLAINT

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: 1100 to 9700

Print Date: 3/25/2025

Asset# Range: PB1301 to PB1301

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>				<u>Cause-Reason</u>
PB1301	5004	AVL -- Repairs	Total Line Count for System Code 5004 :			17
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>		
2224084	1	08/06/2022	901	pm system rear monitor dow, replace monitor, all good		OPERATOR COMPLAINT
2225818	1	08/31/2022	901	AVL		OPERATOR COMPLAINT
1708218	1	05/12/2017	27	AVL--REPAIRS		OPERATOR COMPLAINT
2221301	1	07/14/2022	892	SCREEN NEEDS REPLACEMENT		OPERATOR COMPLAINT
2221301	1	07/14/2022	895	SCREEN NEEDS REPLACEMENT		OPERATOR COMPLAINT
2412895	2	06/07/2024	901	replace mdt screen and router out of bus 1206 program ip and system works properly		OPERATOR COMPLAINT
2218803	1	06/16/2022	892	CHECKED FUSES TO MINITOR OK, CHECK FOR POWER AND GROUND AT CONNECTOR TO MONITOR		OPERATOR COMPLAINT
2218803	1	06/16/2022	895	CHECKED FUSES TO MINITOR OK, CHECK FOR POWER AND GROUND AT CONNECTOR TO MONITOR		OPERATOR COMPLAINT
2219562	1	06/24/2022	29	AVAIL		OPERATOR COMPLAINT
2133477	1	12/03/2021	833	swap avail screen		OPERATOR COMPLAINT
1708444	1	05/16/2017	27	AVL---REPAIRS---PART CHARGE OUT		OPERATOR COMPLAINT
2412895	1	06/07/2024	901	found bad mdt screen and router		OPERATOR COMPLAINT
2230131	1	10/14/2022	901	ck mpm and found ip conflict, re addressed and it went back online		OPERATOR COMPLAINT
2301722	3	01/21/2023	901	could not boot system, replaced bad ts mdt, pm system ok		MECHANIC DEFECT
1311291	1	09/17/2013	707	AVL-REPAIRS. PARTS ONLY		OPERATOR COMPLAINT
2233597	1	11/24/2022	901	adjust apm clock aync time and added 10 minutes intervals		WARRANTY
1312121	1	10/02/2013	707	AVL-REPAIRS		

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: **PB1301** to **PB1301**

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>			<u>Total Line Count for System Code 8010 :</u>	<u>170</u>	<u>Cause-Reason</u>
PB1301	8010	TRAVEL TIME - Road Call					
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>			
1719867	1	11/03/2017	795	TRAVEL TIME-ROAD CALL--SWAP W/1113			OTHER MECHANICAL BREAKDOWN
1513621	1	10/02/2015	778	travel time			MAJOR MECHANICAL BREAKDOWN
1408815	1	06/26/2014	731	t/s engine			MAJOR MECHANICAL BREAKDOWN
1815481	1	07/19/2018	800	TRAVEL TIME---ROAD CALL--SWAP W/1212			MAJOR MECHANICAL BREAKDOWN
1815481	1	07/19/2018	853	TRAVEL TIME---ROAD CALL--SWAP W/1212			MAJOR MECHANICAL BREAKDOWN
1817291	1	08/14/2018	752	TRAVEL TIME--ROAD CALL--SWAP W0721			MAJOR MECHANICAL BREAKDOWN
1817291	1	08/14/2018	848	TRAVEL TIME--ROAD CALL--SWAP W0721			MAJOR MECHANICAL BREAKDOWN
1613987	1	10/01/2016	747	TRAVEL TIME ROAD CALL			NON - MECHANICAL BREAKDOWN
1617140	1	12/07/2016	800	TRAVEL TIME--ROAD CALL-SWAPPED			MAJOR MECHANICAL BREAKDOWN
1911994	1	07/01/2019	798	TRAVEL TIME ROAD CALL			MAJOR MECHANICAL BREAKDOWN
1719440	1	11/02/2017	841	TRAVEL TIME ROAD CALL SWAP W/1125			MAJOR MECHANICAL BREAKDOWN
1900133	1	01/08/2019	822	TRAVEL TIME--ROAD CALL--SWAP W1506			OTHER MECHANICAL BREAKDOWN
1907349	1	04/18/2019	648	TRAVEL TIME---ROAD CALL---			MAJOR MECHANICAL BREAKDOWN
1609162	1	06/28/2016	648	TRAVEL TIME ROAD CALL			MAJOR MECHANICAL BREAKDOWN
2119382	1	07/28/2021	837	TRAVEL TIME			MAJOR MECHANICAL BREAKDOWN
1723336	1	12/29/2017	781	TRAVEL TIME ROAD CALL SWAP WITH 1406			MAJOR MECHANICAL BREAKDOWN
1511967	1	08/26/2015	731	TRAVEL TIME-ROAD CALL			MAJOR MECHANICAL BREAKDOWN
1826105	1	12/05/2018	756	TRAVEL TIME---ROAD CALL--SWAP OUT			MAJOR MECHANICAL BREAKDOWN

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: **PB1301** to **PB1301**

BUS#	SYS Code	SYS Code Description			Total Line Count for System Code 8010 :	170	Cause-Reason
PB1301	8010	TRAVEL TIME - Road Call					
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>			
2205244	1	02/13/2022	848	TRAVEL TIME			OTHER MECHANICAL BREAKDOWN
2225005	1	08/17/2022	752	travel			NON - MECHANICAL BREAKDOWN
1913761	1	07/29/2019	752	TRAVEL TIME ROAD CALL			MAJOR MECHANICAL BREAKDOWN
1909230	1	05/17/2019	753	TRAVEL TIME--ROAD CALL			MAJOR MECHANICAL BREAKDOWN
1815107	1	07/17/2018	828	TRAVEL TIME ROAD CALL -SWAP WITH 1128			MAJOR MECHANICAL BREAKDOWN
2104937	1	03/08/2021	752	TRAVEL TIME--ROAD CALL---SWAP W/2004			MAJOR MECHANICAL BREAKDOWN
1515891	1	11/12/2015	756	ROAD CALL			MAJOR MECHANICAL BREAKDOWN
2017713	1	09/10/2020	799	TRAVEL TIME ROAD CALL			MAJOR MECHANICAL BREAKDOWN
2202116	1	02/28/2022	797	SWAP W/1515			MAJOR MECHANICAL BREAKDOWN
1807676	1	04/17/2018	822	TRAVEL TIME---ROAD CALL--SWAP W/1208			MAJOR MECHANICAL BREAKDOWN
1516359	1	11/23/2015	786	TRAVEL TIME-ROAD CALL-			NON - MECHANICAL BREAKDOWN
1401037	1	01/23/2014	611	TRAVEL TIME-ROAD CALL			OTHER MECHANICAL BREAKDOWN
2416723	1	07/15/2024	907	Travel Time			MAJOR MECHANICAL BREAKDOWN
2018136	1	09/15/2020	859	TRAVEL TIME--ROAD CALL--			MAJOR MECHANICAL BREAKDOWN
1905760	1	04/17/2019	809	TRAVEL TIME---ROAD CALL--SWAP W/TROUBLESHOOT ROAD CALL---			OTHER MECHANICAL BREAKDOWN
1500381	1	01/14/2015	641	TRAVEL TIME-ROAD CALL-SWAP W/1109			MAJOR MECHANICAL BREAKDOWN
1705185	1	03/27/2017	828	TRAVEL TIME ROAD CALL SWAP 1121			MAJOR MECHANICAL BREAKDOWN
2302059	1	01/28/2023	828	ROAD CALL			MAJOR MECHANICAL BREAKDOWN

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: PB1301 to PB1301

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>			<u>Cause-Reason</u>
PB1301	8010	TRAVEL TIME - Road Call	Total Line Count for System Code 8010 :		170
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	
1723466	1	01/02/2018	818	TRAVEL TIME--ROAD CALL--SWAP W/TRUCK	OTHER MECHANICAL BREAKDOWN
1818056	1	08/21/2018	752	TRAVEL TIME ROAD CALL SWAP WITH 1103	NON - MECHANICAL BREAKDOWN
1617260	1	12/10/2016	822	TRAVEL TIME--ROAD CALL--	MAJOR MECHANICAL BREAKDOWN
1501498	1	01/26/2015	731	TRAVEL TIME-ROAD CALL	OTHER MECHANICAL BREAKDOWN
1408567	1	06/18/2014	789	TRAVEL TIME-ROAD CALL-SWAP W/0616	MAJOR MECHANICAL BREAKDOWN
2021881	1	11/04/2020	864	TRAVEL TIME ROAD CALL	OTHER MECHANICAL BREAKDOWN
2021881	1	11/04/2020	778	TRAVEL TIME ROAD CALL	OTHER MECHANICAL BREAKDOWN
1403480	1	03/14/2014	773	road call swap with pb0800	MAJOR MECHANICAL BREAKDOWN
2210458	1	03/31/2022	853	travel time	MAJOR MECHANICAL BREAKDOWN
2116500	1	07/11/2021	799	TRAVEL TIME--ROAD CALL--	MAJOR MECHANICAL BREAKDOWN
1819839	1	09/18/2018	756	TRAVEL TIME ROAD CALL -SWAP	MAJOR MECHANICAL BREAKDOWN
1903696	1	02/25/2019	836	TRAVEL TIME---ROAD CALL-SWAP W/0721--DISCONNECTED COOLANT SENSORS	MAJOR MECHANICAL BREAKDOWN
1511198	1	08/11/2015	808	TRAVEL TIME-ROAD CALL-	MAJOR MECHANICAL BREAKDOWN
2222816	1	07/23/2022	752	travel time	MAJOR MECHANICAL BREAKDOWN
2123652	1	09/09/2021	820	TRAVEL TIME ROADC CALL	OTHER MECHANICAL BREAKDOWN
1511883	1	08/24/2015	824	TRAVEL TIME-ROAD CALL-	OTHER MECHANICAL BREAKDOWN
2301722	1	01/21/2023	849	travel time	OTHER MECHANICAL BREAKDOWN
2016958	1	09/02/2020	828	TRAVEL TIME--ROAD CALL--SWAP W/1101--PERFORM REGEN	MAJOR MECHANICAL BREAKDOWN

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: **PB1301** to **PB1301**

BUS#	SYS Code	SYS Code Description				Total Line Count for System Code 8010 :	170	Cause-Reason
PB1301	8010	TRAVEL TIME - Road Call						
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>				
1903940	1	02/28/2019	820	TROUBLESHOOT ROAD CALL---SWAP W/0725				MAJOR MECHANICAL BREAKDOWN
1315025	1	11/21/2013	641	TRAVEL TIME - ROAD CALL				OTHER MECHANICAL BREAKDOWN
2018491	1	09/22/2020	824	TRAVEL TIME ROAD CALL--				MAJOR MECHANICAL BREAKDOWN
2018880	1	09/25/2020	864	TRAVEL TIME---ROAD CALL--				MAJOR MECHANICAL BREAKDOWN
1722381	1	12/13/2017	825	TRAVEL TIME--ROAD CALL-SWAP W/1213				MAJOR MECHANICAL BREAKDOWN
2122495	1	08/30/2021	848	TRAVEL TIME--ROAD CALL--SEND UTILITY W/SERVICE TRUCK				MAJOR MECHANICAL BREAKDOWN
2224585	1	08/12/2022	752	travel				NON - MECHANICAL BREAKDOWN
1716054	1	09/03/2017	751	TRAVEL TIME ROAD CALL SWAP W/0708				MAJOR MECHANICAL BREAKDOWN
2417025	1	07/18/2024	887	travel time				MAJOR MECHANICAL BREAKDOWN
1508644	1	06/11/2015	809	TRAVEL ITME-ROAD CALL-SWAP W/1302				OTHER MECHANICAL BREAKDOWN
1506459	1	04/23/2015	789	TRAVEL TIME-ROAD CALL-SWAP W/0805				MAJOR MECHANICAL BREAKDOWN
1312519	1	10/09/2013	764	TRAVEL TIME - ROAD CALL				OTHER MECHANICAL BREAKDOWN
1510853	1	08/04/2015	731	TRAVEL TIME-ROAD CALL-SWAP W/0610				MAJOR MECHANICAL BREAKDOWN
2306560	1	03/16/2023	828	ROAD CALL				MAJOR MECHANICAL BREAKDOWN
1907856	1	04/26/2019	836	TRAVEL TIME---ROAD CALL--SWAP W1208				MAJOR MECHANICAL BREAKDOWN
1826733	1	12/19/2018	778	TRAVEL TIME ROAD CALL SWAP 0225				OTHER MECHANICAL BREAKDOWN
1711291	1	06/28/2017	828	TRAVEL TIME-ROAD CALL-				OTHER MECHANICAL BREAKDOWN
2221862	1	07/13/2022	752	TRAVEL- ROAD CALL				MAJOR MECHANICAL BREAKDOWN

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: 1100 to 9700

Print Date: 3/25/2025

Asset# Range: PB1301 to PB1301

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>			<u>Total Line Count for System Code 8010 :</u>	<u>170</u>	<u>Cause-Reason</u>
PB1301	8010	TRAVEL TIME - Road Call					
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>			
1818120	1	08/21/2018	764	TRAVEL TIME ROAD CALL TAKE BUS 1101			NON - MECHANICAL BREAKDOWN
1827651	1	01/03/2019	799	TRAVEL TIME ROAD CALL			MAJOR MECHANICAL BREAKDOWN
1718148	1	10/09/2017	756	TRAVEL TIME- ROAD CALL SWAP OUT			MAJOR MECHANICAL BREAKDOWN
1711950	1	07/11/2017	679	TRAVEL TIME ROAD CALL			MAJOR MECHANICAL BREAKDOWN
1904598	1	03/07/2019	848	TRAVEL TIME--ROAD CALL--			NON - MECHANICAL BREAKDOWN
1902659	1	02/08/2019	752	TRAVEL TIME ROAD CALL TAKE 1215			MAJOR MECHANICAL BREAKDOWN
1616879	1	11/29/2016	800	TRAVEL TIME-ROAD CALL---SWAP W/0615			MAJOR MECHANICAL BREAKDOWN
1713479	1	08/01/2017	823	TRAVEL TIME-ROAD CALL---SWAP W/1406			MAJOR MECHANICAL BREAKDOWN
1717004	1	09/21/2017	841	TRAVEL TIME-ROAD CALL---SWAP W/1116			MAJOR MECHANICAL BREAKDOWN
1808739	1	05/02/2018	809	TRAVEL TIME----ROAD CALL--SWAP W1518--ASSIST W/COOLANT			MAJOR MECHANICAL BREAKDOWN
1808739	1	05/02/2018	837	TRAVEL TIME----ROAD CALL--SWAP W1518--ASSIST W/COOLANT			MAJOR MECHANICAL BREAKDOWN
2008676	1	05/13/2020	836	TRAVEL TIME---ROAD CALL--SWAP W/1214			OTHER MECHANICAL BREAKDOWN
2327305	1	11/14/2023	809	TRAVEL TIME			OTHER MECHANICAL BREAKDOWN
2015728	1	08/14/2020	841	TRAVEL TIME--ROAD CALL--BRING PARTS FOR REPAIR			MAJOR MECHANICAL BREAKDOWN
2015728	1	08/14/2020	762	TRAVEL TIME--ROAD CALL--BRING PARTS FOR REPAIR			MAJOR MECHANICAL BREAKDOWN
1717398	1	09/27/2017	747	TRAVEL TIME- ROAD CALL			MAJOR MECHANICAL BREAKDOWN
2013199	1	07/14/2020	746	TRAVEL TIME--ROAD CALL--SWAP W/1128			NON - MECHANICAL BREAKDOWN
1403547	1	03/15/2014	773	TRAVEL TIME-ROAD CALL-SWAP W/1002			OTHER MECHANICAL BREAKDOWN

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: **PB1301** to **PB1301**

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>			<u>Total Line Count for System Code 8010 :</u>	<u>170</u>	<u>Cause-Reason</u>
PB1301	8010	TRAVEL TIME - Road Call					
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>			
1315639	1	12/03/2013	759	TRAVEL TIME - ROAD CALL			MAJOR MECHANICAL BREAKDOWN
1820644	1	09/24/2018	679	TRAVEL TIME--ROAD CALL--			OTHER MECHANICAL BREAKDOWN
2222897	1	07/23/2022	799	TOWED TO S/C LOCKED ALT.			MAJOR MECHANICAL BREAKDOWN
1615835	1	11/08/2016	762	TRAVEL TIME ROAD CALL SWAP W/ 0902			MAJOR MECHANICAL BREAKDOWN
1710107	1	06/09/2017	642	TRAVEL TIME-ROAD CALL-service truck			MAJOR MECHANICAL BREAKDOWN
1902753	1	02/11/2019	756	TRAVEL TIME---ROAD CALL--SWAP OUT			OTHER MECHANICAL BREAKDOWN
1919511	1	10/21/2019	764	TRAVEL TIME--ROAD CALL--			NON - MECHANICAL BREAKDOWN
2109458	1	04/25/2021	880	TRAVEL TIME--ROAD CALL--SWAP W/1508			MAJOR MECHANICAL BREAKDOWN
1314075	1	11/05/2013	756	TRAVEL TIME - ROAD CALL			OTHER MECHANICAL BREAKDOWN
2228659	1	09/27/2022	887	travel time			MAJOR MECHANICAL BREAKDOWN
2101626	1	01/26/2021	800	TRAVEL TIME ROAD CALL SWAP W1101			MAJOR MECHANICAL BREAKDOWN
1512935	1	09/16/2015	732	Commercial Workorder Entry TRAVEL TIME			MAJOR MECHANICAL BREAKDOWN
2422317	1	09/15/2024	648	Travel Time & wait for the tow truck			MAJOR MECHANICAL BREAKDOWN
2422317	1	09/15/2024	648	Travel Time & wait for the tow truck			MAJOR MECHANICAL BREAKDOWN
2020663	1	10/27/2020	849	TRAVEL TIME--ROAD CALL--			MAJOR MECHANICAL BREAKDOWN
2224296	1	08/10/2022	753	TRAVEL TIME RC			MAJOR MECHANICAL BREAKDOWN
2009828	1	06/03/2020	853	TRAVEL TIME--ROAD CALL--SWAP W/1303			OTHER MECHANICAL BREAKDOWN
2009828	1	06/03/2020	797	TRAVEL TIME--ROAD CALL--SWAP W/1303			OTHER MECHANICAL BREAKDOWN

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: **PB1301** to **PB1301**

BUS#	SYS Code	SYS Code Description			Total Line Count for System Code 8010 :	170	Cause-Reason
PB1301	8010	TRAVEL TIME - Road Call					
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>			
2416122	1	07/10/2024	823	TRAVEL TIME			MAJOR MECHANICAL BREAKDOWN
2018029	1	09/14/2020	747	TRAVEL TIME--ROAD CALL--SWAP W/1117			OTHER MECHANICAL BREAKDOWN
1901012	1	01/21/2019	833	TRAVEL TIME ROAD CALL			MAJOR MECHANICAL BREAKDOWN
1516007	1	11/13/2015	809	travel time road call swap with #1008			OTHER MECHANICAL BREAKDOWN
2020332	1	10/14/2020	795	TRAVEL TIME--ROAD CALL--SWAP W/1114			OTHER MECHANICAL BREAKDOWN
2231206	1	10/27/2022	887	travel			NON - MECHANICAL BREAKDOWN
2229218	1	10/05/2022	828	SWAP BUS			MAJOR MECHANICAL BREAKDOWN
1917708	1	09/26/2019	643	TRAVEL TIME--ROAD CALL----			MAJOR MECHANICAL BREAKDOWN
1904084	1	03/04/2019	836	TRAVEL TIME--ROAD CALL--SWAP W/0725			MAJOR MECHANICAL BREAKDOWN
2221860	1	07/20/2022	752	TRAVEL TIME			OTHER MECHANICAL BREAKDOWN
1608393	1	06/14/2016	809	TRAVEL TIME-ROAD CALL-SWAP W/1008			MAJOR MECHANICAL BREAKDOWN
2422232	1	09/12/2024	849	TRAVEL TIME			NON - MECHANICAL BREAKDOWN
2213020	1	04/24/2022	833	SWAP.			OTHER MECHANICAL BREAKDOWN
1901756	1	01/28/2019	796	TRAVEL TIME--ROAD CALL--SWAP W/0802			MAJOR MECHANICAL BREAKDOWN
2018222	1	09/17/2020	864	TRAVEL TIME ROAD CALL			MAJOR MECHANICAL BREAKDOWN
2020408	1	10/15/2020	795	TRAVEL TIME ROAD CALL			OTHER MECHANICAL BREAKDOWN
2003084	1	02/29/2020	800	TRAVEL TIME---ROAD CALL---SWAP OUT			NON - MECHANICAL BREAKDOWN
2003084	1	02/29/2020	619	TRAVEL TIME---ROAD CALL---SWAP OUT			NON - MECHANICAL BREAKDOWN

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: 1100 to 9700

Print Date: 3/25/2025

Asset# Range: PB1301 to PB1301

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>			<u>Total Line Count for System Code 8010 :</u>	<u>170</u>	<u>Cause-Reason</u>
PB1301	8010	TRAVEL TIME - Road Call					
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>			
1502307	1	02/11/2015	643	TRAVEL TIME-ROAD CALL-SWAP W/ 0618			OTHER MECHANICAL BREAKDOWN
2129262	1	11/04/2021	622	TRAVEL TIME--ROAD CALL--			NON - MECHANICAL BREAKDOWN
2023465	1	12/03/2020	762	TRAVEL TIME--ROAD CALL--SWAP			OTHER MECHANICAL BREAKDOWN
1924219	1	12/30/2019	837	TRAVEL TIME---ROAD CALL--			MAJOR MECHANICAL BREAKDOWN
1617099	1	12/06/2016	825	TRAVEL TIME ROAD CALL SWAP W/1214			MAJOR MECHANICAL BREAKDOWN
2213179	1	04/25/2022	786	TRAVEL TIME/ ROAD CALL			MAJOR MECHANICAL BREAKDOWN
1823613	1	10/31/2018	797	TRAVEL TIME ROAD CALL -SWAP W/0807			MAJOR MECHANICAL BREAKDOWN
2106377	1	03/26/2021	752	TRAVEL TIME ROAD CALL			MAJOR MECHANICAL BREAKDOWN
1409249	1	07/07/2014	764	TRAVEL TIME-ROAD CALL-SWAP			MAJOR MECHANICAL BREAKDOWN
1715663	1	08/28/2017	800	TRAVEL TIME -ROAD CALL			MAJOR MECHANICAL BREAKDOWN
2105414	1	03/15/2021	859	TRAVEL TIME---ROAD CALL---AC THERMO KING CONTROLLER BEHIND AC PANEL WAS OFF--TURNT			MAJOR MECHANICAL BREAKDOWN
1500696	1	01/22/2015	731	TRAVEL TIME-ROAD CALL			MAJOR MECHANICAL BREAKDOWN
2017558	1	09/09/2020	643	TRAVEL TIME ROAD CALL -SWAP WITH 1015			OTHER MECHANICAL BREAKDOWN
2018644	1	09/21/2020	869	TRAVEL TIME ROAD CALL -SWAP 1106			OTHER MECHANICAL BREAKDOWN
2018644	1	09/21/2020	799	TRAVEL TIME ROAD CALL -SWAP 1106			OTHER MECHANICAL BREAKDOWN
1721998	1	12/07/2017	796	TRAVEL TIME -TO PGA ROAD CALL			OTHER MECHANICAL BREAKDOWN
2003851	1	03/12/2020	753	TRAVEL TIME ROAD CALL			OTHER MECHANICAL BREAKDOWN
1500337	1	01/09/2015	789	TRAVEL TIME-ROAD CALL			MAJOR MECHANICAL BREAKDOWN

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: PB1301 to PB1301

BUS#	SYS Code	SYS Code Description			Total Line Count for System Code 8010 :	170	Cause-Reason
PB1301	8010	TRAVEL TIME - Road Call					
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>			
2220941	1	07/05/2022	752	Travel time	MAJOR MECHANICAL BREAKDOWN		
2133816	1	12/09/2021	833	ROAD CALL	OTHER MECHANICAL BREAKDOWN		
2421657	1	09/06/2024	833	travel time	MAJOR MECHANICAL BREAKDOWN		
2416717	1	07/15/2024	913	travel time	MAJOR MECHANICAL BREAKDOWN		
2010684	1	06/12/2020	762	TRAVEL TIME ROAD CALL -SWAP WITH 1123	MAJOR MECHANICAL BREAKDOWN		
1712651	1	07/17/2017	773	TRAVEL TIME ROAD CALL	OTHER MECHANICAL BREAKDOWN		
2214138	1	05/04/2022	731	TRAVEL TIME	OTHER MECHANICAL BREAKDOWN		
2214383	1	05/06/2022	731	TRAVEL TIME	OTHER MECHANICAL BREAKDOWN		
1509861	1	07/10/2015	799	TRAVEL TIME-ROAD CALL-DISCONNECT FIRE HEAT SENSORS-WIP.....	MAJOR MECHANICAL BREAKDOWN		
2018797	1	09/23/2020	839	TRAVEL TIME--ROAD CALL--	MAJOR MECHANICAL BREAKDOWN		
1826381	1	12/10/2018	759	TRAVEL TIME--ROAD CALL-	OTHER MECHANICAL BREAKDOWN		
2214924	1	05/10/2022	731	TRAVEL TIME RC	OTHER MECHANICAL BREAKDOWN		
1506853	1	05/02/2015	828	TRAVEL TIME-ROAD CALL-SWAP BUS	OTHER MECHANICAL BREAKDOWN		
1506853	1	05/02/2015	781	TRAVEL TIME-ROAD CALL-SWAP BUS	OTHER MECHANICAL BREAKDOWN		
2124033	1	09/14/2021	837	TRAVEL TIME--ROAD CALL--SWAP W/1406	NON - MECHANICAL BREAKDOWN		
1316719	1	12/26/2013	789	TRAVEL TIME - ROAD CALL	MAJOR MECHANICAL BREAKDOWN		
2109165	1	04/22/2021	828	TRAVEL TIME--ROAD CALL--	OTHER MECHANICAL BREAKDOWN		
1820375	1	09/20/2018	789	TRAVEL TIME---ROAD CALL-	OTHER MECHANICAL BREAKDOWN		

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: **PB1301** to **PB1301**

BUS#	SYS Code	SYS Code Description			Total Line Count for System Code 8010 :	170	Cause-Reason
PB1301	8010	TRAVEL TIME - Road Call					
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>			<u>Cause-Reason</u>
1820192	1	09/17/2018	823	TRAVEL TIME--ROAD CALL--			MAJOR MECHANICAL BREAKDOWN
1708710	1	05/19/2017	839	TRAVEL TIME-ROAD CALL-			MAJOR MECHANICAL BREAKDOWN
2232215	1	11/08/2022	823	travel time			OTHER MECHANICAL BREAKDOWN
1718433	1	10/16/2017	747	TRAVEL TIME- ROAD CALL			MAJOR MECHANICAL BREAKDOWN
1902141	1	02/01/2019	759	TRAVEL TIME--ROAD CALL--			MAJOR MECHANICAL BREAKDOWN
2305899	1	03/09/2023	809	TRAVEL TIME			MAJOR MECHANICAL BREAKDOWN
2024956	1	12/15/2020	853	TRAVEL TIME--ROAD CALL--SWAP			MAJOR MECHANICAL BREAKDOWN
1801743	1	02/09/2018	798	TRAVEL TIME-ROAD CALL-			MAJOR MECHANICAL BREAKDOWN

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: **PB1301** to **PB1301**

BUS#	SYS Code	SYS Code Description			Total Line Count for System Code 8011 :	137	Cause-Reason
PB1301	8011	TROUBLESHOOT ROAD CALL					
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>			<u>OPERATOR COMPLAINT</u>
2228659	2	09/27/2022	887	WATER LEAK IN FRONT THE DRIVER SEAT.			OPERATOR COMPLAINT
1722381	2	12/13/2017	778	TROUBLESHOOT ROAD CALL---HORN INOP--FOUND BROKEN WIRE @BUTTON			OPERATOR COMPLAINT
2210458	2	03/31/2022	853	trouble shoot road call			OPERATOR COMPLAINT
2105414	2	03/15/2021	795	TROUBLESHOOT ROAD CALL---AC DISPLAY IS BLANK--SYSTEM COMES ON--FOUND AC CONTROL IS			OPERATOR COMPLAINT
1907856	2	04/26/2019	836	TROUBLESHOOT ROAD CALL---CODES 2311/0272--ACTIVE FUEL PRESSURE--E STROKE LIGHT ON			OPERATOR COMPLAINT
2003851	2	03/12/2020	787	T/S ROAD CALL			OPERATOR COMPLAINT
1903696	2	02/25/2019	798	TROUBLESHOOT ROAD CALL--CEL LOW COOLANT			OPERATOR COMPLAINT
2205244	2	02/13/2022	848	SPILL ON FLOOR			OPERATOR COMPLAINT
2106377	2	03/26/2021	752	T/S ROAD CALL -DIAG THERMASAT ON HIGH			OPERATOR COMPLAINT
2224296	2	08/10/2022	753	FOUND BAD CONTACT VOLTAGE REGULATOR ROUND CONNECTOR WAS LOOSE			OPERATOR COMPLAINT
1815107	2	07/17/2018	828	t/s croad call -code 3725 intake nox sensor			OPERATOR COMPLAINT
1817291	2	08/14/2018	752	TROUBLESHOOT ROAD CALL---FOUND COOLANT LEAK			OPERATOR COMPLAINT
2416122	2	07/10/2024	823	HEATER HOSE LEAKING			OPERATOR COMPLAINT
2018491	2	09/22/2020	823	TROUBLESHOOT ROAD CALL----MIL/REGEN NEEDED LIGHT ON			OPERATOR COMPLAINT
1710107	2	06/09/2017	642	TROUBLESHOOT ROAD CALL---body fluids			OPERATOR COMPLAINT
2416723	2	07/15/2024	907	A/C is working but not cooling properly			OPERATOR COMPLAINT
1705185	2	03/27/2017	828	T/S ROAD CALL NEEDS NEW GENERATOR VOLTAGE REGULATOR AND ALTERNATOR BELT			OPERATOR COMPLAINT
2220941	2	07/05/2022	752	Fare box needed reset			OPERATOR COMPLAINT

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: 1100 to 9700

Print Date: 3/25/2025

Asset# Range: PB1301 to PB1301

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>			<u>Cause-Reason</u>
PB1301	8011	TROUBLESHOOT ROAD CALL	Total Line Count for System Code 8011 :		137
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	
1613987	2	10/01/2016	747	T/S ROAD CALL -BLOOD ON THE FLOOR	OPERATOR COMPLAINT
2008676	2	05/13/2020	808	TROUBLESHOOT ROAD CALL---BIKE RACK BROKEN	OPERATOR COMPLAINT
2018029	2	09/14/2020	747	TROUBLESHOOT ROAD CALL--REAR DOOR NOT WORKING	OPERATOR COMPLAINT
2327305	2	11/14/2023	809	TRANS LIGHT ON. NO ENGINE CODE	OPERATOR COMPLAINT
1721998	2	12/07/2017	796	T/S ROAD CALL -REATTACHED TERMINAL TO HORN BUTTON	OPERATOR COMPLAINT
2221860	2	07/20/2022	752	CARD STUCK	OPERATOR COMPLAINT
1719440	2	11/02/2017	841	T/S ROAD CALL -FOUR ACTIVE CODES	OPERATOR COMPLAINT
2109458	2	04/25/2021	828	TROUBLESHOOT ROAD CALL--FIRE HARNESS & SENSORS ARE SHORTED	OPERATOR COMPLAINT
1902753	2	02/11/2019	756	TROUBLESHOOT ROAD CALL----BLOOD ON BUS	OPERATOR COMPLAINT
1516007	2	11/13/2015	809	t/s road call	OPERATOR COMPLAINT
2018136	2	09/15/2020	796	TROUBLESHOOT ROAD CALL---NEEDS REGEN	OPERATOR COMPLAINT
2229218	2	10/05/2022	828	FOUND AIR BAG LEAK	OPERATOR COMPLAINT
2020332	2	10/14/2020	822	TROUBLESHOOT ROAD CALL--REAR DOOR INOP--FOUND SOLENOID NR	OPERATOR COMPLAINT
2213179	2	04/25/2022	786	T/S ROAD CALL	OPERATOR COMPLAINT
1609162	2	06/28/2016	786	TROUBLESHOOT ROAD CALL	OPERATOR COMPLAINT
1617260	2	12/10/2016	822	TROUBLESHOOT ROAD CALL-----COOLANT SYSTEM LOW	OPERATOR COMPLAINT
1617099	2	12/06/2016	825	T/S ROAD CALL BUS A LITTLE LOW ON COOLANT -REFILLED AND PRESSURE CHECK SYSYSTEM -FOU!	OPERATOR COMPLAINT
1818056	2	08/21/2018	752	T/S ROAD CALL -SODA IN AISLE	OPERATOR COMPLAINT

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: **PB1301** to **PB1301**

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>			<u>Cause-Reason</u>
PB1301	8011	TROUBLESHOOT ROAD CALL	Total Line Count for System Code 8011 :		137
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	
2116500	2	07/11/2021	799	TROUBLESHOOT ROAD CALL---	OPERATOR COMPLAINT
1917708	2	09/26/2019	643	TROUBLESHOOT ROAD CALL---BUS START UP---NO CEL LIGHT ON	OPERATOR COMPLAINT
2129262	2	11/04/2021	622	VOMIT ON FLOOR	OPERATOR COMPLAINT
1801743	2	02/09/2018	798	TROUBLESHOOT ROAD CALL---TRANS DOES NOT SHIFT--STAYS IN 2ND GEAR	OPERATOR COMPLAINT
2231206	2	10/27/2022	887	seatbelt stuck (john zanca)	OPERATOR COMPLAINT
1515891	2	11/12/2015	756	T/S ROAD CALL- NEED REGEN	OPERATOR COMPLAINT
1708710	2	05/19/2017	839	TROUBLESHOOT ROAD CALL----COOLANT LEAK	OPERATOR COMPLAINT
1901756	2	01/28/2019	796	TROUBLESHOOT ROAD CALL---ATF LEAKING	OPERATOR COMPLAINT
1902141	2	02/01/2019	759	TROUBLESHOOT ROAD CALL--SEAT BELT STUCK	OPERATOR COMPLAINT
1516359	2	11/23/2015	786	TROUBLESHOOT ROAD CALL-3582 ACTIVE	OPERATOR COMPLAINT
1718433	2	10/16/2017	747	TROUBLESHOOT ROAD CALL- CEL/ SEL NO CHAGRE/ LOW COOLANT	OPERATOR COMPLAINT
1608393	2	06/14/2016	809	TROUBLESHOOT ROAD CALL--SEAT BELT INOP	OPERATOR COMPLAINT
1723336	2	12/29/2017	781	T/S ROAD CALL PURGE VALVE STUCK OPEN	OPERATOR COMPLAINT
2202116	2	02/28/2022	797	diag	OPERATOR COMPLAINT
1826105	2	12/05/2018	756	TROUBLESHOOT ROAD CALL---LOOSE STANCHION@FRONT DOOR	OPERATOR COMPLAINT
1513621	2	10/02/2015	778	t/s road call cleans all lineear fire detection wire	OPERATOR COMPLAINT
1913761	2	07/29/2019	752	T/S ROAD CALL	OPERATOR COMPLAINT
2213020	2	04/24/2022	833	R/R OUTER FLAT.	OPERATOR COMPLAINT

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024 System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: PB1301 to PB1301

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>			<u>Cause-Reason</u>
PB1301	8011	TROUBLESHOOT ROAD CALL	Total Line Count for System Code 8011 :		137
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	
1719867	2	11/03/2017	795	TROUBLESHOOT ROAD CALL--LOW ON COOLANT--TOPPED OFF--LIGHT STILL ON---DISCONNECTED !	OPERATOR COMPLAINT
1717398	2	09/27/2017	747	TROUBLESHOOT ROAD CALL- INSTALL UPPER RADIATOR HOSE NEEDS WATER PUMP BELT	OPERATOR COMPLAINT
1815481	2	07/19/2018	787	TROUBLESHOOT ROAD CALL--INSPECT	OPERATOR COMPLAINT
1617140	2	12/07/2016	800	TROUBLESHOOT ROAD CALL---CODES FOR LOW COOLANT--POURED WATER TO GET BACK	OPERATOR COMPLAINT
2010684	2	06/12/2020	762	T/S ROAD CALL RADIO INOP	OPERATOR COMPLAINT
2306560	2	03/16/2023	828	T/S ROAD CALL	OPERATOR COMPLAINT
1718148	2	10/09/2017	756	TROUBLESHOOT ROAD CALL- WATER PUMP BELT BROKEN	OPERATOR COMPLAINT
2003084	2	02/29/2020	800	TROUBLESHOOT ROAD CALL---DIRTY BUS	OPERATOR COMPLAINT
1808739	2	05/02/2018	809	TROUBLESHOOT ROAD CALL--CEL, SEL, LOW COOLANT LIGHT ON--LOW ON COOLANT	OPERATOR COMPLAINT
2023465	2	12/03/2020	797	TROUBLESHOOT ROAD CALL--GLASS ON MIRROR DAMAGED	OPERATOR COMPLAINT
2222897	2	07/23/2022	839	TROUBLESHOOT ROAD CALL	OPERATOR COMPLAINT
2123652	2	09/09/2021	820	T/S ROAD CALL -FOUND TRANS LIGHT ON AND ALARM	OPERATOR COMPLAINT
1903940	2	02/28/2019	820	TROUBLESHOOT ROAD CALL---ACTIVE CODE FOR REGEN--CK & STOP ENGINE LIGHT ON	OPERATOR COMPLAINT
2017713	2	09/10/2020	648	T/S RODA CALL -ACTIVE CODES 1942 CRANKCASAE PRESS 3875 AFTER DIESEL PART FILTER REGEN	OPERATOR COMPLAINT
2222816	2	07/23/2022	752	bill feed	OPERATOR COMPLAINT
2232215	2	11/08/2022	778	trans light on	OPERATOR COMPLAINT
2018880	2	09/25/2020	864	TROUBLESHOOT ROAD CALL----STOP ENGINE & MIL LIGHT ON--DERATE MODE--ACTIVE CODE 1922-I	OPERATOR COMPLAINT
1820644	2	09/24/2018	679	TROUBLESHOOT ROAD CALL----FILTER CLOGGED---EVAP COIL DIRTY	OPERATOR COMPLAINT

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: PB1301 to PB1301

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>			<u>Cause-Reason</u>
PB1301	8011	TROUBLESHOOT ROAD CALL	Total Line Count for System Code 8011 :		137
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	
1826381	2	12/10/2018	759	TROUBLESHOOT ROAD CALL---DRIVER SEAT BELT JAMMED	OPERATOR COMPLAINT
2119382	2	07/28/2021	837	TRANSMISSION OIL LIFE NEEDS TO BE RESET	OPERATOR COMPLAINT
1615835	2	11/08/2016	762	T/S ROAD CALL	OPERATOR COMPLAINT
1911994	2	07/01/2019	798	T/S ROAD CALL -DRIVER SEAT BACK REST CROOKED ADJ INOP	OPERATOR COMPLAINT
1807676	2	04/17/2018	822	TROUBLESHOOT ROAD CALL -- CURBSIDE REAR TIRE HAS A BULGE ONTHE SIDE--FRONT TIRE NEEI	OPERATOR COMPLAINT
2214924	2	05/10/2022	731	COIN BY-PASS	OPERATOR COMPLAINT
2421657	2	09/06/2024	833	cel	OPERATOR COMPLAINT
1909230	2	05/17/2019	753	TROUBLESHOOT ROAD CALL--HEATER VAVLE LEAKING COOLANT	OPERATOR COMPLAINT
1820192	2	09/17/2018	823	TROUBLESHOOT ROAD CALL---AC IS WORKING--MIL LIGHT ON--SUN VISOR NR	OPERATOR COMPLAINT
2104937	2	03/08/2021	752	TROUBLESHOOT ROAD CALL--RAMP INOP---NEEDS PROXIMITY SWITCH	OPERATOR COMPLAINT
2225005	2	08/17/2022	752	t/s	OPERATOR COMPLAINT
2221862	2	07/13/2022	752	FAREBOX BYPASS	OPERATOR COMPLAINT
1820375	2	09/20/2018	789	TROUBLESHOOT ROAD CALL---LOW FUEL	OPERATOR COMPLAINT
1616879	2	11/29/2016	800	TROUBLESHOOT ROAD CALL---LOW COOLANT	OPERATOR COMPLAINT
2018797	2	09/23/2020	795	TROUBLESHOOT ROAD CALL---FREON LEVEL LOW--EVAP PLUGGED W/DIRT-FANS AREBENT OVER I	OPERATOR COMPLAINT
1819839	2	09/18/2018	756	T/S ROAD CALL-REGEN-FUMES FROM REGEN WAS COMING IN THE OPEN DOORS -NO SMOKE ON BU	OPERATOR COMPLAINT
2124033	2	09/14/2021	705	TROUBLESHOOT ROAD CALL--TSHOOT ON WO 2124040	OPERATOR COMPLAINT
1827651	2	01/03/2019	822	T/S ROAD CALL -ACTIVE CODES 3582 3714 3712 3543 INACTIVE CODES 151 4163 0286 CHEKC FOR EX	OPERATOR COMPLAINT

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024 System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: PB1301 to PB1301

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>			<u>Cause-Reason</u>
PB1301	8011	TROUBLESHOOT ROAD CALL	Total Line Count for System Code 8011 :		137
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	
1818120	2	08/21/2018	764	T/S ROAD CALL NPF	OPERATOR COMPLAINT
1826733	2	12/19/2018	789	T/S ROAD CAALL -LEAKS AT RADIATOR	OPERATOR COMPLAINT
2017558	2	09/09/2020	643	T/S ROAD CALL -SEL ON	OPERATOR COMPLAINT
2018644	2	09/21/2020	787	T/S ROAD CALL INSPECT DIAG	OPERATOR COMPLAINT
1715663	2	08/28/2017	800	T/S ROAD CALL --FRONT ROAD SIDE AIR BAG LEAKING	OPERATOR COMPLAINT
2024956	2	12/15/2020	853	TROUBLESHOOT ROAD CALL--FOUND ENGINE ALT BELT MISSING & DAMAGE BELT TENSIONER	OPERATOR COMPLAINT
2305899	2	03/09/2023	809	INSPECT BRAKES. BRAKES ARE WITHIN SPECT.	OPERATOR COMPLAINT
1717004	2	09/21/2017	841	TROUBLESHOOT ROAD CALL---water pump belt broken	OPERATOR COMPLAINT
2301722	2	01/21/2023	901	bad display	OPERATOR COMPLAINT
2009828	2	06/03/2020	853	TROUBLESHOOT ROAD CALL---install drive shaft--replcd tire left front	OPERATOR COMPLAINT
2009828	2	06/03/2020	797	TROUBLESHOOT ROAD CALL---install drive shaft--replcd tire left front	OPERATOR COMPLAINT
2109165	2	04/22/2021	828	TROUBLESHOOT ROAD CALL--LOW SIDE HOSE IS LOOSE	OPERATOR COMPLAINT
1712651	2	07/17/2017	773	TRAVEL TIME ROAD CALL -BAD RECCAP	OPERATOR COMPLAINT
1907349	2	04/18/2019	648	TROUBLESHOOT ROAD CALL---COOLANT LEAK FROM ENGINE COMP	OPERATOR COMPLAINT
1900133	2	01/08/2019	822	TROUBLESHOOT ROAD CALL---INACTIVE CODE 3582, 4151, 4163--DPF TEMP ABOVE NORMAL OPER	OPERATOR COMPLAINT
2214383	2	05/06/2022	731	DALLARS JAMED	OPERATOR COMPLAINT
2214138	2	05/04/2022	731	DOLLAR JAMMED	OPERATOR COMPLAINT
1924219	2	12/30/2019	837	TROUBLESHOOT ROAD CALL----IBSPECT BRAKES--NPF--NEED TO CLEAN BRAKES	OPERATOR COMPLAINT

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024 System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: PB1301 to PB1301

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>				<u>Cause-Reason</u>
PB1301	8011	TROUBLESHOOT ROAD CALL	Total Line Count for System Code 8011 :			137
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>		
2422317	2	09/15/2024	648	Oil leak. No oil on the dipstick.	OPERATOR COMPLAINT	
2416717	2	07/15/2024	913	low fuel light on	OPERATOR COMPLAINT	
1905760	2	04/17/2019	809	TROUBLESHOOT ROAD CALL---CODES 3582, 3543/ACTIVE--CLEARED CODES	OPERATOR COMPLAINT	
1823613	2	10/31/2018	797	T/S ROAD CALL -DIAG ENG FOUND PARTICULATE FILTER AND SCR AND VGT	OPERATOR COMPLAINT	
2013199	2	07/14/2020	833	TROUBLESHOOT ROAD CALL---BAD GROUND, FANS INOP	OPERATOR COMPLAINT	
1723466	2	01/02/2018	818	TROUBLESHOOT ROAD CALL---CK TRANS LIGHT ON/LOW COOLANT LIGHT ON	OPERATOR COMPLAINT	
2302059	2	01/28/2023	828	T/S ROAD CALL	OPERATOR COMPLAINT	
2020663	2	10/27/2020	849	TROUBLESHOOT ROAD CALL---CEL FOR EGR SYS--BUS NO START WHEN CRANKING--POSSIBLE EGI	OPERATOR COMPLAINT	
2417025	2	07/18/2024	809	dig fuel level sender	OPERATOR COMPLAINT	
1901012	2	01/21/2019	833	T/S ROAD CALL TRANS SHIFTING HARSHLY AND WOULD NO UP SHIFT PASS 25 MPH CODE PO961 M	SCHEDULED SERVICE	
1716054	2	09/03/2017	751	T/S ROAD CALL	OPERATOR COMPLAINT	
2016958	2	09/02/2020	828	TROUBLESHOOT ROAD CALL---DPF SENSOR MODULE ACTING UP	OPERATOR COMPLAINT	
2224585	2	08/12/2022	752	t/s	OPERATOR COMPLAINT	
1919511	2	10/21/2019	762	TROUBLESHOOT ROAD CALL--W/CHAIR RAMP WONT LOCK DOWN	OPERATOR COMPLAINT	
1902659	2	02/08/2019	781	T/S ROAD CA;; FOUND FRONT HB CAPS LEAKING OIL	OPERATOR COMPLAINT	
2021881	2	11/04/2020	778	T/S ROAD CALL -ACTIVE CODES FOR LOW COOLAANT LEVEL WIP	OPERATOR COMPLAINT	
2122495	2	08/30/2021	848	TROUBLESHOOT ROAD CALL---URINE ON FLOOR	OPERATOR COMPLAINT	
1711950	2	07/11/2017	679	CHECK ENG LOW COOLANT PRESSURE LEAK	OPERATOR COMPLAINT	

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: 1100 to 9700

Print Date: 3/25/2025

Asset# Range: PB1301 to PB1301

BUS#	SYS Code	SYS Code Description			Total Line Count for System Code	Cause-Reason
PB1301	8011	TROUBLESHOOT ROAD CALL			137	Cause-Reason
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>		<u>OPERATOR COMPLAINT</u>
2018222	2	09/17/2020	864	T/S ROAD CALL NIGHT EXHAUST TEMP LIGHT ON NO FAILER CODES		HISTORY REOCURING SENSEC
2018222	2	09/17/2020	839	T/S ROAD CALL NIGHT EXHAUST TEMP LIGHT ON NO FAILER CODES		HISTORY REOCURING SENSEC
1711291	2	06/28/2017	828	TROUBLESHOOT ROAD CALL----DEF LEVEL SENSOR PLUG IS LOOSE		OPERATOR COMPLAINT
2015728	2	08/14/2020	841	TROUBLESHOOT ROAD CALL-----water pump belt broke--ac belt nr		OPERATOR COMPLAINT
2101626	2	01/26/2021	800	T/S ROAD CALL 0689 CRANK SPEED POSITION 3714 AND 3382		OPERATOR COMPLAINT
2422232	2	09/12/2024	849	BODY FLUID BY DOOR		OPERATOR COMPLAINT
1904084	2	03/04/2019	795	TROUBLESHOOT ROAD CALL---CODES FOR COOLANT LEVEL--DERATE SCR CONVERSION--UNABLE		OPERATOR COMPLAINT
1904598	2	03/07/2019	848	TROUBLESHOOT ROAD CALL--COFFEE SPILL		OPERATOR COMPLAINT
2133816	2	12/09/2021	833	T/S ROAD CALL		OPERATOR COMPLAINT
1713479	2	08/01/2017	822	TROUBLESHOOT ROAD CALL---LEAKING OIL FROM DIPSTICK		OPERATOR COMPLAINT
2020408	2	10/15/2020	795	T/S ROAD CALL -RR INSIDE TIRE FLAT TIRE TECH		OPERATOR COMPLAINT
PB1301	8015	Travel Time - Parts Pick-Up			5	Cause-Reason
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>		<u>OPERATOR COMPLAINT</u>
2216609	2	05/25/2022	874	PART PICK UP		OPERATOR COMPLAINT
1512935	6	09/16/2015	787	to get part kenworth		SCHEDULED SERVICE
2103029	8	03/03/2021	780	TRAVELT IME TO PICK UP LIGHT MODULE		SCHEDULED SERVICE
1917148	6	09/18/2019	756	TRAVEL TIME		OPERATOR COMPLAINT
1901012	9	01/21/2019	823	DROPPED TRANS TO SOUTH TO BE REBUILD		OPERATOR COMPLAINT
PB1301	8020	MISCELLANEOUS Travel Time			1	Cause-Reason
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>		<u>OPERATOR COMPLAINT</u>
1718433	5	10/16/2017	825	SOUTH FOR PARTS		OPERATOR COMPLAINT

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: 1100 to 9700

Print Date: 3/25/2025

Asset# Range: PB1301 to PB1301

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>				<u>Cause-Reason</u>
PB1301	8060	DRIVE TO DEALER	Total Line Count for System Code 8060 :			2
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>	
1500696	4	01/22/2015	705	TAKE TO CUMMINS	WARRANTY	
1500381	5	01/14/2015	668	TAKE TO CUMMINS- PARTICULATE DIESEL FILTER TEMP	WARRANTY	
PB1301	8080	TOWED BY OUTSIDE WRECKER	Total Line Count for System Code 8080 :			1
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>	
2422317	3	09/15/2024	27	Towed by Sisters Towing	TOWING SERVICE	
PB1301	9400	IN SERVICE P.M.	Total Line Count for System Code 9400 :			3
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>	
1310022	1	08/14/2013	798	IN SERVICE PM	SCHEDULED SERVICE	
2322153	1	09/13/2023	894	IN SERVICE/ SAFTEY INSPECTION	SCHEDULED SERVICE	
2322153	1	09/13/2023	796	IN SERVICE/ SAFTEY INSPECTION	SCHEDULED SERVICE	

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: 1100 to 9700

Print Date: 3/25/2025

Asset# Range: PB1301 to PB1301

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>	Total Line Count for System Code 9406 :			15	<u>Cause-Reason</u>
PB1301	9406	6,000 MILE PM					
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>			
1715363	1	09/01/2017	781	6.000 MILE PM			OPERATOR COMPLAINT
1616392	1	11/16/2016	773	6.000 MILE PM			OPERATOR COMPLAINT
2219725	1	06/24/2022	839	6,000K PM DUE			SCHEDULED SERVICE
2219725	1	06/24/2022	648	6,000K PM DUE			SCHEDULED SERVICE
1811403	1	06/01/2018	841	6K MILE PM---COMPLETED			SCHEDULED SERVICE
1923274	1	12/18/2019	829	8.00 MIILE PM			OPERATOR COMPLAINT
1904977	1	03/18/2019	781	6K MILE PM---COMPLETED			SCHEDULED SERVICE
1410267	1	07/22/2014	818	6,000 MILE PM - COMPLETED			SCHEDULED SERVICE
1602127	1	02/17/2016	828	6,000 MILE PM			OPERATOR COMPLAINT
1313341	1	10/23/2013	797	6K PM - COMPLETED			SCHEDULED SERVICE
2111697	1	05/19/2021	839	6K MILE PM--COMPLETED			SCHEDULED SERVICE
2016013	1	08/19/2020	841	6K MILE PM---COMPLETED			SCHEDULED SERVICE
1506734	1	04/29/2015	764	6K MILE PM-COMPLETED			SCHEDULED SERVICE
2418363	1	08/03/2024	926	6k pm			SCHEDULED SERVICE
2418363	1	08/03/2024	880	6k pm			SCHEDULED SERVICE

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: PB1301 to PB1301

BUS#	SYS Code	SYS Code Description				Total Line Count for System Code 9412 :	14	Cause-Reason
PB1301	9412	12,000 MILE PM						
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>				
1908788	1	05/10/2019	779	12.000 MIL PM				OPERATOR COMPLAINT
1617704	1	12/23/2016	819	12K MILE PM--COMPLETED				SCHEDULED SERVICE
1314797	1	11/18/2013	764	12K PM - COMPLETED				SCHEDULED SERVICE
2018957	1	09/25/2020	786	12K MILE PM---COMPLETED				SCHEDULED SERVICE
2018957	1	09/25/2020	880	12K MILE PM---COMPLETED				SCHEDULED SERVICE
1314797	1	11/18/2013	764	12K PM - COMPLETED				SCHEDULED SERVICE
1411947	1	08/20/2014	764	12,000 MILE PM - COMPLETED P.M.				OPERATOR COMPLAINT
1604062	1	03/21/2016	820	12.000 MILE PM				OPERATOR COMPLAINT
2223716	1	08/02/2022	778	12K PM				SCHEDULED SERVICE
2114518	1	06/13/2021	871	12K MILE PM---COMPLETED----				SCHEDULED SERVICE
1814112	1	07/05/2018	841	12.000 MILE PM				SCHEDULED SERVICE
2001055	1	01/21/2020	800	12.000 MILE PM				OPERATOR COMPLAINT
1508321	1	06/04/2015	828	12K MILE PM				SCHEDULED SERVICE
1717579	1	09/29/2017	781	12,000 MILE PM- COMPLETE				SCHEDULED SERVICE

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: PB1301 to PB1301

BUS#	SYS Code	SYS Code Description				Total Line Count for System Code 9418 :	13	Cause-Reason
PB1301	9418	18,000 MILE PM						
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>				<u>Cause-Reason</u>
1509679	1	07/08/2015	631	a/c system pm				OPERATOR COMPLAINT
1605681	1	04/25/2016	809	18K MILE PM-COMPLETED				SCHEDULED SERVICE
1720113	1	11/07/2017	849	18K MILE PM---COMPLETED				SCHEDULED SERVICE
1316429	1	12/23/2013	819	18K PM - COMPLETE				SCHEDULED SERVICE
1701246	1	01/25/2017	781	18K MILE PM---COMPLETED				SCHEDULED SERVICE
1910738	1	06/11/2019	832	18.000 MILE PM				OPERATOR COMPLAINT
2021158	1	10/27/2020	837	18K MILE PM---COMPLETED				SCHEDULED SERVICE
1413485	1	09/19/2014	760	18,000 MILE PM - COMPLETED P.M.				SCHEDULED SERVICE
1400775	1	01/21/2014	814	24K MILE PM				SCHEDULED SERVICE
2118274	1	07/20/2021	762	18K MILE PM---COMPLETED				SCHEDULED SERVICE
1816746	1	08/06/2018	781	18.000 mile pm				SCHEDULED SERVICE
2002648	1	02/18/2020	828	18.000 MILE PM				OPERATOR COMPLAINT
2226971	1	09/08/2022	823	pm				SCHEDULED SERVICE

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: PB1301 to PB1301

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>				<u>Cause-Reason</u>
PB1301	9424	24,000 MILE PM	Total Line Count for System Code 9424 :			12
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>		
1722193	1	12/12/2017	849	24.000 MILE PM	OPERATOR COMPLAINT	
2004459	1	03/16/2020	828	24K MILE PM---COMPLETED	SCHEDULED SERVICE	
1415202	1	10/20/2014	820	24,000 MILE PM - COMPLETED PM SERVICE/INSPECTION	SCHEDULED SERVICE	
2231100	2	10/26/2022	778	24000 miles pm	SCHEDULED SERVICE	
1912904	1	07/15/2019	679	24.000 MILE PM	SCHEDULED SERVICE	
2024770	1	12/16/2020	841	24.000 MILE PM	SCHEDULED SERVICE	
1511073	1	08/06/2015	764	24,000 MILE PM - COMPLETED	SCHEDULED SERVICE	
1704308	1	03/15/2017	781	24K MILE PM---COMPLETED	SCHEDULED SERVICE	
1607566	1	05/31/2016	762	24K MILE PM-COMPLETED---	SCHEDULED SERVICE	
1819701	1	09/11/2018	841	24K MILE PM---COMPLETED	SCHEDULED SERVICE	
2121073	1	08/17/2021	841	24K MILE PM----COMPLETED	SCHEDULED SERVICE	
1402239	1	02/18/2014	764	24K MILE PM	SCHEDULED SERVICE	

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: PB1301 to PB1301

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>			<u>Total Line Count for System Code 9430 :</u>	<u>14</u>	<u>Cause-Reason</u>
PB1301	9430	30,000 MILE PM					
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>SCHEDULED SERVICE</u>		
1915019	1	08/20/2019	849	REPLCD RAILRAD DECALS	OPERATOR COMPLAINT		
1416992	1	11/20/2014	820	30,000 MILE PM - COMPLETED PM SERVICE/INSPECTION	SCHEDULED SERVICE		
1609490	1	07/05/2016	773	30.00 miel pm	SCHEDULED SERVICE		
1403816	1	03/21/2014	819	30K MILE PM	SCHEDULED SERVICE		
1822636	1	10/19/2018	837	30K MILE PM---COMPLETED	OPERATOR COMPLAINT		
1800959	1	01/22/2018	828	30.000 MILE PM	SCHEDULED SERVICE		
2302250	1	01/28/2023	823	30K PM DUE	SCHEDULED SERVICE		
1512533	1	09/08/2015	773	30K MILE PM - COMPLETED	SCHEDULED SERVICE		
2124040	1	09/14/2021	869	30 MILE PM---COMPLETED	SCHEDULED SERVICE		
2006427	1	04/14/2020	841	30K MILE PM---COMPLETED	SCHEDULED SERVICE		
1706410	1	04/18/2017	809	30.000 MILE PM	SCHEDULED SERVICE		
2204184	1	02/07/2022	871	30K PM	SCHEDULED SERVICE		
2204184	1	02/07/2022	828	30K PM	SCHEDULED SERVICE		
2100874	1	01/17/2021	809	30K MILE PM---COMPLETED	SCHEDULED SERVICE		

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: PB1301 to PB1301

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>				<u>Cause-Reason</u>
PB1301	9436	36,000 MILE PM	Total Line Count for System Code 9436 :			16
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>		
2305456	1	03/05/2023	778	36k pm	SCHEDULED SERVICE	
1611309	1	08/09/2016	820	36.000 MILE PM	SCHEDULED SERVICE	
1708516	1	05/18/2017	828	36K MILE PM----COMPLETED	SCHEDULED SERVICE	
1514753	1	10/23/2015	828	36K MILE PM-COMPLETED	SCHEDULED SERVICE	
2127251	1	10/15/2021	828	36K MILE PM---COMPLETED	SCHEDULED SERVICE	
1825167	1	11/21/2018	643	36K MILE PM----COMPLETED	SCHEDULED SERVICE	
1825167	1	11/21/2018	679	36K MILE PM----COMPLETED	SCHEDULED SERVICE	
1405378	1	04/22/2014	756	36K MILE PM-COMPLETE	SCHEDULED SERVICE	
1405378	1	04/22/2014	819	36K MILE PM-COMPLETE	SCHEDULED SERVICE	
1500016	1	01/05/2015	809	36.000 MILE PM - COMPLETED	SCHEDULED SERVICE	
1500016	1	01/05/2015	828	36.000 MILE PM - COMPLETED	SCHEDULED SERVICE	
2208045	1	03/13/2022	820	complete	SCHEDULED SERVICE	
2103029	1	03/03/2021	809	36K MILE PM---COMPLETED	SCHEDULED SERVICE	
1804075	1	03/05/2018	809	36K MILE PM---COMPLETED	SCHEDULED SERVICE	
1917148	1	09/18/2019	800	36K MILE PM---COMPLETED	SCHEDULED SERVICE	
2008248	1	05/11/2020	837	36.000 MILE PM	SCHEDULED SERVICE	

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: **PB1301** to **PB1301**

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>				<u>Cause-Reason</u>
PB1301	9442	42,000 MILE PM	Total Line Count for System Code 9442 :			13
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>		
1406883	1	05/19/2014	820	42K MILE PM-COMPLETED	SCHEDULED SERVICE	
2010594	1	06/12/2020	800	42.000 MIL E PM	SCHEDULED SERVICE	
1502783	1	02/18/2015	828	42,000 MILE PM - COMPLETED	SCHEDULED SERVICE	
1827559	1	12/28/2018	837	42K MILE PM---COMPLETED	SCHEDULED SERVICE	
1919184	1	10/21/2019	800	42K MILE PM---COMPLETED	SCHEDULED SERVICE	
1710659	1	06/20/2017	809	42K MILE PM---COMPLETED	SCHEDULED SERVICE	
1612957	1	09/13/2016	781	42.000 MILE PM	SCHEDULED SERVICE	
2106173	1	03/22/2021	836	42K MILE PM---COMPLETED	SCHEDULED SERVICE	
2132760	1	12/01/2021	839	42K PM	SCHEDULED SERVICE	
2308083	1	04/02/2023	809	pm	SCHEDULED SERVICE	
1516644	1	11/30/2015	828	42K MILE PM-COMPLETED	SCHEDULED SERVICE	
1806209	1	04/03/2018	828	42K MILE PM---COMPLETED	SCHEDULED SERVICE	
2211758	1	04/14/2022	833	42K PM	SCHEDULED SERVICE	

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: PB1301 to PB1301

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>			<u>Cause-Reason</u>
PB1301	9448	48K PM- TRAN OIL & ENG BREATHE	Total Line Count for System Code 9448 :		13
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	
2135785	1	01/06/2022	839	COMPLETE 48,000 MILE PM	SCHEDULED SERVICE
2013393	1	07/20/2020	837	48K PM--TRAN OIL & ENGINE BREATHE--COMPLETED	SCHEDULED SERVICE
1902347	1	02/08/2019	849	48K PM--TRAN OIL & ENGINE BREATHE	SCHEDULED SERVICE
1504820	1	03/24/2015	809	48K TRAN OIL/ENG BREATHE - COMPLETED	SCHEDULED SERVICE
1614591	1	10/18/2016	819	48K -TRAN OIL	SCHEDULED SERVICE
1600223	1	01/11/2016	820	48K TRAN OIL	SCHEDULED SERVICE
2215435	1	05/16/2022	839	48,000K PM DUE	SCHEDULED SERVICE
1921419	1	11/19/2019	869	48K PM--TRAN OIL & ENGINE BREATHE-	OPERATOR COMPLAINT
1808615	1	05/01/2018	809	48K PM TRAN OIL AND ENG BREATHE	OPERATOR COMPLAINT
1808615	1	05/01/2018	837	48K PM TRAN OIL AND ENG BREATHE	SCHEDULED SERVICE
2108590	1	04/18/2021	841	48K PM--TRAN OIL & ENGINE BREATHE	OPERATOR COMPLAINT
1712977	1	07/21/2017	828	48K TRAN OIL AND AND ENGINE BREATHE	SCHEDULED SERVICE
1408616	1	06/19/2014	796	48K PM-TRAN OIL & ENGINE BREATHE	

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: PB1301 to PB1301

BUS#	SYS Code	SYS Code Description			Total Line Count for System Code 9700 :	127	Cause-Reason
PB1301	9700	TEST RUN/ROAD TEST					
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>SCHEDULED SERVICE</u>		
2021158	24	10/27/2020	837	ROAD TEST	OPERATOR COMPLAINT		
2106295	3	03/25/2021	752	ROAD TEST -CODE WENT INACTIVE	OPERATOR COMPLAINT		
2021825	3	11/02/2020	839	ROAD TEST	OPERATOR COMPLAINT		
1511967	5	08/26/2015	822	ROAD TEST	OPERATOR COMPLAINT		
2305899	5	03/09/2023	809	ROAD TEST	OPERATOR COMPLAINT		
1827651	4	01/03/2019	822	ROA TEST	SCHEDULED SERVICE		
2204184	8	02/07/2022	828	road test, no problem found	OPERATOR COMPLAINT		
2018491	5	09/22/2020	823	ROAD TEST--NEEDS A SHOCK FOR BIKE RACK	OPERATOR COMPLAINT		
1826733	4	12/19/2018	789	ROAD TEST	OPERATOR COMPLAINT		
1907856	4	04/26/2019	836	ROAD TEST--NO CODES--E STROKE LIGHT STILLON	OPERATOR COMPLAINT		
1512935	9	09/16/2015	787	road test	OPERATOR COMPLAINT		
2018797	5	09/23/2020	795	ROAD TEST--AC WORKING--OK	OPERATOR COMPLAINT		
1408815	5	06/26/2014	799	road test	OPERATOR COMPLAINT		
2302059	5	01/28/2023	828	ROAD TEST	OPERATOR COMPLAINT		
2116500	8	07/11/2021	823	ROAD TEST	OPERATOR COMPLAINT		
1711950	10	07/11/2017	643	ROAD TEST	OPERATOR COMPLAINT		
1924219	5	12/30/2019	837	ROAD TEST--DRIVERS SEAT MOVES SIDE 2 SIDE	OPERATOR COMPLAINT		
2225708	3	08/25/2022	809	road test	OPERATOR COMPLAINT		

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: 1100 to 9700

Print Date: 3/25/2025

Asset# Range: PB1301 to PB1301

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>			<u>Total Line Count for System Code 9700 :</u>	<u>127</u>	<u>Cause-Reason</u>
PB1301	9700	TEST RUN/ROAD TEST					
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>			
2114518	11	06/13/2021	869	ROAD TEST	SCHEDULED SERVICE		
2100874	12	01/17/2021	832	ROAD TEST	SCHEDULED SERVICE		
1902659	4	02/08/2019	781	ROAD TEST AFTER CLEANING OUT FROM FRONT WHEEL BUS OKA	OPERATOR COMPLAINT		
1919184	9	10/21/2019	832	ROAD TEST--CKD, NO OIL LEAK	SCHEDULED SERVICE		
2226278	4	09/01/2022	778	road test ok	OPERATOR COMPLAINT		
2016958	7	09/02/2020	820	ROAD TEST--NO CODES	OPERATOR COMPLAINT		
2417561	5	07/24/2024	797	ROAD TEST	OPERATOR COMPLAINT		
1500337	4	01/09/2015	795	ROAD TEST-CEL AND REGEN LIGHT BACK ON-1921, 2639 ACTIVE	OPERATOR COMPLAINT		
1502436	3	02/11/2015	809	ROAD TEST	OPERATOR COMPLAINT		
2015728	5	08/14/2020	841	ROAD TEST BUS	OPERATOR COMPLAINT		
2416916	4	07/17/2024	914	Test drove. Bus shifts fine. No fuel light on.	OPERATOR COMPLAINT		
1822427	10	10/17/2018	797	ROAD TEST--OK	MECHANIC DEFECT		
2101626	5	01/26/2021	799	ROAD TEST	OPERATOR COMPLAINT		
1517893	2	12/29/2015	818	ROAD TEST	OPERATOR COMPLAINT		
1903794	3	02/26/2019	796	ROAD TESTED--OK	OPERATOR COMPLAINT		
1508644	4	06/11/2015	828	ROAD TEST-OK	OPERATOR COMPLAINT		
1719576	2	11/02/2017	756	ROAD TEST	OPERATOR COMPLAINT		
2125401	6	09/26/2021	832	ROAD TEST	OPERATOR COMPLAINT		

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: **PB1301** to **PB1301**

BUS#	SYS Code	SYS Code Description			Total Line Count for System Code 9700 :	127	Cause-Reason
PB1301	9700	TEST RUN/ROAD TEST					
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>			
2122378	5	08/29/2021	837	ROAD TEST			OPERATOR COMPLAINT
2017713	8	09/10/2020	869	ROAD TEST -REGEN LIGHT			OPERATOR COMPLAINT
2017713	8	09/10/2020	778	ROAD TEST -REGEN LIGHT			OPERATOR COMPLAINT
1710659	9	06/20/2017	841	ROAD TEST			SCHEDULED SERVICE
1917708	3	09/26/2019	643	ROAD TEST--OK			OPERATOR COMPLAINT
2001055	5	01/21/2020	781	road test			SCHEDULED SERVICE
1901012	12	01/21/2019	823	ROAD TEST			OPERATOR COMPLAINT
1509861	4	07/10/2015	751	ROAD TEST			OPERATOR COMPLAINT
1718433	7	10/16/2017	825	ROAD TEST			OPERATOR COMPLAINT
1815816	3	07/30/2018	828	ROAD TESTED---ISSUE CORRECTED			OPERATOR COMPLAINT
1804391	2	03/07/2018	809	ROAD TEST -TO VERIFU COMPLAINT -NO PROBLEM FOUND AT THIS TIME			OPERATOR COMPLAINT
1813355	3	06/25/2018	781	ROAD TEST--NPF			OPERATOR COMPLAINT
1900292	3	01/10/2019	837	ROAD TEST			OPERATOR COMPLAINT
1905760	7	04/17/2019	837	ROAD TEST			OPERATOR COMPLAINT
2222897	5	07/23/2022	839	TEST RUN/ ROAD TEST			OPERATOR COMPLAINT
1712596	3	07/17/2017	781	road test			OPERATOR COMPLAINT
2124040	7	09/14/2021	874	ROAD TEST--TSHOOT LOW AIR ALARM WHEN BRAKING--NO ISSUES			SCHEDULED SERVICE
2302250	11	01/28/2023	823	ROAD TEST			SCHEDULED SERVICE

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: **PB1301** to **PB1301**

BUS#	SYS Code	SYS Code Description			Total Line Count for System Code 9700 :	127	Cause-Reason
PB1301	9700	TEST RUN/ROAD TEST					
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>			
2302250	11	01/28/2023	828	ROAD TEST			SCHEDULED SERVICE
2302250	7	01/28/2023	820	CLEARED INACTIVE CODES			SCHEDULED SERVICE
1510853	3	08/04/2015	648	ROAD TEST			OPERATOR COMPLAINT
2105414	4	03/15/2021	795	ROAD TEST---WORKING OK			OPERATOR COMPLAINT
2018644	4	09/21/2020	787	ROAD TEST			OPERATOR COMPLAINT
1711915	3	07/06/2017	781	ROAD TESTED--OK			SCHEDULED SERVICE
2208045	14	03/13/2022	820	unadaptive shift parameters , fast adaptive , cleared inactive codes, road test smooths shift, oil level ok, no lea			SCHEDULED SERVICE
2208045	18	03/13/2022	874	road test, codes inactive did not returned at this time			OPERATOR COMPLAINT
2104540	3	03/02/2021	778	ROAD TESTED--CK FOR LEAKS-NONE			SCHEDULED SERVICE
2127251	7	10/15/2021	869	ROAD TEST			OPERATOR COMPLAINT
2213179	4	04/25/2022	786	ROAD TEST			OPERATOR COMPLAINT
2232215	5	11/08/2022	778	road test			OPERATOR COMPLAINT
2133816	4	12/09/2021	833	ROAD TEST			SCHEDULED SERVICE
2016013	10	08/19/2020	809	ROAD TEST			OPERATOR COMPLAINT
2233965	4	01/19/2023	820	reset all parameters, road test and all ok			OPERATOR COMPLAINT
2233965	4	01/19/2023	832	reset all parameters, road test and all ok			SCHEDULED SERVICE
1912904	5	07/15/2019	799	ROAD TEST			OPERATOR COMPLAINT
2018029	6	09/14/2020	822	ROAD TEST			

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: PB1301 to PB1301

BUS#	SYS Code	SYS Code Description			Total Line Count for System Code 9700 :	127	Cause-Reason
PB1301	9700	TEST RUN/ROAD TEST					
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>			
1903794	8	02/26/2019	822	ROAD TEST	OPERATOR COMPLAINT		
2112218	2	05/24/2021	874	Road Test - no lights while hitting bumps.	OPERATOR COMPLAINT		
2018957	6	09/25/2020	798	ROAD TEST--OK---AC BLOWS COLD	SCHEDULED SERVICE		
1919511	4	10/21/2019	762	ROAD TESTED---W/CHAIR RAMP OK	OPERATOR COMPLAINT		
1904084	5	03/04/2019	779	ROAD TEST	OPERATOR COMPLAINT		
2018222	8	09/17/2020	648	ROAD TEST	OPERATOR COMPLAINT		
1820571	3	09/20/2018	746	ROAD TEST	OPERATOR COMPLAINT		
1907856	6	04/26/2019	836	ROAD TEST---COMPLETED	OPERATOR COMPLAINT		
2419520	8	08/15/2024	832	road test	OPERATOR COMPLAINT		
2422317	6	09/15/2024	648	Test Drive	OPERATOR COMPLAINT		
2422317	6	09/15/2024	925	Test Drive	OPERATOR COMPLAINT		
2302059	7	01/28/2023	820	ROAD TEST	OPERATOR COMPLAINT		
2302059	7	01/28/2023	833	ROAD TEST	OPERATOR COMPLAINT		
2018136	7	09/15/2020	796	plugged back in & road test	OPERATOR COMPLAINT		
1500696	3	01/22/2015	731	ROAD TEST-LIGHT IS ON, ALARM ON 1921A	OPERATOR COMPLAINT		
1503799	2	03/05/2015	819	ROAD TEST IN PARKING LOT, STOP AND GO - COULD NOT DUPLICATE	OPERATOR COMPLAINT		
2110158	3	05/01/2021	874	ROAD TEST	OPERATOR COMPLAINT		
2020663	4	10/27/2020	837	ROAD TEST	OPERATOR COMPLAINT		

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: **PB1301** to **PB1301**

BUS#	SYS Code	SYS Code Description			Total Line Count for System Code 9700 :	127	Cause-Reason
PB1301	9700	TEST RUN/ROAD TEST					
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>			
1901756	4	01/28/2019	796	ROAD TESTED			OPERATOR COMPLAINT
2012150	4	06/30/2020	800	ROAD TEST			OPERATOR COMPLAINT
1617099	3	12/06/2016	825	ROAD TEST			OPERATOR COMPLAINT
1825114	2	11/21/2018	838	ROAD TEST--NEED TO CK WITH ALLISON ABOUT WARRANTY---WIP...			OPERATOR COMPLAINT
2022384	12	11/22/2020	869	ROAD TEST---CLEAR LIGHT			OPERATOR COMPLAINT
2022384	12	11/22/2020	880	ROAD TEST---CLEAR LIGHT			OPERATOR COMPLAINT
2416122	5	07/10/2024	823	ROAD TEST			OPERATOR COMPLAINT
1824617	5	11/15/2018	809	ROAD TEST			OPERATOR COMPLAINT
1719867	5	11/03/2017	822	ROAD TEST			OPERATOR COMPLAINT
2012856	3	07/08/2020	841	ROAD TEST BUS			OPERATOR COMPLAINT
1516644	10	11/30/2015	809	ROAD TEST			SCHEDULED SERVICE
1516991	5	12/07/2015	809	ROAD TEST			OPERATOR COMPLAINT
1417625	3	12/02/2014	752	ROAD TEST			OPERATOR COMPLAINT
1722364	2	12/12/2017	818	ROAD TEST , COULD NOT DUPLICATE PROBLEM			OPERATOR COMPLAINT
2017713	11	09/10/2020	648	ROAD TEST			OPERATOR COMPLAINT
2226703	4	09/05/2022	833	ROAD TEST			OPERATOR COMPLAINT
1513621	3	10/02/2015	778	road tested			OPERATOR COMPLAINT
2021881	5	11/04/2020	778	ROD TEST -OK			OPERATOR COMPLAINT

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: 1100 to 9700

Print Date: 3/25/2025

Asset# Range: PB1301 to PB1301

BUS#	SYS Code	SYS Code Description			Total Line Count for System Code 9700 :	127	Cause-Reason
PB1301	9700	TEST RUN/ROAD TEST					
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>SCHEDULED SERVICE</u>		
2118274	10	07/20/2021	869	ROAD TEST	SCHEDULED SERVICE		
1817291	4	08/14/2018	752	ROAD TEST	OPERATOR COMPLAINT		
2018136	4	09/15/2020	796	ROAD TEST---NO KNOCKING	OPERATOR COMPLAINT		
2216681	3	05/26/2022	820	ROAD TEST BUS NO CODES.	OPERATOR COMPLAINT		
1500381	4	01/14/2015	751	ROAD TEST -CODE 4163 ACTIVE	OPERATOR COMPLAINT		
2303813	5	02/14/2023	778	ROAD TEST	OPERATOR COMPLAINT		
2012856	5	07/08/2020	841	ROAD TEST	OPERATOR COMPLAINT		
1815481	4	07/19/2018	787	ROAD TEST	OPERATOR COMPLAINT		
1617333	3	12/13/2016	819	ROAD TEST	OPERATOR COMPLAINT		
1617140	5	12/07/2016	789	ROAD TEST	OPERATOR COMPLAINT		
1506459	4	04/23/2015	789	ROAD TEST	OPERATOR COMPLAINT		
2108590	11	04/18/2021	869	ROAD TEST BUS FOR BRAKES--NO PULLING--BRAKE PEDAL OK	SCHEDULED SERVICE		
2108590	11	04/18/2021	849	ROAD TEST BUS FOR BRAKES--NO PULLING--BRAKE PEDAL OK	SCHEDULED SERVICE		
2002648	9	02/18/2020	837	ROAD TEST	SCHEDULED SERVICE		
2121073	5	08/17/2021	869	ROAD TEST	SCHEDULED SERVICE		
1904084	3	03/04/2019	795	ROAD TEST--NO LIGHTS/CODES	OPERATOR COMPLAINT		
1808217	5	04/24/2018	809	ROAD TEST--CLEAR INACTIVE CODES	OPERATOR COMPLAINT		
1820990	2	09/26/2018	824	ROAD TEST---NO CODES	OPERATOR COMPLAINT		

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 08/14/2013 to 11/12/2024

System Code Range: **1100** to **9700**

Print Date: 3/25/2025

Asset# Range: **PB1301** to **PB1301**

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>			<u>Cause-Reason</u>
PB1301	9700	TEST RUN/ROAD TEST	Total Line Count for System Code 9700 :		127
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	SCHEDULED SERVICE
1822636	11	10/19/2018	752	ROAD TEST	