

**Report Description: Work Order History by Asset and System Code**

WO Close Date Range: 08/23/2019 to 02/04/2025

System Code Range: 1100 to 9700

Print Date: 5/21/2025

**Asset# Range:** PT1911 to PT1911

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>			<u>Cause-Reason</u>
<b>PT1911</b>	<b>1100</b>	<b>INTERIOR CLEAN</b>	<b>Total Line Count for System Code 1100 :</b>		<b>6</b>
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
1915587	1	08/23/2019	668	INTERIOR CLEAN	SCHEDULED SERVICE
1916327	1	09/08/2019	865	INTEROR CLEAN	OPERATOR COMPLAINT
1916276	1	09/11/2019	826	INTERIOR CLEAN--COMPLETED	SCHEDULED SERVICE
2016263	1	08/25/2020	812	INTERIOR CLEAN---COMPLETED	SCHEDULED SERVICE
2017464	1	09/04/2020	877	INTERIOR CLEAN---COMPLETED	SCHEDULED SERVICE
2019992	1	10/08/2020	815	INTERIOR CLEAN	SCHEDULED SERVICE
<b>PT1911</b>	<b>1301</b>	<b>TROUBLESHOOT AC SYSTEM</b>	<b>Total Line Count for System Code 1301 :</b>		<b>2</b>
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
2403653	1	02/23/2024	823	low freon, no leaks found at this time	OPERATOR COMPLAINT
2404421	2	03/02/2024	823	needs compressor dryer & ex valve	OPERATOR COMPLAINT
<b>PT1911</b>	<b>1303</b>	<b>AC COMPRESSOR REPL</b>	<b>Total Line Count for System Code 1303 :</b>		<b>2</b>
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
2404421	3	03/02/2024	823	R&R a/c compressor	OPERATOR COMPLAINT
2404421	4	03/02/2024	823	R&R exp. valve and dryer	OPERATOR COMPLAINT
<b>PT1911</b>	<b>1318</b>	<b>A/C SYSTEM RE-CHARGE</b>	<b>Total Line Count for System Code 1318 :</b>		<b>1</b>
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
2403653	2	02/23/2024	823	recharge a/c	OPERATOR COMPLAINT
<b>PT1911</b>	<b>1400</b>	<b>ELECTRICAL SYSTEM</b>	<b>Total Line Count for System Code 1400 :</b>		<b>2</b>
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
2410665	1	05/21/2024	823	t/s electrical	OPERATOR COMPLAINT
2232459	4	11/17/2022	797	ck diagnostic connector and reconnected back	OPERATOR COMPLAINT
<b>PT1911</b>	<b>1401</b>	<b>TROUBLESHOOT ELECTRICAL S</b>	<b>Total Line Count for System Code 1401 :</b>		<b>1</b>
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>
2101293	1	01/24/2021	799	TROUBLESHOOT ELECTRICALS--LOW BATT	OPERATOR COMPLAINT

**Report Description: Work Order History by Asset and System Code**

WO Close Date Range: 08/23/2019 to 02/04/2025

System Code Range: 1100 to 9700

Print Date: 5/21/2025

**Asset# Range:** PT1911 to PT1911

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>			<u>Cause-Reason</u>
<b>PT1911</b>	<b>1406</b>	<b>STARTER MOTOR REPL</b>	<b>Total Line Count for System Code 1406 :</b>		<b>1</b>
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	OPERATOR COMPLAINT
2430835	3	02/04/2025	911	remove starter	
<b>PT1911</b>	<b>1407</b>	<b>BATTERIES CHECK</b>	<b>Total Line Count for System Code 1407 :</b>		<b>1</b>
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	OPERATOR COMPLAINT
2101293	3	01/24/2021	753	CHECK C HARGE SYSTEM---OK	
<b>PT1911</b>	<b>1408</b>	<b>BATTERIES REPLACE</b>	<b>Total Line Count for System Code 1408 :</b>		<b>3</b>
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	NORMAL WEAR
2101293	2	01/24/2021	753	R/R BATTERY	
2232459	3	11/17/2022	797	replaced bad battery	OPERATOR COMPLAINT
2325716	3	10/24/2023	823	r/r battery	OPERATOR COMPLAINT
<b>PT1911</b>	<b>1409</b>	<b>EXTERIOR LIGHTING</b>	<b>Total Line Count for System Code 1409 :</b>		<b>1</b>
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	OPERATOR COMPLAINT
2309532	1	04/22/2023	797	r/r signal bulb	
<b>PT1911</b>	<b>1418</b>	<b>INSTRUMENTS &amp; GAUGES</b>	<b>Total Line Count for System Code 1418 :</b>		<b>1</b>
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	OPERATOR COMPLAINT
2425336	1	10/23/2024	849	chk fuel gauge	
<b>PT1911</b>	<b>2200</b>	<b>STEERING SYSTEMS</b>	<b>Total Line Count for System Code 2200 :</b>		<b>1</b>
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	OPERATOR COMPLAINT
2425336	9	10/23/2024	833	remove left lower control arm	
<b>PT1911</b>	<b>2201</b>	<b>TROUBLESHOOT STEERING SYS</b>	<b>Total Line Count for System Code 2201 :</b>		<b>1</b>
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	OPERATOR COMPLAINT
2111111	1	05/15/2021	833	TROUBLESHOOT STEERING SYSTEM--ROAD TEST--UNDERDASH TRIM RUBBING AGAINST STEERIN	
<b>PT1911</b>	<b>2300</b>	<b>SUSPENSION SYSTEM</b>	<b>Total Line Count for System Code 2300 :</b>		<b>1</b>
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	OPERATOR COMPLAINT
2425336	10	10/23/2024	833	install left & right control arms	

**Report Description: Work Order History by Asset and System Code**

WO Close Date Range: 08/23/2019 to 02/04/2025      System Code Range: **1100** to **9700**

Print Date: 5/21/2025

**Asset# Range: PT1911 to PT1911**

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>				<u>Cause-Reason</u>
<b>PT1911</b>	<b>2500</b>	<b>BODY</b>	<b>Total Line Count for System Code 2500 :</b>			<b>7</b>
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>		<u>Cause-Reason</u>
2425336	13	10/23/2024	833	removed cowl to reseal moulding causing noise		OPERATOR COMPLAINT
2111111	2	05/15/2021	833	SECURE TRIM UNDERDASH		OPERATOR COMPLAINT
2001401	1	03/30/2020	864	BODY		OPERATOR COMPLAINT
2001401	2	03/30/2020	864	REPLCD LEFT SIDE ROOF RACK		OPERATOR COMPLAINT
2232459	5	11/17/2022	797	wash and fuel car		SCHEDULED SERVICE
2230380	3	10/19/2022	797	R/R CABIN FILTER		SCHEDULED SERVICE
2402907	2	02/06/2024	823	wip[ers		SCHEDULED SERVICE
<b>PT1911</b>	<b>2505</b>	<b>WIPERS</b>	<b>Total Line Count for System Code 2505 :</b>			<b>7</b>
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>		<u>Cause-Reason</u>
2006020	1	04/07/2020	864	WIPERS===REPLCD WIPER BLADES & WIPER ARM		OPERATOR COMPLAINT
2100444	1	01/11/2021	783	WIPERS---R/R		OPERATOR COMPLAINT
2005736	2	04/01/2020	864	REPLCD REAR WIPER BLADES		SCHEDULED SERVICE
1924037	3	12/27/2019	866	INSTALL NEW WIPER ARM ASSY		NORMAL WEAR
2131836	1	12/01/2021	833	INSTALL WIPER ARMS--DRIVER SIDE PASSENGER		OPERATOR COMPLAINT
2200075	3	01/11/2022	839	replaced rear wiper arm		OPERATOR COMPLAINT
1924037	2	12/27/2019	866	REPAR WIPER ARM MISSING---POO---WIP		SCHEDULED SERVICE
<b>PT1911</b>	<b>2510</b>	<b>MIRRORS</b>	<b>Total Line Count for System Code 2510 :</b>			<b>1</b>
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>		<u>Cause-Reason</u>
2100444	2	01/11/2021	783	MIRROS--DRIVER SIDE		OPERATOR COMPLAINT
<b>PT1911</b>	<b>2600</b>	<b>BRAKES</b>	<b>Total Line Count for System Code 2600 :</b>			<b>1</b>
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>		<u>Cause-Reason</u>
2425336	8	10/23/2024	833	r/r rear pads		OPERATOR COMPLAINT

**Report Description: Work Order History by Asset and System Code**

WO Close Date Range: 08/23/2019 to 02/04/2025

System Code Range: 1100 to 9700

Print Date: 5/21/2025

**Asset# Range:** PT1911 to PT1911

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>			<u>Cause-Reason</u>
<b>PT1911</b>	<b>2601</b>	<b>TROUBLESHOOT BRAKES</b>	<b>Total Line Count for System Code 2601 :</b>		<b>1</b>
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>OPERATOR COMPLAINT</u>
2425336	7	10/23/2024	833	r/r front brakes	
<b>PT1911</b>	<b>2800</b>	<b>ENGINE</b>	<b>Total Line Count for System Code 2800 :</b>		<b>11</b>
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>OPERATOR COMPLAINT</u>
2425336	5	10/23/2024	833	remove fuel fill tube	
2425336	6	10/23/2024	833	replaced fuel fill tube	
2421900	2	09/11/2024	833	Random missfire cylinder number 6	
2421900	3	09/11/2024	833	replace spark plugs.	
2421900	4	09/11/2024	833	Perform compression test.	
2421900	5	09/11/2024	833	R/R injectors #4,5,6 and coil packs	
2430835	4	02/04/2025	809	install starter	
2430835	5	02/04/2025	809	found engine locked up	
2404421	1	03/02/2024	823	rest oil life	
2410665	2	05/21/2024	823	r/r fuel pump	
2405531	2	03/19/2024	823	R/R evap solenoid.	
<b>PT1911</b>	<b>2801</b>	<b>TROUBLESHOOT ENGINE</b>	<b>Total Line Count for System Code 2801 :</b>		<b>2</b>
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>OPERATOR COMPLAINT</u>
2405531	1	03/19/2024	823	Needs evap solenoid	
2421900	1	09/11/2024	833	Engine missfire	
<b>PT1911</b>	<b>2810</b>	<b>AIR FILTER REPL</b>	<b>Total Line Count for System Code 2810 :</b>		<b>1</b>
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>SCHEDULED SERVICE</u>
2230380	2	10/19/2022	797	R/R ENGINE FILTER	

**Report Description: Work Order History by Asset and System Code**

WO Close Date Range: 08/23/2019 to 02/04/2025

System Code Range: 1100 to 9700

Print Date: 5/21/2025

**Asset# Range:** PT1911 to PT1911

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>				<u>Cause-Reason</u>
<b>PT1911</b>	<b>2821</b>	<b>FUEL PUMPS REPL</b>	<b>Total Line Count for System Code 2821 :</b>			<b>3</b>
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>	
2425336	2	10/23/2024	849	removed fuel tank	OPERATOR COMPLAINT	
2425336	3	10/23/2024	849	drained and reset fuel tank float	OPERATOR COMPLAINT	
2425336	4	10/23/2024	849	reinstall fuel pump,	OPERATOR COMPLAINT	
<b>PT1911</b>	<b>2828</b>	<b>MOTOR WASH ENGINE</b>	<b>Total Line Count for System Code 2828 :</b>			<b>1</b>
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>	
2015106	2	08/06/2020	783	WASH ENGINE--CLEAN/WASH INTERIOR	SCHEDULED SERVICE	
<b>PT1911</b>	<b>2829</b>	<b>FUEL LEAK</b>	<b>Total Line Count for System Code 2829 :</b>			<b>1</b>
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>	
2411579	1	06/05/2024	823	LEAK WAS REPAIR	OPERATOR COMPLAINT	
<b>PT1911</b>	<b>2900</b>	<b>TRANSMISSION</b>	<b>Total Line Count for System Code 2900 :</b>			<b>1</b>
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>	
2425336	11	10/23/2024	809	r/r trans mount	OPERATOR COMPLAINT	
<b>PT1911</b>	<b>4000</b>	<b>TIRES</b>	<b>Total Line Count for System Code 4000 :</b>			<b>3</b>
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>	
2312644	1	05/29/2023	823	replace rt rear tire	OPERATOR COMPLAINT	
2309815	2	06/08/2023	849	Rotate tire	SCHEDULED SERVICE	
2007918	1	05/08/2020	746	TIRES	OPERATOR COMPLAINT	
<b>PT1911</b>	<b>4012</b>	<b>R/F TIRE REPLACEMENT</b>	<b>Total Line Count for System Code 4012 :</b>			<b>2</b>
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>	
2007918	2	05/08/2020	746	RR RF TIRE	OPERATOR COMPLAINT	
2200075	1	01/11/2022	823	repair front right tire	OPERATOR COMPLAINT	
<b>PT1911</b>	<b>4013</b>	<b>L/R/O TIRE REPLACEMENT</b>	<b>Total Line Count for System Code 4013 :</b>			<b>1</b>
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>	
2423559	1	09/25/2024	823	R/R rear left tire flat	OPERATOR COMPLAINT	
<b>PT1911</b>	<b>5000</b>	<b>COMMUNICATIONS</b>	<b>Total Line Count for System Code 5000 :</b>			<b>1</b>
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>Cause-Reason</u>	
2102671	1	02/08/2021	822	COMMUNICATIONS---INSTALL GPS	SCHEDULED SERVICE	

**Report Description: Work Order History by Asset and System Code**

WO Close Date Range: 08/23/2019 to 02/04/2025

System Code Range: 1100 to 9700

Print Date: 5/21/2025

**Asset# Range:** PT1911 to PT1911

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>			<u>Cause-Reason</u>
<b>PT1911</b>	<b>5004</b>	<b>AVL -- Repairs</b>	<b>Total Line Count for System Code 5004 :</b>		<b>1</b>
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>SCHEDULED SERVICE</u>
2103952	1	02/24/2021	27	AVL---REPAIRES---PCO	
<b>PT1911</b>	<b>8010</b>	<b>TRAVEL TIME - Road Call</b>	<b>Total Line Count for System Code 8010 :</b>		<b>3</b>
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>MAJOR MECHANICAL BREAKDOWN</u>
2325716	1	10/24/2023	823	travel	
2232459	1	11/17/2022	820	travel time	<u>MAJOR MECHANICAL BREAKDOWN</u>
2430835	1	02/04/2025	823	tow	<u>OTHER MECHANICAL BREAKDOWN</u>
<b>PT1911</b>	<b>8011</b>	<b>TROUBLESHOOT ROAD CALL</b>	<b>Total Line Count for System Code 8011 :</b>		<b>3</b>
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>OPERATOR COMPLAINT</u>
2430835	2	02/04/2025	911	bad starter	
2232459	2	11/17/2022	820	ck chargin system all ok, bad battery	<u>OPERATOR COMPLAINT</u>
2325716	2	10/24/2023	823	t/s	<u>OPERATOR COMPLAINT</u>
<b>PT1911</b>	<b>9103</b>	<b>4,000 MILE PM CARS</b>	<b>Total Line Count for System Code 9103 :</b>		<b>3</b>
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>SCHEDULED SERVICE</u>
2309815	1	06/08/2023	849	PM complete 4K PM	
1924037	1	12/27/2019	866	4K MILE PM CARS---COMPLETED	<u>SCHEDULED SERVICE</u>
2130510	1	12/09/2021	833	4k pmi completed	<u>OPERATOR COMPLAINT</u>
<b>PT1911</b>	<b>9108</b>	<b>8,000 MILE PM CARS</b>	<b>Total Line Count for System Code 9108 :</b>		<b>3</b>
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>SCHEDULED SERVICE</u>
2214134	1	05/04/2022	778	8,000K PM DUE	
2005736	1	04/01/2020	864	8K MILE PM CARS ----COMPLETED	<u>SCHEDULED SERVICE</u>
2402907	1	02/06/2024	823	8k pm	<u>SCHEDULED SERVICE</u>

**Report Description: Work Order History by Asset and System Code**

WO Close Date Range: 08/23/2019 to 02/04/2025

System Code Range: 1100 to 9700

Print Date: 5/21/2025

**Asset# Range:** PT1911 to PT1911

<u>BUS#</u>	<u>SYS Code</u>	<u>SYS Code Description</u>			<u>Cause-Reason</u>
<b>PT1911</b>	<b>9112</b>	<b>12,000 MILE PM CARS</b>	<b>Total Line Count for System Code 9112 :</b>		<b>3</b>
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>SCHEDULED SERVICE</u>
2414756	1	06/26/2024	823	12000 miles pm	SCHEDULED SERVICE
2230380	1	10/19/2022	797	12K PM DUE	SCHEDULED SERVICE
2015106	1	08/06/2020	783	12K MILE PM CARS--COMPLETED	SCHEDULED SERVICE
<b>PT1911</b>	<b>9116</b>	<b>16,000 MILE PM CARS</b>	<b>Total Line Count for System Code 9116 :</b>		<b>3</b>
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>SCHEDULED SERVICE</u>
2020565	1	10/16/2020	833	18.000 MILE PM CARS	SCHEDULED SERVICE
2301015	1	01/14/2023	823	16K PMDUE	SCHEDULED SERVICE
2427383	1	11/07/2024	833	16K Car PM	SCHEDULED SERVICE
<b>PT1911</b>	<b>9120</b>	<b>20,000 MILE PM CARS</b>	<b>Total Line Count for System Code 9120 :</b>		<b>1</b>
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>SCHEDULED SERVICE</u>
2101471	1	01/24/2021	822	20K MILE PM CARS---COMPLETED	SCHEDULED SERVICE
<b>PT1911</b>	<b>9124</b>	<b>24,000 MILE PM CARS</b>	<b>Total Line Count for System Code 9124 :</b>		<b>2</b>
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>	<u>SCHEDULED SERVICE</u>
2116610	1	07/05/2021	828	24K MILE PM CARS---COMPLETED	SCHEDULED SERVICE
2306241	1	03/13/2023	823	24K PM	SCHEDULED SERVICE

**Report Description: Work Order History by Asset and System Code**

WO Close Date Range: 08/23/2019 to 02/04/2025

System Code Range: **1100** to **9700**

Print Date: 5/21/2025

**Asset# Range:** **PT1911** to **PT1911**

<b>BUS#</b>	<b>SYS Code</b>	<b>SYS Code Description</b>			<b>Total Line Count for System Code 9700 :</b>	<b>8</b>	<b>Cause-Reason</b>
<b>PT1911</b>	<b>9700</b>	<b>TEST RUN/ROAD TEST</b>					
<u>Work Order #</u>	<u>Line#</u>	<u>Close Date</u>	<u>Employee#</u>	<u>Description of Work</u>			<u>OPERATOR COMPLAINT</u>
2312644	2	05/29/2023	823	test drive			OPERATOR COMPLAINT
2405531	3	03/19/2024	823	Ready to go back in service.			OPERATOR COMPLAINT
2410665	3	05/21/2024	823	test drive			OPERATOR COMPLAINT
2403653	3	02/23/2024	823	road test			OPERATOR COMPLAINT
2404421	5	03/02/2024	823	road test			OPERATOR COMPLAINT
2200075	2	01/11/2022	823	run/test drive. ordered bracket and blade for rear glass			OPERATOR COMPLAINT
2423559	2	09/25/2024	823	Road test, vehicle is good.			OPERATOR COMPLAINT
2425336	12	10/23/2024	809	road test			OPERATOR COMPLAINT