Asset: 10172265 2008 TORO WORKMAN E2065 Utility Cart, Electric, W/Dump Bed

Vorkorder: 745125	Problem:	Problem: PRE-DELIVERY INSPECTION				
Meter Reading: 0			Labor		Parts	
In Date: 10/04/2007	Close Date: 10/04/	2007	Hours Description			Quantity
- Pre-Delivery Inspection			2.00			
	Parts Charge:	0.00	Labor Charge:	120.00		
Vorkorder: 835700	Problem:	FRONT	SUSPENSION			
Meter Reading: 0			Labor		Parts	
In Date: 03/18/2008	Close Date: 03/20/	2008	Hours Description			Quantity
Adj Ride HeightTest RunTest Run			2.50 SHO	P SUPPLIES		1.00
- Shop Supplies	Parts Charge:	2.00	Labor Charge:	30.00		
Norkorder: 844397	Problem:	PM SER	VICE			
Meter Reading: 51			Labor		Parts	
In Date: 09/18/2008	Close Date: 09/22/	2008	Hours	Description		Quantity
Pm ServiceRoad TestShop Supplies			4.50 SHO	P SUPPLIES		1.00
	Parts Charge:	2.00	Labor Charge:	30.00		
Norkorder: 847797	Problem:	ORDER	6 KEYS FOR NORTH F	ACILITIES-ROD		
Norkorder: 847797 Meter Reading: 51	Problem:	ORDER	6 KEYS FOR NORTH F. Labor	ACILITIES-ROD	Parts	
	Problem: Close Date: 12/30/			ACILITIES-ROD Description	Parts	Quantity
Meter Reading: 51	Close Date: 12/30/		Labor Hours		Parts	Quantity 6.00

Asset: 10172265 2008 TORO WORKMAN E2065 Utility Cart, Electric, W/Dump Bed

Workorder: 932948 Problem: CHARGER READS FAULT WHEN PLUGGED IN.

Meter Reading: 71 Labor Parts

In Date: 01/20/2009 Close Date: 02/09/2009 Hours Description Quantity
- Charge Batteries And Hydrometer Ck All Read 2.00 SHOP SUPPLIES 1.00

Normal-Charger Working Normal

- Shop Supplies

Parts Charge: 2.00 Labor Charge: 120.00

Workorder: 943410 Problem: PM SERVICE

Meter Reading: 71 Labor Parts

 In Date: 09/18/2009
 Close Date: 09/23/2009
 Hours
 Description
 Quantity

 - Pm Service
 5.00
 SHOP SUPPLIES
 1.00

- Wash

- Shop Supplies

Parts Charge: 2.00 Labor Charge: 300.00

Workorder: 1011226 Problem: PM / INSTALL REARVIEW MIRROR

Close Date: 10/21/2010

Meter Reading: 128 Labor Parts

Hours

 - Pm
 6.50
 1401 BRAKE FLUID BRAKE FLUID
 1.00

 - Wash
 REAR VIEW MIRROR ASSY - 5 - PANEL
 1.00

 - Order And Install Rear View Mirror
 SHOP SUPPLIES
 1.00

Description

New Front Decals

In Date: 10/12/2010

Shop Supplies

Parts Charge: 45.52 Labor Charge: 390.00

Workorder: 1110986 Problem: pm service

Meter Reading: 166 Labor Parts
In Date: 10/14/2011 Close Date: 10/24/2011 Hours Description Quantity

- Pm 4.00 SHOP SUPPLIES 1.00

- Shop Supplies

Parts Charge: 2.00 Labor Charge: 240.00

Quantity

Asset: 10172265 2008 TORO WORKMAN E2065 Utility Cart, Electric, W/Dump Bed

					The second se	
Vorkorder: 1212047	Proble	em: PM / Cart	won't charge			
Meter Reading: 196			Labor		Parts	
In Date: 12/13/2012	Close Date: 12	/20/2012	Hours	Description		Quantity
- Pm			6.00 050)88 BRAKE CLEAN		1.00
- Rear Differential Service	Fix Diff. Cover		821	194 GRAY SILICONE P		1.00
 Shop Supplies 			123	345841 GEAR OIL SYN		1.00
			SH	OP SUPPLIES		1.00
	Parts Charge:	33.89	Labor Charge:	360.00		
Workorder: 1302084	Proble	em: Battery no	ot holding charge			
Meter Reading: 202		Labor		Parts		
In Date: 02/28/2013	Close Date: 03	/14/2013	Hours	Description		Quantity
- R/R Batteries			4.00 SH	OP SUPPLIES		1.00
- Shop Supplies	BATTERY					8.00
	Parts Charge:	1,151.24	Labor Charge:	240.00		
Norkorder: 1312550	Proble	em: pm servic	۵			
Meter Reading: 214	110016	eni. pin ocivio	Labor		Parts	
In Date: 12/17/2013 Close Date: 12/20/2013		/20/2013	Hours Description		raits	Quantity
- Pm Service	Ologe Date. 12	120/2013		•		
- Wash Cart			5.00 SH	OP SUPPLIES		1.00
- Shop Supplies						
- Onlop Supplies	Parts Charge:	2.00	Labor Charge:	300.00		
	raits Cliarge.	2.00	Labor Charge.	300.00		
Norkorder: 1409955	Proble	em: pm servic	e			
Meter Reading: 214		-	Labor		Parts	
In Date: 10/02/2014	Close Date:		Hours	Description		Quantity
-				<u> </u>		
	Parts Charge:	0.00	Labor Charge:	0.00		

Asset: 10172265 2008 TORO WORKMAN E2065 Utility Cart, Electric, W/Dump Bed

Workorder: 1500734 Problem: pm service

Meter Reading: 227		Labor		Parts
In Date: 01/21/2015	Close Date: 02/04/2015	Hours	Description	Quantity
- Pm		9.00	DISTILLED WATER 1GAL	2.00
- Diag No Lights And Horn	And Turn Signal-Replace All		SEAT ASSY	2.00
Fuses That Are Blown Fix	Broken Wire Replace Two		SHOP SUPPLIES	1.00
Solenoid	·		SOLENOID	2.00
- Replace Front Windshield	Repalce Two Seats		FOLDING WINDSHIELD ASM	1.00
- Wash Eqpt	·		Freight Charge	1.00
 Clean And Readjust All Br 	ak Drums And Shoes			

- Shop Supplies

Parts Charge:

1,277.28

Labor Charge:

540.00

Workorder: 1601566 Problem: pm service

	Meter Reading: 242		Labor	P	arts
	In Date: 02/12/2016	Close Date: 03/15/2016	Hours	Description	Quantity
-	Pm		8.00	Freight Charge	1.00
-	Dignose Electical Problems Ck Lamps, Harness For			BULB	1.00
	Voltage Drop, R/R Ac/Dc Co	onverter		DISTILLED WATER 1GAL	2.00
_	Shop Supplies			DC/DC 30 CONVERTER	1.00
				FLASHER-THERMAL	1.00
				SHOP SUPPLIES	1.00

SOLENOID

Parts Charge: 226.92 Labor Charge: 480.00

Workorder: 1701956 Problem: Transition Prep Charge

Meter Reading: 242 Labor Parts
In Date: 02/24/2017 Close Date: 02/24/2017 Hours Description

- Transition Prep Charge 2.00

Parts Charge: 0.00 Labor Charge: 0.00

Total Parts Charges: 2,759.09 Total Labor Charges: 3,180.00 Total Comm. Charges: 0.00

2.00

Quantity