



7/15/2025

Palm Beach County Fire Rescue Fleet Maintenance Asset History

J0578000

* BRUSH TRUCK

Workorder: V970

In Date: 12/19/2005
Close Date: 01/04/2006

Meter Reading:

Problem?

R/REAR SCENE LIGHT INOP, B-54

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V1349

In Date: 02/13/2006
Close Date: 03/02/2006

Meter Reading:

Problem?

D/SIDE REVERSE LIGHT INOP, B-54

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V1531

In Date: 02/16/2006
Close Date: 03/03/2006

Meter Reading:

Problem?

WILL NOT START, B-54

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V1094

In Date: 01/03/2006
Close Date: 04/10/2006

Meter Reading:

Problem?

FLOAT A PUMP MUFFLER BROKEN B-54

Task performed:

Parts

Quantity

V1885MUFFLER WATEROUS 1

17210-ZE3-505AIR FILTER HONDA 1

A1211593054HOSE DISCHG 1



7/15/2025

Palm Beach County Fire Rescue Fleet Maintenance Asset History

J0578000

* BRUSH TRUCK

Workorder: V2070

In Date: 04/03/2006

Meter Reading:

Close Date: 04/10/2006

Problem?

HANDLE IS BROKEN IN REAR FOR WATER PUMP, B-54

Task performed:

<u>Parts</u>	<u>Quantity</u>
VCCTX25CABLE THROTTLE 25 FOOT USE 35 FT	1
6811831323068-1183132-30 LENS CLEAR 9E SERIES	2
68118313250OBSOLETE REPLACE UNIT LENS RED 97 E S	2
VCCTX15CABLE LOCKING W/MICRO ADJ	1



7/15/2025

Palm Beach County Fire Rescue Fleet Maintenance Asset History

J0578000

* BRUSH TRUCK

Workorder: V2127

In Date: 04/06/2006

Meter Reading: 18,435.00

Close Date: 04/26/2006

Problem?

B INSPECTION B-54

Task performed:

See B Inspection pre-printed form

Parts	Quantity
800887AD-SP DROP IN DRYER COMPLETE	1
3303133031 FUEL FILTER MULE	1
BD5506516160SWIVEL JOINT	1
531616-SS53-16-16-SS SWIVEL ADPT	1
05-17223-000CAP RADIATOR 10 LB	1
284358GOVERNOR D-2	1
CA32942714 AIR FILTER	1
P1654AWIX 51553 HYD. FILTER	1
S777COUPLING NIPPLE	1
PH7136WIX 51747 LFP2244 OIL FILTER	2
1677004C9133232 FILTER SEPERATOR	1
P1120FUEL FILTER 33239 WIX	1
P1108WIX 33336 FUEL FILTER DO NOT USE LUBER-FINEF	1
PR338324070 WIX FILTER WATER	1
91-14WIPER BLADE	2
9118 SWITCH	1
259974T1167-10 HOSE ASSLY	1
HP-31DBATTERY 950CCA HP-31D	2
52-239BAR ELECT BUS	1
CA1596ASYWIX 42254	1
VML-T1264GASKET P/S COVER	2
VML-T1311COVER PWR STEER RES	1
CA1596WIX 42253 L/F LAF9545 AIR FILTER	1
24F-60BATTERY	1
CA140PLAIR FILTER 46094	1
54-140CIRCUIT BREAK 40 AMP	1
54-11554-115 FUSE	1
1141BULB	1
24143SOLENOID	1
699CHUCK	1
S775COUPLER	1
VML-S1414FILTER P/S	1
VML-T1279WASHER P/S	1



7/15/2025

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

J0578000

* BRUSH TRUCK

Workorder: V2489

In Date: 05/05/2006

Meter Reading:

Close Date: 05/16/2006

Problem?

CHECK PUMP ONLY GOES TO 120 PSI

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V2612

In Date: 05/15/2006

Meter Reading:

Close Date: 05/19/2006

Problem?

PET COCK AT BOTTOM OF PUMP LEAKING, B-54

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V2971

In Date: 06/13/2006

Meter Reading:

Close Date: 06/15/2006

Problem?

Strobes not working on B#54.

Task performed:

Parts

Quantity

UPS96CRPOWER SUPPLY REPAIRED

1

Workorder: V2972

In Date: 06/13/2006

Meter Reading:

Close Date: 06/15/2006

Problem?

Hydraulic piston not working properly on the passenger side (Chainsaw)

Task performed:

Parts

Quantity

NO PARTS USED



7/15/2025

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

J0578000

* BRUSH TRUCK

Workorder: V3356

In Date: 07/09/2006

Meter Reading:

Close Date: 07/14/2006

Problem?

Missing oil dipstick on brush 54 pump

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V3536

In Date: 07/19/2006

Meter Reading:

Close Date: 07/20/2006

Problem?

B54 air horn not working.

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V4245

In Date: 09/05/2006

Meter Reading:

Close Date: 09/08/2006

Problem?

SIREN INOP, B-54

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V5445

In Date: 11/18/2006

Meter Reading:

Close Date: 11/27/2006

Problem?

air horn on brush 54 not working.

Task performed:

Parts

Quantity

1. ADJUST AIR HORNS

NO PARTS USED



7/15/2025

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

J0578000

* BRUSH TRUCK

Workorder: V5464

In Date: 11/20/2006

Meter Reading:

Close Date: 11/29/2006

Problem?

AIR LEAK B54

Task performed:

Parts

Quantity

298818298818 KNOB PARKING BRAKE

2

Workorder: V6074

In Date: 01/03/2007

Meter Reading:

Close Date: 01/04/2007

Problem?

air horns do not work (can hear big air leak) B54

Task performed:

Parts

Quantity

1. Adjusted air horns

NO PARTS USED

Workorder: V5511

In Date: 11/23/2006

Meter Reading:

Close Date: 01/05/2007

Problem?

On B54 mirrior on pass. side cracked

Task performed:

Parts

Quantity

1. Replaced mirror on right side

1149610278 MIRROR

1

Workorder: V6193

In Date: 01/09/2007

Meter Reading:

Close Date: 01/16/2007

Problem?

FIRE PUMP RECIRCULATING VALVE STUCK IN THE OPEN POSITION. B54

Task performed:

Parts

Quantity

Found no problem with valve. Tested pump and tested o

NO PARTS USED



7/15/2025

Palm Beach County Fire Rescue Fleet Maintenance Asset History

J0578000

* BRUSH TRUCK

Workorder: V6336

In Date: 01/18/2007

Meter Reading:

Close Date: 01/29/2007

Problem?

The float-a-pump will not start. B54

Task performed:

1. TRAVELED TO STN 54. REMOVED BAD GAS AND STARTED, RAN UNIT AND TESTED/ OK.
2. TRAVELED TO STN 54. REBUILT TANK FILL VALVE, TEST/ OK.

Parts

Quantity

91378905 VALVE KIT 2 IN AKRON

1

Workorder: V6337

In Date: 01/18/2007

Meter Reading:

Close Date: 01/29/2007

Problem?

There is a leak somewhere between the tank-to-pump valve and the pump on B54. It only leaks when the valve is activated.

Task performed:

1. TRAVELED TO STN 54. RAN PUMP FOUND NO LEAKS.

Parts

Quantity

NO PARTS USED

Workorder: V6457

In Date: 01/25/2007

Meter Reading:

Close Date: 02/02/2007

Problem?

repair pump leak b54

Task performed:

1. Rebuild tank to pump valve

Parts

Quantity

NO PARTS USED

Workorder: V6732

In Date: 02/13/2007

Meter Reading:

Close Date: 02/26/2007

Problem?

repair float pump b54

Task performed:

- SEND TO SHOP

Parts

Quantity

NO PARTS USED



7/15/2025

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

J0578000

* BRUSH TRUCK

Workorder: V6882

In Date: 02/22/2007

Meter Reading:

Close Date: 02/27/2007

Problem?

REPAIR HEAD LIGHT B54

Task performed:

1. TRAVELED TO STN 54. REPAIRED BAD CONNECTION IN HEAD LIGHT. TEST/ OK.

Parts

RSR03ZCRLIGHT LED RED TIR3 SERIES

Quantity

2

Workorder: V7330

In Date: 03/22/2007

Meter Reading:

Close Date: 03/26/2007

Problem?

need to replace all three sections of 2 1/2 hard suction hose B54

Task performed:

Dropped off hose at 54

Parts

NO PARTS USED

Quantity

Workorder: V7337

In Date: 03/22/2007

Meter Reading:

Close Date: 03/26/2007

Problem?

Both sections of hard suction hose appeared to leaking during the RP-53 pump test.R53

Task performed:

Will order new hose BC

Parts

NO PARTS USED

Quantity

Workorder: V7418

In Date: 03/28/2007

Meter Reading:

Close Date: 04/03/2007

Problem?

PUMP MOTOR SHUTS DOWN AFTER APPROX. 10 MINUTES OF RUN TIME AT WIDE OPEN THROTTLE. HAS OCCURRED MORE THAN ONE OCCASSION. B54

Task performed:

Ran pump at 175psi and did not shut down

Parts

NO PARTS USED

Quantity



7/15/2025

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

J0578000

* BRUSH TRUCK

Workorder: V7637

In Date: 04/11/2007

Meter Reading:

Close Date: 04/13/2007

Problem?

PUMP SHUTS OFF UNDER LOAD

Task performed:

Parts

Quantity

Checked pump engine. Found plugs bad. R&R spark plugs

7534-B6HSSPARK PLUG

4

Workorder: V7632

In Date: 04/11/2007

Meter Reading:

Close Date: 04/26/2007

Problem?

ON CALL PUMP SHUTS OFF RUNING AT MAX PRESSURE B54

Task performed:

Parts

Quantity

Call out to brush fire scene, pump cutting out over 150PSI

NO PARTS USED

Workorder: V7963

In Date: 04/27/2007

Meter Reading:

Close Date: 05/02/2007

Problem?

pump motor wont start b54

Task performed:

Parts

Quantity

Found spark plug wire off

NO PARTS USED

Workorder: V8027

In Date: 05/01/2007

Meter Reading:

Close Date: 05/15/2007

Problem?

ON CALL STUCK ON TRACKS CUT TIRES

Task performed:

Parts

Quantity

Stuck on tracks - cut tires

NO PARTS USED



7/15/2025

Palm Beach County Fire Rescue Fleet Maintenance Asset History

J0578000

* BRUSH TRUCK

Workorder: V8108

In Date: 05/04/2007 Meter Reading:
Close Date: 05/18/2007

Problem?

B54 IS LAEKING AT THE PUMP

Task performed:

Adjust packing
Adjust brakes

Parts

NO PARTS USED

Quantity

Workorder: V8176

In Date: 05/09/2007 Meter Reading:
Close Date: 06/05/2007

Problem?

clearance light out on front of Brush 54

Task performed:

1 repaired light that had bad ground

Parts

NO PARTS USED

Quantity

Workorder: V8506

In Date: 05/31/2007 Meter Reading:
Close Date: 06/13/2007

Problem?

make modifications as ness to new skid unit b54

Task performed:

1. Prep new skid units for installation - add & install new components and make up necessary wiring harnesses & modify plumbing 5/1 to 5/25

Parts

87499RY48 RELAY	1
200054014LENS GREEN	1
DOSZ-14448-ADOSZ-14448-A JUNCTION	2
87123USE 9185 RELAY CONNECTOR 99025	1
25-358SWITCH COVER	1
923182-2151 SWITCH MOMENTARY 24-372	1
8126482-2106 TOGGLE GUARD	2
200054000USE 2000540080 LIGHT ASSY GREEN	1
5582-10 82-2111 GROTE ON-OFF WEATHERPROOF	1
34-5725584 TOGGLE SWITCH ON-ON	1
CYBS18206011STRAP	1
UMVS111611STRAP	1

Quantity



7/15/2025

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

J0578000

* BRUSH TRUCK

Workorder: V9856

In Date: 11/13/2006

Meter Reading: 18,435.00

Close Date: 08/13/2007

Problem?

B INSPECTION B-54

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V10287

In Date: 09/06/2007

Meter Reading:

Close Date: 09/25/2007

Problem?

Difficulty starting pump motor. Possible low battery. B54

Task performed:

Parts

Quantity

1. Installed a new Battery.

24-60BATTERY GROUP 24

1

BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY

1

Workorder: V9036

In Date: 06/27/2007

Meter Reading:

Close Date: 09/27/2007

Problem?

driver's side brake lights out, air horn not working. B54

Task performed:

Parts

Quantity

1. Rep bad connection on air horns

14-7014HGR-1 HELMET HOOK

2

2. Traced out problem w/brake light out and fnd bad connection

78R536078R5360M 2PK FILTER AIR COND

2

Workorder: V10773

In Date: 10/02/2007

Meter Reading:

Close Date: 10/02/2007

Problem?

REPAIR AIR LEAK AND WATER LEAK B54

Task performed:

Parts

Quantity

1. CHECKED FOR AIR LEAK, FOUND PARK BRAKE LIGHT SENDER LEAKING, REMOVED AND REPAIRED

NO PARTS USED

2. REPAIRED FITTING ON PUMP THAT WAS LEAKING



7/15/2025

Palm Beach County Fire Rescue Fleet Maintenance Asset History

J0578000

* BRUSH TRUCK

Workorder: V8029

In Date: 05/01/2007

Meter Reading:

Close Date: 10/15/2007

Problem?

REPLACE TIRES AT STA 54 CALLAGHAN ENT

Task performed:

Parts

Quantity

NO PARTS USED

Vendor?: CALLAGHAN

Workorder: V10805

In Date: 10/03/2007

Meter Reading:

Close Date: 10/22/2007

Problem?

B54 WILL NOT START!!!

Task performed:

Parts

Quantity

1. found bad connection on starter. repaired connection.
2. fuel leak on pump motor - repaired connection

NO PARTS USED

Workorder: V11057

In Date: 10/16/2007

Meter Reading:

Close Date: 10/23/2007

Problem?

B54 DEAD, WILL NOT START

Task performed:

Parts

Quantity

1. charged up batteries and ran truck.

NO PARTS USED

Workorder: V11591

In Date: 11/14/2007

Meter Reading:

Close Date: 11/14/2007

Problem?

unit is hard starting b54

Task performed:

Parts

Quantity

1. Recharged battery and ran pump.
2. Water leak at pump-readjusted pump packing.

NO PARTS USED



7/15/2025

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

J0578000

* BRUSH TRUCK

Workorder: V12051

In Date: 12/13/2007

Meter Reading: 19,633.00

Close Date: 01/07/2008

Problem?

c inspection and repairs as needed b54

Task performed:

1. "C" Inspection.
2. Left brake Lt. out.
3. Adjust brakes.
4. Trans cooler lines chaffing on skid plate.
5. Pump comp. light 10-7, replace Lt. assy.
6. Tune up pump engine, plugs, cap, rotor, wires.
7. Service pump gear case.
8. Pack pump.
9. Wiper blades
10. Service transfer case.
11. Service front and rear Diff. Rear axle had 3 small chips, no dust clean oil.
12. Service cooling syste,
13. Pick up and deliver from Sta. 54.
14. Pump valave leaking, rebuild valve
15. Trans cooler line leak at radiator fitting, repair leak.
16. Passenger side seat mirror falling apart, replace mirror.
17. Door open alarm system 10-7, repair wiring open.
18. Replace belts, unable to get matched set.
19. Service dryer.
20. Cab marker light out.
21. Label pump controls.

Parts

Quantity

P1654AWIX 51553 HYD. FILTER	1
P1120FUEL FILTER 33239 WIX	1
P1108WIX 33336 FUEL FILTER DO NOT USE LUBER-FINEF	1
G1FUEL FILTER 33001	1
CA32942714 AIR FILTER	1
CA1596WIX 42253 L/F LAF9545 AIR FILTER	1
CA140PLAIR FILTER 46094	1
9412SPARK PLUG WIRES VW	1
GB324ROTOR VW	1
GB423CAP DIST. VW	1
R950011USE 5008414 DRYER	1
9595 MIRROR	1
7534-B6HSSPARK PLUG	4
194BULB	1
46977FILTER VW CRANKCASE BREATHER	1
91368904 VALVE KIT 1 1/2 IN	1
80350DOME LIGHT	1
109995PURGE VALVE KIT	1
3303133031 FUEL FILTER MULE	1
PR338324070 WIX FILTER WATER	1
PH7136WIX 51747 LFP2244 OIL FILTER	2
1814927C1TR22770 BELT	1
91-14WIPER BLADE	2
1677004C9133232 FILTER SEPERATOR	1
1157BULB	2
1156BULB	1

Workorder: V12646

In Date: 01/17/2008

Meter Reading: 19,633.00

Close Date: 02/01/2008

Problem?

eng cranks slow b54

Task performed:

1. Eng cranks slow; recharged btry & rested.
 2. Air leak; fnd air leaks @ supply tank & rep.
- j

Parts

Quantity

NO PARTS USED



7/15/2025

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

J0578000

* BRUSH TRUCK

Workorder: V2413

In Date: 04/28/2006

Meter Reading:

Close Date: 02/07/2008

Problem?

DISMOUNT AND MOUNT 2 TIRES, B-54

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V13024

In Date: 02/04/2008

Meter Reading: 19,633.00

Close Date: 02/12/2008

Problem?

on call wont start b54

Task performed:

Parts

Quantity

No start - batteires bd/ installed new batteries. j

HP-31DBATTERY 950CCA HP-31D

2

BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY

2

Workorder: V13655

In Date: 03/03/2008

Meter Reading: 1,830.80

Close Date: 03/19/2008

Problem?

Seal around top of tank were neck is that can be looked into to see if tank is full leaks water when water filled above tank. b54

Task performed:

Parts

Quantity

1. Found no leak at this time, will monitor

NO PARTS USED

Workorder: V13654

In Date: 03/03/2008

Meter Reading: 1,830.80

Close Date: 04/02/2008

Problem?

Bracket for mirror on the passanger side has a crack on the bottom were bolt goes. b54

Task performed:

Parts

Quantity

1. Repaired broken mirror bracket as well as a possible, checked horn, OK

MIR4078MIRROR C BRACKET

1

2. Replaced bracket on right door



7/15/2025

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

J0578000

* BRUSH TRUCK

Workorder: V14849

In Date: 05/04/2008
Close Date: 05/13/2008

Meter Reading: 1,830.80

Problem?

The air horn and one of the front speakers are not functioning. B54

Task performed:

1. adjusted air horn and tested
2. checked out front speakers and found them working

Parts

Quantity

NO PARTS USED

Workorder: V16741

In Date: 07/31/2008
Close Date: 08/01/2008

Meter Reading: 19,633.00

Problem?

pump engine overheating B54

Task performed:

Pump going out of svc; getting new skid unit.

Parts

Quantity

NO PARTS USED

Workorder: V14937

In Date: 05/07/2008
Close Date: 10/20/2008

Meter Reading: 1,830.80

Problem?

pump engine shuts down when it gets hot. b54

Task performed:

Parts

Quantity

NO PARTS USED



7/15/2025

Palm Beach County Fire Rescue Fleet Maintenance Asset History

J0578000

* BRUSH TRUCK

Workorder: V20611

In Date: 01/26/2009

Meter Reading: 19,633.00

Close Date: 02/27/2009

Problem?

C INSPECTION AND REPAIRS AS NEEDED OLD B 54 PUMP MOTOR SHUTS OFF AFTER 30 TO 45 MINUTES RUNNING

Task performed:

Parts

Quantity



7/15/2025

Palm Beach County Fire Rescue Fleet Maintenance Asset History

J0578000

* BRUSH TRUCK

1. Tried to charge & jump start unit; need to replc btrys; R/R btrys.
2. C-Inspection.
3. Tune up pump eng; replc plugs, wires, fuel filter, air filter, coil, pickup; cln conditions to sensors service.
4. Take unit to training; run pump & chk for shut down after 40 mins; unit lost suction, primer & pump faded.
5. Rep air horn-inop; rem/cln valve; reinstall & test.
6. Svc air dryer; replc purge valve & filter.
7. Rem/replc all grip tape on rails & step points.
8. Rep primer control pull swtch; cln valve & chk opn.
9. T-shoot primer motor ckt inop; replc solenoid; motor - NG; R/R motor with motor from spare unit in bldg.
10. Swapout into on-call unit; chk inventory; cln truck.
11. Frnt diff yok & T-case yoke; rem frnt axles & diff; cln all parts; replc all seals & reassemble.
12. Swapout of on-call; wash/fuel truck; replc used parts
13. U-Mux training.
14. Replcd T- case frnt ouput seal & refill w/syn oil.
15. Svc power steering sys.
16. Replcd wiperblades; rep windshield washers.
17. Rep maplight.
18. Readj drivers door hinges for proper door closure.
19. Replcd fan belts.
20. R/R trans cooler line; reroute/secure.
21. Rebuil (1) valve; replc (2) valves; rep 2-way ___; paint/identify valve handles.
22. Paint fuel cap.
23. Replc frnt shocks.
24. Assisted in testing pump by pulling draft at training.
25. T-shoot eng shutdown; after 45 mins pump test several times & fnd restriction in air box; rem restriction & retest. j

1847VUSE LX811 ELECTRONIC VW CONVERSION	1
148N43571YOKE	1
3-94-28XU BOLT KIT	1
1S6541OIL PRESS SW	1
5008414CARTRIDGE DC100	1
UC15IGN COIL 12V NO RESISTOR NEEDED USE ON VW E	1
0714021GASKET 2 1/2"	1
109995PURGE VALVE KIT	1
91-14WIPER BLADE	2
VML-S1414FILTER P/S	1
VML-T1279WASHER P/S	1
VML-T1264GASKET P/S COVER	1
7534-B6HSSPARK PLUG	4
GB324ROTOR VW	1
GB423CAP DIST. VW	1
9412SPARK PLUG WIRES VW	1
472414C91FRONT SHOCKS BRUSH TRUCK	2
91368904 VALVE KIT 1 1/2 IN	1
9700BELT	2
516TIRE INFLATOR	1
1677004C9133232 FILTER SEPERATOR	1
CA1596SYUSE ASY AIR FILTER	1
331691HYDRAULIC HOSE	1
3303133031 FUEL FILTER MULE	1
46977FILTER VW CRANKCASE BREATHER	1
CA140PLAIR FILTER 46094	1
CA1596WIX 42253 L/F LAF9545 AIR FILTER	1
CA32942714 AIR FILTER	1
P1108WIX 33336 FUEL FILTER DO NOT USE LUBER-FINEF	1
P1120FUEL FILTER 33239 WIX	1
P1654AWIX 51553 HYD. FILTER	1
PH7136WIX 51747 LFP2244 OIL FILTER	2
PR338324070 WIX FILTER WATER	1
15W40BSYN OIL BULK QTS	35
464305C1ALLEN BOLT DRIVE PLATE	2
1141BULB	1
99080C ROUND CLEAR LENS	1
1814927C1TR22770 BELT	2
711553PINION SEAL FRONT BRUSH	1
593119C91SEAL AXLE HOUS.	2
2000071102000072100 SOLENOID HALE PRIMER	1
1668454C1SEAL OIL SPINDEL	2
1671199C1SEAL TRUNION	4
1663101C1SEAL OUTPUT SHAFT T-CASE	1
CR36364416125 NAT SEAL OIL BRUSH TRUCK	2



7/15/2025

Palm Beach County Fire Rescue Fleet Maintenance Asset History

J0578000

* BRUSH TRUCK

7810VALVE 1 IN	1
78158915 VALVE 1 1/2	1

Workorder: V17587

In Date: 09/08/2008
Close Date: 03/09/2009

Meter Reading: 19,633.00

Problem?

parts only for b54

Task performed:

Parts	Quantity
412311 1/2 EXHAUST ELBOW	2
90RR5FCR900 LED SUPER RED CLEAR	2
ADS765018LHDRAWER SLIDE LOCKING	1
ADS765018RHDRAWER SLIDE LOCKING	1
L31HRFNBEACIN SUPER LED	2
L360BGBBRUSH GAURD	2
WLA205-A00CAB MINI TANKVISION	1
9UCAPCC9UCAPCC END CAP CLEAR	2
01-0263814-50USE 01-026B807-50 CORNER LED 4500 LIG	4
9ULENSCCLEAR LENS FREEDOM BAR	2
M-284-01SWITCH BATTERY MASTER	1
352251 1/2 EXHAUST RAIN CAP	1
3532535325 CLAMP MUFFLER VW	6
372000082CHROME MARKER LIGHT MOUNT	2
372000083GASKET MOUNTING	2
372000084MARKER LIGHT	2
372000085HARNES FOR MARKER LIGHT	2
91368904 VALVE KIT 1 1/2 IN	1

Workorder: V21972

In Date: 03/20/2009
Close Date: 04/01/2009

Meter Reading: 19,633.00

Problem?

door alarm stays on B32

Task performed:

went to Stn37; T-shoot door alarm; fnd faulty switch; had to come to shop for replacement. j

Parts	Quantity
9118-04SWITCH	1
9118 SWITCH	2



7/15/2025

Palm Beach County Fire Rescue Fleet Maintenance Asset History

J0578000

* BRUSH TRUCK

Workorder: V22098

In Date: 03/26/2009
Close Date: 04/02/2009

Meter Reading: 19,633.00

Problem?

"Spare" B-32 compartment warning light won't go off. This is part of the same problem reported on 3/20/09. Mechanic took compartment switch out and buzzer stopped going off but light is still on.

Task performed:

Swapped to B21; installed hoses; rem frnt jump hose from elbow; swapped eqmpt with drivere; w/wrecker & crew. j

Parts

NO PARTS USED

Quantity

Workorder: V22396

In Date: 04/08/2009
Close Date: 04/22/2009

Meter Reading: 20,168.90

Problem?

pin hole in piping B21 (spare)

Task performed:

1. Pull appart piping valves, etc. replc 90 degree & nipple _____ & install all piping valves, etc.
 2. A-Inspection
 3. Vacation
 4. Rep float-a-pump, shock horn valve replacment.
- j

Parts

91378905 VALVE KIT 2 IN AKRON
EAA-8350-90UGSS6558UK STRUT-LIFT
1136SOLENOID AIR HORN WAS

Quantity

1
1
1

Workorder: V23343

In Date: 05/18/2009
Close Date: 05/21/2009

Meter Reading: 20,275.70

Problem?

A inspection and repairs

Task performed:

1. A-Inspection
2. No brake lights; ck fuse; ck ok; fnd swtch bad; replcd swtch; ck opn; ck ok.
3. Adj hand/throttle on pump; rem air cleaner; adj cable; ck ok. j

Parts

86478647 SWITCH
730C10RUSTROBE LIGHT KIT 73 SERIES

Quantity

1
2



7/15/2025

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

J0578000

* BRUSH TRUCK

Workorder: V25508

In Date: 08/13/2009
Close Date: 08/17/2009

Meter Reading: 225.50

Problem?

please mount dashboard compass to b15 aka spare brush for batt1

Task performed:

Drive to Stn; mount compass on dash. j

Parts

NO PARTS USED

Quantity

Workorder: V25510

In Date: 08/13/2009
Close Date: 08/17/2009

Meter Reading: 225.50

Problem?

strobe lights not working, compass is missing. B-15

Task performed:

Drive to Stn; fnd power pack had no grnd; rewire; test ok. j

Parts

NO PARTS USED

Quantity

Workorder: V26536

In Date: 09/29/2009
Close Date: 10/19/2009

Meter Reading: 10.00

Problem?

BRUSH 15 CHAINSAW NOT RUNNING PROPERLY.IT IDLES BUT WONT RUN FULL SPEED.

Task performed:

Drive to Stn; carb needs to be rebuilt; bring to shop for rep; empty old gas & bring to shop. j

Parts

NO PARTS USED

Quantity

Workorder: V27270

In Date: 10/29/2009
Close Date: 11/05/2009

Meter Reading: 20,590.00

Problem?

PUMP ON BRUSH 15 WILL NOT START.POSSIBLE DEAD BATTERY. b15

Task performed:

Drive to Stn; chk connection & cln; chk charging sys-ok; test btry charging-ok. j

Parts

M-608SWITCH

Quantity

1



7/15/2025

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

J0578000

* BRUSH TRUCK

Workorder: V26846

In Date: 10/14/2009
Close Date: 11/16/2009

Meter Reading: 20,590.00

Problem?

repair saw b 15 regan

Task performed:

Repair saw B15 - Regan j

Parts

NO PARTS USED

Quantity

Vendor?: REGAN SMALL ENG

Workorder: V26873

In Date: 10/14/2009
Close Date: 12/23/2009

Meter Reading: 20,590.00

Problem?

B INSPECTION AND REPAIRS AS NEEDED B15

Task performed:

- B-Inspection
- R/R rear plug btrys; cln cables/mount.
- Door open warn sys inop; chk switches, wiring, relay, etc.; fnd brkn wire to light asy; rep wiring; ok.
- Quality control check.
- C/O water tank lights; fnd bad grnd; cln grn lights; ok.
- tighten up mirror/brkt.
- Glue on pass door w/strip.
- Tighten up window handle. jh

Parts

1677004C9133232 FILTER SEPERATOR
 24-60BATTERY GROUP 24
 BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY
 P1108WIX 33336 FUEL FILTER DO NOT USE LUBER-FINEF
 P1120FUEL FILTER 33239 WIX
 PH7136WIX 51747 LFP2244 OIL FILTER
 15W40BSYN OIL BULK QTS

Quantity

1
1
1
1
1
2
35

Workorder: V28958

In Date: 01/10/2010
Close Date: 01/27/2010

Meter Reading: 20,590.00

Problem?

b15 will not start

Task performed:

- Go to Stn15; C/O brush truck-no start; chk btry-NG; replc (2) btrys; go to shop & restock truck. j

Parts

HP-31DBATTERY 950CCA HP-31D
 BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY

Quantity

2
2



7/15/2025

Palm Beach County Fire Rescue Fleet Maintenance Asset History

J0578000

* BRUSH TRUCK

Workorder: V29352

In Date: 01/22/2010

Meter Reading:

Close Date: 02/11/2010

Problem?

pump drain leaking water B15

Task performed:

Parts

Quantity

Went to Stn15; Fan pump eng; adj pump packing; ck ok; parked truck. j

NO PARTS USED

Went to Stn115 frm Stn33; ran/adj pump packing. j

Workorder: V31320

In Date: 04/06/2010

Meter Reading:

Close Date: 04/28/2010

Problem?

A inspection and repairs (from 26)

Task performed:

Parts

Quantity

A-Inspection
2. Chkd street horn; fnd bad relay; fnd piece of rubber on hood; msng some pushpins; replc pushpins-ok; fnd bad bulb in lite on dash. j

HA141LIGHT RED WARNING

1

7001-2.5COUPLING 2.5 IN

1

8126482-2106 TOGGLE GUARD

1

23-12337002RIVET PLASTIC

3

Workorder: V32682

In Date: 06/06/2010

Meter Reading: 20,765.10

Close Date: 06/17/2010

Problem?

emergency light relay making a popping noise. this is a new noise. B15

Task performed:

Parts

Quantity

Went to 15; turned all emergency lights on; fnd solenoid on firewall energizing for ight bark; ck ok. j

NO PARTS USED



7/15/2025

Palm Beach County Fire Rescue Fleet Maintenance Asset History

J0578000

* BRUSH TRUCK

Workorder: V33359

In Date: 07/06/2010
Close Date: 08/16/2010

Meter Reading: 20,765.10

Problem?

C INSPECTION AND REPAIRS AS NEEDED B15

Task performed:

- 1. C-Inspection
- 2. Cln air filter.
- 3. Svc pump/veh btrys.
- 4. Replcd spark plugs & fuel filter; inspect wires cap & rotor - ok.
- 5. Replcd pump gen belt.
- 6. Replcd wiper blades.
- 7. Svc T-case.
- 8. Svc pump gear box.
- 9. Svc air dryer & purge valve.
- 10. Tighten compt door shock mnts.
- 11. Adj mirrors 7 tighten fasteners.
- 12. Tighten air horn brkt.
- 13. Dia no door open warning; fnd bad rotator.
- 14. Svc chain saws.
- 15. Adj pump packing - too tight.
- 16. Chk elect wiring for trans temp gauge - ok. ja

Parts

Quantity

3303133031 FUEL FILTER MULE	1
7534-B6HSSPARK PLUG	4
OS21625STRAINER OIL VW	1
109995PURGE VALVE KIT	1
6410AAMBER STROBE	1
1677004C9133232 FILTER SEPERATOR	1
P1108WIX 33336 FUEL FILTER DO NOT USE LUBER-FINEF	1
P1120FUEL FILTER 33239 WIX	1
P1654AWIX 51553 HYD. FILTER	1
PH7136WIX 51747 LFP2244 OIL FILTER	3
PR338324070 WIX FILTER WATER	1
15W40BSYN OIL BULK QTS	38
91-14WIPER BLADE	2
7360BELT	1
5008414CARTRIDGE DC100	1
4626BPMR7A SPARK PLUG	1

Workorder: V34061

In Date: 08/05/2010
Close Date: 09/08/2010

Meter Reading: 20,870.00

Problem?

Small oil leak appears to be getting slightly larger under pump motor. B15

Task performed:

- Went to 15; fnd eng leaking oil; eng case leaking UW motor. j

Parts

Quantity

NO PARTS USED



7/15/2025

Palm Beach County Fire Rescue Fleet Maintenance Asset History

J0578000

* BRUSH TRUCK

Workorder: V35534

In Date: 10/10/2010
Close Date: 12/02/2010

Meter Reading: 20,870.00

Problem?

warning lights relay making a popping noise. also as reported before small oil leak under pump motor.B15

Task performed:

1. Travel to stn; chk warning lights - strobe box lights working ok.
2. Pump oil leak valve cvr area; clnd off minor seepage.
j

Parts

Quantity

55015-03SWITCH USE 5543-09

1

RK30063BOWL-PLASTIC RACOR FUEL FILTER

1

Workorder: V37038

In Date: 12/09/2010
Close Date: 12/29/2010

Meter Reading: 20,870.00

Problem?

air leak in braking system B15

Task performed:

- (10 TRAVELED TO ST15 TO CHECK SB1 FOR LEAKING DOWN ON AIR PRESSURE. NO FURTHER SAID ON PAPER W.O. J.W.

Parts

Quantity

NO PARTS USED

Workorder: V37171

In Date: 12/15/2010
Close Date: 12/29/2010

Meter Reading: 20,870.00

Problem?

air pressure leaks down to 0 within approx. 1 1/2hrs. when the truck is shut off. b15

Task performed:

- (1) TRAVELED TO ST15 TO CHECK OUT PROBLEM WITH B15 AIR PRESSURE LEAKING DOWN TO 0 WITHIN 1.5 HRS OF BEING OFF. CHECKED AND FOUND A LEAKING HOSE FITTING AND BLEEDER VALVE . REPAIRED BOTH AND LEAKAGE STOPPED. OK. J.W.

Parts

Quantity

NO PARTS USED



7/15/2025

Palm Beach County Fire Rescue Fleet Maintenance Asset History

J0578000

* BRUSH TRUCK

Workorder: V37222

In Date: 12/17/2010 Meter Reading: 20,870.00
Close Date: 01/12/2011

Problem?

BRUSH 15 WON;T START,DEAD BATTERY

Task performed:

(1) TRAVELED TO ST-15 TO REPAIR PROBLEM WITH B15 FOR NOT STARTING. FOUND THE ALTERNATOR NOT CHARGING. ORDERED NEW ONE.
(1) INSTALLED NEW ALTERNATOR THAT WAS ON ORDER. CHARGING SYSTEM NOW WNL.
J.W.

Parts	Quantity
A-1452ALT INT BR TK DELCO 19020309	1

Workorder: V37917

In Date: 01/20/2011 Meter Reading: 20,870.00
Close Date: 02/04/2011

Problem?

strobe warning lights not working, top beacon is fine. B15

Task performed:

1. Travel to stn; (install 4-way strobe supply temporarily); Strobe inop - strobe box shorted; located short in strobe box; ordered new box.
2. Rep wiring for strobe light @ brkr burnt; rep wiring.
j

Parts	Quantity
UPS64RXPOWER SUPPLY REPAIRED	1
UPS690NLA REPAIR ONLY POWER SUPPLY - WHELEN	1

Workorder: V38139

In Date: 01/29/2011 Meter Reading: 20,870.00
Close Date: 02/04/2011

Problem?

front strobe lights not working B15

Task performed:

Travel to stn; rnt strobes inop; wrong strobe box installed temporarily; installed new strobe box. j

Parts	Quantity
NO PARTS USED	

Workorder: V39574

In Date: 03/31/2011 Meter Reading: 21,046.60
Close Date: 04/05/2011

Problem?

outside left rear turn signal light out. B15

Task performed:

Replcd taillight bulbs. j

Parts	Quantity
NO PARTS USED	



7/15/2025

Palm Beach County Fire Rescue Fleet Maintenance Asset History

J0578000

* BRUSH TRUCK

Workorder: V40071

In Date: 04/22/2011 Meter Reading: 21,046.60
Close Date: 04/25/2011

Problem?

B15 WATER TANK LEAKING. THIS IS A NEW LEAK FROM THE FRONT OF THE TANK. Sta 15.

Task performed:

Parts

Quantity

Travel to 15; fnd wtr tank shifted; fnd in body RF side of tank leaking; pinched hose reel feed hose; hose reel still operates; will og in shop. j

NO PARTS USED

Workorder: V40421

In Date: 05/05/2011 Meter Reading: 21,046.60
Close Date: 05/06/2011

Problem?

Pump motor won't turn over sb at 43

Task performed:

Parts

Quantity

Chk solenoid on carb; cln/blow out with air; put it back in & it started & ran good. j

NO PARTS USED

Workorder: V40528

In Date: 05/10/2011 Meter Reading: 21,425.00
Close Date: 06/02/2011

Problem?

B INSPECTION AND REPAIRS B15 NEW CARBURATOR ON ORDER FOR PUMP CHANGE OIL IN PUMP MOTOR

Task performed:

Parts

Quantity

- B-Inspection
- 2. Replc R/R bullet marker light.
- 3. Svc rear eng.
- 4. Rem carb frm rear eng.
- 5. Assist Ken w/moving wtr tank back - Hines.
- 6. Assist Ken w/fab & installing frnt wtr tank mnts - Hines.
- 7. Chk frnt wheel bearings for wtr.
- 8. Drain tank rem all hoses; raise hose bed lift tank & move ____.
- 9. Fab/install (2) frnt wtr tank mnts.
- 10. Assist Flerx w/welding of fabricated parts - Larson
- 11. Chk wtr tank for leaks; tightenE6000 wtr tank tower; refill; chk for leaks.
- 12. Tank still has leak; fnd wtr level sender leaking; lift up hose bed; rescrew/seal wtr level sensor.
- 13. Install/adj new carb.
- 14. Replc brkn btry holddown bolt.
- 15. Assist disconnecting hoses/fitting hose bed. j

9940-00082 IN TRUNNION BEARINGS

2

9940-001020 IN ROLLER

1

LFP22091523932 GAUGE

1

67BULB 12 VOLT

2

3303133031 FUEL FILTER MULE

1

P1108WIX 33336 FUEL FILTER DO NOT USE LUBER-FINEF

1

P1120FUEL FILTER 33239 WIX

1

PH7136WIX 51747 LFP2244 OIL FILTER

2



7/15/2025

Palm Beach County Fire Rescue Fleet Maintenance Asset History

J0578000

* BRUSH TRUCK

Workorder: V40517

In Date: 05/10/2011 Meter Reading: 21,046.60
Close Date: 06/03/2011

Problem?

pump motor wont start sb at 43

Task performed:

- 1. Sent unit to shop; rebuilt carb.
- 2. Rep rear marker lights. j

Parts

Quantity

736CARB KIT VW BRUSH TK

1

Workorder: V41717

In Date: 06/30/2011 Meter Reading: 21,632.00
Close Date: 07/06/2011

Problem?

A inspection.

Task performed:

PUMP WONT START CABLE LOOSE @ STARTER
CLEANED AND TIGHTENED CABLE

MAP LIGHT INOP POOR CONTACT @ SWITCH
REPAIRED SWITCH

DOME LIGHT INOP SWITCH BAD REPLACED DOME
LIGHT ASSEM

1 CAB DOME LIGHT INOP BULB RELACED BULB

A-INSPECTION PERFORMED

MIRRORS LOOSE AND OUT ADJ LS BRAKT BENT
TIGHTENED AND RP MIRRORS STRAIGHTENED LS
BRACKET

R2 COMPT LIGHTS INOP BULB REPLACED BULB

DIESEL AND GAS TANKS NOT LABELED LABELED
FUEL TANKS PROPERLY AK

Parts

Quantity

1664763C91DOME LIGHT INTERNATIONAL

1

Workorder: V42372

In Date: 07/28/2011 Meter Reading: 21,652.00
Close Date: 08/01/2011

Problem?

B15 missing 12V hand spotlight, back from shop yesterday. Sta 15.

Task performed:

Travel to 15; drop off spotlight. j

Parts

Quantity

NO PARTS USED



7/15/2025

Palm Beach County Fire Rescue Fleet Maintenance Asset History

J0578000

* BRUSH TRUCK

Workorder: V42425

In Date: 08/01/2011 Meter Reading: 21,652.00
Close Date: 08/02/2011

Problem?

ON CALL B 15 PUMP WONT START

Task performed:

WENT TO ST 15 FROM ST 16 STARTED TRAN PUMP
MOTOR SHIFT OFF AND STARTED MULTIPLE TIMES
PUMPED 1/2 TANK OF WATER CK OK RETURN
HOME AK

Parts

NO PARTS USED

Quantity

Workorder: V43076

In Date: 08/26/2011 Meter Reading: 21,652.00
Close Date: 08/30/2011

Problem?

B15 BATTERY DEAD.JUMPED THIS AM AND PUMP MOTOR WONT IDLE.WILL NOT RESTART. Sta 15.

Task performed:

Travel to Stn15; C/O btry; R/R btry, svc cables; C/O fuel
sys & carb; cln out carb of old fuel; adj carb; runs ok
now.

Parts

24-60BATTERY GROUP 24

BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY

1

1

Workorder: V44799

In Date: 10/31/2011 Meter Reading:
Close Date: 11/02/2011

Problem?

B15 DEAD,WILL NOT START.

Task performed:

Travel to 15; truck & brush motor started; truck btrys low;
ran truck to charge - ok. j

Parts

NO PARTS USED

Quantity

Workorder: V46069

In Date: 12/25/2011 Meter Reading: 21,652.00
Close Date: 12/29/2011

Problem?

B15 starting hard, sta 15

Task performed:

TRAVEL TO 15 R&R BATTERIES ON BRUSH TRUCK.

Parts

HP-31DBATTERY 950CCA HP-31D

BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY

4

4



7/15/2025

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

J0578000

* BRUSH TRUCK

Workorder: V46255

In Date: 01/03/2012 Meter Reading: 21,682.00
Close Date: 01/12/2012

Problem?

B INSPECTION OIL CHANGE SERVICES B15

Task performed:

B INSPECTION OIL CHANGE SERVICES

Parts

NO PARTS USED

Quantity

Vendor?: OIL CHANGE SERVICES

Workorder: V46600

In Date: 01/16/2012 Meter Reading: 21,682.00
Close Date: 01/18/2012

Problem?

L beacon Emergency Light Inop, Sta 15

Task performed:

TRAVEL TO 15 REPLACED BULB IN LIGHT BAR.

Parts

795 BULB

Quantity

1

Workorder: V46906

In Date: 01/28/2012 Meter Reading: 21,682.00
Close Date: 02/10/2012

Problem?

The lighted level indicators for the foam tank and the H2O tank are not accurately reflecting the actual levels. Sta 54

Task performed:

INSTALLED SOLENOID FOR AIR HORNS.

Parts

EL3601424213 SOLENOID 200 AMP 12V DC

Quantity

1

Workorder: V47110

In Date: 02/06/2012 Meter Reading: 21,682.00
Close Date: 02/28/2012

Problem?

chainsaw leaking fuel while running, Sta 15

Task performed:

TRAVELED TO STATION PICKED UP SAW DELIVERED TO SHOP FOR REPAIR.

Parts

NO PARTS USED

Quantity



7/15/2025

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

J0578000

* BRUSH TRUCK

Workorder: V46532

In Date: 01/12/2012

Meter Reading: 21,682.00

Close Date: 04/25/2012

Problem?

Complete B inspection repairs.

Task performed:

- CHECK REAR PINION AND FRONT AXLE SEALS. CLASS 1 LEAKS WILL MONITOR.
- CHECKED FOR LOOSE EXHAUST. FOUND CLAMP LOOSE AT TURBO SECURED CLAMP AND TESTED OK.
- CHECK PUMP AND PUMP MOTOR FOR WATER AND OIL LEAKS. FOUND LOOSE VALVE COVER CLAMP AND PUSH ROD TUBE. SECURED BOTH ADJUSTED PUMP PACKING OK.
- CHECK TOOL MOUNTING BRACKETS - FOUND LOOSE BRACKET. SECURED ALL BRACKETS.

Parts

Quantity

NO PARTS USED

Workorder: V49610

In Date: 05/24/2012

Meter Reading: 21,691.90

Close Date: 06/07/2012

Problem?

PRESSURE GAUGE ON B15 NOT WORKING. B15

Task performed:

TRAVEL TO 15 RAN BRUSH MOTOR AND PUMP BOTH CAB AND REAR PRESSURE GAUGE WORK FINE NO PROBLEM FOUND.

Parts

Quantity

NO PARTS USED

Workorder: V49750

In Date: 05/30/2012

Meter Reading: 21,691.90

Close Date: 06/08/2012

Problem?

water level indicator light on pump panel does not work accurately. It does not adjust to reflect correct water level, it always reads full!! B54

Task performed:

- RECALABRATED GAUGE AND TESTED.
- REPAIRED LEAF AT PUMP PANEL.

Parts

Quantity

NO PARTS USED



7/15/2025

Palm Beach County Fire Rescue Fleet Maintenance Asset History

J0578000

* BRUSH TRUCK

Workorder: V50095

In Date: 06/13/2012 Meter Reading: 21,691.90
Close Date: 06/22/2012

Problem?

lef outert tail light out on b15.

Task performed:

REPAIRED WIRE TO L/R TAIL LIGHT.

Parts

Quantity

NO PARTS USED

Workorder: V50757

In Date: 07/11/2012 Meter Reading: 21,691.90
Close Date: 07/12/2012

Problem?

Pump on spare B14 not turning over.

Task performed:

TRAVEL TO 14 MOTOR RUNS FINE INSTRUCTED
CREW ON HOW TO START MOTOR.

Parts

Quantity

NO PARTS USED

Workorder: V51952

In Date: 08/28/2012 Meter Reading:
Close Date: 09/06/2012

Problem?

Brush Truck submerged above the rear axle during flood relief assistance in Bat.2 on Monday August 27 and Tuesday Aug 28. b 1

Task performed:

1. TRAVEL TO ST15 CHECK REAR AXEL AND FRONT
AXEL FOR WATER INTERVISION OK LEVELS GOOD

Parts

Quantity

NO PARTS USED

Workorder: V51354

In Date: 08/03/2012 Meter Reading:
Close Date: 09/17/2012

Problem?

slow air leak in braking system.

Task performed:

SSECURED AIR FITTING AT TANK.

Parts

Quantity

NO PARTS USED



7/15/2025

Palm Beach County Fire Rescue Fleet Maintenance Asset History

J0578000

* BRUSH TRUCK

Workorder: V53123

In Date: 10/16/2012

Meter Reading: 22,131.00

Close Date: 10/25/2012

Problem?

C INSPECTION B 15

Task performed:

1. C INSP
2. REPLACED PUMP BATTERY
3. C INSP
4. T-CARE SERVICE.
5. TAKE ENGINE, DIFF, AND TRANS SAMPLE.
6. PUMP GEAR CASE SERVICE.
7. CHK AND SERVICE BELTS, TIGHTEN UP BOTH BELTS LOOKS GOOD.
8. SERVICE P/S UNIT, FLUID AND WIPER BLADES BOTH.
9. WORK ON PUMP MOTOR, RUNNING VERY BAD R&R CARB, CLEAN INSIDE OF CARB ON BENCH REINSTALLED, INSTALLED NEW PLUG, WIRES CAP ROTTEN. REMOVE OLD LINE R&R FUEL TANK AND CLEAN OUT GET NEW FUEL AT DOCKS ADD STAY BUL SEA FOAM INSTALLED TANK READJUST CARB AND REPAIR. EXHAUST LEAK ON FRONT OF MOTOR REINSTALLED SHAFT TO REPAIR.
10. INSTALLED NEW PUMP MOTOR BELT HAVE TO ADJUST ALT PULL TO FIT BELT TIGHT, BY MOVING SHIM TO TIGHTEN AND ADJUST.
11. REPAIR DOOR HANDLE HARD TO GET OPEN DOOR ADJUST AND TAKE TO WORK.
12. CHK AND ADJUST FRONT BRAKES, TEST DRIVE AFTER REPAIR.

Parts

Quantity

54-15 31-15 WIPER BLADE	2
7360BELT	1
46977FILTER VW CRANKCASE BREATHER	1
CA140PLAIR FILTER 46094	1
CA1596WIX 42253 L/F LAF9545 AIR FILTER	1
24-60BATTERY GROUP 24	1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	1
1677004C9133232 FILTER SEPERATOR	1
3303133031 FUEL FILTER MULE	1
ANTICOOLANT ANTIFREEZE GAL	8
TRANSYNDALLISON TRANS FLUID GAL	2
P1108WIX 33336 FUEL FILTER DO NOT USE LUBER-FINEF	1
P1120FUEL FILTER 33239 WIX	1
P1654AWIX 51553 HYD. FILTER	1
PH7136WIX 51747 LFP2244 OIL FILTER	2
OS21625STRAINER OIL VW	1
470031C2INSULATOR	4
109995PURGE VALVE KIT	1
5008414CARTRIDGE DC100	1
PR338324070 WIX FILTER WATER	1
VML-T1264GASKET P/S COVER	1
VML-T1279WASHER P/S	1
VML-S1414FILTER P/S	1
9412SPARK PLUG WIRES VW	1
7534-B6HSSPARK PLUG	4
GB324ROTOR VW	1
GB423CAP DIST. VW	1
GB4273PGB4273P POINTS IGNITION	1
GB136GB136 CONDENSOR VW	1



7/15/2025

Palm Beach County Fire Rescue Fleet Maintenance Asset History

J0578000

* BRUSH TRUCK

Workorder: V53739

In Date: 11/13/2012
Close Date: 11/30/2012

Meter Reading: 22,184.80

Problem?

pump motor wont run B 32

Task performed:

CLEANED OUT CARB AND REPAIRED FUEL LINE AND
REPLACED ONE SPARK PLUG WIRE.

Parts

NO PARTS USED

Quantity

Workorder: V54109

In Date: 11/30/2012
Close Date: 12/03/2012

Meter Reading: 22,197.00

Problem?

A inspection

Task performed:

1. A INSP
2. INSTALL NEW OVERFLOW TUBE ON RAD- OLD HOSE BROKEN OFF 1/2 WAY AND NOT CONNECTED TO EXPANSION TANK.
3. PUMP ENG. MISSING BADLY- CHECK ON PROBLEM FOUND TWO PLUG WIRES OFF- WIPERS WOULD NOT STAY ON PLUGS- INTERIOR CLIPS MISSING, INSTALL NEW SET OF PLUG WIRES.

Parts

9412SPARK PLUG WIRES VW

Quantity

1

Workorder: V54520

In Date: 12/19/2012
Close Date: 12/27/2012

Meter Reading: 22,197.00

Problem?

brush motor inop

Task performed:

REWIRED PUMP C ONTROL PANEL INSTALL
ELECTRIC FUEL PUMP.

Parts

42SFUEL PUMP

VF445F11FSO140A RELAY A/C DIODE SUP

Quantity

1

1

Workorder: V52208

In Date: 09/06/2012
Close Date: 12/28/2012

Meter Reading: 22,009.00

Problem?

Starter switch inside cab for fire pump inop B15

Task performed:

CHECKED SYSTEM OK.

Parts

NO PARTS USED

Quantity



7/15/2025

Palm Beach County Fire Rescue Fleet Maintenance Asset History

J0578000

* BRUSH TRUCK

Workorder: V55118

In Date: 01/17/2013

Meter Reading:

Close Date: 01/28/2013

Problem?

tank water gauges not working properly pump idle running rough, stalling at idle

Task performed:

Parts

Quantity

CHECKED GUAGES WORKING FINE ADJUSTED
CARB ON PUMP OK.

NO PARTS USED

Workorder: V55155

In Date: 01/18/2013

Meter Reading:

Close Date: 01/28/2013

Problem?

Chain will not start.SB-@25

Task performed:

Parts

Quantity

TRAVEL TO 25 ADJUSTED CARB ON SAW RUNS
GOOD.

NO PARTS USED

Workorder: V55099

In Date: 01/16/2013

Meter Reading: 22,364.00

Close Date: 02/22/2013

Problem?

pump motor won't stay running

Task performed:

Parts

Quantity

1. CHECK OUT MOTOR NO RUN, REMOVE ALL FUEL
LINE ALL BAD, REPLACE WITH ALL NEW, INSTALLED
NEW FUEL PUMP, STILL RUNNINGBAD, REMOVE
CARB.

42SFUEL PUMP

1

CLEAN OUT INTIAE CARB FOUND ALL BLOCK UP
REINSTALLED ALL PARTS IN CAR REINSTALLED ON
MOTOR RESTART RUNNING GOOD.

4007BULB NIGHT FIGHTER

1

2. FINISH UP REPAIRS, CHECK FOR SKIDE PLATES
UNDER TRUCK FOR REPLACEMENT, ALL GOOD
WRONG TRUCK FOR PARTS.

1156BULB

1

3. ????? ON TRUCK REPLACE PARKING. REPAIR
HOSE REEL HOSE HOLDER AND BUTTON.



7/15/2025

Palm Beach County Fire Rescue Fleet Maintenance Asset History

J0578000

* BRUSH TRUCK

Workorder: V56481

In Date: 03/18/2013
Close Date: 03/19/2013

Meter Reading: 22,364.00

Problem?

A INSPECTION

Task performed:

1. A-SERVICE CHECK OVER TRUCK.
2. REPLACE LIGHT IN REAR BRAKE LIGHT; REPLACE WIPER BLADES.
3. ADJUST PUMP PACKING, RUN AND RECHECK OK. ADJUST TIRES CHECK AND TOP OFF ALL FLUID.

Parts

Quantity

54-15 31-15 WIPER BLADE

2

Workorder: V59370

In Date: 07/26/2013
Close Date: 07/29/2013

Meter Reading: 22,364.00

Problem?

brush pump no start, throttle cable inop

Task performed:

1. REPAIRED THROTTLE CABLE F OR PUMP MOTOR.
2. CHARGED BATTERY.

Parts

Quantity

NO PARTS USED

Workorder: V62203

In Date: 11/22/2013
Close Date: 11/26/2013

Meter Reading: 22,364.00

Problem?

bad battery

Task performed:

1. CHECK OUT-(NO START) IN YARD VEHICLE STARTED RIGHT UP- CHECK PUMP MOTOR BATT- ASSO STARTED RIGHT UP- LIFT COVER CAB BATTs AND LOOKS LIKE NEW BATTs WERE ALREADY REPLACED.
2. PUMP PACKING WHILE I HAD PUMP MOTOR RUNNING- NOTICED WATER ROOFING OUT OF PUMP PACKING- RUN ENG AND ADJUST PUMP PACKING.

Parts

Quantity

M-456TERMINAL BLOCK

1



7/15/2025

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

J0578000

* BRUSH TRUCK

Workorder: V66424

In Date: 05/12/2014
Close Date: 05/28/2014

Meter Reading: 22,718.00

Problem?

C inspection SB6

Task performed:

1. C insp.
2. service air dryer
3. r/side rear frame rail bolts missing, pony motor frame not secure to frame rail, use fork lift and jacks to align holes in frame rail to pony motor, install new bolts
4. pump packing leaking, repack pump
5. pony motor will not start, check fuel, spark, found no power to coil, check wiring, found wires corroded and some bad connectors, repair all wiring, now gets power to coil, still no star, remove carb and clean, motor now starts runs good

Parts

Quantity

CA32942714 AIR FILTER	1
5008414CARTRIDGE DC100	1
109995PURGE VALVE KIT	1
1677004C9133232 FILTER SEPERATOR	1
3303133031 FUEL FILTER MULE	1
P1108WIX 33336 FUEL FILTER DO NOT USE LUBER-FINEF	1
P1120FUEL FILTER 33239 WIX	1
P1654AWIX 51553 HYD. FILTER	1
PH7136WIX 51747 LFP2244 OIL FILTER	2

Workorder: V68980

In Date: 08/27/2014
Close Date: 09/16/2014

Meter Reading: 22,834.00

Problem?

pump motor no start

Task performed:

- Removed carb cover and checked fuel pump and battery. Found battery bad installed new, found safety fuel switch stuck closed corrected, tested ok.

Parts

Quantity

16450STARTER	1
24-60BATTERY GROUP 24	1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	1



7/15/2025

Palm Beach County Fire Rescue Fleet Maintenance Asset History

J0578000

* BRUSH TRUCK

Workorder: V70421

In Date: 10/24/2014

Meter Reading: 22,834.00

Close Date: 11/05/2014

Problem?

rebuild brush pump

Task performed:

1. Disassembled pump-plumbing and brackets ordered new rebuild parts.
2. Started assembling new parts on to pump
3. Installed gear case and pump housing plumbing and hose wiring.
4. Finished install and started testing pump for leak.

Parts	Quantity
91398907 VALVE KIT 3 IN AKRON	1
36011163601116 O RING SUC HEAD	1
3601610QUAD RING	1
38171048 PER PACK PACKING-PUMPS DARLEY	1
3809600GASKET PUMP CASING	1
103385NDRAIN COCK	1
2052700DARLEY PUMP CASTING	1
34017003401700 SEAL RINGS	1
35408 CLAMP	1
3606207STUD DARLEY MOUTING	2
3606208STUD DARLEY MOUNTING	22
50033005003300 SHAFT - IMPELLER	2
5403003NUT DARLEY SST MOUNTING	24
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	2
FRT V27783FREIGHT CHARGE	1
HP-31DBATTERY 950CCA HP-31D	2

Workorder: V71434

In Date: 12/05/2014

Meter Reading: 22,834.00

Close Date: 12/09/2014

Problem?

batteries dead wont start

Task performed:

Attempted to jumpstart vehicle in parking lot-connected battey charger and charged for 2 hours. Replaced 2 failed batteries in parking lot.

Parts	Quantity
HP-31DBATTERY 950CCA HP-31D	2
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	2



7/15/2025

Palm Beach County Fire Rescue Fleet Maintenance Asset History

J0578000

* BRUSH TRUCK

Workorder: V71625

In Date: 12/13/2014

Meter Reading: 22,834.00

Close Date: 12/29/2014

Problem?

brush motor won't stay running and primer inop

Task performed:

Preformed pump motor and primer tests-pump motor started immediately and ran under varying loads for 30 min. Primer used multiple times with no fault. Operation normal at this time

Parts

Quantity

489078-001A/C KNOB EONE

1

72R311018-2640 VENT A/C NEW # 1719

1

Workorder: V73022

In Date: 02/10/2015

Meter Reading: 22,834.00

Close Date: 02/23/2015

Problem?

pump motor won't start and possible issue with throttle cable

Task performed:

1. a. & b. Check out throttle cables. Front cable works ok. Rear cable broken. Note: Carb has been changed and uses a different style carb (original is obsolete). The linkage on carb is different. It is primarily set up for only to have a single pull cable. The second cable was installed in a way the throttle would only be able to open less than 1/4 without binding up linkage. This would cause the operator to keep turning throttle knob to get more rpms, and because of binding linkage caused the cable housing to brake. Install new throttle cable assembly and modify carb linkage to work with new cable without binding.

2. a. & b. After throttle cable repair, tried to start pump engine - no good from both cab and rear. Check for fuel. Fuel ok. Check ignition system and found no power to coil. Check out ignition switch and found many splices and different colored wiring. Pulled control panel from cab. Wiring on cab ignition switch was connected all wrong. At this point, I started over, making up new wiring harnesses. 2 new ignition switches, relays etc. Wire up all components and test out new system. Engine can be started now from either end and shut off from either end. Added relays, one for starter to operate from front and one for ignition accessories. (carb coil heater and elect. fuel pump, oil pressure light and power to tank level gauges) All these were connected to the positive terminal of ignition coil, robbing the coil of power.

3.1 - 2 1/2 discharge valve leaking badly. Remove and disassemble on bench. Rebuild and reinstall. Note: This is a Darly valve.

Parts

Quantity

KA000072 1/2 IN DARLEY KIT

1

87499RY48 RELAY

2

091-84-022DIODE 6 AMP

1

546-00011-001HALE RED INDICATOR LED

1

CA140PLAIR FILTER 46094

1

VCGTX15CABLE LOCKING W/MICRO ADJ

1

VCGTHOCONTROL

1

34-5725584 TOGGLE SWITCH ON-ON

2



7/15/2025

Palm Beach County Fire Rescue Fleet Maintenance Asset History

J0578000

* BRUSH TRUCK

Workorder: V74153

In Date: 03/25/2015

Meter Reading: 22,834.00

Close Date: 05/11/2015

Problem?

Hose reel inop @21

Task performed:

Parts

Quantity

1. Travel to 21, repaired loose ground on motor and lubricated chain.

NO PARTS USED



Palm Beach County Fire Rescue Fleet Maintenance Asset History

Asset: (J0578000) 1994 - INTERNATIONAL 4800 Brush Truck - Sb4

J0578000

CSHOP-2015-141

Date Opened 4-20-2015 Date Finished 4-27-2015 Meter 1 Reading: 23,125

TASKS PERFORMED

Q PARTS

WIPER BLADES

2 WIPER; 31-15 WIPER BLADE

CSHOP-2015-2594

Comments: **A INSPECTION ON SB6**

Date Opened 8-28-2015 Date Finished 8-31-2015 Meter 1 Reading: 23,332

TASKS PERFORMED

Q PARTS

A INSPECTION
PONY PUMP MOTOR
WIPERS-WASHER
SERPENTINE BELT
SPOT LIGHTS
PARK-CLEARANCE LIGHTS
EMERGENCY EQUIPMENT

2 RELAY; RY48 RELAY
1 BULB; BULB 12 VOLT

CSHOP-2015-2740

Comments: **SPARE BRUSH AT 48 PUMP MOTOR HAVING HARD TIME STARTING**

Date Opened 9-8-2015 Date Finished 9-11-2015 Meter 1 Reading: 23,366

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
FIRE APPARATUS

CSHOP-2015-2787

Comments: **A INSPECTION SPARE BRUSH 6**

Date Opened 9-8-2015 Date Finished 9-9-2015 Meter 1 Reading: 23,366

TASKS PERFORMED

NO PARTS USED

A INSPECTION
WATER TANK LEVEL LIGHTS
BODY EXTERIOR

Asset Work Order History J0578000

CSHOP-2015-473

Comments: **C INSPECTION SPARE BRUSH 6**

Date Opened 5-6-2015

Date Finished

6-2-2015

Meter 1 Reading:

23,224

TASKS PERFORMED

PM SERVICE C

Q PARTS

-1	FILTER; WIX 42254
1	9IP; STRAINER OIL VW
1	FILTER; WIX 33336 FUEL FILTER DO NOT USE LUBER-FINE
1	FILTER; FILTER VW CRANKCASE BREATHER
1	FILTER; 33232 FILTER SEPERATOR
20	FLUID; SYN OIL BULK QTS
1	FILTER; WIX 51553 HYD. FILTER
1	9IP; GASKET 4 IN
1	FILTER; WIX 42254
1	FILTER; FUEL FILTER 33239 WIX
1	FILTER; 33031 FUEL FILTER MULE
1	FILTER; FUEL FILTER
1	FILTER; 42714 AIR FILTER
2	FILTER; WIX 51747 LFP2244 OIL FILTER

CSHOP-2015-915

Comments: **REPAIRS FROM C INSPECTION**

Date Opened 6-1-2015

Date Finished

6-15-2015

Meter 1 Reading:

23,224

AIR DRYER NEEDS SER.

TASKS PERFORMED

PRIMING PUMP FIRE PUMP
WIPER BLADES
AIR FILTER
CAP
INSTRUMENT PANEL LIGHTS
LIGHTING SYSTEM
BATTERY
BELT
FILTER
DEF FLUID
U-BOLTS
RESERVOIR
FRONT BRAKE PADS-SHOES
AIR SYSTEM

Q PARTS

1	STARTER; PARTNER STARTER PULLEY
2	WIPER; WIPER BLADE
1	9IP; WIX 42253 L/F LAF9545 AIR FILTER
1	FILTER; WIX 42254
1	CAP; CAP RADIATOR 10 LB
4	9IP; GE37 BULB
1	BREAKER; CIRCUIT BREAKER 100 AMP
2	BATTERY; BATTERY 950CCA HP-31D
2	BATTERY; BATTERY EPA TAX \$1.50 PER BATTERY
1	BELT; BELT
1	BELT; BELT
-2	BELT; TR22770 BELT
1	DIODE; DIODE 6 AMP
2	BELT; TR22770 BELT
1	FILTER; WIX 51553 HYD. FILTER
5	FLUID; ALLISON TRANS FLUID GAL
33	GEAR; GEAR OIL SYN QT
1	BRAKE; 8T3430 U-BOLT
1	GASKET; GASKET P/S COVER
1	FILTER; FILTER P/S
1	FLUID; ALLISON TRANS FLUID GAL
1	9IP; WASHER P/S
2	9IP; FRONT SHOE KIT INT BR TKS
1	BRAKE; CARTRIDGE DC100
1	VALVE; PURGE VALVE KIT

Asset Work Order History J0578000

CSHOP-2016-1117

Date Opened 3-8-2016 Date Finished 3-11-2016 Meter 1 Reading: 23,395

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
EXHAUST SYSTEM

1 NEWPART; MUFFLER BRUSH TRUCK
2 CLAMP; CLAMP 4" 33969

Service Requests:

03/08/2016 SERVICE REQUEST / 18: LEAKING / EXCHANGE - NEW

CSHOP-2016-1656

Date Opened 4-7-2016 Date Finished 4-18-2016 Meter 1 Reading: 23,395

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
BRAKES
AIR SYSTEM

1 LIGHT; LOW PRESS IND 79164

Service Requests:

04/07/2016 BRAKES / 18: LEAKING / EXCHANGE - NEW
WHILE DRIVING ON I95 THE BRAKE DASH LIGHT AND ALERT SOUND (LOW AIR ALARM) CAME ON. NO DROP IN
PRESSURE AND BRAKES SEEM TO BE WORKING. POSSIBLE AIR LEAK AT REAR WHEEL?

04/07/2016 BRAKES / 49: CAN NOT DUPLICATE CONCERN / INSPECT

CSHOP-2016-374

Comments: **B-14 PULL ROPE ON CHAIN SAWS BROKEN**

Date Opened 1-25-2016 Date Finished 2-4-2016 Meter 1 Reading: 23,395

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
FIRE FIGHTING EQUIPMENT

Service Requests:

01/25/2016 MISCELLANEOUS / 12: BROKEN / REPLACED PULL CORD ON SAW
CHAIN SAW ROPE PULL BROKE ON BRUSH 14 SPARE

CSHOP-2016-3951

Date Opened 8-11-2016 Date Finished 9-26-2016 Meter 1 Reading: 23,395

TASKS PERFORMED

Q PARTS

FIRE PUMP PLUMBING

1 9IP; SEAL
1 SEAL; SEAL
1 SEAL; G150T SEAL

Asset Work Order History J0578000

CSHOP-2016-4216

Comments: **C INSPECTION**

Date Opened 8-26-2016

Date Finished

9-7-2016

Meter 1 Reading:

24,028

TASKS PERFORMED

Q PARTS

PM SERVICE C

1 FILTER; WIX 51553 HYD. FILTER
1 FILTER; WIX 33336 FUEL FILTER DO NOT USE LUBER-FINE
1 FILTER; AIR FILTER 46094
1 FILTER; FUEL FILTER 33239 WIX
1 FILTER; 33031 FUEL FILTER MULE
1 FILTER; FUEL FILTER 33239 WIX
21 FLUID; SYN OIL BULK QTS
1 FILTER; 24070 WIX FILTER WATER
1 FILTER; 33232 FILTER SEPERATOR
2 FILTER; WIX 51747 LFP2244 OIL FILTER

CSHOP-2016-4261

Comments: **REPAIRS FROM PM**

Date Opened 8-30-2016

Date Finished

11-23-2016

Meter 1 Reading:

24,028

TASKS PERFORMED

Q PARTS

WATER TANK LEVEL LIGHTS
COMPARTMENT LIGHT BODY
FIRE PUMP CONTROLS
GEAR BOX FIRE PUMP
HOSE REEL
TURN SIGNAL LIGHTS
BRAKE LIGHTS
PARK-CLEARANCE LIGHTS
HEADLIGHTS LOW BEAM
BATTERY
AIR DRIER
BACK-UP ALARM

1 9IP; AO638 SENDER 4-WIRE
1 SWITCH; HARNESS T/S SWITCH INT.
1 SWITCH; T/S SWITCH BRUSH TRUCK INT.
1 BULB; TAIL LIGHT BULBS
2 BRAKE; BRAKE/TAILLIGHT LED
4 9IP; 600 CHROME FLANGE
2 LENS; 600 SER LENS NON OPTIC
1 ALARM; BACKUP ALARM ECCO 107 DEC
1 LIGHT; HEADLIGHT EXTRA BRIGHT
1 BATTERY; BATTERY GROUP 24
1 VALVE; PURGE VALVE KIT
1 BRAKE; CARTRIDGE DC100
1 ALARM; BACKUP ALARM ECCO 107 DEC

CSHOP-2016-5946

Date Opened 12-20-2016

Date Finished

12-20-2016

Meter 1 Reading:

24,101

TASKS PERFORMED

NO PARTS USED

PRE TRIP INSPECTION

CSHOP-2016-6028

Date Opened 12-27-2016

Date Finished

12-27-2016

Meter 1 Reading:

24,145

TASKS PERFORMED

NO PARTS USED

PRIMING PUMP FIRE PUMP

Service Requests:

12/25/2016 SERVICE REQUEST / 49: CAN NOT DUPLICATE CONCERN / RECEIVED PAGE FROM DISPATCH. C/
SERVICE REQUEST FOR SPARE BRUSH TRUCK AT STATION 28. PRIMER NOT WORKING ON PUMP.

Asset Work Order History J0578000

CSHOP-2017-1731

Date Opened 3-21-2017 Date Finished 5-2-2017 Meter 1 Reading: 0

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
FIRE PUMP

Service Requests:

03/21/2017 SERVICE REQUEST / 12: BROKEN / INSPECT
SERVICE REQUEST WATER PUMP SHUTS DOWN RANDOMLY WHILE PUMPING. SOMETIMES RESTARTS RIGHT AWAY,
SOMETIMES TAKES SEVERAL MINUTES TO RESTART

CSHOP-2017-3557

Comments: **CHECK BRUSH PUMP**

Date Opened 6-15-2017 Date Finished 6-15-2017 Meter 1 Reading: 25,470

BATTERY FAILED LOAD TEST

TASKS PERFORMED

Q PARTS

FIRE PUMP
BATTERY

1 ECH; SWITCH
1 9IP; BATTERY GROUP 24

CSHOP-2017-4220

Date Opened 7-19-2017 Date Finished 7-21-2017 Meter 1 Reading: 25,470

TASKS PERFORMED

Q PARTS

WIPER BLADES

2 9IP; 9IP

CSHOP-2017-4628

Date Opened 8-9-2017 Date Finished 8-15-2017 Meter 1 Reading: 25,470

TASKS PERFORMED

Q PARTS

PM SERVICE C

21 FLUID; SYN OIL BULK QTS
1 FIL; NAPAGOLD FUEL FILTER
1 FIL; NAPAGOLD FUEL FILTER
-21 9OC; SYN 15W40
21 9OC; SYN 15W40
1 FIL; NAPA BREATHER FILTER
1 FIL; NAPAGOLD FUEL FILTER
2 FIL; NAPAGOLD OIL FILTER
1 FIL; NAPAGOLD FUEL FILTER

CSHOP-2017-4629

Comments: **PM REPAIRS AND PUMP MOTOR REPAIRS**

Date Opened 8-9-2017 Date Finished 8-15-2017 Meter 1 Reading: 24,629

TASKS PERFORMED

Q PARTS

PONY PUMP MOTOR

1 9IP; 33031 FUEL FILTER MULE

Asset Work Order History J0578000

CSHOP-2017-6470

Date Opened 11-8-2017 Date Finished 11-28-2017 Meter 1 Reading: 25,470

TASKS PERFORMED

Q PARTS

PRE TRIP INSPECTION
HEADLIGHTS LOW BEAM

1 LMP; HALOGEN LAMP

CSHOP-2017-6863

Comments: **CHECK L/F AXLE SEAL LEAKING**

Date Opened 12-1-2017 Date Finished 3-29-2018 Meter 1 Reading: 25,994

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
STROBE LIGHTS
GRILLE

Service Requests:

03/01/2018 ACCIDENT / 12: BROKEN / INSPECT
THE FRONT GRILL ON SPARE BRUSH 74 HAS A SMALL AREA THAT BROKE OFF DURING TRAINING. NO FURTHER DAMAGE WAS NOTED.

03/27/2018 LIGHTS / 19: LOOSE / REPAIR
VEHICLE LIGHTS NOT WORKING-EMERGENCY LIGHTS ARE NOT WORKING. THE TOP EMERGENCY LIGHT WORK, BUT NOT THE OTHERS

CSHOP-2018-1637

Date Opened 3-21-2018 Date Finished 3-22-2018 Meter 1 Reading: 25,788

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
PONY PUMP MOTOR

Service Requests:

03/21/2018 SERVICE REQUEST / 11: BINDS/STICKS / ADJUST
THE PUMP ON THE BRUSH TRUCK WONT START. IT WAS USED YESTERDAY ON BRUSH FIRE. THIS MORNING IT STARTED FOR 2 MINUTES THEN SHUT OFF ON ITS OWN. WILL NOT START

CSHOP-2018-2429

Date Opened 5-3-2018 Date Finished 5-8-2018 Meter 1 Reading: 26,017

TASKS PERFORMED

Q PARTS

STROBE LIGHTS

1 9IP; NLA REPAIR ONLY POWER SUPPLY - WHELEN
1 9IP; NLA REPAIR ONLY POWER SUPPLY - WHELEN
-1 9IP; NLA REPAIR ONLY POWER SUPPLY - WHELEN
1 9IP; POWER SUPPLY REPAIRED

Asset Work Order History J0578000

CSHOP-2018-2501

Date Opened 5-7-2018 Date Finished 5-25-2018 Meter 1 Reading: 26,017

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER

Service Requests:

05/06/2018 ENGINE / 49: CAN NOT DUPLICATE CONCERN / INSPECT
ENGINE, TROUBLE RUNNING IN IDLE AND OIL LEAK

CSHOP-2018-3353

Date Opened 6-14-2018 Date Finished 6-25-2018 Meter 1 Reading: 26,017

TASKS PERFORMED

Q PARTS

BATTERY
TIRES ALL

2 1AD; BATTERY 31 SERIES

CSHOP-2018-3713

Date Opened 7-2-2018 Date Finished 7-2-2018 Meter 1 Reading: 25,393

THROTTLE NEEDS ADJUSTMENT

TASKS PERFORMED

NO PARTS USED

THROTTLE CONTROLS

CSHOP-2018-4085

Comments: SPARE BRUSH AT ST28

Date Opened 7-20-2018 Date Finished 7-30-2018 Meter 1 Reading: 26,017

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
PONY PUMP MOTOR
DISCHARGE GAUGE

2 5TN; 250400STUPEN

Service Requests:

07/20/2018 ENGINE / 12: BROKEN / EXCHANGE - NEW
ENGINE, PUMP MOTOR HARD TO START. PRESSURE GAUGE NOT WORKING.

Asset Work Order History J0578000

CSHOP-2018-4584

Date Opened 8-15-2018 Date Finished 8-23-2018 Meter 1 Reading: 25,420

TASKS PERFORMED

PM SERVICE B

Q PARTS

1 SME; FUEL FILTER
21 4PC; 15W40 PREMIUM BLUE OIL
1 FIL; NAPAGOLD FUEL FILTER
1 FIL; NAPAGOLD AIR FILTER
4 1AD; 30 SAE QT
1 FIL; NAPAGOLD FUEL FILTER
2 FIL; NAPAGOLD OIL FILTER
1 FIL; NAPAGOLD FUEL FILTER
1 FIL; NAPA BREATHER FILTER

CSHOP-2018-4610

Comments: **REPAIRS FROM PM**

Date Opened 8-16-2018 Date Finished 9-11-2018 Meter 1 Reading: 26,017

TASKS PERFORMED

CONTROL VALVE FIRE PUMP
FIRE PUMP
HOSE REEL
REPAIR FROM PM - TRANS/TRANSFER CASE
TRANSFER CASE
AXLE STUD
FRAME
CAB-INTERIOR ACCESSORIES

Q PARTS

1 VAL; 1QT HP GEAR OIL 75-90
5 9AP; BRAKE CLEAN
1 9HD; OIL SEAL
1 9HD; NUT
1 9HD; NUT
1 9HD; DISC WHEEL STUD

CSHOP-2018-5914

Date Opened 10-18-2018 Date Finished 10-19-2018 Meter 1 Reading: 25,438

TASKS PERFORMED

STARTER
BATTERY

Q PARTS

1 1AD; STARTER
2 1AD; BATTERY 31 SERIES

CSHOP-2018-6018

Comments: **FUEL**

Date Opened 10-22-2018 Date Finished 10-22-2018 Meter 1 Reading: 26,071

TASKS PERFORMED

FUEL SYSTEM

Q PARTS

1 BK; UNIVERSAL FUEL PUMP

Asset Work Order History J0578000

CSHOP-2018-6028

Date Opened 10-23-2018 Date Finished 10-24-2018 Meter 1 Reading: 26,071

TASKS PERFORMED

Q PARTS

FUEL PUMP

1 BK; UNIVERSAL FUEL PUMP

Service Requests:

10/23/2018 SERVICE REQUEST / 18: LEAKING / REPAIR
PUMP NOT WORKING

CSHOP-2018-6468

Comments: **PRE-TRIP**

Date Opened 11-14-2018 Date Finished 11-16-2018 Meter 1 Reading: 25,606

TASKS PERFORMED

NO PARTS USED

PRE TRIP INSPECTION

CSHOP-2018-7373

Date Opened 12-28-2018 Date Finished 1-3-2019 Meter 1 Reading: 26,071

TASKS PERFORMED

NO PARTS USED

ENGINE AND ACCESSORIES

Service Requests:

12/28/2018 ENGINE / 15: FOREIGN MATERIAL / CLEAN
PUMP NOT STARTING

CSHOP-2018-7394

Date Opened 12-30-2018 Date Finished 1-14-2019 Meter 1 Reading: 26,071

TASKS PERFORMED

NO PARTS USED

ENGINE AND ACCESSORIES

Service Requests:

12/30/2018 STARTER / 34: ROUGH / CLEANED
VEHICLE WILL NOT START SPARE BRUSH 48 WILL NOT START STATION 48

CSHOP-2019-1132

Date Opened 3-4-2019 Date Finished 3-12-2019 Meter 1 Reading: 25,849

TASKS PERFORMED

Q PARTS

FIRE PUMP PLUMBING
FIRE APPARATUS

1 9HY; HOSE AND FITTINGS

Service Requests:

03/01/2019 ENGINE / 18: LEAKING / REPAIR
WATER LEAKING FROM PUMP ON BRUSH 21 AT STATION 21

Asset Work Order History J0578000

CSHOP-2019-139

Date Opened 1-8-2019 Date Finished 1-11-2019 Meter 1 Reading: 26,071

TASKS PERFORMED

Q PARTS

CARBURETOR

1 FIL; NAPAGOLD FUEL FILTER
1 FIL; NAPAGOLD FUEL FILTER

Service Requests:

01/08/2019 SERVICE REQUEST / 15: FOREIGN MATERIAL / REPAIR
WATER PUMP WONT START

CSHOP-2019-1621

Date Opened 3-28-2019 Date Finished 7-29-2019 Meter 1 Reading: 26,029

TASKS PERFORMED

Q PARTS

PONY PUMP MOTOR
REAR AXLE
ALIGNMENT
U-BOLTS
FRONT SPRING
SUSPENSION
REPAIR FROM PM - PARKING BRAKE
AIR SYSTEM
AIR HORN

1 2IH; SCAMBRACKET
1 2IH; SLACKAJD
2 MBI; GRIP/KIT
1 2IH; CAMSHAFT
1 2IH; SCAM
2 TWD; BRAKE DRUM
2 2IH; CHAMBER
1 2IH; SCAMBRACKET
12 9AP; BRAKE CLEAN
1 9HY; FITTINGS 12
1 9HY; FITTINGS
1 MBI; DASH VAL
1 TWD; AIRHORN

CSHOP-2019-2006

Date Opened 4-17-2019 Date Finished 4-23-2019 Meter 1 Reading: 26,784

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
PRIMING PUMP FIRE PUMP

Service Requests:

04/17/2019 SERVICE REQUEST / 49: CAN NOT DUPLICATE CONCERN / INSPECT
PUMP DRAFT KNOB STUCK IN CLOSE POSITION. UNABLE TO PULL A DRAFT IF NEEDED. B/U BRUSH 74.

Asset Work Order History J0578000

CSHOP-2019-29

Comments: **B48**

Date Opened 1-2-2019

Date Finished 1-14-2019

Meter 1 Reading: 26,071

TASKS PERFORMED

NO PARTS USED

FIRE APPARATUS

Service Requests:

01/02/2019 SERVICE REQUEST / 18: LEAKING / REPAIR
TYPE PROBLEM INTO DESCRIPTION LEAKING WATER AT THE ELBOW ENTERING THE HOSE REEL

01/14/2019 SERVICE REQUEST / 18: LEAKING / REPAIR
WATER PUMP IN BACK NOT WORKING

CSHOP-2019-292

Date Opened 1-15-2019

Date Finished 1-16-2019

Meter 1 Reading: 25,688

TASKS PERFORMED

NO PARTS USED

ENGINE AND ACCESSORIES
LIGHTING SYSTEM

CSHOP-2019-3981

Date Opened 7-31-2019

Date Finished 8-5-2019

Meter 1 Reading: 26,045

TASKS PERFORMED

Q PARTS

QUALITY CHECK-REPAIRS
ENGINE AND ACCESSORIES
LIGHTING SYSTEM

1 LIT; DOMELAMP

CSHOP-2019-4460

Date Opened 8-22-2019

Date Finished 9-17-2019

Meter 1 Reading: 0

TASKS PERFORMED

Q PARTS

PONY PUMP MOTOR
OIL

6 NOL; NAPA HEAVY DUTY 30QT

Asset Work Order History J0578000

CSHOP-2019-5061

Date Opened 9-25-2019 Date Finished 10-2-2019 Meter 1 Reading: 26,150

TASKS PERFORMED

Q PARTS

PM SERVICE C

1 FIL; NAPAGOLD FUEL FILTER
30 4PC; 15W40 PREMIUM BLUE OIL
2 1AN; WIPER BLADE
1 9AP; KIT OIL STRAINER EMPI 730
1 FIL; NAPAGOLD AIR FILTER
1 FIL; NAPAGOLD FUEL FILTER
2 FIL; NAPAGOLD OIL FILTER
1 FIL; NAPA BREATHER FILTER
1 FIL; FIL
1 FIL; NAPAGOLD FUEL FILTER
1 FIL; NAPA BREATHER FILTER
1 NCB; PURPLE POWER 40 OZ
1 NOL; NAPA HEAVY DUTY 30QT
3 NOL; NAPA HEAVY DUTY 30QT

CSHOP-2019-5080

Date Opened 9-26-2019 Date Finished 6-22-2020 Meter 1 Reading: 26,784

TASKS PERFORMED

NO PARTS USED

REPAIR FROM PM - AIR SYSTEM
REPAIR FROM PM - DIFFERENTIALS
REPAIR FROM PM - CAB

CSHOP-2019-6705

Comments: **QC TRUCK FOR FRONT LINE USE**

Date Opened 12-30-2019 Date Finished 1-3-2020 Meter 1 Reading: 26,784

TASKS PERFORMED

Q PARTS

QUALITY CHECK-REPAIRS
FUEL SYSTEM
AIR DRIER

1 SF; MOTOR TUNE UP 16OZ
1 TWD; TWD
1 TWD; TWD
1 FIL; NAPAGOLD AIR FILTER

CSHOP-2019-752

Comments: **SPARE BRUSH AT STATION 21**

Date Opened 2-6-2019 Date Finished 2-20-2019 Meter 1 Reading: 26,784

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
HOSE REEL

1 9HY; 1" 90 FXF STEEL 4000 PSI SUPER SWL JT

Service Requests:

02/06/2019 SERVICE REQUEST / 18: LEAKING / EXCHANGE - NEW
HOSE REEL LEAKING AT CONNECTION. I HAVE VIDEO IF NEEDED TXT ME

Asset Work Order History J0578000

CSHOP-2020-3152

Date Opened 6-15-2020

Date Finished

7-14-2020

Meter 1 Reading:

26,784

TASKS PERFORMED

ENGINE AND ACCESSORIES
CHARGING SYSTEM
MIRRORS

Q PARTS

20 9HY; LINE CLAMP
1 BK; FUSE HOLDER
2 1AD; 1000 CCA 31 SERIES BATTERY
20 BK; HOSE CLAMP
1 9SM; GAS TANK 12 GALLON HI
1 FIL; NAPAGOLD FUEL FILTER
1 BK; CUBE FUEL PUMP
1 SME; GAS TNK 12 GALLON LOW
1 FIL; NAPAGOLD FUEL FILTER
1 BK; CLAMP
2 GRO; CONVEX MIRROR

Service Requests:

06/14/2020

ENGINE / 18: LEAKING / EXCHANGE - NEW
ENGINE BLOWN

CSHOP-2020-4699

Date Opened 9-9-2020

Date Finished

10-1-2020

Meter 1 Reading:

26,735

TASKS PERFORMED

PM SERVICE B

Q PARTS

1 FIL; NAPAGOLD FUEL FILTER
1 FIL; NAPA BREATHER FILTER
1 FIL; NAPAGOLDAIRFILTER
1 FIL; NAPAGOLD OIL FILTER
1 FIL; NAPAGOLD FUEL FILTER
1 FIL; NAPAGOLD OIL FILTER
4 NOL; NAPA HEAVY DUTY 30QT
1 FIL; NAPAGOLD FUEL FILTER
1 FIL; NAPA BREATHER FILTER
1 FIL; NAPAGOLD FUEL FILTER
21 4PC; 15W40 PREMIUM BLUE OIL

Asset Work Order History J0578000

CSHOP-2020-4812

Date Opened 9-14-2020

Date Finished

11-13-2020

Meter 1 Reading:

26,735

TASKS PERFORMED

Q PARTS

WATER TANK LEVEL LIGHTS	1	5EF; 4 LT GAUGE SENDER
PONY PUMP MOTOR	2	LMP; LAMP
PUMP	1	MMM; MARINE ADH SEAL WHITE
EXHAUST PIPE	1	FIL; NAPAGOLDAIRFILTER
COOLING SYSTEM	1	9HD; 4 CLAMP
TURN SIGNAL LIGHTS	3	BK; CLAMP
LIGHTING SYSTEM	1	EXH; EXH
BATTERY	11	EXH; EXH
CRANKING SYSTEM	1	EXH; EXH
TRANSFER CASE	2	EXH; EXH
FILTER	1	9IP; EXHAUST CLAMP 3 1 2
REAR ASSEMBLY	2	EXH; BAND CLAMP
FRONT ASSEMBLY	1	FIL; NAPA COOLANT FILTER
STEERING	1	5GI; 5GI
FRAME	1	GRO; GRO
BRAKES	2	6WL; LIGHT CLR LED PUMP PNL
REPAIR FROM PM - DECALS/CLEANLINESS	1	BAT; CORE DEPOSIT
	1	BAT; BATTERY
	1	FIL; NAPA HYDRAULIC FILTER
	15	9OC; BULK TRANS SYN
	12	4PC; 15W40 PREMIUM BLUE OIL
	1	FIL; NAPAGOLD OIL FILTER
	3	9OC; BULK TRANS SYN
	12	2IH; 2IH
	3	2IH; SUPPORT BRACKET TANK
	3	2IH; 2IH

CSHOP-2020-6684

Date Opened 12-22-2020

Date Finished

1-2-2021

Meter 1 Reading:

26,778

TASKS PERFORMED

NO PARTS USED

PM SERVICE C

CSHOP-2020-6688

Date Opened 12-22-2020

Date Finished

12-23-2020

Meter 1 Reading:

26,778

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
FUEL INJECTOR

CSHOP-2021-1016

Date Opened 2-23-2021

Date Finished

3-3-2021

Meter 1 Reading:

26,780

TASKS PERFORMED

Q PARTS

FIRE PUMP	2	BK; ELECTRIC FUEL PUMP
	2	BK; FUELPRESSREGULTR
	2	MAC; PREM START FL 11OZ

Asset Work Order History J0578000

CSHOP-2021-1662

Date Opened 3-29-2021 Date Finished 3-29-2021 Meter 1 Reading: 26,780

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
FUEL SYSTEM

Service Requests:

03/29/2021 FUEL / 11: BINDS/STICKS / REPAIR
BRUSH 27 ASSET J0578000 IS LEAKING FUEL

CSHOP-2021-608

Date Opened 2-3-2021 Date Finished 2-11-2021 Meter 1 Reading: 26,780

TASKS PERFORMED

Q PARTS

PONY PUMP MOTOR

1 9AP; REGULATOR IN LINE FUEL
1 9SM; CARB REBUILD KIT
3 CRC; CLEAN R CARB 20OZ

CSHOP-2021-7072

Comments: **INSPECT ONLY**

Date Opened 12-29-2021 Date Finished 12-29-2021 Meter 1 Reading: 26,854

TASKS PERFORMED

NO PARTS USED

INSPECTION

CSHOP-2021-7099

Date Opened 12-30-2021 Date Finished 3-21-2022 Meter 1 Reading: 26,855

TASKS PERFORMED

Q PARTS

PONY PUMP MOTOR
WIPERS-WASHER
OIL
BATTERY

1 9AP; BRACKET PIKE POLE
2 OWI; WIPER BLADE
1 BAT; CORE DEPOSIT
1 BAT; BATTERY
2 1AD; 1000 CCA 31 SERIES BATTERY

CSHOP-2022-2077

Date Opened 4-14-2022 Date Finished 4-26-2022 Meter 1 Reading: 26,855

TASKS PERFORMED

Q PARTS

QUALITY CHECK-REPAIRS
PRIMING PUMP FIRE PUMP
LIGHTING SYSTEM

2 NTH; ADAPTER
1 5TN; PRIMING PUMP AND MOTOR
1 FREIGHT
2 9IP; 97 BULB

Asset Work Order History J0578000

CSHOP-2022-2352

Date Opened 4-29-2022 Date Finished 5-2-2022 Meter 1 Reading: 26,855

TASKS PERFORMED

NO PARTS USED

QUALITY CHECK-REPAIRS

CSHOP-2022-5723

Comments: **TRUCK WON`T START**

Date Opened 10-24-2022 Date Finished 11-4-2022 Meter 1 Reading: 26,855

TASKS PERFORMED

NO PARTS USED

CRANKING SYSTEM

CSHOP-2022-6774

Date Opened 12-30-2022 Date Finished 1-6-2023 Meter 1 Reading: 26,855

TASKS PERFORMED

Q PARTS

BATTERY

1 BAT; BATTERY
1 BAT; CORE DEPOSIT

CSHOP-2023-288

Comments: **SB4 TANK LEAK**

Date Opened 1-19-2023 Date Finished 5-17-2023 Meter 1 Reading: 27,523

TASKS PERFORMED

NO PARTS USED

REPAIR FROM PM - FIRE PUMP SYS

Service Requests:

01/14/2023 BODY / 18: LEAKING / DEFERED
BRUSH TRUCK WATER TANK IS LEAKING OUT OF THE FRONT LEFT CORNER BEHIND THE CAB WHEN THE TANK IS ABOVE 3/4. LEAK IS A CONSTANT FLOW AND KEEPS THE TANK FROM STAYING FULL.

CSHOP-2023-3457

Comments: **B43 TAIL LIGHT ISSUE**

Date Opened 6-28-2023 Date Finished 7-20-2023 Meter 1 Reading: 27,532

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
STROBE LIGHTS

2 1WL; M9 LED FLASH RED W CLR LENS

Service Requests:

06/26/2023 BRAKES / 12: BROKEN / REPAIR
BRAKE LIGHT DRIVERS SIDE LENS IS DRIED OUT AND CRACKED NEEDING REPLACEMENT. RECOMMEND PASSENGER SIDE ALSO AS IT IS DRY AND FADED READY TO GO NEXT.

Asset Work Order History J0578000

CSHOP-2023-4793

Comments: **PUMP MOTOR**

Date Opened 9-13-2023

Date Finished 9-15-2023

Meter 1 Reading: 27,532

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
CRANKING SYSTEM

Service Requests:

09/12/2023 STARTER / 12: BROKEN / OVERHAUL
VEHICLE WILL NOT START/ dead battery

CSHOP-2023-5702

Comments: **PLUMBING VALVE**

Date Opened 11-6-2023

Date Finished 11-29-2023

Meter 1 Reading: 27,532

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
FIRE PUMP PLUMBING

1 5AB; FLANGE F2SS
1 5AB; 2 5 BALL KIT COMPOSITE

Service Requests:

11/03/2023 SERVICE REQUEST / 12: BROKEN / OVERHAUL
direct tank fill connection and valve fell apart. truck is located at station 43

CSHOP-2023-5873

Comments: **BRUSH TRUCK - SB4: BRAKE ISSUES**

Date Opened 11-17-2023

Date Finished 12-11-2023

Meter 1 Reading: 27,532

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
SERPENTINE BELT
BRAKES

1 NBH; FLEETRANNER BELT
1 NBH; V BELT
1 NBH; FLEETRANNER BELT
1 2IH; 50 50 COOLANT FLEETGUARD
2 1AD; ENGINE SEALANT
1 2BE; TF 501 AIR COMP
1 TWD; BENDIX D 2 GOV
1 2BE; CORE DEPOSIT

Service Requests:

11/17/2023 BRAKES / 12: BROKEN / OVERHAUL
BRAKE ISSUES, can not build up air pressure above 50. * Also the chain saw on this brush truck has no assest number, and it won't start. We trouble shot it and it is not getting any spark from plug wire. Thank you

CSHOP-2023-760

Date Opened 2-9-2023

Date Finished 2-9-2023

Meter 1 Reading: 26,971

TASKS PERFORMED

Q PARTS

INSPECTION

1 NOL; NAPA NON DETER 30 QT
1 2IH; 50 50 COOLANT FLEETGUARD

Asset Work Order History J0578000

CSHOP-2023-768

Comments: **LUBE OIL AND FILTERS FOLLOW UP REPAIRS**

Date Opened 2-9-2023

Date Finished 2-28-2023

Meter 1 Reading: 26,973

TASKS PERFORMED

Q PARTS

OIL

1 FIL; NAPAGOLD FUEL FILTER
15 4PC; 15W40 PREMIUM BLUE OIL
1 1FG; AIR FILTER S E
1 FIL; NAPA BREATHER FILTER
1 FIL; NAPAGOLD FUEL FILTER
1 FIL; NAPAGOLD FUEL FILTER
2 FIL; NAPAGOLD OIL FILTER
1 FIL; NAPAGOLD FUEL FILTER
1 FIL; NAPA HYDRAULIC FILTER

CSHOP-2024-1340

Date Opened 3-12-2024

Date Finished 5-17-2024

Meter 1 Reading: 27,532

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
PONY PUMP MOTOR
PRE TRIP INSPECTION

1 1AD; BATTERY GROUP 48
1 8AM; THUNDERMINGO 30 31 VW CARBURATOR
1 5AB; 2 BALL KIT COMPOSITE
1 8AM; SOLID STATE FUEL PUMP 1 2 PSI
3 FIL; NAPAGOLD FUEL FILTER

CSHOP-2024-4836

Date Opened 10-4-2024

Date Finished 10-9-2024

Meter 1 Reading: 27,532

TASKS PERFORMED

Q PARTS

QUALITY CHECK-REPAIRS
LIGHTING SYSTEM
CRANKING SYSTEM

1 LMP; LAMP, RO BPAK
2 1AD; 1000 CCA 31 SERIES BATTERY

CSHOP-2024-762

Date Opened 2-8-2024

Date Finished 2-8-2024

Meter 1 Reading: 27,402

TASKS PERFORMED

NO PARTS USED

INSPECTION

Asset Work Order History J0578000

RADIO-2018-611

Comments: **REMOVAL 10141464, INSTALL 10208468 INTO SPARE BRUSH 4**

Date Opened 6-8-2018

Date Finished

6-8-2018

Meter 1 Reading:

0

TASKS PERFORMED

NO PARTS USED

MOBILE RELATED

Service Requests:

06/06/2018

RADIO / /

REMOVE & INSTALL MOBILE RADIO IN SPARE BRUSH 4
