



10/17/2025

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## K10353

### 2500 CRASH FIRE RESCUE VEHICLE,

**Workorder: V670**

In Date: 11/21/2005  
Close Date: 12/19/2005

Meter Reading: 8,582.00

**Problem?**

B inspection Foam 81

**Task performed:**

See B Inspection pre-printed form

Parts	Quantity
78-72BATTERY GROUP 78	2
CA391446144 AIR FILTER WIX	1
L3546FFUEL FILTER 33376	2
PH5WIX 51060 L/F PH1218 OIL FILTER	1

**Workorder: V947**

In Date: 12/15/2005  
Close Date: 12/30/2005

Meter Reading:

**Problem?**

dead batteries Foam 81

**Task performed:**

Parts	Quantity
NO PARTS USED	

**Workorder: V1887**

In Date: 03/17/2006  
Close Date: 05/11/2006

Meter Reading:

**Problem?**

INSTALL NEW DRY CHEMICAL BOTTLES, SQ-81

**Task performed:**

Parts	Quantity
NO PARTS USED	

**Workorder: V2077**

In Date: 04/03/2006  
Close Date: 05/18/2006

Meter Reading:

**Problem?**

INSTALL NIDRTOGEN BOTTLES, SQ-81

**Task performed:**

Parts	Quantity
04765CLY ASSY 300CF NITROGEN	2
FREIGHTSHIPPING CHARGES	2



10/17/2025

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## K10353

### 2500 CRASH FIRE RESCUE VEHICLE,

**Workorder: V3069**

In Date: 06/21/2006  
Close Date: 06/29/2006

Meter Reading: 8,694.00

**Problem?**

a/c innoperative Foam 81

**Task performed:**

Parts	Quantity
L3546FFUEL FILTER 33376	1
K061010BELT	1
31-18WIPER BLADES	2
PH5WIX 51060 L/F PH1218 OIL FILTER	1

**Workorder: V3342**

In Date: 07/07/2006  
Close Date: 07/25/2006

Meter Reading:

**Problem?**

INSTALL HANDLIGHT AND CHARGER FOAM81

**Task performed:**

Parts	Quantity
NO PARTS USED	

**Workorder: V4097**

In Date: 08/24/2006  
Close Date: 08/28/2006

Meter Reading:

**Problem?**

Engine cuts off when idling.

**Task performed:**

Parts	Quantity
NO PARTS USED	



10/17/2025

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

K10353

2500 CRASH FIRE RESCUE VEHICLE,

**Workorder: V4355**

In Date: 09/10/2006

Meter Reading:

Close Date: 09/26/2006

**Problem?**

Switch for Hazard Lights does not push in to turn on. SQ81

**Task performed:**

1. TEST SWITCH FOUND TO BE O/S.
2. DISASSEMBLE DASH AND STERRING COLUMN SWITCH COVER UNABLE TO FIND ANYTHING JAMMING THE SWITCH. NEW SWITCH ORDERED.
- 3 SECURED HOTEL ROOM/ RESERVATIONS AND EVT TEST REGISTRATION FROM OCT. 23-27 EVT TRAINING SEMINAR.

Parts

Quantity

26100986COMBO SWITCH

1

**Workorder: V4571**

In Date: 09/24/2006

Meter Reading:

Close Date: 10/06/2006

**Problem?**

engine will not start. FOAM 81

**Task performed:**

1. TRUCK SLOW TO START. CHARGED BATTERIES, REMOVE CLEAN RECONNECT CABLES. NOW STARTS/ OPERATES CORRECTLY.

Parts

Quantity

NO PARTS USED

**Workorder: V4948**

In Date: 10/18/2006

Meter Reading:

Close Date: 10/23/2006

**Problem?**

REPLACE INJECTOR PUMP, SQ-81

**Task performed:**

1. SENT UNIT TO OUTSIDE AGENCY FOR R/R INJECTOR PUMP.

Parts

Quantity

NO PARTS USED



10/17/2025

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## K10353

### 2500 CRASH FIRE RESCUE VEHICLE,

**Workorder: V4674**

**In Date:** 10/02/2006

**Meter Reading:**

**Close Date:** 10/26/2006

**Problem?**

batteries seem to be losing charge, possible alternator. vehicle engine just cut off while running. FOAM 81

**Task performed:**

1. START VEH BATTS OK. RUNNING 1500 RPPM STUMBLED THEN INSTALLED 10 SEC. RESTARTED THEN SAME THING AGAIN, RESTARTED - DID NOT STALL THIS TIME. DRIVE VEH NO STALL HOOKED UP SNAP ON SCANNER NO CODES NO HX. NEEDS TO GO TO GMC.
2. CHECK VEH CHARGING SYSTEM 12.2V AT REST 13.6 RUNNING WITH LEAD APPLIED. CHARGING SYSTEM OK.
3. SERVICE DUAL AGENT REEL. LUBE ALL PILLAR BLOCK BEARINGS LUBE CHAIN & GEARS LUBE BOTH AGENT INLET SWIVEL JOINTS & ADJUST REEL BRAKE ASSY.
4. REMOVE GEAR EQUIPMENT FROM VEHICLE DRIVE VEH. TO GENERAL GMC FOR DIAGNOISIS AND OR REPAIR.

**Parts**

**Quantity**

NO PARTS USED

**Workorder: V5692**

**In Date:** 12/05/2006

**Meter Reading:**

**Close Date:** 12/13/2006

**Problem?**

WILL NOT START FOAM 81

**Task performed:**

1. Diagnose no start condition. disconnect all cables and test both batteries both ok. Reattach cables and rotate mating surfaces. Starts now. ordered new cable assy.for truck.
2. Replaced 2 neg. and 2 pos. batt. cables. R&R starter in order to replace pos. cable.

**Parts**

**Quantity**

12157422BATTERY CABLE GMC K-3500

1

12157330GMC K-3500

1

12157215GMC K-3500 BATTERY CABLE

1

12157098BATTERY CABLE GMC K-3500

1

**Workorder: V5855**

**In Date:** 12/18/2006

**Meter Reading:**

**Close Date:** 12/28/2006

**Problem?**

Lightbox Handlight not working... Charger does not appear to be working. SQ81

**Task performed:**

1. Found blown fuse replaced fuse ok. Will monitor. Fuse blew again. Rplced hand light assy. for new one from shop.

**Parts**

**Quantity**

NO PARTS USED



10/17/2025

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

K10353

2500 CRASH FIRE RESCUE VEHICLE,

**Workorder: V6473**

In Date: 01/25/2007

Meter Reading:

Close Date: 02/06/2007

**Problem?**

DEAD BATTERYS FOAM 81

**Task performed:**

Parts

Quantity

1. Radios killed battery also handlight had defective battery. R&R handlight charger and batteries road tested ok

NO PARTS USED

**Workorder: V7094**

In Date: 03/07/2007

Meter Reading:

Close Date: 03/29/2007

**Problem?**

B inspection and related repairs Foam81

**Task performed:**

Parts

Quantity

Change: air filter wix, fuel filter & oil filter

CA391446144 AIR FILTER WIX

1

L3546FFUEL FILTER 33376

1

PH5WIX 51060 L/F PH1218 OIL FILTER

1

**Workorder: V8731**

In Date: 06/12/2007

Meter Reading:

Close Date: 07/02/2007

**Problem?**

weld broken on airpack cabinet door. SQ-81

**Task performed:**

Parts

Quantity

Travel ST81 from CS  
Rem compt door; go to CS w/door; repair (3) broken welds; ret to ST81; reinstall door

NO PARTS USED



10/17/2025

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

K10353

2500 CRASH FIRE RESCUE VEHICLE,

### Workorder: V9104

In Date: 07/02/2007

Meter Reading:

Close Date: 07/09/2007

#### Problem?

ASSIST WITH REPLACEMENT OF NITROGEN ARMING SYSTEM, AFTER DISCHARGE OF DRY CHEMICAL SYSTEM FOAM

#### Task performed:

1. ARTER TESTING FOAM AND DRYCHEM ARMING AND DISCHARGE, REPLACE 2 NITROGEN BOTTLES AND 2 ANSUL ARMINGNITROGEN CYLINDERS. BLOWOUT DUAL AGENT REEL HOSES AND SET ALL VALVES FOR READY OPERATION.
2. R&R NITROGEN REGULATOR FOR FOAM SYSTEM. TEST AND ADJ. REGULATOR- NO GOOD.(BAD DIAPHRAGM)
3. LABELED ALL NITROGEN CYLINDERS IN STORAGE AREA AS "EMPTY" AND FOR HYDROSTAT TEST FOR PRAXAIR PICK UP.

#### Parts

#### Quantity

NO PARTS USED

### Workorder: V9257

In Date: 07/10/2007

Meter Reading:

Close Date: 07/27/2007

#### Problem?

FOAM 81 NEEDS SMALL FIRE EXTINGUISHER TO BE MOUNTED IN LEFT SIDE COMPARTMENT. FIRE EXTINGUISHER MOI IS PRESENTLY ON FLOOR BEHIND SEAT, FIRE EXTINGUISHER IS LOOSE IN LEFT SIDE COMPARTMENT.

#### Task performed:

- Drive to ST81 from C/S
- Drill holes/mount fire ext brkt and extinguisher

#### Parts

#### Quantity

ABM-1BASE MOUNT ALUMINUM

1

CYBS15165011USE UMVS111611 STRAP

1

### Workorder: V9343

In Date: 07/16/2007

Meter Reading:

Close Date: 07/27/2007

#### Problem?

replace nitrogen regulator foam 81

#### Task performed:

- R/R nitrogen reulator on AFFF system

#### Parts

#### Quantity

FREIGHTSHIPPING CHARGES

1

04652REGULATOR NI

1



10/17/2025

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## K10353

### 2500 CRASH FIRE RESCUE VEHICLE,

#### Workorder: V9452

In Date: 07/20/2007

Meter Reading:

Close Date: 08/16/2007

#### Problem?

a/c out foam 81

#### Task performed:

1. Short mtg @ CS; then on-call paperwork; drive to STN81 from CS
2. Chk veh A/C clutch & pulley; brng assy brkn; ordered new parts
3. Trvl frm CS to ST81; get foam 81; drive to CS for repairs; drive foam 81 back to ST81 frm CS after repairs
4. R/R A/C compressor, accumulator, orifice tube; flush sy; add system oil & recharge; R/R A/C fan belt

#### Parts

#### Quantity

K061010BELT	1
19169360COMPRESSOR AC	1
2724924ACCUMULATOR	1
3096068ORIFICE TUBE	1

#### Workorder: V10351

In Date: 09/10/2007

Meter Reading:

Close Date: 09/24/2007

#### Problem?

windshield washer fluid is not coming out of the wiper's. SQ81

#### Task performed:

1. Dia windshield washer sys - ordered parts
2. Get parts from Woodland; drive to St81 from CS
3. R/R btry, btry tray, siren, grill & parking lights in order to R/R/ washer reservoir; R/R/ pump at washer reservoir
4. R/R L/F headlight - discolored
5. Cln mechanis bay at station 81

#### Parts

#### Quantity

H6054USE CV TYPE SEALED BEAM	1
89001122WIPER PUMP MOTOR	1

#### Workorder: V10367

In Date: 09/11/2007

Meter Reading: 9,743.00

Close Date: 09/28/2007

#### Problem?

B INSPECTION AND REPAIRS AS NEEDED SQ81

#### Task performed:

1. "B" INSPECTION.
2. DRIVE VEHICLE TO CALLAGHAN TIRE FOR 4 NEW TIRES- DROP OFF VEHICLE.
3. DRIVE TO CALLAGHAN TIRE FROM STATION 81 PICK-UP VEHICLE AND RETURN TO STATION 81.

#### Parts

#### Quantity

PH5WIX 51060 L/F PH1218 OIL FILTER	1
L3546FFUEL FILTER 33376	1



10/17/2025

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

K10353

2500 CRASH FIRE RESCUE VEHICLE,

**Workorder: V6544**

In Date: 01/31/2007      Meter Reading:  
Close Date: 10/15/2007

**Problem?**

ignition switch detent inadequate SQ81

Task performed:	Parts	Quantity
FOUND NO & COULD NOT REPRODUCE PROBLEM, OPERATOR ERROR	NO PARTS USED	

**Workorder: V10628**

In Date: 09/24/2007      Meter Reading: 9,743.00  
Close Date: 10/23/2007

**Problem?**

replace 4 tires SQ81 (outside agency-callaghan tire)

Task performed:	Parts	Quantity
Replace (4) tires - Callaghan	NO PARTS USED	

Vendor?: CALLAGHAN

**Workorder: V13858**

In Date: 03/12/2008      Meter Reading:  
Close Date: 03/20/2008

**Problem?**

F81 has screw in rt front tire

Task performed:	Parts	Quantity
1 DRIVE TO STATION FROM CENTRAL SHOP 2 REMOVE SCREW FROM TIRE, SOAP TEST AREA AND NO LEAK FOUND.	NO PARTS USED	

**Workorder: V13979**

In Date: 03/19/2008      Meter Reading: 10,731.00  
Close Date: 03/20/2008

**Problem?**

foam tank pressurized foam 81

Task performed:	Parts	Quantity
1. Vent pressure from tank, check foam tank, check nitrogen valves for correct positions. Check nitrogen regulator. Found hand valve on nitrogen bottle not tightly closed and seeping into foam tank. Reset pressure indicator on tank cap.	NO PARTS USED	



10/17/2025

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## K10353

### 2500 CRASH FIRE RESCUE VEHICLE,

#### Workorder: V15188

In Date: 05/19/2008

Meter Reading:

Close Date: 06/10/2008

#### Problem?

Discharge rod for Dry Chemical Broke. foam 81

#### Task performed:

1. R/R drychem discharge valve-overhaul vave; rep bent u-joint coupling on valve rod; R/R split rollpin on rod to valve; R/R/ (2) nitrogen cyls; R/R/ (2) activation pistons to new nitrogen bottles.
2. R/R/ (2) ansul activation cartridges (1) in cab, (1) at discharge control panel. j

#### Parts

NO PARTS USED

#### Quantity

#### Workorder: V15254

In Date: 05/22/2008

Meter Reading: 10,731.00

Close Date: 07/07/2008

#### Problem?

B INSPECTION AND REPAIRS AS NEEDED FOAM 81

#### Task performed:

- B- Inspection
1. Change oil & all filters..
  2. Travel St81 from CS; travel to CS from St81.
  3. Svc transfer case; drain/change oil, etc.
  4. Svc front drive axle asy; change oil, etc. j
  5. Travel to St81 from CS; ret to CS w/foam for repairs; travel to ST81 w/foam.
  6. Svc rear drive axle asy; has no drain plug; R/R rear cover; cln/make gskt; change oil, etc.
  7. Leak test A/C sys; evac sys/vac; leak chk for 10 mins-ok; recharge sys.
  8. Drain coolant; R/R all eng coolant hoses; refill w/new coolant; road test/rechk coolant level; top off reservoir. j

#### Parts

- 15683910RAD HOSE 1
- 15977350RAD HOSE 1
- PH5WIX 51060 L/F PH1218 OIL FILTER 1
- 15W40BSYN OIL BULK QTS 12
- 19663COOLANT HOSE GMC TRUCK 1
- CA391446144 AIR FILTER WIX 1
- L3546FFUEL FILTER 33376 1
- 19672COOLANT HOSE GM 1
- 22210MOLDED COOLANT HOSE GM 1

#### Quantity

#### Workorder: V16766

In Date: 08/01/2008

Meter Reading:

Close Date: 08/05/2008

#### Problem?

change out nitrogen bottles SQ-81

#### Task performed:

1. Travel to St81 from CS. Travel to CS from ST81
2. Sys was "armed" at a emergcall; bleed nitrogen pressure off of AFFF tank & dry chem tank; R/R nitrogen bottles; R/R Ansul activation cyl; R/R Ansul sys charge cyl; reset red activated buttons on vessel caps. j

#### Parts

NO PARTS USED

#### Quantity



10/17/2025

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

K10353

2500 CRASH FIRE RESCUE VEHICLE,

### Workorder: V17370

In Date: 08/28/2008

Meter Reading:

Close Date: 09/08/2008

#### Problem?

f81 glass site -gauge is low on oil SQ 81

#### Task performed:

measure gauge. none in stock. ordered new one

#### Parts

#### Quantity

17631-899-000FUEL CAP GASKET

1

### Workorder: V17883

In Date: 09/23/2008

Meter Reading: 10,731.10

Close Date: 09/30/2008

#### Problem?

replace pressure gauge

#### Task performed:

R/R top pump panel cover; R/R dry chem discharge pressure gauge. j

#### Parts

#### Quantity

91525875CLASS ONE GAUGE 0-300 PSI

1

### Workorder: V18409

In Date: 10/18/2008

Meter Reading:

Close Date: 11/03/2008

#### Problem?

foam tank is pressurized, nitrogen bottle below 1750 sq 81

#### Task performed:

1. Travel to Stn81 from C/S; travel to C/S from ST81.
2. Bleed notrogen pressure off foam vessel; R/R nitrogen cyl & acivation control cyl. j

#### Parts

#### Quantity

NO PARTS USED

### Workorder: V18865

In Date: 11/05/2008

Meter Reading: 10,731.10

Close Date: 11/19/2008

#### Problem?

on call gas put in diesel tank

#### Task performed:

1. C/O to PBIA; drain tank in truck; put gas in diesel; drain about 30 gal.
2. Rem fuel from back of svc truck; pump out waste & clean unit. j

#### Parts

#### Quantity

NO PARTS USED



10/17/2025

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## K10353

### 2500 CRASH FIRE RESCUE VEHICLE,

**Workorder: V22207**

**In Date:** 03/30/2009  
**Close Date:** 04/29/2009

**Meter Reading:** 10,731.10

**Problem?**

B inspection (Foam81)

**Task performed:**

1. Travel to Stn81 from C/S; travel to C/S from ST81.
2. B-Inspection.
3. R/R lens; R/R (2) bulbs on 3rd brake lite.
4. Straighten plumbing on water/foam discharge valve; replc bent pipe nipple.
5. Get parts to do rep fnd on B-Inspection.
6. Travel to Stn81 from C/S; travel to C/S frm Stn81.
7. R/R (2) btrys; cln all connections.
8. R/R wiper blades. j

Parts	Quantity
L3546FFUEL FILTER 33376	1
PH5WIX 51060 L/F PH1218 OIL FILTER	1
15W40BSYN OIL BULK QTS	7
31-18WIPER BLADES	2
78-72BATTERY GROUP 78	2
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	2

**Workorder: V24311**

**In Date:** 06/24/2009  
**Close Date:** 07/06/2009

**Meter Reading:**

**Problem?**

FAN BELT BEARRING SQUEAKING. sq81

**Task performed:**

1. travel to Stn81 from C/S; travel to C/S from St81.
2. Run veh/listedn for hoise; mnone heard; belt leaks ok; rem belt/chk 10 lgs pulley bearings; W/P bearings & alt bearings ok; tensioner past limit arrows; will order new betl/tensioners.
3. Trave to Stn81 from C/S
4. R/R fan belt & fan belt; tensionner asy.

Parts	Quantity
K061010BELT	1
12561092BELT TENSIONER	1

**Workorder: V26734**

**In Date:** 10/07/2009  
**Close Date:** 10/22/2009

**Meter Reading:**

**Problem?**

AC IS NOT BLOWING COLD AIR... SQ81

**Task performed:**

Chk A/C sys discharge evacuate; recharge sys; leak test; no leak found.

Parts	Quantity
NO PARTS USED	



10/17/2025

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## K10353

### 2500 CRASH FIRE RESCUE VEHICLE,

#### Workorder: V28701

In Date: 12/30/2009

Meter Reading:

Close Date: 01/06/2010

#### Problem?

please check batteries and charging system sq 81

#### Task performed:

1. Travel to Stn81 from C/S; gtravel to C/S frm stn81.
2. Test both btrys; both failed test.
3. R/R (2) btrys & cln all connections; test alt output voltage - ok. j

#### Parts

#### Quantity

78-72BATTERY GROUP 78	2
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	2

#### Workorder: V28788

In Date: 01/04/2010

Meter Reading: 12,334.00

Close Date: 03/24/2010

#### Problem?

B inspection and repairs as needed sq 81

#### Task performed:

1. B-Inspection
2. Svc automatic trans; R/R pan & filter; refill trans.
3. Svc T-Case, drain & change oil, etc.
4. Adj all tire press.
5. Finish B-Inspection
6. Rem stabilizer links; new one wrng; reorder/reinstalled parts.
7. Drivers door hard to open/close; hinges nonadjustable striker nonadjustable; called parts to see if bushing/pin kit available for hinges.
8. R/R right/left stabilizer links.
9. Rem L/S cab door; R/R door hinge bushings/pins; cln/lube striker/latch.
10. R/R L/S inner tie rod end boot seal. j

#### Parts

#### Quantity

12546193LINK KITS GMC	2
88891731DOOR HINGE PIN GMC	4
25640501CLIP GMC	4
16632192DOOR BUSHING GMC	4
16632193DOOR PIN BUSHING	4
CA391446144 AIR FILTER WIX	1
K5252LINK KITS	2
ES2837RLINNER TIE ROD K10353	1

#### Workorder: V30311

In Date: 03/01/2010

Meter Reading: 12,334.00

Close Date: 03/24/2010

#### Problem?

AC1 BATTERY FOUND DEAD ON 2/28/10. KEY WAS NOT IN IGNITION. RECHARGED. TAC E81

#### Task performed:

1. No lights on load test; btry ok; chkd all wires at starter; all ok. j

#### Parts

#### Quantity

NO PARTS USED



10/17/2025

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## K10353

### 2500 CRASH FIRE RESCUE VEHICLE,

#### Workorder: V30307

In Date: 02/28/2010  
Close Date: 03/25/2010

Meter Reading: 12,334.00

#### Problem?

foam 81 emergency lights, siren, and airport radio not working. Sta81

#### Task performed:

Travel to Stn81; dia problem wires at relay under hood very hot; old style metal relay no longer available; cut all wires & install female spades & install Bosch style relay.  
j

#### Parts

87401RY-30T RELAY 5 PIN 12V

#### Quantity

1

#### Workorder: V32475

In Date: 05/27/2010  
Close Date: 06/08/2010

Meter Reading: 12,334.00

#### Problem?

f81 WILL NOT START. THANKS.

#### Task performed:

Veh btrys dead; hookup charger after charging; test btrys & charging sys; all ok. j

#### Parts

NO PARTS USED

#### Quantity

#### Workorder: V28381

In Date: 12/15/2009  
Close Date: 06/25/2010

Meter Reading: 10,731.10

#### Problem?

INSTALL TRANS FILTER PARTS ORDERED IN SQ 81

#### Task performed:

R/R trans pan; R/R filter; reill trans oil. j

#### Parts

8684221TRANS FILTER

#### Quantity

1

#### Workorder: V33470

In Date: 07/12/2010  
Close Date: 10/04/2010

Meter Reading: 12,334.00

#### Problem?

install a shore charging system on this vehicle to maintain a charge on the batteries, vehicle found dead again on thursday, happed on a regularly SQ81

#### Task performed:

1. Install on board btry charger & auto-eject asy on to veh.
2. Continue install above.
3. Finish install/test of on-bard charging sys, auto-eject, & btry monitor indicator. j

#### Parts

0913912CHARGER 2000

0915520120AUTO EJECT 20 AERO OTL3925

#### Quantity

1

1



10/17/2025

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## K10353

### 2500 CRASH FIRE RESCUE VEHICLE,

#### Workorder: V36359

In Date: 11/10/2010  
Close Date: 12/02/2010

Meter Reading: 12,334.00

#### Problem?

All Emergency lights not working sq 81

#### Task performed:

1. Dia why all emer lts out; fnd bad grnd under pass side floor mat; cln metal floor & term; install new screw to grnd.
  2. Rem non-working rear facing strobe lts; replc w/series 900 LED emer lts; drill/tap holes; mod opening in body & install lts.
  3. Run wiring frm switch panel in cab to L/R & R/R rear facing emer lts.
  4. Get parts-travel to Stn81; mk final elect connections at swth panel & emerg lts & test; secure wiring when done.
- j

#### Parts

#### Quantity

90R00FRR900 SERIES LED W/O FLANGE - RED	2
9ECAPR9ECAPR END CAP RED	1

#### Workorder: V36596

In Date: 11/21/2010  
Close Date: 12/22/2010

Meter Reading: 13,298.10

#### Problem?

Vehicle stalling at idle or while driving. Sta 81

#### Task performed:

- (1) TRAVELED TO ST81 FOR VEHICLE STALLING. CHECK ENGINE WIRING, FUEL SYSTEM CONNECTIONS, ELECTRIC LIFT PUMP ECT. R&R FUEL FILTER & CHECK FILTER HOUSING FOR CONTAMINATION. TEST DROVE VEHICLE. NO STALLING YET. J.W.

#### Parts

#### Quantity

L3546FFUEL FILTER 33376	1
-------------------------	---

#### Workorder: V36629

In Date: 11/23/2010  
Close Date: 12/22/2010

Meter Reading: 13,387.70

#### Problem?

VEHICAL STALLS OUT WHILE DRIVING.

#### Task performed:

#### Parts

#### Quantity

NO PARTS USED



10/17/2025

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## K10353

### 2500 CRASH FIRE RESCUE VEHICLE,

**Workorder: V37202**

In Date: 12/16/2010      Meter Reading: 13,491.00  
Close Date: 01/10/2011

**Problem?**

B inspection and repairs(outside agency- General GMC)

**Task performed:**

Completed by General GMC.      j

Parts

Quantity

NO PARTS USED

**Workorder: V37163**

In Date: 12/15/2010      Meter Reading: 13,451.00  
Close Date: 01/19/2011

**Problem?**

VEHICAL STALLS OUT WHILE DRIVING.(outside agency- General GMC)

**Task performed:**

Veh stalls out while driving - General GMC      j

Parts

Quantity

NO PARTS USED

**Vendor?:** GENERAL GMC

**Workorder: V38313**

In Date: 02/07/2011      Meter Reading: 13,491.00  
Close Date: 02/14/2011

**Problem?**

r headlight out foam 81

**Task performed:**

R/R R/F headlight sealed beam.      j

Parts

Quantity

H6054USE CV TYPE SEALED BEAM

1

**Workorder: V38330**

In Date: 02/07/2011      Meter Reading: 13,491.00  
Close Date: 03/02/2011

**Problem?**

Foam 81 A/C blowing warm

**Task performed:**

Travel to Stn81, chk A/C sys; needs to go to shop; drive veh to C/S - leak test sys; discharge sys; R/R schrader valves; evac/recharge sys; drive veh back to Stn81.      j

Parts

Quantity

16-31438915 VALVE CORE A/C 3544706C1

1

31-18WIPER BLADES

2



10/17/2025

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

K10353

2500 CRASH FIRE RESCUE VEHICLE,

**Workorder: V41514**

In Date: 06/21/2011  
Close Date: 07/01/2011

Meter Reading: 13,793.50

**Problem?**

LEFT REAR BRAKE LIGHT IS OUT. foam 81

**Task performed:**

R&R tail light assy  
R&R bulb section  
sockets good lens assy no good  
mounting flanges broke off when removing screws  
ordered all new tape lens assy to veh temporary ak

Parts

Quantity

5977867TAIL LIGHT ASS L/H

1

R&R l/s tail light assy ak

**Workorder: V41610**

In Date: 06/26/2011  
Close Date: 07/11/2011

Meter Reading: 13,793.50

**Problem?**

Emergency light is out. Located on metal cabinet driver side. The is on the rear of box. FOAM 81

**Task performed:**

1. Chkd L/S rear emer light; works? chk wiring - ok; tried sev times - NPF.  
2. lube drivers door hinges & holdopen; adj door striker bolt. j

Parts

Quantity

NO PARTS USED

**Workorder: V43926**

In Date: 09/26/2011  
Close Date: 10/17/2011

Meter Reading: 2,255.30

**Problem?**

Dragon 1 windshield wiper is broke, Sta 81.

**Task performed:**

1. Dia wiper sys; adj/tighten wiper thrushaft; realign wiper arms; realign wiper blades & test opn.  
2. Assist in dia wipers inop. j

Parts

Quantity

NO PARTS USED



10/17/2025

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## K10353

### 2500 CRASH FIRE RESCUE VEHICLE,

**Workorder: V44324**

**In Date:** 10/12/2011  
**Close Date:** 10/25/2011

**Meter Reading:** 14,342.00

**Problem?**

C Inspection - SQ81

**Task performed:**

1. C-Inspection - Foam 81; travel to Stn81.
2. Svc dual agent hose reel.
3. Svc T-case on veh; change oil, etc.
4. r/R wiper blades.
5. Adj tire pressures.
6. Cln/lube pass door hinges/holdopen.
7. Chk opn/movement of all valves on wtr/foam sys; chk opn/movement of all valves on drychem sys.
8. R/R drychem vessel cap/gskt & power condition.
9. Inspect wtr tank cap/gskt; chk visually inside of tank.
10. R/R radiator cap. j

Parts	Quantity
91-18WIPER BLADE	2
CA391446144 AIR FILTER WIX	1
L3546FFUEL FILTER 33376	1
PH5WIX 51060 L/F PH1218 OIL FILTER	1
10409635RAD CAP	1

**Workorder: V44373**

**In Date:** 10/13/2011  
**Close Date:** 11/01/2011

**Meter Reading:** 2,255.30

**Problem?**

REPLACE TIRES CALLAGHAN

**Task performed:**

Replace tires - Callaghan j

Parts	Quantity
NO PARTS USED	

**Vendor?:** CALLAGHAN

**Workorder: V44374**

**In Date:** 10/13/2011  
**Close Date:** 11/01/2011

**Meter Reading:** 2,255.30

**Problem?**

ALIGNMENT CALLAGHAN

**Task performed:**

Alignment - Callaghan j

Parts	Quantity
NO PARTS USED	

**Vendor?:** CALLAGHAN



10/17/2025

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## K10353

### 2500 CRASH FIRE RESCUE VEHICLE,

**Workorder: V45145**

In Date: 11/14/2011  
Close Date: 11/28/2011

Meter Reading: 14,492.80

**Problem?**

Replace grille

**Task performed:**

R&R GRILLE TRANSFER REFLECTORS, EMBLEMS,  
AND PLASTIC NUTS TO NEW

Parts

15986073GRILLE

Quantity

1

**Workorder: V45996**

In Date: 12/21/2011  
Close Date: 01/04/2012

Meter Reading: 14,842.10

**Problem?**

Bbelt making alot of noise. Engine just not running right. Back up vehicle. Sta 81

**Task performed:**

WENT TO STA 81 - CHECK BELT - R&R BELT - RAN  
AND CHECK - OK.

Parts

K061010BELT

Quantity

1

STARTED AND RAN ENGINE - CHECK FOR FUEL  
LEAKS AND AIR IN FUEL SYSTEM - CHECK OK AND  
ENGIN RUNS GREAT - WENT TO P.B. ST. 3.

**Workorder: V50502**

In Date: 06/29/2012  
Close Date: 07/26/2012

Meter Reading: 2,324.80

**Problem?**

F81 A/C NOT BLOWING COLD.

**Task performed:**

F81 A/C NOT BLOWING COLD.

Parts

NO PARTS USED

Quantity

Vendor?: ROGER DEAN CHEVROLE

**Workorder: V51843**

In Date: 08/23/2012  
Close Date: 09/07/2012

Meter Reading:

**Problem?**

Strobe lights on light bar 10-7.

**Task performed:**

CHECKED OIL

Parts

NO PARTS USED

Quantity



10/17/2025

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## K10353

### 2500 CRASH FIRE RESCUE VEHICLE,

#### Workorder: V52372

In Date: 09/13/2012

Meter Reading:

Close Date: 09/19/2012

#### Problem?

Battery light on dash is on and battery guage shows low level.

#### Task performed:

BATT LIGHT ON DASH IS OUT 1 BATT SHORTED AND ALTERNATOR DEFECTIVE TRAVEL BACK TO SHOP BATTERIES ON SERVICE TRUCK NO GOOD INSTALLED NEW BATT AND RECHARGE TEST OK.

#### Parts

#### Quantity

1713682GAUGE FLUID

1

78-72BATTERY GROUP 78

2

BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY

2

#### Workorder: V52533

In Date: 09/20/2012

Meter Reading:

Close Date: 09/24/2012

#### Problem?

Grong radio INOP. Wouldn't take on COMM work request. Please forward to radio shop Radio asset #G3781

#### Task performed:

FORWARDED ONTO RADIO SHOP- REQUEST V000440.

#### Parts

#### Quantity

NO PARTS USED

#### Workorder: V52827

In Date: 10/03/2012

Meter Reading: 15,238.00

Close Date: 10/04/2012

#### Problem?

siren inop

#### Task performed:

SIREN INOP / LOOSE POWER CONNECTION/REPAIRED POWER CONNECTION TEST OK.

#### Parts

#### Quantity

NO PARTS USED

#### Workorder: V51844

In Date: 08/23/2012

Meter Reading: 2,324.80

Close Date: 10/05/2012

#### Problem?

AFFF tank pressure guage leaking oil.

#### Task performed:

REMOVED OLD GAUGE AND INSTALLED NEW ONE.

#### Parts

#### Quantity

91523933 GAUGE VAC/PRESS.

1



10/17/2025

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

K10353

2500 CRASH FIRE RESCUE VEHICLE,

**Workorder: V50289**

In Date: 06/21/2012      Meter Reading: 15,150.00  
Close Date: 11/06/2012

**Problem?**

B INSPECTION OIL CHANGE SERVICES

**Task performed:**

B inspection oil change services

Parts

NO PARTS USED

Quantity

Vendor?: OIL CHANGE SERVICES

**Workorder: V53799**

In Date: 11/15/2012      Meter Reading:  
Close Date: 11/19/2012

**Problem?**

The hose reel auto rewind not working and the A/C not working.

**Task performed:**

HOSE REEL REWIND INOP, VOLTAGE DROP TO SOLENOID CLEARED AND TIGHTENED ALL ELECTRICAL CONNECTIONS FOR REEL REWIND ALSO LUBED REWIND ASSY.

Parts

NO PARTS USED

Quantity

**Workorder: V54672**

In Date: 12/27/2012      Meter Reading:  
Close Date: 02/01/2013

**Problem?**

Box light charger will not charge. It's probably the charger because the light works on other chargers.

**Task performed:**

TRACED WIRE TO BAD CONNECTION IN ENGINE COMPARTMENT REPIARED TESTED OK.

Parts

NO PARTS USED

Quantity

**Workorder: V55981**

In Date: 02/24/2013      Meter Reading: 15,461.80  
Close Date: 04/09/2013

**Problem?**

a/c switch will only work on high.

**Task performed:**

1. CHECK OUT A/C ORDER RESISTOR BLOCK.  
2. TRAVEL TOST 81 R&R BLOWER RESISTOR ON UNIT HAD TO LOOSEN DASH TO FIT NEW BLOCK IN DASH AND REMOVE BKTS AND HARNESS TEST OK.

Parts

1539098RESISTOR BLOWER MOTOR

Quantity

1



10/17/2025

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## K10353

### 2500 CRASH FIRE RESCUE VEHICLE,

#### Workorder: V56550

In Date: 03/21/2013  
Close Date: 04/09/2013

Meter Reading: 15,461.80

#### Problem?

Hood Release hatch is not attached secured to sidewall in drivers cab. Hanging loose. Sq-81

#### Task performed:

TRAVEL TO ST 81 R&R HOOD RELEASE IN CAB TEST OK.

#### Parts

15741109HANDLE HOOD RELEASE

#### Quantity

1

#### Workorder: V57273

In Date: 04/25/2013  
Close Date: 04/30/2013

Meter Reading:

#### Problem?

FOAM 81 LEFT REAR SIGNAL LIGHT NOT WORKING.

#### Task performed:

CHECK OUT LIGHTS R&R BULB REPAIR PLUG ON LIGHT CONNECTIONS.

#### Parts

NO PARTS USED

#### Quantity

#### Workorder: V57504

In Date: 05/06/2013  
Close Date: 05/07/2013

Meter Reading: 15,609.70

#### Problem?

Light bar inop Foam truck

#### Task performed:

TRAVEL TO 81 LT BAR POWER SUPPLY.

#### Parts

SL6POWER SUPPLY - WHELEN LIGHT BAR

#### Quantity

1

#### Workorder: V57625

In Date: 05/09/2013  
Close Date: 05/21/2013

Meter Reading:

#### Problem?

Shoreline charging system appears to be inoperable. receptical has power and ground fault is not tripped, but charger does not lig up. Also need a new extension cord because its protective covering has been compromised

#### Task performed:

TRAVEL TO ST 81 CHECK OUT POWER CABLE CUT OUT BAD SPOT ON CABLE REWIRE FILL. CORD PLUG AND RETEST UNIT REPAIR BAD WIRES AND CHARGER OK.

#### Parts

KIT15625P MAXEL SET  
15016KIT15016 PIN KIT

#### Quantity

1

2



10/17/2025

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

K10353

2500 CRASH FIRE RESCUE VEHICLE,

**Workorder: V58534**

In Date: 06/18/2013      Meter Reading: 16,213.00  
Close Date: 06/24/2013

**Problem?**  
AIRCONDITIONING WEAK SQ81

Task performed:	Parts	Quantity
TRAVEL TO ST 81 CHECK OUT A/C ADD FREON CHECK FOR LEAKS NONE FOUND OK.	NO PARTS USED	

**Workorder: V60915**

In Date: 10/01/2013      Meter Reading:  
Close Date: 10/10/2013

**Problem?**  
don't think alternator is operating correctly....put it on tesert and seems to be charging below 14 volts sq 81

Task performed:	Parts	Quantity
1. TESTED ALTERNATOR. 2. TESTED ALTERNATOR.	NO PARTS USED	

**Workorder: V61100**

In Date: 10/07/2013      Meter Reading: 16,213.00  
Close Date: 10/15/2013

**Problem?**  
Foam 81 microphone

Task performed:	Parts	Quantity
WENT TO AIRPORT WHEN WE GET THERE I INSTALLED MICROPHONE IN FOAM 81.	NO PARTS USED	

**Workorder: V61252**

In Date: 10/14/2013      Meter Reading: 16,553.80  
Close Date: 10/23/2013

**Problem?**  
battery terminal loose and one battery bolt stripped out. handlight inop.

Task performed:	Parts	Quantity
REPLACE NEGATIVE BATTERY POST WITH A LONGER BOLT FOR CHARGING PURPOSE.	NO PARTS USED	



10/17/2025

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

K10353

2500 CRASH FIRE RESCUE VEHICLE,

**Workorder: V61748**

In Date: 11/04/2013  
Close Date: 11/04/2013

Meter Reading: 16,714.00

**Problem?**

B-inspection

**Task performed:**

B-inspection  
Replaced master cyl, front calipers and pads  
Replaced rear brakes and cylinders  
Flush and bleed all lines

Vendor?: ROGER DEAN

Parts

Quantity

NO PARTS USED

**Workorder: V62165**

In Date: 11/21/2013  
Close Date: 11/26/2013

Meter Reading:

**Problem?**

Left brake light is out.

**Task performed:**

R&R BULB ON LEFT BRAKE LIGHT AND WENT BACK TO SHOP.

Parts

Quantity

NO PARTS USED

**Workorder: V61422**

In Date: 10/21/2013  
Close Date: 12/12/2013

Meter Reading:

**Problem?**

DRIVER SIDE BATTERY NEGATIVE TERMINAL POST NOT LONG ENOUGH OR STRIPPED INSIDE BATTERY , CANNOT TIGHTEN.

**Task performed:**

CREW BROUGHT TO SHOP CLEANED AND TIGHTENED BATTERY CABLE.

Parts

Quantity

NO PARTS USED

**Workorder: V62610**

In Date: 12/09/2013  
Close Date: 12/18/2013

Meter Reading:

**Problem?**

needs new wiper blades.....starting to split in two.

**Task performed:**

R&R WIPER BLADES THAT WERE BAD.

Parts

Quantity

31-18WIPER BLADES

2



10/17/2025

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### K10353

### 2500 CRASH FIRE RESCUE VEHICLE,

#### Workorder: V60274

In Date: 09/04/2013  
Close Date: 04/18/2014

Meter Reading: 16,213.00

#### Problem?

C inspection

#### Task performed:

C inspection

#### Parts

#### Quantity

33243FUEL FILTER WPB	1
49883AIR FILTER WPB 7C3Z9601A	1
51372OIL FILTER PH2	1
AU2Z8A616LFAN CLUTCH	1

#### Workorder: V69275

In Date: 09/10/2014  
Close Date: 09/16/2014

Meter Reading: 18,137.60

#### Problem?

AC system low on freon. Not blowing cold air.

#### Task performed:

Charged A/C system.

#### Parts

#### Quantity

NO PARTS USED

#### Workorder: V70208

In Date: 10/16/2014  
Close Date: 11/04/2014

Meter Reading: 18,733.00

#### Problem?

shore charger inop

#### Task performed:

Test system for operation  
Found it's working on a single battery outlet, amp outlets  
to make indicator show 2 batteries charging.  
Retest system for operation its's good.

#### Parts

#### Quantity

NO PARTS USED



10/17/2025

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

K10353

2500 CRASH FIRE RESCUE VEHICLE,

**Workorder: V71088**

In Date: 11/20/2014

Meter Reading:

Close Date: 12/15/2014

**Problem?**

passenger side compartment latch broken. It will close but not lock. The vehicle vibration will open door.

**Task performed:**

Parts

Quantity

1. Fabbbed stop for latch and installed it
2. Found tire on trailer low jack up trailer and remove tire spay with soapy water found tire leaking around rim called Steve.R. Elpex couldn't get to airport so i took tire to Elpex they fized it and i went back to airport and installed it.

NO PARTS USED

**Workorder: V71581**

In Date: 12/11/2014

Meter Reading: 18,992.00

Close Date: 12/15/2014

**Problem?**

Battery dead/ INOP. Vehicle O/S battery dead/ will not hold a charge even after being placed on the charger.

**Task performed:**

Parts

Quantity

Went to airport-check volt found 12.8V started track alter. Charging 14.3v-check shore charger it was keeping battery at 12. 80v under plug charge battery went to 11.3v and R/R battery.

78-72BATTERY GROUP 78

2

BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY

2

**Workorder: V69581**

In Date: 09/22/2014

Meter Reading:

Close Date: 12/23/2014

**Problem?**

Driver side brake light works intermittently.

**Task performed:**

Parts

Quantity

Replaced left tail light bulb on w/o #69814.

NO PARTS USED



10/17/2025

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

K10353

2500 CRASH FIRE RESCUE VEHICLE,

**Workorder: V71881**

In Date: 12/27/2014

Meter Reading:

Close Date: 01/05/2015

**Problem?**

shore line not charging. a/c not blowing cold. FOAM 81

**Task performed:**

Parts

Quantity

1. Check out AC add freon-check for leaks will have to go to shop
2. Check out batteries and truck Alt ok-check out 110v charger ok 13.4v

NO PARTS USED

**Workorder: V71982**

In Date: 01/01/2015

Meter Reading: 19,148.00

Close Date: 01/07/2015

**Problem?**

added 1 qt. of oil still needs 1 qt. no more in station.

**Task performed:**

Parts

Quantity

- Check with parts got a case of oil to leave at airport-found e-1 send the wrong joystick and got parts for airport and went to airport

NO PARTS USED

**Workorder: V71850**

In Date: 12/24/2014

Meter Reading: 18,992.00

Close Date: 01/08/2015

**Problem?**

A/C not working

**Task performed:**

Parts

Quantity

1. Check AC system possible leak around compressor charged system
2. Assist with above

NO PARTS USED

**Workorder: V72075**

In Date: 01/05/2015

Meter Reading: 19,148.20

Close Date: 01/08/2015

**Problem?**

batteries dead

**Task performed:**

Parts

Quantity

1. Check batteries and charging system-found charger wired wrong. Corrected checked ok installed new batteries-check for parsite load.
2. Assist with above

BATTERY EPA TAX BATTERY EPA TAX \$1.50 PER BATTERY

2

65-72BXT65750 BATTERY

1

78-72BATTERY GROUP 78

1



10/17/2025

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

K10353

**2500 CRASH FIRE RESCUE VEHICLE,**

**Workorder: V69814**

In Date: 10/01/2014  
Close Date: 01/15/2015

Meter Reading: 18,733.00

**Problem?**

Replace lecft tail light bulb.

**Task performed:**

1. Replace tail light bulb and repair contact on harness.  
Test for operation it is good now.
2. Drive back to shop.

Parts

Quantity

NO PARTS USED

**Workorder: V74708**

In Date: 04/16/2015  
Close Date: 04/16/2015

Meter Reading:

**Problem?**

Veheical will not start. Dead battery.

**Task performed:**

work order in asset works

Parts

Quantity

NO PARTS USED

**Workorder: V73805**

In Date: 03/11/2015  
Close Date: 06/30/2015

Meter Reading:

**Problem?**

A/C inop

**Task performed:**

Parts

Quantity

NO PARTS USED



# Palm Beach County Fire Rescue Fleet Maintenance Asset History

Asset: (K10353) 1996 - GMC 2500 Crash Fire Rescue Vehicle

**K10353**

**CSHOP-2015-1093**

Comments: **SHORELINE CHARGER NOT WORKING CHECK FOR ELECTRIC DRAW CHECK ALTERNATOR AC NOT COOLING  
K10353 FOAM 81 NEEDS TO COME IN FOR SERVICE WILL PULL WHEN WE GET MINI PUMPER BACK**

Date Opened 6-9-2015 Date Finished 6-12-2015 Meter 1 Reading: 14,936

**TASKS PERFORMED**

**Q PARTS**

TRAVEL TO BE CHARGED TO WORK ORDER  
ELECTRICAL

2 BATTERY; BATTERY GROUP 78  
1 PLUG; HBL5366C 20AMP PLUG  
2 BATTERY; BATTERY EPA TAX \$1.50 PER BATTERY

**CSHOP-2015-1417**

Comments: **FOAM TRUCK WORK ORDER**

Date Opened 6-26-2015 Date Finished 6-26-2015 Meter 1 Reading: 14,940

**TASKS PERFORMED**

**Q PARTS**

ELECTRICAL

1 CHARGER; CHARGER 2000

**CSHOP-2015-1760**

Comments: **CHARGE BATTERIES FOUNT BATTERIES ARE NOT GOOD NEEDS NEW ONES ON ORDER**

Date Opened 7-15-2015 Date Finished 7-23-2015 Meter 1 Reading: 14,940

**TASKS PERFORMED**

**Q PARTS**

BATTERY

2 BATTERY; BATTERY GROUP 78  
2 BATTERY; BATTERY EPA TAX \$1.50 PER BATTERY

**CSHOP-2015-2032**

Comments: **AC NOT COLD K10353 DRIVERS DOOR HANDLE ABOUT TO FALL APART / CHECK AC FOUND WAS LOW ON  
FREON CHARGE SYSTEM TEST FOR OPERATION IS OK NOW /DOOR HANDLE IN ORDER**

Date Opened 7-30-2015 Date Finished 9-1-2015 Meter 1 Reading: 14,940

**TASKS PERFORMED**

**Q PARTS**

DOOR HANDLES INSIDE-OUTSIDE  
A/C LOW FREON

1 HANDLE; HANDLE

**CSHOP-2015-3071**

Comments: **REPLACE TIRES**

Date Opened 9-24-2015 Date Finished 9-28-2015 Meter 1 Reading: 20,228

**TASKS PERFORMED**

**NO PARTS USED**

TIRES ALL

**VENDOR?** ELPEX TIRE TIRESOLES

**Asset Work Order History K10353**

**CSHOP-2015-3115**

Comments: **B INSPECTION ROTATE TIRES REPAIR A/C**

Date Opened 9-28-2015 Date Finished 9-28-2015 Meter 1 Reading: 20,028

**TASKS PERFORMED**

**NO PARTS USED**

PM SERVICE B LIGHT

**VENDOR?** AL PACKER

---

**CSHOP-2015-623**

Comments: **K10353 GMC 2500 AIR CONDITIONING BLOWING WARM AIR.**

Date Opened 5-13-2015 Date Finished 5-14-2015 Meter 1 Reading: 14,936

AC NOT BLOWING COLD

**TASKS PERFORMED**

**NO PARTS USED**

A/C BLOWER OPERATES  
HVAC SYSTEM

---

**CSHOP-2015-95**

Date Opened 4-16-2015 Date Finished 4-20-2015 Meter 1 Reading: 14,925

**TASKS PERFORMED**

**NO PARTS USED**

TRAVEL TO BE CHARGED TO WORK ORDER  
ELECTRICAL

---

**CSHOP-2016-1795**

Comments: **AIRPORT FOAM 81**

Date Opened 4-15-2016 Date Finished 5-9-2016 Meter 1 Reading: 20,858

**TASKS PERFORMED**

**NO PARTS USED**

FUEL PUMP  
HOSES-LINES & FITTINGS

**VENDOR?** AL PACKER

**Service Requests:**

04/15/2016 FUEL SYSTEM / 18: LEAKING / SENT TO DEALER FOR REPAIRS.  
LEAKING DIESEL FLUID AND OIL.

---

**CSHOP-2016-2193**

Comments: **AL PACKER PREFORMED B INSPECTION AND REPAIRED FUEL INJECTOR PUMP.**

Date Opened 5-5-2016 Date Finished 5-5-2016 Meter 1 Reading: 20,858

**TASKS PERFORMED**

**NO PARTS USED**

PM SERVICE B LIGHT

**VENDOR?** AL PACKER

---

**Asset Work Order History K10353**

**CSHOP-2016-279**

Date Opened 1-21-2016 Date Finished 3-1-2016 Meter 1 Reading: 20,750

**TASKS PERFORMED**

**Q PARTS**

DOOR HANDLES INSIDE-OUTSIDE

1 NEWPART; DOOR HANDLE INNER

**Service Requests:**

01/20/2016 DOOR / 14: CRACKED / R&I LEFT DOOR TRIM PANEL AND REPLACED INSIDE DOOR HANDLE. FOAM 81 DOOR HANDLE ON THE INSIDE BROKE. DOOR CAN ONLY BE OPEN FROM THE OUTSIDE.

02/04/2016 DOOR / 14: CRACKED / EXCHANGE - NEW  
DRIVERS SIDE INSIDE DOOR HANDLE BROKEN

**CSHOP-2016-3509**

Comments: **SENT TO PACKER**

Date Opened 7-22-2016 Date Finished 7-28-2016 Meter 1 Reading: 21,432

**TASKS PERFORMED**

**NO PARTS USED**

POWER STEERING PUMP

**VENDOR?** AL PACKER

**Service Requests:**

07/21/2016 STEERING / 12: BROKEN / EXCHANGE - NEW  
POSSIBLE POWER STEERING MOTOR ISSUE. VIBRATION WHEN DRIVING

**CSHOP-2016-3606**

Date Opened 7-28-2016 Date Finished 9-23-2016 Meter 1 Reading: 21,793

**TASKS PERFORMED**

**NO PARTS USED**

TRAVEL TO BE CHARGED TO WORK ORDER  
CRANKING SYSTEM

**Service Requests:**

07/27/2016 ENGINE / 12: BROKEN / ALSO, INTERMITTENTLY, WHEN HOT, TRUCK WILL CRANK AND NOT STAI  
IGNITION TURN TABS ARE BROKEN OFF. KEY WILL EVENTUALLY SNAP OFF IN THE IGNITION

**CSHOP-2016-5685**

Comments: **NO START WHEN ENGINE IS HOT**

Date Opened 12-6-2016 Date Finished 12-6-2016 Meter 1 Reading: 22,028

**TASKS PERFORMED**

**NO PARTS USED**

ENGINE AND ACCESSORIES

**VENDOR?** AL PACKER

**Asset Work Order History K10353**

**CSHOP-2016-5808**

Date Opened 12-13-2016 Date Finished 4-27-2017 Meter 1 Reading: 22,598

**TASKS PERFORMED**

**Q PARTS**

TRAVEL TO BE CHARGED TO WORK ORDER  
FIRE FIGHTING EQUIPMENT

1 CRC; CLEAN-R-CARB 20OZ  
1 9IP; SOLENOID INS CONT DUTY  
1 9AP; WELDING KIT  
1 9AP; FIRE COMBAT FOAM TRUCK  
-1 9AP; FIRE COMBAT FOAM TRUCK  
1 9AP; FIRE COMBAT FOAM TRUCK  
-1 9AP; FIRE COMBAT FOAM TRUCK  
1 9HY; HOSE MADE  
1 NONSTOCK; FREIGHT CHARGE  
1 9AP; FIRE COMBAT FOAM TRUCK

**Service Requests:**

12/12/2016 SERVICE REQUEST / 35: RUSTED/CORRODED / PREFORMED VISUAL INSPECTION OF ALL SYSTE

12/12/2016 SERVICE REQUEST / 11: FOUND EXCESSIVE DRAW FROM REEL REWIND MOTOR. / R&I MOTOR C

12/12/2016 HAZARD / 18: LEAKING / REPLACED PRESSURE REGULATORS AND PURGE VALVES.  
HAZARDOUS ISSUE....WHEN BOTH VESSELS CHARGED AND UNDER PRESSURE WITH NITROGEN SYSTEM THE  
PURGE VALVES BLOW OFF AROUND EVERY 30 SECONDS OR SO AND SEEMS OUT OF NORMAL OPERATING  
PROCEDURES. UNSAFE AND NEEDS TO BE LOOKED AT FOR LEAK OR OTHER ISSUES.

**CSHOP-2017-2411**

Date Opened 4-24-2017 Date Finished 4-24-2017 Meter 1 Reading: 22,638

**TASKS PERFORMED**

**NO PARTS USED**

PM SERVICE B LIGHT

**VENDOR?** AL PACKER

**CSHOP-2017-2716**

Comments: **WORK ORDER 2016-5808 WAS BILLED AT 10 PERCENT INSTEAD OF 5 PERCENT CANT REOPEN WORK ORDER SO  
THIS ONE WAS CREATED TO CREDIT AND RECHARGE ON**

Date Opened 5-8-2017 Date Finished 5-19-2017 Meter 1 Reading: 22,598

**TASKS PERFORMED**

**NO PARTS USED**

FOAM SYSTEM

1 9AP; FIRE COMBAT FOAM TRUCK  
-1 9AP; FIRE COMBAT FOAM TRUCK

**Asset Work Order History K10353**

**CSHOP-2017-4298**

Date Opened 7-24-2017 Date Finished 8-11-2017 Meter 1 Reading: 22,835

**TASKS PERFORMED**

**Q PARTS**

TRAVEL TO BE CHARGED TO WORK ORDER  
TOWING HITCH  
ENGINE AND ACCESSORIES

3 MAC; SILICONE SPRAY 10OZ

**Service Requests:**

07/22/2017 ENGINE / 11: BINDS/STICKS / PREFORMED INSPECTION AND DIAGNOSTICS. STARTER IS INOP. F  
WONT START.

**CSHOP-2017-4635**

Date Opened 8-9-2017 Date Finished 8-9-2017 Meter 1 Reading: 22,835

**TASKS PERFORMED**

**NO PARTS USED**

COMMERCIAL WORK - OUTSIDE AGENCY

**VENDOR?** AL PACKER

**CSHOP-2017-5727**

Date Opened 10-2-2017 Date Finished 10-2-2017 Meter 1 Reading: 22,835

**TASKS PERFORMED**

**NO PARTS USED**

TIRE

**VENDOR?** DAN CALLAGHAN ENTERPRISES

**CSHOP-2018-1173**

Comments: **-DRY CHEM VESSEL 50 LBS LOW OF PURPLE K. -WASHER PUMP INOP. -AIR FILTER 6 YEARS OLD AND DIRTY.  
-EARS BROKEN OFF IGNITION KEY CYLINDER, MAKING IT DIFFICULT TO TURN KEY.**

Date Opened 2-27-2018 Date Finished 2-28-2018 Meter 1 Reading: 23,183

**TASKS PERFORMED**

**NO PARTS USED**

PM SERVICE B LIGHT

**CSHOP-2018-1177**

Date Opened 2-27-2018 Date Finished 2-28-2018 Meter 1 Reading: 23,183

**TASKS PERFORMED**

**Q PARTS**

WASHER PUMP  
AIR FILTER  
IGNITION SWITCH KEY-LOCK ASSE

1 1GM; PUMP  
1 1GM; ELEMENT  
1 1GM; CYLINDER

**Asset Work Order History K10353**

**CSHOP-2018-2047**

Date Opened 4-12-2018 Date Finished 5-29-2018 Meter 1 Reading: 23,230

**TASKS PERFORMED**

**NO PARTS USED**

HEADLIGHTS LOW BEAM  
SIREN

**Service Requests:**

- 04/12/2018 LIGHTS / 49: CAN NOT DUPLICATE CONCERN / PREFORMED OPERATIONAL AND VISUAL INSPEC FRONT LEFT HEAD LIGHT NOT WORKING IN EITHER LOW OR HIGH BEAM MODE.
- 04/12/2018 SERVICE REQUEST / 49: CAN NOT DUPLICATE CONCERN / PREFORMED OPERATIONAL INSPECT SIREN FOR F81 IS WORKING INTERMITTENTLY.

**CSHOP-2018-3008**

Date Opened 5-31-2018 Date Finished 6-1-2018 Meter 1 Reading: 23,239

**TASKS PERFORMED**

**NO PARTS USED**

TRAVEL TO BE CHARGED TO WORK ORDER  
HEADLIGHTS LOW BEAM

**Service Requests:**

- 05/31/2018 LIGHTS / 19: HEADLAMP UNPLUGGED. / REMOVED THE SEALED BEAM HEADLAMP FROM THE TF DRIVER SIDE HEADLIGHT OUT.

**CSHOP-2019-102**

Date Opened 1-7-2019 Date Finished 1-14-2019 Meter 1 Reading: 23,436

**TASKS PERFORMED**

**NO PARTS USED**

FUEL SYSTEM

**VENDOR?** AL PACKER

**Service Requests:**

- 01/06/2019 ENGINE / 18: LEAKING / REPAIR FUEL LEAK WHEN ENGINE IS RUNNING. MORE ON THE PASSENGER SIDE OF TRUCK UNDER ENGINE.

**CSHOP-2019-1066**

Date Opened 2-26-2019 Date Finished 6-3-2019 Meter 1 Reading: 23,547

**TASKS PERFORMED**

**Q PARTS**

HEADLIGHTS LOW BEAM

- 1 LMP; LAMP
- 1 AVB; MINIATURE BULB
- 1 AVB; MINIATURE BULB
- 1 LMP; LAMP
- 2 LMP; LAMP

**Service Requests:**

- 05/16/2019 SERVICE REQUEST / 13: CHIPPED / EXCHANGE - NEW TYPE PROBLEM INTO DESCRIPTION, SIREN NOT WORKING

**Asset Work Order History K10353**

**CSHOP-2019-1091**

Date Opened 2-27-2019 Date Finished 2-27-2019 Meter 1 Reading: 23,547

**TASKS PERFORMED**

**NO PARTS USED**

PM SERVICE B LIGHT

**VENDOR?** AL PACKER

---

**CSHOP-2019-261**

Date Opened 1-14-2019 Date Finished 1-14-2019 Meter 1 Reading: 23,436

**TASKS PERFORMED**

**NO PARTS USED**

BATTERY

**VENDOR?** AL PACKER

---

**CSHOP-2019-2865**

Comments: **SIREN INTERMITTENTLY INOP**

Date Opened 6-3-2019 Date Finished 6-3-2019 Meter 1 Reading: 23,722

**TASKS PERFORMED**

**Q PARTS**

TRAVEL TO BE CHARGED TO WORK ORDER  
SIREN

1 1WL; SIREN AMPLIFIER

---

**CSHOP-2019-4632**

Date Opened 8-29-2019 Date Finished 9-19-2019 Meter 1 Reading: 23,804

**TASKS PERFORMED**

**Q PARTS**

TRAVEL TO BE CHARGED TO WORK ORDER  
TAIL LIGHTS

1 1GM; TAIL LAMP DRIVER

---

**Service Requests:**

08/29/2019 LIGHTS / 12: BROKEN / REPLACED LEFT TAIL LAMP ASSEMBLY.  
L/R TAIL LIGHT LENS COMING APART AT THE SEAM, LIKELY TO FALL APART.

---

**CSHOP-2019-5838**

Date Opened 11-6-2019 Date Finished 11-8-2019 Meter 1 Reading: 23,836

**TASKS PERFORMED**

**NO PARTS USED**

STROBE LIGHTS

**Service Requests:**

11/06/2019 LIGHTS / 27: OVERHEATED / VERIFIED CONCERN. PREFORMED DIAGNOSTICS. FOUND AN OVER  
VEHICLE LIGHTS NOT WORKING

---

**Asset Work Order History K10353**

**CSHOP-2019-986**

Date Opened 2-21-2019 Date Finished 2-21-2019 Meter 1 Reading: 23,436

**TASKS PERFORMED**

**NO PARTS USED**

TIRE

**VENDOR?** DAN CALLAGHAN ENTERPRISES

---

**CSHOP-2020-2100**

Date Opened 4-20-2020 Date Finished 4-24-2020 Meter 1 Reading: 23,935

**TASKS PERFORMED**

**NO PARTS USED**

TRAVEL TO BE CHARGED TO WORK ORDER  
CRANKING SYSTEM

**Service Requests:**

---

04/19/2020 ENGINE / 49: CAN NOT DUPLICATE CONCERN / ATTEMPTED TO DUPLICATE CONCERN. STARTED  
ENGINE- CRANKS OVER WILL NOT START.

---

**CSHOP-2020-4000**

Date Opened 8-4-2020 Date Finished 8-6-2020 Meter 1 Reading: 24,152

**TASKS PERFORMED**

**NO PARTS USED**

TRAVEL TO BE CHARGED TO WORK ORDER  
CRANKING SYSTEM

**Service Requests:**

---

08/01/2020 STARTER / 49: CAN NOT DUPLICATE CONCERN / ATTEMPTED TO DUPLICATE CONCERN. STARTED  
CRANK NO START

---

**CSHOP-2020-4795**

Date Opened 9-14-2020 Date Finished 9-17-2020 Meter 1 Reading: 24,289

**TASKS PERFORMED**

**NO PARTS USED**

ENGINE AND ACCESSORIES

**Service Requests:**

---

09/13/2020 ENGINE / 49: CAN NOT DUPLICATE CONCERN / PREFORMED DIAGNOSTICS. MIL LAMP NOT ON. I  
ENGINE- FOAM 81 STALLED OUT TWICE WHILE DRIVING AT SLOW SPEED.

---

**CSHOP-2020-771**

Comments: **IS AT PACKER NOW 2-10-20**

Date Opened 2-10-2020 Date Finished 3-3-2020 Meter 1 Reading: 23,913

**TASKS PERFORMED**

**NO PARTS USED**

PM SERVICE B LIGHT

**VENDOR?** AL PACKER

---

**Asset Work Order History K10353**

**CSHOP-2021-1180**

Date Opened 3-4-2021 Date Finished 3-2-2021 Meter 1 Reading: 24,448

**TASKS PERFORMED**

**NO PARTS USED**

PM SERVICE B LIGHT

**VENDOR?** AL PACKER

**CSHOP-2021-1555**

Date Opened 3-23-2021 Date Finished 3-23-2021 Meter 1 Reading: 0

**TASKS PERFORMED**

**NO PARTS USED**

VENDOR TIRE REPAIR/CHANGE

**VENDOR?** DAN CALLAGHAN ENTERPRISES

**CSHOP-2021-3306**

Date Opened 6-16-2021 Date Finished 6-22-2021 Meter 1 Reading: 24,448

**TASKS PERFORMED**

**Q PARTS**

TRAVEL TO BE CHARGED TO WORK ORDER  
DOOR HANDLES INSIDE-OUTSIDE

1 1GM; DOOR HANDLE DRIVER INSIDE  
1 1GM; BEZEL DRIVER INSIDE HANDLE

**Service Requests:**

06/15/2021 DOOR / 12: BROKEN / DRIVER'S DOOR INSIDE HANDLE ASSEMBLY IS BROKEN. DISASSEMBLED  
VEHICLE DOORS - DRIVER DOOR "OPEN HANDLE" BROKEN. DRIVER IS UNABLE TO EXIT THE VEHICLE

**CSHOP-2021-4011**

Date Opened 7-19-2021 Date Finished 7-26-2021 Meter 1 Reading: 24,450

**TASKS PERFORMED**

**NO PARTS USED**

TRAVEL TO BE CHARGED TO WORK ORDER  
FIRE FIGHTING EQUIPMENT

**Service Requests:**

07/17/2021 SERVICE REQUEST / 18: LEAKING / PREFORMED INSPECTION. DRY CHEM TANK AT 0 PSI. TANK \  
TYPE PROBLEM INTO DESCRIPTION DRIVER SIDE NITRO TANK LEAK/BURST

**CSHOP-2021-7051**

Date Opened 12-28-2021 Date Finished 3-10-2022 Meter 1 Reading: 24,987

**TASKS PERFORMED**

**Q PARTS**

TRAVEL TO BE CHARGED TO WORK ORDER  
LIGHTING SYSTEM

2 9AP; HEADLIGHT ADJUSTMENT SCREW

**Service Requests:**

12/28/2021 LIGHTS / 12: BROKEN / REPAIR  
VEHICLE LIGHTS NOT WORKING HEAD LIGHTS ARE POINTING TO GROUND AND CAN NOT BE ADJUSTED, RUSTED  
OUT THIS TRUCK IS OOS FOR NIGHT OR ROAD DRIVING

**Asset Work Order History K10353**

**CSHOP-2022-1030**

Date Opened 2-22-2022 Date Finished 3-1-2022 Meter 1 Reading: 24,987

**TASKS PERFORMED**

**NO PARTS USED**

---

TRAVEL TO BE CHARGED TO WORK ORDER  
ENGINE AND ACCESSORIES

**Service Requests:**

-----  
02/21/2022 ENGINE / 49: CAN NOT DUPLICATE CONCERN / DROVE ASSET FOR 30 MINUTES UNDER VARYING  
ENGINE CUT OFF WHILE IN DRIVE. . THE ENGINE WILL RESTART.

---

**CSHOP-2022-2878**

Comments: **PRETTY SURE THIS IS 6.5 L GM DIESEL KNOWN SYMPTOM OF ENGINE STALLING IS DEFECTIVE INJECTION  
PUMP THIS HAS BEEN DUPLICATED / NEEDS TO BE REPAIRED**

Date Opened 5-27-2022 Date Finished 6-3-2022 Meter 1 Reading: 25,368

**TASKS PERFORMED**

**NO PARTS USED**

---

FUEL SYSTEM

**Service Requests:**

-----  
05/27/2022 ENGINE / 18: LEAKING / ADJUST  
TRUCK TURNED OFF WHILE DRIVING. DIDN'T HAVE STEERING OR ANY BRAKES.

---

**CSHOP-2022-2918**

Date Opened 5-31-2022 Date Finished 6-1-2022 Meter 1 Reading: 25,368

**TASKS PERFORMED**

**NO PARTS USED**

---

PM SERVICE B LIGHT

**CSHOP-2022-783**

Date Opened 2-10-2022 Date Finished 2-14-2022 Meter 1 Reading: 24,978

**TASKS PERFORMED**

**NO PARTS USED**

---

PM SERVICE B LIGHT

---

**Asset Work Order History K10353**

**CSHOP-2022-784**

Comments: **CHECK BRAKES**

Date Opened 2-10-2022

Date Finished

6-17-2022

Meter 1 Reading:

25,386

**TASKS PERFORMED**

FOAM SYSTEM  
COOLING SYSTEM  
OIL  
ENGINE AND ACCESSORIES  
BATTERY  
BELT  
ELECTRICAL  
SUSPENSION  
BRAKES

**Q PARTS**

1 5CS; GAUGE 2 5 LFP22 0 400PSI  
1 FIL; NAPAGOLD OIL FILTER  
1 SFI; AIR FILTER PRO SELECT  
1 9AP; FUEL FILTER IN LINE  
1 9AP; FUEL FILTER  
8 4PC; 15W40 PREMIUM BLUE OIL  
1 1GM; FUEL INJECTOR PUMP  
1 FPG; MANIFOLD GASKET SET  
1 1AD; FUEL INJECTOR  
1 1GM; CORE DEPOSIT  
1 FREIGHT  
20 9HY; O RING HIGH TEMP  
-1 1GM; CORE DEPOSIT  
1 CRC; CLEAN R CARB 20OZ  
1 9AP; ENGINE INTAKE MANIFOLD GASKET SET  
1 NBH; SERPENTINE BELT  
2 1AD; BATTERY  
1 TEM; CONNECTOR  
1 TEM; CONNECTOR  
2 TTX; STABILIZER BAR LINK  
1 9AP; CORE DEPOSIT  
1 9AP; CORE DEPOSIT  
1 NBF; BFLUIDDOT332OZ  
1 UP; BRAKE HOSE  
1 ADO; DISC PAD  
1 UP; BRAKE HOSE  
1 9AP; FRONT LEFT CALIPER  
1 9AP; FRONT RIGHT CALIPER  
2 9AP; FRONT BRAKE ROTORS

**Service Requests:**

02/11/2022

ENGINE / 18: LEAKING / REPAIR

ENGINE CUT OFF WHILE IN DRIVE . ENGINE RESTART

**CSHOP-2023-192**

Comments: **DEAD BATTERY, NO START**

Date Opened 1-12-2023

Date Finished

1-17-2023

Meter 1 Reading:

25,456

**TASKS PERFORMED**

BATTERY

**Q PARTS**

3 1AD; BATTERY

**Asset Work Order History K10353**

**CSHOP-2023-882**

Comments: **BATTERY**

Date Opened 2-15-2023

Date Finished

3-9-2023

Meter 1 Reading:

25,466

**TASKS PERFORMED**

**NO PARTS USED**

TRAVEL TO BE CHARGED TO WORK ORDER  
CRANKING SYSTEM

**Service Requests:**

02/14/2023

SERVICE REQUEST / 49: CAN NOT DUPLICATE CONCERN / PREFORMED INSPECTION. ALL CONN  
BATTERY TERMINAL NOT CONNECTED, MISSING NUT,

**CSHOP-2024-255**

Comments: **CHECK ENGINE LIGHT**

Date Opened 1-16-2024

Date Finished

8-22-2024

Meter 1 Reading:

0

**TASKS PERFORMED**

**NO PARTS USED**

ENGINE AND ACCESSORIES

**Service Requests:**

01/04/2024

ENGINE / 12: BROKEN / REPAIR

While driving vehicle the engine stopped and a warning light came on that said - service throttle

**CSHOP-2024-2789**

Comments: **PM INSPECTION**

Date Opened 6-6-2024

Date Finished

6-6-2024

Meter 1 Reading:

26,015

**TASKS PERFORMED**

**NO PARTS USED**

PM SERVICE B LIGHT

**CSHOP-2025-2164**

Comments: **REMOVE FOAM SKID**

Date Opened 5-15-2025

Date Finished

9-16-2025

Meter 1 Reading:

26,015

**TASKS PERFORMED**

**Q PARTS**

FIRE FIGHTING EQUIPMENT

1	8HY; 4" X 3/8 POLY KNIT MINI PAINT ROLLER 6PK
1	8HY; 12" WOODEN PAINT STICK 10PK
2	8HY; 2.5QT PAINT MIXING CONTAINER
1	8HY; 4" MINI PAINT ROLLER FRAME
4	8HD; 5" MINI ROLLOR PAINT TRAY
1	9AP; SPECIAL U-BOLT
1	8AM; METAL PREP
1	9AP; 2K URETHANE COATING KIT SAFETY ORANGE
1	9AP; 2K URETHANE SAFETY YELLOW
2	8AM; RUBBER STRIP 1/2" X 3" X 20FT
2	9AP; RUST PREVENTIVE COATING

**Asset Work Order History K10353**

**CSHOP-2025-2474**

Comments: **INSPECTION**

Date Opened 6-5-2025 Date Finished 6-5-2025 Meter 1 Reading: 26,015

**TASKS PERFORMED**

**NO PARTS USED**

PM SERVICE B LIGHT

---

**CSHOP-2025-4433**

Date Opened 10-9-2025 Date Finished 10-14-2025 Meter 1 Reading: 26,015

**TASKS PERFORMED**

**NO PARTS USED**

SURPLUS PREP

---

**RADIO-2019-861**

Date Opened 11-8-2019 Date Finished 11-11-2019 Meter 1 Reading: 0

**TASKS PERFORMED**

**NO PARTS USED**

RADIO

**Service Requests:**

11/06/2019 RADIO / /  
RADIO ISSUES

---

**RADIO-2020-424**

Comments: **MIC REPLACED**

Date Opened 5-5-2020 Date Finished 5-5-2020 Meter 1 Reading: 0

**TASKS PERFORMED**

**NO PARTS USED**

MOBILE RELATED

**Service Requests:**

05/04/2020 RADIO / /  
RADIO ISSUES, NOT POWRING UP AND MIC CORD NEEDS TO BE REPLACED

---

**RADIO-2021-1144**

Comments: **FIXED**

Date Opened 12-28-2021 Date Finished 12-28-2021 Meter 1 Reading: 0

**TASKS PERFORMED**

**NO PARTS USED**

MOBILE RELATED

**Service Requests:**

12/26/2021 RADIO / /  
RADIO ISSUES, AIRCRAFT RADIO POWERS ON HOWEVER YOU ARE NOT ABLE TO HEAR ANY COMMUNICATIONS. THE "BUSY" INDICATOR COMES ON SO ITS PROBABLY RECEIVING BUT YOU CANT HEAR IT. EVEN WHEN ADJUSTING VOLUME YOU CANT HEAR THE BEEPS WITH EACH VOLUME LEVEL.

---

**Asset Work Order History K10353**

**RADIO-2022-117**

Comments: **FIXED**

Date Opened 2-8-2022

Date Finished

2-8-2022

Meter 1 Reading:

0

**TASKS PERFORMED**

**NO PARTS USED**

---

MOBILE RELATED

**Service Requests:**

02/02/2022

RADIO / /

ATCT RADIO NOT WORKING. WILL NOT TURN ON

---

**RADIO-2025-539**

Comments: **REMOVAL OF RADIOS AND EQUIPMENT.SURPLUS PREP.**

Date Opened 5-20-2025

Date Finished

5-20-2025

Meter 1 Reading:

0

**TASKS PERFORMED**

**NO PARTS USED**

---

SURPLUS PREP

**Service Requests:**

05/20/2025

RADIO / /

SURPLUS PREP ON K10353.

---

**SSHOP-2023-574**

Date Opened 5-25-2023

Date Finished

6-6-2023

Meter 1 Reading:

25,493

**TASKS PERFORMED**

**NO PARTS USED**

---

PM SERVICE B LIGHT

---