



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155817

* FULLSIZE 4X4 SUV

Workorder: V242

In Date: 10/17/2005
Close Date: 10/18/2005

Meter Reading:

Problem?

STROBE INOP, IN LIGHT BAR DC-1

Task performed:

Parts	Quantity
4ELTUBE4ELTUBE REFLECTOR ASSY.	1

Workorder: V1242

In Date: 01/20/2006
Close Date: 01/27/2006

Meter Reading: 38,977.00

Problem?

B INSPECTION DC1

Task performed:

See B Inspection pre-printed form

Parts	Quantity
2421095658608 TRANSFILTER 4L80 DEEP PAN	1
3157TAIL LIGHT BULBS	2
CA875642487 FILTER AIR	1
PH3506OIL FILTER 51042	1

Workorder: V1407

In Date: 02/06/2006
Close Date: 02/14/2006

Meter Reading:

Problem?

right headlight out D/C 1 (takes Part # 9006)

Task performed:

Parts	Quantity
90069006 BULB ASSY	1
HLD3999GSS1715UV 30LB STRUT GAS	2



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155817

* FULLSIZE 4X4 SUV

Workorder: V2466

In Date: 05/03/2006
Close Date: 06/29/2006

Meter Reading:

Problem?

BACK UP ALARM, DC-1

Task performed:

Parts	Quantity
12463086WASHER HOSE	1
12487670WASHER BOTTLE	1
89025062WASHER PUMP	1

Workorder: V3197

In Date: 06/28/2006
Close Date: 07/10/2006

Meter Reading:

Problem?

B INSPECTION AND REPAIRS AS NEEDED DC1

Task performed:

Parts	Quantity
11509853BAT BOLT	1
151831561006D REFLECTOR FOR 2004 SUBURBAN	1
15705102BAT TRAY NEW # 15246518 2005 SUBURB,	1
31-1631-16 WIPER BLADES	1
356668USE 14005061 BAT HOLD DOWN	1
78-72BATTERY GROUP 78	2
89025062WASHER PUMP	1
PH3506OIL FILTER 51042	1



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155817

* FULLSIZE 4X4 SUV

Workorder: V4156

In Date: 08/28/2006
Close Date: 08/31/2006

Meter Reading:

Problem?

REPAIR LIGHTS ON TRAILER BC1

Parts ----- Quantity -----

Task performed:

NO PARTS USED

Workorder: V5516

In Date: 11/24/2006
Close Date: 12/01/2006

Meter Reading:

Problem?

speedometer not working DC-1

Parts ----- Quantity -----

Task performed:

1. TRAVELED TO STN 14. SPOKE WITH D.C. DROVE TRUCK FOUND NO PROBLEM WITH VEHICLE.

NO PARTS USED

Workorder: V6159

In Date: 01/08/2007
Close Date: 01/09/2007

Meter Reading: 58,033.00

Problem?

B INSPECTION AND REPAIRS AS NEEDED DC1

Parts ----- Quantity -----

Task performed:

B Inspection

01046301700S30HACP STROBE CLEAR	1
AF1518 42488 FILTER AIR-SUBURB	1
PH3506OIL FILTER 51042	1



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155817

* FULLSIZE 4X4 SUV

Workorder: V6160

In Date: 01/08/2007
Close Date: 01/11/2007

Meter Reading: 58,033.00

Problem?

REPLACE TIRES AT CALLAGHAN DC1

Parts	Quantity
NO PARTS USED	

Task performed:

Replaced tires at Callaghan Ent DC1

Vendor? CALLAGHAN ENT

Workorder: V6300

In Date: 01/16/2007
Close Date: 01/17/2007

Meter Reading: 58,545.00

Problem?

replace leaking battery dc1

Parts	Quantity
78-72BATTERY GROUP 78	1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER B/	1

Task performed:

Battery leaking removed battery cleaned battery box replaced battery

Workorder: V7054

In Date: 03/04/2007
Close Date: 03/08/2007

Meter Reading:

Problem?

Right front headlight not working DC1

Parts	Quantity
44364436 BULB	1
90069006 BULB ASSY	1

Task performed:

R&R headlight



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155817

* FULLSIZE 4X4 SUV

Workorder: V8126

In Date: 05/07/2007 Meter Reading:
Close Date: 05/22/2007

Problem?

a/c stopped blowing cold air 5/6/07. DC-1

Parts ----- Quantity -----

Task performed:

Chk pressure & wire; walk with DC; NPF

NO PARTS USED

Workorder: V8338

In Date: 05/21/2007 Meter Reading: 65,563.00
Close Date: 06/11/2007

Problem?

on call dc1 brakes feel sponge

Parts ----- Quantity -----

Task performed:

1. Travel to sta 16, check fluid, check wheels for leaks- (OK), Road test, vehicles brakes stop OK, but seems pedel is low. May need to bring by shop for inspection tomorrow. Travel home.

NO PARTS USED

Workorder: V8576

In Date: 06/04/2007 Meter Reading: 66,481.00
Close Date: 06/19/2007

Problem?

running lights out D/C1

Parts ----- Quantity -----

Task performed:

1. Drive to sta, R/R bulb for running lights, test OK

4114DAYLITE BULB 15199562	1
HA238CHA238C STROBE BULB	1



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155817

* FULLSIZE 4X4 SUV

Workorder: V8635

In Date: 06/06/2007
Close Date: 06/22/2007

Meter Reading: 66,481.00

Problem?

B inspection and related repairs D/C 1

Task performed:

1. Performed B service. Replaced oil filter, air filter, greased chasis 2. Replaced engine serpentine belts 3. Removed wheels, checked brakes, rotated tires 4. Adjusted headlight aiming

Parts	Quantity
31-1631-16 WIPER BLADES	1
91-22WIPER BLADE	2
CA875642487 FILTER AIR	1
K040378BELT SUBURBANS 2002/2003	1
K060930BELT	1
PH3506OIL FILTER 51042	1

Workorder: V9054

In Date: 06/28/2007
Close Date: 07/06/2007

Meter Reading: 67,692.00

Problem?

a/c 10-7 dc1

Task performed:

1. A/C control head. Order control head 2. Drive to sta. R&R control head. Test OK

Parts	Quantity
21997352A/C CONTROL HEAD	1
91-22WIPER BLADE	2

Workorder: V9842

In Date: 08/13/2007
Close Date: 08/13/2007

Meter Reading: 70,026.00

Problem?

ON CALL DC1 TRANS 10-7

Task performed:

Chkd engine light

Parts	Quantity
NO PARTS USED	



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155817

* FULLSIZE 4X4 SUV

Workorder: V9854

In Date: 08/13/2007 Meter Reading: 70,026.00
Close Date: 08/30/2007

Problem?

tow unit from shop to atlas transmission dc1

Parts ----- Quantity -----

Task performed:

Tow unit from shop to Atlas Transmission

NO PARTS USED

Vendor? SISTERS TOW

Workorder: V9840

In Date: 08/28/2007 Meter Reading: 70,026.00
Close Date: 09/07/2007

Problem?

B inspection and related repairs, dc1

Parts ----- Quantity -----

Task performed:

B-Inspection Change oil/filter; replc air filter; clear engine codes

46134AIR FILTER C.V.	1
AF1518 42488 FILTER AIR-SUBURB	1
G801833595 FILTER FUEL WIX	1
PH2USE 51372 OIL FILTER L/F PH820	1
PH59WIX 51522 FRM PH3675 OIL FILTER	1



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155817

* FULLSIZE 4X4 SUV

Workorder: V9851

In Date: 08/13/2007
Close Date: 09/10/2007

Meter Reading: 70,026.00

Problem?

repair transmission dc1

Parts

Quantity

Task performed:

Repair transmission - Atlas Transmission

NO PARTS USED

Vendor? ATLAS TRANS

Workorder: V10786

In Date: 10/02/2007
Close Date: 10/03/2007

Meter Reading: 70,026.00

Problem?

A inspection and related repairs (Back from trans overhaul-test drive for trans)D/C1

Parts

Quantity

Task performed:

1. ROAD TEST- TRANSMISSION SHIFTING IN ALL GEARS AT THIS TIME 2. P/S FLUID LOW- ADD 1/3 OF A QUART 3. DIAGNOSE LOW VOLTAGE- FOUND BATTERY WEAK, R/R NEW SET OF BATTERIES 4. WHEEL COVER MISSING PART ON ORDER

15052378305K HUB CAP

1

78-72BATTERY GROUP 78

2

BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER B/

2

Workorder: V11110

In Date: 10/18/2007
Close Date: 10/23/2007

Meter Reading: 71,894.00

Problem?

a/c 10-7 dc1

Parts

Quantity

Task performed:

1. a/c inoperable. possible relay at low preesure switch. intermittent problem. swapped relays and ordered new switch.

361000005RELAY FERRARA/EONE

2



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155817

* FULLSIZE 4X4 SUV

Workorder: V11483

In Date: 11/07/2007

Meter Reading: 71,894.00

Close Date: 11/19/2007

Problem?

remove tic and charger from unit

Parts

Quantity

Task performed:

drive to stn; Rem TIC from truck j

NO PARTS USED

Workorder: V11924

In Date: 12/04/2007

Meter Reading:

Close Date: 12/10/2007

Problem?

Speedometer is not working properly. Check noise in rear while truck is running dc1

Parts

Quantity

Task performed:

1. Checked out Spedo Inop. Found spedo working normaly. 2. Road tested truck to listen for noise, found Front Tire scalloped badly causing a roaring noise. 3. Travel to station 19

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155817

* FULLSIZE 4X4 SUV

Workorder: V12572

In Date: 01/14/2008
Close Date: 01/18/2008

Meter Reading: 75,870.00

Problem?

b inspection and repairs as needed dc1

Task performed:

1. "B" inspection, test drive, change oil and filter replace air filter, replace wiper blades. 2. Fix corner strobe and take down.

Parts	Quantity
15-18150-04OIL DRAIN CUMMINS ISB ISC	1
15W40BSYN OIL BULK QTS	27
91-22WIPER BLADE	2
CA8193AIR FILTER 46744 WIX	1
CA875642487 FILTER AIR	1
FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
PH3506OIL FILTER 51042	1
PR338324070 WIX FILTER WATER	1
R90PFILTER FUEL 33231	1

Workorder: V12237

In Date: 12/26/2007
Close Date: 01/24/2008

Meter Reading:

Problem?

1) rattling noise at idle and low speeds, sound like a loose heatshield or similiar noise. 2) Speedodometer working intermittently. 3) Takedown lights out. dc1

Task performed:

Drive to stn; order parts for muffler & speedo. 2. Drive to stn; in stalled muffler hanger; test ok; speedo under warranty at Chevy. j

Parts	Quantity
15092802TAIL PIPE MOUNT BUSHING	2



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155817

* FULLSIZE 4X4 SUV

Workorder: V12994

In Date: 02/01/2008
Close Date: 02/04/2008

Meter Reading: 75,870.00

Problem?

dead batterys dc1

Task performed:

1. Drive to St 1 install battery 2. Drive to St R/R Battery on Truck, they were dead. Wait for Batt from shop, installed 3. Drive to St on call and Diag that it needs fuel pump.

Parts	Quantity
78-72BATTERY GROUP 78	4
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER B/	4

Workorder: V13041

In Date: 02/04/2008
Close Date: 02/05/2008

Meter Reading: 75,870.00

Problem?

unit runs poorly dc1

Task performed:

1. Run fuel pressure test, wnl, run scan test, no problem error codes found, clean throttle body.

Parts	Quantity
NO PARTS USED	

Workorder: V13028

In Date: 02/04/2008
Close Date: 02/06/2008

Meter Reading: 75,870.00

Problem?

tow unit from sta 19 to shop

Task performed:

tow unit from Stn19 to shop - Sisters Towing j

Parts	Quantity
NO PARTS USED	

Vendor? SISTERS TOWING



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155817

* FULLSIZE 4X4 SUV

Workorder: V12927

In Date: 01/30/2008
Close Date: 02/07/2008

Meter Reading: 75,870.00

Problem?

INSTALL BATTERY CHARGER AND AUTO EJECT IN REAR OF VEHICLI
DC-1

Parts ----- Quantity -----

Task performed:

1. Installed charger, run wires 2. Assist install charger 3. Assist install
charger 4. Repair and re-wire rear tailgate worklight

091-20WP-120AUTO EJECT	1
0913912CHARGER 2000	1
30063-30BREAKER 30 AMP	2

Workorder: V14142

In Date: 03/27/2008
Close Date: 03/28/2008

Meter Reading:

Problem?

Brake light is out on DC1 vehicle

Parts ----- Quantity -----

Task performed:

1. travel to sta repaired blown right brake light.

3157TAIL LIGHT BULBS	1
----------------------	---

Workorder: V14343

In Date: 04/07/2008
Close Date: 04/18/2008

Meter Reading: 80,907.00

Problem?

replace tires at callaghan dc1

Parts ----- Quantity -----

Task performed:

Replace tires DC1 - Callaghan j

NO PARTS USED	
---------------	--

Vendor? CALLAGHAN



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155817

* FULLSIZE 4X4 SUV

Workorder: V14485

In Date: 04/15/2008
Close Date: 04/23/2008

Meter Reading: 80,907.00

Problem?

SEAT COVERS DC1

Parts

Quantity

Task performed:

- 1. ORDER SEAT COVER FROM TRUCK AND TRAILER.

NO PARTS USED

Workorder: V14333

In Date: 04/07/2008
Close Date: 05/01/2008

Meter Reading: 80,907.00

Problem?

b inspection and repairs as needed dc 1

Parts

Quantity

Task performed:

- 1. checked out front end noise,found toasted left front wheel bearing.replaced wheel bearing/hub assem. 2. performed a- service 3. replaced brakes on all 4 wheels. 4. replaced wiper blades. 5. replaced left side daytime running light bulb. 6. replaced left rear strobe light.

15225770FRONT HUB 02 SUBURBAN	1
18041762FRONT PADS SUBURBAN	2
4114DAYLITE BULB 15199562	1
50R03ZCRLIGHT LED RED TIR 6	1
88964201MKD784 FRONT PADS SUBURBAN	2
91-22WIPER BLADE	2
CA875642487 FILTER AIR	1
PH3506OIL FILTER 51042	1



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155817

* FULLSIZE 4X4 SUV

Workorder: V14340

In Date: 04/07/2008 Meter Reading: 80,907.00
Close Date: 05/02/2008

Problem?

REBALANCE TIRES AT STA 14

Parts ----- Quantity -----

Task performed:

Rebalance tires at Stn14 - Callaghan j

NO PARTS USED

Vendor? CALLAGHAN

Workorder: V15230

In Date: 05/21/2008 Meter Reading: 83,341.00
Close Date: 06/06/2008

Problem?

check unit for coolant leak dc1

Parts ----- Quantity -----

Task performed:

1. Drive to Stn; pressure chk sys & run unit; test ok; order cap; installed.
2. Drive to Stn; installed cap. j

102487046 15 LB RADCAP GM	1
5-15PPLUG GROUNDING STRAIGHT BLADE 5C369	1

Workorder: V14324

In Date: 04/06/2008 Meter Reading: 80,907.00
Close Date: 06/17/2008

Problem?

on call noise in front of unit dc1

Parts ----- Quantity -----

Task performed:

1. talk w/ dc #1 on phone after he explained problem he felt confident to bring vehicle to shop had DC #1 SWAP OUT TO A NEW VEHICLE # 10174222.

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155817

* FULLSIZE 4X4 SUV

Workorder: V15102

In Date: 05/14/2008
Close Date: 06/17/2008

Meter Reading:

Problem?

Front right headlight is out on DC1

Task performed:

1. drive to station r/r head lite

Parts	Quantity
3U2Z14S411FKAAWIRE ASY	1
90069006 BULB ASSY	1

Workorder: V16022

In Date: 06/27/2008
Close Date: 07/10/2008

Meter Reading: 85,368.00

Problem?

unit overheats dc1

Task performed:

Road tested unit several times; never overheated; chkd cooling sy for leaks-none found; tested cap; fnd does not lrease pressure; R/R cap. j

Parts	Quantity
102487046 15 LB RADCAP GM	1

Workorder: V18841

In Date: 11/04/2008
Close Date: 11/19/2008

Meter Reading:

Problem?

TIC charger is not working in the DC1 vehicle DC 1

Task performed:

Drive to Stn; rewire TIC charger. j

Parts	Quantity
NO PARTS USED	



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155817

* FULLSIZE 4X4 SUV

Workorder: V20131

In Date: 01/05/2009
Close Date: 02/12/2009

Meter Reading: 94,045.00

Problem?

b inspection and repairs as needed dc 1

Task performed:

B-Inspection & road test. 2. Rem frnt & rear tires to inspect brake pad wear due to low fluid level, pads all good; fluid level low, no leaks; fnd fill to proper level. 3. Rem A/C & engine belt. 4. Center nount high stop lamp out; rem/ck asy; LEDS blown. 5. Windshield wiper fluid low; fill fluid bottle & add bug solvent. 6. Install A/C & eng belt. 7. Frnt lower control arm body bumper damage. Rem damage bumper & install new ones left/right side. 8. Push bar warning light out; dia fault; fnd loose grnd connection in wiring; correct fault. 9. Tailgate work light out; trace wiring; no power; follow wiring to fuse; fuse blown; unit pulling more amps than fuse can handle; go from 3AMP to 5AMP & chk wiring. 10. Center mount high stoplight asy; install & tested; operating normal. j

Parts

Quantity

151709553RD BRAKE LITE LED	1
15835666306E BUMPERS	2
15W40BSYN OIL BULK QTS	6
CA875642487 FILTER AIR	1
K040378BELT SUBURBANS 2002/2003	1
K060930BELT	1
PH3506OIL FILTER 51042	1

Workorder: V21438

In Date: 03/02/2009
Close Date: 03/02/2009

Meter Reading: 97,343.00

Problem?

ON CALL COOLANT LEAK DC1

Task performed:

Drive to Stn19; chk DC1 for burning smell from A/C vents-coolant; swapout. j

Parts

Quantity

NO PARTS USED	
---------------	--



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155817

* FULLSIZE 4X4 SUV

Workorder: V21448

In Date: 03/02/2009
Close Date: 03/16/2009

Meter Reading: 97,343.00

Problem?

b inspection and repairs as needed dc1

Task performed:

1. B-Inspection; inflate tires to proper press; fill washer fluid reservoir.
2. Test btrys; (1) NG; replcd both btrys; cln cables.
3. R/R heater core.
4. Heater core, radios, A/C, coolant, battery.
5. Dia/rep LF strobe; grind hole in bumper guard for plug to fit throught; protect wires.
6. Cln shop.
7. R/R water pump; replcd upper/lower rad hoses.
8. Replcd L/turn/marker bulb; rem headlight/turn asy.
9. Dia no frt strobes; fnd bad strobe pack & shorted strobe bulb; replcd frt strobe bulbs/strobe pack; dia no wigwags.
10. Dia no DRL lights; problem in BCM; not to be fixed per Ed Ehrke. j

Parts

Quantity

12600171THERMOSTATE	1
15179498UPPER RADIATOR HOSE	1
19130015HOSE	1
4114DAYLITE BULB 15199562	2
50R03ZRRLIGHT 500 TIR LED	1
78-72BATTERY GROUP 78	2
89018166WATER PUMP KIT	1
89018297HEATER CORE	1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER B/	2
PH3506OIL FILTER 51042	1
S30HACSTROBE BULB	2
UPS64LXPOWER SUPPLY	1

Workorder: V21783

In Date: 03/13/2009
Close Date: 03/17/2009

Meter Reading: 97,343.00

Problem?

remove graphics on rear of unit, tic charger 10-7

Task performed:

1. Rem decals from rear of vehicle.
2. Rep radio connection for antenna; R/R radio & trim piece.
2. Charge A/C with freon & leak check.
4. Replcd TIC c harger. j

Parts

Quantity

K080653BELT WPB	1
-----------------	---



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155817

* FULLSIZE 4X4 SUV

Workorder: V21834

In Date: 03/16/2009
Close Date: 04/13/2009

Meter Reading: 36,338.40

Problem?

replace tires at callaghan

Parts

Quantity

Task performed:

Replace tires at Callaghan j

NO PARTS USED

Vendor? CALLAGHAN

Workorder: V22918

In Date: 04/29/2009
Close Date: 05/08/2009

Meter Reading: 98,406.00

Problem?

B inspection and repairs (outside agency-al packer ford)

Parts

Quantity

Task performed:

B-Inspection/repairs - Al Packer j

NO PARTS USED

Vendor? AL PACKER FORD

Workorder: V22916

In Date: 04/29/2009
Close Date: 05/11/2009

Meter Reading: 100,186.00

Problem?

B inspection... Al Packer Ford

Parts

Quantity

Task performed:

B inspection...Al Packer Ford

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155817

* FULLSIZE 4X4 SUV

Workorder: V23303

In Date: 05/15/2009
Close Date: 05/15/2009

Meter Reading: 100,689.00

Problem?

repair ABS light on (outside agency-al packer ford) DC1

Parts

Quantity

Task performed:

NO PARTS USED

Vendor? AL PACKER

Workorder: V23265

In Date: 05/13/2009
Close Date: 05/20/2009

Meter Reading: 100,689.00

Problem?

antilock brake lt on dc 1

Parts

Quantity

Task performed:

Chk for codes; code reader unable to hookup; wire bad in sys; was told to let run. j

NO PARTS USED

Workorder: V23653

In Date: 05/29/2009
Close Date: 06/22/2009

Meter Reading: 100,689.00

Problem?

a inspection and repairs as needed sdc 5

Parts

Quantity

Task performed:

A-Inspection 2. Replcd complete harness & fab to veh; also rep connection at fue panel under hood. j

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155817

* FULLSIZE 4X4 SUV

Workorder: V25830

In Date: 08/27/2009
Close Date: 09/03/2009

Meter Reading: 101,816.00

Problem?

A inspection, backup alarm stays on(currently unplugged), seems to shift intermittantly, radio comes on at different times, siren 10-7

Task performed:

A-Inspection 2. Diss light bar & replc corner strobe light asy. 3. Rem both frnt headlight asys & replc (2) clear strobe bulbs. 4. Replc wiper blades; frnt/rear. 5. Replc (1) brkn & (1) msng hub cap. 6. Diss panels on rear hatch & rep connector of wiring to both interior hatch ights. 7. Rep wiring at switch asy of dash for power to rear wiper. 8. Replc msng washer bottle cap & refill sys. 9. R/Rear quarter panel emerg light inop; Rem light fixture frm panel & test for power-ok; install newer style LED fixture; some wiring mod was ness to install new style. 10. Rear action area maplight inop; ren rear radio access panel to gain access to maplight wiring & fuses; fnd pinched wiring thus a blown fuse; replc fuse & rep. 11. Siren inop; pull siren head from center console & chk wiring-no power; trace back wiring frm center console to batry & fnd badly pinched wire in kick panel; mk wire rep; rerought wire & replc burnt out fuse. 12. Backup fore warn alarm does not operate properly; (stays on all the time); C/O entire sys & fnd (1) ckt was wired wrong; mk up new wire harness; install/retest-now ok. j

Parts

Quantity

22-51950-000HEADLINER RETAINER PLUG	1
25731418WASHER BOTTLE CAP	1
50R03ZRRRLIGHT 500 TIR LED	1
80350DOME LIGHT	1
91-16USE 31-16 WIPER BLADE	1
91-22WIPER BLADE	2
9597161HUB CAP	2
9UTUBELINEAR REF CORNER	1
S30HACSTROBE BULB	2

Workorder: V26366

In Date: 09/21/2009
Close Date: 09/28/2009

Meter Reading: 101,816.00

Problem?

A inspection and repairs (from 23)

Task performed:

A-Inspection 2. Replcd valve stem caps & adj air press in tires. 3. Chkd fo rubbing node; fnd no problems; wheel bearings & drive line ok. j

Parts

Quantity

435 VALVE CAP	4
---------------	---



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155817

* FULLSIZE 4X4 SUV

Workorder: V26887

In Date: 10/14/2009
Close Date: 11/30/2009

Meter Reading: 101,816.00

Problem?

A INSPECTION AND REPAIRS AS NEEDED

Task performed:

A-Inspection 2. C/O light; fnd no power; fnd brkn wire on unit; replc connection. 3. Add washer fluid. j

Parts

Quantity

NO PARTS USED

Workorder: V21786

In Date: 03/13/2009
Close Date: 12/01/2009

Meter Reading: 97,343.00

Problem?

forewarn works in drive (presently unplugged in rear)

Task performed:

repaired on 25830

Parts

Quantity

NO PARTS USED

Workorder: V28317

In Date: 12/14/2009
Close Date: 12/21/2009

Meter Reading: 105,121.00

Problem?

A inspection and repairs, a/c 10-7

Task performed:

A-Inspection 2. Install shutoff switch for btrys. 3. Charge btrys, chk charging sys. 4. Rem flywheel cover chk torque connector to flywheel bolts; all tight; flex to crnk shaft; poss cracked; sent to Al Packer Ford. j

Parts

Quantity

M-284-01SWITCH BATTERY MASTER

1



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155817

* FULLSIZE 4X4 SUV

Workorder: V28356

In Date: 12/15/2009 Meter Reading: 105,121.00
Close Date: 01/15/2010

Problem?

noise coming from flex plate

Parts ----- Quantity -----

Task performed:

Noise coming from flex plate - Al Packer j

NO PARTS USED

Vendor? AL PACKER

Workorder: V29286

In Date: 01/20/2010 Meter Reading: 105,678.00
Close Date: 02/19/2010

Problem?

A inspection and repairs (from 23)

Parts ----- Quantity -----

Task performed:

A-Inspection 2. Repair strobelights. 3. Rep take down light. j

02-0363769255D400 LED SPLIT RED RED 1

Workorder: V30228

In Date: 02/25/2010 Meter Reading: 106,225.00
Close Date: 02/25/2010

Problem?

B inspection and repairs (from sta 19)(performed by-al packer ford)

Parts ----- Quantity -----

Task performed:

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155817

* FULLSIZE 4X4 SUV

Workorder: V29755

In Date: 02/17/2010
Close Date: 03/19/2010

Meter Reading: 106,225.00

Problem?

B inspection and repairs (from sta 19)(outside agency-al packer ford)

Parts

Quantity

Task performed:

B-Inspection/repairs - Al Packer j

NO PARTS USED

Vendor? AL PACKER

Workorder: V30755

In Date: 03/15/2010
Close Date: 03/29/2010

Meter Reading: 106,452.00

Problem?

wont start D/C 9

Parts

Quantity

Task performed:

REPLACE (2) BTRYS. J

78-72BATTERY GROUP 78

2

BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER B/

2

Workorder: V27992

In Date: 11/30/2009
Close Date: 04/14/2010

Meter Reading: 101,816.00

Problem?

a inspection and repairs as needed sdc

Parts

Quantity

Task performed:

A inspection repair marker It

9UTUBELINEAR REF CORNER

2



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155817

* FULLSIZE 4X4 SUV

Workorder: V31872

In Date: 04/29/2010 Meter Reading: 105,678.00
Close Date: 05/05/2010

Problem?

A inspection and repairs (from 57)

Parts ----- Quantity -----

Task performed:

A-Inspection 2. Tighten driver seat. j

NO PARTS USED

Workorder: V31504

In Date: 04/13/2010 Meter Reading: 105,678.00
Close Date: 05/07/2010

Problem?

A inspection and repairs (from 42)

Parts ----- Quantity -----

Task performed:

road test & A-Inspection 2. Complete A-inspection 3. Fill washer fluid reservoir & add bug solvent. 4. Push bar strobes out; replc strobe lite; thir brake lite out; fnd loose connection; securely fasten connection. j

50R00FRRFLASHER RED LED FLANGED 1

Workorder: V31881

In Date: 04/29/2010 Meter Reading: 108,872.00
Close Date: 05/13/2010

Problem?

repair window, lock, and mirror on pass door, check antenna on radio (from sta 57)(outside agency-Shumacher Buick)

Parts ----- Quantity -----

Task performed:

Repair window, lock & mirror on pass door; chk antenna on radio - Shumacher Buick. j

NO PARTS USED

Vendor? 1



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155817

* FULLSIZE 4X4 SUV

Workorder: V33146

In Date: 06/25/2010
Close Date: 06/30/2010

Meter Reading: 105,678.00

Problem?

A inspection and repairs (from 23)

Parts

Quantity

Task performed:

A-Inspection j

NO PARTS USED

Workorder: V34379

In Date: 08/19/2010
Close Date: 08/26/2010

Meter Reading: 111,164.00

Problem?

A inspection and repairs (from 23)

Parts

Quantity

Task performed:

A-Inspection & road test. 2. Top off windshield wiper fluid reservoir & adding solvent. ja

NO PARTS USED

Workorder: V34567

In Date: 08/27/2010
Close Date: 09/03/2010

Meter Reading: 106,452.00

Problem?

wont start

Parts

Quantity

Task performed:

NPF. js

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155817

* FULLSIZE 4X4 SUV

Workorder: V34679

In Date: 09/01/2010
Close Date: 09/29/2010

Meter Reading: 111,173.00

Problem?

B inspection and repairs(outside agency-al packer ford)

Parts ----- Quantity -----

Task performed:

B-Inspection/repairs - Al Packer j

NO PARTS USED

Vendor? AL PACKER

Workorder: V34923

In Date: 09/13/2010
Close Date: 09/29/2010

Meter Reading: 111,205.00

Problem?

A INSPECTION, repair a/c

Parts ----- Quantity -----

Task performed:

1. Test A/C; avac, lileak test, charge. 2. A-Inspection 3. Replc strobe bulb.

01046301700S30HACP STROBE CLEAR 1

Workorder: V34737

In Date: 09/03/2010
Close Date: 10/07/2010

Meter Reading: 111,189.00

Problem?

A INSPECTION

Parts ----- Quantity -----

Task performed:

1. a service jab

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155817

* FULLSIZE 4X4 SUV

Workorder: V35133

In Date: 09/23/2010
Close Date: 10/18/2010

Meter Reading: 111,384.00

Problem?

A/C inop ,exhaust leak

Task performed:

A-Inspection 2. Inspect exh sys; brkn belts - fnd (2) left side; tightened. 3. Test A/C sys - order parts. 4. Replc ____ control module. 5. Rem exh manifold, left/right; rem (3) brkn bolts; replc exh flange gskts. 6. Install spark plug. 7. Install exh manifold gskts. 8. replc temp sensor. 9. Mnt tire & inner fender. 10. Rep brkn heater hose. j

Parts	Quantity
11518860EXH MANIFOLD BOLT	12
12068814WATER TEMP SENSOR	1
12558573EXH MANIFOLD GASKET	2
12608814FITTING HEATER CORE	1
15077362EXH FLANGE GASKET	2
21997352A/C CONTROL HEAD	1
41-110SPARK PLUGS 6.0 SUBURBAN	8
748HHSPARK PLUG WIRE SET 04 GMC	1
S448GAUGE TIRE TREAD DEPTH	1

Workorder: V31263

In Date: 04/05/2010
Close Date: 10/19/2010

Meter Reading: 101,816.00

Problem?

power window inop Dc9

Task performed:

Completed j

Parts	Quantity
19115820DOOR SWITCH	1
19179942WINDOW MOTOR	1
L PLACARDLARGE SIDE PLACARD	4



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155817

* FULLSIZE 4X4 SUV

Workorder: V35070

In Date: 09/20/2010
Close Date: 10/20/2010

Meter Reading: 111,298.00

Problem?

Vehicle blowing warm air in the front vents. SDC AT 57

Parts

Quantity

Task performed:

Chkd A/C; fnd unit blowing cold. j

NO PARTS USED

Workorder: V36154

In Date: 11/03/2010
Close Date: 11/17/2010

Meter Reading: 111,384.00

Problem?

Master battery switch getting hot, a/c quit D/C 2

Parts

Quantity

Task performed:

Problem as abo br; gnf brty loodr & on btry; tighten cable; ok, problem gone. j

NO PARTS USED

Workorder: V38890

In Date: 03/01/2011
Close Date: 03/09/2011

Meter Reading: 113,612.00

Problem?

A inspection

Parts

Quantity

Task performed:

A-Inspection & road test 2. Washer fluid low; add fluid & bug solvent. j

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155817

* FULLSIZE 4X4 SUV

Workorder: V39012

In Date: 03/07/2011
Close Date: 03/29/2011

Meter Reading: 114,521.00

Problem?

A inspection, headlight out, R/F wheel well plastic has missing fastners

Task performed:

A-Inspection 2. Replc R/frnt headlight bulb. 3. Resecure R/frnt inner whee wall. j

Parts ----- Quantity

90069006 BULB ASSY	1
--------------------	---

Workorder: V40322

In Date: 05/04/2011
Close Date: 05/26/2011

Meter Reading: 115,096.00

Problem?

A inspection.

Task performed:

A-Inspection 2. R/R rear door struts. j

Parts ----- Quantity

15147257L/H DOOR STRUT	1
15147258R/H DOOR STRUT	1

Workorder: V40808

In Date: 05/23/2011
Close Date: 06/03/2011

Meter Reading: 115,484.00

Problem?

B Inspection at Roger Dean

Task performed:

B-Inspection - Roger Dean h

Parts ----- Quantity

NO PARTS USED	
---------------	--

Vendor? ROGER DEAN



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155817

* FULLSIZE 4X4 SUV

Workorder: V45455

In Date: 11/28/2011 Meter Reading: 120,223.00
Close Date: 11/30/2011

Problem?

ON CALL TRANS MAKES NOISE DC7

Parts ----- Quantity -----

Task performed:

spare unit dc 7 was in, had problems swapped into another unit

NO PARTS USED

Workorder: V45448

In Date: 11/28/2011 Meter Reading: 120,223.00
Close Date: 12/01/2011

Problem?

B INSPECTION ROGER DEAN

Parts ----- Quantity -----

Task performed:

1. B INSPECTION ROGER DEAN 2. REPLACE TRANSFER CASE

NO PARTS USED

Vendor? ROGER DEAN

Workorder: V45563

In Date: 12/01/2011 Meter Reading: 120,223.00
Close Date: 12/28/2011

Problem?

REPLACE TIRES

Parts ----- Quantity -----

Task performed:

REPLACE TIRES.

NO PARTS USED

Vendor? CALLAGHAN TIRE



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155817

* FULLSIZE 4X4 SUV

Workorder: V46481

In Date: 01/11/2012
Close Date: 01/23/2012

Meter Reading: 121,192.00

Problem?

Tail light inop. DC9

Task performed:

1. REPLACED REAR TAIL LIGHT. 2. REAR DOOR LEAKS, REPLACED DOOR GASKET. 3. REAR DOOR DOES NOT STAY UP - REPLACED PISTONS.

Parts	Quantity
15147257L/H DOOR STRUT	1
15147258R/H DOOR STRUT	1
15768195REAR WINDOW SEAL	1
15832091TAIL LIGHT ASSBY	1
15832092RIGHT REAR LAMP ASSBY	1
VTX609RVERTEX SINGLE RED	2

Workorder: V47058

In Date: 02/03/2012
Close Date: 02/06/2012

Meter Reading: 121,756.00

Problem?

A inspection.

Task performed:

1. A-INSPECTION 2. LOW OIL - CHECK FOR LEAKS NONE FOUND ADD OIL TO FULL LEVEL.

Parts	Quantity
NO PARTS USED	



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155817

* FULLSIZE 4X4 SUV

Workorder: V49207

In Date: 05/09/2012
Close Date: 05/18/2012

Meter Reading: 66,203.00

Problem?

rear door piston broken

Task performed:

REPLACED DOOR PISTONS.

Parts	Quantity
15029087WINDOW STRUT	1
15029088WINDOW STRUT	1
15147257L/H DOOR STRUT	1
15147258R/H DOOR STRUT	1

Workorder: V50035

In Date: 06/11/2012
Close Date: 06/11/2012

Meter Reading: 124,214.00

Problem?

CHECK ENGINE LIGHT ON

Task performed:

CHECK ENGINE LIGHT ON.

Parts	Quantity
NO PARTS USED	

Vendor? ROGER DEAN CHEVROLE

Workorder: V49761

In Date: 06/11/2012
Close Date: 06/13/2012

Meter Reading: 66,203.00

Problem?

green command light

Task performed:

PARTS ONLY NO LABOR.

Parts	Quantity
800-CLPG800-CLPG STROBE LIGHT	1



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155817

* FULLSIZE 4X4 SUV

Workorder: V49558

In Date: 05/22/2012
Close Date: 09/06/2012

Meter Reading: 124,200.00

Problem?

B inspection - Roger Dean

Task performed:

B inspection replace exhaust manifold gaskets replace front brake pads and rotors replaced I-shaft replaced air filter replaced wiper blades replaced a/c cycling switch

Vendor? AL PACKER

Parts

Quantity

NO PARTS USED

Workorder: V51613

In Date: 08/15/2012
Close Date: 09/14/2012

Meter Reading: 124,599.00

Problem?

wont start sta 23

Task performed:

1. JUMP START UNIT BROUGHT INTO SHOP REPLACED BOTH BATT REPLACED TERMAL ENDS FOR CHARGER WIRING. ALSO CHKD CHARGING.

Parts

Quantity

78-72BATTERY GROUP 78

2

BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER B/

2

Workorder: V51892

In Date: 08/27/2012
Close Date: 09/20/2012

Meter Reading: 124,599.00

Problem?

A INSPECTION

Task performed:

1. A INSPECTION AND WASHER FLUID AND AIR TIRES TO PROPER PSI. TIGHTEN POS BATTERYPOAT/CABLES REPLACED LICENSE RATE BULB.

Parts

Quantity

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155817

* FULLSIZE 4X4 SUV

Workorder: V51977

In Date: 08/29/2012
Close Date: 09/24/2012

Meter Reading: 124,599.00

Problem?

A/C INTERMITTENT.

Parts

Quantity

Task performed:

COULD NOT DUPLICATE CONCERN AT THIS TIME NO REPAIR.

NO PARTS USED

Workorder: V52374

In Date: 09/14/2012
Close Date: 09/25/2012

Meter Reading: 125,059.00

Problem?

DC9 belts squealing

Parts

Quantity

Task performed:

REPLACED BELTS AND ROAD TESTED.

NO PARTS USED

Workorder: V52605

In Date: 09/24/2012
Close Date: 09/27/2012

Meter Reading:

Problem?

Bottom hinge to storage box behind driver's seat is broken. Vehicle is being utilized as DC1 currently.

Parts

Quantity

Task performed:

MARKED HINGE ON DRAWER WILL ORDER PARTS.

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155817

* FULLSIZE 4X4 SUV

Workorder: V52645

In Date: 09/26/2012
Close Date: 10/18/2012

Meter Reading:

Problem?

A/C works intermittently. Blows very hot when started working again.

Parts

Quantity

Task performed:

NO PARTS USED

Vendor? ROGER DEAN

Workorder: V53641

In Date: 11/08/2012
Close Date: 11/29/2012

Meter Reading:

Problem?

Looks like a slow leak from rear seal. DC 2

Parts

Quantity

Task performed:

TRUCK AT SHOP FOR REPAIR.

NO PARTS USED

Workorder: V54225

In Date: 12/05/2012
Close Date: 12/10/2012

Meter Reading:

Problem?

dc2 needs engine oil, it half way to empty

Parts

Quantity

Task performed:

DONE ON 54226.

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155817

* FULLSIZE 4X4 SUV

Workorder: V54226

In Date: 12/05/2012
Close Date: 01/10/2013

Meter Reading:

Problem?

dc2 needs engine oil, it half way to empty. needs antifreeze and windshield washer fluid... rear main seal has bad leak

Parts

Quantity

Task performed:

ADDED FLUIDS TO CORRECT LEVELS.

15W40QSYN OIL QT

3

ALA00350-50 EXTENDED LIFE COOLANT GAL

2

Workorder: V54772

In Date: 01/03/2013
Close Date: 01/14/2013

Meter Reading:

Problem?

Center "bumper grill" emergency light not functioning on Spare DC9. ATech Tommy informed of situation at the end of the business day, Wed 1/2/13 (This is an FYI Follow Up to confirm that it is not working) DC 2

Parts

Quantity

Task performed:

REPAIRED REAR TAIL BOARD SCENE LIGHTS.

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155817

* FULLSIZE 4X4 SUV

Workorder: V55067

In Date: 01/15/2013
Close Date: 01/16/2013

Meter Reading: 96,817.00

Problem?

A inspection

Task performed:

1. A INSP AIR TIRES TOP OFF FLUIDS. 2. REPLACE R/F TURN/MARKER BULB. 3. FRT AND REAR STROBES INOP- DIAGNOSE PROBLEM FOUND BAD GROUND TECHNICAL AT CONNECTOR. CUT AND CRIMP NEW PIN AND INSTALL IN NEW SOCKET TEST OK. 4. REAR SPEAKER MAKING NOISE CONSULTED WITH RANDY FROM RADIO SHOP. CHECKED SOUND COMMING OUT OF SPEAKER. VOLUME LEVEL ON SPEAKER SET TO HIGH ADJ VOLUME. 5. OIL LEAK. DIAGNOSE MOTOR RUN VEHICLE AND INSPECT FOR LEAKS LEAK AT R/R OIL PAN OR MAIN SEAL TO BE SENT TO ROGER DEAN PER STEVE REINES.

Parts

Quantity

NO PARTS USED

Workorder: V55940

In Date: 02/22/2013
Close Date: 02/25/2013

Meter Reading: 131,061.00

Problem?

A-inspection AM/FM inop

Task performed:

1. A INSPECTION. 2. TRANSMISSION OIL LEAK-CLEAN TRANSMISSION- ADD 2 QUARTS OIL AND LET UNIT RUN.

Parts

Quantity

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155817

* FULLSIZE 4X4 SUV

Workorder: V52298

In Date: 09/11/2012
Close Date: 04/08/2013

Meter Reading:

Problem?

AC while responding to call suddenly started blowing very hot DC 9

Task performed:

Parts	Quantity
6C3Z15442ALIGHT CAB MARKER F450	1
K040378BELT SUBURBANS 2002/2003	1
K060935BELT	1

Workorder: V57897

In Date: 05/22/2013
Close Date: 05/28/2013

Meter Reading: 132,041.00

Problem?

A/C blows heat intermittently

Task performed:

1. HAD TO JUMP START TRUCK BATT DEAD-TEST DROVE- FOUND PASS VENTS BLOWING HOT- TROUBLESHOOT BAD CONTROL HEAI ORDERED CONTROL HEAD. 2. REPALCE A/C CONTROL HEAD ASSEMBLE- REMOVED TRIM PANEL AND CONTROL HEAD- REPLACED CONTROLLED- REASSEMBLED- TEST DROVE- CHK OK.

Parts	Quantity
21997352A/C CONTROL HEAD	1



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155817

* FULLSIZE 4X4 SUV

Workorder: V58400

In Date: 06/13/2013
Close Date: 07/02/2013

Meter Reading: 132,041.00

Problem?

A/C blows heat intermittently, control head as been replaced before

Parts

Quantity

Task performed:

NO PARTS USED

Vendor? ROGER DEAN

Workorder: V59015

In Date: 07/11/2013
Close Date: 07/25/2013

Meter Reading: 132,713.00

Problem?

B-inspection Not running properly

Parts

Quantity

Task performed:

B-inspection Replace ECU

NO PARTS USED

Vendor? ROGER DEAN

Workorder: V59860

In Date: 08/16/2013
Close Date: 08/21/2013

Meter Reading: 132,606.00

Problem?

Swap DC-1 into spare and wire TIC and battery charger

Parts

Quantity

Task performed:

MOVE TIC CHARGER AND BATTERY CHARGER WRENCH TRUCK TC DPARE DC-1.

5648056480 PLUG-POWER/ACCESS. 2



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155817

* FULLSIZE 4X4 SUV

Workorder: V60179

In Date: 08/30/2013
Close Date: 09/05/2013

Meter Reading: 133,234.00

Problem?

Check for oil leak at St28

Parts

Quantity

Task performed:

DRIVER COMPLAINS OF OIL LEAK ON BAY FLOOR. CHECKED FOR LEAK. INFORMED CHIEF WE ARE GOING TO SWAP OUT TRUCK.

NO PARTS USED

Workorder: V61501

In Date: 10/24/2013
Close Date: 10/24/2013

Meter Reading: 133,905.00

Problem?

REPAIR OIL LEAKS

Parts

Quantity

Task performed:

REPLACE OIL PAN GASKETS REPAIR COOLANT LEAK

NO PARTS USED

Vendor? ROGER DEAN



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155817

* FULLSIZE 4X4 SUV

Workorder: V61960

In Date: 11/12/2013
Close Date: 11/20/2013

Meter Reading: 133,905.00

Problem?

Restore headlights

Task performed:

1. CLEAN ALL OILY AREAS ON VEH. ROAD TEST VEH AND RECHECK AREAS. OIL PAN GASKET OR REAR MAIN SEAL OR OIL GALLEY PLUGS AT REMOVE ENG BLOCK LEAKING. 2. BUFF ALL LENSES ON LIGHT BAR. 3. MOVE VEH TO BAY WITH L.V HOIST LIFT VEH R&R FLYWHEEL COVER TO CHECK OIL LEAK. 4. RESTORE HEADLIGHT LENSES.

Parts

Quantity

39045HEADLITE KIT WITH SEALER

1

Workorder: V62418

In Date: 12/02/2013
Close Date: 12/02/2013

Meter Reading: 133,905.00

Problem?

Engine oil leak

Task performed:

Replaced rear main seal Replaced steering box Replaced sensor

Parts

Quantity

NO PARTS USED

Vendor? ROGER DEAN



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155817

* FULLSIZE 4X4 SUV

Workorder: V63017

In Date: 12/30/2013
Close Date: 12/31/2013

Meter Reading: 134,619.00

Problem?

Burning smell when using emergency lighting

Parts ----- Quantity -----

Task performed:

BURNING SMELL WHEN USING EMERGENCY LIGHTING, MAXI FUSE WIRING SHORTED, REPAIRED WIRING.

NO PARTS USED

Workorder: V62636

In Date: 12/11/2013
Close Date: 01/02/2014

Meter Reading:

Problem?

DC9 spare was not starting and the inverter was not charging any of the auxillary charging systems. Atech came out, swapped out 2 batteries and rewired the rear harness with success.

Parts ----- Quantity -----

Task performed:

BATTERIES DEAD REPLACED CHECKED ALTERNATOR AND SHORE CHARGER OUTPUT OK. DC ASKED ABOUT POWER TO REAR AUX BOX CHARGERS. ADDED POWER AND GROUND TO POWER CHARGERS.

78-72BATTERY GROUP 78	2
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER B/	2

Workorder: V64945

In Date: 03/15/2014
Close Date: 03/27/2014

Meter Reading:

Problem?

FUEL GAUGE READING DEAD EMPTY WITH FULL TANK. RIGHT SIDE REVERSE LIGHT OUT ALSO. DC 1

Parts ----- Quantity -----

Task performed:

REPAIRED BY OUTSIDE VENDOR.

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155817

* FULLSIZE 4X4 SUV

Workorder: V65181

In Date: 03/24/2014
Close Date: 03/28/2014

Meter Reading:

Problem?

Need new windshield wiper blade on passenger side. DC 1

Parts	Quantity
-------	----------

Task performed:

REPLACED BLADES.

91-22WIPER BLADE	2
------------------	---

Workorder: V66965

In Date: 06/03/2014
Close Date: 06/03/2014

Meter Reading: 135,935.00

Problem?

B-inspection

Parts	Quantity
-------	----------

Task performed:

B-inspection Inspect brakes and rotate tires Install steering wheel cover

NO PARTS USED	
---------------	--

Vendor? AL PACKER

Workorder: V67419

In Date: 06/24/2014
Close Date: 06/25/2014

Meter Reading: 135,867.00

Problem?

replace right front

Parts	Quantity
-------	----------

Task performed:

replace right front

NO PARTS USED	
---------------	--

Vendor? BOULEVARD TIRE



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155817

* FULLSIZE 4X4 SUV

Workorder: V67821

In Date: 07/10/2014
Close Date: 07/11/2014

Meter Reading: 135,867.00

Problem?

dead battery - clean battery terminals

Parts

Quantity

Task performed:

jump started truck in lot. changed batteries and load tested. (tested good).
cleaned terminals and cable ends. Checked fluids.

NO PARTS USED

Workorder: V70748

In Date: 11/06/2014
Close Date: 11/24/2014

Meter Reading: 135,867.00

Problem?

Fuel leak from rear near vapor recovery solenoid

Parts

Quantity

Task performed:

1. Check out truck and repair lights out on unit. Swap out unit with DC. 2.
Swap out DC unit equipment. 3. Sent to Al Packer Ford for repair. Fuel
leak near rear bumper. Change purge valve.

NO PARTS USED

Vendor? AL PACKER

Workorder: V70207

In Date: 10/16/2014
Close Date: 01/23/2015

Meter Reading: 136,416.00

Problem?

B inspection Spare DC

Parts

Quantity

Task performed:

B service oil and filter rotate tires replace wiper blades replace rear
shocks check engine light - repaired evap system

NO PARTS USED

Vendor? AL PACKER



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155817

* FULLSIZE 4X4 SUV

Workorder: V73550

In Date: 03/02/2015
Close Date: 04/02/2015

Meter Reading: 135,867.00

Problem?

1 strobe inop

Parts ----- Quantity -----

Task performed:

1. Install new strobe- Repair loose connector.

01046301700S30HACP STROBE CLEAR	1
3157TAIL LIGHT BULBS	1

Workorder: V73590

In Date: 03/03/2015
Close Date: 04/24/2015

Meter Reading: 136,626.00

Problem?

Engine runs rough

Parts ----- Quantity -----

Task performed:

1. Cleaned throttle body, will monitor.

FRT 27150FREIGHT CHARGE	1
MCS-CUPHOLD2DUAL CUP HOLDER	1