

3/4/2026  
11:22:46 AM

**Palm Beach County Fleet Management Asset Maintenance History**  
**10201958 2017 FORD TRANSIT T250 Van, 3/4 Ton, Cargo**

---

**Total Hours: 190.20 Labor: 13,368.60 Parts: 11,048.96 Comm: 5,449.57 Charged: 29867.13**

---

**Work Order:** 1612666      **Meter:** 321      **In Date:** 12/12/2016      **Closed:** 12/12/2016  
**Problem:** 1061 - Pre Delivery Inspection

**Work Completed**

- Pre Delivery Inspection

Hours: 2.00      Comm: 0.00      Labor: 120.00      Parts: 0.00      Total: 120.00

---

**Work Order:** 1613194      **Meter:** 330      **In Date:** 12/29/2016      **Closed:** 01/12/2017  
**Problem:** Install four corner strobes.

**Work Completed**

- Install four corner strobes.fabricate and install wiring and switch.  
- Shop Supplies

**Parts Issued**

**Quantity**

Vtx609a Led Strobe Am	2.00
Vtx609c Led Strobe Cl	2.00
Clr Rtv Silcn Sealant	1.00
Rocker Led Blk Ambe	1.00
Vinyl Electrical Tape	1.00
Vertex Flange Mount Blk	2.00
Fab Loom-split Poly	30.00
Shop Supplies	1.00

Hours: 8.00      Comm: 0.00      Labor: 480.00      Parts: 507.82      Total: 987.82

---

**Work Order:** 1702340      **Meter:** 1666      **In Date:** 03/08/2017      **Closed:** 03/16/2017  
**Problem:** Right rear tire going flat.

**Work Completed**

- Repair and balance right rear tire.  
- Shop Supplies

**Parts Issued**

**Quantity**

Shop Supplies	1.00
---------------	------

Hours: 1.00      Comm: 0.00      Labor: 60.00      Parts: 2.00      Total: 62.00

3/4/2026  
11:22:46 AM

**Palm Beach County Fleet Management Asset Maintenance History**  
**10201958 2017 FORD TRANSIT T250 Van, 3/4 Ton, Cargo**

---

**Work Order:** 1705989      **Meter:** 4334      **In Date:** 06/16/2017      **Closed:** 06/26/2017  
**Problem:** P.M. service and damage to left side of van.

**Work Completed**

- P.m. Service.
- Rotate and balance tires.
- Shop Supplies

**Parts Issued**

**Quantity**

5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
Washer Fluid Concentr	1.00
Used Fire X Refurbished	1.00
Shop Supplies	1.00

Hours: 3.75      Comm: 0.00      Labor: 225.00      Parts: 34.40      Total: 259.40

---

**Work Order:** 1706627      **Meter:** 4357      **In Date:** 06/20/2017      **Closed:** 07/06/2017  
**Problem:** Damage to left side of body above wheel opening at crease

**Work Completed**

- Damage to left side of body above wheel opening at crease

Hours: 0.00      Comm: 501.00      Labor: 0.00      Parts: 0.00      Total: 501.00

---

**Work Order:** 1709863      **Meter:** 8230      **In Date:** 10/10/2017      **Closed:** 10/17/2017  
**Problem:** Repair flat tire.

**Work Completed**

- Repair right rear tire .remount and balance.
- Shop Supplies

**Parts Issued**

**Quantity**

Shop Supplies	1.00
---------------	------

Hours: 1.00      Comm: 0.00      Labor: 60.00      Parts: 2.00      Total: 62.00

3/4/2026  
11:22:46 AM

**Palm Beach County Fleet Management Asset Maintenance History**  
**10201958 2017 FORD TRANSIT T250 Van, 3/4 Ton, Cargo**

**Work Order:** 1801021      **Meter:** 12366      **In Date:** 01/26/2018      **Closed:** 01/30/2018  
**Problem:** P.M. service.

**Work Completed**

- P.m. service.
- Check and inspect left rear broken tail lamp assembly.fabricate and mount strobe bulb in new tail lamp lens.
- Rotate and high speed balance all four wheels.nitrogen fill all.
- Shop Supplies

**Parts Issued**

**Quantity**

5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
Wiper Blade	1.00
Wiper Blade	1.00
Washer Fluid Concentr	1.00
Lamp Asy	1.00
Clr Rtv Silcn Sealant	1.00
Shop Supplies	1.00

Hours: 6.25

Comm: 0.00

Labor: 375.00      Parts: 299.03      Total: 674.03

**Work Order:** 1807667      **Meter:** 16669      **In Date:** 07/27/2018      **Closed:** 08/06/2018  
**Problem:** PM Service, Recall.

**Work Completed**

- P.m. service.
- Replace all four tires. Balance and nitrogen fill all tires.
- Complete front end alignment and road test.
- Remove and dry out right rear tail light lens and reseal strobe bulb.
- Transport to and from dealer for recalls 17s15 and 17s34 .
- Shop Supplies

**Parts Issued**

**Quantity**

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
Washer Fluid Concentr	1.00
Floor Mat-2pc Rub Bk	1.00
Used Fire X Refurbished	1.00
235/65/16 Tire Hankook	4.00
Shop Supplies	1.00
Tire Disposal Fee	4.00

Hours: 11.00

Comm: 0.00

Labor: 660.00      Parts: 1,093.93      Total: 1,753.93





3/4/2026  
11:22:46 AM

**Palm Beach County Fleet Management Asset Maintenance History**  
**10201958 2017 FORD TRANSIT T250 Van, 3/4 Ton, Cargo**

**Work Order:** 2008152

**Meter:** 37427

**In Date:** 08/14/2020 **Closed:** 08/19/2020

**Problem:** PM Service,

**Work Completed**

- P.m. service.
- Replace cabin air filter and clean fresh air intake .
- Replace three tires . Rotate and balance all four tires . Nitrofill all.
- Perform complete front end alignment and road test .
- Secure fire extinguisher bracket to floor .
- Shop Supplies

**Parts Issued**

**Quantity**

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
Wiper Blade	1.00
Wiper Blade	1.00
Washer Fluid Concentr	1.00
Used Fire X Refurbished	1.00
Cabin Air Filter	1.00
235/65/16 Tire Hankook	3.00
Shop Supplies	1.00
Tire Disposal Fee	3.00

Hours: 9.30

Comm: 0.00

Labor: 678.90

Parts: 1,006.78

Total: 1,685.68

3/4/2026  
11:22:46 AM

**Palm Beach County Fleet Management Asset Maintenance History**  
**10201958 2017 FORD TRANSIT T250 Van, 3/4 Ton, Cargo**

**Work Order:** 2101272

**Meter:** 45415

**In Date:** 02/03/2021 **Closed:** 02/11/2021

**Problem:** bridge Darwin, van is over due for PM and side door inop .

**Work Completed**

- Preventive Maint. Service
- 1 tire worn down to 4/32nds min. Remove and replace 1 tire with new. Rotate and balance all other tires. Nitrogen fill and reset Tpms.
- Rr side door will not open. Operator mounted water jug inside door. Cable is unlatched from lock. Remove door trim to access bolts. Remove mounting bolts and remove stuck door latch assembly. Cut old latch off. Replace latch and stricker w new.
- Service rear brakes. Both rear brake pads worn below min spec. Remove and replace both rear brake pads, rotors, and clean/ lube calipers. Reassemble. Verify brake operations
- Shop Supplies

**Parts Issued**

**Quantity**

Rear Brake Pad Set	1.00
Rotor Rear	2.00
Non-chlor Brake Clnr	2.00
Brk Fluid Dot 4-32oz	1.00
235/65/16 Tire Hankook	1.00
Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
Wiper Blade	1.00
Wiper Blade	1.00
Washer Fluid Concentr	1.00
Striker	1.00
Latch	1.00
Shop Supplies	1.00
Tire Disposal Fee	1.00

Hours: 13.00

Comm: 0.00

Labor: 949.00

Parts: 728.36

Total: 1,677.36

3/4/2026  
11:22:46 AM

**Palm Beach County Fleet Management Asset Maintenance History**  
**10201958 2017 FORD TRANSIT T250 Van, 3/4 Ton, Cargo**

**Work Order:** 2107447      **Meter:** 52341      **In Date:** 07/09/2021      **Closed:** 07/14/2021  
**Problem:** PM Service.

**Work Completed**

- Preventive Maint. Service
- Rotate and speed balance all, nitro fill
- Inspect all brakes, R & I new front Brakes, service caliper slide pins, resurface rotors, bleed brake system, Road test
- Check and replace driver side outside mirror, broken
- Shop Supplies

**Parts Issued**

**Quantity**

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
Wiper Blade	1.00
Wiper Blade	1.00
Washer Fluid Concentr	1.00
Brk Fluid Dot 4-12oz	1.00
Non-chlor Brake Clnr	1.00
Brake Pad	1.00
Mirror Glas	1.00
Used Fire X Refurbished	1.00
Shop Supplies	1.00

Hours: 9.50

Comm: 0.00

Labor: 693.50      Parts: 155.19      Total: 848.69

**Work Order:** 2113213      **Meter:** 59587      **In Date:** 12/15/2021      **Closed:** 12/20/2021  
**Problem:** PM Service. Bridge on-call vehicle if possible can get back soon recall 19S38 , brake noise and pulsation .

**Work Completed**

- Preventive Maint. Service , Top off trans fluid
- Rotate and speed balance, nitro fill
- Check and replace cabin filter
- Check all brakes, R & I New front brake pads, Resurface rotors, bleed brake system, road test
- Transport to and from dealer for recall 19s38 .
- Shop Supplies

**Parts Issued**

**Quantity**

5w20 Engine Oil	6.00
Filter	1.00
Washer Fluid Concentr	1.00
Wiper Blade	1.00
Wiper Blade	1.00
Cabin Air Filter	1.00
Brk Fluid Dot 4-12oz	1.00
Brake Pad	1.00
Shop Supplies	1.00

Hours: 11.50

Comm: 0.00

Labor: 839.50      Parts: 130.79      Total: 970.29

3/4/2026  
11:22:46 AM

**Palm Beach County Fleet Management Asset Maintenance History**  
**10201958 2017 FORD TRANSIT T250 Van, 3/4 Ton, Cargo**

---

**Work Order:** 2205761      **Meter:** 66567      **In Date:** 05/31/2022      **Closed:** 06/01/2022  
**Problem:** Bridge Darwin, battery is going bad

**Work Completed**

- check battery, charging system after fully charge it fails load test , Remove left front seat to replaced defective battery .
- Shop Supplies

**Parts Issued**

**Quantity**

Battry Motorcraft	1.00
Shop Supplies	1.00

Hours: 1.50      Comm: 0.00      Labor: 109.50      Parts: 144.95      Total: 254.45

---

**Work Order:** 2206381      **Meter:** 67552      **In Date:** 06/16/2022      **Closed:** 06/21/2022  
**Problem:** PM Service. turn in today needs tire

**Work Completed**

- Preventive Maint. Service
- Front Left Tire Nail Dismount And Repair, Replaced 2 Front Tires Balance All With Nitro Fill
- Test Drive And Perform Front End Alignemnt Retest
- Shop Supplies

**Parts Issued**

**Quantity**

5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
Wiper Blade	1.00
Wiper Blade	1.00
Used Fire X Refurbished	1.00
235/65/16 Tire Hankook	2.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 8.50      Comm: 0.00      Labor: 620.50      Parts: 556.40      Total: 1,176.90

3/4/2026  
11:22:46 AM

**Palm Beach County Fleet Management Asset Maintenance History**  
**10201958 2017 FORD TRANSIT T250 Van, 3/4 Ton, Cargo**

---

**Work Order:** 2211151      **Meter:** 74098      **In Date:** 10/28/2022      **Closed:** 11/02/2022  
**Problem:** PM Service. need back soon as possible

**Work Completed**

- Perform Pm service
- R & I two new on front, Rotate and speed balance, nitro fill
- Perform front alignment, Road test
- R & I new cabin filter and clean fresh air intake
- Check noise at left front door, R & I door check
- Shop Supplies

**Parts Issued**

**Quantity**

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
Washer Fluid Concentr	1.00
Wiper Blade	1.00
Wiper Blade	1.00
235/65r16c Gy Fortitudte Ht	2.00
Cabin Filter A/c	1.00
Door Check Asy	1.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 9.80

Comm: 0.00

Labor: 715.40

Parts: 498.86

Total: 1,214.26

---

**Work Order:** 2212108      **Meter:** 74099      **In Date:** 11/01/2022      **Closed:** 12/01/2022  
**Problem:** Damage to right side, right side doors, rear doors & rear bumper.

**Work Completed**

- Damage to right side, right side doors, rear doors & rear bumper.

Hours: 0.00

Comm: 4,856.77

Labor: 0.00

Parts: 0.00

Total: 4,856.77

3/4/2026  
11:22:46 AM

**Palm Beach County Fleet Management Asset Maintenance History**  
**10201958 2017 FORD TRANSIT T250 Van, 3/4 Ton, Cargo**

**Work Order:** 2306814      **Meter:** 85110      **In Date:** 07/11/2023      **Closed:** 08/01/2023

**Problem:** PM Service flat tire will bring by and will drop off for PM Drivers rear tire, Side door latch.

**Work Completed**

- Preventive Maint. Service completed
- replaced two tires,balance and rotate all 4 . Nitro fill all.
- check,verify need brakes front and rear,replaced front & rear rotors,pads,calipers, ten rear axles bolts,flush and bleed fluid,roat test to verify normal operation
- check ,pin point test,sop and r&r side door locks by r&i all necessary parts and verify normal operation
- Shop Supplies

**Parts Issued**

**Quantity**

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
Wiper Blade	1.00
Wiper Blade	1.00
Used Fire X Refurbished	1.00
235/65/16 Tire Hankook	2.00
Brake Fl-dot 3-4 32oz	2.00
Brake Caliper	1.00
Brake Caliper	1.00
Brake Pads	1.00
Rotor	2.00
Caliper	1.00
Caliper	1.00
Seal	2.00
Bolt	10.00
Rotor Rear	2.00
Brake Pad	1.00
Latch	1.00
Latch	1.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 15.10

Comm: 0.00

Labor: 1,102.30

Parts: 1,587.64

Total: 2,689.94

3/4/2026  
11:22:46 AM

**Palm Beach County Fleet Management Asset Maintenance History**  
**10201958 2017 FORD TRANSIT T250 Van, 3/4 Ton, Cargo**

**Work Order:** 2402042

**Meter:** 93602

**In Date:** 02/27/2024 **Closed:** 03/04/2024

**Problem:** PM Service turning in today need back soon as possible

**Work Completed**

- Performed P.m. Service & Inspection.
- Performed Tire Rotation Balance On All 4 Wheels, Add Nitro Fill Reset Tpms.
- Removed Damaged Passenger Side Rear Taillight Assembly, Modify New Taillight Assembly For Strobes Then Install And Check.
- Removed And Replaced The Cabin Air Filter Clean A/c Vents & Check.
- Perform Engine Decarb Cleaning & Fuel Injection Flush. Removed Throttle Body And Clean.
- Performed Tune-up, Removed & Replaced All 6 Spark Plugs, Then Test Drove Vehicle & Check.
- Factory Back Up Camera Inop, Removed Rear Trim Panel Check For Signal Voltage & Ground. Signal Is Good. Found Camera Defective Removed & Replaced. Then Check Working As Design.
- Shop Supplies

Hours: 14.50

Comm: 0.00

**Parts Issued**

**Quantity**

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
Washer Fluid Concentr	1.00
Wiper Blade	1.00
Wiper Blade	1.00
Used Fire X Refurbished	1.00
Napa Air Filter	1.00
Cabin Air Filter	1.00
Intake Cleaner Kit	1.00
Plenum Gskt Set	1.00
Spark Plug	6.00
Lamp Assy	1.00
Backup Camera	1.00
Shop Supplies	1.00

Labor: 1,058.50

Parts: 743.34

Total: 1,801.84

3/4/2026  
11:22:46 AM

**Palm Beach County Fleet Management Asset Maintenance History**  
**10201958 2017 FORD TRANSIT T250 Van, 3/4 Ton, Cargo**

**Work Order:** 2405040

**Meter:** 97241

**In Date:** 05/21/2024 **Closed:** 05/31/2024

**Problem:** PM Service Bridge Darwin, has a low brake fuel light

**Work Completed**

- Preventive Maint. Service
- Replaced 2 tires. Rotated and balanced all 4 tires. Nitrogen filled all tires.
- Battery tested bad. Charged battery fully and retested bad. Remove driver seat to R&r bad battery. Use scan tool to reset Bms.
- Diagnose brake fluid warning light on. Found Lr caliper to be blown out and leaking fluid. Replaced Lr caliper. Resurfaced rear rotors and replaced rear pads due to fluid contamination Flush brake fluid and test drove.
- Shop Supplies

**Parts Issued**

**Quantity**

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
Wiper Blade	1.00
Wiper Blade	1.00
235/65/16 Tire Gooyer	2.00
Battry Motorcraft	1.00
Rear Caliper	1.00
Brake Pad	1.00
Brk Fluid Dot 4-32oz	1.00
Non-chlor Brake Clnr	1.00
Caliper Plate Assy	1.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 12.00

Comm: 0.00

Labor: 876.00

Parts: 844.43

Total: 1,720.43

3/4/2026  
11:22:46 AM

**Palm Beach County Fleet Management Asset Maintenance History**  
**10201958 2017 FORD TRANSIT T250 Van, 3/4 Ton, Cargo**

**Work Order:** 2503320      **Meter:** 111058      **In Date:** 04/10/2025      **Closed:** 04/17/2025  
**Problem:** PM Service . Detail

**Work Completed**

**Parts Issued**

**Quantity**

- Performed P.m. Service & Inspection.
- Mount 2 Tires Then Balance & Rotate All 4 Tires. Add Nitro Fill Reset Tpms.
- Performed Front Wheel Alignment & Test Drove Vehicle Then Check.
- Both Front Shocks Are Worn & Leaking. Removed & Replaced Both Front Shocks Then Check.
- Vehicle Is Makin A Humming Noise When Driving. Test Drove Vehicle And Found Both Front Wheel Hub Bearings Defective. Removed & Replaced Then Check. Working As Design.
- Front & Rear Brakes Below Manufacture Below Specs. Removed Both Front & Rear Brake Pads, Resurfaced Both Front Rotors, Replaced Both Rear Rotors And Axle Seals. Replaced Pads, R/r Leaking Calipe Then Bleed And Flush Entire Brake Sytem Burnish Brakes.
- Washer Fluid Leaking From Cracked Washer Fluid Resrvoir. Removed & Replaced. Then Check.
- Shop Supplies

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
Wiper Blade	1.00
Wiper Blade	1.00
235/65/16 Tire Gooyer	2.00
Hub Bearing Assy	2.00
Brake Pad	1.00
Seal	2.00
Non-chlor Brake Clnr	2.00
Brk Fluid Dot 4-32oz	1.00
Rotor Rear	2.00
Brake Pad	1.00
Used Fire X Refurbished	1.00
Front Strut Assy	2.00
Brake Caliper	1.00
Washer Reservoir Assy	1.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 27.00      Comm: 0.00      Labor: 1,971.00      Parts: 2,052.60      Total: 4,023.60

**Work Order:** 2503607      **Meter:** 111058      **In Date:** 04/17/2025      **Closed:** 04/17/2025  
**Problem:** 1 - Detail Vehicle Wash Ticket(s) Issued WO: 2503320 for: Michael Kenney

**Work Completed**

- 1 - Detail Vehicle Wash Ticket(s) Issued Wo: 2503320 for: Michael Kenney

Hours: 0.00      Comm: 91.80      Labor: 0.00      Parts: 0.00      Total: 91.80

3/4/2026  
11:22:46 AM

**Palm Beach County Fleet Management Asset Maintenance History**  
**10201958 2017 FORD TRANSIT T250 Van, 3/4 Ton, Cargo**

---

**Work Order:** 2505005      **Meter:** 112865      **In Date:** 05/29/2025      **Closed:** 06/02/2025

**Problem:** Bridge Darwin, van has no brakes and needs a side mirror is broken

**Work Completed**

**Parts Issued**

**Quantity**

- Check customer concern, Removed & Replaced leaking right rear brake caliper then bleed entire brake system. test drove vehicle and check.

Mirror Glas

1.00

Shop Supplies

1.00

- Removed & Replaced damaged Left rearview mirror insert.

- Shop Supplies

Hours: 2.00

Comm: 0.00

Labor: 146.00

Parts: 69.77

Total: 215.77

---

**Work Order:** 2505184      **Meter:** 112922      **In Date:** 06/03/2025      **Closed:** 06/04/2025

**Problem:** Brakes feel soft

**Work Completed**

**Parts Issued**

**Quantity**

- Check Concern, Performed Brake Bleeding Procedure With Scan Tool . Test Drove Vehicle And Check.

Shop Supplies

1.00

- Shop Supplies

Hours: 1.00

Comm: 0.00

Labor: 73.00

Parts: 2.65

Total: 75.65

---

**Work Order:** 2600248      **Meter:** 122548      **In Date:** 01/09/2026      **Closed:** 01/13/2026

**Problem:** Transition Prep Charge

**Work Completed**

- Transition Prep Charge

Hours: 2.00

Comm: 0.00

Labor: 146.00

Parts: 0.00

Total: 146.00

**Total Hours: 190.20**

**Total Labor: 13,368.60**

**Total Comm: 5,449.57**

**Total Parts: 11,048.96**