

3/4/2026
12:00:56 PM

Palm Beach County Fleet Management Asset Maintenance History
10208443 2018 FORD F350 Pickup, 1 Ton, 4X4

Total Hours: 185.85 Labor: 13,433.85 Parts: 15,496.16 Comm: 96.00 Charged: 29026.01

Work Order: 1810133 **Meter:** 306 **In Date:** 10/01/2018 **Closed:** 10/02/2018
Problem: pre delivery inspection

Work Completed

Parts Issued

Quantity

- pre delivery inspection
- missing hitch reducer & bar, strobes grounded to trailer wiring causing codes to come on
- Shop Supplies

Shop Supplies 1.00

Hours: 4.00 Comm: 0.00 Labor: 268.00 Parts: 3.00 Total: 271.00

Work Order: 1810394 **Meter:** 306 **In Date:** 10/09/2018 **Closed:** 10/11/2018
Problem: needs locking hitch pin

Work Completed

Parts Issued

Quantity

- parts only

Hitch Pin Lock 1.00

Hours: 0.00 Comm: 0.00 Labor: 0.00 Parts: 13.55 Total: 13.55

Work Order: 1810995 **Meter:** 1006 **In Date:** 10/25/2018 **Closed:** 10/31/2018
Problem: Replace tires with off road tires and install tool box.

Work Completed

Parts Issued

Quantity

- Replace all four tires with all terrain tires . Balance and nitrogen fill tires.
- Fabricate and install tool box .
- Shop Supplies

Lt285/70/17 Tire 4.00

Shop Supplies 1.00

Tool Box (weatherguard Defender) 1.00

Tire Disposal Fee 4.00

Hours: 4.00 Comm: 0.00 Labor: 268.00 Parts: 1,590.20 Total: 1,858.20

3/4/2026
12:00:56 PM

Palm Beach County Fleet Management Asset Maintenance History
10208443 2018 FORD F350 Pickup, 1 Ton, 4X4

Work Order: 1902323 **Meter:** 6073 **In Date:** 03/01/2019 **Closed:** 03/13/2019

Problem: PM Service, Drivers door handle comes off, Trailer disconnect alarm sounds.

Work Completed

- P.m. service.
- Diagnose trailer warning on dash . Test and replace defective trailer plug connector and rewire as needed.
- Inspect and test drivers door handle . Remove trim panel to replace left front outside door handle and remove latch to replace inner door handle cable . Retest .
- Replace broken pintle pin .
- Inspect and service winch .
- Rotate and high speed balance all four tires . Nitrofill all.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00	
5w20 Engine Oil	7.00	
Mac Wite Lithium Gres	1.00	
Used Fire X Refurbished	1.00	
2pc Hd Mat Set Blk	1.00	
Ford Triton Pvc Swc	1.00	
Washer Fluid Concentr	1.00	
trailer plug	1.00	
Handle Asy	1.00	
Pintle Pin W/clip	1.00	
Door Cable	1.00	
Shop Supplies	1.00	
Labor: 616.40	Parts: 197.75	Total: 814.15

Hours: 9.20

Comm: 0.00

Work Order: 1906740 **Meter:** 12105 **In Date:** 06/26/2019 **Closed:** 07/16/2019

Problem: P.M. service.

Work Completed

- P.m. service.
- Rotate and high speed balance all four tires . Nitrofill all.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00	
5w20 Engine Oil	7.00	
Used Fire X Refurbished	1.00	
Washer Fluid Concentr	1.00	
Mac Wite Lithium Gres	1.00	
Shop Supplies	1.00	
Labor: 335.00	Parts: 47.55	Total: 382.55

Hours: 5.00

Comm: 0.00

3/4/2026
12:00:56 PM

Palm Beach County Fleet Management Asset Maintenance History
10208443 2018 FORD F350 Pickup, 1 Ton, 4X4

Work Order: 2011843 **Meter:** 33952 **In Date:** 11/30/2020 **Closed:** 12/09/2020
Problem: PM Service. Thank you.

Work Completed

- Performed P.m. service & inspection
- Mount and balance 4 new tires. Reset tpms.
- Load test battery recommend to charge, charged battery then retest, battery failed. Removed and replaced then reset to basic settings.
- Strokes light inop, check power and ground to Strobe switch. power and ground ok. Found Defective switch removed and replaced.
- Removed crack rear tail light. Modify tail light for strobe bulb and seal and install.
- Performed front wheel alignment. Test drive vehicle.
- Shop Supplies

Parts Issued

Quantity

Napa Quart 5w30	7.00
Napagold Oil Filter	1.00
22" Wiper Blade	2.00
Washer Fluid Concentr	1.00
Lt285/70/17 Nit	4.00
Battery 65	1.00
Universal Switch	1.00
Boxed Miniatures	1.00
Lamp Asy	1.00
Shop Supplies	1.00
Tire Disposal Fee	4.00

Hours: 10.50

Comm: 0.00

Labor: 766.50 Parts: 2,100.50 Total: 2,867.00

Work Order: 2103555 **Meter:** 39547 **In Date:** 03/29/2021 **Closed:** 04/07/2021
Problem: P.M. service and winch cable stuck .

Work Completed

- Preventive Maint. Service
- check,removed &installed winch gears,clean & lube due to water intrusion ,then service
- rotate and balance all 4 tires
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Napa Quart 5w30	8.00
22" Wiper Blade	2.00
Mac Wite Lithium Gres	1.00
Air Fltr	1.00
Shop Supplies	1.00

Hours: 7.50

Comm: 0.00

Labor: 547.50 Parts: 83.44 Total: 630.94

3/4/2026
12:00:56 PM

Palm Beach County Fleet Management Asset Maintenance History
10208443 2018 FORD F350 Pickup, 1 Ton, 4X4

Work Order: 2105994 **Meter:** 43153 **In Date:** 06/01/2021 **Closed:** 07/20/2021
Problem: Check Engine light on.

Work Completed

Parts Issued

Quantity

- Transport to and from dealer for check engine light .codes P0741 , P1744 . torque converter replacement
- Shop Supplies

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 2.65 Total: 148.65

Work Order: 2109624 **Meter:** 44801 **In Date:** 09/02/2021 **Closed:** 09/13/2021
Problem: PM Service.

Work Completed

Parts Issued

Quantity

- Performed P.m. Service & Inspection.
- Performed Tire Rotation Balance On All 4 Wheels, Reset Tpms.
- Removed And Replaced Cabin Air Filter, Clean A/c Vents Then Check.
- Performed Service & Inspection On Winch.
- Shop Supplies

Hours: 6.50 Comm: 0.00 Labor: 474.50 Parts: 58.41 Total: 532.91

3/4/2026
12:00:56 PM

Palm Beach County Fleet Management Asset Maintenance History
10208443 2018 FORD F350 Pickup, 1 Ton, 4X4

Work Order: 2200402 **Meter:** 50120 **In Date:** 01/12/2022 **Closed:** 01/21/2022
Problem: PM Service.

Work Completed

- Preventive Maint. Service
- resurfaced both front brakes rotors, replaced pads, calipers, flush and bleed fluid, then road test
- performed major tune up by replaced all 16 spark plugs, 8 plugs wire, clean throttle body
- performed top engine decab and injector flush
- replaced all 4 tires balance and nitro fill all.
- completed front end alignment and road test
- check, sop, and replaced broken r/r tail lamp, installed strobe light
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Napa Quart 5w30	8.00
22" Wiper Blade	2.00
Used Fire X Refurbished	1.00
Non-chlor Brake Clnr	1.00
Brk Fluid Dot 4-32oz	1.00
Reman/ca	1.00
Reman/ca	1.00
Brake Pad	1.00
Spark Plug	16.00
Spark Plug Wire	8.00
Intake Cleaner Kit	1.00
Motor Tune-up 16oz	1.00
Lt285/70/17 Nit	4.00
Tail Lamp Asy Rh	1.00
Shop Supplies	1.00
Tire Disposal Fee	4.00

Hours: 22.10

Comm: 0.00

Labor: 1,613.30

Parts: 2,060.79

Total: 3,674.09

Work Order: 2205029 **Meter:** 54811 **In Date:** 05/10/2022 **Closed:** 05/16/2022
Problem: PM Service.

Work Completed

- Preventive Maint. Service
- rotate and balance all 4 tire nitro fill all
- inspect winch and all moving parts lubricate
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	7.00
22" Wiper Blade	2.00
Macs Chain Cable Lube	1.00
Shop Supplies	1.00

Hours: 4.75

Comm: 0.00

Labor: 346.75

Parts: 35.93

Total: 382.68

3/4/2026
12:00:56 PM

Palm Beach County Fleet Management Asset Maintenance History
10208443 2018 FORD F350 Pickup, 1 Ton, 4X4

Work Order: 2303668 **Meter:** 69138 **In Date:** 04/12/2023 **Closed:** 04/24/2023
Problem: PM Service

Work Completed

- Preventive Maint. Service completed
- inspect and service winch
- inspect and service transmission fluid ,replaced filter and flush system . Road test .
- replaced all 4 tires and balance . Nitro fill all.
- Diagnose engine misfire and replaced defective # 4 &1 ignition coil & spark plugs verify normal operation and clear codes
- completed front end alignment and road test
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Napa Quart 5w30	8.00
22" Wiper Blade	2.00
oil auto	16.00
Trams Filter	1.00
Lt285/70/17 Nit	4.00
Ing Coil	1.00
Spark Plug	2.00
Ing Coil	1.00
Spark Plug	1.00
Ing Coil	2.00
Shop Supplies	1.00
Tire Disposal Fee	4.00

Hours: 13.80

Comm: 0.00

Labor: 1,007.40 Parts: 2,233.86 Total: 3,241.26

Work Order: 2308205 **Meter:** 74246 **In Date:** 08/16/2023 **Closed:** 08/30/2023
Problem: PM Service.

Work Completed

- Preventive Maint. Service completed
- balance and rotate all 4 tires . Nitro fill all.
- inspect and service winch
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Napa Quart 5w30	8.00
22" Wiper Blade	2.00
Shop Supplies	1.00

Hours: 6.00

Comm: 0.00

Labor: 438.00 Parts: 47.67 Total: 485.67

3/4/2026
12:00:56 PM

Palm Beach County Fleet Management Asset Maintenance History
10208443 2018 FORD F350 Pickup, 1 Ton, 4X4

Work Order: 2311160 **Meter:** 78682 **In Date:** 11/06/2023 **Closed:** 11/16/2023
Problem: PM Service. nail in passanger rear tire

Work Completed

Parts Issued

Quantity

- Preventive Maint. Service
- Customer States Nail In Right Rear Tire. Inspect, Repair Right Rear Tire And Rotate To Front. Rotate And Balance Four. Relearn Tire Sensors.
- Inspect And Service Power Winch.
- Resurface Rear Rotors On Car, R&r Worn Brake Pads, Lube Caliper Parts, Flush And Bleed Brake System. Road Test To Verify Repair.
- Shop Supplies

Napagold Oil Filter	1.00
Napa Quart 5w30	7.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Used Fire X Refurbished	1.00
Non-chlor Brake Clnr	1.00
Brake Fl-dot 3-4 32oz	1.00
Brake Pads	1.00
Brake Master Cap	1.00
Shop Supplies	1.00

Hours: 12.00

Comm: 0.00

Labor: 876.00 Parts: 164.59 Total: 1,040.59

Work Order: 2402161 **Meter:** 83167 **In Date:** 02/28/2024 **Closed:** 03/18/2024
Problem: PM Service.

Work Completed

Parts Issued

Quantity

- Preventive Maint. Service
- Service And Inspect Winche And Cable, Winche Hook Latch Broken
- Replace 4 Tires Balance With Nitro Fill
- Test Drive And Perform Front End Alignment Retest
- Shop Supplies

Drain Plug	1.00
Napagold Oil Filter	1.00
Napa Quart 5w30	7.00
Washer Fluid Concentr	1.00
Wiper Blade	2.00
Used Fire X Refurbished	1.00
Air Fltr	1.00
Clevis Slip Hook-bulk	1.00
Lt285/70/17 Nit	4.00
Tire Pressure Monitoring System Sensor (4.00
Shop Supplies	1.00
Tire Disposal Fee	4.00

Hours: 9.50

Comm: 0.00

Labor: 693.50 Parts: 1,827.25 Total: 2,520.75

3/4/2026
12:00:56 PM

Palm Beach County Fleet Management Asset Maintenance History
10208443 2018 FORD F350 Pickup, 1 Ton, 4X4

Work Order: 2504947 **Meter:** 100023 **In Date:** 05/28/2025 **Closed:** 06/11/2025
Problem: PM Service

Work Completed

- Preventive Maint. Service
- Inspect and Replace four new A/t tires, speed balance, nitro fill
- Inspect and service winches
- Check & replace trailer plug
- Check circuit & replace strobe light switch
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Napa Quart 5w30	8.00
Washer Fluid Concentr	1.00
Wiper Blade	2.00
Trailer Connector Truck Side	1.00
Led Rocker Switch Round	1.00
Lt285/70/17 Nit	4.00
Shop Supplies	1.00
Tire Disposal Fee	4.00

Hours: 8.50 Comm: 0.00

Labor: 620.50 Parts: 1,731.38 Total: 2,351.88

Work Order: 2510950 **Meter:** 103021 **In Date:** 11/20/2025 **Closed:** 11/20/2025
Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00 Comm: 0.00

Labor: 146.00 Parts: 0.00 Total: 146.00

Total Hours: 185.85

Total Labor: 13,433.85

Total Comm: 96.00

Total Parts: 15,496.16