

3/4/2026
12:03:11 PM

Palm Beach County Fleet Management Asset Maintenance History
10195563 2015 FORD F350 Utility Body, 14,000 Gvwr, Medium Duty Crane

Total Hours: 276.65 Labor: 19,262.00 Parts: 19,836.79 Comm: 4,729.25 Charged: 43828.03

Work Order: 1501691 **Meter:** 377 **In Date:** 02/17/2015 **Closed:** 02/17/2015
Problem: 1061 - Pre Delivery Inspection

Work Completed

- Pre Delivery Inspection

Hours: 4.00 Comm: 0.00 Labor: 240.00 Parts: 0.00 Total: 240.00

Work Order: 1503530 **Meter:** 607 **In Date:** 04/06/2015 **Closed:**
Problem: Install winch.

Work Completed

-

Hours: 0.00 Comm: 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00

Work Order: 1507447 **Meter:** 3171 **In Date:** 07/27/2015 **Closed:** 08/10/2015
Problem: P.M. service.

Work Completed

- P.m. Service.
- Inspect and service crane.
- Rotate and balance tires.
- Shop Supplies

Parts Issued

Quantity

15-40 Oil	13.00
Napagold Oil Filter	1.00
Fuel Filter Kit	1.00
Used Fire X Refurbished	1.00
Floor Mat-2pc Rub Bk	1.00
Napa Hydraulic Filtr	1.00
Aw68 Hydro Fluid Hydr	15.00
Def Quart	8.00
Handle Pitch Pin	1.00
Shop Supplies	1.00
Labor: 360.00 Parts: 256.27 Total: 616.27	

Hours: 6.00 Comm: 0.00

3/4/2026
12:03:11 PM

Palm Beach County Fleet Management Asset Maintenance History
10195563 2015 FORD F350 Utility Body, 14,000 Gvwr, Medium Duty Crane

Work Order: 1607948 **Meter:** 11421 **In Date:** 08/02/2016 **Closed:** 08/23/2016
Problem: P.M. service.

Work Completed

- P.m. Service.
- Inspect and service crane.
- Rotate and balance all tires.
- Shop Supplies

Parts Issued

Quantity

15-40 Oil	13.00
Napagold Oil Filter	1.00
Napagold Fuel Filter	1.00
Napagold Fuel Filter	1.00
Aw68 Hydro Fluid Hydr	12.00
Def Quart	12.00
Used Fire X Refurbished	1.00
Shop Supplies	1.00

Hours: 6.50

Comm: 0.00

Labor: 390.00

Parts: 161.59

Total: 551.59

Work Order: 1701986 **Meter:** 18774 **In Date:** 02/27/2017 **Closed:** 03/28/2017
Problem: P.M. service and raise outriggers and missing sand pads on right side.

Work Completed

- P.m. Service.
- Replace founr tire,rotate and balance all six.
- Inspect and service crane.
- Replace broken pintle pin.
- Replace missing right side outrigger pad.adjust both outrigger height per request.
- Complete wheel alignment.test drive.
- Shop Supplies

Parts Issued

Quantity

15-40 Oil	13.00
Napagold Oil Filter	1.00
Napagold Fuel Filter	1.00
22" Wiper Blade	2.00
Washer Fluid Concentr	1.00
Napagold Air Filter	1.00
179636492 Lt245-75r17	4.00
Napa Hydraulic Filtr	1.00
Pintle Pin W/clip	1.00
Outrigger Mount	1.00
Def Bulk Qts	24.00
Air Filter	1.00
Air Filter (gold), Air Panel	1.00
Shop Supplies	1.00
Tire Disposal Fee	4.00

Hours: 11.75

Comm: 0.00

Labor: 705.00

Parts: 1,348.95

Total: 2,053.95

3/4/2026
12:03:11 PM

Palm Beach County Fleet Management Asset Maintenance History
10195563 2015 FORD F350 Utility Body, 14,000 Gvwr, Medium Duty Crane

Work Order: 1712039 **Meter:** 25588 **In Date:** 12/07/2017 **Closed:** 12/19/2017
Problem: P.M. service and check crane operation and hoses.

Work Completed

Parts Issued

Quantity

- P.m. service.
- Inspect and service crane hoisting devices.
- Replaced two front tires and rotated and balanced all six tires.nitrogen fill tires.
- Replaced two rear strobe lights.had to modify to accomodate new type of strobe light.
- Test batteries and charging system .charge batteries fully .batteries failed load test .remove and replace both batteries.
- Shop Supplies

15-40 Oil	13.00
Napagold Oil Filter	1.00
Used Fire X Refurbished	1.00
22" Wiper Blade	2.00
Battery 65	2.00
Air Filter (gold), Air Panel	1.00
ridgid vise handle	1.00
Blue Df	3.00
Slip Plate Spray 12oz	1.00
Napagold Fuel Filter	1.00
Aw68 Hydro Fluid Hydr	4.00
Napa Hydraulic Filtr	1.00
179636492 Lt245-75r17	2.00
Big G Degreaser 1 Gal	1.00
Lighting	2.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 11.00

Comm: 0.00

Labor: 660.00

Parts: 1,372.01

Total: 2,032.01

Work Order: 1712353 **Meter:** 25588 **In Date:** 12/15/2017 **Closed:** 12/15/2017
Problem: Weld Vice

Work Completed

- Weld vice handle

Hours: 0.50

Comm: 0.00

Labor: 30.00

Parts: 0.00

Total: 30.00

3/4/2026
12:03:11 PM

Palm Beach County Fleet Management Asset Maintenance History
10195563 2015 FORD F350 Utility Body, 14,000 Gvwr, Medium Duty Crane

Work Order: 1807347

Meter: 29582

In Date: 07/19/2018 **Closed:** 07/30/2018

Problem: P.M. service.

Work Completed

- P.m. service.
- Inspect and service crane . Replace broken safety latch on crane hook.
- Rotate and balance all six tires.
- Shop Supplies

Parts Issued

Quantity

Latch Hook Kit	1.00	
Napagold Oil Filter	1.00	
15-40 Oil	13.00	
22" Wiper Blade	2.00	
Used Fire X Refurbished	1.00	
Washer Fluid Concentr	1.00	
Ford Triton Pvc Swc	1.00	
Napagold Fuel Filter	1.00	
Blue Df	2.00	
Aw68 Hydro Fluid Hydr	4.00	
Napa Hydraulic Filtr	1.00	
Safety Latch Kit	1.00	
Shop Supplies	1.00	
Labor: 420.00	Parts: 315.77	Total: 735.77

Hours: 7.00

Comm: 0.00

3/4/2026
12:03:11 PM

Palm Beach County Fleet Management Asset Maintenance History
10195563 2015 FORD F350 Utility Body, 14,000 Gvwr, Medium Duty Crane

Work Order: 1901352 **Meter:** 34387 **In Date:** 02/04/2019 **Closed:** 02/22/2019
Problem: P.M. service and PTO inop at times .

Work Completed

- P.m. service.
- Inspect and service crane and outriggers . Diagnose switch inop . R&r defective Pto switch. retest.
- Resurface front brake rotors and service calipers . Replace brake pads and flush and bleed brakes . Road test .
- Replace two worn tires . Rotate and balance all six tires . Nitrofill all.
- Tesdt and replace defective trailer plug connector and rewire as needed . Replace missing pintle pin . Computer diagnose wiper stay on byself . Replace defective wiper switch .
- Remove right front door panel to replace damaged outside mirror assembly .
- Complete front end alignment .road test.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
15-40 Oil	13.00
Napagold Fuel Filter	1.00
22" Wiper Blade	2.00
Used Fire X Refurbished	1.00
Blue Df	2.00
Napa Hydraulic Filtr	1.00
Front Brake Pad	1.00
Tr416 Valve Stem	2.00
Lt245/75r17 Mich Defend Ltx	2.00
Pintle Pin W/clip	1.00
trailer plug	1.00
Mirror	1.00
rocker switch pto	1.00
Switch Asy	1.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 20.50

Comm: 0.00

Labor: 1,373.50

Parts: 1,353.16

Total: 2,726.66

Work Order: 1906940 **Meter:** 38670 **In Date:** 07/03/2019 **Closed:** 07/16/2019
Problem: Check engine light on .

Work Completed

- Transport to and from dealer for 18m01 replacement of Def sending unit .
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
---------------	------

Hours: 2.00

Comm: 0.00

Labor: 134.00

Parts: 3.00

Total: 137.00

3/4/2026
12:03:11 PM

Palm Beach County Fleet Management Asset Maintenance History
10195563 2015 FORD F350 Utility Body, 14,000 Gvwr, Medium Duty Crane

Work Order: 2001555 **Meter:** 44385 **In Date:** 02/13/2020 **Closed:** 05/07/2020

Problem: P.M. service and check crane cable .

Work Completed

- P.m. service.
- Computer diagnose check engine light , code P04db . Install crankcase ventilation collar kit and reprogram Pcm with up dated calibration per Tsb 18-2301. Clear code and road test .
- Inspect and service crane and outriggers . Replace leaking right side outrigger . Replace rusted anti two block bolt and rustout weight . Retest operation .
- Rotate and balance all six tires . Nitrofill all.
- Test and repair open circuit to power inverter . Resolder battery cable end . Retest operation .
- Computer diagnose check engine light . R&r broken forced air outlet tube from cooler to intake . Clear code and test drive .
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
15-40 Oil	13.00
Napagold Fuel Filter	1.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Napagold Air Filter	1.00
Used Fire X Refurbished	1.00
Non-chlor Brake Clnr	3.00
Blue Df	1.00
Cabin Air Filter	1.00
Aw68 Hydro Fluid Hydr	15.00
Reman Outrigger Cylinder	1.00
Clamp Kit	1.00
Tube - Outlet	1.00
Pickle Weight Atb Assy	1.00
Shop Supplies	1.00

Hours: 15.30

Comm: 0.00

Labor: 1,116.90

Parts: 1,199.64

Total: 2,316.54

Work Order: 2002787 **Meter:** 43007 **In Date:** 03/17/2020 **Closed:** 03/18/2020

Problem: Heard loud pop and now want hardly move

Work Completed

- Tow From: 1/2 n of glades & mile s of yamata rd on powerline To: lv shop

Hours: 0.00

Comm: 96.00

Labor: 0.00

Parts: 0.00

Total: 96.00

3/4/2026
12:03:11 PM

Palm Beach County Fleet Management Asset Maintenance History
10195563 2015 FORD F350 Utility Body, 14,000 Gvwr, Medium Duty Crane

Work Order: 2007650 **Meter:** 47380 **In Date:** 08/04/2020 **Closed:** 08/12/2020

Problem: PM Service, Two front tires, Pulls from side to side, Replace crane cable.

Work Completed

- P.m. service.
- Replace four tire . Rotate and balance all six tires . Nitrofill all..
- Test and replace both defective headlight bulbs .
- Inspect and service crane . Replace worn crane cable and hook assembly .
- Perform complete front end alignment and road test .
- Shop Supplies

Parts Issued

Quantity

F75z6730ba Drain Plug	1.00
Napagold Oil Filter	1.00
15-40 Oil	13.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Napagold Fuel Filter	1.00
Blue Df	1.00
Lt245/75r17 Mich Defend Ltx	4.00
Boxed Capsules	2.00
Latch Hook Kit	1.00
Napa Hydraulic Filtr	1.00
Crane Cable	1.00
Shop Supplies	1.00
Tire Disposal Fee	4.00

Hours: 13.80

Comm: 0.00

Labor: 1,007.40 Parts: 1,369.64 Total: 2,377.04

3/4/2026
12:03:11 PM

Palm Beach County Fleet Management Asset Maintenance History
10195563 2015 FORD F350 Utility Body, 14,000 Gvwr, Medium Duty Crane

Work Order: 2101181 **Meter:** 51330 **In Date:** 02/01/2021 **Closed:** 02/10/2021

Problem: Crane plug is not working. Also, PM Service. Thank you for your help! Will come in today.

Work Completed

- Preventive Maint. Service
- Aps service. Service bed mounted crane. Respool winch cable and lube. Lube all pivot points. Crane not working. no power at crane handler. Locate blown fuse and replace. readjust rear turn stop.
- Rotate and balance all six wheels and tires. 1 Rro tire had leaking valve stem. Remove tire from vehicle, dismount and replace leaking valve stem. Nitrogen fill all tires to proper psi.
- Check engine light on, code P04db, Perform pinpoint test . Use snap on diagnostic tool to diagnose faulty/ dirty crankcase ventilation filter. Remove and replace filter. Use scan tool to clear codes, test drive, and retest.
- Shop Supplies

Parts Issued

Quantity

Napagold Fuel Filter	1.00
Napagold Fuel Filter	1.00
Blue Df	2.00
Air Filter (gold), Air Panel	1.00
Napagold Oil Filter	1.00
15-40 Oil	13.00
Non-chlor Brake Clnr	2.00
22" Wiper Blade	2.00
Used Fire X Refurbished	1.00
1cart Palladium 2 Grs	1.00
Filler Breather	1.00
Aw68 Hydro Fluid Hydr	5.00
Napa Hydraulic Filtr	1.00
oil separator	1.00
Shop Supplies	1.00

Hours: 11.50

Comm: 0.00

Labor: 839.50

Parts: 473.08

Total: 1,312.58

Work Order: 2103660 **Meter:** 52729 **In Date:** 03/31/2021 **Closed:** 04/01/2021

Problem: Drivers side front storage bin, the key lock keeps spinning, won't unlock. Staff will bring it by to see if it can be po

Work Completed

- Force entry into left front bin door . Remove plate and reinstall lock cylinder lever and spring and lock tight all bolts . Retest operation .
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
---------------	------

Hours: 1.00

Comm: 0.00

Labor: 73.00

Parts: 4.00

Total: 77.00

3/4/2026
12:03:11 PM

Palm Beach County Fleet Management Asset Maintenance History
10195563 2015 FORD F350 Utility Body, 14,000 Gvwr, Medium Duty Crane

Work Order: 2105119 **Meter:** 54072 **In Date:** 05/07/2021 **Closed:** 07/06/2021

Problem: Drivers side downrigger leaking hydraulic fluid through the seal when PTO activated.

Work Completed

- check,,r&r defective l/r outrigger cylinder ,verify normal operation and paint
- Shop Supplies

Hours: 2.00

Comm: 0.00

Parts Issued

	Quantity
Outrigger Cylinder	1.00
Shop Supplies	1.00
Freight Charge	1.00
Labor: 146.00	Parts: 872.46
Total: 1,018.46	

Work Order: 2109269 **Meter:** 55838 **In Date:** 08/26/2021 **Closed:** 09/08/2021

Problem: PM Service. Coming in for PM Tomorrow. Please top off all fluids.

Work Completed

- Preventive Maint. Service
- Check all tires, R & I two new on front, Rotate and speed balance all six tires, nitro fill
- Check interior light inop, R & I bulb
- Check brake all, R & I new Rear brakes, resurface both rotors, service caliper slide pins, bleed brake, road test
- Shop Supplies

Hours: 12.00

Comm: 0.00

Parts Issued

	Quantity
Napagold Oil Filter	1.00
15-40 Oil	13.00
Blue Df	2.00
Washer Fluid Concentr	1.00
Slip Plate Spray 12oz	1.00
Steering Wheel Cover Large	1.00
Napagold Fuel Filter	1.00
Napagold Fuel Filter	1.00
Lt245/75r17 Mich Defend Ltx	2.00
Boxed Miniatures	1.00
Non-chlor Brake Clnr	1.00
Brk Fluid Dot 4-32oz	1.00
Brake Pad	1.00
Brake Caliper	1.00
Brake Caliper	1.00
Shop Supplies	1.00
Tire Disposal Fee	2.00
Labor: 876.00	Parts: 774.78
Total: 1,650.78	

3/4/2026
12:03:11 PM

Palm Beach County Fleet Management Asset Maintenance History
10195563 2015 FORD F350 Utility Body, 14,000 Gvwr, Medium Duty Crane

Work Order: 2110858 **Meter:** 55838 **In Date:** 09/07/2021 **Closed:** 10/06/2021
Problem: Description of repairs: right side of body, front bin ,rear fender, right front cab door, front bumper, l door/fender

Work Completed

- Description of repairs: right side of body, front bin ,rear fender, right front cab door, front bumper, l door/fender

Hours: 0.00 Comm: 4,023.25 Labor: 0.00 Parts: 0.00 Total: 4,023.25

Work Order: 2200504 **Meter:** 58020 **In Date:** 01/12/2022 **Closed:** 01/14/2022
Problem: rear passenger, INSIDE tire has a large nail in it

Work Completed

- Tire Service: Jpp Maintenance Compound by our sign shop area Problem: rear passenger, Inside tire has a large nail in it

Hours: 0.00 Comm: 66.15 Labor: 0.00 Parts: 0.00 Total: 66.15

3/4/2026
12:03:11 PM

Palm Beach County Fleet Management Asset Maintenance History
10195563 2015 FORD F350 Utility Body, 14,000 Gvwr, Medium Duty Crane

Work Order: 2202625 **Meter:** 59338 **In Date:** 03/09/2022 **Closed:** 03/14/2022

Problem: PM Service. Engine Light on intermittently. - Check wipers.

Work Completed

- Preventive Maint. Service
- Check Engine Light On Codes U0401, Pcv Replaced Wiht Updated Hose before but not updated program , Reprogram Pcm with update program per Tsb 17m04
- Inspect And Service Crane And Out Riggers .
- Load Test Battery And Check Charging System, Recharged Battery Failed Load Test R&r Both Batteries
- Inspect All Tires Rotate And Balance All 6 With Nitro Fill
- Inspected Front Brakes, Brake Pads At Miniuum Depth And Warped Rotors, R&r Front Brake Pads Resurface Rotors And Change Calipers With Hoses Flush And Bleed Brake System Road Test .
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Drain Plug	1.00
15-40 Oil	14.00
Blue Df	2.00
22" Wiper Blade	2.00
Washer Fluid Concentr	1.00
Used Fire X Refurbished	1.00
Napagold Fuel Filter	1.00
Napa Hydraulic Filtr	1.00
Battery	2.00
Brake Hose	1.00
Brake Hose	1.00
Reman/ca	1.00
Reman/ca	1.00
Front Brake Pad	1.00
B Fluid Dot 3-32oz	1.00
Shop Supplies	1.00

Hours: 15.50

Comm: 0.00

Labor: 1,131.50

Parts: 718.97

Total: 1,850.47

3/4/2026
12:03:11 PM

Palm Beach County Fleet Management Asset Maintenance History
10195563 2015 FORD F350 Utility Body, 14,000 Gvwr, Medium Duty Crane

Work Order: 2209521 **Meter:** 62189 **In Date:** 09/13/2022 **Closed:** 09/22/2022
Problem: P.M. service. Drivers side outrigger has a hose that is broken. Possible to order a new hose before we bring it in?

Work Completed

Parts Issued

Quantity

- Preventive Maint. Service
- rotate and balance all 6 tires nitro fill all
- Inspect and service crane and out riggers . lube all moving parts insure proper function of device . replace hydraulic line after found leaking on left stringer clean all old residue and inspect for leaks after replacement
- Shop Supplies

Prem Blue 15w40 1 Gal	3.00
Napagold Oil Filter	1.00
22" Wiper Blade	2.00
Napagold Fuel Filter	1.00
Blue Df	1.00
White Lithium Grease	1.00
Hose Assy	1.00
Shop Supplies	1.00

Hours: 10.50

Comm: 0.00

Labor: 766.50

Parts: 268.53

Total: 1,035.03

Work Order: 2211436 **Meter:** 63296 **In Date:** 11/03/2022 **Closed:** 11/08/2022
Problem: Tires: RRAO; Flat. Repair Tire

Work Completed

- Tire Service: 5020 S. Congress Ave Lw (john Prince Park Maint) Problem: Tires: Rrao; Flat. Repair Tire

Hours: 0.00

Comm: 85.32

Labor: 0.00

Parts: 0.00

Total: 85.32

Work Order: 2212431 **Meter:** 63828 **In Date:** 12/05/2022 **Closed:** 12/12/2022
Problem: Tires: RRAO; Wear. Replace Tire

Work Completed

- Tire Service: Jpp fuel station Problem: Tires: Rrao; Wear. Replace Tire

Hours: 0.00

Comm: 221.23

Labor: 0.00

Parts: 0.00

Total: 221.23

3/4/2026
12:03:11 PM

Palm Beach County Fleet Management Asset Maintenance History
10195563 2015 FORD F350 Utility Body, 14,000 Gvwr, Medium Duty Crane

Work Order: 2303603 **Meter:** 67063 **In Date:** 04/11/2023 **Closed:** 04/26/2023
Problem: PM Service wipers will not clear and recall 20E08.

Work Completed

Parts Issued

Quantity

- Preventive Maint. Service
- R & I six new tires, speed balance, nitro fill
- Perform complete alignment, road test
- Body side marker amber round, Repair short in light circuit, Replace burnt fuse
- Replace missing Pintle pin
- Inspect & service crane and outriggers
- Transport to and from dealer for recall 20e08 .
- Shop Supplies

Napagold Oil Filter	1.00
Napa Qt 15w40	14.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Blue Df	2.00
Fuel Filter Kit	1.00
Used Fire X Refurbished	1.00
Napagold Fuel Filter	1.00
Lt245/75r17 Mich Defend Ltx	6.00
Grommet Mount Kit	1.00
Pintle Pin W/clip	1.00
Napa Hydraulic Filtr	1.00
Shop Supplies	1.00
Tire Disposal Fee	6.00

Hours: 14.50

Comm: 0.00

Labor: 1,058.50 Parts: 1,756.15 Total: 2,814.65

Work Order: 2304294 **Meter:** 67152 **In Date:** 04/28/2023 **Closed:** 05/04/2023
Problem: Reduce Engine (running rough)

Work Completed

Parts Issued

Quantity

- Perform Ids diagnoses engine light on, code# P0087, Perform fuel system test for low pressures, Inspect fuel Rail and fuel filter for leaks, Replace primary fuel filter o'ring leaking test & verify, road test
- Shop Supplies

Shop Supplies	1.00
---------------	------

Hours: 1.00

Comm: 0.00

Labor: 73.00 Parts: 2.65 Total: 75.65

3/4/2026
12:03:11 PM

Palm Beach County Fleet Management Asset Maintenance History
10195563 2015 FORD F350 Utility Body, 14,000 Gvwr, Medium Duty Crane

Work Order: 2304839 **Meter:** 67431 **In Date:** 04/28/2023 **Closed:** 05/15/2023
Problem: Reduce Engine (running rough)

Work Completed

- Tow From: Congres Auto Parts off of 10th Ave To: 2601 Vista Pkwy, West
Palm Beach 33411(lv Shop)

Hours: 0.00 Comm: 124.30 Labor: 0.00 Parts: 0.00 Total: 124.30

Work Order: 2304916 **Meter:** 67490 **In Date:** 05/16/2023 **Closed:** 05/17/2023
Problem: crane broke

Work Completed

Parts Issued

Quantity

- broke hyd hose - manually stow crane
- to and from scrp
- Shop Supplies

Shop Supplies 1.00

Hours: 3.00 Comm: 0.00 Labor: 219.00 Parts: 2.65 Total: 221.65

Work Order: 2304926 **Meter:** 67528 **In Date:** 05/17/2023 **Closed:** 05/22/2023
Problem: Hydraulic hose popped off on crane - Call Joe 561-880-1962

Work Completed

Parts Issued

Quantity

- Untangle crane hoses and remove pressure hose to have made . Repair
wiring to crane and refill hydraulic tank . Clean and inspect and test
operation of crane and outriggers
- Shop Supplies

Aw68 Hydro Fluid Hydr 8.00
Big G Degreaser 1 Gal 1.00
Hose Assy 1.00
Shop Supplies 1.00

Hours: 4.00 Comm: 0.00 Labor: 292.00 Parts: 162.67 Total: 454.67

Work Order: 2306348 **Meter:** 70000 **In Date:** 06/28/2023 **Closed:** 09/28/2023
Problem: Need a safety latch for the crane hook.

Work Completed

Parts Issued

Quantity

- Order and replace 6 crane hook safety latches
- Shop Supplies

Latch Kit 6.00
Shop Supplies 1.00
Freight Charge 1.00

Hours: 0.20 Comm: 0.00 Labor: 14.60 Parts: 596.78 Total: 611.38

3/4/2026
12:03:11 PM

Palm Beach County Fleet Management Asset Maintenance History
10195563 2015 FORD F350 Utility Body, 14,000 Gvwr, Medium Duty Crane

Work Order: 2310945

Meter: 70000

In Date: 10/30/2023 **Closed:** 11/14/2023

Problem: PM Service.

Work Completed

- Preventive Maint. Service completed
- balance and rotate all six tires. Nitro fill all.
- inspect and service crane system and top off fluid
- check ,pin point rear tail lamp assembly ,sop r&r tail am then verify normal operation
- check batteries,charging system after fully charge it fails load test, r&r both defective acid build up/ batteries and performed draw test
- check and r&r defective engine oil Seperator
- check and replaced all six defective body mounts
- Shop Supplies

Parts Issued

Quantity

Blue Df	1.00
Fuel Filter Kit	1.00
Air Filter (gold), Air Panel	1.00
22" Wiper Blade	2.00
Napagold Oil Filter	1.00
Napa Gal 15w40	4.00
Aw68 Hydro Fluid Hydr	8.00
Napa Hydraulic Filtr	1.00
ldbar	1.00
Battery	2.00
oil separator	1.00
Body Mount Kit	4.00
Body Mount Kit	2.00
Shop Supplies	1.00

Hours: 18.30

Comm: 0.00

Labor: 1,335.90

Parts: 1,286.60

Total: 2,622.50

3/4/2026
12:03:11 PM

Palm Beach County Fleet Management Asset Maintenance History
10195563 2015 FORD F350 Utility Body, 14,000 Gvwr, Medium Duty Crane

Work Order: 2405348 **Meter:** 76675 **In Date:** 05/30/2024 **Closed:** 06/10/2024

Problem: PM Service. Makes loud noise from front end upon acceleration and when making u-turns.

Work Completed

- Preventive Maint. Service. attention front end noise ? Lube wheel stops
- Rotate and speed balance, nitro fill
- Inspect and service crane and out riggers
- Inspect all brakes, R & i new front brakes, Resurface both rotors, service caliper slide pins, bleed brakes, burnish brakes on road test
- Modify Pto Pump to body vibration on turns
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Napa Qt 15w40	14.00
Washer Fluid Concentr	1.00
Wiper Blade	2.00
Fuel Filter	1.00
Blue Df	1.00
Used Fire X Refurbished	1.00
Napa Hydraulic Filtr	1.00
Non-chlor Brake Clnr	1.00
Brake Fl-dot 3-4 32oz	1.00
Front Brake Pad	1.00
Shop Supplies	1.00

Hours: 13.00

Comm: 0.00

Labor: 949.00

Parts: 257.53

Total: 1,206.53

Work Order: 2406083 **Meter:** 76001 **In Date:** 06/24/2024 **Closed:** 08/01/2024

Problem: Needs new starter, going bad. Staff will bring in to shop. Need a new Diesel cap. Will pick up when ready.

Work Completed

- Order and replace fuel cap
- Diagnose starting issues . Perform starter circuit test . R&r defective starter assembly . Retest
- Shop Supplies

Parts Issued

Quantity

fuel cap green	1.00
Starter	1.00
Shop Supplies	1.00

Hours: 2.20

Comm: 0.00

Labor: 160.60

Parts: 295.33

Total: 455.93

3/4/2026
12:03:11 PM

Palm Beach County Fleet Management Asset Maintenance History
10195563 2015 FORD F350 Utility Body, 14,000 Gvwr, Medium Duty Crane

Work Order: 2500807

Meter: 81039

In Date: 01/28/2025 **Closed:** 02/18/2025

Problem: PM Service.

Work Completed

- Performed P.m. Service & Inspection.
- Mount 2 Tires Then Balance & Rotate All 6 Tires Add Nitrofill Fill Reset Tpms.
- Performed Service & Inspection On Crane With Outriggers.
- Removed And Replaced Both Front Broken Washer Sprayers.
- Performed Front Wheel Alignment & Test Drove Vehicle Then Check.
- Removed And Replaced Damaged Trailer Connector Re Wire And Check.
- Rear Brake Pads Below Manufacture Specs, Removed Rear Brake Pads And Calipers, Resurfaced Both Rear Brake Rotors, Replaced Both Rear Brake Calipers, Lubricate Caliper Slides. Then Bleed & Flush Entire Brake System. Test Drove Vehicle & Burnish Brakes
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Napa Qt 15w40	14.00
Fuel Fil	1.00
Wiper Blade	2.00
Tire Lt245/75/17 Mich	2.00
1cart Palladium 2 Grs	1.00
Napa Hydraulic Filtr	1.00
Trailer Connector Truck Side	1.00
Washer Jet	2.00
Fuel Filter	1.00
Brk Fluid Dot 4-32oz	1.00
Non-chlor Brake Clnr	2.00
Brake Pad Set	1.00
Bracketed Caliper	1.00
Bracketed Caliper	1.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 17.50

Comm: 0.00

Labor: 1,277.50

Parts: 986.26

Total: 2,263.76

3/4/2026
12:03:11 PM

Palm Beach County Fleet Management Asset Maintenance History
10195563 2015 FORD F350 Utility Body, 14,000 Gvwr, Medium Duty Crane

Work Order: 2508941 **Meter:** 87496 **In Date:** 09/22/2025 **Closed:** 10/08/2025

Problem: PM Service. A/C stopped blowing cold air, may need to be charged.

Work Completed

- perform Preventive Maint. Service
- op complaint ac stopped blowing cold air, performed ac diag, Replace Shrader valve at ports and recharge to factory spec . perform ac service.
- load test battery, failed, recharge, retest, failed, R&r both batteries, reset bms clean and protect terminals, clean and paint corroded battery tie downs
- right turn signal inop, R&r faulty turn signal lamp
- mount 2 tires, balance rotate and nitrofill all, tpms relearn
- perform crane pm
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
15-40 Oil	14.00
Wiper Blade	2.00
Fuel Filter	1.00
Blue Df	2.00
Used Fire X Refurbished	1.00
Slip Plate Spray 12oz	1.00
Freon Lv Shop 1	2.00
Cap And Valve Kit	1.00
Battery	2.00
Air Filter (gold), Air Panel	1.00
Pintle Pin W/clip	1.00
Cabin Air Filter	1.00
Tire Lt245/75/17 Mich	2.00
Prem Aw 68 Hyd Fl 5g	1.00
Napa Hydraulic Filtr	1.00
Drain Plug	1.00
Toggle Switch	1.00
Led Sup Mdl 44 42 Dio	1.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 14.00

Comm: 0.00

Labor: 1,022.00

Parts: 1,434.01

Total: 2,456.01

3/4/2026
12:03:11 PM

Palm Beach County Fleet Management Asset Maintenance History
10195563 2015 FORD F350 Utility Body, 14,000 Gvwr, Medium Duty Crane

Work Order: 2509737 **Meter:** 87745 **In Date:** 10/16/2025 **Closed:** 11/03/2025
Problem: A/C blowing hot air.

Work Completed

- op complaint ac not blowing cold.evac recharge and add stop leak and perform leak test
- Shop Supplies

Hours: 2.00 Comm: 0.00

Parts Issued

	Quantity
Red Angel Ac Stop Lk	1.00
Freon Lv Shop 1	2.00
Shop Supplies	1.00
Labor: 146.00 Parts: 61.24	Total: 207.24

Work Order: 2511828 **Meter:** 89376 **In Date:** 12/19/2025 **Closed:** 12/30/2025
Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00 Comm: 0.00

Labor: 146.00 Parts: 0.00 Total: 146.00

Total Hours: 276.65 Total Labor: 19,262.00 Total Comm: 4,729.25 Total Parts: 19,836.79