

3/4/2026
12:13:25 PM

Palm Beach County Fleet Management Asset Maintenance History
10200772 2016 FORD F350 Utility Body, 14,000 Gvwr, 4X4

Total Hours: 299.50 Labor: 21,236.75 Parts: 14,457.21 Comm: 237.30 Charged: 35931.26

Work Order: 1607743 **Meter:** 338 **In Date:** 07/29/2016 **Closed:** 07/29/2016
Problem: 1061 - Pre Delivery Inspection

Work Completed

- Pre Delivery Inspection

Hours: 4.00 Comm: 0.00 Labor: 240.00 Parts: 0.00 Total: 240.00

Work Order: 1610455 **Meter:** 1704 **In Date:** 10/11/2016 **Closed:** 10/17/2016
Problem: Dead battery.Had to jump start at WUD parking lot.

Work Completed

- Jump start vehicle from Wud parking lot.recharge battery.check charging system,found inverter was on.

- Shop Supplies

Hours: 1.00 Comm: 0.00 Labor: 60.00 Parts: 2.00 Total: 62.00

Work Order: 1702511 **Meter:** 6285 **In Date:** 03/10/2017 **Closed:** 03/20/2017
Problem: PM Service.Rear bumper hang low when towing.

Work Completed

- Pm service.

- Rotate and balance six tires.

- Align.rear bumper.replace two bolts and secure..advised to take to He shop for weld.

- Shop Supplies

Hours: 7.00 Comm: 0.00 Labor: 420.00 Parts: 40.75 Total: 460.75

Work Order: 1705765 **Meter:** 9621 **In Date:** 06/09/2017 **Closed:** 06/19/2017
Problem: Pintle pin broken

Work Completed

- Replace pintle pin.

Hours: 0.25 Comm: 0.00 Labor: 15.00 Parts: 2.61 Total: 17.61

Parts Issued	Quantity
Shop Supplies	1.00

Parts Issued	Quantity
Napa Quart 5w20	7.00
Napagold Oil Filter	1.00
Washer Fluid Concentr	1.00
Wd40 Spr	1.00
Shop Supplies	1.00

3/4/2026
12:13:25 PM

Palm Beach County Fleet Management Asset Maintenance History
10200772 2016 FORD F350 Utility Body, 14,000 Gvwr, 4X4

Work Order: 1706538 **Meter:** 10043 **In Date:** 07/03/2017 **Closed:** 07/10/2017
Problem: repair rear bumper & hitch

Work Completed

- Staighthen rear bumper, replace bolts, clean and weld hitch to frame
- Shop Supplies

Parts Issued

Quantity

Shop Supplies 1.00

Hours: 4.00 Comm: 0.00 Labor: 240.00 Parts: 2.00 Total: 242.00

Work Order: 1707774 **Meter:** 11803 **In Date:** 08/09/2017 **Closed:** 08/28/2017
Problem: PM Service

Work Completed

- Pm Service.
- Replace both damage brake lamp and both damage cab front amber marker lamp assemblies.had to drill out rivets.
- Rotate and balance all 6 tires.
- Clean and lube trailer plug connection from moisture inside plug.
- Transport vehicle to and from dealer for replacing air bag clock spring.
- Shop Supplies

Parts Issued

Quantity

Amber Marker Lamp 2.00

22" Wiper Blade 2.00

Washer Fluid Concentr 1.00

Napagold Oil Filter 1.00

Napa Quart 5w20 7.00

Napagold Air Filter 1.00

Used Fire X Refurbished 1.00

Drain Plug 1.00

Led Sup Mdl 44 42 Dio 2.00

Shop Supplies 1.00

Hours: 10.00 Comm: 0.00 Labor: 600.00 Parts: 223.06 Total: 823.06

Work Order: 1802017 **Meter:** 13613 **In Date:** 02/22/2018 **Closed:** 03/12/2018
Problem: P.M.SERVICE, DEAD BATTERY

Work Completed

- Pm Service.
- Has to jump start vehicle all the time.fully charge battery.test starting and charging system with rotunda tester.battery failed load test.aces code Hc89t.dtc code 84amka .replace bad battery.
- Rotate and balance six tires.
- Shop Supplies

Parts Issued

Quantity

Napa Quart 5w30 7.00

Napagold Oil Filter 1.00

22" Wiper Blade 2.00

Battery 65 1.00

Shop Supplies 1.00

Hours: 6.50 Comm: 0.00 Labor: 390.00 Parts: 199.39 Total: 589.39

3/4/2026
12:13:25 PM

Palm Beach County Fleet Management Asset Maintenance History
10200772 2016 FORD F350 Utility Body, 14,000 Gvwr, 4X4

Work Order: 1809527 **Meter:** 17914 **In Date:** 09/14/2018 **Closed:** 10/29/2018
Problem: P.M.SERVICE, BATTERY WEAK ALL TIME,SMALL NOISE FROM DRIVE TRAIN WHEN TURNING SLOW,CHECK TIRES.

Work Completed

Parts Issued

Quantity

- Pm Service.
- Mount and balance six tires.
- Repair both rear Led brake lamps.
- Jump start vehicle in Wud parking lotcharge and tested battery.failed.replace battery Napa warranty part.aces code Heoah..dtc code 9co12h
- Clean debris from radiator.clogged not cooling properly
- Install friction modifier to rear differential to reduce noise around turns.ssm45579.road test vehicle to verify repairs.
- Shop Supplies

Napagold Oil Filter	1.00
Napa Quart 5w30	7.00
Used Fire X Refurbished	1.00
Napagold Air Filter	1.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
179636492 Lt245-75r17	6.00
Led Sup Mdl 44 42 Dio	2.00
Battery 65	1.00
Friction Modifier	2.00
Shop Supplies	1.00
Tire Disposal Fee	6.00

Hours: 11.50

Comm: 0.00

Labor: 770.50

Parts: 1,697.18

Total: 2,467.68

Work Order: 1811238 **Meter:** 18753 **In Date:** 10/31/2018 **Closed:** 11/13/2018
Problem: Left front tire flat.

Work Completed

Parts Issued

Quantity

- Repair and balance left front tire.
- Shop Supplies

Shop Supplies	1.00
---------------	------

Hours: 1.00

Comm: 0.00

Labor: 67.00

Parts: 3.00

Total: 70.00

Work Order: 1902400 **Meter:** 21044 **In Date:** 03/05/2019 **Closed:** 03/18/2019
Problem: Check engine light on.Misfires.

Work Completed

Parts Issued

Quantity

- Transport vehicle to and from dealer for repairing for cylinder # 3 misfire.
- Shop Supplies

Shop Supplies	1.00
---------------	------

Hours: 2.00

Comm: 0.00

Labor: 134.00

Parts: 3.00

Total: 137.00

3/4/2026
12:13:25 PM

Palm Beach County Fleet Management Asset Maintenance History
10200772 2016 FORD F350 Utility Body, 14,000 Gvwr, 4X4

Work Order: 1903554 **Meter:** 22290 **In Date:** 04/02/2019 **Closed:** 04/15/2019
Problem: Left rear tire flat.Broken pintle pin.

Work Completed

- Repair and balance left rear inner tire.
- Replace broken pintle pin and chain.
- Shop Supplies

Parts Issued

Quantity

Pintle Pin W/clip	1.00
Shop Supplies	1.00

Hours: 1.25 Comm: 0.00 Labor: 83.75 Parts: 5.61 Total: 89.36

Work Order: 1905541 **Meter:** 23352 **In Date:** 05/24/2019 **Closed:** 06/17/2019
Problem: PM Service Right front tire flat.

Work Completed

- Pm Service
- Replace right and left Led brake lamp assemblies.repaired loosed ground to tail lamp left side also replace right side amber marker lamps on cab box assembly.
- Replace front Oem brake pads.service front rotors,calipers and slides.bleed brake system.
- Replace 6 way trailer plug and wiring harness.
- Mount one tire.rotate and balance six tires.
- Tighten loose hitch ball.
- Vacume debris from engine compartment.
- Shop Supplies

Parts Issued

Quantity

Napa Quart 5w30	7.00
Napagold Oil Filter	1.00
Napagold Air Filter	1.00
22" Wiper Blade	2.00
Washer Fluid Concentr	1.00
Used Fire X Refurbished	1.00
Thinline Marker Amber	2.00
Led Sup Mdl 44 42 Dio	2.00
Non-chlor Brake Clnr	2.00
Brake Pad	1.00
trailer plug	1.00
179636492 Lt245-75r17	1.00
Shop Supplies	1.00
Tire Disposal Fee	1.00

Hours: 16.75 Comm: 0.00 Labor: 1,122.25 Parts: 605.00 Total: 1,727.25

3/4/2026
12:13:25 PM

Palm Beach County Fleet Management Asset Maintenance History
10200772 2016 FORD F350 Utility Body, 14,000 Gvwr, 4X4

Work Order: 1907198 **Meter:** 24600 **In Date:** 07/12/2019 **Closed:** 07/29/2019
Problem: Bad battery.Has to jump start all the time.

Work Completed

Parts Issued

Quantity

- Fully recharge and test battery and charging system.battery failed loadtest.replace battery.napa warranty part.
- Shop Supplies

Battery 65	1.00
Shop Supplies	1.00

Hours: 1.00 Comm: 0.00 Labor: 67.00 Parts: 179.69 Total: 246.69

Work Order: 1912871 **Meter:** 27720 **In Date:** 12/17/2019 **Closed:** 01/27/2020
Problem: PM Service.AC inop.Wiper stay on.Ticking spark sound from engine.

Work Completed

Parts Issued

Quantity

- Pm Service.
- Scan to diagnose wiper system.replace wiper switch.clear codes.
- Replace all 16 sparkplugs and two right side coils.#2 and #3
- R/r throttlebody to service and clean intake system.
- Evac and recharge Ac System.add dye to diag. for leak.
- Replace 6 way socket and repairs wiring harness.
- Rotate and balance 6 tires.
- Clean engine compartment.
- Recover system.vacume and reseal system then recharge to specs.ac Performance test.
- Shop Supplies

Napagold Oil Filter	1.00
Napa Quart 5w30	8.00
Napagold Air Filter	1.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Switch Asy	1.00
Spark Plug	16.00
Coil	2.00
Throttle Body Cleaner	1.00
Freon Sr Shop	2.00
E8 A/c Oil Univ W Dye	1.00
trailer plug	1.00
Red Angel Ac Stop Lk	1.00
Shop Supplies	1.00

Hours: 20.75 Comm: 0.00 Labor: 1,514.75 Parts: 638.77 Total: 2,153.52

3/4/2026
12:13:25 PM

Palm Beach County Fleet Management Asset Maintenance History
10200772 2016 FORD F350 Utility Body, 14,000 Gvwr, 4X4

Work Order: 2004449 **Meter:** 29273 **In Date:** 05/04/2020 **Closed:** 05/11/2020
Problem: Check engine light on.Ac not working.

Work Completed

Parts Issued

Quantity

- Scan and diagnose driveability issues.replace #6 and #7 ignition coils.cleared codes.

Coil 2.00

Shop Supplies 1.00

- Test ac,evact.and recharge to specs.

- Road test to verify repairs.

- Shop Supplies

Hours: 7.50

Comm: 0.00

Labor: 547.50

Parts: 302.41

Total: 849.91

Work Order: 2005540 **Meter:** 29695 **In Date:** 06/02/2020 **Closed:** 07/28/2020
Problem: Ac not working.Flat tire and windshield washer inop.

Work Completed

Parts Issued

Quantity

- R/r inner fender cover to replace expansion valve and seals.replace schrader valves.evacuate and recharge ac system.r/r dash cover to replace ac controller.assembly.

Control 1.00

Relay 2.00

Relay 2.00

- Replace corroded relays in junction box.

Hose Wacher 1.00

- Replace washer nozzles and lines.refill washer fluid.

Washer Jet 2.00

- Repaired left front and right front tires.nitrogen fill and balance both.

Valve 1.00

- Shop Supplies

High Side Schrader Valve 1.00

Freon Sr Shop 2.00

A/c Seal Kit 1.00

A/c Expansion Valve 1.00

Shop Supplies 1.00

Hours: 9.50

Comm: 0.00

Labor: 693.50

Parts: 429.25

Total: 1,122.75

3/4/2026
12:13:25 PM

Palm Beach County Fleet Management Asset Maintenance History
10200772 2016 FORD F350 Utility Body, 14,000 Gvwr, 4X4

Work Order: 2008642 **Meter:** 31654 **In Date:** 08/27/2020 **Closed:** 09/16/2020
Problem: PM Service.Outside temperature inop

Work Completed

- Pm Service.
- Replace both Led brake lamps.repaired wiring ground inside cabinet.
- Rotate and balance 6 tires.
- Use scan tool to reset and reconfigure module for ambient temperature sensor to work on dash.
- Clean engine compartment.
- Shop Supplies

Hours: 9.75

Comm: 0.00

Parts Issued

	Quantity
Used Fire X Refurbished	1.00
Napa Quart 5w30	8.00
Napagold Oil Filter	1.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Led Sup Mdl 44 42 Dio	2.00
Shop Supplies	1.00

Labor: 711.75

Parts: 201.27

Total: 913.02

Work Order: 2010297 **Meter:** 32267 **In Date:** 10/13/2020 **Closed:** 10/27/2020
Problem: Ignition spark jumping and check battery.

Work Completed

- Scan and found code # p0316, perform pinpoint test and found coil pack for cylinder # 3 leaking, Replace both spark plug, coil pack, wire and clear codes.
- check and replace failed battery, check charging system.
- Test drive after repair.
- Shop Supplies

Hours: 53.50

Comm: 0.00

Parts Issued

	Quantity
Spark Plug	2.00
Coil	1.00
Espak Plug Wire	1.00
Battery	1.00
Shop Supplies	1.00

Labor: 3,905.50

Parts: 304.98

Total: 4,210.48

Work Order: 2101226 **Meter:** 34089 **In Date:** 02/02/2021 **Closed:** 02/09/2021
Problem: Check engine light on and stalls.

Work Completed

- c/s c/k light is on & stalls. scan and found code # p0171, p0174, perform pinpoint test and found bad evap canister and purge valve. replace evap canister, valves and clear codes.
- Teat drive before and after repair.
- Shop Supplies

Hours: 6.00

Comm: 0.00

Parts Issued

	Quantity
Solenoid	1.00
Valva Asy	1.00
cannister	1.00
Shop Supplies	1.00

Labor: 438.00

Parts: 225.13

Total: 663.13

3/4/2026
12:13:25 PM

Palm Beach County Fleet Management Asset Maintenance History
10200772 2016 FORD F350 Utility Body, 14,000 Gvwr, 4X4

Work Order: 2103962 **Meter:** 35588 **In Date:** 04/08/2021 **Closed:** 04/21/2021

Problem: PM Service.Check strobes and front end.

Work Completed

- Preventive Maint. Service
- Replaced Hydrobooster And Bleed Air From System
- Wash Engine Compartment From Brake Booster Leaks
- Replaced Rear Brake Pads Service Rotors Calipers And Slides
- Mount And Balanced 6 New Tires
- Replaced Worn Decal
- Shop Supplies

Parts Issued

Quantity

Napa Quart 5w30	8.00
Napagold Oil Filter	1.00
Napagold Air Filter	1.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Real Brake Pad	1.00
Syn Atf Bulk South	1.00
Reman Brake Booster	1.00
Non-chlor Brake Clnr	2.00
Lt245/75r17 Mich Defend Ltx	6.00
Shop Supplies	1.00
Tire Disposal Fee	6.00

Hours: 14.75

Comm: 0.00

Labor: 1,076.75 Parts: 2,178.75 Total: 3,255.50

Work Order: 2107383 **Meter:** 36166 **In Date:** 07/08/2021 **Closed:** 07/13/2021

Problem: Bad battery.Has to be jump started all the time.

Work Completed

- Recharge Battery, test batter, charging system, sating system, battery failed load test. Replace battery.
- Shop Supplies

Parts Issued

Quantity

Battery	1.00
Shop Supplies	1.00

Hours: 1.00

Comm: 0.00

Labor: 73.00 Parts: 108.11 Total: 181.11

3/4/2026
12:13:25 PM

Palm Beach County Fleet Management Asset Maintenance History
10200772 2016 FORD F350 Utility Body, 14,000 Gvwr, 4X4

Work Order: 2112061 **Meter:** 38866 **In Date:** 11/09/2021 **Closed:** 12/07/2021
Problem: PM Service.

Work Completed

- Preventive Maint. Service
- jump start in wud parking lot recharged and test battery replaced failed battery
- patched repaired left rear inner tire rotate and balanced 6 tires
- replaced both brake lamp led assemblies
- Shop Supplies

Parts Issued

Quantity

Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Napagold Oil Filter	1.00
Napa Quart 5w30	8.00
Used Fire X Refurbished	1.00
Right Angle S T Pgtl	2.00
Lamp	2.00
Battery	1.00
Steering Wheel Cover Large	1.00
Shop Supplies	1.00

Hours: 9.00

Comm: 0.00

Labor: 657.00 Parts: 251.92 Total: 908.92

Work Order: 2205394 **Meter:** 42460 **In Date:** 05/23/2022 **Closed:** 05/26/2022
Problem: PM Service.

Work Completed

- Preventive Maint. Service
- R&r battery tray assy to replace washer pump and line assembly
- drill out rivets to replaced both amber marker lamps on front of utility bed
- replaced leaking power brake booster clean off fluid residue
- rotate balanced 6 tires
- Shop Supplies

Parts Issued

Quantity

Used Fire X Refurbished	1.00
Napagold Oil Filter	1.00
Napa Quart 5w30	8.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Napagold Air Filter	1.00
Hose	1.00
Amber Marker Lamp	2.00
Syn Atf Bulk South	1.00
Non-chlor Brake Clnr	1.00
Washer Pump	1.00
Brakr Booster	1.00
Shop Supplies	1.00

Hours: 11.75

Comm: 0.00

Labor: 857.75 Parts: 363.44 Total: 1,221.19

3/4/2026
12:13:25 PM

Palm Beach County Fleet Management Asset Maintenance History
10200772 2016 FORD F350 Utility Body, 14,000 Gvwr, 4X4

Work Order: 2212603 **Meter:** 47380 **In Date:** 12/15/2022 **Closed:** 01/31/2023

Problem: PM Service. Oil smell from pass side rear. Strobes not working.

Work Completed

- Preventive Maint. Service
- replaced front brake pads service rotors calipers and slides
- R&r both rear axles inspect bearings, replaced both rear axle seals and axle o'rings fill rear diff fluid and limited slip additive
- R&r front grill and head lamp assemblies fabricate replaced left rear and right front strobe lamps in lenes and repaired wiring harness
- rotate balanced 6 tires
- road test to verify repairs
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Napa Quart 5w30	8.00
Napagold Air Filter	1.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Non-chlor Brake Clnr	3.00
Front Brake Pad	1.00
Wrn Ambr	2.00
Mnt Conc Led Clear	2.00
Dif Oil	3.00
Axle O Ring	2.00
Seal	2.00
Axle Gasket	2.00
75w140 Ford Axle Lube	3.00
Friction Modifier	1.00
Seal	2.00
Shop Supplies	1.00

Hours: 17.00

Comm: 0.00

Labor: 1,241.00

Parts: 819.27

Total: 2,060.27

Work Order: 2301585 **Meter:** 48326 **In Date:** 02/16/2023 **Closed:** 02/21/2023

Problem: Wont Start

Work Completed

- Diagnose no start & found bad starter. replace starter and clean connections. test drive.
- Shop Supplies

Parts Issued

Quantity

Starter	1.00
Shop Supplies	1.00

Hours: 2.00

Comm: 0.00

Labor: 146.00

Parts: 181.30

Total: 327.30

3/4/2026
12:13:25 PM

Palm Beach County Fleet Management Asset Maintenance History
10200772 2016 FORD F350 Utility Body, 14,000 Gvwr, 4X4

Work Order: 2307335 **Meter:** 51008 **In Date:** 07/25/2023 **Closed:** 08/09/2023

Problem: PM Service. Wrench light on. Misfire. Hesitates. outside over head lights don't work.

Work Completed

- Preventive Maint. Service
- C/s hesitation, scan, perform pinpoint test & found bad coils. Replace 3 coil, 16 spark plugs, wires & clear codes.
- Clean throttle plate & service fuel system.
- Diagnose light bar not working & found bad circuit board, Replace circuit board & test operation. Replace utility body right front marker light, rivet In place & rewire.
- Replace how's my driving & county decal.
- Fill all tires with nitrogen, balance & rotate.
- Shop Supplies

Parts Issued

Quantity

22" Wiper Blade	2.00
Washer Fluid Concentr	1.00
Napa Quart 5w30	1.00
Napagold Oil Filter	1.00
Used Fire X Refurbished	1.00
Napagold Air Filter	1.00
Espak Plug Wire	4.00
Espak Plug Wire	4.00
Coil	1.00
Coil	2.00
Spark Plug	16.00
Motor Tune-up 16oz	1.00
Intake Cleaner Kit	1.00
Led M C Lamp	1.00
Mount	1.00
I/o Board - Liberty li	1.00
Shop Supplies	1.00
Freight Charge	1.00

Hours: 14.25

Comm: 0.00

Labor: 1,040.25

Parts: 1,265.01

Total: 2,305.26

Work Order: 2311109 **Meter:** 52425 **In Date:** 11/03/2023 **Closed:** 11/06/2023

Problem: Battery dead

Work Completed

- Battery Dead Jump Start In Wud Parking Lot Recharged And Tested
- Battery Replaced Failed Battery
- Shop Supplies

Parts Issued

Quantity

Battery	1.00
Shop Supplies	1.00

Hours: 1.00

Comm: 0.00

Labor: 73.00

Parts: 132.98

Total: 205.98

3/4/2026
12:13:25 PM

Palm Beach County Fleet Management Asset Maintenance History
10200772 2016 FORD F350 Utility Body, 14,000 Gvwr, 4X4

Work Order: 2312455 **Meter:** 53242 **In Date:** 12/18/2023 **Closed:** 12/27/2023
Problem: Steering problem.. Death wobble

Work Completed

Parts Issued

Quantity

- Replaced Steering Linkage Damper 20n04b Recall
- Front tires worn below min 32nds. Mount /balanced 2 New Front Tires
- Shop Supplies

Damper Asy	1.00
Lt 245/75/17ttr Mic	2.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 2.00

Comm: 0.00

Labor: 146.00 Parts: 594.77 Total: 740.77

Work Order: 2404033 **Meter:** 55915 **In Date:** 04/24/2024 **Closed:** 05/22/2024
Problem: PM Service.

Work Completed

Parts Issued

Quantity

- Preventive Maint. Service
- mount 4 new tires rotate balanced 6 tires
- Shop Supplies

Napagold Oil Filter	1.00
Napa Quart 5w30	8.00
Napagold Air Filter	1.00
2pc Hd Mats Blk	1.00
Steering Wheel Cover Large	1.00
Used Fire X Refurbished	1.00
Lt 245/75/17ttr Mic	4.00
Shop Supplies	1.00
Tire Disposal Fee	4.00

Hours: 6.75

Comm: 0.00

Labor: 492.75 Parts: 1,176.33 Total: 1,669.08

Work Order: 2406363 **Meter:** 57102 **In Date:** 07/01/2024 **Closed:** 07/05/2024
Problem: wipers do not work

Work Completed

Parts Issued

Quantity

- Replaced Wiper Motor Assembly And Wiper / Multi Function Switch Assembly
- Shop Supplies

Switch Asy	1.00
Motor Asy	1.00
Shop Supplies	1.00

Hours: 2.50

Comm: 0.00

Labor: 182.50 Parts: 211.40 Total: 393.90

3/4/2026
12:13:25 PM

Palm Beach County Fleet Management Asset Maintenance History
10200772 2016 FORD F350 Utility Body, 14,000 Gvwr, 4X4

Work Order: 2408738 **Meter:** 58574 **In Date:** 09/10/2024 **Closed:** 09/13/2024
Problem: wiper blades and windshield sprayer

Work Completed

- Driver front windshield wiper arm broke. Replace arm and broken spray nozzle.
- Shop Supplies

Hours: 0.50

Comm: 0.00

Parts Issued

Quantity

Washer Jet	2.00
Washer Fluid 1gal	1.00
Wiper Blade	2.00
Shop Supplies	1.00

Labor: 36.50

Parts: 36.42

Total: 72.92

Work Order: 2410604 **Meter:** 59805 **In Date:** 11/04/2024 **Closed:** 11/22/2024
Problem: PM Service.Battery dead

Work Completed

- Preventive Maint. Service
- Full recharge & test battery, battery failed load test, replace battery.
- Replace both washer nozzle.
- Shop Supplies

Hours: 5.50

Comm: 0.00

Parts Issued

Quantity

Napagold Oil Filter	1.00
Napa Quart 5w30	8.00
Washer Fluid Concentr	1.00
Wiper Blade	2.00
Battery	1.00
Washer Jet	2.00
Shop Supplies	1.00

Labor: 401.50

Parts: 200.90

Total: 602.40

Work Order: 2500614 **Meter:** 60657 **In Date:** 01/22/2025 **Closed:** 02/05/2025
Problem: AC Inop

Work Completed

- Cs a/c inop, diagnose & found leaking schrader valves, evacuate system, replace High & low side schrader valves, vacuum, recharge & leak test system.
- Shop Supplies

Hours: 2.00

Comm: 0.00

Parts Issued

Quantity

R134a Pag 46 W Uv Dy	1.00
Valve	1.00
Valve Assy	1.00
Valve Assy	1.00
Freon Sr Shop	2.00
Shop Supplies	1.00

Labor: 146.00

Parts: 69.91

Total: 215.91

3/4/2026
12:13:25 PM

Palm Beach County Fleet Management Asset Maintenance History
10200772 2016 FORD F350 Utility Body, 14,000 Gvwr, 4X4

Work Order: 2501726 **Meter:** 60960 **In Date:** 02/21/2025 **Closed:** 05/01/2025

Problem: ac not working smells when ac is on

Work Completed

- C/s a/c not working, diagnose, found leaking evaporator coil, recover refrigerant, remove and replace light bar wire harness, dash board, evaporator coil, remove condenser, replace dryer, evacuate, recharge & leak test system.

- Test drive before & after repair to verify vehicle operates as designed.

- Shop Supplies

Parts Issued

Quantity

Kit O	1.00
Seal Kits	2.00
Freon Sr Shop	2.00
accumulator	1.00
Evaporator Core	1.00
Coolent	1.00
Non-chlor Brake Clnr	1.00
Hose	1.00
Washer Fluid Concentr	1.00
Hose	1.00
Shop Supplies	1.00

Hours: 15.50

Comm: 0.00

Labor: 1,131.50 Parts: 479.13 Total: 1,610.63

Work Order: 2505464 **Meter:** 63474 **In Date:** 06/11/2025 **Closed:** 07/11/2025

Problem: PM Service.

Work Completed

- Preventive Maint. Service

- Diagnose Check Engine Light On Scan Code P0456 Very Small Evap Leak. Replaced Evap Purge Solenoid Valve And Gas Cap. Cleared Codes

- R&r Front Grill And Headlamp Assymbles To Replace Both Front Side Marker Lamps And One Roof Marker Lamp

- Rotate Balanced 6 Tires Nitro Filled To Specs

- Road Test To Verify Repairs For Check Engine Light On

- Shop Supplies

Parts Issued

Quantity

Used Fire X Refurbished	1.00
Washer Fluid Concentr	1.00
Wiper Blade	2.00
oil filter	1.00
Napa Quart 5w30	8.00
Napagold Air Filter	1.00
Boxed Miniatures	4.00
Solenoid	1.00
Cap Gas Assy	1.00
Valve Asm	1.00
Shop Supplies	1.00

Hours: 9.50

Comm: 0.00

Labor: 693.50 Parts: 201.68 Total: 895.18

3/4/2026
12:13:25 PM

Palm Beach County Fleet Management Asset Maintenance History
10200772 2016 FORD F350 Utility Body, 14,000 Gvwr, 4X4

Work Order: 2506783 **Meter:** 64133 **In Date:** 07/23/2025 **Closed:** 08/14/2025
Problem: wipers not working ***WAITING FOR NAPA TO RETURN TRANSMISSION***

Work Completed

Parts Issued

Quantity

- Diagnose wipers not working & found bad motor, replace wiper motor
- Shop Supplies

Wiper Motor Assy	2.00
Wiper Tram Assy	2.00
Shop Supplies	1.00

Hours: 1.00 Comm: 0.00

Labor: 73.00 Parts: 476.19 Total: 549.19

Work Order: 2509285 **Meter:** 65332 **In Date:** 09/30/2025 **Closed:** 10/07/2025
Problem: Has to jump start all the time.

Work Completed

Parts Issued

Quantity

- Test starting and charging system.battery failed load test after recharge.replace battery.
- Shop Supplies

Battery	1.00
Shop Supplies	1.00

Hours: 1.00 Comm: 0.00

Labor: 73.00 Parts: 132.00 Total: 205.00

Work Order: 2600233 **Meter:** 67463 **In Date:** 01/09/2026 **Closed:** 01/12/2026
Problem: Transition Prep Charge

Work Completed

Parts Issued

Quantity

- Transition Prep Charge

Blue Df	3.00
---------	------

Hours: 2.00 Comm: 0.00

Labor: 146.00 Parts: 45.73 Total: 191.73

Total Hours: 299.50

Total Labor: 21,236.75

Total Comm: 237.30

Total Parts: 14,457.21