

4/28/2017  
10:12:31AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10182846 2010 TORO 3040 Ballfield Groomer

<b>Workorder:</b> 1100574		<b>Problem:</b> Pre Delivery Inspection		
<b>Meter Reading:</b> 0		<b>Labor</b>	<b>Parts</b>	
<b>In Date:</b> 01/14/2011	<b>Close Date:</b> 01/14/2011	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>
- Pre Delivery Inspection		<b>2.00</b>		
	<b>Parts Charge:</b> 0.00	<b>Labor Charge:</b>	120.00	

<b>Workorder:</b> 1200476		<b>Problem:</b> PM / Repair muffler		
<b>Meter Reading:</b> 219		<b>Labor</b>	<b>Parts</b>	
<b>In Date:</b> 01/13/2012	<b>Close Date:</b> 01/19/2012	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>
- Pm		<b>6.00</b>	492932 B&S OIL FILTER FRAM PH8170 WIX 57035	1.00
- Hydraulic Service			3031 FUEL FILTER 1/4" FRM G1 WIX 33031	1.00
- Ign Service			51551 HYDRAULIC FILTER	1.00
- Shop Supplies			BKR5E SPARK PLUG 7938	2.00
			10W30 MOTOR OIL	2.00
			SHOP SUPPLIES	1.00
			6449 AIR FILTERFRM CA9248 WIX 46449	1.00
	<b>Parts Charge:</b> 33.89	<b>Labor Charge:</b>	360.00	

<b>Workorder:</b> 1302173		<b>Problem:</b> pm service		
<b>Meter Reading:</b> 377		<b>Labor</b>	<b>Parts</b>	
<b>In Date:</b> 03/04/2013	<b>Close Date:</b> 03/14/2013	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>
- Pm Service		<b>7.50</b>	SHOP SUPPLIES	1.00
- Ign Sys Service Tune Up			NAPAGOLD AIR FILTER	1.00
- Fix Parking Brake-Fabricate Hardware For Cables			NAPAGOLD OIL FILTER	1.00
- Wash Eqpt			NAPA 10W30 QT	2.00
- Shop Supplies			BRAKE CLEANER	1.00
			SPARK PLUG	2.00
			NAPAGOLD FUEL FILTER	1.00
	<b>Parts Charge:</b> 37.09	<b>Labor Charge:</b>	450.00	

4/28/2017  
10:12:31AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10182846 2010 TORO 3040 Ballfield Groomer

**Workorder:** 1306934

**Problem:** engine floods/ see notes

Meter Reading: 377	Labor	Parts	
In Date: 07/11/2013	Hours	Description	Quantity
- Carb Rebuild And Clean Order Parts	3.00	CARBURETOR FLOAT	1.00
- Replace Fuel Shut Off Valve		CLEAN-R-CARB 200Z	1.00
- Tune Up Repalce Plugs Ign Sys Service		FUEL SHUT OFF VALVE	1.00
- Shop Supplies		SPARK PLUG	2.00
		SHOP SUPPLIES	1.00
		Freight Charge	1.00
		CARB OVERHAUL KIT	1.00
<b>Parts Charge:</b>	222.49	<b>Labor Charge:</b>	180.00

**Workorder:** 1404536

**Problem:** pm service

Meter Reading: 474	Labor	Parts	
In Date: 05/08/2014	Hours	Description	Quantity
- Pm	15.00	PEDAL PAD	1.00
- Clean Unit		LIP SEAL	1.00
- R&R Hydraulic Cooling Fan And Repalce Shaft Seal		SHOP SUPPLIES	1.00
- Fr&R Covers To Gain Access To Hyd Cooler And Fan		NAPAGOLD OIL FILTER	1.00
- Hydro Sys Service W/Total Sys Drain And Refill		SEAL-LIP	2.00
- Ign Sys Service		AW68 HYDRO FLUID HYDR	20.00
- Replace Tire Leaking Fan Crack In Sidewall		10W30 MOTOR OIL	2.00
- Shop Supplies		NAPAGOLD AIR FILTER	1.00
		22X1100X8 KNOBBY	1.00
		NAPA HYDRAULIC FILTR	1.00
		NAPAGOLD FUEL FILTER	1.00
		SPARK PLUG	2.00
		TIRE DISPOSAL FEE	1.00
<b>Parts Charge:</b>	279.29	<b>Labor Charge:</b>	900.00

4/28/2017  
10:12:31AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10182846 2010 TORO 3040 Ballfield Groomer

**Workorder:** 1408912

**Problem:** hydraulic leak

Meter Reading: 487	Labor	Parts	
In Date: 09/04/2014	Hours	Description	Quantity
- Diagnose Hydro Leak Replace Hoses And Fitting And Gaskets	4.00	HYD HOSE ASM O-RING	1.00 2.00
- Wash Out Dirt In Oil Cooler		Freight Charge	1.00
- Shop Supplies		FITTING HYD FITTING O RING	3.00 3.00 2.00
		AW68 HYDRO FLUID HYDR	10.00
		SHOP SUPPLIES	1.00
		O-RING	2.00
<b>Parts Charge:</b>	222.37	<b>Labor Charge:</b>	240.00

**Workorder:** 1501903

**Problem:** check tires, poss. rgt rear bad

Meter Reading: 514	Labor	Parts	
In Date: 02/23/2015	Hours	Description	Quantity
- Pm	6.00	TIRE DISPOSAL FEE	1.00
- Replace Tire Rr		SHOP SUPPLIES	1.00
- Wash Eqpt		NAPAGOLD OIL FILTER	1.00
- Shop Supplies		NAPAGOLD AIR FILTER BRAKE CLEANER 10W30 MOTOR OIL 22X1100X8 KNOBBY NAPAGOLD FUEL FILTER	1.00 1.00 2.00 1.00 1.00
<b>Parts Charge:</b>	165.70	<b>Labor Charge:</b>	360.00

4/28/2017  
10:12:31AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10182846 2010 TORO 3040 Ballfield Groomer

**Workorder:** 1604473

**Problem:** pm service

Meter Reading: 525	Labor	Parts
In Date: 04/28/2016	Hours	Quantity
Close Date: 05/24/2016	Description	
- Pm	<b>17.00</b>	SPARK PLUG 2.00
- Engine No Power Low Compression-R&R Engine And		SHOP SUPPLIES 1.00
Disassemble And Replace Piston Rings, Cylinders,		CYLINDER HEAD GASKET 2.00
Replace Valve Seals And Lap Valves, Test Run And		RING SET 2.00
Readjust Valve Lash		NAPA 10W30 QT 2.00
- Drain Fuel Sys And Install New Gas		OIL SEAL 1.00
- Shop Supplies		VALVE SEAL 2.00
		CRANKCASE GASKET 1.00
		EXHAUST GASKET 2.00
		INTAKE GASKET 2.00
		ROCKER COVER GASKET 2.00
		OIL SEAL 1.00
		NAPAGOLD OIL FILTER 1.00
		NAPAGOLD FUEL FILTER 1.00
<b>Parts Charge:</b>	276.17	<b>Labor Charge:</b> 1,020.00

**Workorder:** 1704038

**Problem:** Transition Prep Charge

Meter Reading: 525	Labor	Parts
In Date: 04/21/2017	Hours	Quantity
Close Date: 04/21/2017	Description	
- Transition Prep Charge	<b>2.00</b>	
<b>Parts Charge:</b>	0.00	<b>Labor Charge:</b> 0.00

Total Parts Charges:	<b>1,237.00</b>	Total Labor Charges:	<b>3,630.00</b>	Total Comm. Charges:	<b>0.00</b>
----------------------	-----------------	----------------------	-----------------	----------------------	-------------