

4/10/2026
9:32:28 AM

Palm Beach County Fleet Management Asset Maintenance History
10196003 2015 FORD F350 Pickup, 1 Ton, Crew Cab, 4X4

Total Hours: 214.55 Labor: 14,619.20 Parts: 11,394.51 Comm: 713.75 Charged: 26727.46

Work Order: 1500022 **Meter:** 329 **In Date:** 01/02/2015 **Closed:** 01/12/2015
Problem: fill def fluid

Work Completed

- Fill def tank parts only

Hours: 0.00

Comm: 0.00

Parts Issued

Def Quart

4.00

Labor: 0.00

Parts: 6.18

Total: 6.18

Work Order: 1500129 **Meter:** 332 **In Date:** 01/06/2015 **Closed:** 01/15/2015
Problem: Replace tires with A/T tires.

Work Completed

- Replace and balance all six tires.

- Shop Supplies

Hours: 3.00

Comm: 0.00

Parts Issued

Lt265 70r17 Disc A/t3 Tire

6.00

Shop Supplies

1.00

Tire Disposal Fee

6.00

Labor: 180.00

Parts: 1,748.03

Total: 1,928.03

Work Order: 1500179 **Meter:** 329 **In Date:** 01/06/2015 **Closed:** 01/06/2015
Problem: 1061 - Pre Delivery Inspection

Work Completed

- Pre Delivery Inspection

Hours: 3.00

Comm: 0.00

Labor: 180.00

Parts: 0.00

Total: 180.00

Work Order: 1502492 **Meter:** 597 **In Date:** 03/10/2015 **Closed:** 03/10/2015
Problem: 2 - Wash ticket(s) issued

Work Completed

- 2 - Wash ticket(s) issued

Hours: 0.00

Comm: 19.08

Labor: 0.00

Parts: 0.00

Total: 19.08

4/10/2026
9:32:28 AM

Palm Beach County Fleet Management Asset Maintenance History
10196003 2015 FORD F350 Pickup, 1 Ton, Crew Cab, 4X4

Work Order: 1512712 **Meter:** 2431 **In Date:** 12/16/2015 **Closed:** 01/19/2016
Problem: P.M. service and check engine light on and back up camera not clear.

Work Completed

Parts Issued

Quantity

- Pm service.
- Check back up camera operation.clean lens and adjust.
- Inspect and service winch.
- Rotate and balance all six tires.
- Transport vehicle to and from dealer for Nox sensor replacement.(p2201)
- Shop Supplies

15-40 Oil	14.00
Napagold Oil Filter	1.00
Napagold Fuel Filter	1.00
Floor Mat-2pc Rub Bk	1.00
Stg Wheel Cov - Ford	1.00
Shop Supplies	1.00

Hours: 9.00 Comm: 0.00 Labor: 540.00 Parts: 142.28 Total: 682.28

Work Order: 1606516 **Meter:** 4361 **In Date:** 06/27/2016 **Closed:** 06/30/2016
Problem: P.M. Service.

Work Completed

Parts Issued

Quantity

- P.m. Service.
- Inspect and service winch.
- Rotate and balance all; tires.
- Shop Supplies

15-40 Oil	14.00
Napagold Oil Filter	1.00
Napagold Fuel Filter	1.00
Used Fire X Refurbished	1.00
Def Quart	8.00
Shop Supplies	1.00

Hours: 6.00 Comm: 0.00 Labor: 360.00 Parts: 129.16 Total: 489.16

Work Order: 1608236 **Meter:** 4541 **In Date:** 08/10/2016 **Closed:** 08/29/2016
Problem: DEF fluid level warning on dash.

Work Completed

Parts Issued

Quantity

- Refill Def system.clear light.
- Shop Supplies

Blue Df	1.00
Shop Supplies	1.00

Hours: 1.00 Comm: 0.00 Labor: 60.00 Parts: 15.58 Total: 75.58

4/10/2026
9:32:28 AM

Palm Beach County Fleet Management Asset Maintenance History
10196003 2015 FORD F350 Pickup, 1 Ton, Crew Cab, 4X4

Work Order: 1612675 **Meter:** 5499 **In Date:** 12/12/2016 **Closed:** 01/03/2017
Problem: P.M. Service.

Work Completed

- P.m. Service.
- Inspect and service winch.
- Rotate and balance tires.
- Shop Supplies

Parts Issued

Quantity

15-40 Oil	14.00
Napagold Oil Filter	1.00
Napagold Fuel Filter	1.00
Wd40 Spr	1.00
22" Wiper Blade	2.00
Def Bulk Qts	3.00
Shop Supplies	1.00

Hours: 6.50 Comm: 0.00 Labor: 390.00 Parts: 117.77 Total: 507.77

Work Order: 1700471 **Meter:** 6075 **In Date:** 01/17/2017 **Closed:** 01/31/2017
Problem: Nails in left rear outter tire.

Work Completed

- Replace and balance damaged lef rear outter tire.
- Shop Supplies

Parts Issued

Quantity

Lt265/70/17 Tire Cooper A/t3	1.00
Shop Supplies	1.00
Tire Disposal Fee	1.00

Hours: 1.00 Comm: 0.00 Labor: 60.00 Parts: 270.03 Total: 330.03

Work Order: 1700860 **Meter:** 6006 **In Date:** 01/27/2017 **Closed:** 01/27/2017
Problem: 12 - Wash ticket(s) issued

Work Completed

- 12 - Wash ticket(s) issued

Hours: 0.00 Comm: 114.48 Labor: 0.00 Parts: 0.00 Total: 114.48

4/10/2026
9:32:28 AM

Palm Beach County Fleet Management Asset Maintenance History
10196003 2015 FORD F350 Pickup, 1 Ton, Crew Cab, 4X4

Work Order: 1705747 **Meter:** 9145 **In Date:** 06/09/2017 **Closed:** 06/15/2017
Problem: Exhaust fluid light on and runs rough at highway speeds.

Work Completed

- Fill Def tank.hook-up lds to perform Scr fill activation to reset level sensor retest.
- Test drive .could not duplicate running rough at highway speeds.computer scan .no codes found.perform manuel regen.
- Shop Supplies

Parts Issued

Quantity

Def Bulk Qts	22.00
Shop Supplies	1.00

Hours: 2.00 Comm: 0.00 Labor: 120.00 Parts: 35.66 Total: 155.66

Work Order: 1706356 **Meter:** 9237 **In Date:** 06/27/2017 **Closed:** 07/10/2017
Problem: P.M. Service.Replace back up camera.

Work Completed

- P.m. service.
- Check batteries and charging system.charged both batteries and retest .found positive cable on drivers side removed .reinstalled cable and crimped new end onto aux battery cable.normal operation of starting and charging systems.
- found rear view camera lens foggy due to calciun build up.used compound to buff put lens.found rear view camera visible at this time.
- High speed balance all six tires.nitro filled.
- Found condensation in right rear tail light .reseled strobe light and reinstalled.
- Replaced corroded trailer connector.
- Completed winch service and inspection.
- Shop Supplies

Parts Issued

Quantity

trailer plug	1.00
Napagold Oil Filter	1.00
15-40 Oil	13.00
Fuel Filter Kit	1.00
22" Wiper Blade	2.00
Washer Fluid Concentr	1.00
Used Fire X Refurbished	1.00
Def Bulk Qts	1.00
Shop Supplies	1.00

Hours: 10.85 Comm: 0.00 Labor: 651.00 Parts: 184.13 Total: 835.13

4/10/2026
9:32:28 AM

Palm Beach County Fleet Management Asset Maintenance History
10196003 2015 FORD F350 Pickup, 1 Ton, Crew Cab, 4X4

Work Order: 1801190 **Meter:** 10938 **In Date:** 01/31/2018 **Closed:** 02/06/2018
Problem: P.M. service and had to jump start.

Work Completed

- P.m. service.
- Load test both batteries ,failed load test due to bad cell.replace both batteries with new.
- Insect and service power winch.
- Rotate and balance all six tires.
- Shop Supplies

Parts Issued

Quantity

15-40 Oil	13.00
Napagold Oil Filter	1.00
Napagold Fuel Filter	1.00
Washer Fluid Concentr	1.00
Blue Df	1.00
22" Wiper Blade	2.00
Battery 65	2.00
Terminal Prot 2pk	2.00
Shop Supplies	1.00

Hours: 8.50

Comm: 0.00

Labor: 510.00

Parts: 433.27

Total: 943.27

Work Order: 1803044 **Meter:** 12771 **In Date:** 03/22/2018 **Closed:** 03/22/2018
Problem: 12 - Wash ticket(s) issued

Work Completed

- 12 - Wash ticket(s) issued

Hours: 0.00

Comm: 114.48

Labor: 0.00

Parts: 0.00

Total: 114.48

Work Order: 1805816 **Meter:** 13148 **In Date:** 06/06/2018 **Closed:** 06/12/2018
Problem: Vibration above 60 mph.

Work Completed

- Test drive vehicle for vibration at high speeds.rotate and balance all tire.index and rebalance one wheel.
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
---------------	------

Hours: 1.50

Comm: 0.00

Labor: 90.00

Parts: 2.00

Total: 92.00

4/10/2026
9:32:28 AM

Palm Beach County Fleet Management Asset Maintenance History
10196003 2015 FORD F350 Pickup, 1 Ton, Crew Cab, 4X4

Work Order: 2002177 **Meter:** 26220 **In Date:** 03/02/2020 **Closed:** 03/02/2020
Problem: 5 - Wash ticket(s) issued

Work Completed

- 5 - Wash ticket(s) issued

Hours: 0.00 Comm: 47.70 Labor: 0.00 Parts: 0.00 Total: 47.70

Work Order: 2003651 **Meter:** 26786 **In Date:** 04/13/2020 **Closed:** 04/16/2020
Problem: P.M. service.

Work Completed

- P.m. service.
- Replace four tires . Rotate and balance all six tires . Nitrofill all.
- Inspect and service winch .
- Water leak test left tail lamp lens . Remove to reseal strobe bulb . and dry out light . Retest .
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
15-40 Oil	13.00
Napagold Fuel Filter	1.00
Blue Df	2.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Lt265/70r17 Tire E	4.00
Shop Supplies	1.00
Tire Disposal Fee	4.00

Hours: 8.80 Comm: 0.00 Labor: 642.40 Parts: 1,182.24 Total: 1,824.64

Work Order: 2006871 **Meter:** 27375 **In Date:** 07/14/2020 **Closed:** 07/14/2020
Problem: 5 - Wash ticket(s) issued

Work Completed

- 5 - Wash ticket(s) issued

Hours: 0.00 Comm: 47.70 Labor: 0.00 Parts: 0.00 Total: 47.70

4/10/2026
9:32:28 AM

Palm Beach County Fleet Management Asset Maintenance History
10196003 2015 FORD F350 Pickup, 1 Ton, Crew Cab, 4X4

Work Order: 2009720 **Meter:** 27991 **In Date:** 09/28/2020 **Closed:** 10/05/2020
Problem: P.M. service and check hitch height .

Work Completed

- P.m. service.
- Rotate and balance all six tires . Nitrofill all.
- Inspect and service winch .
- Adjust trailer hitch height per request .
- Shop Supplies

Parts Issued

Quantity

15-40 Oil	13.00
Napagold Oil Filter	1.00
Air Filter (gold), Air Panel	1.00
22" Wiper Blade	2.00
Washer Fluid Concentr	1.00
Napagold Fuel Filter	1.00
Used Fire X Refurbished	1.00
Shop Supplies	1.00

Hours: 7.00

Comm: 0.00

Labor: 511.00

Parts: 144.54

Total: 655.54

Work Order: 2104250 **Meter:** 29960 **In Date:** 04/15/2021 **Closed:** 04/26/2021
Problem: Due for PM. Had to jump start .

Work Completed

- Preventive Maint. Service
- Rotated and balanced all 6 tires. Nitrogen filled all tires
- Charged both batteries fully. Tested starting and charging system. Both batteries tested bad. R and R both batteries.
- Inspect and serviced winch
- Shop Supplies

Parts Issued

Quantity

Napagold Fuel Filter	1.00
22" Wiper Blade	2.00
Napagold Oil Filter	1.00
15-40 Oil	13.00
Blue Df	1.00
Battery	2.00
Shop Supplies	1.00

Hours: 8.50

Comm: 0.00

Labor: 620.50

Parts: 509.76

Total: 1,130.26

Work Order: 2106943 **Meter:** 30425 **In Date:** 06/24/2021 **Closed:** 06/24/2021
Problem: 5 - Wash ticket(s) issued

Work Completed

- 5 - Wash ticket(s) issued

Hours: 0.00

Comm: 47.70

Labor: 0.00

Parts: 0.00

Total: 47.70

4/10/2026
9:32:28 AM

Palm Beach County Fleet Management Asset Maintenance History
10196003 2015 FORD F350 Pickup, 1 Ton, Crew Cab, 4X4

Work Order: 2111483 **Meter:** 31436 **In Date:** 10/25/2021 **Closed:** 11/02/2021
Problem: PM Service. Key fob weak and wiper blades

Work Completed

- Preventive Maint. Service
- Test And Replace Key Fob Battery . Retest .
- Inspect And Service Winch
- Inspect Tires, Rotate And Balance All 6 Tires With Nitro Fill
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
15-40 Oil	14.00
Napagold Fuel Filter	1.00
22" Wiper Blade	2.00
Used Fire X Refurbished	1.00
Enr Elect Battery	1.00
Blue Df	1.00
Fuel Filter Ford Only	1.00
20" Wiper Blade	2.00
Napagold Oil Filter	1.00
Shop Supplies	1.00

Hours: 6.70

Comm: 0.00

Labor: 489.10 Parts: 197.47 Total: 686.57

Work Order: 2203983 **Meter:** 33498 **In Date:** 04/13/2022 **Closed:** 04/18/2022
Problem: PM Service.

Work Completed

- Preventive Maint. Service
- Rotate and speed balance all six, nitro fill
- Inspect and service winches
- Shop Supplies

Parts Issued

Quantity

Blue Df	1.00
Wd40 Spr	1.00
Napagold Fuel Filter	1.00
Napagold Oil Filter	1.00
15-40 Oil	14.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Shop Supplies	1.00

Hours: 6.50

Comm: 0.00

Labor: 474.50 Parts: 126.38 Total: 600.88

4/10/2026
9:32:28 AM

Palm Beach County Fleet Management Asset Maintenance History
10196003 2015 FORD F350 Pickup, 1 Ton, Crew Cab, 4X4

Work Order: 2211373 **Meter:** 35442 **In Date:** 11/04/2022 **Closed:** 12/20/2022

Problem: PM Service. Please water test roof around clearance lights/ antenna.

Work Completed

- Preventive Maint. Service
- Water Leak Check Roof And Found Water Leaking Into Roof Lamp On Driver Side. Drop Down Head Liner To Replace Roof Marker Lamps. Recheck And Verified Repair Complete.
- Inspect And Service Power Winch.
- Rotate And Balance Six Tires.
- Shop Supplies

Parts Issued

Quantity

Prem Blue 15w40 1 Gal	3.00
Napagold Oil Filter	1.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Used Fire X Refurbished	1.00
Napagold Fuel Filter	1.00
Blue Df	1.00
Napa Qt 15w40	1.00
Lamp	2.00
Shop Supplies	1.00

Hours: 9.00

Comm: 0.00

Labor: 657.00

Parts: 203.06

Total: 860.06

Work Order: 2305807 **Meter:** 38429 **In Date:** 06/12/2023 **Closed:** 06/15/2023

Problem: PM Service and water leaking on radios

Work Completed

- Preventive Maint. Service
- rotate and balance all 6 tires nitro fill all
- both battery failed load test during inspection remove and replace both defective batteries
- customer states water can be found inside cabin on radios water was found to be coming in through cab light on the out side remove and replace 3 cab lights test again after repairs to insure proper seal
- replace front brake pads and machine rotors, service calipers, flush and bleed brake systems, test drive after repairs
- inspect and service winch and all moving parts
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Napa Qt 15w40	13.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Blue Df	1.00
Air Filter (gold), Air Panel	1.00
Battery	2.00
Non-chlor Brake Clnr	1.00
Brake Fl-dot 3-4 32oz	1.00
Front Brake Pad	1.00
Lamp	3.00
Fuel Filter	1.00
Shop Supplies	1.00

Hours: 15.50

Comm: 0.00

Labor: 1,131.50

Parts: 528.60

Total: 1,660.10

4/10/2026
9:32:28 AM

Palm Beach County Fleet Management Asset Maintenance History
10196003 2015 FORD F350 Pickup, 1 Ton, Crew Cab, 4X4

Work Order: 2308759 **Meter:** 38997 **In Date:** 08/30/2023 **Closed:** 08/31/2023

Problem: Please perform a health check for vehicle deployment out of county.

Work Completed

Parts Issued

Quantity

- Perform vehicle safety inspection, Replace wipers, top off fluids, inflate tire pressures.
- Shop Supplies

Wiper Blade	2.00
Shop Supplies	1.00

Hours: 1.00 Comm: 0.00 Labor: 73.00 Parts: 46.91 Total: 119.91

Work Order: 2311841 **Meter:** 40439 **In Date:** 11/29/2023 **Closed:** 12/12/2023

Problem: PM Service and trailer light inop and brake light out and back up camera foggy

Work Completed

Parts Issued

Quantity

- Preventive Maint. Service
- rotate and balance. all 6 tires nitro fill all
- customer states left rear brake light out Remove and replace rear brake bulb . Clean and buff back up camera .retest .
- customer states trailer light inop trailer plug was inspected and moisture was found remove and replace trailer plug
- Shop Supplies

Napagold Oil Filter	1.00
Napa Qt 15w40	13.00
Washer Fluid Concentr	1.00
Wiper Blade	2.00
Fuel Filter	1.00
Blue Df	1.00
Used Fire X Refurbished	1.00
Boxed Miniatures	1.00
Trailer Connector Truck Side	1.00
Shop Supplies	1.00

Hours: 7.30 Comm: 0.00 Labor: 532.90 Parts: 167.64 Total: 700.54

Work Order: 2401005 **Meter:** 41103 **In Date:** 01/29/2024 **Closed:** 02/01/2024

Problem: A/C not blowing. Please check trailer plug connection. Not getting running lights on trailers

Work Completed

Parts Issued

Quantity

- A/c performance test . Diagnose blower inop . Replace defective relay and retest operation .
- Diagnose trailer parking lights inop . Replace corroded trailer plug and replace blow 30 amp box fuse .
- Shop Supplies

Trailer Connector Truck Side	1.00
Bp Fmx-lp F Mx Fuse	2.00
Relay	1.00
Shop Supplies	1.00

Hours: 2.60 Comm: 0.00 Labor: 189.80 Parts: 47.85 Total: 237.65

4/10/2026
9:32:28 AM

Palm Beach County Fleet Management Asset Maintenance History
10196003 2015 FORD F350 Pickup, 1 Ton, Crew Cab, 4X4

Work Order: 2409178 **Meter:** 43896 **In Date:** 09/24/2024 **Closed:** 09/30/2024
Problem: exposed wires in bed and check for trip .

Work Completed

- Repair rear strobe lamp bar light wiring. Diagnose and Replace blown high mount brake lamp fuse #31.
- Diagnose traction light on. Codes U0028, C0061, C0063, C0062 and C0064. Perform pin-point tests. Remove driver's seat, trace can-bus wiring look for chafed wiring etc. Replace Rcm and service connectors.
- Replace wiper blades and fill Def. Check all fluid levels and tire pressures
- Shop Supplies

Parts Issued	Quantity
Sensor Asy Mudule	1.00
Wiper Blade	2.00
Shop Supplies	1.00

Hours: 5.50 Comm: 0.00 Labor: 401.50 Parts: 471.57 Total: 873.07

Work Order: 2410993 **Meter:** 44459 **In Date:** 11/15/2024 **Closed:** 11/26/2024
Problem: truck and center console is vibrating aggressively. not sure if its 6th gear or specifically 40-50mph.

Work Completed

- Road test . Computer diagnose check engine light , P02ee . Perform pin point test . Clean corroded connector at Pcm for injector one . Clear code and retest drive at 45 mph for 10 miles Ok at this time
- Shop Supplies

Parts Issued	Quantity
Shop Supplies	1.00

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 2.65 Total: 148.65

Work Order: 2412219 **Meter:** 44691 **In Date:** 12/30/2024 **Closed:** 01/13/2025
Problem: PM Service . back up camera is blurry/cloudy

Work Completed

- Preventive Maint. Service
- Rotated and balanced all 6 tires. Nitrogen filled all tires.
- Inspect and serviced winch.
- Cleaned and polished back up camera Lense.
- Shop Supplies

Parts Issued	Quantity
Napagold Oil Filter	1.00
Napa Qt 15w40	13.00
Blue Df	1.00
Fuel Filter	1.00
Used Fire X Refurbished	1.00
Mac Battery Protect	1.00
Shop Supplies	1.00

Hours: 7.10 Comm: 0.00 Labor: 518.30 Parts: 140.25 Total: 658.55

4/10/2026
9:32:28 AM

Palm Beach County Fleet Management Asset Maintenance History
10196003 2015 FORD F350 Pickup, 1 Ton, Crew Cab, 4X4

Work Order: 2501986 **Meter:** 45185 **In Date:** 02/19/2025 **Closed:** 02/27/2025
Problem: 1 - Wash ticket(s) Issued to: Justin Klosenberg

Work Completed

- 1 - Wash ticket(s) Issued to: Justin Klosenberg

Hours: 0.00 Comm: 8.59 Labor: 0.00 Parts: 0.00 Total: 8.59

Work Order: 2507599 **Meter:** 46834 **In Date:** 08/13/2025 **Closed:** 08/27/2025
Problem: PM Service, Vehicle was erratically shaking when on the highway. No engine light and no visible issues with the tires. I

Work Completed

- Preventive Maint. Service Test drove vehicle and could not duplicate concern only felt tire vibration.
- Mount and balance 4 new tires due to tires coming apart. Rotated and balanced all 6 tires. Nitrogen filled all tires.
- Batteries tested bad. Charged batteries fully and retested bad. Replaced bad batteries.
- Inspect and serviced winch
- Shop Supplies

Parts Issued

Quantity

Battery	2.00
Fuel Filter	1.00
Blue Df	1.00
Wiper Blade	2.00
Washer Fluid Concentr	1.00
Napa Qt 15w40	13.00
Napagold Oil Filter	1.00
Lt265/70/17 Tire Goodyear	4.00
Shop Supplies	1.00
Tire Disposal Fee	4.00

Hours: 10.00 Comm: 0.00 Labor: 730.00 Parts: 1,232.58 Total: 1,962.58

Work Order: 2508892 **Meter:** 46881 **In Date:** 09/19/2025 **Closed:** 10/08/2025
Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 3.00 Comm: 0.00 Labor: 219.00 Parts: 0.00 Total: 219.00

Total Hours: 214.55

Total Labor: 14,619.20

Total Comm: 713.75

Total Parts: 11,394.51