

4/10/2026  
9:36:49 AM

**Palm Beach County Fleet Management Asset Maintenance History**  
**10208242 2019 FORD F350 Utility Body, 14,000 Gvwr**

---

**Total Hours: 158.75   Labor: 11,528.75   Parts: 16,812.63   Comm: 84.75   Charged: 28426.13**

---

**Work Order:** 1904431      **Meter:** 321      **In Date:** 04/24/2019   **Closed:** 05/03/2019  
**Problem:** ore delivery inspection

**Work Completed**

- pre delivery inspection
- Shop Supplies

Hours: 3.00

Comm: 0.00

**Parts Issued**

Shop Supplies

**Quantity**

1.00

Labor: 201.00

Parts: 3.00

Total: 204.00

---

**Work Order:** 1906158      **Meter:** 3957      **In Date:** 06/11/2019   **Closed:** 08/06/2019  
**Problem:** Install shovel box.

**Work Completed**

- Install box.
- Shop Supplies

Hours: 1.00

Comm: 0.00

**Parts Issued**

open top pipe box

**Quantity**

1.00

Shop Supplies

1.00

Labor: 67.00

Parts: 1,034.25

Total: 1,101.25

---

**Work Order:** 1909253      **Meter:** 5203      **In Date:** 09/09/2019   **Closed:** 09/17/2019  
**Problem:** Pm service, check a/c blower operation.

**Work Completed**

- Pm service.
- Blower motor only working on high speed. Replace shorted blower motor assy.
- Test drive.
- Shop Supplies

Hours: 6.00

Comm: 0.00

**Parts Issued**

Napagold Oil Filter

**Quantity**

1.00

Napa Quart 5w30

7.00

Washer Fluid Concentr

1.00

22" Wiper Blade

2.00

Air Fltr

1.00

Blower Motor Asy

1.00

Air Fltr

1.00

Shop Supplies

1.00

Labor: 402.00

Parts: 332.93

Total: 734.93







4/10/2026  
9:36:49 AM

**Palm Beach County Fleet Management Asset Maintenance History**  
**10208242 2019 FORD F350 Utility Body, 14,000 Gvwr**

**Work Order:** 2110176      **Meter:** 39109      **In Date:** 09/20/2021      **Closed:** 09/23/2021  
**Problem:** PM Service.

**Work Completed**

- Test drive
- Pm service
- Both front tire worn. Mount and balance both front tires.
- Replace worn front brake pads, sticking brake calipers, rotors and flush brake fluid.
- Replace cabin air filter
- Shop Supplies

**Parts Issued**

**Quantity**

Air Fltr	1.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Napa Quart 5w30	8.00
Napagold Oil Filter	1.00
Lt245/75r17 Mich Defend Ltx	2.00
Cap	2.00
Non-chlor Brake Clnr	1.00
Brk Fluid Dot 4-32oz	3.00
Brake Caliper	1.00
Brake Caliper	1.00
Seal	2.00
Rotor	2.00
Brake Pad Motorcraft	1.00
Cabin Filter	1.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 10.00

Comm: 0.00

Labor: 730.00

Parts: 1,356.46

Total: 2,086.46

**Work Order:** 2113442      **Meter:** 43673      **In Date:** 12/20/2021      **Closed:** 12/21/2021  
**Problem:** Two flat tires.Right rear tires has nail thru them.

**Work Completed**

- Patched and balanced two right rear tires.nitrogen fill all six tires and reset Tpms light.
- Shop Supplies

**Parts Issued**

**Quantity**

Shop Supplies	1.00
---------------	------

Hours: 2.00

Comm: 0.00

Labor: 146.00

Parts: 2.65

Total: 148.65

4/10/2026  
9:36:49 AM

**Palm Beach County Fleet Management Asset Maintenance History**  
**10208242 2019 FORD F350 Utility Body, 14,000 Gvwr**

**Work Order:** 2201680      **Meter:** 46389      **In Date:** 02/15/2022      **Closed:** 02/28/2022  
**Problem:** PM Service.

**Work Completed**

- Preventive Maintenance Service
- Test drive
- Rear ties worn. Mount and balance 4 tires.
- Battery fail test, installed new battery.
- Replaced shorted both rear tail/turn lamps. Repaired ground on left rear bed marker light.
- Replaced missing trailer hitch pin
- Shop Supplies

**Parts Issued**

**Quantity**

Napagold Oil Filter	1.00
Napa Quart 5w30	8.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Used Fire X Refurbished	1.00
Macs Chain Cable Lube	1.00
Lt245/75r17 Mich Defend Ltx	4.00
Battery	1.00
Led S44 42 Diod S T T	2.00
Air Filter	1.00
Pintle Pin W/clip	1.00
Shop Supplies	1.00
Tire Disposal Fee	4.00

Hours: 9.00

Comm: 0.00

Labor: 657.00      Parts: 1,193.03      Total: 1,850.03

**Work Order:** 2205870      **Meter:** 52461      **In Date:** 06/02/2022      **Closed:** 06/08/2022  
**Problem:** PM Service.

**Work Completed**

- Preventive Maintenance Service
- Test Drive
- Replace 2 worn rear tires and rotate to the front.
- Replaced cabin air filter.
- Shop Supplies

**Parts Issued**

**Quantity**

Napa Quart 5w30	7.00
Napagold Oil Filter	1.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Lt245/75r17 Mich Defend Ltx	2.00
Cabin Air Filter	1.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 6.50

Comm: 0.00

Labor: 474.50      Parts: 554.03      Total: 1,028.53



4/10/2026  
9:36:49 AM

**Palm Beach County Fleet Management Asset Maintenance History**  
**10208242 2019 FORD F350 Utility Body, 14,000 Gvwr**

**Work Order:** 2300780      **Meter:** 62318      **In Date:** 01/25/2023      **Closed:** 02/01/2023  
**Problem:** PM Service.

**Work Completed**

- Preventive Maint. Service
- both front tire are under 4/32nds replaced both front tires rotated and balance rear tires
- replaced cabin filter
- test drive
- Shop Supplies

**Parts Issued**

**Quantity**

22" Wiper Blade	2.00
Washer Fluid Concentr	1.00
Air Filter	1.00
Napagold Oil Filter	1.00
Napa Quart 5w30	7.00
Used Fire X Refurbished	1.00
Lt245/75r17 Mich Defend Ltx	2.00
Cabin Filter Replaces Fp92	1.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 6.50

Comm: 0.00

Labor: 474.50

Parts: 620.38

Total: 1,094.88

**Work Order:** 2303460      **Meter:** 65305      **In Date:** 04/05/2023      **Closed:** 04/06/2023  
**Problem:** NAIL IN TIRE

**Work Completed**

- driver rear inner tire had nail in it repaired tire
- Shop Supplies

**Parts Issued**

**Quantity**

Shop Supplies	1.00
---------------	------

Hours: 1.00

Comm: 0.00

Labor: 73.00

Parts: 2.65

Total: 75.65

**Work Order:** 2305724      **Meter:** 67817      **In Date:** 06/08/2023      **Closed:** 07/31/2023  
**Problem:** PM Service.

**Work Completed**

- Preventive Maintenance Service
- Replaced worn outer rear tires and rotate to the front.
- Test Drive
- Replaced shorted right rear and left front bed marker light.
- Plug wire/cop arching to cylinder head. Replaced all Cop, wires and 16 spark plugs.
- Service rear diff
- Change transmission fluid and filter

**Parts Issued**

**Quantity**

22" Wiper Blade	2.00
Washer Fluid Concentr	1.00
Napa Quart 5w30	7.00
Napagold Oil Filter	1.00
Ball Joint	2.00
Ball Joint	1.00
Pintle Pin W/clip	1.00

4/10/2026  
9:36:49 AM

**Palm Beach County Fleet Management Asset Maintenance History**  
**10208242 2019 FORD F350 Utility Body, 14,000 Gvwr**

- Replaced worn front brake calipers, pads, Flush contaminated fluid from system. Repack wheel bearing.
- Replaced worn rear brake pads, calipers. Repack wheel bearings...
- Replaced worn front lower and upper ball joints on both sides
- Replaced hitch pin clip
- Shop Supplies

<b>Parts Issued</b>	<b>Quantity</b>	
Lt245/75r17 Mich Defend Ltx	2.00	
Thinline Marker Red	1.00	
Amber Marker Light B52	1.00	
Dielect Silicone Comp	1.00	
Spark Plug	16.00	
Spark Plug Wire	8.00	
Ignition Coil	4.00	
Ing Coil	4.00	
Non-chlor Brake Clnr	1.00	
75w140 Ford Axle Lube	4.00	
Non-chlor Brake Clnr	1.00	
Syn Atf Bulk Pahokee	14.00	
trans pan gasket	1.00	
Transmission Filter	1.00	
Brk Fluid Dot 4-32oz	2.00	
Non-chlor Brake Clnr	1.00	
Brake Caliper	1.00	
Brake Caliper	1.00	
Brake Pad Motorcraft	1.00	
Brake Pads	1.00	
Brake Caliper	1.00	
Brake Caliper	1.00	
Ball Joint	1.00	
Shop Supplies	1.00	
Tire Disposal Fee	2.00	
<b>Labor: 2,263.00</b>	<b>Parts: 2,946.72</b>	<b>Total: 5,209.72</b>

Hours: 31.00

Comm: 0.00

4/10/2026  
9:36:49 AM

**Palm Beach County Fleet Management Asset Maintenance History**  
**10208242 2019 FORD F350 Utility Body, 14,000 Gvwr**

---

**Work Order:** 2307919      **Meter:** 69612      **In Date:** 08/09/2023      **Closed:** 08/23/2023

**Problem:** Blower motor will not operate.

**Work Completed**

- Diagnose for blower motor inop.pin point test and found bad blower motor relay.replace blower relay and ac relay.
- Shop Supplies

**Parts Issued**

**Quantity**

Relay	2.00
Shop Supplies	1.00

Hours: 2.00      Comm: 0.00      Labor: 146.00      Parts: 46.30      Total: 192.30

---

**Work Order:** 2312167      **Meter:** 76092      **In Date:** 12/07/2023      **Closed:** 01/05/2024

**Problem:** PM Service.

**Work Completed**

- Pm Service
- Worn/damaged tires. Mount and balance six tires.
- Test Drive
- Slow/won't start. Charge and load test battery it failed. Installed new battery and check charging system.
- Both rear led tail/stop light shorted. Check wiring and fuses, passed. Installed new led tail/stop light assemblies.
- No washer fluid coming from window washer nozzles. Pin point test window washer fluid pump wiring and it passed. Installed pump.
- Replaced cabin air filter
- Shop Supplies

**Parts Issued**

**Quantity**

Wiper Blade	2.00
Washer Fluid Concentr	1.00
Air Fltr	1.00
Napa Quart 5w30	7.00
Napagold Oil Filter	1.00
Used Fire X Refurbished	1.00
Lt245/75r17 Mich Defender2	6.00
Battery	1.00
Led Sup Mdl 44 42 Dio	2.00
Washer Pump	1.00
Cabin Air Filter	1.00
Lt245/75r17 Mich Defender2	6.00
Shop Supplies	1.00
Tire Disposal Fee	6.00
Freight Charge	1.00

Hours: 10.00      Comm: 0.00      Labor: 730.00      Parts: 4,757.02      Total: 5,487.02

4/10/2026  
9:36:49 AM

**Palm Beach County Fleet Management Asset Maintenance History**  
**10208242 2019 FORD F350 Utility Body, 14,000 Gvwr**

---

**Work Order:** 2400645                      **Meter:** 76669                      **In Date:** 01/22/2024   **Closed:** 01/22/2024  
**Problem:** low tire pressure

**Work Completed**

- repaired right rear outter tire

Hours: 0.50                                      Comm: 0.00                      Labor: 36.50                      Parts: 0.00                      Total: 36.50

---

**Work Order:** 2405328                      **Meter:** 82228                      **In Date:** 05/30/2024   **Closed:** 07/22/2024  
**Problem:** PM Service.

**Work Completed**

- Pm service  
- Test drive  
- Rotate and balance six tires  
- Dash flashed trailer disconnected/connected and L/r trailer light failure.  
Upon inspection found corroded trailer light socket. Cut old socket out and replaced with new.  
- Truck will not start. Charge and load test battery, it failed (bad-cell).  
Installed new battery and checked charging system.  
- Shop Supplies

**Parts Issued**

**Quantity**

Wiper Blade	2.00
Washer Fluid Concentr	1.00
Napa Quart 5w30	7.00
Napagold Oil Filter	1.00
Trailer Connector Truck Side	1.00
Battery	1.00
Shop Supplies	1.00

Hours: 7.50                                      Comm: 0.00                      Labor: 547.50                      Parts: 187.85                      Total: 735.35

---

**Work Order:** 2409476                      **Meter:** 85668                      **In Date:** 09/30/2024   **Closed:** 09/30/2024  
**Problem:** FLAT TIRE (DRIVER SIDE BACK(OUTSIDE))

**Work Completed**

- repaired left rear outer tire had nail in it  
- Shop Supplies

**Parts Issued**

**Quantity**

Shop Supplies	1.00
---------------	------

Hours: 1.00                                      Comm: 0.00                      Labor: 73.00                      Parts: 2.65                      Total: 75.65



4/10/2026  
9:36:49 AM

**Palm Beach County Fleet Management Asset Maintenance History**  
**10208242 2019 FORD F350 Utility Body, 14,000 Gvwr**

Hours: 2.00      Comm: 0.00      Labor: 146.00      Parts: 0.00      Total: 146.00

**Total Hours: 158.75**

**Total Labor: 11,528.75**

**Total Comm: 84.75**

**Total Parts: 16,812.63**