

4/10/2026  
9:43:24 AM

**10203868 Palm Beach County Fleet Management Asset Maintenance History**  
**2018 INTERNATIONAL 7500 Sewer Cleaner/Vac Combo, Truck Mntd, 66,000 Gvwr**

---

**Total Hours: 597.50 Labor: 42,909.00 Parts: 49,596.74 Comm: 23,373.71 Charged: 115879.44**

---

**Work Order:** 1710842      **Meter:** 3034      **In Date:** 11/01/2017      **Closed:** 11/13/2017  
**Problem:** Check In

**Work Completed**

**Parts Issued**

**Quantity**

- check in	Blue Df	1.00		
- def	Shop Supplies	1.00		
- add fuel				
- Shop Supplies				
Hours: 9.00	Comm: 0.00	Labor: 540.00	Parts: 15.56	Total: 555.56

---

**Work Order:** 1711049      **Meter:** 3034      **In Date:** 11/07/2017      **Closed:** 11/07/2017  
**Problem:** 1062 - Make & Apply Decals. Check Fluids, Belts and Operation

**Work Completed**

- Make & Apply Decals. Check Fluids, Belts and Operation				
Hours: 1.00	Comm: 0.00	Labor: 60.00	Parts: 0.00	Total: 60.00

---

**Work Order:** 1800305      **Meter:** 3034      **In Date:** 01/09/2018      **Closed:** 01/29/2018  
**Problem:** replace rear gate valve

**Work Completed**

**Parts Issued**

**Quantity**

- replace rear gate valve	valve installed	1.00		
- Shop Supplies	Shop Supplies	1.00		
Hours: 0.00	Comm: 0.00	Labor: 0.00	Parts: 1,328.34	Total: 1,328.34

---

**Work Order:** 1801349      **Meter:** 3034      **In Date:** 02/05/2018      **Closed:** 02/05/2018  
**Problem:** dead battery

**Work Completed**

**Parts Issued**

**Quantity**

- Jump Start	Shop Supplies	1.00		
- Shop Supplies				
Hours: 1.00	Comm: 0.00	Labor: 60.00	Parts: 2.00	Total: 62.00









4/10/2026  
9:43:24 AM

10203868

**Palm Beach County Fleet Management Asset Maintenance History**  
**2018 INTERNATIONAL 7500 Sewer Cleaner/Vac Combo, Truck Mntd, 66,000 Gvwr**

**Work Order:** 1907039      **Meter:** 16245      **In Date:** 07/08/2019      **Closed:** 08/07/2019  
**Problem:** pm/E-stop switch missing

**Work Completed**

**Parts Issued**

**Quantity**

- Pm	15-40 Oil	30.00
- Aps Pm	Rotell Elc Antifeerze	2.00
- Def	Non-chlor Brake Clnr	3.00
- Replace Def filter	Drive Belt	1.00
- Service Ac	Napagold Oil Filter	1.00
- Replace U-joints on Pto shafts and relocate grease fittings	Napagold Air Filter	1.00
- To Total Truck 2xs	Napagold Air Filter	1.00
- Test run	Filter	1.00
- Shop Supplies	Washer Fluid Concentr	1.00
	Wiper Blade	2.00
	Used Fire X Refurbished	1.00
	Lucas Red-tacky Grs	3.00
	Emer Stop Switch	1.00
	Blue Df	2.00
	Def Filter	1.00
	Cabin Air Filter	1.00
	Napa Cabin Air Filter	1.00
	1350 U-joint Kit	6.00
	Shop Supplies	1.00
Hours: 26.00	Labor: 1,742.00	Parts: 1,096.43
Comm: 0.00		Total: 2,838.43

**Work Order:** 1909424      **Meter:** 17793      **In Date:** 09/13/2019      **Closed:** 09/13/2019  
**Problem:** 4 tires

**Work Completed**

- Tire Service vista - 4 tires  
Hours: 0.00      Comm: 1,751.52      Labor: 0.00      Parts: 0.00      Total: 1,751.52





4/10/2026  
9:43:24 AM

10203868

**Palm Beach County Fleet Management Asset Maintenance History**  
**2018 INTERNATIONAL 7500 Sewer Cleaner/Vac Combo, Truck Mntd, 66,000 Gvwr**

**Work Order:** 2001164

**Meter:** 21424

**In Date:** 02/03/2020 **Closed:** 03/24/2020

**Problem:** pm/list

**Work Completed**

- pm
- def
- test drive
- service vac pump add fluid
- check brakes
- replace hyd filter
- replace clear hoses on tanks
- replace indicator bulbs
- replace power steering hose
- Shop Supplies

**Parts Issued**

**Quantity**

15-40 Oil	30.00
Blue Df	3.00
Rotell Elc Antifeerze	1.00
Psf Qt	3.00
Napagold Oil Filter	1.00
Filter	1.00
Napagold Air Filter	1.00
Napagold Air Filter	1.00
Wiper Blade	2.00
Non-chlor Brake Clnr	2.00
Napa Cabin Air Filter	1.00
Cabin Air Filter	1.00
Qt/40hd	2.00
Hydraulic Filter	1.00
Permatex	1.00
New Pig	1.00
Clear Vinyl Tube	25.00
Hose	1.00
Round Indicator Light	2.00
Hose Made Mako	1.00
Aw68 Hydro Fluid Hydr	20.00
Non-chlor Brake Clnr	2.00
Shop Supplies	1.00
Freight Charge	1.00

Hours: 20.00

Comm: 0.00

Labor: 1,460.00

Parts: 1,108.15

Total: 2,568.15







4/10/2026  
9:43:24 AM

10203868

**Palm Beach County Fleet Management Asset Maintenance History**  
**2018 INTERNATIONAL 7500 Sewer Cleaner/Vac Combo, Truck Mntd, 66,000 Gvwr**

**Work Order:** 2009784  
**Problem:** PM

**Meter:** 25251

**In Date:** 09/29/2020 **Closed:** 11/20/2020

**Work Completed**

- Pm service
- r&r service hydro system
- add def
- Tire
- service hydraulic system
- Road test
- Drove to dealer 2xs
- Shop Supplies

**Parts Issued**

**Quantity**

Air Elbow	1.00
Big G Degreaser 1 Gal	1.00
15-40 Oil	30.00
Napagold Oil Filter	1.00
Napagold Air Filter	1.00
Napagold Air Filter	1.00
Filter	1.00
Wiper Blade	2.00
Used Fire X Refurbished	1.00
Rotell Elc Antifeerze	2.00
Cabin Air Filter	1.00
Napa Cabin Air Filter	1.00
Blue Df	1.00
42565r225 20ply	1.00
Hyd Filter	1.00
hyd filter high	1.00
hyd filter	1.00
hyd filter	1.00
Hose Made Mako	1.00
Shop Supplies	1.00
Tire Disposal Fee	1.00

Hours: 19.50

Comm: 0.00

Labor: 1,423.50

Parts: 2,185.20

Total: 3,608.70

**Work Order:** 2010260  
**Problem:** LF tire

**Meter:** 25251

**In Date:** 10/08/2020 **Closed:** 10/13/2020

**Work Completed**

- Tire Service He - Lf tire

Hours: 0.00

Comm: 104.96

Labor: 0.00

Parts: 0.00

Total: 104.96





4/10/2026  
9:43:24 AM

**10203868 Palm Beach County Fleet Management Asset Maintenance History**  
**2018 INTERNATIONAL 7500 Sewer Cleaner/Vac Combo, Truck Mntd, 66,000 Gvwr**

**Work Order:** 2109760      **Meter:** 30347      **In Date:** 09/09/2021      **Closed:** 09/28/2021  
**Problem:** PM/ wont start, check for draw, battery keeps dying

**Work Completed**

- jump start
- Pm service
- to croc
- Service hydraulic system
- Road test
- Add Def
- Service A/c system
- Charge batterys
- Shop Supplies

**Parts Issued**

**Quantity**

15-40 Oil	30.00
Non-chlor Brake Clnr	2.00
Napagold Oil Filter	1.00
Filter	1.00
Napagold Air Filter	1.00
Napagold Air Filter	1.00
Used Fire X Refurbished	1.00
Washer Fluid Concentr	1.00
Wiper Blade	2.00
Rotell Elc Antifeerze	2.00
Cabin Air Filter	1.00
Napa Cabin Air Filter	1.00
Blue Df	1.00
Hyd/fil	1.00
Shop Supplies	1.00

Hours: 17.00

Comm: 0.00

Labor: 1,241.00

Parts: 359.03

Total: 1,600.03

**Work Order:** 2111385      **Meter:** 30674      **In Date:** 10/22/2021      **Closed:** 11/08/2021  
**Problem:** Check engine light is on.

**Work Completed**

- Pull engine code Spn-4364, Aftertreatment Conversion Efficiency
- Road test
- Regen Exhaust system
- Add Def
- Shop Supplies

**Parts Issued**

**Quantity**

Blue Df	3.00
Shop Supplies	1.00

Hours: 4.00

Comm: 0.00

Labor: 292.00

Parts: 40.01

Total: 332.01

4/10/2026  
9:43:24 AM

10203868

**Palm Beach County Fleet Management Asset Maintenance History**  
**2018 INTERNATIONAL 7500 Sewer Cleaner/Vac Combo, Truck Mntd, 66,000 Gvwr**

**Work Order:** 2112955      **Meter:** 31609      **In Date:** 12/07/2021      **Closed:** 12/09/2021  
**Problem:** NEED D.E.F

**Work Completed**

- Add Def Fluid
- Shop Supplies

Hours: 1.00

Comm: 0.00

**Parts Issued**

Blue Def 2.5 Gallon	3.00
Shop Supplies	1.00

Labor: 73.00      Parts: 40.20      Total: 113.20

**Work Order:** 2113220      **Meter:** 31794      **In Date:** 12/15/2021      **Closed:** 04/11/2022  
**Problem:** driver side headlight needs to be replaced

**Work Completed**

- Operator states headlight out. Found Lf headlight out and housing broken. Order replacement housing. R&r bulb for use while housing on order
- Fender broken. Cut out old fender and grind off panel bonding material. Trim and fit new fender assy.
- Pm
- Pm Aps
- Add Def
- R&r Def filter
- Service A/c
- R&r Air drier
- Service Power steering system
- Replace broken reflectors
- Service cooling system
- Degas bottle deformed and leaking coolant at sensor assy. R&r degas bottle assy and coolant level sensor assy.
- Power steering leak from high pressure hoses. R&r High pressure hoses and return lines.
- To Mako
- Front drums and shoes heat cracked. R&r front drums and shoes.
- Rear shoes at or below min thickness and drums cracked. R&r both tandem axle brakes.
- Front tires wearing improperly. Inspect front end and found loose axle bearings. Retorque axle bearings and service front hubs.

**Parts Issued**

Halogen Sealed Beams	1.00
Headlight Assy	1.00
Panel	1.00
Acetone	1.00
Blade Kit	3.00
Hose Made Mako	1.00
Temp Sensor	1.00
Tank	1.00
3m Panel Bond	6.00
Mixing N0zzle	1.00
Dispensing Gun Kit	1.00
Filter Cover	1.00
Drum	4.00
brake shoe kit	4.00
Non-chlor Brake Clnr	4.00
Front Drum	2.00
Brake Shoes	2.00
13 Oz Aero Kroil	1.00
Steering Link	1.00
steering arm	1.00
steering box	1.00

4/10/2026  
9:43:24 AM

**10203868 Palm Beach County Fleet Management Asset Maintenance History  
2018 INTERNATIONAL 7500 Sewer Cleaner/Vac Combo, Truck Mntd, 66,000 Gvwr**

- Passenger side gearbox sector shaft has excessive play and fluid leaking from sector shaft seal. R&r gearbox, pitman arm, and drag link.
- Hydro leak from port plugs and fitting at main Dcv block. Repair leaks.
- Hydro pressure supply hose for secondary Dcv block leaking at crimp. R&r supply hose.
- Tank float gauge greaser line broken. R&r greaser line from top of tank to grease block
- Decant valve air lines broken. Repair air line
- Hydraulic accumulators severely corroded around nitrogen charge fitting. Unit to be repaired under water utilities contract with vendor.
- Test Run
- Unit covered in hydraulic oil. Wash down unit
- Operator states check engine light on. Connect scan tool and retrieve codes. Codes present for can bus communication failure and Nox conversion failures. Unit to go to dealer for repairs
- To International
- Shop Supplies

<b>Parts Issued</b>	<b>Quantity</b>
15-40 Oil	30.00
Napagold Oil Filter	1.00
Filter	1.00
Napagold Air Filter	1.00
Napagold Air Filter	1.00
Washer Fluid Concentr	1.00
Wiper Blade	2.00
Used Fire X Refurbished	1.00
Cabin Air Filter	1.00
Napa Cabin Air Filter	1.00
Stick-on Rd Reflector	2.00
Rotell Elc Antifeerze	7.00
New Pig	1.00
Big G Degreaser 1 Gal	1.00
Non-chlor Brake Clnr	13.00
Hyd/fil	1.00
Blue Df	2.00
Urea Def Filter	1.00
Ad Ip Dryer Cart	1.00
Psf Qt	4.00
Power Steering Filter	1.00
1qt Syngear Oil 75-90	4.00
Hub Cap	2.00
L0152-063 Gear Shield	1.00
Cable Tie	1.00
Hose Made Mako	1.00
Aw68 Hydro Fluid Hydr	4.00
Shop Supplies	1.00
Labor: 9,964.50	Parts: 8,376.81
Total: 18,341.31	

Hours: 136.50

Comm: 0.00

4/10/2026  
9:43:24 AM

10203868

**Palm Beach County Fleet Management Asset Maintenance History**  
**2018 INTERNATIONAL 7500 Sewer Cleaner/Vac Combo, Truck Mntd, 66,000 Gvwr**

---

**Work Order:** 2200819      **Meter:** 32445      **In Date:** 01/25/2022      **Closed:** 02/25/2022  
**Problem:** SCREWS FOR TANK BACK DOOR LOCK SHEARD OFF. NEED TO BE TAKEN OUT.

**Work Completed**

- Operator states rock jammed in lock assy and sheared lock bolts. Attempt to extract sheared lock bolts. Weld new bolt heads onto sheared bolts for extraction. Order new weldment. Tech157 cut and reweld new weldment and perform lock pin alignment.

- Rear tank door safety catch damaged and non functional. Remove safety catch and repair catch. Torch and straighten safety bar. Repair damaged safety bar retainer assy. Repaint safety bar and retainer assy.

- Front bumper damage, remove front tool box assembly and cut off front bumper corner panel, straighten bent bumper panel and reweld back to main bumper. Primer and paint, reinstall tool box

- Shop Supplies

**Parts Issued**

**Quantity**

Weldment	1.00
Supplies	1.00
Shop Supplies	1.00
Freight Charge	1.00
Freight Charge	1.00

Hours: 33.00

Comm: 0.00

Labor: 2,409.00

Parts: 669.88

Total: 3,078.88

---

**Work Order:** 2201588      **Meter:** 32445      **In Date:** 01/11/2022      **Closed:** 02/11/2022  
**Problem:** paint new fender off the truck

**Work Completed**

- paint new fender off the truck

Hours: 0.00

Comm: 542.40

Labor: 0.00

Parts: 0.00

Total: 542.40

---

**Work Order:** 2202186      **Meter:** 32445      **In Date:** 02/11/2022      **Closed:** 02/25/2022  
**Problem:** RF Tire

**Work Completed**

- Tire Service: He Problem: Rf Tire

Hours: 0.00

Comm: 689.30

Labor: 0.00

Parts: 0.00

Total: 689.30

---

**Work Order:** 2202187      **Meter:** 32445      **In Date:** 02/25/2022      **Closed:** 02/25/2022  
**Problem:** RF tire

**Work Completed**

- Tire Service: He Problem: Rf tire

Hours: 0.00

Comm: 179.11

Labor: 0.00

Parts: 0.00

Total: 179.11



4/10/2026  
9:43:24 AM

**10203868 Palm Beach County Fleet Management Asset Maintenance History**  
**2018 INTERNATIONAL 7500 Sewer Cleaner/Vac Combo, Truck Mntd, 66,000 Gvwr**

---

**Work Order:** 2209293      **Meter:** 35123      **In Date:** 09/06/2022      **Closed:** 09/12/2022  
**Problem:** Send for Detail. hose busted running hot

**Work Completed**

- R/r coolant hardline and replaced blown coolant line to oil cooler. Fill up system and bleed air. Cleared check engine light for overheat codes.
- Travel time to and from Hydraulic supply.
- Shop Supplies

**Parts Issued**

	<b>Quantity</b>
Rotell Elc Antifeerze	7.00
Heater Hose	1.00
Shop Supplies	1.00

Hours: 3.00      Comm: 0.00      Labor: 219.00      Parts: 103.12      Total: 322.12

---

**Work Order:** 2211188      **Meter:** 35759      **In Date:** 10/31/2022      **Closed:** 11/30/2022  
**Problem:** RSL Light is on

**Work Completed**

- Preventive Maint. Service
- check engine light on found coolant level sensor bad replaced sensor and cleared code
- added def
- replaced 3 rear tires under 4/32nds
- test drive
- pm aps
- Shop Supplies

**Parts Issued**

	<b>Quantity</b>
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
15w40 Bulk Tank Pahokee	30.00
Napagold Oil Filter	1.00
Filter	1.00
Blue Df	2.00
Temp Sensor	1.00
11r22.5 G661 Tire	3.00
Shop Supplies	1.00
Tire Disposal Fee	3.00

Hours: 17.50      Comm: 0.00      Labor: 1,277.50      Parts: 1,959.70      Total: 3,237.20

4/10/2026  
9:43:24 AM

10203868

**Palm Beach County Fleet Management Asset Maintenance History**  
**2018 INTERNATIONAL 7500 Sewer Cleaner/Vac Combo, Truck Mntd, 66,000 Gvwr**

**Work Order:** 2300372

**Meter:** 36152

**In Date:** 01/12/2023 **Closed:** 01/17/2023

**Problem:** Boom not working

**Work Completed**

**Parts Issued**

**Quantity**

- Boom not operating on 3 different function. Perform testing of Hyd electrical system found no output to Hyd solenoid causing function not to work. Check system Fuses, control switches, and powers and ground. Found loose ground wires on ground bus bar

Shop Supplies

1.00

- Found air leaking from compressor governor broken fitting and fan control valve also leaking. Replace both leaking fitting, No parts bill

- Pto light not working, Replace open Pto light bulb. Disassemble Pto control panel for bulb replacement, No parts bill

- Shop Supplies

Hours: 11.00

Comm: 0.00

Labor: 803.00

Parts: 2.65

Total: 805.65

4/10/2026  
9:43:24 AM

**10203868 Palm Beach County Fleet Management Asset Maintenance History**  
**2018 INTERNATIONAL 7500 Sewer Cleaner/Vac Combo, Truck Mntd, 66,000 Gvwr**

**Work Order:** 2303967      **Meter:** 38899      **In Date:** 04/21/2023      **Closed:** 07/10/2023

**Problem:** pressure hose front under chaise leaking/ PM

**Work Completed**

- Rodder pump to front reel hose blown through fitting. Replace High pressure water hose assy.
- Pm
- Pm Aps assy.
- Add Def
- R&r Def Filter
- Coolant level low. Pressure test cooling system and found coolant leaking from turbo hose. Repair leak and top off coolant.
- To Mako
- Service A/c system
- Reflectors missing. Remove old adhesive and prep area. Replace reflectors
- Hose reel extension cylinder leaking at shaft seal. R&r cylinder for rebuild. Top Off hydraulic oil.
- Wash hydro and grease from unit.
- Front tandem axle leaking. Inspection found worn u-joint and loose pinion input and output shaft yokes. Unit to dealer for repairs 2x.
- To International 4x
- Test Run 2x
- Shop Supplies

Hours: 32.50

Comm: 1,664.09

**Parts Issued**

**Quantity**

Hose Made Mako	1.00
Napagold Oil Filter	1.00
15-40 Oil	31.00
Napagold Air Filter	1.00
Napagold Air Filter	1.00
Used Fire X Refurbished	1.00
Wiper Blade	2.00
Non-chlor Brake Clnr	3.00
Hyd/fil	1.00
Blue Df	2.00
Urea Def Filter	1.00
Cabin Air Filter	1.00
Napa Cabin Air Filter	1.00
Filter	1.00
Stick-on Rd Reflector	1.00
D Ring Kit	1.00
O Ring Kit	1.00
Reseal Cylinder	1.00
Aw68 Hydro Fluid Hydr	20.00
Shop Supplies	1.00

Labor: 2,372.50

Parts: 2,610.96

Total: 6,647.55







4/10/2026  
9:43:24 AM

10203868

**Palm Beach County Fleet Management Asset Maintenance History**  
**2018 INTERNATIONAL 7500 Sewer Cleaner/Vac Combo, Truck Mntd, 66,000 Gvwr**

<b>Parts Issued</b>	<b>Quantity</b>
Coolant Level Sensor	1.00
Roller Bushing	4.00
Hose Made Mako	1.00
Aw68 Hydro Fluid Hydr	250.00
H13/9008 Led Light	1.00
G85w140p	2.00
Fan Clutch Repair Kit	1.00
Adh Screw Mt Base	1.00
Group 31 Stud Delco	3.00
Coolent Combustion Kit	1.00
Hose Made Mako	1.00
Oil Filter	1.00
Steering Gear Box	1.00
Tank	1.00
Pinion Seal	1.00
Nut-lock	1.00
Output Cage Asy	1.00
Washer	1.00
Shim Kit	1.00
Shop Supplies	1.00
Freight Charge	1.00
Freight Charge	1.00

Hours: 59.00

Comm: 0.00

Labor: 4,307.00

Parts: 7,689.95

Total: 11,996.95

**Work Order:** 2400608

**Meter:** 43832

**In Date:** 01/08/2024 **Closed:** 01/19/2024

**Problem:** overheating

**Work Completed**

- Tow From: 8100 Forest Hill Blvd, in lot west fuel island To: fleet vista He Shop

Hours: 0.00

Comm: 282.50

Labor: 0.00

Parts: 0.00

Total: 282.50



4/10/2026  
9:43:24 AM

**10203868 Palm Beach County Fleet Management Asset Maintenance History**  
**2018 INTERNATIONAL 7500 Sewer Cleaner/Vac Combo, Truck Mntd, 66,000 Gvwr**

---

**Work Order:** 2408874      **Meter:** 45468      **In Date:** 09/03/2024      **Closed:** 09/13/2024  
**Problem:** Tires: LFS; Flat. Replace Tire

**Work Completed**

- Tire Service: Croc Problem: Tires: Lfs; Flat. Replace Tire

Hours: 0.00      Comm: 762.96      Labor: 0.00      Parts: 0.00      Total: 762.96

---

**Work Order:** 2410463      **Meter:** 46326      **In Date:** 10/30/2024      **Closed:** 11/05/2024  
**Problem:** tank leak

**Work Completed**

- Weld up cracks on rear tank body. Clean and protect bare metal area after welding.

- Shop Supplies

**Parts Issued**      **Quantity**

Supplies      1.00

Shop Supplies      1.00

Hours: 4.00      Comm: 0.00      Labor: 292.00      Parts: 172.93      Total: 464.93

---

**Work Order:** 2410961      **Meter:** 46696      **In Date:** 11/15/2024      **Closed:** 11/20/2024  
**Problem:** steering fluid leak/coolant low

**Work Completed**

- leak - tighten clamps top off fluid ok for now

- low - coolant res. cap loose top off ok for now

- Shop Supplies

**Parts Issued**      **Quantity**

Psf Qt      1.00

Rotell Elc Antifeerze      1.00

Shop Supplies      1.00

Hours: 1.50      Comm: 0.00      Labor: 109.50      Parts: 20.39      Total: 129.89

---

**Work Order:** 2412059      **Meter:** 47635      **In Date:** 12/23/2024      **Closed:** 06/25/2025  
**Problem:** PM / overheating

**Work Completed**

- Pm

- Repair by Rechten/check overheating

- Pm Aps

- Add Def

- R&r Def filter

- Service a/c system and foam. Cowl cover broken. Replace cowl cover.

- Service air drier assy. R&r driveshaft and air drier assy for service access.

- Service cooling system

**Parts Issued**      **Quantity**

Parts And Service Rechten      1.00

Alingment And Parts On Site      1.00

Non-chlor Brake Clnr      12.00

Washer Fluid Concentr      2.00

Wiper Blade      2.00

Filter      1.00

Napagold Oil Filter      1.00

Mobil Delvac 2.5 Gal      3.00

4/10/2026  
9:43:24 AM

10203868

**Palm Beach County Fleet Management Asset Maintenance History**  
**2018 INTERNATIONAL 7500 Sewer Cleaner/Vac Combo, Truck Mntd, 66,000 Gvwr**

- Service transmission
- Service transfer case
- Service blower assy
- Power divider oil filter leaking. R&r filter and internal pump screens. Service power divider and both rear differentials.
- Pto shaft yoke sloppy. R&r Pto shaft assy.
- Hose reel skid plate, swivel, hose pivot guide, and water supply hose damaged. R&r plate, swivel, and hose. Repair and straighten pivot guide assy.
- Service P/s system
- Foot valve sloppy and leaking air. R&r foot valve assy.
- Aps Emergency stop switch broken. R&r emergency stop switch assy.
- on-site alignment / kingpins
- Operator states Rf hub cap leaking. R&r hub cap and refill.
- To Mako with a very long wait.
- Reel locks sticking. Locking pin sleeves corroded. Clean out debris and corrosion. Lubricate sleeves.
- Test Run
- Reverse lights inop. R&r lights.
- Shop Supplies

<b>Parts Issued</b>	<b>Quantity</b>
Napagold Air Filter	1.00
Napagold Air Filter	1.00
Used Fire X Refurbished	1.00
Napagold Oil Filter	1.00
Psf Qt	3.00
Power Steering Filter	1.00
Foot Valve	1.00
1cart Palladium 2 Grs	3.00
Hyd/fil	1.00
Blue Df	2.00
Def Filter	1.00
Evap Odor Elinitator	1.00
Cabin Air Filter	1.00
Napa Cabin Air Filter	1.00
Ad Ip Dryer Cart	1.00
Rotell Elc Antifeerze	8.00
Napa Trans Filter	1.00
Transynd 668 3x1g	6.00
Transynd 668 3x1g	6.00
Agma Ep5 Iso 220 Ge	1.00
Tran Flu Qt Dexron3i	12.00
Transynd 668 3x1g	-6.00
Screen Cowl Vent	1.00
Lucas 85-140 Gear Oil	1.00
Hub Cap	1.00
New Pig	1.00
Hose Made Mako	1.00
2507061c1 Gasket P-st	1.00
Oil Filter Screen	2.00
G85w140p	3.00

4/10/2026  
9:43:24 AM

10203868

**Palm Beach County Fleet Management Asset Maintenance History**  
**2018 INTERNATIONAL 7500 Sewer Cleaner/Vac Combo, Truck Mntd, 66,000 Gvwr**

<b>Parts Issued</b>	<b>Quantity</b>
Napa Gold Oil Filter	1.00
Cable Tie	1.00
Bottom Cover	1.00
End Cover	1.00
Plate-hose Support	1.00
Reel Bearing	1.00
Cable Tie	1.00
Push Button	1.00
Parts And Service	1.00
Led Back-up Lamp Sys	2.00
Shop Supplies	1.00
Freight Charge	1.00
Freight Charge	1.00

Hours: 52.00

Comm: 0.00

Labor: 3,796.00

Parts: 9,640.51

Total: 13,436.51

---

**Work Order:** 2412089

**Meter:** 47561

**In Date:** 12/20/2024 **Closed:** 12/26/2024

**Problem:** Tow- overheating

**Work Completed**

- Tow From: state rd 7 and 87 place To: 2601 Vista Pkwy, West Palm Beach  
33411

Hours: 0.00

Comm: 270.00

Labor: 0.00

Parts: 0.00

Total: 270.00

---

**Work Order:** 2503541

**Meter:** 47561

**In Date:** 04/15/2025 **Closed:** 04/17/2025

**Problem:** Tow-please tow to dealer for overheating issues

**Work Completed**

- Tow From: Fleet Vista He shop To: Rectien International, Riveria Beach.

Hours: 0.00

Comm: 270.00

Labor: 0.00

Parts: 0.00

Total: 270.00

4/10/2026  
9:43:24 AM

10203868

**Palm Beach County Fleet Management Asset Maintenance History**  
**2018 INTERNATIONAL 7500 Sewer Cleaner/Vac Combo, Truck Mntd, 66,000 Gvwr**

---

**Work Order:** 2505920      **Meter:** 47968      **In Date:** 06/25/2025      **Closed:** 06/30/2025  
**Problem:** pto

**Work Completed**

- Operator states Pto will not engage. Confirm complaint. Check fluid level, inhibit switches and E-stops. Found Damaged wire harness to Pto solenoid.
- Damaged wire at Pto harness. Repair wiring at Pto wiring harness. Check Pto and accessory operation.
- Service Call to Croc and back.
- Test run.
- Shop Supplies

**Parts Issued**

**Quantity**

Electrical Tape	1.00
Cable Tie	1.00
Shop Supplies	1.00

Hours: 4.50      Comm: 0.00      Labor: 328.50      Parts: 18.15      Total: 346.65

---

**Work Order:** 2601158      **Meter:** 51501      **In Date:** 02/04/2026      **Closed:** 02/10/2026  
**Problem:** Transition Prep Charge

**Work Completed**

- Transition Prep Charge

Hours: 2.00      Comm: 0.00      Labor: 146.00      Parts: 0.00      Total: 146.00

**Total Hours: 597.50      Total Labor: 42,909.00      Total Comm: 23,373.71      Total Parts: 49,596.74**