



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V558**

In Date: 11/14/2005  
Close Date: 11/18/2005

Meter Reading:

**Problem?**

a/c blower in cab not working R45B

Parts	Quantity
NO PARTS USED	

Task performed:

**Workorder: V723**

In Date: 11/25/2005  
Close Date: 11/30/2005

Meter Reading:

**Problem?**

PAT, COMPT, A/C INOP, R-45

Parts	Quantity
NO PARTS USED	

Task performed:

**Workorder: V566**

In Date: 11/14/2005  
Close Date: 12/05/2005

Meter Reading:

**Problem?**

A/C FAN 10-7 R45

Parts	Quantity
ABPN8330101701-0604 3924 BLOWER A/C BOA 852	2

Task performed:



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V764**

In Date: 12/01/2005  
Close Date: 12/15/2005

Meter Reading:

**Problem?**

REAR A/C INOP, R-45

Parts

Quantity

Task performed:

NO PARTS USED

**Workorder: V887**

In Date: 12/12/2005  
Close Date: 12/15/2005

Meter Reading:

**Problem?**

REAR A/C 10-7 R45

Parts

Quantity

Task performed:

NO PARTS USED

**Workorder: V909**

In Date: 12/13/2005  
Close Date: 12/30/2005

Meter Reading:

**Problem?**

REAR A/C FAN NOT WORKING R45

Parts

Quantity

Task performed:

UNT1400BLOWER MTR. + SQU IRREL CAGE ASSY.

1



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V869**

In Date: 12/09/2005  
Close Date: 01/04/2006

Meter Reading:

**Problem?**

L/SIDE COMPT DOOR HINGE BROKEN, WILL NOT DRAFT FRONT  
SUCTION RE-45

Parts ----- Quantity -----

**Task performed:**

680-620-01-16DOOR HINGE BRACE	1
6807200537HINGE	1

**Workorder: V1366**

In Date: 01/31/2006  
Close Date: 02/01/2006

Meter Reading:

**Problem?**

FRONT AND REAR A/C INOP, R-45B

Parts ----- Quantity -----

**Task performed:**

ABPN8332229011-3050 SWITCH BLOWER	1
-----------------------------------	---

**Workorder: V1724**

In Date: 02/17/2006  
Close Date: 03/03/2006

Meter Reading:

**Problem?**

NEED 4 REAR TIRES, R-45

Parts ----- Quantity -----

**Task performed:**

NO PARTS USED	
---------------	--

Vendor? TCI



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

\* **ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V1695**

In Date: 03/01/2006

Meter Reading:

Close Date: 03/27/2006

**Problem?**

NOISE FROM ENGINE, R-45

Parts

Quantity

Task performed:

NO PARTS USED

**Workorder: V1986**

In Date: 03/28/2006

Meter Reading:

Close Date: 04/03/2006

**Problem?**

FRONT A/C INOP, R-45B

Parts

Quantity

Task performed:

NO PARTS USED



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

\* **ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V1890**

In Date: 03/17/2006

Close Date: 04/06/2006

Meter Reading:

**Problem?**

**B INSPECTION R45**

Parts

Quantity



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

\* **ADVANCED LIFE SUPPORT VEHICLE**

**Task performed:**

See B Inspection pre-printed form

000090155133634 FUEL FILTER WIX MERCEDES	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES	1
0127110042BELT MERCEDES MOTORS	1
107796DRYER KIT AD9 -NEW	1
107800VALVE CHECK AD9	1
1156BULB	1
1157BULB	1
194BULB	4
203FFBEARING PULLEY	1
20S-500EXHAUST CLAMP 33225 5 IN	1
22-49905-000CABLE HEATER	1
22512960001498 SWITCH BINA	1
3744BRAKE DRUM REAR	2
52-24WIPER BLADES ANCO 24	2
6805450828PLUG A/C BLR	1
6806970098SEAL DOOR	1
716907-0610A DRYER	1
78R536078R5360M 2PK FILTER AIR COND	1
800405PURGE VALVE KIT	1
91513AMBER LENS	2
9425BELT MERCEDES RESCUE 12.5X1075 OE	1
98003RREFLECTOR RED 40132 GROTE	1
A1834388002MOLD L/H	2
A1834388003MOLD R/H	2
A22451940011499 SWITCH A/C HIGH PRESSURE NC	1
ACX-8453LUG CAPS WHEELED COACH # CH2732	5
CA8193AIR FILTER 46744 WIX	1
FG87904MFG3937557S FILTER P/S NEW STYLE	1
FGQ79699GASKET-P/S FILTER NEW STYLE	1
HP-31DBATTERY 950CCA HP-31D	4



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

**\* ADVANCED LIFE SUPPORT VEHICLE**

KSMA3124710QKSMA3124710QP REAR BRAKE SHC	2
LTC1020606LATCH	1
LTC5993SSM1-63-8 LATCH STAINLESS	1
R90PFILTER FUEL 33231	1
UNT7744USE PINK A/C FILTER MEDIC MASTER	1
VML-T1413T3248 SIGHT GLASS	1

**Workorder: V063**

In Date: 10/28/2005      Meter Reading:  
Close Date: 05/11/2006

**Problem?**

A/C leaking at comp. R45

Parts ----- Quantity -----

Task performed:

NO PARTS USED

**Workorder: V1834**

In Date: 03/13/2006      Meter Reading:  
Close Date: 05/11/2006

**Problem?**

COMPT, HAS BROKEN LATCH IN BACK OF RESCUE R-45B

Parts ----- Quantity -----

Task performed:

NO PARTS USED



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V2664**

In Date: 05/17/2006  
Close Date: 05/22/2006

Meter Reading:

**Problem?**

-Driver's door outside latch handle is loose. -Rain leak in cab coming from lights over front seats.

Parts ----- Quantity -----

Task performed:

NO PARTS USED

**Workorder: V2866**

In Date: 06/05/2006  
Close Date: 06/09/2006

Meter Reading:

**Problem?**

front a/c blows warm R45b

Parts ----- Quantity -----

Task performed:

NO PARTS USED

**Workorder: V2929**

In Date: 06/10/2006  
Close Date: 06/13/2006

Meter Reading:

**Problem?**

Pull-handle for bottom drawer in patient compartment broke off. Handle is in Lt. office if needed.

Parts ----- Quantity -----

Task performed:

LTC5993SSM1-63-8 LATCH STAINLESS 2





4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

\* **ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V3032**

In Date: 06/18/2006  
Close Date: 06/16/2006

Meter Reading:

**Problem?**

right front siren speaker not working on R45 4-door

Parts

Quantity

Task performed:

NO PARTS USED

**Workorder: V3006**

In Date: 06/15/2006  
Close Date: 06/22/2006

Meter Reading:

**Problem?**

TOW R-45 FROM STA-45 TO DETROIT DIESEL IN FORT PIERCE  
(SISTERS TOWING)

Parts

Quantity

Task performed:

NO PARTS USED

Vendor? SISTERS TOWING

**Workorder: V3528**

In Date: 07/19/2006  
Close Date: 07/20/2006

Meter Reading:

**Problem?**

right rear scene light stays on when truck is running. E45

Parts

Quantity

Task performed:

NO PARTS USED



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V3629**

In Date: 07/25/2006  
Close Date: 07/31/2006

Meter Reading:

**Problem?**

when the two right side doors of the front cab are open and the truck is in drive no alarm sounds r45

Parts \_\_\_\_\_ Quantity \_\_\_\_\_

Task performed:

NO PARTS USED

**Workorder: V3697**

In Date: 07/31/2006  
Close Date: 08/02/2006

Meter Reading:

**Problem?**

tow to shop- unit has electrical burning smell- R45 (outside agency-sisters towing)

Parts \_\_\_\_\_ Quantity \_\_\_\_\_

Task performed:

NO PARTS USED

Vendor? SISTERS TOWING

**Workorder: V3872**

In Date: 08/10/2006  
Close Date: 08/17/2006

Meter Reading:

**Problem?**

TOW TO SHOP FROM STA 43 SISTERS TOWING

Parts \_\_\_\_\_ Quantity \_\_\_\_\_

Task performed:

NO PARTS USED

Vendor? SISTERS TOWING



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

\* **ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V3768**

In Date: 08/03/2006

Meter Reading:

Close Date: 08/18/2006

**Problem?**

REPAIR SEATS AT CENTRAL AUTO TRIM R45

Parts

Quantity

Task performed:

NO PARTS USED

Vendor? CENT0002



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V3704**

In Date: 07/31/2006

Meter Reading: 44,296.00

Close Date: 08/22/2006

**Problem?**

**B INSPECTION AND REPAIRS AS NEEDED R45B**

**Task performed:**

UNIT PULLED FROM SERVICE FOR CHARGING SYSTEM PROBLEM

Parts

Quantity

000090155133634 FUEL FILTER WIX MERCEDES	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES	1
1836267000VISOR RETRN	1
23-11345-714INSTRUMENT CLUSTER SCREWS 1 1/	1
231134571223-11345-712 DASH SCREW	1
4867JB320 UPGRADE ALTERNATOR	1
6805400182BEZEL DASH	1
6806970098SEAL DOOR	1
91823SWITCH SWT5499 MED MASTER	2
CLR9185109186-1500-10 MARKER LT. RED LED	1
DOOR5LEXAN 9 X 38 1/2 IN	1
HA49102C2-32-15 LATCH NON LOCKING	1
HND5941USE HAN-1L METAL LATCH INTERIOR LO	2
LTC5992C5-12-15-3 LATCH LEVER NON-LOCKING	1
R90PFILTER FUEL 33231	1



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

\* **ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V4181**

In Date: 08/31/2006  
Close Date: 09/06/2006

Meter Reading:

**Problem?**

handle on drawer is broken, will not open R45

**Task performed:**

Parts	Quantity
LTC5993SSM1-63-8 LATCH STAINLESS	1

**Workorder: V4221**

In Date: 09/02/2006  
Close Date: 09/11/2006

Meter Reading:

**Problem?**

"Heater Intake Light" is activated on the driver's console. R45B

**Task performed:**

Parts	Quantity
NO PARTS USED	

**Workorder: V5154**

In Date: 10/30/2006  
Close Date: 11/03/2006

Meter Reading: 5,995.00

**Problem?**

R45 4-door dome lighting in rear out

**Task performed:**

REPLACE 4 PT COMPARTMENT LIGHTS

Parts	Quantity
322502BULB PATIENT GH22	8



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V5206**

In Date: 11/01/2006  
Close Date: 11/07/2006

Meter Reading: 47,506.00

**Problem?**

Water can extinguisher on R45 leaks while under pressure, near the valve.

Parts \_\_\_\_\_ Quantity \_\_\_\_\_

**Task performed:**

1. water can on r45 leaks when under pressure, contacted bc , he will handle

NO PARTS USED

**Workorder: V5728**

In Date: 12/07/2006  
Close Date: 12/12/2006

Meter Reading: 6,210.00

**Problem?**

rear right valve stem bracket broken and scratching tire rim r45

Parts \_\_\_\_\_ Quantity \_\_\_\_\_

**Task performed:**

AMH-1AMH-1 VALVE EXTENSION 1

**Workorder: V5922**

In Date: 12/22/2006  
Close Date: 01/03/2007

Meter Reading: 49,863.00

**Problem?**

tires bald on r45a, need replacement asap REPLACE TIRES AT STATION 45 CALLAGHAN ENT.

Parts \_\_\_\_\_ Quantity \_\_\_\_\_

**Task performed:**

1. Replaced tires at Sta45 Callaghan Ent.

NO PARTS USED

**Vendor?** CALLAGHAN ENT



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

\* **ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V6502**

**In Date:** 01/27/2007

**Meter Reading:** 6,530.30

**Close Date:** 02/02/2007

**Problem?**

patient compartment lights out need replacement.. R-45

Parts

Quantity

**Task performed:**

1. Replaced 3 patient lights in rear

NO PARTS USED



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## 10154110

### \* ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V6760**

**In Date:** 02/14/2007

**Meter Reading:** 52,183.00

**Close Date:** 02/27/2007

**Problem?**

B Inspection and related repairs (R45B)

**Task performed:**

B-inspection 1.Replace oil/filter, air/fuel; svc rear end; greased chassis  
2.Retorque all U-bolts; tighten loose front spring hanger bolts 3.Replace  
belts, A/C tensioner pulley bearing 4. R/R air dryer 5. Remove battery  
cables; clean/svc batteries; tighten connections 6. Replc pat compt door  
handle assy; tighten door latches 7. Replc all door trims/moulding 8.  
inspect/adj front/rear brakes; replc missing lug covers

**Parts**

**Quantity**

000090155133634 FUEL FILTER WIX MERCEDES	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES	1
0127110042BELT MERCEDES MOTORS	1
107796DRYER KIT AD9 -NEW	1
107800VALVE CHECK AD9	1
203FFBEARING PULLEY	1
52-24WIPER BLADES ANCO 24	2
680-10LAMERICAN FLAG W UV CLEAR LEFT	1
680-10RAMERICAN FLAG W UV CLEAR RIGHT	1
6806970098SEAL DOOR	2
6808300074VENT A/C LH	1
78R536078R5360M 2PK FILTER AIR COND	1
800405PURGE VALVE KIT	1
91513AMBER LENS	2
9425BELT MERCEDES RESCUE 12.5X1075 OE	1
98003RREFLECTOR RED 40132 GROTE	3
A0631087000CABLE BATT. POS.	1
A0631088000CABLE BATT. NEG.	1
A1834388002MOLD L/H	2
A1834388003MOLD R/H	2
ACX-84534LUG NUT COVER PK10	11
CA8193AIR FILTER 46744 WIX	1
R90PFILTER FUEL 33231	1
UNT7744USE PINK A/C FILTER MEDIC MASTER	1





4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V7099**

In Date: 03/07/2007  
Close Date: 03/14/2007

Meter Reading: 532,875.00

**Problem?**

RE45 k-12 saw is spewing fuel out cap while running also leaking in compartment.

**Task performed:**  
Repaired fuel cap

Parts ----- Quantity

NO PARTS USED

**Workorder: V7364**

In Date: 03/25/2007  
Close Date: 04/03/2007

Meter Reading: 54,206.00

**Problem?**

A/C in cab blows warm. R45

**Task performed:**  
1. Ran a/c system and checked temp. ok 2. Adjusted left side air bag 3. Adjusted side door entry linkage

Parts ----- Quantity

NO PARTS USED

**Workorder: V7442**

In Date: 03/30/2007  
Close Date: 04/06/2007

Meter Reading: 6,904.00

**Problem?**

AC not working on R45 alpha, also need to dry vacuum test E45

**Task performed:**  
Recharged system and tested

Parts ----- Quantity

NO PARTS USED



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V7715**

In Date: 04/14/2007  
Close Date: 04/25/2007

Meter Reading: 6,994.00

**Problem?**

A/C in front cab not working. R45

Parts ----- Quantity -----

**Task performed:**

Recharged A/C Repaired & adjusted heater cable

NO PARTS USED

**Workorder: V7977**

In Date: 04/28/2007  
Close Date: 05/08/2007

Meter Reading: 55,568.00

**Problem?**

headlight out on r45b. none in station

Parts ----- Quantity -----

**Task performed:**

Dropped off headlights

NO PARTS USED

**Workorder: V8562**

In Date: 06/04/2007  
Close Date: 06/14/2007

Meter Reading: 57,141.00

**Problem?**

REAR A/C 10-7 R45

Parts ----- Quantity -----

**Task performed:**

1. Cleaned condenser fans and checked charge, checked temp and tested OK

NO PARTS USED



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V9057**

In Date: 06/28/2007  
Close Date: 07/02/2007

Meter Reading: 740.10

**Problem?**

fault indicator on node 1 pin B on command console r45

Parts

Quantity

**Task performed:**

Chkd problem w/fault code; Fnd hdlight out; replc from stock at station

NO PARTS USED

**Workorder: V9081**

In Date: 07/01/2007  
Close Date: 07/06/2007

Meter Reading: 7,414.00

**Problem?**

Need front left tire, tread is low and wore out on the outside. R-45

Parts

Quantity

**Task performed:**

1. Checked tires need two front

NO PARTS USED

**Workorder: V9363**

In Date: 07/17/2007  
Close Date: 07/18/2007

Meter Reading: 58,584.00

**Problem?**

REAR A/C 10-7 R45

Parts

Quantity

**Task performed:**

1. CLEANED CONDENSER FAN AND RECHARGE SYSTEM AND REPAIRED LEAK.

NO PARTS USED



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

\* **ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V9106**

In Date: 07/02/2007

Meter Reading: 58,316.00

Close Date: 07/25/2007

**Problem?**

REPLACE TIRES AT STA 45 CALLAGHAN ENT R45

Parts

Quantity

**Task performed:**

Replace tires at Stn45 - Callaghan

NO PARTS USED

**Vendor?** CALLAGHAN



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## 10154110

### \* ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V10034**

**In Date:** 08/21/2007

**Meter Reading:** 60,246.00

**Close Date:** 09/04/2007

**Problem?**

b inspection and repairs as needed r45 replace front bumper repair a/c condenser mount

**Task performed:**

B-Inspection/road test 2. Condenser mount(sides) broken 3. Svc transmission 4. Rear Brakes Svc 5. Door moldings broken 6. On-call-late call out; E. Ehrke authorized 10:00a.m. start; moving equipment to new shop; swapout of on-call truck clean unit 7. Door panels loose; locks damage & screws missing; mk necessary repairs 8. Front A/C line leaking; research part due to Mako having fitting made 9. Prep equipment & supply for move to new shop 10. Stretcher safety hook bar 11. Front/rear A/C filter 12.Oil fill cap leaking; rem cap/install new 13. Cabinet strut inop; rem/install new 14. L-4 comp vent damaged; rem/install new 15 Cab R-F door lock bent; adj/reinstall 16. Adj pat comp cabinet door locks 17. Low btry voltage; chk btry fluid & top off fluid; cln all connections; btry volt came up to 14.0V 18. ABS light-chk for code; fnd air cap on L&R front sensors; cln pickup sensor on wheel & reinsert 19. A/C bearing-scheduled replacement; rem/install new 20. Setting equipment up in new shop 21. A/C UV bulb blown; rem/install new 22. Pat comp Li/Lo lights inop; replc blown bulb to correct electrical short to light bulb assy 23. Defroster inop; fnd hose disconnected; reconnect 24. Water pump deferred; L-2 door out, weld crack dererred by E. Ehrke 25. Clean up work area

**Parts**

**Quantity**

000090155133634 FUEL FILTER WIX MERCEDES	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES	1
05-17223-002RAD CAP 20 LB	1
090-0278STRECHER BAR NEW	1
203FFBEARING PULLEY	1
29526898 29548988 TRANS FILTER ALLISON	1
322502BULB PATIENT GH22	2
52-24WIPER BLADES ANCO 24	2
78R536078R5360M 2PK FILTER AIR COND	1
A1834388002MOLD L/H	2
A1834388003MOLD R/H	1
ACX-84534LUG NUT COVER PK10	1
DDE-0000100285OIL CAP M2	1
HLD374211 IN HOLD-OPEN 30LB	1
HLD3999GSS1715UV 30LB STRUT GAS	2
HND5941USE HAN-1L METAL LATCH INTERIOR LOC	2
KSMA3124710QKSMA3124710QP REAR BRAKE SHC	2
R90PFILTER FUEL 33231	1
UNT7744USE PINK A/C FILTER MEDIC MASTER	1
UVBULBAPS253PLS11W/TUV BULB A/C RESCUES	1



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

\* **ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V10049**

In Date: 08/22/2007  
Close Date: 09/11/2007

Meter Reading: 60,246.00

**Problem?**

REPACE TIRES AT SHOP CALLAGHAN R45

Parts ----- Quantity -----

**Task performed:**

Replace tire at shop - Callaghan

NO PARTS USED

Vendor? CALLAGHAN

**Workorder: V10428**

In Date: 09/13/2007  
Close Date: 09/27/2007

Meter Reading: 7,713.50

**Problem?**

The white light on the L in the rear that indicates the rear door is open is out. r45

Parts ----- Quantity -----

**Task performed:**

1. Replc bulb in rear light bar 2. Adj air horns 3. Adj rear door linkage that was hard to open 4. Rep stretcher mount that was hard to release

H6054USE CV TYPE SEALED BEAM 2

**Workorder: V10627**

In Date: 09/24/2007  
Close Date: 09/27/2007

Meter Reading: 61,152.00

**Problem?**

ON CALL R45 SIREN 10-7

Parts ----- Quantity -----

**Task performed:**

1. TRAVEL TO STA 45, DIAGNOSE NO SIREN, FOUND BAD AMPLIFEF NO PART ON TRUCK. TRAVE TO SHOP FOR PARTS, TRAVEL FROM SHOP TO STA 45. INSTALL AMPLIFIER AND TEST O.K. 2. BLOW OUT A/C DRAINS ON E45. TRAVEL HOME.

NO PARTS USED



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V8086**

In Date: 05/03/2007  
Close Date: 10/15/2007

Meter Reading: 55,706.00

**Problem?**

REPLACE 4 REAR TIRES (CALLAGHAN)

Parts ----- Quantity -----

Task performed:

NO PARTS USED

Vendor? CALLAGHAN

**Workorder: V11018**

In Date: 10/14/2007  
Close Date: 10/23/2007

Meter Reading: 62,007.00

**Problem?**

left rear scene light is out. R-45

Parts ----- Quantity -----

Task performed:

- 1. repaired broken wire for rear scene light

NO PARTS USED



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

\* **ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V11233**

**In Date:** 10/24/2007

**Meter Reading:** 62,172.00

**Close Date:** 11/08/2007

**Problem?**

b inspection and repairs as needed r45

Parts

Quantity





4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## 10154110

### \* ADVANCED LIFE SUPPORT VEHICLE

#### Task performed:

B-Inspection 10/14/07 4.0 hrs 10/26/07 2.0 hrs Total 6.0 hrs 2. Svc Trans  
 3. Svc air dryer 4. Replc exh flex pipe at muffler 5. went to Red wing store  
 to get new boots 6. Replc both T/S side lenses (cracked) 7. Replc both  
 R-side door latches 8. Replc R-cab A/C filter 9. Replc pat compt A/C filter  
 10. Replc 110 A/C outlet cover (cracked) 11. Replc wiper blades 12. Rem  
 seat to be sent out for rep; reinstalled seat after repair 10/29/07 .5 hrs  
 11/1/07 .5 hrs Total 1.0 hrs 13. Replace water pump 10/30/07 2.0 hrs  
 11/1/07 3.5 hrs Total 5.5 hrs 14. Replc turbo clamp 10/30/07 .5 hrs  
 11/1/07 .5 hrs Total 1.0 hr 15. Replc eng air filter 16 Paint fuel cap 17.  
 Rep pat compt latch (bent) 18. Replc (2) door weather strips 19. Svc P/S  
 20. Replc btrys 21. Swapped out of on-call truck; restocked parts from  
 prev night on-call; cln/fuled 22. Replc no-skid on all cab step surfaces 23.  
 Chnged out coolant drum in oil room 24. Rep L2 compt skin seperatine  
 from door frame; drilled out door/frame & bolted door skin to frame 25.  
 Straighten dent/bend in frnt bumper; tied truck to truck to bldg w/snatch  
 cord & used truck to pull 26. Clnd work area 27. Replc pat compt side  
 entry door inner ltch bezel 28. Replc broken fuse panel cover 29.  
 Troubleshoot electrical problem with intake heater dash light; finaly  
 dissabled sys at cab ECU in dash

000090155133634 FUEL FILTER WIX MERCEDES	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES	1
0127110042BELT MERCEDES MOTORS	1
091-3YWCOVER KUSSMAUL AUTO EJECT	1
107796DRYER KIT AD9 -NEW	1
107800VALVE CHECK AD9	1
18-29935-001RH DOOR LATCH NEW	1
18-45484-000LATCH L/H	1
20A-400CLAMP 4" 33969	2
29526898 29548988 TRANS FILTER ALLISON	1
52-24WIPER BLADES ANCO 24	1
6806870807COVER FUSE PANEL	1
6806970098SEAL DOOR	1
78R536078R5360M 2PK FILTER AIR COND	1
800405PURGE VALVE KIT	1
9062010080GASKET M2 WATER PUMP	1
91513AMBER LENS	2
9425BELT MERCEDES RESCUE 12.5X1075 OE	1
AEVDOOR LOCK BEZEL	1
AMH-1AMH-1 VALVE EXTENSION	1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER B/	6
CA8193AIR FILTER 46744 WIX	1
DDE-0052035975A0052032675 THERMOSTAT ELEMI	1
DDE-9062030180GASKET SOCKET TO HEAD M2	1
DDE/0209971148A0249972848 SEAL RING	2
DDE/R9062006201RA906200620 WATER PUMP REM	1
FG87904MFG3937557S FILTER P/S NEW STYLE	1
FGQ79699GASKET-P/S FILTER NEW STYLE	1
FREIGHTSHIPPING CHARGES	1
HP-31DBATTERY 950CCA HP-31D	6



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

**\* ADVANCED LIFE SUPPORT VEHICLE**

R90PFILTER FUEL 33231	1
UNT7744USE PINK A/C FILTER MEDIC MASTER	1

**Workorder: V11247**

In Date: 10/25/2007      Meter Reading: 62,172.00

Close Date: 11/08/2007

**Problem?**

install frame rail I sert per campain r45

Parts	Quantity
-------	----------

**Task performed:**

1. install frame rail I sert per campain

25-SF350-002L-SERT REINFORCEMENT	1
----------------------------------	---

**Workorder: V11310**

In Date: 10/29/2007      Meter Reading: 62,172.00

Close Date: 11/13/2007

**Problem?**

seat repair central auto trim

Parts	Quantity
-------	----------

**Task performed:**

seat repair central auto trim

NO PARTS USED	
---------------	--

**Vendor?** CENTRAL AUTO TRIM CO



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V11847**

In Date: 11/30/2007  
Close Date: 12/06/2007

Meter Reading: 8,143.00

**Problem?**

drivers front door is sticking and it takes a few pulls to get it open R45

Parts ----- Quantity -----

**Task performed:**

- 1. Adjusted drivers door latch that was hard to open.

NO PARTS USED

**Workorder: V11925**

In Date: 12/04/2007  
Close Date: 12/19/2007

Meter Reading: 8,148.70

**Problem?**

stretcher antler holder in rescue45 4dr broken

Parts ----- Quantity -----

**Task performed:**

- 1. Removed and replaced front bracket for stretcher.

NO PARTS USED

**Workorder: V12103**

In Date: 12/17/2007  
Close Date: 12/21/2007

Meter Reading: 64,676.00

**Problem?**

LIGHT ON LIGHTBAR OUT ON R-45B

Parts ----- Quantity -----

**Task performed:**

- 1. Replaced rotator in light bar.

01-0416333-00LIGHT ROTATOR	1
H50SN12BULB	2



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V12457**

In Date: 01/09/2008  
Close Date: 01/25/2008

Meter Reading: 65,507.00

**Problem?**

wont start r45a

**Task performed:**

1. Side entre door handle Inop. replaced side entre door handle. 2. Starter, replaced starter and started solenoid. 3. Rear draw slides, replaced rear sliders. 4. O2 leak, checked for leaks found bottle leaking change out air bottle.

Parts	Quantity
190114036842 29MT 9 TOOTH STARTER	1
AEVDOOR LOCK BEZEL	1
HND5941USE HAN-1L METAL LATCH INTERIOR LO	1
HND5948TM22676-02 HANDLE DOOR ENTRY	1
SLD5366HT4932-16 DRAWER SLIDE 16	4

**Workorder: V3696**

In Date: 07/31/2006  
Close Date: 01/31/2008

Meter Reading:

**Problem?**

ON CALL CHARGING SYSTEM R45

**Task performed:**

Parts	Quantity
NO PARTS USED	

**Workorder: V4995**

In Date: 10/20/2006  
Close Date: 02/07/2008

Meter Reading: 2,212.00

**Problem?**

rescue 45b internal O2 gauge is not working.

**Task performed:**

Parts	Quantity
AS75600MONI-A01 O2 MINDER KIT	1
M54-13SPM5413 NIPPLE	1



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V13062**

In Date: 02/05/2008  
Close Date: 02/08/2008

Meter Reading: 8,519.00

**Problem?**

2 interior rear compartment dome light out r45 Main belt slipping  
"screech" upon cold start

Parts ----- Quantity -----

**Task performed:**

1. Replaced bulbs in rear pt lights

NO PARTS USED

**Workorder: V12984**

In Date: 02/01/2008  
Close Date: 04/08/2008

Meter Reading: 66,793.00

**Problem?**

replace tires at sta 45 callaghan

Parts ----- Quantity -----

**Task performed:**

Replace tires at Stn45 - Callaghan j

NO PARTS USED

**Vendor?** CALLAGHAN



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V14252**

In Date: 04/03/2008  
Close Date: 05/13/2008

Meter Reading: 69,811.00

**Problem?**

REPAIR COMP DOOR HINGE R45

**Task performed:**

1. repaired door hinge that was bent

Parts	Quantity
HLD374211 IN HOLD-OPEN 30LB	2
SAHSVS2510STRAP	3
UMVS-0811-11STRAP ZICO	4
UMVS111611STRAP	5
UMVS162511STRAP	3
UMVS254411STRAP 46 IN	2

**Workorder: V14869**

In Date: 05/05/2008  
Close Date: 05/13/2008

Meter Reading: 9,068.10

**Problem?**

R45 right rear scene light is out.

**Task performed:**

1. scan light out repaired broken ground wire in light bar

Parts	Quantity
H27SN12BULB	1



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## 10154110

### \* ADVANCED LIFE SUPPORT VEHICLE

#### Workorder: V14844

In Date: 05/04/2008  
Close Date: 06/02/2008

Meter Reading: 9,020.00

#### Problem?

R45A needs multiple bulbs replaced in the pt compartment over head lighting and one flod light bulb replaced in rear light bar R45 A

#### Task performed:

1. Slides broken in rollout trays. 2. Pt lights out (4); replcd pat lights. 3. Scene light out; replcd lights. j

Parts	Quantity
2220-145632-14 DRAWER SLIDE	2
322502BULB PATIENT GH22	4
H27SN12BULB	1

#### Workorder: V15356

In Date: 05/27/2008  
Close Date: 06/06/2008

Meter Reading: 72,169.00

#### Problem?

B INSPECTION AND REPAIRS AS NEEDED R 45

#### Task performed:

B-Inspection 2. Road call to Stn24 to ck out poss tire problem on rescue 3 Swap out of on-call trck. 4. Svc battries 5. Replc percer asy in light bar(shorted) 6. Replc cab roof marker bulb 7. Remov/extract (20 brkn exh manifold bolts & replc w/new. 8. Replc both turn signal side marker lenses(cracked). 9. Replc brkn valve stem ext hose stand on right rear wheel. 10. Replc rear cab A/C filter 11. Replc pat compt A/C filter 12. Replc pat compt floor light flourescent tubes. 13. Replc pat compt dome light bulb. 14. Installed (9) new lug jut covers(missing). 15. Clean shop. j

Parts	Quantity
000090155133634 FUEL FILTER WIX MERCEDES	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES	1
15W40BSYN OIL BULK QTS	24
194BULB	1
322502BULB PATIENT GH22	1
78R536078R5360M 2PK FILTER AIR COND	1
91513AMBER LENS	2
ACX-84534LUG NUT COVER PK10	9
DDE/9049900412EXHAUST BOLTS	2
PRMISCCNLA PIERCER 2 DUAL STROBE	1
R90PFILTER FUEL 33231	1
UNT7744USE PINK A/C FILTER MEDIC MASTER	1



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V15290**

In Date: 05/23/2008  
Close Date: 06/11/2008

Meter Reading: 72,058.00

**Problem?**

replace tires at sta 45 r45

Parts ----- Quantity -----

**Task performed:**

Replace tires R45 - Callaghan j

NO PARTS USED

Vendor? CALLAGHAN

**Workorder: V15598**

In Date: 06/08/2008  
Close Date: 07/02/2008

Meter Reading: 9,228.00

**Problem?**

The rescue is idling high and the "SUSP AIR" light came on. R45

Parts ----- Quantity -----

**Task performed:**

1. Chkd for problem w/high idle; FNP at this time. 2. Chkd problem w/air sys on truck & fnd air leak; repaired. j

NO PARTS USED

**Workorder: V16616**

In Date: 07/27/2008  
Close Date: 07/30/2008

Meter Reading: 9,480.40

**Problem?**

oxygen leak in hose for onboard system. R-45

Parts ----- Quantity -----

**Task performed:**

1. o2 leak / found fitting leaking on o2 regulator 2. rear pt lights in op on l / side . found bad connection at lights 3. air horns inop. / adjusted air horns 4. latch broken - installed new latch in rear door

NO PARTS USED





4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

\* **ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V16990**

In Date: 08/12/2008  
Close Date: 08/15/2008

Meter Reading: 9,571.40

**Problem?**

cab a/c not blowing cold on r45

Parts ----- Quantity -----

**Task performed:**

Cleaned condensor fans & recharged. j

NO PARTS USED

**Workorder: V17159**

In Date: 08/20/2008  
Close Date: 08/20/2008

Meter Reading: 102,289.10

**Problem?**

on call r45 park brake 10-7

Parts ----- Quantity -----

**Task performed:**

diagnose parking brake problem. unable to reproduce.

NO PARTS USED

**Workorder: V17273**

In Date: 08/24/2008  
Close Date: 09/02/2008

Meter Reading: 9,633.90

**Problem?**

passenger rear window does not roll up or down R-45

Parts ----- Quantity -----

**Task performed:**

Replaced window handle. j

A18-43563-000WINDOW HANDLE M2 2



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V17289**

In Date: 08/25/2008  
Close Date: 09/09/2008

Meter Reading: 9,633.90

**Problem?**

biohazardous material containment drawer broke.R45

**Task performed:**

Installed new slides in bio-drawer. j

Parts	Quantity
2220-10SLIDE 10 IN	2
2220-12USE 5632-12 DOOR SLIDE	4

**Workorder: V18537**

In Date: 10/23/2008  
Close Date: 10/28/2008

Meter Reading: 77,990.60

**Problem?**

A/C INOP, R-45A

**Task performed:**

Recharged cab A/C and repaired leak. j

Parts	Quantity
NO PARTS USED	

**Workorder: V18588**

In Date: 10/24/2008  
Close Date: 10/31/2008

Meter Reading: 9,926.40

**Problem?**

mechanism that locks stretcher to vehicle is loose R45

**Task performed:**

1. Stretcher latch loose; readj latch for stretcher. 2. Rear door hard to open; adj rear box door linkage. 3. Rear patient A/C warm; FNP with rear A/C. j

Parts	Quantity
NO PARTS USED	



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V18801**

In Date: 11/03/2008  
Close Date: 11/18/2008

Meter Reading: 78,481.70

**Problem?**

ON CALL R45 STRETCHER LOCK 10-7

**Task performed:**

Stretcher lock not working; went to shop to get part; fnd lock bar on s vc truck; returned to Stn; replc bar; adj bar; ck opn; ck ok. j

Parts ----- Quantity

090-0278STRECHER BAR NEW	1
--------------------------	---

**Workorder: V19241**

In Date: 11/21/2008  
Close Date: 11/25/2008

Meter Reading: 79,130.70

**Problem?**

repair a/c r45

**Task performed:**

Cab A/C inop; heater cable borken & low refrigerant; shutoff; comin g for C-Inspection. j

Parts ----- Quantity

NO PARTS USED	
---------------	--

**Workorder: V18970**

In Date: 11/10/2008  
Close Date: 12/01/2008

Meter Reading: 14.60

**Problem?**

Window arm crank broken off rescue 45.

**Task performed:**

1. Air leak; traced air leak; fnd none at this time. 2. Window crank brkn; replcd window crank. j

Parts ----- Quantity

A1818557002HANDLE-WINDOW	3
--------------------------	---



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

\* **ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V19256**

In Date: 11/21/2008  
Close Date: 12/05/2008

Meter Reading: 79,130.70

**Problem?**

REPLACE FRONT TIRES AT STA 45

Parts

Quantity

**Task performed:**  
replace front tires

NO PARTS USED

Vendor? CALLAGHAN

**Workorder: V19473**

In Date: 12/03/2008  
Close Date: 01/05/2009

Meter Reading: 79,484.10

**Problem?**

power steering leak r45

Parts

Quantity

**Task performed:**  
1. Air leaks down; chkd truck for air leak; fnd none at this time. 2. P/S leak; rep fitting that was leaking. j

NO PARTS USED

**Workorder: V19490**

In Date: 12/03/2008  
Close Date: 01/05/2009

Meter Reading: 110.40

**Problem?**

R45A front driver side blinker not working. R-45

Parts

Quantity

**Task performed:**  
Fnd no lights out on rescue. j

NO PARTS USED



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V19577**

In Date: 12/06/2008  
Close Date: 01/05/2009

Meter Reading: 151.70

**Problem?**

a/c unit blowing hot air only R-45

**Task performed:**

A/C blowing warm; need A/C compressor. j

Parts	Quantity
0127110042BELT MERCEDES MOTORS	1
07-0608A7160 DRIER A/C FRTLNR ABP-N83-319714	1
533303-0609 A/C COMPRESSOR M2 4485	1
8201L17-3428 ESTER OIL E7	1
R134AFREON LB	4

**Workorder: V19781**

In Date: 12/16/2008  
Close Date: 01/05/2009

Meter Reading: 189.30

**Problem?**

Front cab/ compartment AC is not blowing cold air.

**Task performed:**

Recharge sys & chkd for leak. j

Parts	Quantity
NO PARTS USED	

**Workorder: V19974**

In Date: 12/26/2008  
Close Date: 01/06/2009

Meter Reading: 257.00

**Problem?**

air conditioning in the cab not working and burning smell from under hood.  
Possibly a recurring problem from 2 weeks ago. R45

**Task performed:**

Check & charg front A/C sys; about 1.5 lbs; R134A. j

Parts	Quantity
R134AFREON LB	2



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V20181**

In Date: 01/07/2009  
Close Date: 01/27/2009

Meter Reading: 327.00

**Problem?**

A/C not working in front compartment. Weather stripping missing from the patient compartment rear door. r45

Parts \_\_\_\_\_ Quantity \_\_\_\_\_

**Task performed:**

1- Truck swap out due to accident.

NO PARTS USED

**Workorder: V20232**

In Date: 01/08/2009  
Close Date: 02/05/2009

Meter Reading: 81,289.00

**Problem?**

unit involved in accident r45

Parts \_\_\_\_\_ Quantity \_\_\_\_\_

**Task performed:**

1. Went to scene of accident; access damage; wait for wrecker; help swap unit. 2. Dlvr SR2 to Atlantic Ave; swap rescue; return to shop. j

NO PARTS USED

**Workorder: V20238**

In Date: 01/08/2009  
Close Date: 02/19/2009

Meter Reading: 81,289.00

**Problem?**

tow unit to shop involved in signal 4

Parts \_\_\_\_\_ Quantity \_\_\_\_\_

**Task performed:**

Tow unit to shop involved in signal 4 - Sisters Towing j

NO PARTS USED

**Vendor?** SISTERS TOWING



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

\* **ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V20549**

In Date: 01/23/2009  
Close Date: 02/19/2009

Meter Reading: 81,289.00

**Problem?**

TOW VEHICLE TO POMPANO, SOUTHEAST AUTO BODY R-45

Parts

Quantity

**Task performed:**

Tow vehicle to Pompano, Southeast Auto Bodhy - Sisters Towing j

NO PARTS USED

Vendor? SISTERS TOWING

**Workorder: V21054**

In Date: 02/11/2009  
Close Date: 02/23/2009

Meter Reading: 81,289.00

**Problem?**

provide window assy for side patient door and 1 tire R45 (accident damage)  
Give to southeast auto body

Parts

Quantity

**Task performed:**

Parts only 2/11/09 j

WIN6488PATIENT WINDOW LOWER SMALL

1

**Workorder: V19661**

In Date: 12/10/2008  
Close Date: 03/02/2009

Meter Reading: 182.00

**Problem?**

Driver front blinker light is out R-45

Parts

Quantity

**Task performed:**

NO PARTS USED



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

\* **ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V21763**

**In Date:** 03/12/2009

**Meter Reading:** 81,289.00

**Close Date:** 04/08/2009

**Problem?**

C INSPECTION AND REPAIRS AS NEEDED R45

Parts

Quantity





4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## 10154110

### \* ADVANCED LIFE SUPPORT VEHICLE

#### Task performed:

Perform C-Inspection. 2. Overtime 3. Make parts list & start repairs. 3. Rem air horns & side strobes for decals. 4. install air horns & strobes; splice wires. 6. Drill out stripped door latch bolts; replc all door latches. 7. Go to work comp doctor. 8. Replc btry tender light gauge plate; rep hold down & fuse wiring. 9. Replc all (4) lower door seals; rem all plates & cln drains out. 10. Rem drivers/officers seats; send out for rep. 11. Replc frnt u-bolts; torque to specs & replc frnt shocks. 12. Blow out both condensors 13. Recover leak test & recharge rear A/C; replc high side svc part; rep several leaks, evac & recharge sys (2) times. 14. Replc A/C control head. 19. Replc all (4) A/C diverters. 16. Paint fuel cap. 17. Rebuild air dryer. 18. Replc fan belts. 19. Rep/adj L/R right height control valve. 20. Recove leak tst & recharge frnt A/C low side; svc port leaking 21. Safety mtg. 22. Replc plexiglass on sharps door; new plexi cracked on install; R/R again. 23. Rem sharps drawer; mod cabinet to install larger sliders. 24. Replc heater control cables; bleed door cables & chk opn. 25. Replc pat rear door seal & adj strikers, lube latches. 26. Replc stretcher lock. 27. Chk leak at washer reservoir; R/R reservoir. 28. Recenter steering wheel; pulle holes stripped out; drill (2) new holes & tap out; pull steering wheel & recenter; resecure wheel to column. 29. Rem rear step from veh; straighten out step & back plate; reweld back plate to step & replc onto veh. 30. Reinstall pat door window seal. 31. Perform brake performance before/after brake replacement. 32. Rep wiring to door open lamp for L-front door; drill hole for new swtch & install. 33. Replc frnt/rear brakes. 34. Swap into on-call. 35. Replc both air bags & reset ride height. 36. Assist with brake distance test - George. 37. Replc A/C high side fittings a compressor for frnt sys. j

0000900087DDE/A0000900087 FILTER HEAD SM MEI	1
000090155133634 FUEL FILTER WIX MERCEDES	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES	1
0127110042BELT MERCEDES MOTORS	1
032-0116549297 BATTERY INDICATOR	1
090-0278STRECHER BAR NEW	1
107796DRYER KIT AD9 -NEW	1
107800VALVE CHECK AD9	1
1500900017000USE 9 X 14 FILTER	1
15W40BSYN OIL BULK QTS	24
16-15762-00016-19471-000 AIR BAG	2
16-31438915 VALVE CORE A/C 3544706C1	1
16-3444CAP R134A - RED 5575/5557	1
18-29935-001RH DOOR LATCH NEW	2
18-45484-000LATCH L/H	2
22-40867-000RESERVOIR	1
22-40868-000WASHER CAP WPB-FREIGHTLINER	1
22-49905-000CABLE HEATER	1
2220-12USE 5632-12 DOOR SLIDE	3
23-11345-714INSTRUMENT CLUSTER SCREWS 1 1/	4
23-11865-000SPRING NUT	4
23-12149-082SCREW - DOOR	4
298818298818 KNOB PARKING BRAKE	1
334123HOSE-N-FITTINGS	1
3744BRAKE DRUM REAR	2
3753BRAKE DRUM RUMPER FRONT	2
4909SCUT AND FAB FITTING	1
6803230300 65482 SHOCK FRONT ENGINE	2
6806970098SEAL DOOR	1
6808300074VENT A/C LH	1



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## 10154110

**\* ADVANCED LIFE SUPPORT VEHICLE**

6808330631CABLE ASSY HEATER	1
78R536078R5360M 2PK FILTER AIR COND	1
800405PURGE VALVE KIT	1
8201L17-3428 ESTER OIL E7	2
8T3420U BOLT	4
9425BELT MERCEDES RESCUE 12.5X1075 OE	1
A2241332074A22-41332-074 HOSE ASSY.	1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER B/	4
DN34NUT FOR UBOLT	8
E-2769MKT4515QB BRAKE KIT	1
EST-1THERMAL TREATMENT	8
EST-2DDIAMOND TREATMENT	4
HP-31DBATTERY 950CCA HP-31D	4
KSMA2124703QFRONTBRAKE KIT RUMPER AND 4D	2
KSMA3124710QKSMA3124710QP REAR BRAKE SHC	2
R90PFILTER FUEL 33231	1
R955341ABS SENSOR FRONT OLD # S4410328130	1
SUW34WASHER U BOLT	8

**Workorder: V21835**

In Date: 03/16/2009      Meter Reading: 81,289.00

Close Date: 04/14/2009

**Problem?**

REPAIR FRONT BODY DAMAGE FROM ACCIDENT, R-45

Parts ----- Quantity -----

**Task performed:**

Repair front body damage from accident R45 - Southeast Truck j

NO PARTS USED

**Vendor?** SOUTHEAST TRUCK



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

\* **ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V22100**

In Date: 03/26/2009  
Close Date: 04/14/2009

Meter Reading: 81,289.00

**Problem?**

repair 2 seats (outside agency-central auto trim) R45

Parts

Quantity

**Task performed:**

Repair (2) seats - Central Auto Trim j

NO PARTS USED

Vendor? ENTRAL AUTO TRIM

**Workorder: V22336**

In Date: 04/06/2009  
Close Date: 05/08/2009

Meter Reading: 81,496.00

**Problem?**

REPLACE TIRES AT SHOP CALLAGHAN R45

Parts

Quantity

**Task performed:**

Replcd tires at shop - Callaghan j

NO PARTS USED

Vendor? CALLAGHAN

**Workorder: V21760**

In Date: 03/12/2009  
Close Date: 05/11/2009

Meter Reading: 81,289.00

**Problem?**

INSTALL GRAPHICS ON L/SIDE DOOR, R/SIDE DOOR, AND HOOD R-4!

Parts

Quantity

**Task performed:**

Install graphics on L/side door; R/side rood & hood R45 - Graphic Designs. j

333991A/C HOSE

1

Vendor? GRAPHIC DESIGNS



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V22847**

In Date: 04/27/2009  
Close Date: 05/26/2009

Meter Reading: 459.00

**Problem?**

R45 pro splint compartment on left side of truck inside bracket is broken. ( Not conected to side of the inner compartment )

Parts \_\_\_\_\_ Quantity \_\_\_\_\_

**Task performed:**

Rep brkn slides in rear compt. j

NO PARTS USED

**Workorder: V22857**

In Date: 04/28/2009  
Close Date: 05/26/2009

Meter Reading: 472.70

**Problem?**

rear door does not close or open well

Parts \_\_\_\_\_ Quantity \_\_\_\_\_

**Task performed:**

1. Readj rear door linkage. 2. Air leak; rep air leak at air ride seat. j

NO PARTS USED

**Workorder: V23196**

In Date: 05/11/2009  
Close Date: 05/26/2009

Meter Reading: 526.20

**Problem?**

R45 AIR HORN IS NOT WORKING r45

Parts \_\_\_\_\_ Quantity \_\_\_\_\_

**Task performed:**

1. Air horn inop; replcd air horn solenoid. 2. Rear door hard to open; readj rear door linkage. 3. Rep stretcher latch. j

HDY-H005700SOLENOID HORN AIR 1



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

\* **ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V24207**

In Date: 06/19/2009      Meter Reading: 643.90  
Close Date: 07/06/2009

**Problem?**

front driver side headlight out R-45

Parts ----- Quantity -----

**Task performed:**

1. Replcd hed lights. 2. Rear light bar inop; rep bad connection. j

NO PARTS USED

**Workorder: V24208**

In Date: 06/19/2009      Meter Reading: 643.90  
Close Date: 07/06/2009

**Problem?**

o2 bottle strap and cover ripped unable to secure bottle to stretcher R-45

Parts ----- Quantity -----

**Task performed:**

1. Air leak; fnd no air leaks. 2. Rear door had to open; adj rear door linkage. 3. Rear A/C not blowing cold; recharged sys. j

NO PARTS USED

**Workorder: V24594**

In Date: 07/06/2009      Meter Reading: 10,972.00  
Close Date: 07/17/2009

**Problem?**

belt squealing while driving and during idle. error showing on computer module r45

Parts ----- Quantity -----

**Task performed:**

1. Belt squeal-A/C belt loose; adjusted belt. 2. Fuel leak - #2 inejctor line loose; cldn eng area. 3. Node #3 error warning; pin loose connection; cldn/tightened connector. j

NO PARTS USED



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V24486**

In Date: 07/01/2009  
Close Date: 07/28/2009

Meter Reading: 85,256.50

**Problem?**

A/C 10-7 R 45

Parts ----- Quantity -----

**Task performed:**

1. A/C inop; recharged unit. 2. Spotlight out; rep bad connection. 3. Air leak; fnd no air leaks. j

NO PARTS USED

**Workorder: V24758**

In Date: 07/14/2009  
Close Date: 08/05/2009

Meter Reading: 85,404.00

**Problem?**

an error comes up on and off on the menu screen. there is no obvious problem noticed only the error message about a node malfunction. r45

Parts ----- Quantity -----

**Task performed:**

Error message for node #3; pin "C" problem condensor #1 draws excessive current; damaged connector; replc node & fan; travel to Stn. j

600000003NODE HERCULES V-MUX	1
60027FAN A/C COND 12IN 860026-2-W	1

**Workorder: V25778**

In Date: 08/25/2009  
Close Date: 08/28/2009

Meter Reading: 87,222.10

**Problem?**

PATIENT COMPARTMENT A/C INOP

Parts ----- Quantity -----

**Task performed:**

Pat compt A/C inop; poss hose line board failure; T-shoot A/C sys; reprogram node; was working & then failed again; sent to main shop. j

NO PARTS USED



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

\* **ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V25779**

**In Date:** 08/25/2009

**Meter Reading:** 87,222.10

**Close Date:** 09/02/2009

**Problem?**

patient a/c innop R45

**Task performed:**

1. Trace problem w/rear A/C; replc oil press switch & condensor fan problem; switch exists. 2. Hooked up all wiring back to factory & replcd relay for A/C sys; run ok. j

**Parts**

**Quantity**

0332002156USE 380830 RELAY 12V 75A RLY5491	1
60027FAN A/C COND 12IN 860026-2-W	2
DDE-0041534928A0071530828 OIL PRESSURE SENS	1



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

\* **ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V25797**

**In Date:** 08/26/2009

**Meter Reading:** 87,222.10

**Close Date:** 09/11/2009

**Problem?**

**B INSPECTION AND REPAIRS AS NEEDED R45**

Parts

Quantity





4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## 10154110

### \* ADVANCED LIFE SUPPORT VEHICLE

#### Task performed:

B-Inspectin 2. Replcd pat compt inner door handle coilz. 3. Replcd outer drivers door handle. 4. Secured inner drivers door panel w/new plastic rivets. 5. Replcd LR door molding- msng completely. 6. Replcd cab A/C filter. 7. Reglued insulation by drivers feet. 8. Dia/rep pat compt A/C sys. 9. Replcd instrument cluster. 10. Replcd both rear seat belts. 11. Secured SCBA brkts. 12. Replcd alt; had to grind down brkt to get alt out; can be done on road now. 13. Replcd fuel pump, return fuel line & chk valve on return side; primed sys & started. 14. Replcd valve cvr gskt, cld breather element & replcd breather cvr gskt. 15. Rep supports & replcd msng inner fender on RF hood. 17. Replcd officers door exterior handle. 18. Replcd drivers door seal. 19. Replcd LF amber clearance light. 20. Replcd dome light bulb. 21. Replcd flourescent light bulbs. 22. Rem bent screws frm action area. 23. Adj inner doors on all compts. 24. Tightened door latches. 25. Tightened panels on interior of compt doors. 26. Replcd lens on LR LED. 27. Replcd hold opens on L-3 compt. 28. Adj door linkage R1 compt. 29. Replcd cabinet holdopens in pat compt. 30. Replcd plexi-glass door in pat compt. 31. Replcd side door holdopen. 32. R/R wipers. 33. Fab/installed (2) brkts to support diamond plate cvr over fuel tank. 34. Torque u-bolts. 35. Replcd traffic advisor head. 36. Replcd non-skid tape on steps. 37. Adj tire pressures. 38. Made label for emergency master button. j 31

000090155133634 FUEL FILTER WIX MERCEDES	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES	1
01068234000CTACTLD1 CONTROL PANEL TRAFFIC	1
15W40BSYN OIL BULK QTS	24
17125540001712554004 SHIELD SPLASH R/H	1
322502BULB PATIENT GH22	1
4867JB320 UPGRADE ALTERNATOR	1
52-24WIPER BLADES ANCO 24	2
6807600070HANDLE DOOR EXT L/H	1
6807600170HANDLE DOOR EXT. R/H	1
6809880278TURN PLUG	8
68118354250900 SERIES RED LENS	1
78R536078R5360M 2PK FILTER AIR COND	1
9060910580FUEL PUMP GASKET M2	1
9060920510FUEL CHECK VALVE	1
9062001170IDLER MERCEDES	1
98003RREFLECTOR RED 40132 GROTE	1
A0000160521GASKET VALVE COVER	1
A0000180133DIAPHRAM SEAL	1
A0079932401SPRING DIAPHRAM	1
A1834388002MOLD L/H	1
A2249250001 A22-49250-003 CLUSTER ASSY	1
A9060160080GROMET VALVE COVER	7
A9060160721SIDE GASKET	1
A9060901276A9060903376 FUEL LINE	1
CLR9185209186-1500-20 MARKER LT.AMBER LED	1
DDE-R0040910501FUEL PUMP M2	1
DDE/007603016102RING FUEL PUMP	1
DOOR5LEXAN 9 X 38 1/2 IN	1
GSS1717UL1717UL0270N 343/09 GAS SHOCK 60 LB	4



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

**\* ADVANCED LIFE SUPPORT VEHICLE**

HAN-1LBEZEL AND HANDLE	2
HLD39917DC23-5011 50 # HOLD-OPEN RESCUE	1
HLD44614446 1/4 LATCH	1
IMMF13240REAR SEAT BELT OLD # IMMF11847	1
R90PFILTER FUEL 33231	1
RCB BOXBOX/COVER FOR RCB3000	1
RCB-3000CONTROL BOARD USE WITH CM3000	1

**Workorder: V25829**

In Date: 08/27/2009      Meter Reading: 87,222.10  
Close Date: 09/14/2009

**Problem?**

REPLACE 2 FRONT TIRES, R-45B

Parts ----- Quantity

**Task performed:**

Replace (2) front tires R45B - Callaghan j

NO PARTS USED

Vendor? CALLAGHAN

**Workorder: V26304**

In Date: 09/16/2009      Meter Reading: 1,096.00  
Close Date: 09/29/2009

**Problem?**

R45 cab AC not working.

Parts ----- Quantity

**Task performed:**

Cab A/C inop; discharge line leaking; locate leak & rep/recrimped fitting. j

NO PARTS USED



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

\* **ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V26967**

In Date: 10/19/2009  
Close Date: 11/12/2009

Meter Reading: 88,904.10

**Problem?**

PROGRAM NODE TO DEFAULT A/C ON R45

Parts ----- Quantity -----

**Task performed:**

1. Air leak; fnd no air leaks. 2. Spotlight inop; rep bad connection. j

NO PARTS USED

**Workorder: V27514**

In Date: 11/09/2009  
Close Date: 11/17/2009

Meter Reading: 90,002.00

**Problem?**

ON CALL STRETCHER LOCK 10-7 R45B

Parts ----- Quantity -----

**Task performed:**

Drive to Stn45; rep stretcher lock; wld not lock in a hold. j

NO PARTS USED

**Workorder: V27826**

In Date: 11/20/2009  
Close Date: 01/13/2010

Meter Reading:

**Problem?**

R45 Alpha has a air leak, hard to disengage emergency brake to respond to calls. Needs to be repaired.

Parts ----- Quantity -----

**Task performed:**

Air leak; replcd parking brake valve. j

800034VALVE PARKING BRK. 1



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V28444**

In Date: 12/17/2009  
Close Date: 02/22/2010

Meter Reading: 1,497.80

**Problem?**

"water in fuel" light is on R45

Parts ----- Quantity -----

**Task performed:**

road tested; fnd no light on. j

NO PARTS USED

**Workorder: V30154**

In Date: 02/23/2010  
Close Date: 03/17/2010

Meter Reading: 93,891.00

**Problem?**

on call r45 no a/c

Parts ----- Quantity -----

**Task performed:**

1. Cab A/C inop; fnd press swtchs & swtchs on air dryer disconnected. 2. Door openlight on; fnd rear door swtch wire grnd out. 3. Installed cvr over fan in radio box. j

NO PARTS USED

**Workorder: V30581**

In Date: 03/09/2010  
Close Date: 03/17/2010

Meter Reading: 94,813.70

**Problem?**

SCBA BRACKET STRAP WILL NOT LOCK IN PLACE, R-45B

Parts ----- Quantity -----

**Task performed:**

replace scba braket in rear seat behind driver

NO PARTS USED



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

\* **ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V29596**

**In Date:** 02/01/2010

**Meter Reading:** 93,891.00

**Close Date:** 03/19/2010

**Problem?**

replace tires boulevard tire r45

Parts

Quantity

**Task performed:**

Replace tires R45 - Boulevard j

NO PARTS USED

**Vendor?** BOULEVARD TIRE



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

\* **ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V29501**

**In Date:** 01/28/2010

**Meter Reading:** 93,891.00

**Close Date:** 03/22/2010

**Problem?**

C INSPECTION AND REPAIRS AS NEEDED R45

Parts

Quantity



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

\* **ADVANCED LIFE SUPPORT VEHICLE**

**Task performed:**

C-Inspection 2. R/R wipers 3. Set up trk for tire guy for replacement tires. 4. Svc P/S sys; swap to syn lube. 5. Svc rear 6. R/R air compressor seals. 7. R/R exh man/gskt, turbo gskt, etc.; rem brkn lights in head. 8. Rep A/C leak; rem freon, get access to hoses; rem hose/fittings; get to parts. 9. R/F & rewire 110V A/C sys. 10. paint fuel cap; R/R high compt bulb. 11. C/O UV light out; R/R bulb, still out; R/R unit. 12. Straighten out door latches on med boxes doors & readj. 13. Replc A/C line leaking; R/R dryer; R/R pres: switch; vaca sys & fill; R/R fittings. 14. R/R dryer & rebuild. 15. Svc cooling sys; replc coolant drum in back; replc cab & drain plug. 16. R/R belts. j 17. Replc rear valve stem ext. brkts-brkn. 18. Rear window glass rubber trim loose; reinstalled rubber trim. 19. Rear lab A/C filter brkn; replcd filter. j

000090155133634 FUEL FILTER WIX	MERCEDES	1
0001801709OIL FILTER 03 57215 WIX	MERCEDES	1
0127110042BELT MERCEDES MOTORS		1
05-17223-002RAD CAP 20 LB		1
0634313640O-RING COMPRESSOR		2
071601A07-0602A DRIER A/C 7118		1
107796DRYER KIT AD9 -NEW		1
107800VALVE CHECK AD9		1
15-22150-06OIL PLUG ADAPTER MBE900		1
15W40BSYN OIL BULK QTS		28
29526898 29548988 TRANS FILTER ALLISON		1
322502BULB PATIENT GH22		1
359-5990PLUG - HUB OIL CAP		2
52-24WIPER BLADES ANCO 24		2
78R536078R5360M 2PK FILTER AIR COND		1
800405PURGE VALVE KIT		1
9061420057SEAL RING EXHAUST MANIFOLD		2
9061421101EXHAUST MANIFOLD CENTER		1
9061421201EXHAUST MANIFOLD R/L		2
9425BELT MERCEDES RESCUE 12.5X1075 OE		1
A0029979790CLAMP		1
ACX-84534LUG NUT COVER PK10		10
AMH-1AMH-1 VALVE EXTENSION		1
CA8193AIR FILTER 46744 WIX		1
DDE-000000001069USE V007603014104 SEAL WASH		2
DDE-5411870080GASKET OIL RETURN TUBE TURBO		1
DDE/00009903150TURBO NUTS		8
DDE/0019904605TURBO STUD		6
DDE/9061420280USE A9261420080 EXHAUST MANIF		3
DDE/A0289976348TURBO ORINGS		1
EXO3AH00015SPLUG RAD. DRAIN		1



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## 10154110

### \* ADVANCED LIFE SUPPORT VEHICLE

FG87904MFG3937557S FILTER P/S NEW STYLE	1
FGQ79699GASKET-P/S FILTER NEW STYLE	2
FTT53931491 SW PRESS. HI SIDE NC OPEN-350 CLC	1
N000000001069SEAL BANJO	1
N007603014104WASHER SEAL	4
R90PFILTER FUEL 33231	1
RA9061301415AIR COMPRESSOR	1
UNT620515USE CARRIER	1
UVAPS253 UNIT UV LIGHT A/C RESCUES	1
VML-T1413T3248 SIGHT GLASS	1

#### Workorder: V29248

In Date: 01/19/2010      Meter Reading: 1,713.00  
Close Date: 03/26/2010

#### Problem?

Would like to have the MOD button stay on full time on the rescue again. It used to do that, now we have to hit the MOD button everytime we start the rescue. Can we get it changed back? r45

Parts ----- Quantity

#### Task performed:

Stretcher latch inop; readj latch & tested. j

NO PARTS USED

#### Workorder: V30276

In Date: 02/26/2010      Meter Reading: 94,161.00  
Close Date: 03/26/2010

#### Problem?

the blower for the bay needs a new spark plug (Station 45)

Parts ----- Quantity

#### Task performed:

1. Rep blower that had bad gas. 2. Rep frnt A/C that was blowing warm ai  
j

NO PARTS USED





4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V31531**

In Date: 04/14/2010  
Close Date: 04/14/2010

Meter Reading: 95,479.00

**Problem?**

parts only R45

Parts	Quantity
-------	----------

**Task performed:**

DDE/9049900412EXHAUST BOLTS	12
-----------------------------	----

**Workorder: V31296**

In Date: 04/06/2010  
Close Date: 05/01/2010

Meter Reading: 95,479.00

**Problem?**

A/C 10-7 R45

Parts	Quantity
-------	----------

**Task performed:**

Recharged sys & chkd A/C. j

NO PARTS USED	
---------------	--

**Workorder: V31440**

In Date: 04/11/2010  
Close Date: 05/01/2010

Meter Reading: 95,479.00

**Problem?**

AC in patient compartment only works intermittently. R45

Parts	Quantity
-------	----------

**Task performed:**

tested A/C; fnd unit cutting out; replc low press switch. j

142211-2028 SWITCH PRESS OPEN-6 CLOSE-34	1
6000000003NODE HERCULES V-MUX	1



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V32598**

In Date: 06/02/2010  
Close Date: 06/02/2010

Meter Reading: 98,445.00

**Problem?**

r45 pager not functional

Parts ----- Quantity -----

**Task performed:**

reported to radio shop 06/02

NO PARTS USED

**Workorder: V32477**

In Date: 05/27/2010  
Close Date: 06/25/2010

Meter Reading: 98,445.00

**Problem?**

drivers side turn lamp is broke off. turn lamp is on the wheel well. R45

Parts ----- Quantity -----

**Task performed:**

R/R t-signal light. j

6808200020LIGHT ASSY. TURN SIGNAL 2

**Workorder: V31860**

In Date: 04/28/2010  
Close Date: 07/02/2010

Meter Reading: 97,067.00

**Problem?**

R45A passenger side mirror bracket broken.

Parts ----- Quantity -----

**Task performed:**

1. replace r/side mirror bracket 2. tighten belts

11133MIRROR MOUNT 1



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V32946**

In Date: 06/16/2010  
Close Date: 07/21/2010

Meter Reading: 99,196.00

**Problem?**

Air horn on R45 not working.

Parts ----- Quantity -----

**Task performed:**

Replcd air horn solenoid. j

NO PARTS USED

**Workorder: V32955**

In Date: 06/17/2010  
Close Date: 07/21/2010

Meter Reading: 99,196.00

**Problem?**

ST45-radiator upper tank is extremely corroded and showing signs of leakage. Please repair/replace as needed. r45

Parts ----- Quantity -----

**Task performed:**

Chkd tank for coolant & tank was fine. j

VML-T1413T3248 SIGHT GLASS 1

**Workorder: V33313**

In Date: 07/03/2010  
Close Date: 07/29/2010

Meter Reading: 100,192.00

**Problem?**

The rubber divider that seperates the cab and the work area is leaking water thier is a hole in it. R45

Parts ----- Quantity -----

**Task performed:**

Holew is too big to seal; temporary covered w/duct tape; needs new bolt. j

NO PARTS USED



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V33627**

In Date: 07/19/2010  
Close Date: 08/11/2010

Meter Reading: 100,192.00

**Problem?**

b inspection and repairs R45

**Task performed:**

C-Inspection 2. Replc florescent light in pat c ompt. 3. Replc light (round) in pat compt over stretcher. 4. Rep side entry door hinge. 5. Replc bulb in R/side cab roof marker light. 6. Evac A/C frnt sys; charge sys; chk for leaks; fnd valve leaking on lo-side; replc shrader valve; rechk ok. ja

**Parts**

**Quantity**

000090155133634 FUEL FILTER WIX MERCEDES	1
0000902051FILTER FUEL 03 MERCEDES	1
00009247080000925208 FILTER HEAD CAP NEW NU	1
0001801709OIL FILTER 03 57215 WIX MERCEDES	1
15W40BSYN OIL BULK QTS	24
322502BULB PATIENT GH22	1
R90PFILTER FUEL 33231	1

**Workorder: V34129**

In Date: 08/09/2010  
Close Date: 09/08/2010

Meter Reading: 95,479.00

**Problem?**

coolant leak R45(callout repair)

**Task performed:**

Press tsted sys; fnd hoses leaking; rep hoses & road tested. j

**Parts**

**Quantity**

NO PARTS USED	
---------------	--



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V33733**

In Date: 07/22/2010  
Close Date: 09/10/2010

Meter Reading: 100,192.00

**Problem?**

REPLACE TIRES AT STA 42 R45 BOULEVARD

Parts ----- Quantity -----

**Task performed:**

Replc tires at Stn42 R45 - Boulevard ja

NO PARTS USED

Vendor? BOULEVARD TIRE

**Workorder: V34232**

In Date: 08/12/2010  
Close Date: 09/17/2010

Meter Reading: 101,565.00

**Problem?**

Driver side headlight on R45 Alpha is out. Please change it has soon as possible.

Parts ----- Quantity -----

**Task performed:**

Replcd headlight. j

H6054USE CV TYPE SEALED BEAM 4

**Workorder: V34283**

In Date: 08/15/2010  
Close Date: 09/17/2010

Meter Reading: 101,565.00

**Problem?**

TRANSMISSION FLUID LEAKING AND AC PATIENT COMPARTMENT WORKING INTERMITTENT R45

Parts ----- Quantity -----

**Task performed:**

Fnd no trans leak after road test. j

NO PARTS USED



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V35370**

In Date: 10/04/2010  
Close Date: 10/25/2010

Meter Reading: 15,225.60

**Problem?**

ON CALL SLOW STARTING R45

Parts ----- Quantity -----

**Task performed:**

check for slow starting, check and found loose power stud on starter, tightened and checked ok. jab

NO PARTS USED

**Workorder: V35372**

In Date: 10/04/2010  
Close Date: 10/25/2010

Meter Reading: 15,225.60

**Problem?**

ON CALL A/C 10-7 R 45

Parts ----- Quantity -----

**Task performed:**

1. check a/c, ran a/c temp was 50 degrees, everything tested ok. jab

NO PARTS USED

**Workorder: V35897**

In Date: 10/25/2010  
Close Date: 11/05/2010

Meter Reading: 103,982.00

**Problem?**

A inspection and repairs

Parts ----- Quantity -----

**Task performed:**

1. a inspection 2. check city horns, found bad city horn , r&r high city horn, test ok. 3. r&r patient comp light. jab

322502BULB PATIENT GH22	1
921LIGHT BULB	1
A0631117000HORN HIGH NEW # 06-52125-039	1



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V36093**

**In Date:** 11/01/2010  
**Close Date:** 12/03/2010

**Meter Reading:** 104,175.00

**Problem?**

A INSPECTION SR15

**Task performed:**

(1) "A" INSPECTION SR15 (2) REPLACED LEFT REAR INNER TIRE INFLATION HOSE ASSEMBLY. (3) FILL ALL TIRES TO 100 PSI. (4) INSTALLED MISSING BOLT IN ENGINE INTAKE HEATER. (5) MIX AND FILL WASHER FLUID RESERVOIR. (6) REPAIRED HOSES & TEE FITTING AT COWL FOR WINDSHIELD WASHER. (7) REPLACED DOOF OPEN WARNING SWITCH FOR RIGHT REAR CAB DOOR. (8) REPLACED BULB ON CEILING OF PATIENT COMPARTMENT AREA. (9) SECURED HOLD OPEN LEFT #3 COMPARTMENT DOOR. (10) REPLACED REAR AXLE BRAKES. 11-04-10 REPLACED REAR AXLE BRAKES. 11-05-10

Parts

Quantity

91823SWITCH SWT5499 MED MASTER	1
KSMA3124710Q-TDIAMOND TREATED REAR BRAKE	2
SPR-W58-1TEE PLASTIC	1

**Workorder: V36387**

**In Date:** 11/12/2010  
**Close Date:** 12/16/2010

**Meter Reading:** 104,366.00

**Problem?**

AIR LEAKS SR AT 41

**Task performed:**

(1) TRAVELED TO ST41 TO REPAIR AIR LEAK ON SR15. CHECKED OUT AIR SYSTEM AND FOUND AIR LEAK AND REPAIRED. OK. J.W.

Parts

Quantity

NO PARTS USED



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

\* **ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V37010**

In Date: 12/08/2010  
Close Date: 12/29/2010

Meter Reading: 104,519.00

**Problem?**

right rear light cover is missing sr at 29

**Task performed:**

(1) TRAVELED TOST29 TO CHECK OUT REAR LIGHT COVER ON R29 NEED NEW LIGHT COVER. WILL ORDER. (2) TRAVELED TO ST29 AN R&R LIGHT COVER WITH NEW ONE. OK. J.W.

Parts	Quantity
6811813495LENS-RED 68-1181349-5	1

**Workorder: V37035**

In Date: 12/09/2010  
Close Date: 12/29/2010

Meter Reading: 104,519.00

**Problem?**

light came on stating " water in fuel" SR AT 29

**Task performed:**

(1) TRAVELED TO ST29 TO CHECK SR29 FOR LIGHT COMING ON SHOWING H2O IN FUEL. CHECKED OUT FUEL/H2O FILTER. STILL OI UNPLUGGED SENSOR PER MIKE LEHANS ORDERS. WILL SOLVE PROBLEM UPON PM INSPECTION AT SHOP AT A LATER DATE. J.W.

Parts	Quantity
NO PARTS USED	

**Workorder: V37579**

In Date: 01/03/2011  
Close Date: 01/06/2011

Meter Reading: 106,236.00

**Problem?**

WATER IN FUEL light activated on dash SR AT 14

**Task performed:**

(1) TRAVELED TO ST-14 TO REPAIR PROBLEM ON SR14 THAT HAS THE WATER IN FUEL LIGHT ACTIVATED. FOUND THE SENSOR DIRT CLEANED THE SENSOR AND LIGHT WENT OFF. OK. J.W.

Parts	Quantity
NO PARTS USED	





4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## 10154110

### \* ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V37871**

**In Date:** 01/18/2011  
**Close Date:** 02/08/2011

**Meter Reading:** 107,000.00

**Problem?**

C INSPECTION AND REPAIRS AS NEEDED SR 10

**Task performed:**

1. Tighten & adj all door latches/pins. 2. Replc eng air filter, pat air filter & rear cab A/C filters. 3. T-shoot city horns; fnd unplugged. 4. Rem L-3 compt hinge mnts; redrill/tap to 5/16 18; remnt hinge. 5. Rem both rear doors for paint. 6. C-Inspection 7. Svc air dryer. 8. Tighten stretcher lock mntng bolts. 9. Rem officer's door panel & tighten door handle asy. 10. Help with C-inspection. j

Parts	Quantity
000090155133634 FUEL FILTER WIX MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES	1
103385NDRAIN COCK	2
107796DRYER KIT AD9 -NEW	1
107800VALVE CHECK AD9	1
1501450007750USE 0775145	1
15W40BSYN OIL BULK QTS	24
52-24WIPER BLADES ANCO 24	2
78R536078R5360M 2PK FILTER AIR COND	1
800405PURGE VALVE KIT	1
923182-2151 SWITCH MOMENTARY 24-372	1
CA8193AIR FILTER 46744 WIX	1
R90PFILTER FUEL 33231	1
VML-T1413T3248 SIGHT GLASS	1

**Workorder: V37368**

**In Date:** 12/22/2010  
**Close Date:** 03/08/2011

**Meter Reading:** 106,999.60

**Problem?**

a inspection back from 29

**Task performed:**

A-Inspection 2. Top off P/S, trans, & coolant fluids. 3. Replcd R/siren speaker. j

Parts	Quantity
SD-210RXSIREN DRIVER SMALL	1



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V38589**

In Date: 02/17/2011      Meter Reading: 107,151.00  
Close Date: 03/09/2011

**Problem?**

water in fuel indicator light on sr at 48

Parts ----- Quantity -----

**Task performed:**

Chk for wtr in fuel - all tested ok. j

NO PARTS USED

**Workorder: V38590**

In Date: 02/17/2011      Meter Reading: 107,151.00  
Close Date: 03/09/2011

**Problem?**

spare truck-unable to open rear door from inside sr at 48

Parts ----- Quantity -----

**Task performed:**

Adj rear door linkage & tested. j

NO PARTS USED

**Workorder: V38684**

In Date: 02/22/2011      Meter Reading: 107,151.00  
Close Date: 03/15/2011

**Problem?**

shore line does not click into truck and not working SR AT 48

Parts ----- Quantity -----

**Task performed:**

Rep outlet plug that was ran over. j

NO PARTS USED



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

\* **ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V38731**

In Date: 02/23/2011  
Close Date: 03/24/2011

Meter Reading: 107,151.00

**Problem?**

water in fuel light is on AT 48

Parts ----- Quantity -----

**Task performed:**

Water in fuel; fnd no wtr; reset light. j

NO PARTS USED

**Workorder: V38898**

In Date: 03/01/2011  
Close Date: 03/24/2011

Meter Reading: 107,151.00

**Problem?**

A INSPECTION AND REPAIRS AS NEEDED

Parts ----- Quantity -----

**Task performed:**

A-Inspection 2. Drained wtr \_\_\_\_; light went off; went for test; drove truck. ran good. 3. Put new asy # sticker in window. j

NO PARTS USED

**Workorder: V39492**

In Date: 03/28/2011  
Close Date: 04/04/2011

Meter Reading: 107,151.00

**Problem?**

Rectangular light out in pt compartment near rear door over stretcher. R28

Parts ----- Quantity -----

**Task performed:**

Travel to 28; replc flourescent bulbs in pat compt. j

NO PARTS USED



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V39587**

In Date: 03/31/2011  
Close Date: 04/05/2011

Meter Reading: 195,824.00

**Problem?**

A INSPECTION AND REPAIRS AS NEEDED

Parts ----- Quantity -----

**Task performed:**  
A-Service j

NO PARTS USED

**Workorder: V39892**

In Date: 04/13/2011  
Close Date: 04/18/2011

Meter Reading: 195,824.00

**Problem?**

A INSPECTION AND REPAIRS AS NEEDED

Parts ----- Quantity -----

**Task performed:**  
A-Inspection 2. Adj tire pressures. 3. Blowout & aim windshield washers.  
4. Chk wiring at t-signal switch; adj lever tension screw. 5. Rem 4 qts eng oil to bring level to full mark. j

14-7014HGR-1 HELMET HOOK 2

**Workorder: V40333**

In Date: 05/02/2011  
Close Date: 05/10/2011

Meter Reading: 109,026.00

**Problem?**

A inspection.

Parts ----- Quantity -----

**Task performed:**  
A-Inspection 2. Pat compt rear entrance overhead padding loose; drill/present holes & secure padding. 3. left rear window outer seal msg; cln surface & install new window seal. 4. Left rear to frnt right window modling damage; rem/install new moldings. j

6737200054673-720-00-54 SEAL WINDOW 1  
A1834388002MOLD L/H 1  
A1834388003MOLD R/H 1



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

\* **ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V40883**

In Date: 05/26/2011  
Close Date: 06/07/2011

Meter Reading: 109,890.00

**Problem?**

A inspection.

**Task performed:**

1. A-Inspection 2. R/R rear tires. 3. Chk rear A/C for leaks; tighten schrader, vac sys & recharge. 4. Redrill & tap L-3 compt hinge mntng bolts. 5.Rem & reinstall rear window seals. j

Parts	Quantity
52-24WIPER BLADES ANCO 24	2

**Workorder: V40897**

In Date: 05/26/2011  
Close Date: 06/08/2011

Meter Reading: 109,757.00

**Problem?**

REPLACE TEAR TIRES

**Task performed:**

Replace rear tires - Boulevard j

Parts	Quantity
NO PARTS USED	

Vendor? BOULEVARD

**Workorder: V41250**

In Date: 06/10/2011  
Close Date: 06/10/2011

Meter Reading: 110,486.00

**Problem?**

A inspection.

**Task performed:**

A-Svc. 2. Rep air horns. 3. Top off washer lfuid; replc A/C filter. 4. Replc door handle on med door. j

Parts	Quantity
78R536078R5360M 2PK FILTER AIR COND	1
LTC5993SSM1-63-8 LATCH STAINLESS	1



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V41829**

In Date: 07/06/2011  
Close Date: 07/14/2011

Meter Reading: 23,774.00

**Problem?**

A inspection.

**Task performed:**

A-Service 2. Rebuild both air horns; new kits & adj. 3. Replc wiper blades & fill washer fluid. 4. Rep street horns. 5. Chk/rep wires & replc back-up camera. 6. Replc (2) latches on rear compt in rear. 7. Chk/replc both A/C fans under truck. 8. Sand/cln fuel cap & paint. 9. Adj all tire press; R/rear inside ext leaking; replc. 10. Lube all door locks - sticking. 11. Replc L/frnt tire w/used good tire. j

Parts	Quantity
1094KIT-AIR HORN-GROVER	2
52-24WIPER BLADES ANCO 24	2
60027FAN A/C COND 12IN 860026-2-W	2
CVM680LCDLCD MONITOR SCREEN	1

**Workorder: V42246**

In Date: 07/23/2011  
Close Date: 07/25/2011

Meter Reading: 3,220.00

**Problem?**

rear door wont fully closed R51

**Task performed:**

REAR DOOR IN PATIENT COMPT. WONT CLOSE / LATCHES OUT OF TIME / ADJUSTED DOOR LATCHES OK AK

Parts	Quantity
NO PARTS USED	

**Workorder: V42434**

In Date: 08/01/2011  
Close Date: 08/03/2011

Meter Reading: 111,643.00

**Problem?**

A inspection.

**Task performed:**

A INSPECTION FILL W/WAHSER RESERVOIR ADD AIR TO LOW TIRE: AK

Parts	Quantity
47153582-2116 TOGGLE SW ON/OFF	1



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V42278**

In Date: 07/25/2011  
Close Date: 08/12/2011

Meter Reading: 1,111,423.70

**Problem?**

replace tire

Parts

Quantity

**Task performed:**

Replace tire - Boulevard j

NO PARTS USED

Vendor? BOULEVARD

**Workorder: V42809**

In Date: 08/15/2011  
Close Date: 08/17/2011

Meter Reading: 112,676.00

**Problem?**

A inspection.

Parts

Quantity

**Task performed:**

A INSPECTION REPAIRED BROKEN STEP AT DRIVER'S DOOR  
REPAIRED AIR LEAK MAIN VALVE LEAK REPLACED

NO PARTS USED



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V43604**

**In Date:** 09/12/2011

**Meter Reading:** 114,191.00

**Close Date:** 09/21/2011

**Problem?**

**B INSPECTION SR 10**

**Task performed:**

B INSPECTION AIR BAGS DAMAGE REMOVE TO INSTALL NEW AIR BAGS CAB A/C FILTER SERVICE PASSENGER SIDE MIRROR LOOSE SECURE LOOSE MIRROR MODULAR BODY FOOR PANELS LOOSE SECURE ALL LOOSE DOOR PANEL SCREWS L REAR CAB WINDOW MOLDING SCREWS TO CLIP FELL OUT REPLACE MISSING SCREW AND MOLDING CLIP R REAR WINDOW MOLDING BROKEN REMOVE AND INSTALL NEW WINDOW MOLDING PT. COMPT. CABINET WILL NOT LATCH ADJUST STRIKER TO SECURE L3 DOOR HOLD OPEN MOUNT LOOSE SECURE LOOSE BOLTS AND MOUNT A/C LINE HAD OIL CHECK SYSTEM PRESSURE LOW ON FREON VACUME SYSTEM CHECK FOR LEAK CLEAN LINES CHARGE SYSTEM AND OPERATE TEMP OUTLET AT 28 DEGREES

Parts

Quantity

000090155133634 FUEL FILTER WIX MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES	1
16-15762-00016-19471-000 AIR BAG	2
78R536078R5360M 2PK FILTER AIR COND	1
A1834388003MOLD R/H	1
R90PFILTER FUEL 33231	1

**Workorder: V43697**

**In Date:** 09/15/2011

**Meter Reading:** 114,191.00

**Close Date:** 09/21/2011

**Problem?**

**REPLACE FRONT TIRES BLVD. sr 15**

**Task performed:**

outside agency

Parts

Quantity

NO PARTS USED

**Vendor?** BOULEVARD





4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V43556**

In Date: 09/09/2011

Meter Reading: 114,035.00

Close Date: 09/23/2011

**Problem?**

Pt comartment camera not working Sta 53 Rescue

Parts

Quantity

**Task performed:**

NO PARTS USED

**Workorder: V43885**

In Date: 09/23/2011

Meter Reading: 114,776.00

Close Date: 10/03/2011

**Problem?**

A inspection.

Parts

Quantity

**Task performed:**

a inspection found left front tire valve core leaking r&r core infalste tire ck ok found no right turn signal ck flasher ck ok, trouble shoot and repair connection at switch ck ok

NO PARTS USED



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V45327**

**In Date:** 11/21/2011  
**Close Date:** 12/01/2011

**Meter Reading:** 119,274.00

**Problem?**

A inspection.

**Task performed:**

a inspection diagnose coolant leaks found upper rad tank cracked air tires to proper psi, If valve core broken, drill core and extract core, replaced core and air tire charge batteries drain coolant and remove leakin grad, new rad on order, strip down rad, install frame brakets from old rad onto new rad and change over cool air charge rad, some modifications necessary to install frame brackets onto new rad and trans oil cooler fittings needed to be modified replace all four batteries, reapiir broken hold hown brakes and repalce wire connectos on three ends battery drawer very hard to open, wash and clean out drawer in slide rails spray with wash out again and lube work drawer again to free

Parts	Quantity
396635HOSE & FITTING	1
404-100 VALVE CORE	1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER B/	4
BHT-B0184USE F10 RADIATOR	1
HP-31DBATTERY 950CCA HP-31D	4

**Workorder: V45950**

**In Date:** 12/19/2011  
**Close Date:** 12/22/2011

**Meter Reading:** 31,909.80

**Problem?**

A inspection.

**Task performed:**

A-INSPECTION. AIM W/WASHER NOZZLES. TIGHTEN ALL BATTERY CABLES. REPAIR TURN SIGNAL SWITCH COVER. R&R DRAWER TRACK AND SLIDE REPAIR MOUNTING HOLES. DIAGNOSE COMPT OPEN WARNING LT. IN CAB NOT WORKING. R&R LIGHT ASSY IN CAB. TEST SYSTEM AGAIN FOUND 3 DOORS NOT SETTING ALARM AND LT. ON R&R 3 DOOR SWITCHES. REPAIR 110V A/C PANEL ON CEILING OF PATIENT AREA.

Parts	Quantity
50R03ZRRRLIGHT 500 TIR LED	1
91822OBSOLETE USE SERV TKS SWITCH - DOOR	3
91823SWITCH SWT5499 MED MASTER	2
SLD5366HT4932-16 DRAWER SLIDE 16	1



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V45815**

In Date: 12/12/2011  
Close Date: 01/03/2012

Meter Reading:

**Problem?**

medical drawer needs to be replaced, R56

**Task performed:**

REPLACED LOCK ON DRAWER REPLACED 110 CORD PLUG

Parts	Quantity
5-20PH1PGK4 CONNECTOR 120V 20A FEMALE	4
5632-1010 IN DRAWER SLIDES PR	2

**Workorder: V46446**

In Date: 01/09/2012  
Close Date: 01/09/2012

Meter Reading:

**Problem?**

Door Open Alarm is going off intermittentlysr at 45

**Task performed:**

1. check door ajar alarm going off, found d/side rear cab door switch bad.  
replace switch

Parts	Quantity
91823SWITCH SWT5499 MED MASTER	1

**Workorder: V47160**

In Date: 02/07/2012  
Close Date: 02/09/2012

Meter Reading: 33,996.50

**Problem?**

replace 4 rear tires

**Task performed:**

REPLACE 4 REAR TIRES.

Parts	Quantity
NO PARTS USED	

**Vendor?** BOULEVARD TIRE CENTE



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V46380**

**In Date:** 01/06/2012  
**Close Date:** 02/16/2012

**Meter Reading:** 32,271.00

**Problem?**

A inspection.

**Task performed:**

1. A-SERVICE, 2. INSTALLED TRANS INTERLOCK SWITCH IN DASH 3  
INSTALL NEW WIPER BALDES - FLUID. 4. ADJUST ALL TIRE  
PRESSURE 5. WATER IN HEAD LIGHT, INSTALLED SENSOR AND  
DASH BOARD. 6. INSTALLED NEW U V LIGHT ASSEMBLE IN REAR  
A/C. 7. REPLACE OVER HEAD FLOOR LIGHTS. 8. REPAIR COOLANT  
LEAK. 9. INSTALLED MISSING LUG CAP. 10. R&R LEFT SIDE TOP  
MARKER LIGHT AND REAR A/C FILTER. 11. REPLACE A/C  
COMPRESSOR TO REAR A/C SYSTEM BAD BEARING AND CLUTCH  
ASSEMBLE, PUMP DOWN AND REMOVE AND REPLACE VAC AND  
CHARGE SYSTEM.

Parts	Quantity
532703-0602 COMPRESSOR U4735 4471	1
78R536078R5360M 2PK FILTER AIR COND	1
A2249250001 A22-49250-003 CLUSTER ASSY	1
CLR9185209186-1500-20 MARKER LT.AMBER LED	1
RAIRK30880N122WSKL4000 SENSOR WATER IN FU	1
SWT54917SW ROCKER DPDT ON-ON RED	1
SWT5492744435 ACTUATOR-BLACK	1
U-24RWIPER REFILL	1
UVAPS253 UNIT UV LIGHT A/C RESCUES	1

**Workorder: V47538**

**In Date:** 02/24/2012  
**Close Date:** 03/02/2012

**Meter Reading:** 122,385.30

**Problem?**

A inspection.

**Task performed:**

1. A-SERVICE SR-15 2. CHECK AND REPLACE LIGHT IN OVER HEAD  
REAR COMPARTMENT. 3. ADJUST ALL TIRES PRESSURE.

Parts	Quantity
322502BULB PATIENT GH22	1



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V47686**

In Date: 03/01/2012  
Close Date: 03/07/2012

Meter Reading: 122,961.00

**Problem?**

A inspection.

**Task performed:**

1. CHECK OUT LIGHTS AND A/C AND TIRE PRESSURE. 2. INSTALL TRACKS ON DRAWER IN THE COMPARTMENT.

Parts	Quantity
SLD5366HT4932-16 DRAWER SLIDE 16	2

**Workorder: V48183**

In Date: 03/26/2012  
Close Date: 04/02/2012

Meter Reading: 123,873.00

**Problem?**

A inspection

**Task performed:**

1. A-SERVICE SR-15- 2. R&R RIGHT FRONT TIRE AND BRAKE DRUM, CLEAN BACKING FROM GREASE AND OIL REPLACE GREASE OIL SEAL REINSTALLED BRAKES AND ADJUST REASSAMBLE ACE. ADJUST ACE TIRE PRESSURE. 3. R&R DOOR PANEL, CHECK OUT LIGHT NOT WORKING, FOUND SWITCH BROKEN REPLACE WITH NEW ALSO REPLACE OUTSIDE DOOR HANDLE BROKEN REINSTALLED ALL PARTS OK. 4. CHECK AND REPAIR AIR LEAK IN TURBO CHARGER SYSTEM 5. ADJUST DOOR LATCHES IN REAR COMPARTMENT. 6. REPLACE OVERHEAD LIGHTS IN REAR COMPARTMENT.

Parts	Quantity
322502BULB PATIENT GH22	1
370001ASEAL 35066	1
923182-2151 SWITCH MOMENTARY 24-372	1
HND5948TM22676-02 HANDLE DOOR ENTRY	1



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V48533**

In Date: 04/09/2012  
Close Date: 04/10/2012

Meter Reading: 3,289.00

**Problem?**

rear doo of pt compartmentr will not open from inside. R15

Parts ----- Quantity -----

**Task performed:**

TRAVEL TO ST 15 CHECK OUT REAR DOORS PULL DOOR APART  
PULL WINDOWS REMOVE OUTER HANDLE ADJUST AND INSTALL  
ADJUST DOOR LATCHES AND LUBE SYSTEM ADJUST INSIDE LATCH  
OK.

NO PARTS USED

**Workorder: V48632**

In Date: 04/12/2012  
Close Date: 04/13/2012

Meter Reading: 2,452.50

**Problem?**

a inspection

Parts ----- Quantity -----

**Task performed:**

1. A-INSPECTION. 2. CAB-ROOF CLEARANCE LIGHTS - INOP.  
REMOVE ALL FIVE LENSES - ALL BULBS BURNT OUT; REPLACE  
BULBS AND REINSTALL COVERS. 3. L/SIDE WIPER ARM BENT -  
REMOVE ARM AND STRAIGHTEN BENT ARM.

NO PARTS USED



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V48478**

**In Date:** 04/06/2012

**Meter Reading:** 123,873.00

**Close Date:** 04/25/2012

**Problem?**

stretcher issue

**Task performed:**

REMOVED IV POLE SO STRETCHER WOULD LOCK INTO PLACE.

Parts

Quantity

000090155133634 FUEL FILTER WIX	MERCEDES	1
0001801709OIL FILTER 03 57215 WIX	MERCEDES	1
01-29866-118BELT ALT. M2		1
107796DRYER KIT AD9 -NEW		1
107800VALVE CHECK AD9		1
800405PURGE VALVE KIT		1



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

\* **ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V48898**

**In Date:** 04/25/2012

**Meter Reading:** 127,075.60

**Close Date:** 05/11/2012

**Problem?**

**A INSPECTION SR 15**

**Task performed:**

1. A-INSPECTION. 2. REPLACE LEAKING VALVE CORE IN R/Front TIRE. 3. STARTER DRAGS - SLOW STARTING - REPLACE STARTER ASSEMBLY - NOTE: HAD TO REMOVE POSITIVE BAT CABLES ROUTED BEHIND STARTER TO GAIN ACCESS TO REAR BOLTS. 4. DRIVER'S DOOR PANEL FALLING OFF - REDRILL BOTTOM SECTION AND RETAIN WITH SHEFT METAL SCREWS - REINSTALL PLASTIC CLIPS ON BACK SIDE OF PANEL AND RESECURE. 5. AIR SYSTEM VERY SLOW IN RECOVERY - CHECK OUT AND DIAGNOSE - REMOVE SPLIT TANK AND REPLACE WITH NEW - REPLACE CHECK VALVE ON PRIM. TANK AND ONE PROTECTION VALVE - ASSEMBLE ALL REMOVED AIR LINES AND ROAD TEST. 6. CAB A/C BLOWS COOL - CHECK OUT SYSTEM - FOUND SMALL LEAK FROM LOW SIDE A/C LINE INSIDE L/SIDE CONDENSOR/FAN ASSEMBLY - REMOVE STEP, UNBOLT FOR ACCESS TO INTERNAL PARTS - REPLACE BAD HOSE AND DRYER - REASSEMBLE COMPLETE COND/FAN ASSEMBLY - ALSO REPLACE DRYER FOR FRONT UNIT NOT REPLACE SINCE S00 - VACUUM DOWN SYSTEM - RECHARGE AND RETEST WITH SNIFFER.

**Parts**

**Quantity**

103385NDRAIN COCK	1
190114036842 29MT 9 TOOTH STARTER	1
223-485V91-8301 85 PSI CLOSED 67 OPEN PREEES	1
408322HOSE & FITTING	1
5004049GOV CHK VALVE KIT M2	1
6804320901AIR TANK	1
716907-0610A DRYER	1
800376 VALVE CHECK 90 DEG	1
RD-5-7063-OP07-2618A A/C DRIER 7155	1





4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V49348**

**In Date:** 05/15/2012  
**Close Date:** 05/16/2012

**Meter Reading:** 127,075.60

**Problem?**

check brakes

**Parts**

**Quantity**

NO PARTS USED

**Task performed:**

CHECK FRONT AND REAR BRAKES AND ADJUST TAKE ON LONG TEST DRIVE; OK AT THIS TIME.

**Workorder: V46097**

**In Date:** 12/27/2011  
**Close Date:** 06/05/2012

**Meter Reading:** 120,808.00

**Problem?**

C INSPECTION AND REPAIRS R 300

**Parts**

**Quantity**

000090155133634 FUEL FILTER WIX MERCEDES	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES	1
1501450007750USE 0775145	1
15W40BSYN OIL BULK QTS	26
607141-05USE 61H01 COPMPARTMENT LIGHT	1
HLD3999GSS1715UV 30LB STRUT GAS	2
R90PFILTER FUEL 33231	1

**Task performed:**

1. C-INSPECTION. 2. ASSIST MAC. 3. TIRE TRENDS DEPTL LOW - SERVICE DEFERRED AS PER EE. 4. FRONT LEFT SPRING MOUNT BOLTS LOOSE - SECURE LOOSE NUT AND BOLTS TORQUE AS BES AS POSSIBLE. 5. FRONT LEFT SIDE BUMPER SUPPORT BRACKET NUT AND BOLTS LOOSE - RETORQUE NUTS AND BOLTS. 6. OFFICERS DOOR LIGHT 10-7 - REMOVE BLOWN LED LIGHT. ASSEMBLY AND INSTALL NEW REPLACEMENT. 7. PACENT COMP. A/C FILTER DIRTY - REMOVE AND INSTALL NEW FILTER. 8. PACENT COMP LINNEN CABINET DOOR STRUT WEAK - REMOVE AND INSTA 2 NEW STRUTS. 9. LEFT FRONT TIRE VALVESTEM LEAKING - INSTALL NEW 3 INCH VALVE STEM EXTENCION AND AIR TIRE TO 11 PSI. 10. PACENT COMP LATCH INOP - ADJUST LATCHING PIN ON COMPARTMENT CABINET.



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

\* **ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V49857**

In Date: 06/04/2012  
Close Date: 06/05/2012

Meter Reading: 124,931.00

**Problem?**

low power

Parts

Quantity

NO PARTS USED

**Task performed:**

WENT TO P.G.A. AND TURNPIKE - CHECK SO 34 RESCUE FOR LOW POWER FOUND TURBO HOSE CLAMP BROKEN - REPLACED CLAMP AND INSTALLED HOSE - CHECK OK - RETURN HOME.

**Workorder: V50476**

In Date: 06/29/2012  
Close Date: 07/05/2012

Meter Reading: 247,084.00

**Problem?**

A INSPECTION SR 15

Parts

Quantity

607141-05USE 61H01 COPMPARTMENT LIGHT	2
78R536078R5360M 2PK FILTER AIR COND	1
HLD3999GSS1715UV 30LB STRUT GAS	2

**Task performed:**

1. A-INSPECTION. 2. FABRICATE CAB AUX A/C FILTER GURD. INSTALLNEW FILTER AND GUARD. 3. REPAIR 3 MEDICAL COMPARTMENT DOORS. ADJUST STRIKERS LUBE LATCHES REPLACE 2 HOLD OPENS AND R&R ONE STRIKER TO BEND BACK II TO SHAPE. 4. LUBE AND ADJUST SIDE ENTRY DOOR HINGE. 5. R&R COMPARTMENT L-4 LIGHT ASSY AND BOOT. ALSO REMOVE BROKE PINS IN CONNECTOR FROM OLD LIGHTS. 6. SQUAD BENCH DOESN LATCH CLOSED. R&R STRIKER AND LUBE LATCH HAD TO DRILL NEW HOLES. NEW STRIKER DIFFERENT THAN ORIGINAL.



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V50741**

**In Date:** 07/10/2012  
**Close Date:** 07/10/2012

**Meter Reading:**

**Problem?**

Patient compartment A/C went out stopped blowing cold air during a transport to North Broward Hospital. This is the rescue we switch into this morning

Parts ----- Quantity -----

**Task performed:**

1. check pat. a/c , hook up gauges, low on freon, replace 1lb freon recheck and run for 1/2 hour cools to 43deg.

NO PARTS USED

**Workorder: V51079**

**In Date:** 07/24/2012  
**Close Date:** 08/03/2012

**Meter Reading:** 125,913.00

**Problem?**

FLAT TIRE R 55

Parts ----- Quantity -----

**Task performed:**

1. NAIL IN FRONT LEFT TIRE - CALL BOULEVARD TIRE. FLAT TIRE R-55

NO PARTS USED

**Vendor?** BOULEVARD TIRE CENTE



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V51439**

In Date: 08/07/2012  
Close Date: 08/09/2012

Meter Reading: 125,913.00

**Problem?**

A INSPECTION SR5

**Task performed:**

1. A-INSPECTION. 2. L-2 TOOL HOLDER BROKEN, REAR PATIENT DOOR NATER PIN COVER - REPLACE BROKEN TOOL HOLDER AND NATER PIN COVER SECURE COAT HOOK. 3. CAB TO MOD MOLDING FALLING OFF - REMOVE AND RETAG NEW ANCHORING HOLES, REMOUNT AND SECURE. 4. LEFT SIDE OF MODULAR BOX HAS SCRAPES AND SCRATCHES NOTIFIED FOREMAN.

Parts ----- Quantity -----

5269LPVM-5 SM MOUNT	1
---------------------	---

**Workorder: V51934**

In Date: 08/27/2012  
Close Date: 09/11/2012

Meter Reading:

**Problem?**

The outer skin of the left side rear compartment door is seperating from the door itself at the top.. SR AT 24

**Task performed:**

1. SECRED DOOR SKIN- DRILLED TAPPED AND INSTALLED BOLTS TO SECURE DOOR SKIN.

Parts ----- Quantity -----

NO PARTS USED	
---------------	--



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V51715**

In Date: 08/20/2012  
Close Date: 09/17/2012

Meter Reading: 126,670.00

**Problem?**

ON CALL R 24 STUCK

Parts

Quantity

**Task performed:**

GO TO SCENE TO SEE IF TRUCK WAS OUT OF SERVICE FOR DAMAGES TRUCK OK, WAIT FOR WEST TO LIFT TRUCK OUT OF SIM HOLE OK FOR SERVICE.

NO PARTS USED

**Workorder: V51775**

In Date: 08/21/2012  
Close Date: 09/17/2012

Meter Reading: 127,114.50

**Problem?**

REAR PATIENT A/C BLOWING WARM AND SEAT AIR LEAK. R24

Parts

Quantity

**Task performed:**

1. CLEANED OUT CONDENSER FOR REAR A/C AND CHKD FOUND OK. 2. REMOVED OFFICERS SEAT AND REPAIRED AIR LEAK.

NO PARTS USED

**Workorder: V52292**

In Date: 09/10/2012  
Close Date: 09/26/2012

Meter Reading: 249,872.90

**Problem?**

B INSPECTION OIL CHANGE SERVICES

Parts

Quantity

**Task performed:**

B INSPECTION OIL CHANGE SERVICES

NO PARTS USED

Vendor? OIL CHANGE SERVICES



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

\* **ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V52740**

In Date: 10/01/2012  
Close Date: 10/02/2012

Meter Reading: 129,585.90

**Problem?**

NO AIR PRESSURE

Parts \_\_\_\_\_ Quantity \_\_\_\_\_

**Task performed:**

TRACED OUT PROBLEM WITH TRUCK - RAN TRUCK BUILT UP PRESSURE ROAD TESTED AND ROAD TESTED OK.

NO PARTS USED

**Workorder: V52615**

In Date: 09/25/2012  
Close Date: 10/04/2012

Meter Reading: 129,197.20

**Problem?**

Spare R24: Have noticed some uneven tire wear on both front tires. Located at Station 24.

Parts \_\_\_\_\_ Quantity \_\_\_\_\_

**Task performed:**

TRAVEL TO 24 CHECKED FRONT TIRES THEY STILL HAVE LIFE WILL MONITOR.

NO PARTS USED

**Workorder: V54327**

In Date: 12/10/2012  
Close Date: 12/10/2012

Meter Reading: 1,336,306.00

**Problem?**

ON CALL DOOR ALRM GOING OFF R 24

Parts \_\_\_\_\_ Quantity \_\_\_\_\_

**Task performed:**

WENT TO 24 FOUND REAR COMPARTMENT SETTING- OFF ALARM, CLEARED AND ADJUSTED SW, CHK OK, R&R STRETCHER LOCK-TOPPED OFF PAT A/C SYSTEM- CHK OK RETURN HOME.

090-0278STRECHER BAR NEW 1



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V54291**

In Date: 12/07/2012  
Close Date: 12/19/2012

Meter Reading:

**Problem?**

REPLACE TIRES

Parts

Quantity

**Task performed:**  
REPLACE TIRES.

NO PARTS USED

**Vendor?** BOULEVARD TIRE

**Workorder: V54788**

In Date: 01/03/2013  
Close Date: 01/04/2013

Meter Reading: 134,791.80

**Problem?**

A INSPECTION

Parts

Quantity

**Task performed:**

1. A INSP AND INFLATE ALL TIRES TO 110PSI. 2. R&R WIPER BLADES. 3. R&R PATIENT CEILING LENS AND BULB. 4. DISCHARGE A/C SYSTEM (REAR) CHECK AMT REMOVED. EVACUATE AND RECHARGE SYSTEM. TEST RUN AND CHECK TEMP. 5. FOUND SCHRADER VALVE LEAKING IN A/C SYSTEM DISCHARGE SYSTEM R&R BOTH SCHRADER VALVES- ONE VALVE TUCK IN BORE WOULD NOT COME OUT- EXTRA TIME-GOT BROKEN PRECENT EVACUATE AND RECHARGE SYSTEM.

16-31438915 VALVE CORE A/C 3544706C1	2
322502BULB PATIENT GH22	1
52-24WIPER BLADES ANCO 24	2



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V54250**

In Date: 12/06/2012  
Close Date: 01/17/2013

Meter Reading:

**Problem?**

Install SCBA bracket in driver compartment. It is currently just hanging on a hook. Reported by (JMAKI). R24

Parts ----- Quantity -----

**Task performed:**

ALL SCBA'S ARE MOUNTED.

21481SEARCHLIGHT CONTROL	1
--------------------------	---

**Workorder: V55164**

In Date: 01/19/2013  
Close Date: 01/22/2013

Meter Reading:

**Problem?**

MDT not working after reboot, and calling Dispatch to reset and reboot again. Router/modem and MDT also rebooted, still not working. MDT Asset #10182076 R31 Assest # 10154110

Parts ----- Quantity -----

**Task performed:**

forwarded to radio shop

NO PARTS USED	
---------------	--





4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V55558**

In Date: 02/05/2013  
Close Date: 02/07/2013

Meter Reading: 135,329.60

**Problem?**

A inspection

**Task performed:**

1. A-INSPECTION. 2. DURING A INSPECTION FOUND REAR BRAKES BAD CHANGED PADS AND DRUMS.

Parts	Quantity
3744BRAKE DRUM REAR	2
KSMA3124710QKSMA3124710QP REAR BRAKE SHC	2
S690AIR CHUCK	1
S693AIR CHUCK	1
S777COUPLING NIPPLE	2

**Workorder: V56371**

In Date: 03/13/2013  
Close Date: 04/10/2013

Meter Reading: 14,656.70

**Problem?**

O2 system leak SR @ ST47

**Task performed:**

1. TRACED OUT O2 LEAK AND REPAIRED. 2. ADJUSTED REAR ENTR DOOR THAT WAS HARD TO OPEN.

Parts	Quantity
NO PARTS USED	

**Workorder: V55937**

In Date: 02/22/2013  
Close Date: 04/11/2013

Meter Reading: 14,656.70

**Problem?**

A inspection

**Task performed:**

1. A-INSPECTION. 2. ADJUST AIR HORNS. 3. PULL DOWN AND RECHARGE A/C CHECK FOR LEAKS. 4. ADJUST AIR BAGS.

Parts	Quantity
NO PARTS USED	



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## 10154110

### \* ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V57147**

In Date: 04/19/2013  
Close Date: 04/23/2013

Meter Reading: 138,432.00

**Problem?**

replace flat tire

**Task performed:**  
REPLACE FLAT TIRE.

**Vendor?** BOULEVARD TIRE CENTE

Parts	Quantity
297518265/70R19.5 BRIDGESTONE R250	1

**Workorder: V57704**

In Date: 05/13/2013  
Close Date: 05/22/2013

Meter Reading: 138,432.00

**Problem?**

C inspection SR15

**Task performed:**

1. C INSP. 2. ADJ ALL TIRE PRESSURE TO 110PSI. 3. TIGHTEN BOTH FRT SHOCKS LOWER MOUNTING BOLTS. 4. R&R LENS R&R ON R/F FENDER MARKER LT. 5. R&R COOLANT TANK SIGHT GLASS. 6. DIAC AND REPAIR CAB DOOR LT R/R. RESPLICE AND SECURE HARNESS 7. R&R L.E.D INDICATOR PANEL ON BOARD BATT CHARGER. 8. R&F ALUMINUM NUMBER AND CAMPAIGN SIGN FRAMES. INSTALL NEW PLASTIC FRAMES. 9. OVERHAUL AD-9 DRYER CHECK VALVE AND R&R PURGE VALVE ASSY. 10. DIAG AND REPAIR COMPT DOOR OPEN SYSTM ON VEH R&R COMPT WARN LT. 11. REMOVE ACREDITATION STICKER FROM VEH. 12. Q.C TRUCK.

Parts	Quantity
000090155133634 FUEL FILTER WIX MERCEDES	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES	1
032-0116549297 BATTERY INDICATOR	1
107796DRYER KIT AD9 -NEW	1
107800VALVE CHECK AD9	1
15W40BSYN OIL BULK QTS	26
50R00FRRFLASHER RED LED FLANGED	1
800405PURGE VALVE KIT	1
CA8193AIR FILTER 46744 WIX	1
L PLACARDLARGE SIDE PLACARD	2
R90PFILTER FUEL 33231	1
VML-T1413T3248 SIGHT GLASS	1



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V58508**

In Date: 06/18/2013  
Close Date: 06/24/2013

Meter Reading: 17,264.90

**Problem?**

a/c blower motor inop

**Task performed:**

CLEANED CONDENSER FANS AND TESTED UNIT. TESTED OK.

Parts	Quantity
60027FAN A/C COND 12IN 860026-2-W	2
UNT1400BLOWER MTR. + SQU IRREL CAGE ASSY.	1

**Workorder: V59008**

In Date: 07/11/2013  
Close Date: 07/11/2013

Meter Reading:

**Problem?**

AC ON THE FRONT CAB OF R41 IS OUT.

**Task performed:**

1. check cab a/c, eveacute system, low on freon, also found red dot condenser fans inop. check fuse, ok, remove side step under cab, remove both fansand motors , install new fan motors, reinstall step. top off freon and check for leaks, both scharder valves leaking, install new valves, vac. system down and recharge, recheck for leaks, none found 2. O2 bottle leaking down, spray with soap and water, found solinoid leaking remove and install thread tape, recheck for leaks, none found

Parts	Quantity
RD571290 01-2616 MOTOR 12V 73R-0542 3512	2



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V58456**

In Date: 06/15/2013  
Close Date: 07/19/2013

Meter Reading: 17,142.00

**Problem?**

Pt's compartment AC blowing warm air. R31

Parts ----- Quantity -----

**Task performed:**

RECHARGED SYSTEM AND REPAIRED LEAK.

NO PARTS USED

**Workorder: V59173**

In Date: 07/17/2013  
Close Date: 07/22/2013

Meter Reading: 140,117.00

**Problem?**

A-inspection

Parts ----- Quantity -----

**Task performed:**

1. A-INSPECTION; INSTALL REPLACEMENT POWER/VOLUME CONTROLE BUTTON FOR FIREMAN RADIO. 2. ROOF TOP SPOT LIGHT INOP - CHECK FUSE NO POWER. REMOVE CENTER CONSOLE COVER - FOUND POSITIVE LEAD DISCONNECTED CHECK FOR POWER ON WIRE AND RECONNECT - OPERATE LIGHT. 3. PATIENT SIDE DOOR REFLECTOR BROKEN - REMOVE DAMAGE REFLECTOR CLEAN SURFACE - INSTALL NEW REFLECTOR. 4. L-2 COMPT. TOOL HOLDER DAMAGE - REMOVE TOOL HOLDER - RETAP MOUNTING HOLE AND INSTALL TOOL HOLDER. 5. DRIVER WINDOW MOLDING - L/REAR DOOR PANEL LOOSE - SECURE DOOR PANEL WITH REPLACEMENT RIVIT AND SIRENS - REMOVE BROKEN MOLDING AND INSTALL NEW WINDOW MOLDING. 6. WATER PIN COVER - DRILL HOLES IN NEW PIN - REMOVE DAMAGE PIN - INSTALL NEW PIN COVERS. 7. R-2 TRAY FALLING OUT - REMOVE HOLD DOWN BOLT REALIGN AND SECURE TRAY.

98003RREFLECTOR RED 40132 GROTE	1
A1834388002MOLD L/H	1
LPVM-7LG MOUNT	1



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V60028**

In Date: 08/26/2013  
Close Date: 08/26/2013

Meter Reading: 221,720.00

**Problem?**

R36 park brake switch faulty

Parts ----- Quantity -----

**Task performed:**

WENT TO 36 FOUND TRANS KEYPAD BLINKING - TROUBLESHOOT AND REMOVE DASH PANELS - REPAIR CONNECTIONS AT PARK VALVE SENDING UNIT. MOVED CHAIN AND CALPON ENGINE.

NO PARTS USED

**Workorder: V60471**

In Date: 09/12/2013  
Close Date: 09/16/2013

Meter Reading: 142,317.00

**Problem?**

Get rescue ready for swap out

Parts ----- Quantity -----

**Task performed:**

A-INSPECTION.

NO PARTS USED

**Workorder: V60884**

In Date: 09/30/2013  
Close Date: 10/11/2013

Meter Reading: 142,317.00

**Problem?**

A inspection SR15

Parts ----- Quantity -----

**Task performed:**

1. A-INSP. 2. REPAIRS WIRES TO START TO STREET. HORN CUT OPEN FOUND BAD WIRES REPAIR AND REPLACE BOTH HIGH AND LOW HORN, CHECK ALL RELAYS AND LINES CLEAN AS NEEDED. 3. TOP OFF ALL FLUIDS PLS/ COOLANT/ TRANS/ ENG ECT. 4. REPLACI REAR A/C FILTER VERY BAD REPLACE WIPES BLADES.

78R536078R5360M 2PK FILTER AIR COND	1
91-22WIPER BLADE	2
A0631117000HORN HIGH NEW # 06-52125-039	1
A0631117003HORN LOW NEW #06-52125-041	1



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

\* **ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V61558**

In Date: 10/27/2013  
Close Date: 10/30/2013

Meter Reading:

**Problem?**

left headlight out R231

Parts ----- Quantity -----

**Task performed:**

TRAVEL TO DRIVER COMPLAINT HEADLIGHT OUT R&R HEADLIGHT

H6054USE CV TYPE SEALED BEAM	1
------------------------------	---

**Workorder: V62598**

In Date: 12/09/2013  
Close Date: 12/16/2013

Meter Reading: 24,550.50

**Problem?**

Perform "A" inspection

Parts ----- Quantity -----

**Task performed:**

1. A INSP. 2. R&R R/S W/WASHER NOZZLE. TEST AND AIM NOZZLES  
3. R&R LENS R&R BULB AND INSTALL 3 MISSING SCREWS ON LENS  
FOR PATIENT CIELING LT. 4. DIAGNOSE AND REPAIR PATIENT  
CEILING FLOURESCENT LT. 5.R&R CAB AUX A/C FILTER. 6. R&R A/C  
FANBELT. HAD TO R&R FAN AND FAN CLUTCH AIRLINE TO R&R  
BELT. 7. COMPT R-1 WEATHERSTRIP- CLEAN ALL OLD ADHESIVE  
FROM DOOR AND WEATHERSTRIP. APPLY NEW ADHESIVE AND  
REATTACH WEATHER STRIP. 8. SOAP ENTIRE AIR SYSTEM TO LOO  
FOR AIR LEAKS- NO LEAKS FOUND.

322502BULB PATIENT GH22	1
78R536078R5360M 2PK FILTER AIR COND	1
9425BELT MERCEDES RESCUE 12.5X1075 OE	1
SPRGW2612WASHER NOZZLE W/RELIEF	1



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V62676**

In Date: 12/12/2013  
Close Date: 12/23/2013

Meter Reading: 24,550.50

**Problem?**

REPLACE REAR TIRES

Parts	Quantity
-------	----------

**Task performed:**  
REPLACE REAR TIRES.

NO PARTS USED

**Vendor?** BOULEVARD TIRE CENTE

**Workorder: V61815**

In Date: 11/05/2013  
Close Date: 12/31/2013

Meter Reading: 144,280.00

**Problem?**

A inspection

Parts	Quantity
-------	----------

**Task performed:**  
1. A-INSP. 2. CLEAN RIGHT SIDE OF DRESSER AND OIL ON ENGINE.  
3. L-2 DOOR REFLECTION BROKEN OFF- REMOVE PIECE AND  
INSTALL NEW REFLECTION. 4. STREAM LIGHT CHARGER THATS  
BROKEN- REMOVE CHARGER, REWIRE AND INSTALL NEW  
CHARGING STATION. 5. L-3&4 HOLD OPEN LOOSE, DOOR SLUNG  
LOOSE- SECURE LOOSE DOOR HOLD OPEN SUPPORT BRACKET  
AND HOOK, SECURE LOOSE DOOR SLUNG SCREWS. 6. CAB L/R  
BROKEN HOLDING BROKEN- REMOVE AND INSTALL NEW MOLDING

98003RREFLECTOR RED 40132 GROTE	1
A1834388002MOLD L/H	1



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

\* **ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V63131**

In Date: 01/04/2014  
Close Date: 01/27/2014

Meter Reading: 147,887.50

**Problem?**

Oil is below minimum R32

Parts ----- Quantity -----

**Task performed:**

CHECKED FOR LEAKS AND TOPPED OFF OIL

NO PARTS USED

**Workorder: V63811**

In Date: 01/29/2014  
Close Date: 01/31/2014

Meter Reading:

**Problem?**

Stretcher mount not remaining locked properly---will be bringing rescue to central shop this morning. R36

Parts ----- Quantity -----

**Task performed:**

STRETCHER LOCK INOP- REMOVE AND INSTALL NEW STRETCHER LOCK BAR.

090-0278STRECHER BAR NEW 1

**Workorder: V64477**

In Date: 02/23/2014  
Close Date: 03/19/2014

Meter Reading:

**Problem?**

Two overhead dome lights and action area light are out in the patient compartment area and need the bulbs replaced. R36

Parts ----- Quantity -----

**Task performed:**

REPLACED BULBS ND REPAIRED LIGHT SWITCH.

322502BULB PATIENT GH22 4





4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V64989**

In Date: 03/17/2014  
Close Date: 03/21/2014

Meter Reading: 151,991.80

**Problem?**

REPAIRS FROM B INSPECTION

**Task performed:**

1. BRAKES LOW- REPLACE BRAKES- WHEEL SEALS- SLACK ADJUSTERS. 2. DRIVER SEAT TORN/HEAD REST ON PAT BROKEN OFF REMOVED DRIER SEAT FOR REPAIR- REPAIRED PAD HEAD REST. 3. OIL LEAK-TURBO DRAIN LINE LOOSE AT ENGINE BLOCK TIGHTEN CLAMP. 4. A/C CLUTCH SHORT CYCLE. 5. REPLACED FIRE EXTINGUISHER BRACKET. 6. DOOR ALARM ALWAYS ON REAR STRETCHER DOOR SENSOR NO GOOD.

Parts	Quantity
03910030SWITCH COMPARTMENT DOORS	1
330-3024HUB COVER GASKET	2
370001ASEAL 35066	2
614836NUT SPINDLE TEMPER LOC	2

**Workorder: V64664**

In Date: 03/03/2014  
Close Date: 04/15/2014

Meter Reading: 152,283.00

**Problem?**

B inspection SR15 OCS

**Task performed:**

B inspection filter change

Parts	Quantity
000090155133634 FUEL FILTER WIX MERCEDES	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES	1
R90PFILTER FUEL 33231	1

Vendor? OCS



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

\* **ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V65872**

In Date: 04/22/2014  
Close Date: 04/22/2014

Meter Reading: 31,553.00

**Problem?**

replaced left front tire

Parts

Quantity

**Task performed:**

replaced left front tire

NO PARTS USED

Vendor? BOULEVARD TIRE

**Workorder: V65672**

In Date: 04/13/2014  
Close Date: 05/09/2014

Meter Reading:

**Problem?**

The front driver side tire of Rescue 45 has a screw in the tread. The air pressure is still good.

Parts

Quantity

**Task performed:**

REMOVED SCREW AND PUT TRUCK BACK IN SERVICE.

NO PARTS USED

**Workorder: V65155**

In Date: 04/07/2014  
Close Date: 05/15/2014

Meter Reading: 31,179.00

**Problem?**

battery switch inop, R-45

Parts

Quantity

**Task performed:**

1. battery switch inop, disconnect battery, remove switch, had to cut termnials, nuts were crossed thread, install new switch

75908SWITCH BATTERY MASTER 300A

1



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

\* **ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V65687**

In Date: 04/14/2014  
Close Date: 07/07/2014

Meter Reading:

**Problem?**

The rescue, 45 A, has a screw in the driver's side front tire

Parts

Quantity

**Task performed:**

REPAIRS COMPLETE ON TICKET V65872

NO PARTS USED

**Workorder: V67949**

In Date: 07/16/2014  
Close Date: 07/17/2014

Meter Reading:

**Problem?**

patient and cab AC blowing hot air now while sitting still running, gets cold when driving R19

Parts

Quantity

**Task performed:**

1.Travel to 19 driver complaint A/C inop. Broken bad for 110v A/C. None on truck will meet truck at training. 2.Travel to training site.Replaced blow broken on 110v system.

QO120GFIGFI CIRCUIT BREAKER 20 AMP

1

**Workorder: V67698**

In Date: 07/05/2014  
Close Date: 07/18/2014

Meter Reading:

**Problem?**

D/O side headlight is out. R53

Parts

Quantity

**Task performed:**

head light replaced head light. repaired rear step that wood not stay up.

NO PARTS USED



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V67946**

In Date: 07/16/2014  
Close Date: 07/21/2014

Meter Reading: 33,434.70

**Problem?**

REPAIR CAB A/C R55

Parts ----- Quantity -----

**Task performed:**

recharged a/c and tested ok. repaired rear door that was hard to open.

NO PARTS USED

**Workorder: V68059**

In Date: 07/21/2014  
Close Date: 07/21/2014

Meter Reading: 155,487.00

**Problem?**

pat a/c inop

Parts ----- Quantity -----

**Task performed:**

ck, system on visable leaks. charged unit ck, ok returned to services.

NO PARTS USED

**Workorder: V68288**

In Date: 07/30/2014  
Close Date: 08/01/2014

Meter Reading:

**Problem?**

A/C not blowing cold in patient compartment @55

Parts ----- Quantity -----

**Task performed:**

Cleaned AC condensor fans and ran truck. AC was blowing colder.

NO PARTS USED



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V67937**

In Date: 07/15/2014  
Close Date: 08/05/2014

Meter Reading:

**Problem?**

Patient compartment and cab AC running warm not cold. R55

Parts ----- Quantity -----

**Task performed:**  
WORK WAS COMPLETED

NO PARTS USED

**Workorder: V68038**

In Date: 07/19/2014  
Close Date: 08/05/2014

Meter Reading:

**Problem?**

right headlight out R55

Parts ----- Quantity -----

**Task performed:**  
REPAIRED HEAD LIGHTS.

NO PARTS USED

**Workorder: V68436**

In Date: 08/05/2014  
Close Date: 08/05/2014

Meter Reading: 34,427.00

**Problem?**

Siren inop spare @42

Parts ----- Quantity -----

**Task performed:**  
1. remove center console, check control head, check amp, remove r/side speaker and install new speaker

01-0862062-00CSIREN REAR SIDE	1
SD-210RXSIREN DRIVER SMALL	1



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

\* **ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V67552**

In Date: 06/30/2014      Meter Reading:  
Close Date: 08/06/2014

**Problem?**

R451 needs headlight bulb replaced.

Parts ----- Quantity -----

**Task performed:**  
WORK WAS COMPLETE ON W/O V67698

NO PARTS USED

**Workorder: V68676**

In Date: 08/14/2014      Meter Reading: 34,427.00  
Close Date: 08/15/2014

**Problem?**

Deliver to 57

Parts ----- Quantity -----

**Task performed:**  
drive sr15 from sta,42 to sta,57 and wait for ride back to sta,42 then come back to c/s

NO PARTS USED

**Workorder: V68893**

In Date: 08/23/2014      Meter Reading: 156,796.00  
Close Date: 08/29/2014

**Problem?**

Pt compartment A/C inop, blowing warm to hot air.

Parts ----- Quantity -----

**Task performed:**  
Recharge system and cleaned condensor fans and repaired connection on compressor.

NO PARTS USED



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V68951**

In Date: 08/26/2014  
Close Date: 08/29/2014

Meter Reading: 156,796.00

**Problem?**

Pt compartment A/C blows hot. No cold air.

**Task performed:**

1. Check patient A/C. Found unit cooling. Found 1 condensor fan not working properly. Recover freon. Remove and replace shrader cores. Remove and replace both condensor fans. Vaccum and charge system. Checked ok. 2. Check spot light inop. Remove and replace fuse on controller. Removed and repaired wire at controller. Remove and replace bulb. Check ok.

**Parts**

**Quantity**

16-31438915 VALVE CORE A/C 3544706C1	2
18753-0455H7935-1 SPOT LIGHT BULB SPT6008	1
60027FAN A/C COND 12IN 860026-2-W	2

**Workorder: V69033**

In Date: 08/29/2014  
Close Date: 08/29/2014

Meter Reading: 157,023.00

**Problem?**

rear cab a/c inop

**Task performed:**

Checked all connection and road tested. Could not get unit to fail. Checked pressure and all tested ok.

**Parts**

**Quantity**

NO PARTS USED

**Workorder: V68900**

In Date: 08/24/2014  
Close Date: 09/08/2014

Meter Reading:

**Problem?**

Diamond plate on drivers SCBA comp door is loose. R57

**Task performed:**

repaired diamont plate cover and repaired door. r&r latch on door and tested ok

**Parts**

**Quantity**

HA49102C2-32-15 LATCH NON LOCKING	2
-----------------------------------	---



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V69233**

**In Date:** 09/08/2014  
**Close Date:** 09/10/2014

**Meter Reading:** 157,023.00

**Problem?**

A inspection SR15

**Task performed:**

1. Preform "A" service. 2. Replaced all 4 batteries. (Load tested weak)  
3. Replaced wiper blades. 4. Replaced left and right front. Turn signal side marker light lenses. (broken) 5. Repaired right front headlight. (falling off) removed headlight straighten headlight bucket (bent). Reinstalled retainer spring. Replaced all screws with stainless and reassembled. Aimed headlights. 6. Replaced rear metal placard frame with plastic. 7. Replaced action area fluorescent light bulbs. (burnt out) 8. Replaced all fluorescent bulbs for floor lights in patient compartment had to remove and replace lights to check for power.

Parts	Quantity
91-22WIPER BLADE	2
91513AMBER LENS	2
BATTERY EPA TAX BATTERY EPA TAX \$1.50 PER B/	4
HP-31D BATTERY 950CCA HP-31D	4
S PLACARD FRONT AND BACK PLACARD	1

**Workorder: V68735**

**In Date:** 08/17/2014  
**Close Date:** 09/19/2014

**Meter Reading:**

**Problem?**

spot light on the roof will not turn on. Spot light will turn and osc. The fuses on the controller are intact. R57

**Task performed:**

TESTED LIGHTS AND TESTED OK. TRACED OUT AIR LEAK AND REPAIRED AT REAR AIR VALVES.

Parts	Quantity
NO PARTS USED	





4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V69777**

**In Date:** 09/30/2014

**Meter Reading:** 157,405.00

**Close Date:** 09/30/2014

**Problem?**

Check brakes

**Task performed:**

Travel to station. Check brakes - driver complaint. Inspected brakes and road tested OK.

Parts

Quantity

NO PARTS USED

**Workorder: V70190**

**In Date:** 10/16/2014

**Meter Reading:** 157,500.00

**Close Date:** 12/03/2014

**Problem?**

C inspection SR15

**Task performed:**

1. Unit dead-Jump start unit 2. "C" inspection 3. Battery not holding charge-Check charging system, alternator working-Cable and connection clean and secure. Install new battery. 4. 110 charger tripping-Diagnose fault, found charger tripping on full load. All wires and connectors secure-charger bad-remove and install new charger-operate full load system working normal. Fabricate new charge for charger and install. 5. Pt. comp. A/C filter and cab rear A/C filter dirty. Remove and install new filters. 6. Pt. comp. rear flourescent light inop-bulbs blown. Remove and install new bulb. 7. Tran. service oil filter 8. Power steering service oil and filter 9. Coolant service 10. Left side air bag not inflating-Adjust leveling valve and check for leak. Air bag not leaking on associated parts. 11. Back up alarm inop. test alarm found component defective and ground bad-Install new back up alarm and ground. 12. Pat. A/C cool-Diagnose fault-pressures good. Found e-core dirty and condensor fan clogged ,clean componets and check compartment temp. 28 degrees F 13. Right rear side marker light inop-Remove marker light assembly and install new assembly

Parts

Quantity

000090155133634 FUEL FILTER WIX MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES	1
0775145PANEL FILTER	1
0913912CHARGER 2000	1
15W40BSYN OIL BULK QTS	26
29526898 29548988 TRANS FILTER ALLISON	1
4758 TERM BOX	1
575BACKUP ALARM ECCO 107 DEC	1
78R536078R5360M 2PK FILTER AIR COND	1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER B/	4
CLR9185109186-1500-10 MARKER LT. RED LED	1
FG87904MFG3937557S FILTER P/S NEW STYLE	1
FGQ79699GASKET-P/S FILTER NEW STYLE	1
HP-31DBATTERY 950CCA HP-31D	4
R90PFILTER FUEL 33231	1



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V71207**

**In Date:** 11/25/2014  
**Close Date:** 01/06/2015

**Meter Reading:** 158,187.00

**Problem?**

A-inspection The rescue is leaning toward the driver's side. R23

**Task performed:**

Travel to 23, adjusted linkage for air bags 1. A inspection 2. Tighten and readjust leveling valve rods 3. Re-install rear window molding 4. Remove aluminum placard frames

Parts ----- Quantity

NO PARTS USED

**Workorder: V72170**

**In Date:** 01/09/2015  
**Close Date:** 01/16/2015

**Meter Reading:** 38,717.60

**Problem?**

air bag level

**Task performed:**

1. Found vehicle riding low on the L/R. Inspection showed L/R air suspension valve link broken and bent. Replaced valve link. Adjusted air suspension to correct and level height.

Parts ----- Quantity

S4334010032LEVEL KIT 1

**Workorder: V72505**

**In Date:** 01/21/2015  
**Close Date:** 01/21/2015

**Meter Reading:**

**Problem?**

Passenger mirror damaged, mirror needs to be replaced

**Task performed:**

replace broken mirror mount

Parts ----- Quantity

11133MIRROR MOUNT 1



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V67727**

In Date: 07/07/2014

Meter Reading:

Close Date: 01/23/2015

**Problem?**

Driver side front headlight is out

Parts

Quantity

**Task performed:**

Repaired on 67698

NO PARTS USED

**Workorder: V73854**

In Date: 03/12/2015

Meter Reading:

42,038.20

Close Date: 03/12/2015

**Problem?**

REPLACES REAR TIRES

Parts

Quantity

**Task performed:**

REAR TIRES REPLACED

NO PARTS USED

Vendor? BOULERVARD



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V73666**

In Date: 03/05/2015  
Close Date: 03/30/2015

Meter Reading: 42,038.20

**Problem?**

replace broken a/c compressor

**Task performed:**

1. Start to replace A/C parts, compressor, blower up part throughout system. 2. A- Service, check over, resecure. 3. Need L-R door stricker, door will not stay closed. Need all tires on rear of truck. 4. High low beam turn signal sw, broken replace with new, recheck operation ok. 5. Replace right door pull handle broken. 6. Replace hangers broken. 7. Wire in new handle spot light in cab. 8. Replace both front tires. 9. Replace both front wiper blades and top off fluid and top off coolant also and rechecked coolant for leaks. 10. Check codes in modes for that it was ligh on right side scene light replace with new.

Parts	Quantity
18-45484-000LATCH L/H	1
533103-0607 A/C COMPRESSOR U4482 USE 7169 D	1
6805450124SWITCH TURN SIGNAL	1
6807200575HANDLE DOOR	1
716907-0610A DRYER	1
91-22WIPER BLADE	2
A2245482000 12-0615A VALVE EXPANSION FTRLNF	1
H50SN12BULB	1
RD-5-7063-OP07-2618A A/C DRIER 7155	1

**Workorder: V73191**

In Date: 02/16/2015  
Close Date: 03/31/2015

Meter Reading:

**Problem?**

Main O2 on truck leaks and needs to be replaced. It's a spare rescue #15. We've went through 4 bottles in a week. One of the bottles were faulty but the leak drains them slowly.

**Task performed:**

1. Traced out O2 leak and found and repaired.

Parts	Quantity
NO PARTS USED	



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154110

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V72162**

In Date: 01/09/2015  
Close Date: 06/30/2015

Meter Reading:

**Problem?**

R-42 spare-15 left air-bag leaking and not on balance.

Parts ----- Quantity -----

Task performed:

NO PARTS USED

**Workorder: V72438**

In Date: 01/19/2015  
Close Date: 06/30/2015

Meter Reading:

**Problem?**

Passenger side mirror bracket broken and mirror is loose. R42

Parts ----- Quantity -----

Task performed:

NO PARTS USED

**Workorder: V73345**

In Date: 02/22/2015  
Close Date: 06/30/2015

Meter Reading:

**Problem?**

Driver headlight out, high beams not working R52

Parts ----- Quantity -----

Task performed:

NO PARTS USED