

5/22/2017
4:28:41PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10116484 1998 INTERNATIONAL 8ST Trailer, Transport

Workorder: 46771

Problem: JACK STAND

Meter Reading: 0	Labor	Parts	
In Date: 10/03/2000	Hours	Description	Quantity
- Install Jack Stand	3.50	1/4X2X20 ANGLE STEEL	2.00
- Welding Supplies		JACKSTAND 30837	1.00
		18411 PINTAL PIN, 2 3/4" NEW # 66063	1.00
		SHOP SUPPLIES	1.00
		1/4X7X20' STEEL FLAT BAR	1.00
Parts Charge:	116.92	Labor Charge:	157.50

Workorder: 136545

Problem: NO TRAILER LIGHTS.

Meter Reading: 0	Labor	Parts	
In Date: 03/22/2001	Hours	Description	Quantity
- R/R Defective Trailer Plug.	1.00	TC101M/5403 TRAILER PLUG MALE TRAILER PLUG,11-604	1.00
- Shop Supplies		SHOP SUPPLIES	1.00
Parts Charge:	7.23	Labor Charge:	45.00

Workorder: 148319

Problem: NEEDS TIRES/PM

Meter Reading: 0	Labor	Parts	
In Date: 10/11/2001	Hours	Description	Quantity
- Replaced 2 Rear Tires.	9.50		2.00
- P.M. Service			2.00
- Replaced Brakes On All 4 Wheels & 1 Drum Assembly.			3.00
Clean & Repack All Bearings.		SHOP SUPPLIES	1.00
- Shop Supplies			1.00
Parts Charge:	438.84	Labor Charge:	475.00

5/22/2017
4:28:41PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10116484 1998 INTERNATIONAL 8ST Trailer, Transport

Workorder: 237503

Problem: CHECK ALL LIGHTS SEE NOTE

Meter Reading: 0	Labor	Parts	
In Date: 04/01/2002	Hours	Description	Quantity
- Ck. All Lighting Circuits & Replace L/R Brake Light Assy. Both Front Amber Marker Lights. Locate & Repair Open Circuit To Marker Lights.	4.50	4099 BREAKAWAY SWITCH 2010 06133 3M ELECTRIC TAPE STOCK #832260101 SHOP SUPPLIES	1.00 1.00 1.00
- R/R Break-Away Switch. R/R Trailer Battery. Locate & Repair Open Circuit In Brakes.		10205Y MARKER LIGHT 2.5" YELLOW GROTE 45813	2.00
- Shop Supplies		PS1250F1 BATTERY (POWER SONIC PS-1250-F1) 40002R T/L 52782 GROTE SS 4042	1.00 1.00
Parts Charge:	57.66	Labor Charge:	225.00

Workorder: 250128

Problem: PM, REPAIR TIRE

Meter Reading: 0	Labor	Parts	
In Date: 10/21/2002	Hours	Description	Quantity
- Pm Svc	6.00	SHOP SUPPLIES	1.00
- Mount Two New Tires		700-15 WORK HORSE 700-15	2.00
- Repair Tail Light Plug			
- Shop Supplies			
Parts Charge:	142.05	Labor Charge:	300.00

Workorder: 534206

Problem: TIRESOLES OF BROWARD INC T076002

Meter Reading: 0	Labor	Parts	
In Date: 01/07/2005	Hours	Description	Quantity
- Tiresoles Of Broward Inc T076002			
Parts Charge:	0.00	Labor Charge:	0.00
		Commercial Charge:	48.00

5/22/2017
4:28:41PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10116484 1998 INTERNATIONAL 8ST Trailer, Transport

Workorder: 541469

Problem: BOTH REAR TIRES LEAK/P.M.

Meter Reading: 0		Labor		Parts	
In Date: 04/11/2005	Close Date: 04/19/2005	Hours	Description		Quantity
-	Replace 2 Rear Tires Move To Frt Axle	11.50	312049090 700-15 DON'T REORDER		2.00
-	Pm Tandem Axle Trailer		42385 SEAL		-4.00
-	Replace Brake Shoes Both Axles And Adjust		42379 SEAL		4.00
-	Replace Brake Away Battery And Test Circuit		171048 BRAKE SHOES		4.00
-	Replace 1 Side Marke Lite And Repair Trailer Plug		PS1250F1 BATTERY (POWER SONIC PS-1250-F1)		1.00
-	Pressure Wash Eqpt		SHOP SUPPLIES		1.00
-	Shop Supplies		10205Y MARKER LIGHT 2.5" YELLOW GROTE 45813		1.00
			42385 SEAL		4.00
Parts Charge:		241.50	Labor Charge:	575.00	

Workorder: 832752

Problem: CK.TIRES P.M.

Meter Reading: 0		Labor		Parts	
In Date: 01/14/2008	Close Date: 01/25/2008	Hours	Description		Quantity
-	Pm Service	13.00	2616 RED MARKER LIGHT SQUARE		2.00
-	Replace 4 Tires		4053 BATTERY BOX		1.00
-	Replace New Side Markers And Brake Light		755-5046 MALE CONNECTOR		1.00
-	Rewire Whole Trailer, Put New Battery Box And Battery On		BEARING		4.00
			10205R MARKER LIGHT 2.5" RED GROTE 45812		1.00
-	Trailer Plug-Rewire Trailer Plug		BEARING		1.00
-	New Brake Away Switch		RACE		1.00
-	Shop Supplies		42379 SEAL		4.00
			42379 SEAL		-4.00
			SHOP SUPPLIES		1.00
			67010 RACE TIMKEN USE SET 6		4.00
			67048 BEARING TIMKEN USE SET 6		4.00
			004098 BREAKAWAY SWITCH		1.00
			67048 BEARING TIMKEN USE SET 6		-1.00
			SIDE MARKER LIGHTS		2.00
			PS1250F1 BATTERY (POWER SONIC PS-1250-F1)		1.00
			42385 SEAL		2.00
			700-15 WORKHORSE D		4.00
			67010 RACE TIMKEN USE SET 6		-1.00
			RACE		4.00
Parts Charge:		672.17	Labor Charge:	60.00	

5/22/2017
4:28:41PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10116484 1998 INTERNATIONAL 8ST Trailer, Transport

Workorder: 836536

Problem: REPAIR THE LIGHTS

Meter Reading: 0	Labor	Parts		
In Date: 04/03/2008	Hours	Description	Quantity	
- Replace Brake & Running Lights Install 2 Side Running Lightsrepair Wire By Battery.	1.50	10205R MARKER LIGHT 2.5" RED GROTE 45812	1.00	
- Shop Supplies		26301Y YELLOW MARKER LIGHT	2.00	
		SHOP SUPPLIES	1.00	
		40202R TAIL LIGHT 4" RED (GROTE 52772)	1.00	
		94926 LIGHT PLUG	1.00	
Parts Charge:	12.97	Labor Charge:	90.00	

Workorder: 840323

Problem: FLATIRE 616 S.W.11TH STREET

Meter Reading: 0	Labor	Parts		
In Date: 06/20/2008	Hours	Description	Quantity	
- Repair Flat Tire	1.00	SHOP SUPPLIES	1.00	
- Set Up For Commercial Repair On Tire				
- Shop Supplies				
Parts Charge:	2.00	Labor Charge:	30.00	

Workorder: 840694

Problem: AKRON TIRE CO. INC.

Meter Reading: 0	Labor	Parts		
In Date: 06/30/2008	Hours	Description	Quantity	
- Akron Tire Co. Inc.				
Parts Charge:	0.00	Labor Charge:	0.00	Commercial Charge: 14.40

Workorder: 841510

Problem: TIRESOLES OF BROWARD INC

Meter Reading: 0	Labor	Parts		
In Date: 07/09/2008	Hours	Description	Quantity	
- Tiresoles Of Broward Inc				
Parts Charge:	0.00	Labor Charge:	0.00	Commercial Charge: 107.60

5/22/2017
4:28:41PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10116484 1998 INTERNATIONAL 8ST Trailer, Transport

Workorder: 841511	Problem: TIRESOLES OF BROWARD INC				
Meter Reading: 0		Labor		Parts	
In Date: 07/09/2008	Close Date: 07/16/2008	Hours	Description		Quantity
<hr/>					
- Tiresoles Of Broward Inc					
	Parts Charge: 0.00	Labor Charge: 0.00	Commercial Charge: 54.00		

Workorder: 844460	Problem: TIRESOLES OF BROWARD INC				
Meter Reading: 0		Labor		Parts	
In Date: 09/03/2008	Close Date: 09/19/2008	Hours	Description		Quantity
<hr/>					
- Tiresoles Of Broward Inc					
	Parts Charge: 0.00	Labor Charge: 0.00	Commercial Charge: 107.60		

Workorder: 844461	Problem: TIRESOLES OF BROWARD INC				
Meter Reading: 0		Labor		Parts	
In Date: 09/03/2008	Close Date: 09/19/2008	Hours	Description		Quantity
<hr/>					
- Tiresoles Of Broward Inc					
	Parts Charge: 0.00	Labor Charge: 0.00	Commercial Charge: 54.00		

Workorder: 943693	Problem: P.M. / ENGINE CUTS OUT AT NORMAL OPERATION			SEE REQUEST	
Meter Reading: 0		Labor		Parts	
In Date: 09/24/2009	Close Date:	Hours	Description		Quantity
<hr/>					
-					
	Parts Charge: 0.00	Labor Charge: 0.00			

Workorder: 943805	Problem: Passenger Rear flat				
Meter Reading: 0		Labor		Parts	
In Date: 09/21/2009	Close Date: 09/28/2009	Hours	Description		Quantity
<hr/>					
- 8100 Forest Hill Blvd Next To Fuel Pumps					
	Parts Charge: 0.00	Labor Charge: 0.00	Commercial Charge: 66.00		

5/22/2017
4:28:41PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10116484 1998 INTERNATIONAL 8ST Trailer, Transport

Workorder: 944473

Problem: pm service

Meter Reading: 0		Labor	Parts	
In Date: 10/13/2009	Close Date: 10/27/2009	Hours	Description	Quantity
- Pm Service		12.00	09997 BRAKE CLEAN	2.00
- Replace And Repack Wheel Bearings			RACE	4.00
- Replace Marker Assy., Trailer Plug And Battery			PS1250F1 BATTERY (POWER SONIC PS-1250-F1)	1.00
- Shop Supplies			8616-100 TRAILER WIRE 6 WIRE 14 GAUGE	15.00
			10250R MARKER LIGHT 2.5" RED LED	1.00
			93745 ADAPTER PLUG PLUG LED MARKER LIGHT	1.00
			26301Y YELLOW MARKER LIGHT	2.00
			BEARING	4.00
			755-5046 MALE CONNECTOR	1.00
			2850 1/4" LINK	2.00
			26301R RED MARKER LITE (DON'T REORDER)	1.00
			SHOP SUPPLIES	1.00
			SET 6 BEARING SET 67010 67048 (TIMKEN)	3.00
			BEARING / 15123	1.00
			40202R TAIL LIGHT 4" RED (GROTE 52772)	1.00
			RACE / 15245	1.00
			26330 TAG LIGHT (TKR LITE)	1.00
	Parts Charge: 287.64	Labor Charge: 690.00		

Workorder: 945296

Problem: hitch

Meter Reading: 0		Labor	Parts	
In Date: 10/27/2009	Close Date: 10/28/2009	Hours	Description	Quantity
- Replace Tow Ring		0.70	TOW RING 6070	1.00
- Shop Supplies			SHOP SUPPLIES	1.00
	Parts Charge: 49.94	Labor Charge: 42.00		

Workorder: 1000641

Problem: repair the lights

Meter Reading: 0		Labor	Parts	
In Date: 01/15/2010	Close Date: 01/19/2010	Hours	Description	Quantity
- Repair Trailer Wiring		3.00	SHOP SUPPLIES	1.00
- Shop Supplies				
	Parts Charge: 2.00	Labor Charge: 180.00		

5/22/2017
4:28:41PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10116484 1998 INTERNATIONAL 8ST Trailer, Transport

Workorder: 1103764

Problem: PM SERVICE, CHECK TRAILER LIGHTS , TRAILER JACK NOT WORKING

Meter Reading: 0	Labor	Parts		
In Date: 04/07/2011	Hours	Description	Quantity	
- Pm Service	10.50	JACK / 30833	1.00	
- Replace Miker Lite Rt Front		SHOP SUPPLIES	1.00	
- Replace Jack		26301Y YELLOW MARKER LIGHT	2.00	
- Replace Tire				
- Shop Supplies				
Parts Charge:	63.36	Labor Charge:	630.00	Commercial Charge: 121.32

Workorder: 1105605

Problem: Transition Prep Charge

Meter Reading: 0	Labor	Parts		
In Date: 05/27/2011	Hours	Description	Quantity	
- Transition Prep Charge	2.00			
Parts Charge:	0.00	Labor Charge:	120.00	

Total Parts Charges:	2,094.28	Total Labor Charges:	3,619.50	Total Comm. Charges:	572.92
----------------------	-----------------	----------------------	-----------------	----------------------	---------------