



6/23/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10130845

* VAN SUPPORT

Workorder: V3726

In Date: 08/01/2006
Close Date: 08/22/2006

Meter Reading:

Problem?
UNIT RUNS POORLY

Task performed:

Parts	Quantity
17113205SEAL KIT INJECTION FOR WORKHORSE	1
17113206SEAL KIT FOR WORKHORSE	1
24203876SPEED SENSOR FOR GMC	2
25315352FUEL PUMP ASSY. FOR 2000 WORKHORSE	1
41932SPARK PLUG	8
78-72BATTERY GROUP 78	1
89017453FUEL REGULATOR FOR 2000 WORKHORSE	1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTER	1
DR331ROTOR	1
DR474CAP	1
FREIGHTSHIPPING CHARGES	1
G372733481 FUEL FILTER L/F G481 WIX	1

Workorder: V4150

In Date: 08/28/2006
Close Date: 08/31/2006

Meter Reading:

Problem?
REPAIR UNIT AT GENERAL GMC

Task performed:

Parts	Quantity
NO PARTS USED	

Vendor? GENE0004

Workorder: V8759

In Date: 06/12/2007
Close Date: 04/15/2007

Meter Reading: 24,595.00

Problem?
b inspection done at fleet

Task performed:

Parts	Quantity
NO PARTS USED	



6/23/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10130845

* VAN SUPPORT

Workorder: V9973

In Date: 08/17/2007
Close Date: 09/10/2007

Meter Reading: 24,854.00

Problem?

engine runs poorly

Task performed:

Parts

Quantity

1. Drive to new shop-no key to vehicle; come back to old shop; set key & btry; return to new shop; start truck & run diagnostics; no code found
2. Fnd water laying on ECM; chk for gasekts; fnd one missing; seal with d. compound & order part

NO PARTS USED

Workorder: V10642

In Date: 09/24/2007
Close Date: 09/28/2007

Meter Reading: 24,854.00

Problem?

check engine light on, abs light on, speedometer reads twice as high as normal, rattling noise under vehicle(sounds like exhaust)
(warehouse step van)

Task performed:

Parts

Quantity

1. Install hoist battery charger
2. Road test to verify prolem; chkd engine codes 0171 bank one ; ABS light on-no codes; chkd eng data FT & 02 readings; chkd scanner against speedo reading the same; VCM bad
3. Send to General GMC 9/27/07
4. Travel to GMC; Travel to Cummins & back

NO PARTS USED

Workorder: V11774

In Date: 11/27/2007
Close Date: 12/03/2007

Meter Reading: 24,854.00

Problem?

flash ecm maroone cheverolet

Task performed:

Parts

Quantity

Flash ECM - Mar4oone Chev

j

NO PARTS USED

Vendor? MAROONE CHEV



6/23/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10130845

* VAN SUPPORT

Workorder: V11644

In Date: 11/16/2007 Meter Reading: 24,854.00
Close Date: 12/04/2007

Problem?

repair electrical problem general gmc

Task performed:

Repair electrical problem - General GMC j

Parts

NO PARTS USED

Quantity

Vendor? GEN GMC

Workorder: V11647

In Date: 11/16/2007 Meter Reading: 24,854.00
Close Date: 12/04/2007

Problem?

replace bad ecu

Task performed:

1. Replc U-joint; install drive shaft
2. Replc brkn PCM mount
3. Attempt to program ECM "security" system
4. Install ECM j

Parts

330U-JOINT 1
 78-72BATTERY GROUP 78 1
 BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTEF 1
 EM3494UFLASH ECM 1
 S638AIR REGULATOR FITTING 1

Quantity

Workorder: V11792

In Date: 11/28/2007 Meter Reading: 24,854.00
Close Date: 12/04/2007

Problem?

A/C compressor clutch is slipping (step van)

Task performed:

1. test drive and check A/C system WNL. no problem found.
2. Checked out A/C system, replaced heater control unit (by passing hot coolant). Also adjusted fresh air mixture door (not closing all the way)
3. Replaced serpentene belt (freyed/cracked)
4. Replaced belt tensioner. (low tension).
5. Replaced idler pully (seized bearing)
6. Installed 2 Inline manual shut off valves in the heater hoses to keep hot coolant out of heater core to ensure efficient Evap. core operation.

Parts

277814USE 2104 HEATER VALVE 1
 71847062455 VALVE HEATER 2
 89006IDLER SUBURBAN 38001 1
 89231TENSIONER 1
 K060960BELT 1

Quantity



6/23/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10130845

* VAN SUPPORT

Workorder: V11646

In Date: 11/16/2007

Meter Reading: 24,854.00

Close Date: 12/06/2007

Problem?

tow unit from gms to shop

Task performed:

Parts

Quantity

Tow unit from Shop to Vista

NO PARTS USED

Vendor? SISTERS TOWING

Workorder: V11775

In Date: 11/27/2007

Meter Reading: 24,854.00

Close Date: 12/07/2007

Problem?

tow unit to maroone chevrolet

Task performed:

Parts

Quantity

Tow unit to Maroone Chevrolet j

NO PARTS USED

Vendor? MAROONE CHEV

Workorder: V12172

In Date: 12/20/2007

Meter Reading: 24,854.00

Close Date: 01/07/2008

Problem?

FRONT BRAKES SMOKING,

Task performed:

Parts

Quantity

1. Inspect and diagnose brake problem.
2. Install new left and right caliper and pads.
3. Replace brake fluid to rear brakes and clean master cylinder and remove front brake lines.
4. Replace front left and right brake lines replace ABS left front to center mad-line bleed entire system.

12388969FRONT CALIPER

1

12388970FRONT CALIPER

1

12389421FRONT PADS

1

22112623FRONT BRAKE HOSE

1

22112624BRAKE HOSE

1

Workorder: V10706

In Date: 09/27/2007

Meter Reading: 24,854.00

Close Date: 01/15/2008

Problem?

speedo reads double of real speed-engine derates at reading of 90 mph (warehouse step van-outside agency-General GMC)

Task performed:

Parts

Quantity

NO PARTS USED



6/23/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10130845

* VAN SUPPORT

Workorder: V14625

In Date: 04/22/2008

Meter Reading: 24,854.00

Close Date: 04/28/2008

Problem?

A/C COMPRESSOR CLUTCH BURNT UP,

Task performed:

1. remove and replace locked up a/c compressor-replace dryer-replace belt and belt tensioner-evacuate and recharge system.

Parts

Quantity

18190A16-3409 A/C FITTING HIGH SIDE	1
58950AC COMPRESSOR	1
89231TENSONER	1
91-20WIPER BLADE 20 IN	2
K060960BELT	1
RD-5-7063-OP07-2618A A/C DRIER 7155	1

Workorder: V14363

In Date: 04/08/2008

Meter Reading: 24,854.00

Close Date: 04/30/2008

Problem?

B INSPECTION AND REPAIRS AS NEEDED

Task performed:

1. b-service
2. check and charged a/c.
3. removed broken grease fitting,check and cleaned all engine codes.
4. installed new wiper blades.

Parts

Quantity

91-20WIPER BLADE 20 IN	2
G372733481 FUEL FILTER L/F G481 WIX	1
PH3980WIX 51036 L/F#PH51A OIL FILTER	1

Workorder: V16433

In Date: 07/18/2008

Meter Reading: 24,854.00

Close Date: 08/12/2008

Problem?

replace battery check charging system

Task performed:

- 1 replace altenator on engine.
- 2 check out truck running ruff. found water in computer. r&r computer, need to program at dealer.
- 3 take computer to dealer to flash. could not do without truck, installed back in truck and the old one taken back to dealer.
- 4 remount computer in cab of truck for water problem. made bracket to mount under dash.

Parts

Quantity

10463688ALTERNATOR	1
6806970098SEAL DOOR	1
78-72BATTERY GROUP 78	1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTEF	1
EM3494UFLASH ECM	1



6/23/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10130845

* VAN SUPPORT

Workorder: V16776

In Date: 08/01/2008 Meter Reading: 24,854.00
Close Date: 10/17/2008

Problem?
reprogram ECU (step van-outside agency-general gmc)

Task performed:	Parts	Quantity
Reprogram ECU (step van) Gen GMC Truck j	NO PARTS USED	

Vendor? GEN GMC TRUCK

Workorder: V18847

In Date: 11/04/2008 Meter Reading: 24,854.00
Close Date: 03/02/2009

Problem?
B INSPECTION AND REPAIRS AS NEEDED

Task performed:	Parts	Quantity
	15W40BSYN OIL BULK QTS	6
	91-20WIPER BLADE 20 IN	2
	PH3980WIX 51036 L/F#PH51A OIL FILTER	1

Workorder: V22022

In Date: 03/23/2009 Meter Reading: 25,858.90
Close Date: 03/26/2009

Problem?
REPLACE BATTERY, WILL NOT START, STEP VAN

Task performed:	Parts	Quantity
1. Replcd btry; van still did not start.	1219360123-11276-041 RELAY VF28-35F14-Z05	1
2. T-shoot electrical sys; fnd no power going to starter solenoid. truck will require further T-shooting.	78-72BATTERY GROUP 78	1
3. Towed truck into shop; T-shoot no start condition; traced problem to faulty start solenoid; replcd solenoid & tested sys.	BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTEF	1
4. Assist w/dianosis of starting problem; tow into shop. (Levy). j		



6/23/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10130845

* VAN SUPPORT

Workorder: V23941

In Date: 06/09/2009

Meter Reading: 25,858.90

Close Date: 06/19/2009

Problem?

B inspection and repairs (step van)

Task performed:

1. Start B-Inspection
2. Finish B-Inspection
3. Adj parking brake cable.
4. Charge A/C sys. j

Parts

Parts	Quantity
15W40BSYN OIL BULK QTS	6
G372733481 FUEL FILTER L/F G481 WIX	1
PH3980WIX 51036 L/F#PH51A OIL FILTER	1

Quantity

Workorder: V28173

In Date: 12/07/2009

Meter Reading: 27,424.00

Close Date: 12/21/2009

Problem?

A inspection and repairs

Task performed:

1. A-Inspection
2. Replace wiperblades.
3. Replc btry; adj btry compt latches. j

Parts

Parts	Quantity
78-72BATTERY GROUP 78	1
91-20WIPER BLADE 20 IN	2
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTEF	1

Quantity

Workorder: V32352

In Date: 05/20/2010

Meter Reading: 27,424.00

Close Date: 05/24/2010

Problem?

fuel truck and generator

Task performed:

1. Drive veh to St23; fuel veh tank & fill portable gen. j

Parts

NO PARTS USED

Quantity



6/23/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10130845

* VAN SUPPORT

Workorder: V36064

In Date: 11/01/2010
Close Date: 12/01/2010

Meter Reading: 27,785.00

Problem?

B inspection and repairs (step van)

Task performed:

(1) B-INSPECTION

Parts	Quantity
15W40BSYN OIL BULK QTS	6
78-72BATTERY GROUP 78	1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTER	1
CA391446144 AIR FILTER WIX	1
G372733481 FUEL FILTER L/F G481 WIX	1
PH3980WIX 51036 L/F#PH51A OIL FILTER	1

Workorder: V38240

In Date: 02/02/2011
Close Date: 02/15/2011

Meter Reading: 27,785.00

Problem?

A INSPECTION AND REPAIRS AS NEEDED

Task performed:

- A-Inspection
- 2. Top off coolant to proper level.
- 3. Replc wiper blades.
- 4. Fill all tires to proper air press. j

Parts	Quantity
91-20WIPER BLADE 20 IN	2

Workorder: V42162

In Date: 07/20/2011
Close Date: 09/26/2011

Meter Reading: 27,785.00

Problem?

B Inspection @ Roger Dean

Task performed:

WORK TO BE COMPLETED ON WO 43867

Parts	Quantity
NO PARTS USED	



6/23/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10130845

* VAN SUPPORT

Workorder: V43867

In Date: 09/23/2011
Close Date: 09/27/2011

Meter Reading: 28,154.00

Problem?

Outside B inspection.

Task performed:

Parts

Quantity

WO 42168 IS ATTACHED TO THIS WO FOR REFERENCE ONLY

NO PARTS USED

B-Inspection - Roger Dean j
Vendor? ROGER DEAN

Workorder: V44317

In Date: 10/11/2011
Close Date: 11/04/2011

Meter Reading: 28,132.00

Problem?

install a/c for rear of unit

Task performed:

Parts

Quantity

Start research on installing A/C in rear of unit. j

NO PARTS USED

Workorder: V49188

In Date: 05/08/2012
Close Date: 05/14/2012

Meter Reading: 28,665.00

Problem?

mount storage cabinet to inside of van. Please install new latch. Thanks

Task performed:

Parts

Quantity

INSTALLED CABINET ON WALL.

NO PARTS USED

Workorder: V49193

In Date: 05/08/2012
Close Date: 05/14/2012

Meter Reading: 28,665.00

Problem?

Please install and fasten second supply cabinet to passenger side wall opposite existing mounted cabinet

Task performed:

Parts

Quantity

INSTALLED CABINET ON WALL.

NO PARTS USED



6/23/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10130845

* VAN SUPPORT

Workorder: V49437

In Date: 05/17/2012
Close Date: 05/25/2012

Meter Reading: 28,665.00

Problem?

wont start roger dean

Task performed:

WON'T START ROGER DEAN.

Parts

NO PARTS USED

Quantity

Vendor? ROGER DEAN CHEVROLE

Workorder: V49961

In Date: 06/07/2012
Close Date: 06/11/2012

Meter Reading: 28,665.00

Problem?

REPAIR LEAK / CARPET COMING OFF CIELING

Task performed:

1. REATTACH CARPET TO ROOF.
2. RESEAL CLEARANCE LIGHTS.

Parts

NO PARTS USED

Quantity

Workorder: V53257

In Date: 10/23/2012
Close Date: 10/23/2012

Meter Reading: 29,344.00

Problem?

A/C inop and battery low Step Van

Task performed:

1. JUMP START PULL IN BAY AND CHARGE BATTERY.
2. CHK A/C RECOVER FREON AND VACCUM SYSTEM AND RECHARGE.
3. TEST BATTERY AND REPLACE.
4. REMOVE MIRRORS AND REPOSITION.

Parts

78-72BATTERY GROUP 78	1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTER	1

Quantity



6/23/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10130845

* VAN SUPPORT

Workorder: V53291

In Date: 10/24/2012

Meter Reading: 29,344.00

Close Date: 11/09/2012

Problem?

B inspection

Task performed:

1. B INSP, ADD WASHER FLUID.
2. B INSP, ADD TRANS FLUID.
3. DRILLED NEW MOUNTING HOLE, FOR WINDSHIELD WASHER RESERVOIR BOTTLE AND BOLTED. (BROKEN).
4. REPLACED WIPER BLADES.
5. REPLACED LEFT FRT TOP MARKER LIGHT ASSEMBLY. CHESELED OFF MOUNTING BOLTS (RUSTED) DRILLED NEW HOLES INSTALLED NEW LIGHT.
6. CHK OUT REAR TRIPLE LIGHT BAR INOP TRACED PROBLEM TO FAULTY POSITIVE CONNECTION INSIDE TRUCK AT ROOF LINE RECONNECTED BROKEN WIRE LIGHTS NOW WORK NORMALLY.
7. CHK OUT COOLANT LEAK ATWATER PUMP MOUNT TRACED LEAK TO INTAKE MANIFOLD LEAK (OIL) LEAK IS NOT SEVERE ENOUGH (CLASS 1) TO WARRANT ANY REPAIRS AT THIS TIME.
8. CHK AND REMOVED NAIL IN RIGHT REAR OUTER TIRE LEAK CHK W/ SOAPY WATER. NAIL DID NOT GO AL THE WAY THROUGH. NO LEAKS.
9. CHECKED OUT SWAY BAR BUSHINGS AND ORDERED NEW. 3 OF THE 4 BUSHINGS ARE COMPLETELY GONE.
10. CHK OUT LOWER BALL JINTS WHEEL BEARING END PLAY TIE ROD ENDS. VERY VERY SMALL AMOUNT OF WEAR (MARGINAL) NO REPAIRS REQUIRED AT THIS TIME.
11. REPLACED SERPENTENE BELT.

Parts	Quantity
46792LIGHT MARKER	2
91-20WIPER BLADE 20 IN	2
B138-15ALENS AMBER	1
G372733481 FUEL FILTER L/F G481 WIX	1
K060960BELT	1
PH3980WIX 51036 L/F#PH51A OIL FILTER	1

Workorder: V53754

In Date: 11/14/2012

Meter Reading: 29,584.00

Close Date: 11/14/2012

Problem?

replace parts that were on order

Task performed:

REPLACED ALL FRT SWAYBARS BUSHLINE. ALL MOUNTING BOLTS VERY RUSTY. ROAD TESTED AND REINSPECTED. ALL REPAIRS ARE GOOD.

Parts	Quantity
8803039BUSHING WORKHORSE CHASIS	4



6/23/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10130845

* VAN SUPPORT

Workorder: V53811

In Date: 11/16/2012

Meter Reading: 29,584.00

Close Date: 11/20/2012

Problem?

REPLACE FRONT TIRES

Task performed:

REPLACE FRONT TIRES.

Parts

NO PARTS USED

Quantity

Vendor? ELPEX

Workorder: V56946

In Date: 04/10/2013

Meter Reading:

Close Date: 05/13/2013

Problem?

please add at last 3 led strip lights in rear, rear camera for safty, fan drivers compartment (round ones like in old engines) first aid kit., Lock on door between cab and rear, warning light of rear missing,

Task performed:

1. SEARCHED THROUGH SPARE KEY BOX AND FOUND KEY FOR INTERIOR CARGO DOOR LOCK.
2. INSTALLED AND WIRED STRIP LIGHTS.
3. BEGAN INSTALLING BACK UP CAMERA. BUILT/FABBED MOUNTING BRACKET FOR DASH FOR MONITOR AND MOUNTED. ATTACHED CAMERA TO REAR OF TRUCK AT LICENSE PLATE AND DRILLED HIDE IN BODY FOR WIRE PASS THROUGH. RAN CABLE FROM FRT TO BACK OF TRUCK AND SECURED. DRILLED HIDE IN FRT WALL FOR CABLE. NOW WAITING FOR REMAINING PARTS TO COME IN
4. MOUNTED NEW ROOF STROBE ON ROOF OF TRUCK. HAD TO CUT HOLE IN ROOF TO ACCES WIRES AND REPAIR ROF WHERE PREVIOUS LIGHT WAS RIPPED OFF. REPAIRED ROOF, REPAIRED WIRES INSTALLED NEW LIGHT.
5. MOUNT FIRST AID KIT INSIDE CARGO AREA.
6. REPLACED WIPER BLADES.
7. CONT INSTALLING BACK UP CAMERA WIRED POWER AND GROUND TO CAMERA AT REAR OF TRUCK WIRED IN CONTROL BOX BEHIND DASH.
8. CONT INSTALLING BACK UP CAMERA RAN WIRE FROM DASH BACK TO REVERSE SWITCH TO ACTIVATE CAMERA AND COMPLETED WIRING OF CONTROL CENTER.

Parts

- 01-06635060-C90PSC0CDCR STRIP LIGHT STEADY WHITE 5
- 0130503855 FAN BE29012 - CAB 2
- 800-CLRPSTROBE LIGHT 1
- 91-20WIPER BLADE 20 IN 2
- CYBS21237011CYBS21237011 STRAP 5
- MFG01876GROUND LT BRACKET 2
- PLCM7200CAMERA KIT W 7 IN MONITOR 1
- UMFS-0311UTILITY STRAP 5
- UMVS111611STRAP 1
- UMVS254411STRAP 46 IN 4

Quantity



6/23/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10130845

* VAN SUPPORT

Workorder: V56947

In Date: 04/10/2013

Meter Reading:

Close Date: 05/13/2013

Problem?

am/ fm not working Logistics van

Task performed:

1. TROUBLESHOOT AM/FM RADIO INOP: FOUND RADIO NO GOOD. REMOVED RADIO AND ORDERED NEW ONE.
2. INSTALLED TWO FANS IN CAB. FABBED MOUNTING BRACKET AND WIRED. TURNED ON FANS AND KEPT BLOWING FUSE. TRACED PROBLEM TO ONE FAULTY FAN. REMOVED FAN AND ORDERED NEW.
3. CHECKED OUT A/C NOT CODING: FOUND FREON LOW, RECOVERED SYSTEM AND FILLED WITH NITROGEN LEAK CHECKED FOUND LEAK AT HIGH SIDE SERVICE PORT. REPLACED SHRADER VALVE. FILLED WITH FREON AFTER VACUUM. LEAK CHECKED VALVE. NO FURTHER LEAKAGE. SYSTEM IS NOW COOLING NORMALLY.
4. RECIEVED NEW FAN FROM PARTS DEPT, INSTALLED AND WIRED NEW FAN RUNS NORMALLY. NO LONGER BLOWS FUSE.
5. RECIEVED NEW RADIO FROM PARTS DEPT, CUT NEW HOLE IN OVERHEAD CONSOLE, INSTALLED MOUNTING BRACKET, INSTALLED RADIO.
6. REWIRED RADIO & SPEAKERS. TESTED RADIO OPERATION.
7. REWIRED BACK UP LIGHTS WITH L.E.D'S AND NEW PIGTAILS.
8. INSTALLED AND WIRED STROBE LIGHT PACK IN WINDSHIELD AND WIRED INTO EXISTING IN DASH.

Parts

Quantity

CQCP137U4ARADIO

1

PP202147HARNES RADIO

1

Workorder: V57772

In Date: 05/16/2013

Meter Reading: 31,431.00

Close Date: 05/22/2013

Problem?

resecure cabinet

Task performed:

SECURED METAL STORAGE TO WALLS OF STEP WAV (RIPPED LOOSE).

Parts

Quantity

NO PARTS USED



6/23/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10130845

* VAN SUPPORT

Workorder: V56856

In Date: 04/05/2013

Meter Reading: 30,975.00

Close Date: 06/06/2013

Problem?

wiper blades worn

Task performed:

Parts	Quantity
91-20WIPER BLADE 20 IN	2
H3-100WBP1210H3 BULB	1
MS-290STIHL FUEL CAPS	1

Workorder: V58940

In Date: 07/08/2013

Meter Reading: 31,953.00

Close Date: 07/15/2013

Problem?

install fridge

Task performed:

- CHECKED OUT TRUCK AND FRIDGE TO PLAN INSTALLATION. GATHER ALL NEEDED PARTS, CALLED DOMETIC TO ENSURE PROPER INSTALLATION. MEET WITH MARK G. AND JULIO TO ARRANGE DAY FOR INSTALLATION.
- BEGAN INSTALLING FRIDGE AND WIRING IN 12 VOLTS AND 120 VOLT CONNECTIONS. ALSO INSTALLED AND WIRED 2ND TRUCK BATTERY.
- CONTINUED/COMPLETED FRIDGE INSTALL ALONG WITH ABOVE MENTIONED ITEMS, ALSO INSTALLED AUTO EJECT FOR 110 VOLT SUPPLY.

Parts	Quantity
091-3YWCOVER KUSSMAUL AUTO EJECT	1
0915520120AUTO EJECT 20 AERO OTL3925	1
134RLENS	1
14005061RETAINER BATTERY	2
78-72BATTERY GROUP 78	1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTEF	1
UMVS254411STRAP 46 IN	1

Workorder: V58219

In Date: 06/05/2013

Meter Reading: 31,953.00

Close Date: 08/02/2013

Problem?

repair brakes total truck

Task performed:

REPAIR BRAKES TOTAL TRUCK.

Parts	Quantity
NO PARTS USED	

Vendor? *



6/23/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10130845

* VAN SUPPORT

Workorder: V61574

In Date: 10/28/2013
Close Date: 11/06/2013

Meter Reading: 35,561.00

Problem?

B-inspection

Task performed:

B INPECTION OIL CHANGE SERVICES

Parts

Quantity

CA391446144 AIR FILTER WIX	1
G372733481 FUEL FILTER L/F G481 WIX	1
PH3980WIX 51036 L/F#PH51A OIL FILTER	1

Vendor? OIL CHANGE SERVICES

Workorder: V64625

In Date: 03/02/2014
Close Date: 03/04/2014

Meter Reading: 38,943.00

Problem?

won't start

Task performed:

CHECK AND CHARGER BATTERY LEFT LIGHT ON IN
SEAR OF TRUCK, BATTERY VERY LOW.

Parts

Quantity

NO PARTS USED

Workorder: V60093

In Date: 08/26/2013
Close Date: 03/19/2014

Meter Reading: 33,835.00

Problem?

parts only for vollys

Task performed:

PARTS ONLY NO LABOR.

Parts

Quantity

594014 BIKE RACK	1
------------------	---

Workorder: V61841

In Date: 11/06/2013
Close Date: 04/18/2014

Meter Reading: 35,967.00

Problem?

SWAY BAR BUSHINGS RT FRONT MARKER OUT CHECK ENG LT ON

Task performed:

SWAY BAR BUSHINGS
RT FRONT MARKER OUT
CHECK ENG LT ON. COMPLETE CH OK.

Parts

Quantity

NO PARTS USED



6/23/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10130845

* VAN SUPPORT

Workorder: V66542

In Date: 05/16/2014
Close Date: 05/16/2014

Meter Reading: 42,355.00

Problem?

B-inspection

Task performed:

B-inspection

Parts

NO PARTS USED

Quantity

Vendor? AL PACKER

Workorder: V66791

In Date: 05/27/2014
Close Date: 06/18/2014

Meter Reading: 42,580.00

Problem?

coolant leak

Task performed:

- 1) intake manifold leaking coolant R&R manifold and distributor
- 2) start eng out of time reset and run
- 3) strighten front bumper test driver ok.

Parts

7085773C917085773C92 BREATHER M7
MS90131-2GASKET SET MANIFOLD

Quantity

1
1

Workorder: V67550

In Date: 06/29/2014
Close Date: 07/01/2014

Meter Reading: 43,781.00

Problem?

Tail light inop

Task performed:

- 1. REWIRED LEFT TAIL LIGHT/ BRAKE LIGHT (SHORTED).
- 2. CONTINUED REWIRING TAIL LIGHTS AND BACK UP LIGHTS REPLACED ALL PIGTAILS GOING TO BRAKE TURN SIGNAL RUNNING LIGHTS AND BACK UP LIGHTS. ALSO REPLACED T/S FLASHER.

Parts

94993PIGTAIL TRUCKLITE 3-WIRE
EL12FLASHER ELECTRONIC

Quantity

4
1



6/23/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10130845

* VAN SUPPORT

Workorder: V68224

In Date: 07/28/2014
Close Date: 08/05/2014

Meter Reading: 44,890.00

Problem?

install roof a/c

Task performed:

- 1.Started gathering parts needed for roof AC isntall. Inspected truck also.
- 2.Installed roof AC unit(110v.)
- 3.Continued/completed 110v. AC roof unit installtion.

Parts

Quantity

63152HVAC UNIT ROOF MOUNTED	1
QO120GFIGFI CIRCUIT BREAKER 20 AMP	1

Workorder: V70368

In Date: 10/22/2014
Close Date: 10/29/2014

Meter Reading: 47,987.00

Problem?

Power steering noise

Task performed:

1. ck, noise found p/s pump making noise ck, fluid low add fluid test drive noise still present order pump and belt.
2. power streeing pump on good dran oil removed pump install new one new hose and o ring fluid bleed out air and test drive ok.

Parts

Quantity

FRT V27624FREIGHT CHARGE	1
WCC26135377PS PUMP WORK HORSE	1
WCCW8800310FAN BELT WORK HORSE	1



6/23/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10130845

* VAN SUPPORT

Workorder: V70380

In Date: 10/23/2014

Meter Reading: 47,987.00

Close Date: 10/30/2014

Problem?

B-inspection

Task performed:

1. Rear differential cover seeping oil "class #1 leak".
Check oil - clean. Retorque screws. Add oil to full mark.

2. A/C core leaking in cab. Remove G-core cover.
Clean tray, E-core and drain pan, over flow tube.
Reassemble.

3. B Inspection. Replace air filter

4. Transmission cooler hose leaking. Remove hose.
Parts on order. Install new hose-washer to o-ring. Fill
transmission and operate.

5. Inoperable right headlight, right front marker light,
rear 3 marker lights. Replace defective/failed parts,
fabricate and rewire electrical lighting components.

6. Right side headlight and turn signal inoperable.
Repair broken ground. Replace blown bulbs. Secure
loose grill and fastners.

Parts

Quantity

1157BULB	2
15741R49172 BAR LIGHT	1
194BULB	1
484926HOSE AND FITTINGS	1
CA391446144 AIR FILTER WIX	1
G372733481 FUEL FILTER L/F G481 WIX	1
G4603MARKER LIGHT LED AMBER	1
H6014HEADLAMP BULB LARGE ROUND	1
PH3980WIX 51036 L/F#PH51A OIL FILTER	1

Workorder: V71027

In Date: 11/18/2014

Meter Reading: 48,875.00

Close Date: 11/19/2014

Problem?

wiper blades

Task performed:

Installed blades

Parts

Quantity

91-20WIPER BLADE 20 IN	2
------------------------	---



Palm Beach County Fire Rescue

Fleet Maintenance Asset History

Asset: (10130845) 2000 - WORKHORSE P SERIES Van - Support

10130845

CSHOP-2015-1553

Comments: **UNIT WILL NOT START**

Date Opened: 7-6-2015

Date Finished

7-9-2015

Meter 1 Reading:

56,186

TASKS PERFORMED

Q PARTS

EXHAUST PIPE
BATTERY

1	NONSTOCK; FREIGHT CHARGE
1	GASKET WORK HORSE
2	BATTERY; BATTERY GROUP 78
2	BATTERY; BATTERY EPA TAX \$1.50 PER BATTERY

CSHOP-2015-2387

Comments: **NO START**

Date Opened: 8-18-2015

Date Finished

8-20-2015

Meter 1 Reading:

56,186

TASKS PERFORMED

NO PARTS USED

ENGINE AND ACCESSORIES

CSHOP-2015-2581

Comments: **FUEL PUMP FAULTY**

Date Opened: 8-27-2015

Date Finished

8-27-2015

Meter 1 Reading:

59,365

TASKS PERFORMED

NO PARTS USED

FUEL PUMP

VENDOR? RECHTIEN INTERNATIONAL TRUCKS

CSHOP-2015-3489

Comments: **MED VAN OVERHEATING**

Date Opened: 10-19-2015

Date Finished

10-21-2015

Meter 1 Reading:

60,333

TASKS PERFORMED

Q PARTS

COOLING SYSTEM

8	FLUID; COOLANT ANTIFREEZE GAL
1	NEWPART; WATER PUMP
1	BELT; BELT

CSHOP-2015-3860

Comments: **TURN SIGNALS INOP**

Date Opened: 11-9-2015

Date Finished

11-10-2015

Meter 1 Reading:

60,333

TASKS PERFORMED

NO PARTS USED

DIAGNOSE ELECTRICAL

Asset Work Order History 10130845

CSHOP-2015-441

Comments: **STEP VAN. AIR CONDITIONING NOT WORKING.**

Date Opened: 5-4-2015 Date Finished 5-6-2015 Meter 1 Reading: 55,967

TASKS PERFORMED

Q PARTS

OIL
AIR CONDITIONING

3 FLUID; SYN OIL QT
2 SEAL; SEALING WASHER 14MM
1 HOSE AND FITTING
1 DRYER; 07-2618A A/C DRIER 7155
1 RELAY; 23-11276-041 RELAY VF28-35F14-Z05

CSHOP-2015-703

Comments: **B-INSPECTION**

Date Opened: 5-18-2015 Date Finished 5-18-2015 Meter 1 Reading: 56,186

TASKS PERFORMED

NO PARTS USED

PM SERVICE B LIGHT

VENDOR? AL PACKER

CSHOP-2016-2721

Comments: **B SERVICE**

Date Opened: 6-7-2016 Date Finished 6-7-2016 Meter 1 Reading: 64,875

TASKS PERFORMED

NO PARTS USED

PM SERVICE B LIGHT

VENDOR? AL PACKER

CSHOP-2016-764

Date Opened: 2-17-2016 Date Finished 2-17-2016 Meter 1 Reading: 64,859

TASKS PERFORMED

NO PARTS USED

REAR TIRES

VENDOR? DAN CALLAGHAN ENTERPRISES

CSHOP-2017-2401

Date Opened: 4-24-2017 Date Finished 4-24-2017 Meter 1 Reading: 65,093

TASKS PERFORMED

NO PARTS USED

PM SERVICE B LIGHT

VENDOR? AL PACKER

Asset Work Order History 10130845

CSHOP-2017-2959

Comments: **PREP FOR SURPLUS**

Date Opened: 5-18-2017

Date Finished

6-21-2017

Meter 1 Reading:

65,098

TASKS PERFORMED

NO PARTS USED

SURPLUS PREP
