



6/26/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10169729

21FT OPEN FISHERMAN W/FIRE PUMP \*

**Workorder: V32547**

In Date: 06/01/2010  
Close Date: 06/08/2010

Meter Reading: 1.00

**Problem?**

PUMP MOTOR WONT RUN

**Task performed:**

Pump inop; throttle stuck; freed up throttle & got running for training; needs a new throttle cable. j

Parts

Quantity

J19LMUSE 1147 NGK SPARK PLUG

2

**Workorder: V32660**

In Date: 06/04/2010  
Close Date: 07/14/2010

Meter Reading: 3.00

**Problem?**

bilge pump and stwirth inop vol boat

**Task performed:**

1. Throttle for fire pump inopl.
2. Btry for fire pump worn; rep cables & installed new connector. j

Parts

Quantity

327561PUMP BILGE

1

359984FNSTBRPN HOSE

1

375196PUMP BILGE

1

8247090FLOAT SWITCH

1

98279CONNECTOR

2

CYBS21237011CYBS21237011 STRAP

4

UMVS254411STRAP 46 IN

2



6/26/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10169729

21FT OPEN FISHERMAN W/FIRE PUMP \*

**Workorder: V33524**

**In Date:** 07/13/2010

**Meter Reading:** 5.00

**Close Date:** 09/13/2010

**Problem?**

SERVICE PUMP AND OUTBOARD

**Task performed:**

1. Svc outboard
  2. Svc fire pump
  3. Wiring frm coil pack melted; rep wiring.
  4. L/S marker brkn; replc lights & brkn mnt.
  5. Pump throttle inop calbe mnt loose; rep mnt.
  6. Console loose - bolts stripped; old fiberglass; made new frame for mntng console.
  7. Reroute fuel filter mntng; new filter wont fit.
  8. Spotlights inop; controls/switches corroded; replcd corroded switches & rep wiring.
  9. install 12V power port in dash.
  10. Rem \_\_\_\_ frm stern; bolts seized; rem & extracted bolts.
  11. Install voltmeter - doesn't have one.
  12. Rep buss bar wiring-loose & corroded;
  13. Install AVL; needs to be mntd all in \_\_\_\_.
  14. Rem spotlight; handlight hard wired in.
  15. Air tires-low
  16. Btry charger inop; fuse blown; replc.
  17. Trailer jack difficult to operate; gear pin sheared off; diss & tried to rep; ordered & installed new jack.
  18. not pumping wtr out of weed hole; line clogged; cln wtr lines & got wtr out of weed hole.
  19. Test boat opn in lake; Ralph adjusted shifter/throttle.
- j

**Parts**

**Quantity**

30-230FH3683 STRAP-RATCHET TYPE	2
33757FUEL FILTER OUTBOARD	1
46-96148A8PUMP KIT	1
5582-10 82-2111 GROTE ON-OFF WEATHERPROOF	1
559282-2122 SWITCH	1
6431SPARK PLUG	6
80019SEALANT #3	1
8126482-2106 TOGGLE GUARD	1
9706CLEAR FILTER	1
9747CLEAR FILTER	1
BUL-30858TRAILER JACK	1
CLR9185209186-1500-20 MARKER LT.AMBER LED	1
F6DZ-8100-A9C3Z8101B RADIATOR CAP 10238 STANT	1
PH361451348 OIL FILTER FOCUS	1
UMVS162511STRAP	2

**Workorder: V34967**

**In Date:** 09/15/2010

**Meter Reading:** 5.00

**Close Date:** 12/22/2010

**Problem?**

BATTERY CHARGER INOP, VOLLY FIRE BOAT

**Task performed:**

1. CHECK BATTERY CHARGER AND POWER CORD TO CHARGER, BATTERY CHARGER BLOWS CIRCUIT BREAKER WHEN PLUGGED IN.

**Parts**

**Quantity**

NO PARTS USED



6/26/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10169729

21FT OPEN FISHERMAN W/FIRE PUMP \*

**Workorder: V37301**

In Date: 12/20/2010

Meter Reading: 12.00

Close Date: 02/16/2011

**Problem?**

fire pump wont run vol 42

**Task performed:**

1. C/O motor; make up list & order new parts to get running; get SN #, etc.
2. Pull pump frm boat; replc carb, rem muffler & order msgng parts; rem starter switch & order new one; rebuilt & paint.
3. paint/replace all \_\_\_\_\_.
4. Rep all trailer \_\_\_\_\_ brakes, wires & burnt out \_\_\_\_\_.
5. Install marker ights on trailer.
6. Fab & fit exh pipe frm head to muffler on cyl on fire pump.
7. Fab exh pipe for head to muffler \_\_\_\_\_ & install muffler.
8. Replc \_\_\_\_\_ & shock \_\_\_\_\_.
9. Fab plate for primer pump & installl.
10. Rep/paint air filter box & replc air filter. j

**Parts**

**Quantity**

100-023CABLE	1
121200PUSH PULL CABLE	1
404-100 VALVE CORE	1
42359AIR FILTER HALE PUMP VOL. BOAT	1
43980LIGHT BRACKET	2
52958000050HAND PRIMER	1
67BULB 12 VOLT	1
91839183 SWITCH	1
G1503LIGHT ASSY LED	2

**Workorder: V40059**

In Date: 04/15/2011

Meter Reading: 83,095.00

Close Date: 05/17/2011

**Problem?**

steering not working properly. Sra 73.

**Task performed:**

1. install prop guard
2. check battery's, check battery charger, replace fuse holder for charger, ok
- 3 check steering system out, remove motor from steering bracket, problem is in steering assy., remove steering assy. clean and grease reinstall, still locks up on left turns.
4. Steering inop - cable/helm worn; replc cable/helm.
5. Install wiring for rear emergency lighting; mnt emergency lighting includes fab of brkts.
6. Replc btrys &install (4) pos btry switch; includes locate & order parts; rep wiring & fab btry mntng.
7. Forward/reverse selector wont lock in neutral; brkn lock - replc selector.
8. Chk brg cooling sys; low wtr press @ dash; cln out wtr passages, fittings/tubes, etc.
9. Rep gauges/wiring; volt drop @ buss bar; cldn/tightened all connections; rep instrument wiring.

**Parts**

**Quantity**

34-574Q34-574Q SWITCH	1
52691BATTERY BOX	2
8126482-2106 TOGGLE GUARD	2
M-754SWITCH BATTERY DUAL	1
RSC03ZCRTIR3 CLEAR WHITE	2
RSR03ZCRLIGHT LED RED TIR3 SERIES	2

j



6/26/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10169729

21FT OPEN FISHERMAN W/FIRE PUMP \*

**Workorder: V40816**

In Date: 05/24/2011

Meter Reading: 83,096.00

Close Date: 05/25/2011

**Problem?**

throttle cable for pump broken, M-920

**Task performed:**

1. throttle cable broken for the boat pump, per Ed W parts are not available, remove broken cable from housing and install new cable in old housing, adjust cable and run unit.

**Parts**

**Quantity**

100-019CABLE

1

**Workorder: V41071**

In Date: 06/02/2011

Meter Reading: 83,096.00

Close Date: 07/01/2011

**Problem?**

water pump.

**Task performed:**

pump not running properly  
throttle cable  
repaired throttle and repaired shut down  
ground and tune up engine test ok ak

**Parts**

**Quantity**

12-191833SEAL BLUE

1

144791DIAPHRAGM MERCURY 200HP

1

14480POPPET MERCURY 200HP

1

27-62386001GASKET MERCURY 200HP

2

27-78690002GASKET MERCURY 200HP

3

33757FUEL FILTER OUTBOARD

1

35-816296Q2FUEL FILTER MERCURY 200HP

1

46-96148A8PUMP KIT

1

75692THERMOSTAT MERCURY 200 HP

2

92-858064K01MERCURY GEAR LUBE

2

BU8HSPARK PLUG MERCURY 200HP

6

J19LMUSE 1147 NGK SPARK PLUG

2



6/26/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10169729

21FT OPEN FISHERMAN W/FIRE PUMP \*

**Workorder: V44059**

**In Date:** 09/30/2011

**Meter Reading:** 10.00

**Close Date:** 11/03/2011

**Problem?**

see list repair boat

**Task performed:**

1. Fuel leak/fuel lines & fittings; rep fuel leak; resealed fittings & replcd lines as needed.
2. PU parts @ West marine.
3. Install prop guard - brkn; installed new prop guage; had to rem/reinstall, was not mntd below cavitation plate; reinstalled properly.
4. Sea trial motor; spun hub trailer to lake & back.
5. Sea trial - chk over; fnd prop hub spin sea trial installed new prop; sent out old one for rep.
6. Rem prop.
7. Fire pump throttle inop - cable bad; tried to rep - needs a new cable\_\_\_; will replc, also needs new cntrl arm.
8. Sea trial boat w/new prop & chk pump opn.
9. Globe warning LED inop - light defective.
10. Trailer marker lights inop; (1) bad grd, (1) bad lamp asy; rep marker lights. j

Parts	Quantity
CLR9185209186-1500-20 MARKER LT.AMBER LED	1
L22HRPBEACON LED L22	1



6/26/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10169729

21FT OPEN FISHERMAN W/FIRE PUMP \*

Workorder: V54288

In Date: 12/07/2012

Meter Reading: 20.00

Close Date: 01/04/2013

**Problem?**

B inspection and install new pump

**Task performed:**

1. PERFORM B SERVICE.
2. CHANGE OUT PUMP MOTOR AND PUMP.
3. CHANGE OUT PUMP MOTORASSEMBLY.
4. WELD BOLTS TO BRACKET FOR MOTOR.
5. CONT CHANGING OVER PUMP MOTOR PUMP.
6. CONT CHANGING OVER PUMO MOTOR PUMP.
7. CONT COMPLETED PUMP MOTOR ASSEMBLY CHANGE OVER.
8. CONT SERV REPLACED FUEL FILTER REPLACED SPARK PLUGS CHANGED LOWER UNIT GEAR OIL GREASED MOTOR AND TRAILER.
9. REPLACED FUEL FILTER ON PUMP MOTOR (WRONG SIZE FOR HOSE) REMOUNTED FUEL LINE AWAY FROM NEW PUMP MPTPR.
10. WENT TO FUEL ISLAND WITH PUMP FUEL TANK AND FILLED CONNECTED FUEL TANL AND PRIMER. REPAIRED SMALL FUEL LEAK IN LINE.
11. STARTE PUMP MOTOR AND WORKED ALL CONTROLD ALL WORKING NORMALLY AT THIS TIM
12. TOWED BOAT TO MAKE TO HAVE NEW HOSES MADE FOR NEW PUMP MOTOR (INTAKE AND DISCHARGE).
13. WENT TO MAKE TO PICK UP BOAT AFTER HOSES WERE MADE.
14. REPLACED MARKER LIGHT ASSEMBLY ON BOAT TRAILER (CORODED/BROKEN) DRILL OUT BROKEN SCREWS. GRIND COROSION FRM TRAILER MOUNT AND WIRE NEW LIGHT.
15. REPLACED TRAILER JACK/FOOT ASSEMBLY TO JACK/BOLLER ASSEMBLY FABBED AND PAINTED BASE TO FIT PROPERLY (RUSTED /CORODED).
16. REMOVED OLD SAFETY CABLES AND S HOOKS (BROKEN/CORODED) ORDER NEW SAFTEY CABLE ASSEMBLIES ALSO REPAIRE EMG BREAK LOOSE CABLE FOR BRAKE LOCK DOWN (BROKEN).
17. FINSIH SERVICE.
18. RECIEVED NEW SAFETY CHAINS AND HOOKS FROM PARTS AND INSTALLED.
19. CHANGED BATTERIES ON BOAT HOOKED UP TOWS VEHICLE CHANGED BATTERIES ON TOW VEHICLE. WIPED DOWN BOAT AS BEST I COULD.

Parts	Quantity
121312HOSE AND FITTINGS	1
30852TRAILER JACK	1
33012FUEL FILTER 5/16	1
33757FUEL FILTER OUTBOARD	1
43239SAFETY CHAIN TRAILER	2
6431SPARK PLUG	2
80555CASTER WHEEL	1
92-858064K01MERCURY GEAR LUBE	2
CLR9185209186-1500-20 MARKER LT.AMBER LED	1
G1FUEL FILTER 33001	1



6/26/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10169729

**21FT OPEN FISHERMAN W/FIRE PUMP \***

**Workorder: V55902**

**In Date:** 02/21/2013

**Close Date:** 02/27/2013

**Meter Reading:** 20.00

**Problem?**

replace tires

**Task performed:**

REPLACE TIRES.

Parts

Quantity

NO PARTS USED

**Vendor?** BOULEVARD TIRE

---



6/26/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10169729

**21FT OPEN FISHERMAN W/FIRE PUMP \***

**Workorder: V55749**

**In Date:** 02/14/2013

**Meter Reading:** 20.00

**Close Date:** 03/07/2013

**Problem?**

Trailer jack needs replacement Check tachometer on boat

**Task performed:**

Parts

Quantity





6/26/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10169729

### 21FT OPEN FISHERMAN W/FIRE PUMP \*

1. CHECKED OUT TRAILER TORQUE/HITCH AND CRANK. REMOVED TORQUE/MASTER CYLINDER ASSEMBLY. ALSO PROVIDED PARTS DEPT. WITH PART # FOR CRANK ASSEMBLY. ORDERED ALL PARTS.
2. DRILLED NEW HOLES IN TRAILER TO REMOUNT CRANK ASSEMBLY IN NEW LOCATION. ALSO DISASSEMBLED CRANK TO CLEAN AND LUBE AND REASSEMBLED. (RUSTED/BINDING).
3. BEGAN CHECKING OUT TACHOMETER INOP.
4. CONTINUED TROUBLESHOOT OF TARCHOMETER PROBLEM. TRACED PROBLEM TO POSSIBLE FAULTY TACH. ORDERED NEW TACH.
5. BEGAN INSTALLING PREVIOUSLY ORDERED TRAILER PARTS: INSTALLED NEW WINCH STRAP, INSTALL REBUILD KIT FOR RATCHET ASSEMBLY ON WINCH AND INSTALLED NEW BOW ROLLER ON FRONT OF TRAILER.
6. CONTINUED INSTALLING TRAILER PARTS. INSTALLED NEW TRAILER JACK, ALTERED MOUNTING BRACKET TO ENABLE MOUNTING TO TRAILER, DRILLED OUT PIN TO ACCOMODATE ROLLER.
7. INSTALLED NEW HITCH/MASTER CYL. ASSEMBLY, BENCH BLED MASTER CYLINDER, MOUNTED UNIT, CONNECTED BRAKE LINE AND REWIRED REVERSE CYLINDER LOCK OUT.
8. REMOVED TRAILER TIRES TO BLEED BRAKES AND FOUND TRILER IN NEED OF BRAKE ROTORS, PADS AND POSSIBLY CALIPERS. BEGAN REMOVAL OF ALL MENTIONED PARTS.
9. CONTINUED REMOVAL AND CLEANING OF WHEEL BEARINGS AND HARDWARE. ALSO ORDERED ALL NEEDED NEW PARTS.
10. RECEIVED ALL PARTS FOR BRAKES AND SAFETY CHAIN. FABBED CHAIN TO PROPER LENGTH FOR SAFETY CHAIN, DRILLED MOUNTING HOLES IN TRAILER AND MOUNTED CHAIN. INSTALLED CLASP AND CONNECTING LINK.
11. INSTALLED NEW ROTORS WITH NEW BEARING AND SEALS. PACKED BEARINGS AND PRELOADED. LOADED NEW BRAKE PADS INTO NEW CALIPERS AND INSTALLED BLED BRAKES. ANTISIEZED WHEEL STUDS AND INSTALLED WHEELS WITH NEW TIRES AND LUG NUTS.
12. ASSIST IN REPAIRES.
13. RECEIVED TACHOMETER FROM PARTS DEPT CONNECTED ALL WIRES STARTED ENGINE. FOUND TACH WORKING DURING CRANKING BUT WOULD NOT WORK AFTER ENGINE WAS RUNNING. PERFORMED SOME TROUBLESHOOTING WITH TECH LINE AND BELIEVE PROBLEM IS IN STATOR. BOAT WILL HAVE TOGO TO MARINE TECHNICIAN.
14. CONNECTED BOAT TO TRUCK, PULLED BOAT

13854617FUEL CONNECTOR	2
13854641FUEL CONNECTOR	2
1562STRAP KIT	1
205544TACH	1
2850LINK 1/4	1
2854QUICK LINK	1
2880SNAP HOOK	1
2883SNAP HOOK	1
30852TRAILER JACK	1
3116BOW ROLLER	1
3118BELL END	2
3654TRAILER STRAP	1
4258LUG NUTS	12
47211TRAILER ACTUATOR	1
5888BRAKE KIT ASSY	1



6/26/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10169729

21FT OPEN FISHERMAN W/FIRE PUMP \*

INTO BAY AND CHARGED BATTERIES.

**Workorder: V50260**

In Date: 06/20/2012

Meter Reading: 10.00

Close Date: 04/11/2013

**Problem?**

Hoses that go from gas tank to motor need to be replaced

Task performed:

Parts

Quantity

NO PARTS USED

**Workorder: V44452**

In Date: 01/01/1900

Meter Reading:

Close Date: 04/23/2013

**Problem?**

Outside repair of prop

Task performed:

Parts

Quantity

NO PARTS USED

**Workorder: V57712**

In Date: 05/14/2013

Meter Reading: 45.00

Close Date: 05/16/2013

**Problem?**

Repair emergency LED lighting [front] Marine radio inop

Task performed:

Parts

Quantity

DIAGNOSE ELECTRICAL SYSTEM. R&R TO GAIN ACCESS REPAIR MARINE RADIO AND FRT AND REAR STROBES.

NO PARTS USED

**Workorder: V56973**

In Date: 04/11/2013

Meter Reading: 45.00

Close Date: 06/06/2013

**Problem?**

repair tach

Task performed:

Parts

Quantity

NO PARTS USED



6/26/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10169729

21FT OPEN FISHERMAN W/FIRE PUMP \*

**Workorder: V58233**

In Date: 06/06/2013

Meter Reading: 50.00

Close Date: 06/06/2013

**Problem?**

Replace trailer jack wheel

**Task performed:**

Parts

Quantity

80555CASTER WHEEL

1

**Workorder: V63784**

In Date: 01/28/2014

Meter Reading: 10.00

Close Date: 02/12/2014

**Problem?**

install exhaust system, service fire pump, Marine- 970

**Task performed:**

Parts

Quantity

1. remove rusted exhaust system on fire pump, remove primer assy., install new exhaust system, primer assy, and all new fittings, install new primer cable,

006009D RING

6

2. replace foot man loops on l/side front bow, replace foot man loops on battery box cover, test battery's, failed test, new battery's on order, remove front discharge valves for preconnect hoses, found valves hard to open due to salt water, clean and lube both valves and reinste

2150SAMG DEEP CYCLE

2

33757FUEL FILTER OUTBOARD

1

50-20WIPER BLADE

2

51348OIL FILTER

1

6962SPARK PLUG QC12YC

2

9705897058 CONNECTOR

2

A0631117000HORN HIGH NEW # 06-52125-039

1

A0631117003HORN LOW NEW #06-52125-041

1

B2-LMB2-LM SPARK PLUG

2

G1FUEL FILTER 33001

2

RSR03ZCRLIGHT LED RED TIR3 SERIES

4

SPT6008146SL LIGHT-REMOTE SPOT

1

3. service pump motor, replace fuel lines from gas filter to carb, remount fuel tank for pump motor, install foot man loops and straps for fuel tank, tune up pump motor, repack wheel bearings for trailer

4. replace battery's, clean terminals and seal. check battery charger, found blown fuse

5. fire pump motor will not start from push button switch, trace out wiring, found voltage drop at battery disconnect to motor corroded, replace disconnect connector, crimp and solder cables, and heat shrink

6. front spot light inop, trace wiring found control head and connectors corroded, replace control head, light comes on but does not move, install new search light and wiring on bow of boat, heat shrink wires

7. run motor and check all lights and radio's, top off oil, replace foot man loops on battery cover and back board tie downs



6/26/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10169729

**21FT OPEN FISHERMAN W/FIRE PUMP \***

**Workorder: V64567**

In Date: 02/12/2014 Meter Reading: 10.00

Close Date: 02/27/2014

**Problem?**

install fuel shut off for outboard motor, Marine-970

**Task performed:**

Parts

Quantity

1. make up fittings for shutoff valve, mount valve on rear of boat for outboard motor, install new fuel lines to valve

NO PARTS USED

**Workorder: V64857**

In Date: 03/11/2014 Meter Reading: 10.00

Close Date: 03/18/2014

**Problem?**

1 of the new battery's are dead, Marine 970

**Task performed:**

Parts

Quantity

1. check battery's found 1 battery at 4.8 volts, charge battery's, check battery charger found 1 leg of charger inop, other leg charging, order battery charger, also found bad ground, add ground cable to battery's, per vendor battery that is that low will need to be charged 24 to 36 hours then tested.

NO PARTS USED

2. battery's fully charged, install new on board battery charger, rewire to shore plug,

**Workorder: V59651**

In Date: 08/07/2013 Meter Reading: 60.00

Close Date: 03/19/2014

**Problem?**

Parts only for S.O. to repair boat

**Task performed:**

Parts

Quantity

PARTS ONLY NO LABOR.

1165067KEEL GAURD

1

546-6280-00-0HALE MUFFLER KIT

1

**Workorder: V59902**

In Date: 08/19/2013 Meter Reading: 60.00

Close Date: 03/19/2014

**Problem?**

gaskets

**Task performed:**

Parts

Quantity

PARTS ONLY NO LABOR.

4BOLTGASK4 IN ANSI GASKET

4



6/26/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10169729

21FT OPEN FISHERMAN W/FIRE PUMP \*

### Workorder: V65065

In Date: 03/20/2014

Meter Reading: 10.00

Close Date: 03/20/2014

#### Problem?

mirror broken, marine-970

#### Task performed:

1. remove broken mirror mount, sand and paint mirror mount, install new mirror and bracket, install on front console

\* had a DNI rear view mirror in stock, which was used

#### Parts

NO PARTS USED

#### Quantity

### Workorder: V65071

In Date: 03/20/2014

Meter Reading: 10.00

Close Date: 04/24/2014

#### Problem?

Install battery charger

#### Task performed:

installed on w/o#64857

#### Parts

9368606MARINE CHARGER

#### Quantity

1

### Workorder: V65944

In Date: 04/24/2014

Meter Reading: 10.00

Close Date: 05/02/2014

#### Problem?

Install batter charger

#### Task performed:

1. BEGAN INSTALLATION OF BATTERY CHARGER.  
2. CONTINUED INSTALLATION OF BATTERY CHARGER AND AUTO EJECT REMOVED BATTERIES AND ORDERED NEW. REPAIRED BATTERY HOLD DOWN AND TRAY. (BROKEN MOUNTING BOLTS).

3. MOUNTED LIFE PERSERVER AND MOUNTING BRACKET BRACKET. STRAIGHTEN CENTER CONSOLE ENTRY DOOR HOLD OPEN BRACKET (BENT) FILLED NUMEROUS HOLES IN CENTER CONSOLE.

4. GOT NEW BATTERIES FROM PARTS AND INSTALLED, COMPLETED FOUND WIRING OF BATTERY CHARGER. MADE ADAPTER EXTENSION CORD FOR AUTO EJECT PLUGGED SYSTEM IN AND CHECKED CHARGER OPERATION. ALL IS NORMAL.

#### Parts

091-20WP-120AUTO EJECT

14152169CHARGER PRO SPORT

8A24MAGM MARINE BATTERY

BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTER

#### Quantity

1

1

2

2



6/26/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10169729

21FT OPEN FISHERMAN W/FIRE PUMP \*

**Workorder: V67072**

In Date: 06/09/2014

Meter Reading: 10.00

Close Date: 07/23/2014

**Problem?**

make up shore line, Marine-970

**Task performed:**

repairs complete on ticket v65944

**Parts**

**Quantity**

03-32613-004BRACKET	1
03-32976-616ISOLATOR	1
03-33412-696ISOLATOR	1
5-20PH1PGK4 CONNECTOR 120V 20A FEMALE	2
A03-33883-004BAND FUEL	1
FRT V66885FREIGHT CHARGE	1

**Workorder: V68753**

In Date: 08/18/2014

Meter Reading: 10.00

Close Date: 09/16/2014

**Problem?**

repair parts

**Task performed:**

part were deliver to south shop by light duty personal close ticket per John M.

**Parts**

**Quantity**

14533426EXPLORER COMPAC	1
19431SEACHOICE FLOAT SWITCH	2
5362371COVER CONSOL	3
FRT 65616FREIGHT CHARGE	1
FRT 65980FREIGHT CHARGE	2
R-2000G2000 SERIES GOLD	2

**Workorder: V69724**

In Date: 09/26/2014

Meter Reading: 10.00

Close Date: 10/10/2014

**Problem?**

Needs a new battery charger Parts only

**Task performed:**

Parts only

**Parts**

**Quantity**

14152151PRO SPORT CHARGER	1
---------------------------	---



6/26/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10169729

21FT OPEN FISHERMAN W/FIRE PUMP \*

**Workorder: V70829**

In Date: 11/10/2014

Meter Reading: 10.00

Close Date: 11/25/2014

**Problem?**

rebuild boat pump

**Task performed:**

1. Clean and or replace all auxillary components. Assemble all sections of pump.

2. Measure and cut a 10 ft. soft suction hose to be 5 ft. R & R one end coupling.

3. Go over suction and discharge options for repaired fire pump.

4. Assemble discharge manifold, gate valve and suction adapter.

5. Tried to match threads on new discharge manifold shipped with pump. No good. Had to disassemble and clean old discharge adapter for re-use.

6. Remove corroded stack tip on deckgun. Had to cut and chisel into small pieces until removed. Clean threads of all salt corrosion. Install new stack section.

**Parts**

**Quantity**

069894HP300 REBUILD KIT	1
103385NDRAIN COCK	1
1120800SCREEN 4 INCH SCREEN	2

**Workorder: V70051**

In Date: 10/10/2014

Meter Reading: 10.00

Close Date: 12/24/2014

**Problem?**

Parts for shore power

**Task performed:**

**Parts**

**Quantity**

12998415ADAPTER POWER CORD	1
12998449ADAPTER POWER Y	1
13854732FUEL FITTING CONNECT	2
13854740CONNECT FUEL FITTING	2
487134HOSE AND FITTING	1
488570*	1
5528492DOCK LINE	2
5528500DOCK LINE	2
5528518DOCK LINE	2
5528831DOCK LINE	4
SAHSVS2510STRAP	2
UMVS162511STRAP	2



# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

Asset: (10169729) 1993 - WAHOO 21FT Open Fisherman W Fire Pump

10169729

### CSHOP-2017-1750

Comments: **REPAIR BOAT TRAILER PLEASE CHECK THE BRAKE LIGHTS ON THIS TRAILER ALSO**  
Date Opened: 3-22-2017      Date Finished: 5-3-2017      Meter 1 Reading: 10

#### TASKS PERFORMED

#### Q      PARTS

BRAKE LIGHTS	1	LIGHT; 9186-1500-20 MARKER LT.AMBER LED
WHEEL STUDS	4	9AP; 8.75R16 FIRESTONE
TIRES & WHEELS	1	TIR; TIRE MOUNTING
BUMPER FRONT	4	9AP; 16.5X6.75 WHEEL

### CSHOP-2017-3673

Comments: **PREP FOR SURPLUS**  
Date Opened: 6-22-2017      Date Finished: 6-23-2017      Meter 1 Reading: 10

#### TASKS PERFORMED

#### NO PARTS USED

SURPLUS PREP