

10/17/2016
2:52:55PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169542 2008 FORD F350 Utility Body, 1 Ton, 4X4, W/ Tow Pkg

Workorder: 835966 **Problem:** PRE-DELIVERY INSPECTION

Meter Reading: 0	Labor	Parts
In Date: 03/24/2008	Hours	Description
Close Date: 03/24/2008	Quantity	
- Pre-Delivery Inspection	4.00	
Parts Charge: 0.00	Labor Charge: 240.00	

Workorder: 836929 **Problem:** INSTALL COMPUTER STAND.

Meter Reading: 1109	Labor	Parts
In Date: 04/14/2008	Hours	Description
Close Date: 04/15/2008	Quantity	
- Fabricate,Mount And Wire Computer Stand.	4.00	SHOP SUPPLIES
- Shop Supplies		1.00
Parts Charge: 2.00	Labor Charge: 240.00	

Workorder: 841220 **Problem:** P.M SERVICE,SEE NOTE

Meter Reading: 4430	Labor	Parts
In Date: 07/10/2008	Hours	Description
Close Date: 07/22/2008	Quantity	
- Pm Service	9.00	CA10270 AIR FILTER MTC FA1886 WIX 49886
- Rotate High Speed Balance All 6 Tires,Repair L/Rear Inner Flat Tire.		7312 OIL FILTERFRM CH9549 WIX 57312
- Nitrogen Service On 6 Tires.		15/40 OIL
- Fabricate & Reposition Striken To Correct Problem On Utility Door.		USED FIREX REFURBED FIRE EXTINGSHERS
- Shop Supplies		CS10263 FUEL FILTER (USE CS10263A)
		SHOP SUPPLIES
Parts Charge: 204.08	Labor Charge: 60.00	

Workorder: 846147 **Problem:** 001 KEY ISSUED OUT 10/24/08

Meter Reading: 0	Labor	Parts
In Date: 10/24/2008	Hours	Description
Close Date: 10/24/2008	Quantity	
- 001 Key Issued Out	0.20	DUPLICATE VEHICLE KEYS
Parts Charge: 3.00	Labor Charge: 12.00	

10/17/2016
2:52:55PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169542 2008 FORD F350 Utility Body, 1 Ton, 4X4, W/ Tow Pkg

Workorder: 933997

Problem: RECALL,CHECK FLOOR MAT.P.M SERVICE

Meter Reading: 7147	Labor	Parts	
In Date: 02/13/2009	Hours	Description	Quantity
- Pm Service	7.50	SHOP SUPPLIES	1.00
- Replace Missing Pindle Hitch Safety Pin.		15/40 OIL	15.00
- Remove And Reinstall Computer Stand And Fire Ext. Bracket		7312 OIL FILTERFRM CH9549 WIX 57312	1.00
- Install Floor Mats.		CS10263 FUEL FILTER (USE CS10263A)	1.00
- Transport Vehicle To And Fr Dealer For Warranty Repairs.		18410 PINTLE PIN	1.00
- Shop Supplies		FRONT FLOOR MAT SET	1.00
		PM-22-A ADDITIVE DIESEL FUEL (M/CRAFT)	1.00
Parts Charge:	188.42	Labor Charge:	390.00

Workorder: 944268

Problem: pm service also see notes on installing water tank

Meter Reading: 9368	Labor	Parts	
In Date: 10/07/2009	Hours	Description	Quantity
- P.M Service.	7.50	1/2"X2"X20' ALUM FLAT BAR	4.00
- Fabricate Mount System & Install Customers 16 Gal Water Tank.		7312 OIL FILTERFRM CH9549 WIX 57312	1.00
- Rotate & Balance All Six Tires.		USED FIREX REFURBED FIRE EXTINGSHERS	1.00
- Shop Supplies		15/40 OIL	15.00
		SHOP SUPPLIES	1.00
		CA10270 AIR FILTER MTC FA1886 WIX 49886	1.00
		31-20 WIPER BLADES 20" BLADE	2.00
		CS10263 FUEL FILTER (USE CS10263A)	1.00
		WD40 SPRAY LUBE STOCK# 405540002	1.00
Parts Charge:	163.28	Labor Charge:	450.00
		Commercial Charge:	46.80

10/17/2016
2:52:55PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169542 2008 FORD F350 Utility Body, 1 Ton, 4X4, W/ Tow Pkg

Workorder: 1003920

Problem: P.M service, battery going dead.

Meter Reading: 11601	Labor	Parts	
In Date: 04/15/2010	Hours	Description	Quantity
- P.M Service.	7.50	SHOP SUPPLIES	1.00
- Test Starting & Charging System, Charge & Test Both		GROUP 65 BATTERY (MTC BXT-65-850)	2.00
Batteries, Both Batteries Failed Load Test, Replace Both		15/40 OIL	15.00
Defective Batteries.		TIRE DISPOSAL FEE	2.00
- Mount, Balance & Nitro Fill Two New Front Tires.		7312 OIL FILTERFRM CH9549 WIX 57312	1.00
- Fabricate New Ground For Center Rear Marker Lamps On		WWASHER NOZZLE	1.00
Utility Box.		CS10263 FUEL FILTER (USE CS10263A)	1.00
- Shop Supplies		179636492 LT245/75R17 WRANGLER SR-A E	2.00
Parts Charge: 733.28		Labor Charge: 450.00	

Workorder: 1004646

Problem: damage to frt bumper & grille

Meter Reading: 11601	Labor	Parts	
In Date: 04/23/2010	Hours	Description	Quantity
- Damage To Frt Bumper & Grille			
Parts Charge: 0.00		Labor Charge: 0.00	Commercial Charge: 1,231.42

Workorder: 1007309

Problem: Check engine light on. Regen light on.

Meter Reading: 13092	Labor	Parts	
In Date: 07/12/2010	Hours	Description	Quantity
- Transport Vehicle To Dealer For Check Engine And	2.00	SHOP SUPPLIES	1.00
Regen. Light Stays On.(Tsb. Reprogram Pcm.)			
- Shop Supplies			
Parts Charge: 2.00		Labor Charge: 60.00	

10/17/2016
2:52:55PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169542 2008 FORD F350 Utility Body, 1 Ton, 4X4, W/ Tow Pkg

Workorder: 1011203

Problem: Pm service also see notes center console and flat tire.

Meter Reading: 14389	Labor	Parts		
In Date: 10/12/2010	Hours	Description	Quantity	
- P.M. Service.	10.25	15/40 OIL	15.00	
- Replace Four Tires,Rotate And Balance All Six.		7312 OIL FILTERFRM CH9549 WIX 57312	1.00	
- Replace Missing Pintle Pin.		179636492 LT245/75R17 WRANGLER SR-A E	4.00	
- Replace Missing Door Striker And Door Stop Chain In Utility Bed.		TIRE DISPOSAL FEE	4.00	
- Complete Wheel Alignment.		CS10263 FUEL FILTER (USE CS10263A)	1.00	
- Shop Supplies		TR416 VALVE STEM	4.00	
		18410 PINTLE PIN	1.00	
		61A P/STEERING FLUID	1.00	
		31-20 WIPER BLADES 20" BLADE	2.00	
		USED FIREX REFURBED FIRE EXTINGSHERS	1.00	
		SHOP SUPPLIES	1.00	
		PM-22-A ADDITIVE DIESEL FUEL (M/CRAFT)	1.00	
Parts Charge:	876.22	Labor Charge:	615.00	

Workorder: 1103885

Problem: R/R flat tire

Meter Reading: 17746	Labor	Parts		
In Date: 03/28/2011	Hours	Description	Quantity	
- 4100 40Th Street North, Loxahatchee				
Parts Charge:	0.00	Labor Charge:	0.00	Commercial Charge: 66.00

10/17/2016
2:52:55PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169542 2008 FORD F350 Utility Body, 1 Ton, 4X4, W/ Tow Pkg

Workorder: 1105437

Problem: P.M. service.

Meter Reading: 18615 In Date: 05/23/2011	Close Date: 06/06/2011	Labor Hours	Description	Parts	Quantity
- Perform Pm Service.		7.75	SHOP SUPPLIES		1.00
- Install One New Tire To The Right Rear Wheel.Nitrogen Fill And Balance All Six.			CS10263 FUEL FILTER (USE CS10263A) 15/40 OIL		1.00 15.00
- Diagnose Blower Low Speed Inop.Test And Replace Failed Blower Motor Resistor With New.			7312 OIL FILTERFRM CH9549 WIX 57312 CA10270 AIR FILTER MTC FA1886 WIX 49886		1.00 1.00
- Dismantle Light Bar.Test And Replace Failed Right Side Alley Lamp Bulb With New.			31-20 WIPER BLADES 20" BLADE 18410 PINTLE PIN		2.00 1.00
- Shop Supplies			YH1715 A/C BLOWER RESISTOR (MOTORCRAFT) 179636492 LT245/75R17 WRANGLER SR-A E FXAM1 LIGHT SOCKET ASSY (WHELEN) 05046 BATTERY PROTECTOR (CRC) TIRE DISPOSAL FEE		1.00 1.00 1.00 1.00 1.00
Parts Charge:		409.49	Labor Charge:		465.00

Workorder: 1113196

Problem: P.M. service and right rear tires going flat and A/C inop blows warm.

Meter Reading: 23313 In Date: 12/15/2011	Close Date: 01/04/2012	Labor Hours	Description	Parts	Quantity
- P.M. Service.		13.00	15/40 OIL		15.00
- Pereformance And Leak Test A/C System.Replace Leaking High Side Hose.Evacuate And Recharge Sytem.			3963 FUEL FILTER FRM CS10263A WIX 33963 UPPER RADIATOR HOSE		1.00 1.00
- Pressure Test Cooling System.Replace Leaking Upper Radiator Hose.Flush And Refill Cooling System.			31-20 WIPER BLADES 20" BLADE 7312 OIL FILTERFRM CH9549 WIX 57312		2.00 1.00
- Repair Right Rear Tire,Rotate And Balance All Six.			SEAL KIT		1.00
- Repair Wiring To Tag Lamp.			SHOP SUPPLIES		1.00
- Shop Supplies			USED FIREX REFURBED FIRE EXTINGSHERS R134A REFRIGERANT O-RING ANTIFREEZE EXT/LIFE ALL MAKES (PEAK 407) A/C HIGH SIDE HOSE CAP		1.00 2.00 1.00 2.00 1.00 1.00
Parts Charge:		332.71	Labor Charge:		780.00

10/17/2016
2:52:55PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169542 2008 FORD F350 Utility Body, 1 Ton, 4X4, W/ Tow Pkg

Workorder: 1200035

Problem: fab / mount vise

Meter Reading: 23313	Labor	Parts	
In Date: 01/03/2012	Hours	Description	Quantity
- Fab/ Weld Vise Mount And Install Vise	4.50	3/8X3X20 STEEL FLAT BAR	6.00
- Shop Supplies		SHOP SUPPLIES	1.00
		66997 COMBO VISE (RIGID F-60)	1.00
		3/4X3X12 CRS FLAT BAR	7.00
Parts Charge:	553.10	Labor Charge:	270.00

Workorder: 1204506

Problem: P.M. service.

Meter Reading: 29769	Labor	Parts	
In Date: 05/11/2012	Hours	Description	Quantity
- Perform Pm Service.	16.50	RADIATOR	1.00
- Pressure Test And Inspect Cooling System.Test And Replace Failed Radiator Assembly And Lower Coolant Hose With New.Reverse Flush Cooling System And Renew Coolant.		ANTIFREEZE EXT/LIFE ALL MAKES (PEAK 407)	2.00
		7312 OIL FILTERFRM CH9549 WIX 57312	1.00
		31-20 WIPER BLADES 20" BLADE	2.00
		3963 FUEL FILTER FRM CS10263A WIX 33963	1.00
- Dismantle Light Bar.Test And Replace Failed Left Alley Lamp Bulb And Socket With New.Fabricate Wiring Harness.		ALLEY LAMP SOCKET	1.00
		TIRE DISPOSAL FEE	4.00
		15/40 OIL	15.00
- Install Four New Tires.Nitrogen Fill And Balance All Six.		179636492 LT245/75R17 WRANGLER SR-A E	4.00
- Perform Wheel Alignment Complete.		LOWER RADIATOR HOSE	1.00
- Shop Supplies		SHOP SUPPLIES	1.00
		TR416 VALVE STEM	4.00
		46-0763846-13 SOCKET MR11 BULB	1.00
Parts Charge:	1,803.84	Labor Charge:	990.00

Workorder: 1205722

Problem: Coolant leak and check over all lights.

Meter Reading: 31334	Labor	Parts	
In Date: 06/15/2012	Hours	Description	Quantity
- Perform Cooling System Pressure Test.Replace Defective Radiator(Warranty)Refill System And Retest.	5.50	SHOP SUPPLIES	1.00
- Check Parking Lights,Fuse Blown.Trace And Repair Short.Replace Blown Fuses.			
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	330.00

10/17/2016
2:52:55PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169542 2008 FORD F350 Utility Body, 1 Ton, 4X4, W/ Tow Pkg

Workorder: 1207579

Problem: Left rear outter tire flat.

Meter Reading: 34103	Labor	Parts	Quantity
In Date: 08/13/2012	Hours	Description	Quantity
- Repair And Balanceouter Left Rear Tire.	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge: 2.00	Labor Charge: 60.00		

Workorder: 1209020

Problem: Pm service.Park lamps keep shorting fuse.Request to install tool box/fuel tank,see notes.

Meter Reading: 36252	Labor	Parts	Quantity
In Date: 09/20/2012	Hours	Description	Quantity
- P.M. Service.	14.50	CH9549 OIL FILTER MTC	1.00
- Trace And Repair Short In Ground Circuit For Rear Marker		USED FIREX REFURBED F	1.00
Lights.Replace Left Rear Marker Lamp And Fuse.		19006R MARKER LIGHT 4	1.00
- Replace Two Tires,Rotate And Balance All Six.		12 VDC PUMP 15 GPM	1.00
- Fabricate And Install Aux. Fuel Tank In Truck Bed.Install		NAPA GAL 15W40	15.00
And Wire Pump And Meter.		CS10263A FUEL FILTER	1.00
- Shop Supplies		SHOP SUPPLIES	1.00
		CA10270 AIR FILTER MT	1.00
		31-20 WIPER BLADES 20	2.00
		PUMP FLOW METER	1.00
		80865 FUSEHOLDER IMPE	1.00
		FILTER KIT	1.00
		179636492 LT245-75R17	2.00
Parts Charge: 1,976.62	Labor Charge: 870.00		

Workorder: 1209662

Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

Meter Reading: 36252	Labor	Parts	Quantity
In Date: 10/10/2012	Hours	Description	Quantity
- 1 - Detail Vehicle Wash Ticket(S) Issued			
Parts Charge: 0.00	Labor Charge: 0.00	Commercial Charge: 97.92	

10/17/2016
2:52:55PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169542 2008 FORD F350 Utility Body, 1 Ton, 4X4, W/ Tow Pkg

Workorder: 1301426

Problem: P.M. service.

Meter Reading: 45099		Labor		Parts	
In Date: 02/08/2013	Close Date: 02/27/2013	Hours	Description	Quantity	
-	P.M. Service.	6.50	HYDRAULIC HOSE	28.00	
-	Inspect And Service Aux. Fuel Tank.		15-40 OIL	15.00	
-	Rotate And Balance All Tires.		OIL FILTER	1.00	
-	Shop Supplies		NAPAGOLD FUEL FILTER	1.00	
			31-20 WIPER BLADES 20	2.00	
			FUEL FILTER 260HS-30	1.00	
			SHOP SUPPLIES	1.00	
Parts Charge: 145.60		Labor Charge: 390.00			

Workorder: 1306410

Problem: Pm service.Check trailer plug circuits,left rear bed door damage and front bumper

Meter Reading: 51941		Labor		Parts	
In Date: 06/26/2013	Close Date: 07/18/2013	Hours	Description	Quantity	
-	P.M. Service.	19.00	SHOP SUPPLIES	1.00	
-	Inspect And Service Aux. Fuel Tank.		31-20 WIPER BLADES 20	2.00	
-	Check Batteries And Charging System.Replace Both Bad Batteries.		TIRE DISPOSAL FEE	2.00	
-	Replace Left Rear Light Assemble.Diagnose Inop		USED FIRE X REFURBISHED	1.00	
-	Lightbar.Replair Coroded Wiring Close To Battery..Repair		FMX-30 FUSE	2.00	
-	Wiring To Center Light Below Tailgate.		BRAKE PADS	1.00	
-	Replace Two Tires,Rotate And Balance All Six.		44202R TAIL LIGHT 4IN	1.00	
-	Resurface Rear Brake Rotors,Replace Rear Brake		1401 BRAKE FLUID BRA	1.00	
-	Pads.Service And Lube Calipers.Flush And Bleed System		NAPAGOLD FUEL FILTER	1.00	
-	And Road Test.		NAPAGOLD FUEL FILTER	1.00	
-	Complete Wheel Alignment.Test Drive.		NAPAGOLD OIL FILTER	1.00	
-	Shop Supplies		BATTERY	2.00	
			BRAKE CLEANER	1.00	
			15-40 OIL	15.00	
			179636492 LT245-75R17	2.00	
Parts Charge: 967.79		Labor Charge: 1,140.00			

10/17/2016
2:52:55PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169542 2008 FORD F350 Utility Body, 1 Ton, 4X4, W/ Tow Pkg

Workorder: 1310753

Problem: needs 3 body keys

Meter Reading: 58050	Labor	Parts	
In Date: 10/28/2013	Hours	Description	Quantity
- Secure Keys For Dept	0.50	READING BODY KEYS	3.00
- Shop Supplies		Freight Charge	1.00
		SHOP SUPPLIES	1.00
Parts Charge:	28.75	Labor Charge:	30.00

Workorder: 1311553

Problem: P.M. service.

Meter Reading: 58881	Labor	Parts	
In Date: 11/15/2013	Hours	Description	Quantity
- P.M. Service.	17.50	NAPAGOLD OIL FILTER	1.00
- Replace Four Tires,Rotate And Balance All Six.		FUEL FILTER FORD ONLY	1.00
- Resurface Front And Rear Brake Rotors,Replace Brake Pads.Service And Lube Caliper.Flush And Bleed System.		179636492 LT245-75R17	4.00
- Inspect And Service Aux. Fuel System.		BRAKE PADS	1.00
- Replace Right Rear Marker Lamp.		2232 BRAKE FLUID QUAR	1.00
- Shop Supplies		NAPAGOLD FUEL FILTER	1.00
		TR416 VALVE STEM	4.00
		REAR PADS	1.00
		USED FIRE X REFURBISHED	1.00
		TIRE DISPOSAL FEE	4.00
		M C LAMP	1.00
		WIPER BLADE	2.00
		SHOP SUPPLIES	1.00
		15-40 OIL	15.00
Parts Charge:	1,314.77	Labor Charge:	1,050.00

Workorder: 1401874

Problem: 2 - Key(s) issued

Meter Reading: 61544	Labor	Parts	
In Date: 02/26/2014	Hours	Description	Quantity
- 2 - Key(S) Issued	0.40	DUPLICATE VEHICLE KEYS	2.00
Parts Charge:	6.00	Labor Charge:	36.00

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169542 2008 FORD F350 Utility Body, 1 Ton, 4X4, W/ Tow Pkg

Workorder: 1402279 **Problem:** 1 - Key(s) issued

Meter Reading: 61544	Labor	Parts
In Date: 03/07/2014	Hours	Description
Close Date: 03/07/2014		Quantity
- 1 - Key(S) Issued	0.20	DUPLICATE VEHICLE KEYS
Parts Charge: 3.00	Labor Charge: 18.00	1.00

Workorder: 1403246 **Problem:** Light Tower

Meter Reading: 67841	Labor	Parts
In Date: 04/02/2014	Hours	Description
Close Date: 07/15/2014		Quantity
- Install Go Light In Bed. Wire Unit	8.50	HITCH MOUNT LIGHT POLE
- Test Run		FUSE HOLDER
- Shop Supplies		POWER SUPPLY CORD
		PERMANENT MOUNT W WIR
		SHOP SUPPLIES
		U-BOLT
Parts Charge: 793.07	Labor Charge: 510.00	1.00
		1.00
		1.00
		1.00
		1.00
		2.00

Workorder: 1404314 **Problem:** Pm service.

Meter Reading: 65102	Labor	Parts
In Date: 05/02/2014	Hours	Description
Close Date: 05/14/2014		Quantity
- Perform Pm Service.	9.00	SHOP SUPPLIES
- Inspect And Service Auxiliary Fuel Tank.		TRANS FILTER
- Inspect And Service Transmission.Replace Filter And		15-40 OIL
Gasket With New.Flush And Renew Transmission Fluid.		FUEL FILTER FORD ONLY
- Rotate And Balance All Six Tires.		BIGG DEGREASER
- Shop Supplies		SYN-ATF TRANS FLUID S
		PLATINUM FILTER KIT
		WIPER BLADE
		NAPAGOLD FUEL FILTER
		NAPAGOLD AIR FILTER
		NAPAGOLD OIL FILTER
Parts Charge: 321.47	Labor Charge: 540.00	1.00
		1.00
		15.00
		1.00
		1.00
		16.00
		1.00
		2.00
		1.00
		1.00
		1.00

10/17/2016
2:52:55PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169542 2008 FORD F350 Utility Body, 1 Ton, 4X4, W/ Tow Pkg

Workorder: 1406383

Problem: Lock cylinder for utility bed vandalised.Send to HE Shop to fabricate and install light tower.

Meter Reading: 67841	Labor	Parts	
In Date: 06/30/2014	Hours	Description	Quantity
- Fabricate And Replace Damage/Vandalised Door Lock Cylinder On Left Front Door Of Utility Body With New.	1.00	LOCK CLINDER SHOP SUPPLIES	1.00 1.00
- Shop Supplies			
Parts Charge:	15.20	Labor Charge:	60.00

Workorder: 1411462

Problem: Pm service.Check four wheel driver selector

Meter Reading: 73207	Labor	Parts	
In Date: 11/17/2014	Hours	Description	Quantity
- Pm Service.	14.25	15-40 OIL	15.00
- Disassemble Light Bar To Aceso And Replace Defective Right Side Alley Lamp Bulb And Socket.		WIPER BLADE	2.00
- Check And Replace Worn Transfer Case Shift Lever Assembly And Linkage Bushings.Also Service Transfer Case.		FUEL FILTER FORD ONLY	1.00
- Replace Three Tires.Rotate And Balance All Six.		NAPAGOLD OIL FILTER	1.00
- Inspect And Service Auxiliary Fuel Tank		FUSE	1.00
- Replace Leaking Right Rear Axle Hub Seal .Also Service Rear Differential.		USED FIRE X REFURBISHED	1.00
- Shop Supplies		17189E BULB MR11-12V	1.00
		PIGTAIL SOCKET	1.00
		179636492 LT245-75R17	3.00
		FORD TRANSFER CASE FLUID	2.00
		NAPAGOLD FUEL FILTER	1.00
		1QT SYNGEAR OIL 75-90	4.00
		PTEX ULTRA GREY 3OZ	1.00
		BRAKE CLEANER	1.00
		SEAL	1.00
		SHOP SUPPLIES	1.00
		TIRE DISPOSAL FEE	3.00
		TRANSFER CASE SHIFTER	1.00
		TRANSFER CASE SHIFTER BUSHING	2.00
		TR416 VALVE STEM	3.00
Parts Charge:	1,292.31	Labor Charge:	855.00

10/17/2016
2:52:55PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169542 2008 FORD F350 Utility Body, 1 Ton, 4X4, W/ Tow Pkg

Workorder: 1412473

Problem: Towed in.Stalled after switching fuel tank.

Meter Reading: 73631		Labor		Parts	
In Date: 12/15/2014	Close Date: 12/24/2014	Hours	Description		Quantity
-	Inspect For Chirping Noise From Engine.Replace Defective Serpentine Belt Tensioner And Serpentine Belt.	5.50	TENSIONER-HEAVY DUTY DRIVE BELT		1.00
-	Diagnose For Engine Stalling.Air In Fuel.Add Fuel To Rear Tank.Bleed System,Test Fuel Pressure.At Specs.Test Drive While Switching Tanks,Ok.		SHOP SUPPLIES		1.00
-	Shop Supplies				
Parts Charge:		117.68	Labor Charge:	330.00	

Workorder: 1412599

Problem: stalled out

Meter Reading: 73267		Labor		Parts	
In Date: 12/14/2014	Close Date: 12/17/2014	Hours	Description		Quantity
-	Tow From: Sr80				
Parts Charge:		0.00	Labor Charge:	0.00	Commercial Charge: 134.77

Workorder: 1502802

Problem: Towed in for no start.

Meter Reading: 75286		Labor		Parts	
In Date: 03/18/2015	Close Date: 04/14/2015	Hours	Description		Quantity
-	Fully Recharge Batteries.Test Starting And Charging System.Ok Scan Test For Codes. None.Bleed Fuel System.	2.00	15-40 OIL		15.00
-	Shop Supplies		NAPAGOLD OIL FILTER		1.00
			179636492 LT245-75R17		6.00
			TR416 VALVE STEM		6.00
			FUEL FILTER FORD ONLY		1.00
			TIRE DISPOSAL FEE		0.00
			SHOP SUPPLIES		1.00
			NAPA HYDRAULIC FILTR		1.00
			WIPER BLADE		2.00
Parts Charge:		2.00	Labor Charge:	120.00	

10/17/2016
2:52:55PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169542 2008 FORD F350 Utility Body, 1 Ton, 4X4, W/ Tow Pkg

Workorder: 1502812

Problem: No Start

Meter Reading: 74993	Labor	Parts			
In Date: 03/17/2015	Hours	Description	Quantity		
- Tow From: 11150 Okeechobee Blvd (Next To Cuban Restaurant) To: Lv Shop					
Parts Charge:	0.00	Labor Charge:	0.00	Commercial Charge:	134.77

Workorder: 1507485

Problem: P.M. service.

Meter Reading: 78128	Labor	Parts	
In Date: 07/28/2015	Hours	Description	Quantity
- P.M. Service.			
	14.00	WIPER BLADE	2.00
- Inspect And Service Aux. Fuel System.			
		NAPAGOLD OIL FILTER	1.00
- Replace Both Headlamps And Rear Lamps.			
		USED FIRE X REFURBISHED	1.00
- Replace Two Tires,Rotate And Balance All Six.			
		15-40 OIL	15.00
- Replace Six Cab Mount Bushing/Insulator.			
		HALOGEN LAMP	2.00
- Replace Front Bump Stoppers.			
		TIRE DISPOSAL FEE	2.00
- Shop Supplies			
		BODY MOUNT KIT	4.00
		bumper	2.00
		BODY MOUNT KIT	2.00
		BIGG DEGREASER	1.00
		NAPAGOLD FUEL FILTER	1.00
		FUEL FILTER FORD ONLY	1.00
		LED SUP MDL 44 42 DIO	2.00
		SHOP SUPPLIES	1.00
		179636492 LT245-75R17	2.00
Parts Charge:	1,352.41	Labor Charge:	840.00

Workorder: 1509450

Problem: Gas Cap

Meter Reading: 78843	Labor	Parts	
In Date: 09/18/2015	Hours	Description	Quantity
- Fuel Cap			
		FUEL CAP	1.00
Parts Charge:	25.35	Labor Charge:	0.00

10/17/2016
2:52:55PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169542 2008 FORD F350 Utility Body, 1 Ton, 4X4, W/ Tow Pkg

Workorder: 1511358

Problem: Towed in.No start.Air locked.

Meter Reading: 80410	Labor	Parts
In Date: 11/05/2015	Hours	Quantity
Close Date: 11/24/2015	Description	Quantity
- Diagnose For No Start Due To Air Lock.R&R Front Fuel Tank.Drain Fuel.Replace Defective Float Strainer Assembly And Fuel Switching Valve.Refill Tank.	6.00	SENDER ASSEMBLY SHOP SUPPLIES SELECTOR VALVE
- Shop Supplies		1.00 1.00 1.00
Parts Charge:	Labor Charge:	
818.73	360.00	

Workorder: 1511413

Problem: No start (out of fuel)

Meter Reading: 80125	Labor	Parts
In Date: 11/04/2015	Hours	Quantity
Close Date: 11/06/2015	Description	Quantity
- Tow From: 60Th Ave North And Banyan Blvd (Loxahatchee) To: Lv Shop		
Parts Charge:	Labor Charge:	Commercial Charge:
0.00	0.00	96.00

Workorder: 1602089

Problem: P.M. Service.

Meter Reading: 83919	Labor	Parts
In Date: 02/29/2016	Hours	Quantity
Close Date: 03/17/2016	Description	Quantity
- Pm Service.	13.30	15-40 OIL
- Check Starting And Charging System.Both Batteries Failed Loadtest After Recharge.Replace Both Defective Batteries.		NAPAGOLD OIL FILTER 179636492 LT245-75R17 20" WIPER BLADE
- Inspect And Service Auxiliary Fuel Tank.		U JOINT
- Replace Defective Upper Light Bulbs For Marker And Rear Clearance Lamp Bulb For Bar Above Bumper.		USED FIRE X REFURBISHED BATTERY
- Replace Missing Fuel Cap.		NAPAGOLD FUEL FILTER
- Replace Two Tires.Rotate And Balance All Six.		TR416 VALVE STEM
- R&R Defective Universal Joints.		fuel cap green
- Shop Supplies		BULB SHOP SUPPLIES FUEL FILTER FORD ONLY LED BAR SEALED TIRE DISPOSAL FEE
Parts Charge:	Labor Charge:	
1,087.15	798.00	15.00 1.00 2.00 2.00 2.00 1.00 1.00 2.00 1.00 1.00 1.00 2.00

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169542 2008 FORD F350 Utility Body, 1 Ton, 4X4, W/ Tow Pkg

Workorder: 1606845

Problem: No start /Check Eng Light on

Meter Reading: 87807	Labor	Parts			
In Date: 07/07/2016	Hours	Description	Quantity		
- Tow From: Frt Of Wayne Akers Southern Blvd Near Sr7 To: Lv Shop					
Parts Charge:	0.00	Labor Charge:	0.00	Commercial Charge:	96.00

Workorder: 1606847

Problem: Towed in check engine light on and shut off would not startor crank washers inop.

Meter Reading: 87845	Labor	Parts			
In Date: 07/07/2016	Hours	Description	Quantity		
- Diagnose No Start Condition.Rep[Lace Three Defective Exhaust Temp Sensor.Clear Codes And Test Drive.					
	4.50	WASHER NOZZLE	2.00		
- Replace Both Windshield Washer Nozzles.					
		exhaust sensor	3.00		
- Shop Supplies					
		SHOP SUPPLIES	1.00		
Parts Charge:	283.86	Labor Charge:	270.00		

Workorder: 1609987

Problem: Transition Prep Charge

Meter Reading: 89823	Labor	Parts			
In Date: 09/23/2016	Hours	Description	Quantity		
- Transition Prep Charge					
	2.00				
Parts Charge:	0.00	Labor Charge:	0.00		

Total Parts Charges:	15,827.18	Total Labor Charges:	13,629.00	Total Comm. Charges:	1,903.68
----------------------	------------------	----------------------	------------------	----------------------	-----------------