

10/17/2016
2:54:49PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169530 2008 FORD F450 Utility Truck, 15000 Gvwr

Workorder: 835018 **Problem:** PRE-DELIVERY INSPECTION

Meter Reading: 0	Labor	Parts
In Date: 03/05/2008	Hours	Description
Close Date: 03/05/2008	Quantity	
- Pre-Delivery Inspection	4.00	
Parts Charge:	0.00	Labor Charge: 240.00

Workorder: 842216 **Problem:** TIRESOLES OF BROWARD INC

Meter Reading: 0	Labor	Parts
In Date: 07/28/2008	Hours	Description
Close Date: 07/31/2008	Quantity	
- Tiresoles Of Broward Inc		
Parts Charge:	0.00	Labor Charge: 0.00 Commercial Charge: 60.00

Workorder: 844620 **Problem:** P.M.SERVICE

Meter Reading: 6740	Labor	Parts
In Date: 09/23/2008	Hours	Description
Close Date: 09/24/2008	Quantity	
- Pm Service	7.00	7312 OIL FILTERFRM CH9549 WIX 57312
- Install Nitrogen		CA10270 AIR FILTER MTC FA1886 WIX 49886
- Tighten Body Hold-Downs		SHOP SUPPLIES
- Shop Supplies		31-20 WIPER BLADES 20" BLADE
		15/40 OIL
		CS10263 FUEL FILTER (USE CS10263A)
Parts Charge:	213.36	Labor Charge: 60.00
		1.00
		1.00
		1.00
		2.00
		15.00
		1.00

Workorder: 933143 **Problem:** RECALL#08B07/08B06.

Meter Reading: 11688	Labor	Parts
In Date: 01/26/2009	Hours	Description
Close Date: 01/30/2009	Quantity	
- Transport & Pick Up At Dealer For Recall # 08B07/08B06	2.00	SHOP SUPPLIES
- Shop Supplies		
Parts Charge:	2.00	Labor Charge: 60.00
		1.00

10/17/2016
2:54:49PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169530 2008 FORD F450 Utility Truck, 15000 Gvwr

Workorder: 933810

Problem: P.M.SERVICE

Meter Reading: 11688	Labor	Parts	
In Date: 02/10/2009	Hours	Description	Quantity
- Pm Service	6.25	CS10263 FUEL FILTER (USE CS10263A)	1.00
- Ck & Lube Squeaking Bushing For Rear Suspension		1066 WHITE LITHIUM (CRC 05037)	1.00
- Install New Decal		SHOP SUPPLIES	1.00
- Ck Fuel Leak From Rear Tank & Found Damaged Filler Neck Touching Leaf Springs; R&R Damaged Pipe & Reroute		10003 INJECTOR CLEANER DON'T REORDER	1.00
- Shop Supplies		15/40 OIL	15.00
Parts Charge: 163.01		Labor Charge: 375.00	

Workorder: 941744

Problem: P.M.SERVICE

Meter Reading: 16814	Labor	Parts	
In Date: 08/05/2009	Hours	Description	Quantity
- Pm Service	5.00	15/40 OIL	15.00
- Tighten Body Hold-Downs		USED FIREX REFURBED FIRE EXTINGSHERS	1.00
- Shop Supplies		SHOP SUPPLIES	1.00
		1066 WHITE LITHIUM (CRC 05037)	1.00
		7312 OIL FILTERFRM CH9549 WIX 57312	1.00
		CS10263 FUEL FILTER (USE CS10263A)	1.00
Parts Charge: 144.15		Labor Charge: 300.00	

Workorder: 1000504

Problem: P. M.

Meter Reading: 22097	Labor	Parts	
In Date: 01/13/2010	Hours	Description	Quantity
- P. M.	8.00	15/40 OIL	15.00
- Repaired 2 Body Light Grounds.		SHOP SUPPLIES	1.00
- Retightened Body Belt Downs.		CA10270 AIR FILTER MTC FA1886 WIX 49886	1.00
- Transport & Pick Up Vehicle At Dealer. (Anti-Freeze Leak At Lower Rad Hose.)		7312 OIL FILTERFRM CH9549 WIX 57312	1.00
- Shop Supplies		31-20 WIPER BLADES 20" BLADE	2.00
		CS10263 FUEL FILTER (USE CS10263A)	1.00
Parts Charge: 226.78		Labor Charge: 420.00	

10/17/2016
2:54:49PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169530 2008 FORD F450 Utility Truck, 15000 Gvwr

Workorder: 1001218

Problem: Check bin latch

Meter Reading: 22231	Labor	Parts	
In Date: 02/02/2010	Hours	Description	Quantity
- Repaired & Adjusted Bin Latch Assy.	1.25	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge: 2.00	Labor Charge: 75.00		

Workorder: 1005151

Problem: Made noise (fan like), & low on antifreeze.

Meter Reading: 26458	Labor	Parts	
In Date: 05/18/2010	Hours	Description	Quantity
- Refilled Coolant Level & Rd Tested. Noise Is The Clutch Fan Engaging Keeping The Engine From Overheating. Pressure Tested System, Leak At Radiator.	3.00	SHOP SUPPLIES	1.00
- Transport & Pick Up Vehicle At Dealer. (Defective Radiator).			
- Shop Supplies			
Parts Charge: 2.00	Labor Charge: 120.00		

Workorder: 1006475

Problem: P. M. Service

Meter Reading: 28060	Labor	Parts	
In Date: 06/18/2010	Hours	Description	Quantity
- P. M. Service.	11.25	CA10270 AIR FILTER MTC FA1886 WIX 49886	1.00
- R&R Pintle Pin.		7312 OIL FILTERFRM CH9549 WIX 57312	1.00
- Retightened Body Hold Downs.		18411 PINTAL PIN, 2 3/4" NEW # 66063	1.00
- Unsiezed & Lubed Vise & Hook.		USED FIREX REFURBED FIRE EXTINGSHERS	1.00
- Repaired Ground For Two Markers. R&R Bulbs For Clip Light. Repaired One Connection For Tail Light.		15/40 OIL	15.00
- Retightened Rear Stabilizer & Links.		CS10263 FUEL FILTER (USE CS10263A)	1.00
- Installed Driving Decal.		SHOP SUPPLIES	1.00
- Transport & Pick Up Vehicle At Dealer. (Coolant Leak At Upper Radiator Hose).		31-20 WIPER BLADES 20" BLADE	2.00
- Dealer Warranty Repair Only. (Upper Radiator Hose To Front Cover O-Ring Leaking).			
- Shop Supplies			
Parts Charge: 237.25	Labor Charge: 615.00		

10/17/2016
2:54:49PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169530 2008 FORD F450 Utility Truck, 15000 Gvwr

Workorder: 1007459

Problem: STALLS(BEEPING/STOP SAFELY NOW)

Meter Reading: 28330	Labor	Parts		
In Date: 07/14/2010	Hours	Description	Quantity	
- From: 6Th Ave South. I 95 Ramp So. Bound To: Sr Shop				
Parts Charge:	0.00	Labor Charge:	0.00	Commercial Charge: 114.00

Workorder: 1007460

Problem: TOW IN/STALLS(BEEPING/STOP SAFELY NOW)

Meter Reading: 28640	Labor	Parts		
In Date: 07/14/2010	Hours	Description	Quantity	
- Scanned Computer For Code P200E Catalyst System Oper Temp, Bank 1.				
- Transport & Pick Up Vehicle At Dealer. (Defective E.G.T. Sensors).				
- Dealer Warranty Repair. Defective Exhaust Gas Temp Sensors.				
- Shop Supplies				
Parts Charge:	2.00	Labor Charge:	150.00	

Workorder: 1007980

Problem: Slow down display comes on & once it was stopped, thermostat emblem came on & it was on "H" for heat

Meter Reading: 28719	Labor	Parts		
In Date: 07/27/2010	Hours	Description	Quantity	
- Transport&Pick Up Veh. At Dealer For Warranty Repair(Temp.Gauge Shows Hot When Engine At Idle)				
- Shop Supplies				
Parts Charge:	2.00	Labor Charge:	90.00	

10/17/2016
2:54:49PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169530 2008 FORD F450 Utility Truck, 15000 Gvwr

Workorder: 1010706

Problem: Check battery, had to jump start.

Meter Reading: 31006 In Date: 09/29/2010	Close Date: 10/13/2010	Labor Hours	Description	Parts	Quantity
- Transport & Pick Up Vehicle At Dealer. (Defective Battery).		2.00	SHOP SUPPLIES		1.00
- Dealer To Replace Battery. (Warranty).					
- Shop Supplies					
Parts Charge:		2.00	Labor Charge:		60.00

Workorder: 1010958

Problem: receiver step

Meter Reading: 30891 In Date: 10/05/2010	Close Date: 10/15/2010	Labor Hours	Description	Parts	Quantity
- Receiver Hitch Step			RECEIVER STEP		1.00
- Shop Supplies			SHOP SUPPLIES		1.00
Parts Charge:		189.50	Labor Charge:		0.00

Workorder: 1100721

Problem: P. M., & overheating light flashed & fan came on.

Meter Reading: 34751 In Date: 01/19/2011	Close Date: 02/18/2011	Labor Hours	Description	Parts	Quantity
- P. M. Service.		10.00	7312 OIL FILTERFRM CH9549 WIX 57312		1.00
- Repaired Wiring To Tail Lights. Repaired Ground For Body Light.			CA10270 AIR FILTER MTC FA1886 WIX 49886 15/40 OIL		1.00 16.00
- Retightened Body Hold Downs.			31-20 WIPER BLADES 20" BLADE		2.00
- Unsiezed & Lubed Vise & Hook, & Rerightened Ladder Rack.			3963 FUEL FILTER FRM CS10263A WIX 33963 SHOP SUPPLIES		1.00 1.00
- Transport & Pick Up Vehicle At Dealer For Warranty Repair. (Oil In Coolant Reservoir).					
- Dealer To Repair Oil In Coolant System & Coolant Reservoir.					
- Shop Supplies					
Parts Charge:		145.22	Labor Charge:		600.00

10/17/2016
2:54:49PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169530 2008 FORD F450 Utility Truck, 15000 Gvwr

Workorder: 1104725

Problem: NO A/C

Meter Reading: 37462	Labor	Parts	
In Date: 05/03/2011	Hours	Description	Quantity
- C/S: A/C Not Cold, Verify, Ck System & Found Low Pressure. Evacuate, Charge, Add Leak U/V Dye, Ck For Leaks & Was Unable To Find Leaks At This Time.	2.50	R134A REFRIGERANT	2.00
- Shop Supplies		SHOP SUPPLIES	1.00
Parts Charge:	7.96	Labor Charge:	150.00

Workorder: 1106529

Problem: P. M. SERVICE, & NO A/C

Meter Reading: 40320	Labor	Parts	
In Date: 06/21/2011	Hours	Description	Quantity
- P. M. Performed.	7.50	15/40 OIL	16.00
- Installed New Pin & Lubed Hook.		3963 FUEL FILTER FRM CS10263A WIX 33963	1.00
- Unsiezed & Lubed Vise.		31-20 WIPER BLADES 20" BLADE	2.00
- Repaired Grounds For Two Body Lights, & R&R Bulb For Clip Lights.		7312 OIL FILTERFRM CH9549 WIX 57312	1.00
- Retightened Body Hold Downs.		SHOP SUPPLIES	1.00
- Shop Supplies		CA10270 AIR FILTER MTC FA1886 WIX 49886	1.00
Parts Charge:	134.86	Labor Charge:	450.00

10/17/2016
2:54:49PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169530 2008 FORD F450 Utility Truck, 15000 Gvwr

Workorder: 1106902 **Problem:** COOLING IN ENGINE OIL PAN/OIL IN COOLANT RESERVOIR,A/C BLOWS WARM AIR

Meter Reading: 40320	Labor	Parts			
In Date: 06/29/2011	Hours	Description	Quantity		
- Checked For Leak, Tightened Low Side 134 Fitting. Recharged System & Vacuumed Down & Recovered.	4.75	SHOP SUPPLIES	1.00		
- Readjust Engine Oil Level.		R134A REFRIGERANT	2.00		
- Set Up Elpex To Replace 6 Tires (2 Front New Tires, & 4 Rear Recap Tires).		15/40 OIL	3.00		
- Transport & Pick Up Vehicle At Dealer. (Coolant In Oil Pan & Oil In Coolant Reservoir, Also Check Engine Light Stays On).		TIRE DISPOSAL FEE	6.00		
- Dealer To Replace Oil Cooler Assy, E.G.T. Sensor & Diesel Particulate Filter.		225/70R195 G647 STEER ONLY(RECAP TIRE)	4.00		
- Shop Supplies		WASTE FEE	2.00		
		225/70R19.5 G G647RSS	2.00		
Parts Charge: 1,243.41		Labor Charge: 285.00	Commercial Charge: 108.00		

Workorder: 1107634 **Problem:** ON-SITE SERVICE, invoice # L-015077

Meter Reading: 40320	Labor	Parts			
In Date: 07/20/2011	Hours	Description	Quantity		
- Sr Shop					
Parts Charge: 0.00		Labor Charge: 0.00	Commercial Charge: 24.00		

Workorder: 1112178 **Problem:** Right rear tire flat

Meter Reading: 43523	Labor	Parts			
In Date: 11/15/2011	Hours	Description	Quantity		
- Set Up Elpex To Repair Right Rear Flat Tire.	0.50				
Parts Charge: 0.00		Labor Charge: 30.00			

Workorder: 1112278 **Problem:** On-site service call, Right rear tire flat, repair tire, DO-410-4222, ELPEX / TIRESOLES.

Meter Reading: 43408	Labor	Parts			
In Date: 11/15/2011	Hours	Description	Quantity		
- Sr Shop					
Parts Charge: 0.00		Labor Charge: 0.00	Commercial Charge: 60.00		

10/17/2016
2:54:49PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169530 2008 FORD F450 Utility Truck, 15000 Gvwr

Workorder: 1200314

Problem: P.M.SERVICE

Meter Reading: 45400	Labor	Parts	
In Date: 01/10/2012	Hours	Description	Quantity
- P. M. Service.	11.00	SHOP SUPPLIES	1.00
- Installed New Pintal Pin. Unsized & Lubed Vise And Hook.		7312 OIL FILTERFRM CH9549 WIX 57312	1.00
		31-20 WIPER BLADES 20" BLADE	2.00
- Repaired Grounds For Running Lights.		CA10270 AIR FILTER MTC FA1886 WIX 49886	1.00
- Retightened Body Hold Downs.		15/40 OIL	16.00
- Retightened Ladder Brackets.		18411 PINTAL PIN, 2 3/4" NEW # 66063	1.00
- Installed Lap Top, Po128 & P1000		3963 FUEL FILTER FRM CS10263A WIX 33963	1.00
- Transport & Pick Up Vehicle At Dealer. (Thermostat Problem & Recall).			
- Dealer To Replace Defective Thermostat.			
- Dealer Performed Recall # 11B23B (Reprogram Control Modules).			
- Shop Supplies			
Parts Charge:	132.85	Labor Charge:	660.00

Workorder: 1206362

Problem: pm

Meter Reading: 51086	Labor	Parts	
In Date: 07/06/2012	Hours	Description	Quantity
- Pm	20.00	09997 BRAKE CLEAN	2.00
- Installed New Pental Pin Lubed And Freed Hook And Visor		SHOP SUPPLIES	1.00
		31-20 WIPER BLADES 20" BLADE	2.00
- Removed Gronds For Light Assy Repaired Connect To Tail Light Assy		18411 PINTAL PIN, 2 3/4" NEW # 66063	1.00
		3963 FUEL FILTER FRM CS10263A WIX 33963	1.00
- Batt Failed Load Recharged Both Batt And Fail Again Rr Both Batt		7312 OIL FILTERFRM CH9549 WIX 57312	1.00
		GROUP 65 BATTERY (MTC BXT-65-850)	2.00
- Rr Frt And Rear Brakes		USED FIREX REFURBED FIRE EXTINGSHERS	1.00
- Tighten Hold Downs		CA10270 AIR FILTER MTC FA1886 WIX 49886	1.00
- Adj Rack And Tightened		1401 BRAKE FLUID BRAKE FLUID	3.00
		FRONT ANS REAR BRAKE PADS	2.00
- Shop Supplies		15/40 OIL	16.00
Parts Charge:	567.09	Labor Charge:	1,200.00

10/17/2016
2:54:49PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169530 2008 FORD F450 Utility Truck, 15000 Gvwr

Workorder: 1212266

Problem: pintle pin

Meter Reading: 53891 In Date: 12/20/2012	Close Date: 12/27/2012	Labor Hours	Description	Parts	Quantity
- Ck Missing Pintle Pin Install Pintle Pin Lube And Inspect Hitch		0.50	18410 PINTLE PIN		1.00
Parts Charge:		2.19	Labor Charge:		30.00

Workorder: 1300922

Problem: pm

Meter Reading: 54525 In Date: 01/28/2013	Close Date: 01/31/2013	Labor Hours	Description	Parts	Quantity
- Pm		7.50	OIL FILTER		1.00
- Unsiezed Lubed Vise And Hook			31-20 WIPER BLADES 20		2.00
- Repaired Clip Light And Repaired Grounds For Running Light			FUEL FILTER		1.00
- Tightened Body Hold Downs			SHOP SUPPLIES		1.00
- Tighened Ladder Rack Assy			05046 BATTERY PROTECT		1.00
- Shop Supplies			15w40 BULK SOUTH REG		16.00
			AIR FILTER		1.00
Parts Charge:		170.65	Labor Charge:		450.00

Workorder: 1307273

Problem: pm, vadriour locks need replacement

Meter Reading: 60271 In Date: 07/22/2013	Close Date: 08/08/2013	Labor Hours	Description	Parts	Quantity
- Pm		13.00	NAPAGOLD AIR FILTER		1.00
- Rr One Marker Assy Repaired Grounds For Rear Light Assy Repaired Ground For Running Light			SHOP SUPPLIES		1.00
- Reanchered Rear Stabilizer Assy			NAPAGOLD FUEL FILTER		1.00
- Tightened Body Hold Downs			15w40 BULK SOUTH REG		16.00
- Unseized And Lubed Vise And Hook And Tightened Ladder Rack Assy			PADDLE LATCH		1.00
- Repaired Two Latches For Utility Body And Adj Need To Replace Two Other Refab New Locks And Latches To Fit Door And Painted			NAPAGOLD OIL FILTER		1.00
- Shop Supplies			SPEC ORDER STAINL LATCH		1.00
			SPEC ORDER STRIKER		1.00
			Freight Charge		1.00
			31-20 WIPER BLADES 20		2.00
			ROTARY LATCH STRIKER		1.00
			M C LAMP		1.00
Parts Charge:		545.77	Labor Charge:		780.00

10/17/2016
2:54:49PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169530 2008 FORD F450 Utility Truck, 15000 Gvwr

Workorder: 1310065

Problem: flat tire inner pass rear, also leaking fuel

Meter Reading: 61756		Labor		Parts	
In Date: 10/04/2013	Close Date: 10/23/2013	Hours	Description	Quantity	
-	Replace Right Rear Inner Tire	7.00	TIRE DISPOSAL FEE		1.00
-	Lower Fuel Tank And Replace Damage Fuel Hose And		FUEL FILLER NECK		1.00
	Replace Fuelcap		FUEL FILLER HOSE KIT		1.00
-	Shop Supplies		FUEL CAP		1.00
			225 70R19.5 RC		1.00
			SHOP SUPPLIES		1.00
Parts Charge:		770.47	Labor Charge:		420.00

Workorder: 1310164

Problem: flat tire

Meter Reading: 61728		Labor		Parts	
In Date: 10/04/2013	Close Date: 10/08/2013	Hours	Description	Quantity	
-	Tow From: 345 S Cong Facility To: Sr Shop				
Parts Charge:		0.00	Labor Charge:		0.00
			Commercial Charge:		134.77

Workorder: 1401244

Problem: pm

Meter Reading: 64807		Labor		Parts	
In Date: 02/06/2014	Close Date: 02/26/2014	Hours	Description	Quantity	
-	Pm	12.00	NAPAGOLD AIR FILTER		1.00
-	Rr Frt Tires		NAPAGOLD OIL FILTER		1.00
-	Repaired Open To Marker In Cabinet Repaired Tag Ligth		225 70R19.5 New w/Rim		2.00
	And Rear Light Connection		SHOP SUPPLIES		1.00
-	Tightened Ladder Rack Assy		TIRE DISPOSAL FEE		2.00
-	Removed Shock And Straightened Mount And Reinsrtalled		FUEL FILTER FORD ONLY		1.00
	Shock		WASHER FL		1.00
-	Unsiezed And Lubed Vise And Hook		15w40 BULK SOUTH REG		16.00
-	Adj Tail Gate Latch And Hinges		WIPER BLADE		2.00
-	Removed Hose To Tank Reposition And Reinstalled				
-	Shop Supplies				
Parts Charge:		1,122.04	Labor Charge:		720.00

10/17/2016
2:54:49PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169530 2008 FORD F450 Utility Truck, 15000 Gvwr

Workorder: 1407849

Problem: pm

Meter Reading: 69566	Labor	Parts	
In Date: 08/11/2014	Hours	Description	Quantity
- Pm	9.00	SHOP SUPPLIES	1.00
- Rr Two Tail Light Assy Replace Wiring Through Cabinet		NAPAGOLD AIR FILTER	1.00
For Running Light		NAPAGOLD OIL FILTER	1.00
- Retightened Ladder Rack		FUEL FILTER FORD ONLY	1.00
- Unsiezed And Lubed Hook		15w40 BULK SOUTH REG	16.00
- Removed Door Panel And Adj Window Tack And Lubed		WIPER BLADE	2.00
- Repaired And Adj Body Bushngs On Cab		WASHER FL	1.00
- Shop Supplies		MAC WITE LITHIUM GRES	1.00
		LED SUP MDL 44 42 DIO	2.00
Parts Charge:	313.53	Labor Charge:	540.00

Workorder: 1501307

Problem: P.M.SERVICE

Meter Reading: 73497	Labor	Parts	
In Date: 02/04/2015	Hours	Description	Quantity
- Pm	12.50	NAPAGOLD AIR FILTER	1.00
- Repaires Wiring Throigh Cabinets For Running Lights		NAPAGOLD OIL FILTER	1.00
- Repaired Hoses And Unclogged Nozzles		15w40 BULK SOUTH REG	16.00
- Tightened Ladder Rack And Rack		WIPER BLADE	2.00
- Unsiezed And Luybed Hook And Vise		FUEL FILTER FORD ONLY	1.00
- Repoaired Latch And Striker Fore Two Cabinet		225 70R19.5 New w/Rim	2.00
Reattached Fire Ex		LIFT SUPPORT	2.00
- Rr Hood Shock Struts		WASHER FL	1.00
- Rr Two Tires		TIRE DISPOSAL FEE	2.00
- Shop Supplies		SHOP SUPPLIES	1.00
Parts Charge:	1,275.37	Labor Charge:	750.00

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169530 2008 FORD F450 Utility Truck, 15000 Gvwr

Workorder: 1502817 **Problem:** WONT CRANK IT SOUNDS LIKE STARTER

Meter Reading: 74697	Labor	Parts	
In Date: 03/18/2015	Hours	Description	Quantity
- Ck Batt Fail Charged Both Retested Failed Again Rr Bith Batteries	6.00	BATTERY	2.00
- Ck Starter Operation Removed Wheel Well Assy Repaired Wiring Rr Starter Assy		STARTER MOTOR	1.00
- Shop Supplies		SHOP SUPPLIES	1.00
Parts Charge: 725.69		Labor Charge: 360.00	

Workorder: 1502906 **Problem:** no start

Meter Reading: 74213	Labor	Parts	
In Date: 03/18/2015	Hours	Description	Quantity
- Tow From: 451 S Congress Ave Delray To: Sr Delray			
Parts Charge: 0.00		Labor Charge: 0.00	
		Commercial Charge: 134.77	

Workorder: 1507077 **Problem:** towed in, wont start

Meter Reading: 78386	Labor	Parts	
In Date: 07/16/2015	Hours	Description	Quantity
- Installed Scanner Icp Code Followed Code Ck Fuel Filter Housing And Ck Leads To Fill Module Followed Into Hareness Reaired Open	7.50	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge: 2.00		Labor Charge: 450.00	

Workorder: 1507119 **Problem:** no start

Meter Reading: 77927	Labor	Parts	
In Date: 07/16/2015	Hours	Description	Quantity
- Tow From: I 95 S Bound At 6Th Ave To: Sr Shop Delray			
Parts Charge: 0.00		Labor Charge: 0.00	
		Commercial Charge: 134.77	

10/17/2016
2:54:49PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169530 2008 FORD F450 Utility Truck, 15000 Gvwr

Workorder: 1507262

Problem: need spot mirror/ p.m.service

Meter Reading: 78535	Labor	Parts	Quantity
In Date: 07/21/2015	Hours	Description	Quantity
- Pm	13.00	225 70R19.5 New w/Rim	3.00
- Rr Side View Morrор		LED M C LAMP	1.00
- Unsiezed And Lubed Hook And Installed New Pin		MIRROR	1.00
- Rr Two Light Assy Repaired Ground For Marker Repaired		TIRE DISPOSAL FEE	3.00
Open Load To Back Tail Light		SHOP SUPPLIES	1.00
- Rr Three Tires		MIRROR	1.00
- Tightened Ladder Rack		MIRROR	1.00
- Repaired Latch For Ds Cab		NAPAGOLD AIR FILTER	1.00
- Remove Shock And Repaired Mount And Reinstalled		FUEL FILTER FORD ONLY	1.00
Shock		15w40 BULK SOUTH REG	16.00
- Shop Supplies		NAPAGOLD OIL FILTER	1.00
		M C LAMP	1.00
		LOCK PIN	1.00
		MOUNT	1.00
		WIPER BLADE	2.00
Parts Charge: 1,920.70		Labor Charge: 780.00	

Workorder: 1508807

Problem: ac blowing hot

Meter Reading: 79544	Labor	Parts	Quantity
In Date: 09/02/2015	Hours	Description	Quantity
- Tune Up Ac	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge: 2.00		Labor Charge: 60.00	

10/17/2016
2:54:49PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169530 2008 FORD F450 Utility Truck, 15000 Gvwr

Workorder: 1509723

Problem: ENGINE LIGHT IS ON AND ENGINE HESITATES

Meter Reading: 80300	Labor	Parts	
In Date: 09/25/2015	Hours	Description	Quantity
- Ck Engine Light On Scan Found Code Po472, P2263	13.50	WASHER NOZZLE	2.00
Perform Pinpoint Test Found Bad Back Pressure Sensor		SENSOR ASSEMBLY	1.00
Update Pcm Replace Back Pressure Sensor Clean Def		FUEL CAP DIESEL	2.00
Sys And Clear Codes		FITTING	3.00
- Replace Both Fuel Cap		SHOP SUPPLIES	1.00
- Replace Both Washer Nozzle			
- Test Drive 56 Miles After Repair			
- Repair Center Rear Marker Light			
- Shop Supplies			
Parts Charge:	179.90	Labor Charge:	810.00

Workorder: 1600632

Problem: pm

Meter Reading: 83202	Labor	Parts	
In Date: 01/20/2016	Hours	Description	Quantity
- Pm	9.50	NAPAGOLD OIL FILTER	1.00
- Repaired Ground For Rrear Light Assy		15w40 BULK SOUTH REG	16.00
- Tighened Ladder Rack		NAPAGOLD AIR FILTER	1.00
- Unsiezed And Lubed Vise And Hook		20" WIPER BLADE	2.00
- Rr Axle And Resealed		FUEL FILTER FORD ONLY	1.00
- Cabinet Would Not Unlock Opened Cabinet And Repair		SHOP SUPPLIES	1.00
Lock And Reassemble			
- Shop Supplies			
Parts Charge:	187.13	Labor Charge:	570.00

10/17/2016
2:54:49PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169530 2008 FORD F450 Utility Truck, 15000 Gvwr

Workorder: 1607941

Problem: Pm service.Ac blows hot air.

Meter Reading: 88594 In Date: 08/02/2016	Close Date: 08/12/2016	Labor Hours	Description	Parts	Quantity
- P.M.Service.		10.00	SHOP SUPPLIES		1.00
- R/R Windshield Washer Nozzles			PINTLE PIN W/CLIP		1.00
- R/R Pintle Pin			15w40 BULK SOUTH REG		16.00
- C/S A/C Blows Hot Air, Perform System Pressure Test.			WD40 16OZ		1.00
- R/R Both Schrader Valves, Recharge & Test For Leaks			NAPAGOLD AIR FILTER		1.00
- Rotate, Balance, Fill All 6 Tires W/Nitrogen.			WASHER NOZZLE		2.00
- Shop Supplies			20" WIPER BLADE		2.00
			WASHER FLUID CONCENTR		1.00
			AC VALVE CORE HIGH		1.00
			VALVE CORE		1.00
			NAPAGOLD OIL FILTER		1.00
			FUEL FILTER FORD ONLY		1.00
			E8 A/C OIL UNIV W DYE		1.00
			SOUTH REGION R134A		2.00
Parts Charge:		266.90	Labor Charge:		600.00

Workorder: 1609323

Problem: Transition Prep Charge

Meter Reading: 88937 In Date: 09/07/2016	Close Date: 09/07/2016	Labor Hours	Description	Parts	Quantity
- Transition Prep Charge		2.00			
Parts Charge:		0.00	Labor Charge:		0.00

Total Parts Charges:	10,901.78	Total Labor Charges:	13,260.00	Total Comm. Charges:	770.31
----------------------	------------------	----------------------	------------------	----------------------	---------------