

10/17/2017
12:05:49PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10179154 2009 FORD F350 Utility Body, 1 Ton, W/ Tow Pkg

Workorder: 937015

Problem: PRE-DELIVERY INSPECTION

Meter Reading: 0	Labor	Parts	
In Date: 04/27/2009	Hours	Description	Quantity
- Pre-Delivery Inspection	4.00		
Parts Charge: 0.00	Labor Charge: 240.00		

Workorder: 937478

Problem: INSTALL VISE

Meter Reading: 35	Labor	Parts	
In Date: 05/06/2009	Hours	Description	Quantity
- Fabricate & Install Vise Mount & Vise.	10.00	66997 COMBO VISE (RIGID F-60)	1.00
- Shop Supplies		T-4 WHITE PAINT	2.00
		SHOP SUPPLIES	1.00
		T-235 GRAY PRIMER	1.00
Parts Charge: 441.02	Labor Charge: 600.00		

Workorder: 938024

Problem: MAKE 2 SPARE KEYS

Meter Reading: 35	Labor	Parts	
In Date: 05/20/2009	Hours	Description	Quantity
- Cut 2 New Spare Keys	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge: 2.00	Labor Charge: 60.00		

10/17/2017
12:05:49PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10179154 2009 FORD F350 Utility Body, 1 Ton, W/ Tow Pkg

Workorder: 1000128

Problem: P. M., & Long bin does not close (right side, center bin)

Meter Reading: 5390 In Date: 01/05/2010	Close Date: 01/08/2010	Labor Hours	Description	Parts	Quantity
- P. M.		10.25	CS10263 FUEL FILTER (USE CS10263A)		1.00
- R/R Pintle Pin.			CA10270 AIR FILTER MTC FA1886 WIX 49886		1.00
- Repaired Ground For Body Light & Repaired Ground For Tag Light.			15/40 OIL		15.00
- Strobe Out, Checked Bulb & Wiring. Repaired Section Of Wiring Through Frame.			7312 OIL FILTERFRM CH9549 WIX 57312		1.00
- Unsiezed & Lubed Vise.			USED FIREX REFURBED FIRE EXTINGSHERS		1.00
- Retightened Body Bolts.			18411 PINTAL PIN, 2 3/4" NEW # 66063		1.00
- Fabricated Striker Assy. Adjusted Horizontal Center Compartment To Lock. Installed No Smoking Decals.			SHOP SUPPLIES		1.00
- Shop Supplies			1401 BRAKE FLUID BRAKE FLUID		1.00
			05046 BATTERY PROTECTOR (CRC)		1.00
			1066 WHITE LITHIUM (CRC 05037)		1.00
			WD40 SPRAY LUBE STOCK# 405540002		1.00
Parts Charge:		250.36	Labor Charge:		615.00

Workorder: 1002935

Problem: Install customers computer stand

Meter Reading: 9029 In Date: 03/23/2010	Close Date: 03/23/2010	Labor Hours	Description	Parts	Quantity
- Fabricate & Install Customers Computer Stand & Wire Harness.		4.00	SHOP SUPPLIES		1.00
- Shop Supplies					
Parts Charge:		2.00	Labor Charge:		240.00

10/17/2017
12:05:49PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10179154 2009 FORD F350 Utility Body, 1 Ton, W/ Tow Pkg

Workorder: 1005995

Problem: P. M., & remove computer mount (return computer mount to customer)

Meter Reading: 10879		Labor		Parts	
In Date: 06/08/2010	Close Date: 06/09/2010	Hours	Description	Quantity	
-	P. M.	10.00	15/40 OIL		15.00
-	Repaired Body Light Grounds.		CA10270 AIR FILTER MTC FA1886 WIX 49886		1.00
-	R&R Strobe Bulb & Repaired Connection.		HA238C STROBE BULB USE WHELEN #S30HAC		1.00
-	Unsized Vise & Hook, & Lubed.		CS10263 FUEL FILTER (USE CS10263A)		1.00
-	Retightened Body Hold Downs.		SHOP SUPPLIES		1.00
-	Repaired Flat Tire.		7312 OIL FILTERFRM CH9549 WIX 57312		1.00
-	Removed Computer Mount & Installed Driving Decal (As Requested Per Billy Schmitt).				
-	Shop Supplies				
Parts Charge:		252.86	Labor Charge:		600.00

Workorder: 1007843

Problem: REFLASH AND REPAIR CANCEIVER

Meter Reading: 12001		Labor		Parts	
In Date: 07/23/2010	Close Date: 07/29/2010	Hours	Description	Quantity	
-	Flash Canceiver	2.00	SHOP SUPPLIES		1.00
-	Install Updated Screws To Correct Intermittent Problem				
-	Shop Supplies				
Parts Charge:		2.00	Labor Charge:		120.00

Workorder: 1013268

Problem: P. M., Check tires (had to fill a front tire with air).

Meter Reading: 14765		Labor		Parts	
In Date: 12/01/2010	Close Date: 12/15/2010	Hours	Description	Quantity	
-	P. M.	11.50	USED FIREX REFURBED FIRE EXTINGSHERS		1.00
-	R&R, And Balance 4 Tires.		CA10270 AIR FILTER MTC FA1886 WIX 49886		1.00
-	Tire Repair.		179636492 LT245/75R17 WRANGLER SR-A E		4.00
-	Retightened Body Bolts.		CS10263 FUEL FILTER (USE CS10263A)		1.00
-	Repaired Grounds For Two Body Lights.		SHOP SUPPLIES		1.00
-	Repaired Connection At Pach.		31-22 WIPER BLADES 22" WIPER BLADE		2.00
-	Unsized & Lubed Vise & Hook.		TIRE DISPOSAL FEE		4.00
-	Shop Supplies		15/40 OIL		15.00
			7312 OIL FILTERFRM CH9549 WIX 57312		1.00
Parts Charge:		896.87	Labor Charge:		690.00

10/17/2017
12:05:49PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10179154 2009 FORD F350 Utility Body, 1 Ton, W/ Tow Pkg

Workorder: 1013628 **Problem:** flash canceiver

Meter Reading: 14830		Labor		Parts	
In Date: 12/10/2010	Close Date: 12/15/2010	Hours	Description		Quantity

- Flash Canceiver		1.00	SHOP SUPPLIES		1.00
- Shop Supplies					

Parts Charge: 2.00 **Labor Charge:** 60.00

Workorder: 1013661 **Problem:** LOST FUEL CAP

Meter Reading: 14857		Labor		Parts	
In Date: 12/13/2010	Close Date: 12/15/2010	Hours	Description		Quantity

- Install Fuel Cap.		0.25	FUEL CAP		1.00
---------------------	--	-------------	----------	--	------

Parts Charge: 17.01 **Labor Charge:** 15.00

Workorder: 1106430 **Problem:** P. M., Check battery/alternator, also, inside overhead light burnt out

Meter Reading: 19064		Labor		Parts	
In Date: 06/20/2011	Close Date: 06/24/2011	Hours	Description		Quantity

- Performed P.M.Service.		12.75	15/40 OIL		16.00
- R&R Tail Light Assy. Repaired Grounds For Running Lights.			7312 OIL FILTERFRM CH9549 WIX 57312		1.00
			3963 FUEL FILTER FRM CS10263A WIX 33963		1.00
- Went To Parking Lot, Jump Started Truck. Charged Both Batteries, & Tested. D/S Battery Bad.			31-22 WIPER BLADES 22" WIPER BLADE		2.00
- R&R Strobe Bulb & Repaired Connection.			1066 WHITE LITHIUM (CRC 05037)		1.00
- Unsiezed & Lubed Hook & Vise.			HA238C STROBE BULB USE WHELEN #S30HAC		1.00
- Retightened Body Bolts.			SHOP SUPPLIES		1.00
- Installed Roach Bomb & Cleaned Out Cab.			44202R TAIL LIGHT 4" RED 42 LED		1.00
- Transport & Pick Up Vehicle At Dealer. (Defective L/Side Battery & Dome Light Inop).			CA10270 AIR FILTER MTC FA1886 WIX 49886		1.00
- Dealer To Replace Defective L/Side Battery.					
- Shop Supplies					

Parts Charge: 228.54 **Labor Charge:** 765.00

10/17/2017
12:05:49PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10179154 2009 FORD F350 Utility Body, 1 Ton, W/ Tow Pkg

Workorder: 1110957

Problem: Nail in front passenger tire

Meter Reading: 22678		Labor		Parts	
In Date: 10/14/2011	Close Date: 10/17/2011	Hours	Description	Quantity	
-	Replace Both Front Tires.	1.50	SHOP SUPPLIES		1.00
-	Shop Supplies		179636492 LT245/75R17 WRANGLER SR-A E		2.00
			TIRE DISPOSAL FEE		2.00
Parts Charge: 375.39		Labor Charge: 90.00			

Workorder: 1113280

Problem: P. M. SERVICE

Meter Reading: 24377		Labor		Parts	
In Date: 12/19/2011	Close Date: 12/27/2011	Hours	Description	Quantity	
-	P. M. Service.	11.50	TIRE DISPOSAL FEE		1.00
-	Batteries Failed Load, Recharged & Retested, Passed.		7312 OIL FILTERFRM CH9549 WIX 57312		1.00
-	R&R Bulb For Center Brake Light. Repaired Ground For Triple Light Assy. Repaired Ground For Marker Light.		3963 FUEL FILTER FRM CS10263A WIX 33963		1.00
-	Strobe Inop Checked Bulb, Checked Wiring, Repaired Connection At Socket.		179636492 LT245/75R17 WRANGLER SR-A E		1.00
-	Unsized & Lube Vise And Hook.		15/40 OIL		16.00
-	Retightened Loose Body Bolts.		USED FIREX REFURBED FIRE EXTINGSHERS		1.00
-	R&R And Balanced One Tire.		31-22 WIPER BLADES 22" WIPER BLADE		2.00
-	Repaired Rr Tire.		SHOP SUPPLIES		1.00
-	Shop Supplies		CA10270 AIR FILTER MTC FA1886 WIX 49886		1.00
Parts Charge: 346.91		Labor Charge: 690.00			

10/17/2017
12:05:49PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10179154 2009 FORD F350 Utility Body, 1 Ton, W/ Tow Pkg

Workorder: 1204718

Problem: P. M. SERVICE

Meter Reading: 29691	Labor	Parts	
In Date: 05/18/2012	Hours	Description	Quantity
- Performed P. M.	13.00	SHOP SUPPLIES	1.00
- R&R Tail Light Assy. Repaired Grounds For Two Body Lights.		CA10270 AIR FILTER MTC FA1886 WIX 49886	1.00
- Installed Pintal Pin, Lubed Hook & Vise.		7312 OIL FILTERFRM CH9549 WIX 57312	1.00
- Repaired Connection To Coil Pack.		TIRE DISPOSAL FEE	2.00
- R&R Two Tires.		179636492 LT245/75R17 WRANGLER SR-A E	2.00
- Tire Repair L/R.		44202R TAIL LIGHT 4" RED 42 LED	1.00
- Tightened All Body Bolts.		3963 FUEL FILTER FRM CS10263A WIX 33963	1.00
- Batts Failed Load, Recharged Batteries & Retested, Passed.		15/40 OIL	16.00
- Set Off 4 Roach Bombs In Truck, & Cleaned Out All Roaches.		31-22 WIPER BLADES 22" WIPER BLADE	2.00
- Shop Supplies		18410 PINTLE PIN	1.00
Parts Charge: 594.78		Labor Charge: 780.00	

Workorder: 1206555

Problem: L/FRONT TIRE FLAT

Meter Reading: 31328	Labor	Parts	
In Date: 07/13/2012	Hours	Description	Quantity
- Ck Left Front Tire Verify Front Right Tire Damaged	1.75	179636492 LT245/75R17 WRANGLER SR-A E	1.00
- Replace Mount Balance Add N2 Transport Tools To Repair		SHOP SUPPLIES	1.00
- Shop Supplies		TIRE DISPOSAL FEE	1.00
Parts Charge: 210.57		Labor Charge: 105.00	

Workorder: 1206627

Problem: pm service

Meter Reading: 31328	Labor	Parts	
In Date: 07/17/2012	Hours	Description	Quantity
-			
Parts Charge: 0.00		Labor Charge: 0.00	

10/17/2017
12:05:49PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10179154 2009 FORD F350 Utility Body, 1 Ton, W/ Tow Pkg

Workorder: 1212087

Problem: pm, service dome light inop

Meter Reading: 35295 In Date: 12/14/2012	Close Date: 12/27/2012	Labor Hours	Description	Parts	Quantity
- Pm		10.00	44202R TAIL LIGHT 4IN		2.00
- Repaired Ground To Rear Light Rr Tail Light Light Assy Rr Dome Bulb			BULB		2.00
			SHOP SUPPLIES		1.00
- Repaired Connections To Strobe Bulb And Plug			TIRE DISPOSAL FEE		2.00
- Unsiezed And Lubed Vise And Hook			15w40 BULK SOUTH REG		16.00
- Rr Balanced Two Tires			AIR FILTER		1.00
- Tightened Body Hold Downs			USED FIREX REFURBED F		1.00
- Repaired Lr Tire			OIL FILTER		1.00
- Shop Supplies			179636492 LT245-75R17		2.00
			31-22 WIPER BLADES 22		2.00
			FUEL FILTER		1.00
Parts Charge:		799.21	Labor Charge:		600.00

Workorder: 1302394

Problem: battery problem

Meter Reading: 36975 In Date: 03/11/2013	Close Date: 03/13/2013	Labor Hours	Description	Parts	Quantity
- Jumped Off Truck In Lot Tested Batt Both Failed Removed And Recharged Batt Botdy Failed Again D/S 10.98 40Cca Access He Oor Dtc 9Caa3P Rr Boith Batt		2.25	SHOP SUPPLIES		1.00
- Ck For Draw And Charge Rate Both Good			BATTERY 65		2.00
- Shop Supplies					
Parts Charge:		289.22	Labor Charge:		135.00

Workorder: 1304157

Problem: ck right rear tire

Meter Reading: 38408 In Date: 04/26/2013	Close Date: 04/29/2013	Labor Hours	Description	Parts	Quantity
- Ci All Tire Pressure Al Tires Ok At This Time		0.25			
Parts Charge:		0.00	Labor Charge:		15.00

10/17/2017
12:05:49PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10179154 2009 FORD F350 Utility Body, 1 Ton, W/ Tow Pkg

Workorder: 1306871

Problem: pm

Meter Reading: 40018	Labor	Parts	
In Date: 07/10/2013	Hours	Description	
Close Date: 07/25/2013		Quantity	
- Pm	10.50	15-40 OIL	16.00
- Repaired Grounds For 3 Body Lights		NAPAGOLD FUEL FILTER	1.00
- Ck Switch Operation Repaired Connection At Coil Pack		NAPAGOLD OIL FILTER	1.00
- Rr One Tire And Balanced		179636492 LT245-75R17	1.00
- Lr Tire Repair		TIRE DISPOSAL FEE	1.00
- Unsized And Lubed Hook And Vise		NAPAGOLD AIR FILTER	1.00
- Tightned Body Hold Downs		USED FIRE X REFURBISHED	1.00
- Tail Gate Adjusted Hindges And Latch		WIPER BLADE	2.00
- Shop Supplies		SHOP SUPPLIES	1.00
		15w40 BULK SOUTH REG	16.00
Parts Charge:	398.99	Labor Charge:	630.00

Workorder: 1400078

Problem: needs pintle pin

Meter Reading: 43974	Labor	Parts	
In Date: 01/03/2014	Hours	Description	
Close Date: 01/09/2014		Quantity	
- Ck Pintle Pin Install New Pintle Pin	0.25	PINTLE PIN W/CHAIN	1.00
Parts Charge:	2.61	Labor Charge:	15.00

Workorder: 1400088

Problem: cancevier problem

Meter Reading: 43955	Labor	Parts	
In Date: 01/03/2014	Hours	Description	
Close Date: 01/09/2014		Quantity	
- Test And Remove Cancevier And Issue Fuel Card	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	60.00

10/17/2017
12:05:49PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10179154 2009 FORD F350 Utility Body, 1 Ton, W/ Tow Pkg

Workorder: 1402029

Problem: pm

Meter Reading: 45585	Labor	Parts
In Date: 03/03/2014	Hours	Quantity
Close Date: 03/11/2014	Description	
- Pm	22.50	FUEL FILTER FORD ONLY 1.00
- Repaired Grounds For Running Lights Rr Bulb For Clip Light		NAPAGOLD OIL FILTER 1.00
		SHOP SUPPLIES 1.00
- Ck Strobe Light Sperations Ck Pack Rr Bulb		15w40 BULK SOUTH REG 16.00
- Unsiezed And Lubed Vise And Hook		WIPER BLADE 2.00
- Removed Door Panel And Adj And Lubed Track Assy		TIRE DISPOSAL FEE 6.00
- Rr And Balanced 6 Tires		NAPAGOLD AIR FILTER 1.00
- Rr Frt And Rear Brakes		USED FIRE X REFURBISHED 1.00
- Reinstalled Stabilizer Bar Bushings		BRAKE CLEANER 1.00
- Shop Supplies		BRAKE PADS 1.00
		BRAKE PAD 1.00
		HIDE AWAY STROB 1.00
		1401 BRAKE FLUID BRA 2.00
		179636492 LT245-75R17 6.00
Parts Charge:	1,924.56	Labor Charge: 1,350.00

Workorder: 1403592

Problem: wrench light on no power in engine

Meter Reading: 47089	Labor	Parts
In Date: 04/14/2014	Hours	Quantity
Close Date: 07/10/2014	Description	
- Ck Engine Light Is On Code Po88 Calibrate Pcm To The Latest Calibraion Change Engine II And Clear All Codes	8.00	15w40 BULK SOUTH REG 16.00
		SHOP SUPPLIES 1.00
- Clean Diesel Particulate Filter		
- Transport And Pick Up Vehicle At Dealer For Warranty Repair Rad And Hoses		
- Shop Supplies		
Parts Charge:	52.88	Labor Charge: 480.00

10/17/2017
12:05:49PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10179154 2009 FORD F350 Utility Body, 1 Ton, W/ Tow Pkg

Workorder: 1408502

Problem: pm, ck brakes , odor in cab, please test drive seems to have problem sometime when shifting

Meter Reading: 48902	Labor	Parts	
In Date: 08/26/2014	Hours	Description	Quantity
- Pm Rd Tested And Inspected Braked Ok	18.50	SHOP SUPPLIES	1.00
- Rr Both Tail Light Assy Repaired Grounds To Running Light		CURVED RADIATOR HOSE	1.00
		LED SUP MDL 44 42 DIO	2.00
- Ck Strobe Pack Rr Bulb To Strobe		CURVED RADIATOR HOSE	1.00
- Unsiezed And Lubed Vise And Hook		WASHER FL	1.00
- Repaired And Reinstalled Cab Mount		HIDE AWAY STROB	1.00
- Removed Shock And Straightened Mounting Bracket		WIPER BLADE	2.00
- Repaired Lf Tire		15w40 BULK SOUTH REG	16.00
- Rr Hoses Removed Power Steerig Resivoir And Turbo Hoses And Trans Line Fender Well To Access Hoseses		COOLANT FORD GOLD	4.00
		NAPAGOLD OIL FILTER	1.00
- Coolant Svc		FUEL FILTER FORD ONLY	1.00
		NAPAGOLD AIR FILTER	1.00
- Scanned Truck Po700 Followed Trace Took Pinpoint Voltage Cleaned Up Connector Had Some Corrosion In Female And Rd Tested Ok No Code		NAPAKOOL	2.00
- Shop Supplies			
Parts Charge:	555.07	Labor Charge:	1,110.00

Workorder: 1410983

Problem: DEAD BATTERY

Meter Reading: 50514	Labor	Parts	
In Date: 11/03/2014	Hours	Description	Quantity
- Jump Start Veicle From Wud Parking Lot Charge Both Battery Ck Charging Sys Ck For Draw And Found Both Battery Bad Replace Both Batteries	2.00	SHOP SUPPLIES	1.00
		BATTERY	2.00
- Shop Supplies			
Parts Charge:	241.22	Labor Charge:	120.00

10/17/2017
12:05:49PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10179154 2009 FORD F350 Utility Body, 1 Ton, W/ Tow Pkg

Workorder: 1412430

Problem: broken belt

Meter Reading: 20 In Date: 12/12/2014	Close Date: 12/29/2014	Labor Hours	Description	Parts	Quantity
- Broken Bolt Ck Found Broken Alternator Belt And Broken Belt Tensioner Remove Fan Shroud Replace Ac Belt Alt Belt Tensioner And Alterator Belt And Bleed Ps System		7.50	PWR STEERING FL-QUART STG WHEEL COV - FORD BELT TENSIONER		1.00 1.00 1.00
- Install Steering Wheel Cover			DRIVE BELT		1.00
- Test Drive To Bleed Ps System And After Repair			A/C BELT		1.00
- Shop Supplies			SHOP SUPPLIES		1.00
Parts Charge:		188.67	Labor Charge:		450.00

Workorder: 1412873

Problem: ac blowing warm air

Meter Reading: 52315 In Date: 12/30/2014	Close Date: 01/15/2015	Labor Hours	Description	Parts	Quantity
- Ck Ac Blowing Warm Air Perform Sys Pressure Test Found Low Freon Charge Sys Ck For Leaks Found Leaking Low And High Side Shrader Valves Evacuate Replace Shrader Valves Recharge Ck For Leaks		4.00	CORE AC VALVE CORE HIGH SOUTH REGION R134A E8 A/C OIL UNIV W DYE		1.00 1.00 2.00 1.00
- Shop Supplies			SHOP SUPPLIES		1.00
Parts Charge:		37.35	Labor Charge:		240.00

Workorder: 1502331

Problem: pm, install comouter stand

Meter Reading: 53820 In Date: 03/04/2015	Close Date: 03/13/2015	Labor Hours	Description	Parts	Quantity
- Pm		12.00	SHOP SUPPLIES		1.00
- Repaired Open In Cabinet To Running Light Repaired Ground For Side Marker			NAPAGOLD AIR FILTER FUEL FILTER FORD ONLY		1.00 1.00
- Rr Sealed Beam			15w40 BULK SOUTH REG		16.00
- Ck Strobe Operations Ck Pack And Power Source Rr 4 Strobe Bulbs And Repaired Connections			HALOGEN LAMP NAPAGOLD OIL FILTER		1.00 1.00
- Unsiezed And Lubed Vise			HIDE AWAY STROB		4.00
- Repaired Rr Tire			BAT TERM PROTECTOR		1.00
- Installed Computer Stand			WIPER BLADE		2.00
- Shop Supplies			USED FIRE X REFURBISHED		1.00
Parts Charge:		427.31	Labor Charge:		720.00

10/17/2017
12:05:49PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10179154 2009 FORD F350 Utility Body, 1 Ton, W/ Tow Pkg

Workorder: 1506307

Problem: pm

Meter Reading: 58741	Labor	Parts	
In Date: 06/23/2015	Hours	Description	
Close Date: 06/30/2015		Quantity	
- Pm	9.00	NAPAGOLD AIR FILTER	1.00
- Repaired Wiring To Rear Lights Repaired Grounds For Body Light		WIPER BLADE	1.00
- Repaired Socket End For Strobe		NAPAGOLD OIL FILTER	1.00
- Unsiezed And Lubed Vise And Hook And Replaced Pin		SHOP SUPPLIES	1.00
- Reinstalled Stablizer Bushings		15w40 BULK SOUTH REG	16.00
- Repaired R Rear Tire		LOCK PIN	1.00
- Shop Supplies		FUEL FILTER FORD ONLY	1.00
		WASHER FLUID CONCENTR	1.00
Parts Charge:	186.68	Labor Charge:	540.00

Workorder: 1510576

Problem: battery dead

Meter Reading: 60105	Labor	Parts	
In Date: 10/20/2015	Hours	Description	
Close Date: 10/27/2015		Quantity	
- Pushed Into Shop Both Batt Failed Load Test Recharged Batt Failed Load Test Again Rr Batteries Ck Charge Rete And Draw Tested All Good Batt Warranty By Napa Luis	2.00	SHOP SUPPLIES	1.00
- Shop Supplies		BATTERY	2.00
Parts Charge:	2.00	Labor Charge:	120.00

10/17/2017
12:05:49PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10179154 2009 FORD F350 Utility Body, 1 Ton, W/ Tow Pkg

Workorder: 1512605

Problem: pm, steering noise

Meter Reading: 61636	Labor	Parts	Quantity
In Date: 12/14/2015	Hours	Description	Quantity
- Pm Frt Bumper Hit Bad Needs To Go To Body Shop	42.00	HOSE ASY	1.00
- Repaired Ground For Lights Repaired Open In Cabinet For Marker Light		NAPAGOLD AIR FILTER	1.00
- Repaired Connection And Plug To Light		HOSE ASY	1.00
- Unsiezed And Lubed Vise And Hook		NAPAGOLD OIL FILTER	1.00
- Repaired Rr Tire		COOLANT FORD GOLD	3.00
- Power Pump Leaking Removed Cooler Rad Cross Member		FUEL FILTER FORD ONLY	1.00
Whl Well Moved Abs Valve Assy Removed Bolts To Steer		CLEANER	2.00
Gear Rr Lines Reassembled Above		22" WIPER BLADE	2.00
- Coolant Svc		DRIVE BELT	1.00
- Rr Belt Tensioner And Rr Belts Drilled Out Broken Bolts On Bracket		BELT TENSIONER	1.00
- Removed Bumper And Pulled Away From Cooler And Straightened So Hood Would Shut Correctly		15w40 BULK SOUTH REG	16.00
- Shop Supplies		PAWER STEERING PUMP	1.00
		SHOP SUPPLIES	1.00
		A/C BELT	1.00
		SYN ATF BULK SOUTH	3.00
Parts Charge:	841.69	Labor Charge:	2,520.00

Workorder: 1607326

Problem: Broken hitch pintle pin.

Meter Reading: 65867	Labor	Parts	Quantity
In Date: 07/18/2016	Hours	Description	Quantity
- Replace Broken Hitch Pintle Pin.	0.25	PINTLE PIN W/CLIP	1.00
Parts Charge:	2.61	Labor Charge:	15.00

10/17/2017
12:05:49PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10179154 2009 FORD F350 Utility Body, 1 Ton, W/ Tow Pkg

Workorder: 1608060

Problem: Pm service.Check engine light on.Right front tire flat.

Meter Reading: 66362 In Date: 08/04/2016	Close Date: 08/17/2016	Labor Hours	Description	Parts	Quantity
- P.M.Service		15.25	NAPAGOLD AIR FILTER		1.00
- Replace 6 Tires			TIRE DISPOSAL FEE		6.00
- Repair Both Tail Lights And Tag Light			SHOP SUPPLIES		1.00
- Replace 6 Body/Cab Mounts			NAPAGOLD OIL FILTER		1.00
- Fill All Tires W/N2			15w40 BULK SOUTH REG		16.00
- Shop Supplies			USED FIRE X REFURBISHED		1.00
			FUEL FILTER FORD ONLY		1.00
			179636492 LT245-75R17		6.00
			22" WIPER BLADE		2.00
			WASHER FLUID CONCENTR		1.00
			RECIP SAW BLADE		1.00
			BODY MOUNT KIT		2.00
			BODY MOUNT KIT		4.00
			LED SUP MDL 44 42 DIO		2.00
			BULB		2.00
			RECIP SAW BLADE		1.00
	Parts Charge: 2,401.12	Labor Charge: 915.00			

Workorder: 1612009

Problem: Drain water from fuel/water seperator.

Meter Reading: 68764 In Date: 11/21/2016	Close Date: 11/28/2016	Labor Hours	Description	Parts	Quantity
- Diagnose For Drain Fuel/Water Seperator Message On Dash. Remove Fuel Condition Module And Clean Housing.		2.00	SHOP SUPPLIES		1.00
- Shop Supplies					
	Parts Charge: 2.00	Labor Charge: 120.00			

10/17/2017
12:05:49PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10179154 2009 FORD F350 Utility Body, 1 Ton, W/ Tow Pkg

Workorder: 1613084

Problem: Ac blows hot air.Whistling noise when running.

Meter Reading: 69981 In Date: 12/27/2016	Close Date: 01/25/2017	Labor Hours	Description	Parts	Quantity
- Remove Fan Shroud,Replace Ac Belt,Alternator Belt And Tensioners.Repair Power Steering Pump Pulley.		10.25	DRIVE BELT		1.00
			BELT TENSIONER		1.00
- C/S Ac Blow Hot Air.Perform System Pressure Test And Leak Test.Found Leaking Schrader Valves.Evacuate,Replace Valves, Recharge And Leak Test.			A/C BELT		1.00
			SHOP SUPPLIES		1.00
			BELT TENSIONER		1.00
			FREON SR SHOP		3.00
			A/C SERVICE PORT		1.00
- Shop Supplies			HIGH SIDE SCHRADER VALVE		1.00
Parts Charge:		392.35	Labor Charge:		615.00

Workorder: 1700737

Problem: Check engine light on.Reduce engine power on display.

Meter Reading: 69981 In Date: 01/25/2017	Close Date: 01/30/2017	Labor Hours	Description	Parts	Quantity
- Diagnose For Engine Light On.Code P246C. Perform Dpf Manual Regeneration With Scan Tool To Clean Dpfsystem.Clear Code And Road Test.		2.00	SHOP SUPPLIES		1.00
- Shop Supplies					
Parts Charge:		2.00	Labor Charge:		120.00

10/17/2017
12:05:49PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10179154 2009 FORD F350 Utility Body, 1 Ton, W/ Tow Pkg

Workorder: 1701638

Problem: P.M.SERVICE,CHECK ENGINE LIGHT ON/REDUCED ENGINE POWER.

Meter Reading: 69981 In Date: 02/15/2017	Close Date: 03/20/2017	Labor Hours	Description	Parts	Quantity
- Pm Service.		15.75	PINTLE PIN W/CLIP		1.00
- Replace Pintle Pin.			EXHA		1.00
- Remove Exhaust System.Dismantle And Clean Dpf.Clear Codes With Scan Tool And Perform Regen.Road Test.			SHOP SUPPLIES		1.00
- Repair Tig Light.			NAPAGOLD OIL FILTER		1.00
- Rotate And Balance Tires.			13 OZ AERO KROIL		1.00
- Diagnose And Replace Three Exhaust Temp Sensors.Drill And Extract Broken Temp Sensor.Reweld Sensor Adaptor To Exhaust Pipe.Clear Code With Scan Tool And Roadtest.			22" WIPER BLADE		2.00
- Shop Supplies			WASHER FLUID CONCENTR		1.00
			15w40 BULK SOUTH REG		16.00
			exhaust sensor		3.00
			FUEL FILTER FORD ONLY		1.00
Parts Charge:		606.48	Labor Charge:		945.00

Workorder: 1705688

Problem: Dead batteries in WUD parking lot.

Meter Reading: 72060 In Date: 06/08/2017	Close Date: 06/19/2017	Labor Hours	Description	Parts	Quantity
- Had To Jump Start Vehicle In Wud Parking Lot.Fully Recharge And Test Both Batteries And Charging System.Ok		1.00	SHOP SUPPLIES		1.00
- Shop Supplies					
Parts Charge:		2.00	Labor Charge:		60.00

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10179154 2009 FORD F350 Utility Body, 1 Ton, W/ Tow Pkg

Workorder: 1706126

Problem: AC blows hot air.Check engine/wrench light on.

Meter Reading: 72208		Labor		Parts	
In Date: 06/21/2017	Close Date: 07/27/2017	Hours	Description		Quantity
-	Change Oil And Filter.Clear Codes .Perform Regen With Scan Tool.	7.00	NAPAGOLD OIL FILTER		1.00
			RED ANGEL AC STOP LK		1.00
-	Ac Performance And Leak Test.R/R And Reseal Ac Plumbing.Vacume And Recharge System To Specs.		FREON SR SHOP		3.00
			SHOP SUPPLIES		1.00
-	Repair And Balance Right Rear Inner Tire.		A/C SUPER SEALER		1.00
-	Shop Supplies		PAG OIL		1.00
			15w40 BULK SOUTH REG		16.00
Parts Charge:		159.10	Labor Charge:		420.00

Workorder: 1707623

Problem: Check engine light on.Reduce power.

Meter Reading: 72608		Labor		Parts	
In Date: 08/03/2017	Close Date: 08/21/2017	Hours	Description		Quantity
-	Diagnose For No Power Clean Fuel Condition Modume.Perform Regen With Scan Tool.And Clean Def.Road Test Vehicle.	5.00	SHOP SUPPLIES		1.00
-	Repair And Balance Left Rear Inner Tire.				
-	Shop Supplies				
Parts Charge:		2.00	Labor Charge:		300.00

Workorder: 1708525

Problem: Transition Prep Charge

Meter Reading: 72608		Labor		Parts	
In Date: 08/29/2017	Close Date: 08/29/2017	Hours	Description		Quantity
-	Transition Prep Charge	2.00			
Parts Charge:		0.00	Labor Charge:		120.00

Total Parts Charges:	13,141.43	Total Labor Charges:	18,405.00	Total Comm. Charges:	0.00
----------------------	------------------	----------------------	------------------	----------------------	-------------