



10/17/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10182237

### INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

**Workorder: V32837**

In Date: 06/11/2010      Meter Reading: 1,397.00  
 Close Date: 06/18/2010

**Problem?**  
 remove air horns for graphics installation

Task performed:	Parts	Quantity
Rem horns for Jeff the sticker guy & 110V plugs on side of truck; reinstall.      j	NO PARTS USED	

**Workorder: V32917**

In Date: 06/15/2010      Meter Reading: 1,346.00  
 Close Date: 07/20/2010

**Problem?**  
 B inspection mount equipment R14

Task performed:	Parts	Quantity
B-Inspection; chk in truck.	101-124-000CRASH RESTRAINT STRAPS	1
2. Set up new truck; mnt eqmpt, stickers, # plates, etc.	14-7014HGR-1 HELMET HOOK	3
3. Rset tire 6 on rear brake to steady burn.	1878042C91FUEL FILTER 2008 HORTON	1
4. Pull appart ___ panel to get access to wiring for diode; inwtall on dome lites for Orlando to do on another trk per Ed; put back tog.	5269LPVM-5 SM MOUNT	6
5. C/O A/C not cold; evac sys, add charge to sys; retest ok.	680-10LAMERICAN FLAG W UV CLEAR LEFT	1
6. Go to Central Auto, drop for seat cvr; install, go PU.      j	680-10RAMERICAN FLAG W UV CLEAR RIGHT	1
	KD-UN-5-SFUSE 6-SF BRACKET	1
	L PLACARDLARGE SIDE PLACARD	2
	LPVM-7LG MOUNT	3
	S PLACARDFRONT AND BACK PLACARD	1
	UMVS162511STRAP	3
	UMVS254411STRAP 46 IN	1

**Workorder: V33494**

In Date: 07/12/2010      Meter Reading: 1,397.00  
 Close Date: 08/02/2010

**Problem?**  
 New rescue truck needs, Gutters put on, rear door above tailboard needs adjustment, R- rear door weatherstrip loose. R14

Task performed:	Parts	Quantity
1. installed gutters on side; adj rear door & rear step.	090-0278STRECHER BAR NEW	1
2. R/R stretcher lock; rem old stretcher & adj lock; ck ok.      ja		



10/17/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10182237

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

### Workorder: V33534

In Date: 07/14/2010

Meter Reading: 147.80

Close Date: 08/02/2010

#### Problem?

lower stercher on new rescue 14

#### Task performed:

Parts

Quantity

Rem predrilled stops off other new rescue; went to 14;  
R/R axle stops on 14; ck stretcher opn; ck ok. ja

NO PARTS USED

### Workorder: V34217

In Date: 08/12/2010

Meter Reading: 2,599.00

Close Date: 09/03/2010

#### Problem?

front cab and rear box AC not blowing cold air while vehicle is driven R14

#### Task performed:

Parts

Quantity

1. Went to 14; ran/ck pat A/C; ck ok.  
2. Ran cab A/C; added small amnt of freon to sys; ck ok.  
js

NO PARTS USED

### Workorder: V33812

In Date: 07/27/2010

Meter Reading: 1,668.00

Close Date: 09/07/2010

#### Problem?

Rework rear compartment for stair chair R14

#### Task performed:

Parts

Quantity

1. Went to 14; mod plate; wld not work  
2. Returned to 14 - installed original plate; ck ok. js

NO PARTS USED

### Workorder: V34477

In Date: 08/24/2010

Meter Reading: 3,424.00

Close Date: 09/07/2010

#### Problem?

on call unit stuck r14

#### Task performed:

Parts

Quantity

Call out truck stuck; tried to mov - cld not; called  
dispatch for tow out. js

NO PARTS USED



10/17/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10182237

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

**Workorder: V34777**

In Date: 09/07/2010  
Close Date: 09/23/2010

Meter Reading: 3,935.00

**Problem?**

rear a/c not cool. r14

**Task performed:**

Parts

Quantity

Went to 14; fnd shoreline A/C blowing warm; turned temp down on t-stat; ran/ck ok. j

NO PARTS USED

**Workorder: V35063**

In Date: 09/20/2010  
Close Date: 10/05/2010

Meter Reading: 4,252.00

**Problem?**

Latch on rear compartment door malfunction.

**Task performed:**

Parts

Quantity

Went to 14; fnd door not shutting on rear compt. adj latch; ck ok. j

NO PARTS USED

**Workorder: V36547**

In Date: 11/18/2010  
Close Date: 11/18/2010

Meter Reading: 7,318.00

**Problem?**

Pt compartment shoreline AC blowes burning plastic smell. Engine AC OK. R14

**Task performed:**

Parts

Quantity

CONTACTED HALLMARK FOR WARRANTY REPAIR

NO PARTS USED

**Workorder: V36345**

In Date: 11/10/2010  
Close Date: 11/19/2010

Meter Reading: 6,648.00

**Problem?**

PINK OILY FLUID LEAKING OUT OF ENGINE COMPARTMENT. UNABLE TO FIND SOURCE r14

**Task performed:**

Parts

Quantity

1. check for coolant leak, found loose hose clamp on left side behind turbo, tighten hose clamp and pressure check, checks ok, top off coolant. jab

NO PARTS USED



10/17/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10182237

**INTERNATIONAL 4400 ADVANCED LIFE SUPPORT**

### Workorder: V36411

In Date: 11/12/2010

Meter Reading: 6,861.00

Close Date: 12/02/2010

#### Problem?

One of the auto eject outlet covers for the shoreline charging system on the side of R14 broke off when R14 started up to respond a call. R14

#### Task performed:

Travel to stn; Auto-eject cvr brkn; installed new cvr.  
j

#### Parts

NO PARTS USED

#### Quantity

### Workorder: V34413

In Date: 08/20/2010

Meter Reading: 2,953.00

Close Date: 12/22/2010

#### Problem?

rear a/c inop R14

#### Task performed:

#### Parts

NO PARTS USED

#### Quantity

### Workorder: V35179

In Date: 09/25/2010

Meter Reading: 4,252.00

Close Date: 12/22/2010

#### Problem?

Rear view camera has loose power connection. It flickers on and off when moved. R14

#### Task performed:

(1) TRAVELED TO ST 14 TO REPAIR POWER CONNECTOR TO THE REAR VIEW CAMERA ON E14. REPAIRED THE POWER CONNECTOR, TESTED OK.  
(2) TRAVELED BACK TP ST 14 TO REPAIR THE SPOT LIGHT ON E14. REPLACED THE CONTROLLER TO THE SPOY LIGHT AND CHECKED OUT OK. J.W.

#### Parts

2020-DDASH MOUNT REMOTE CONTROL  
6811813493LENS CLEAR 68-1181349-3

1

1

#### Quantity

### Workorder: V35217

In Date: 09/27/2010

Meter Reading: 4,701.00

Close Date: 12/22/2010

#### Problem?

1)Whelen Siren is not working correctly. only works when main button is pushed. Please call the Station for a better explanation. : Joy stick for top cab spotlight movement is broke off and lost. r14

#### Task performed:

#### Parts

NO PARTS USED

#### Quantity



10/17/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10182237

**INTERNATIONAL 4400 ADVANCED LIFE SUPPORT**

**Workorder: V35329**

In Date: 10/01/2010  
Close Date: 12/22/2010

Meter Reading: 4,701.00

**Problem?**

Drivers side light lenses (2) broken off.

**Task performed:**

Parts

Quantity

(1) TRAVELED TO ST 14 TO REPLACE TWO CODE 3 LIGHTS ON THE DRIVER SIDE OF R14 THAT HAD BEEN BROKEN . DONE. J.W.

NO PARTS USED

**Workorder: V35354**

In Date: 10/03/2010  
Close Date: 12/22/2010

Meter Reading: 4,701.00

**Problem?**

2 left side emergency light covers missing. Not scene light. lights do work. Thank you R14

**Task performed:**

Parts

Quantity

(1) TRAVELED TO ST14 TO REPAIR MISSING LENS COVER ON CODE 3 LIGHTS. REPAIRS DONE ON WO# V35329 J.W.

NO PARTS USED

**Workorder: V37011**

In Date: 12/08/2010  
Close Date: 01/03/2011

Meter Reading: 8,074.00

**Problem?**

Shore line cover broken off, siren only works using manual button. No rush, Thanx R14

**Task performed:**

Parts

Quantity

(1) TRAVELED TO ST-14 TO REPAIR SHORELINE COVER. FOUND THE COVER WAS BROKEN. REPLACED WITH A NEW COVER.  
(2) CHECK OUT SIREN FOR ONLY WORKING ON MANUEL. FOUND IT WORKING PROPERLY. J.W.

091-3YWCOVER KUSSMAUL AUTO EJECT

1



10/17/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10182237

**INTERNATIONAL 4400 ADVANCED LIFE SUPPORT**

**Workorder: V37525**

**In Date:** 12/31/2010

**Meter Reading:** 9,171.00

**Close Date:** 01/11/2011

**Problem?**

R-14 will not start dead battery

**Task performed:**

(1) OT. TRAVELED TO ST-14 FOR R14 NOT STARTING.  
HOOKED UP LAPTOP. ENGINE CODE FAILED FUEL  
INJECTION PUMP. OOS- GAVE A SPARE RESCUE  
TO ST-14.  
J.W.

Parts

Quantity

NO PARTS USED



10/17/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10182237

**INTERNATIONAL 4400 ADVANCED LIFE SUPPORT**

**Workorder: V37606**

In Date: 01/03/2011

Meter Reading: 9,171.00

Close Date: 01/25/2011

**Problem?**

C INSPECTION AND REPAIRS AS NEEDED R14

Task performed:

Parts

Quantity



10/17/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10182237

**INTERNATIONAL 4400 ADVANCED LIFE SUPPORT**

(1) "C" INSPECTION AND NEEDED REPAIRS.	1501450007750USE 0775145	3
(2) REPLACED CAB A/C FILTER.	15W40BSYN OIL BULK QTS	30
(3) REPLACED TRANS FILTER AND FILLED TO PROPER LEVEL.	1878042C91FUEL FILTER 2008 HORTON	1
(4) AIRED UP TIRES TO PROPER PSI SPECS.	2506656C124316 WIX CAB A/C FILTER	1
(5) TOPPED OFF P/S FLUID.	29526898 29548988 TRANS FILTER ALLISON	1
(6) SERVICED BATTERIES,LOAD TESTED AND CLEANED CABLE ENDS AND BATTERY POSTS.	5774457744XD OIL FILTER	1
(7)REPLACED LOWER KING PIN ZIRKS.	HLD3999GSS1715UV 30LB STRUT GAS	1
(8) REPLACED ALL PATIENT COMP A/C FILTERS.	K022105PURGE VALVE AD-IP-IS	1
(9) REBUILT AIR DRYER AND PURGE VALVE.	L PLACARDLARGE SIDE PLACARD	2
(10) REPLACED RUBBER PADS ON BATTERY COMP DOOR LATCHES & ADJUSTED LATCHES.	L PLACARD INSERTLARGE PLACARD INSERT CARD	4
(11) CHECKED ENGINE, BODY, TRANS AND ABS CODES, ERASED INACTIVE CODES.	SD-210RXSIREN DRIVER SMALL	1
(12) CONNECTED SHOPS 02 TEST BOTTLE AND CHECKED FOR LEAKS.		
(13) REPAIRED DOOR SCREWS THAT WERE STRIPPED O L-1 AND TIGHTENED ALL OTHERS.		
(14) REPAIRED BRACKET BOLT HOLES THAT WERE STRIPPED ON L-2.		
(15) TIGHTENED SHOCK MOUNTS ON L-2, R-3, R-1 DOORS.		
(16) PLACED LOOSE REAR DOOR WEATHERSTRIP INTO THE TRACK AND SECURED CORNERS WITH WEATHERSTRIP.		
(17)TIGHTENED ALL DOOR PANEL SCREWS AND LATCH BOLTS.		
(18) FEED CORDING BACK INTO PLACE ON L-2 WEATHERSTRIP.		
(19) REMOVED DRAWER FROM PATIENT COMP, SHIMED THE STRIKER DOWN SO THE LATCH WILL HOLD ON STRIKER. REINSTALLED THE DOOR AND TESTED. OK.		
(20) REPLACED PATIENT COMP SHOCK.		
(21)REPAIRED LICENSE PLATE LIGHT . POLARITY WAS BACKWARDS.		
(22) REPLACED RIGHT SIREN SPEAKER DRIVER.		
(23)TORQUED U-BOLTS TO PROPER TORQUE.		
(24) REPLACED TIRE PRESSURE SENSORS THAT WAS BAD. HAD EXTRA GOOD USED ONES, NO PART CHARGE. CALIBRATED SENSORS.		
(25) DIAGNOSED SIREN FOR NOT WORKING FROM HORN BUTTON. FOUND SIREN ONLY WORKS FROM HF FROM HORN BUTTON. OK.		
(26) START ON CAMPAIGN SIGNS, AND INSTALL. J.W.		





10/17/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10182237

**INTERNATIONAL 4400 ADVANCED LIFE SUPPORT**

**Workorder: V39276**

In Date: 03/17/2011

Meter Reading: 11,952.30

Close Date: 03/24/2011

**Problem?**

rubber stopper on flip down rear bumper missing please fix R14

**Task performed:**

Parts

Quantity

Travel to stn14. Rep mud rubber bumper \_\_\_ on step.

NO PARTS USED

**Workorder: V39439**

In Date: 03/25/2011

Meter Reading: 12,683.00

Close Date: 04/01/2011

**Problem?**

T1 not working, siren not working in wail only all other siren usable, sta.14.

**Task performed:**

Parts

Quantity

Travel to 14; replcd siren head. j

295SLSA1SIREN

1

**Workorder: V39011**

In Date: 03/07/2011

Meter Reading: 11,779.00

Close Date: 04/14/2011

**Problem?**

replace rt front tire

**Task performed:**

Parts

Quantity

Replc R/frnt tire - Boulevard j

NO PARTS USED

Vendor? BOULEVARD

**Workorder: V40016**

In Date: 04/19/2011

Meter Reading: 13,655.00

Close Date: 04/22/2011

**Problem?**

REAR AC PT. COMPARTMENT AC NOT WORKING WHEN PLUGED INTO SHORE POWER IN THE STATION BAY. REAR AC WORKING WHEN TRUCK IS RUNNING THOUGH. R14

**Task performed:**

Parts

Quantity

Travel to 14; fnd converter bad for Danheart A/C unit; called to shop to scheduled vender repair. j

NO PARTS USED



10/17/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10182237

**INTERNATIONAL 4400 ADVANCED LIFE SUPPORT**

### Workorder: V40191

In Date: 04/26/2011  
Close Date: 05/03/2011

Meter Reading: 14,133.00

#### Problem?

Driver side mirror found dented and with the plastic stabilization bar broken off. R14

#### Task performed:

1. Ordered parts for mirror.
2. Travel to 14; install mirror brkts. j

#### Parts

#### Quantity

2507655C91MIRROR SUPPORT

1

2509068C91MIRROR MOUNT UPPER

1

### Workorder: V40510

In Date: 05/10/2011  
Close Date: 05/13/2011

Meter Reading: 14,561.00

#### Problem?

R14 shoreline not working when when parked in bay

#### Task performed:

C/O all breaker set; still no blower; Eddie having Horton to look at this warranty. j

#### Parts

NO PARTS USED

#### Quantity

### Workorder: V40193

In Date: 04/26/2011  
Close Date: 06/07/2011

Meter Reading: 14,133.00

#### Problem?

Clear lens cover for drivers side warning light on grill of R14 is cracked around the screw that holds it in place. R14

#### Task performed:

Ordered parts. j

#### Parts

NO PARTS USED

#### Quantity

### Workorder: V40244

In Date: 04/29/2011  
Close Date: 06/07/2011

Meter Reading: 14,763.00

#### Problem?

FRONT GRILL STROB LIGHT LENS COVER BROKEN. REAR AC ALSO NOT WORKING WHEN SHORE POWER PLUGGED I WHILE SITTING IN THE BAY. R14

#### Task performed:

See W.O. 40193 - parts ordered 4/27/11. j

#### Parts

NO PARTS USED

#### Quantity



10/17/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10182237

**INTERNATIONAL 4400 ADVANCED LIFE SUPPORT**

**Workorder: V41000**

In Date: 05/31/2011  
Close Date: 06/07/2011

Meter Reading: 16,004.00

**Problem?**

B INSPECTION AND REPAIRS AS NEEDED R 14

**Task performed:**

- B-Service
- 2. Top off fluids.
- 3. Top off air in all tires.
- 4. Chk on parts ordered for truck; grill light cover not in; deferred to road tech. j

Parts	Quantity
1878042C91FUEL FILTER 2008 HORTON	1
2506656C124316 WIX CAB A/C FILTER	1
5774457744XD OIL FILTER	1

**Workorder: V41292**

In Date: 06/13/2011  
Close Date: 06/14/2011

Meter Reading: 16,312.00

**Problem?**

driver side tailboard flasher works intermittently R 14

**Task performed:**

- Travel to 14; R/R TIR6 LED. j

Parts	Quantity
50R03ZCRLIGHT LED RED TIR 6	1

**Workorder: V41521**

In Date: 06/22/2011  
Close Date: 06/30/2011

Meter Reading: 16,312.00

**Problem?**

Replace lens on emergency light.

**Task performed:**

- 1. Replc lens onr escue; fnd second brkn; will replc.
- 2. Travel to 14; R/R lens. j

Parts	Quantity
Z8012013BLENS CLEAR	2

**Workorder: V41564**

In Date: 06/23/2011  
Close Date: 06/30/2011

Meter Reading: 16,312.00

**Problem?**

regulator on main o2 broken, Sta 14.

**Task performed:**

- Replc O2 gauge. j

Parts	Quantity
MG-C23SPMGC23 GAUGE	1



10/17/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10182237

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

### Workorder: V41968

In Date: 07/13/2011

Meter Reading: 17,830.00

Close Date: 07/20/2011

#### Problem?

R14 yellow position lights left and right on rear of hood are not lighting up. Not a priority. Thanx.

#### Task performed:

TRAVEL TO 14 REPAIRED MAL-- LIGHT AK

#### Parts

194-ABULB

#### Quantity

3

### Workorder: V42337

In Date: 07/27/2011

Meter Reading: 18,406.00

Close Date: 07/29/2011

#### Problem?

R14 O2 regulator is showing empty when O2 tank is full.

#### Task performed:

1. Travel to 14; fnd gauge at tank bad; ordered parts.
2. Travel to 14; replc O2 gauge at tank. j

#### Parts

MG-C23SPMGC23 GAUGE

#### Quantity

1

### Workorder: V42362

In Date: 07/28/2011

Meter Reading: 18,406.00

Close Date: 07/29/2011

#### Problem?

oxygen gauge for main tank is not working, Sta 14.

#### Task performed:

Repaired on W.O. 42337 7/27 & 28/11. j

#### Parts

NO PARTS USED

#### Quantity

### Workorder: V40329

In Date: 05/02/2011

Meter Reading: 14,441.00

Close Date: 08/03/2011

#### Problem?

REPLACE TIRES R14

#### Task performed:

Replace tires R14 - Boulevard j

#### Parts

NO PARTS USED

#### Quantity

Vendor? BOULEVARD



10/17/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10182237

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

### Workorder: V42931

In Date: 08/20/2011 Meter Reading: 19,533.00  
Close Date: 08/24/2011

#### Problem?

R-14 AIR HORN LEAK LT SIDE R14

#### Task performed:

Rep air horn right side. j Parts ----- Quantity  
NO PARTS USED

### Workorder: V43441

In Date: 09/06/2011 Meter Reading: 20,218.00  
Close Date: 09/13/2011

#### Problem?

rear a/c making noise and running hot.

#### Task performed:

Replc rear A/C condensor fans & tested. j Parts ----- Quantity  
NO PARTS USED

### Workorder: V44254

In Date: 10/10/2011 Meter Reading: 21,900.00  
Close Date: 10/13/2011

#### Problem?

right flood light lens missing R 14

#### Task performed:

repalced scene light lens Parts ----- Quantity  
6811813493LENS CLEAR 68-1181349-3 1  
87123USE 9185 RELAY CONNECTOR 99025 2  
87401RY-30T RELAY 5 PIN 12V 2  
H6054USE CV TYPE SEALED BEAM 2

### Workorder: V44599

In Date: 10/21/2011 Meter Reading:  
Close Date: 10/26/2011

#### Problem?

Slow leak in air system (brake,dump) R14

#### Task performed:

let truck sit for 2.5hrs --leaked down sprayed all air Parts ----- Quantity  
system componets, no leaks found NO PARTS USED



10/17/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

**10182237**

**INTERNATIONAL 4400 ADVANCED LIFE SUPPORT**

**Workorder: V44649**

In Date: 10/24/2011  
Close Date: 10/26/2011

Meter Reading: 22,435.00

**Problem?**  
A/C inop

**Task performed:**

diagnose a/c comprssor not pumping, replace a/c compressor, drier and expansion valve, also rechimp low side hose to compressor, e---recharge

Parts	Quantity
3611894C9103-0805 A/C COMPRESSOR 4347	1
3660853C22512331C1 EXP VALVE NAV	1
3670134C1ACCUMULATOR ASSY INT.	1

**Workorder: V44624**

In Date: 10/24/2011  
Close Date: 11/01/2011

Meter Reading:

**Problem?**  
Front cab ac does not blow cold, Sta 14.

**Task performed:**

Chkd A/C; sent to shop for condensor. j

Parts	Quantity
NO PARTS USED	



10/17/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10182237

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

**Workorder: V45639**

**In Date:** 12/05/2011

**Meter Reading:** 24,503.00

**Close Date:** 12/16/2011

**Problem?**

C INSPECTION AND REPAIRS R 14

**Task performed:**

C INSPECTION

FOUND BATT. BAD - R&R 3 BATT. CK OK.

FOUND L.R.I. TIRE GOPSI - FOUND VALVESTEM NUT LEAKING TIGHTENED NUT - AIRED TIRE. CK. FOR LEAKS - CK OK.

SERVICE AIR DRIER - R&R CARTRIDGE AND PURGE VALVES RAN AND CK. OK.

TORQUE ALL AXLE V-BOLTS.

FOUND RT. LEVELING VALVE BENT - REPAIRED AND STRAIGHTEN VALVE RAN AND ADJUSTED HEIGHT. -CK. OK.

R&R 3 PAT. A/C FILTERS, R&R WIPER BLADES, FILLED WASHER BOTTLE TIGHTEN SCBA DOOR.

CK. FOR COOLANT LEAK - FILLED SYSTEM - PRESS. TEST - FOUND TUBE LEAKING ON RT. SIDE - TIGHTEN CLAMPS - CK. OK.

INSTALL HEATER SHUTT-OFF VALVES - DRAINED ROD - REMOVED HOSES - INSTALLED VALVES AND FITTINGS - FILLED RAD - RAN AND CK. OK.

CLEAN PAT. A/C CONDENSER - CLEANED BOTH COND. FOUND REAR STEP/FOLD DOWN LOOSE - REMOVED TREAD PLATE - DRILL ACCESS HOLES - R&R BOLDS - GREASED - CK. OK.

FOUND STAR WASHERS ON ALL BODY GROUNDS - REMOVED GROUNDS AND WASHERS - CLEANED CONNECTIONS AT FRAM - CK. OK.

Q&A INSPECTION

**Parts**

**Quantity**

065624AD-IP DRIER	1
1501450007750USE 0775145	3
1878042C91FUEL FILTER 2008 HORTON	1
2506656C124316 WIX CAB A/C FILTER	1
388863HOSE KIT	2
5774457744XD OIL FILTER	1
91-22WIPER BLADE	2
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTEF	3
HP-31DBATTERY 950CCA HP-31D	3
K022105PURGE VALVE AD-IP-IS	1



10/17/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10182237

**INTERNATIONAL 4400 ADVANCED LIFE SUPPORT**

**Workorder: V45998**

In Date: 12/21/2011  
Close Date: 12/22/2011

Meter Reading: 24,851.00

**Problem?**

Left front clear scene light lense missing. Left rear clear scene light lense cracked around bolts. R14

**Task performed:**

TRAVEL TO 14RDR BROKEN LENS

Parts

6811813493LENS CLEAR 68-1181349-3

Quantity

2

**Workorder: V45689**

In Date: 12/06/2011  
Close Date: 12/29/2011

Meter Reading: 24,503.00

**Problem?**

replace body mounts r 14

**Task performed:**

REPLACE BODY MOUNTS FOR PAT. BOX -  
REMOVED MOUNT BOLTS - RAISED BODY -  
REMOVED STAIR CHAIR DOOR, TRIM AND  
COMPARTMENT - RECHECKED ALL BODY MOUNTS

Parts

NO PARTS USED

Quantity

**Workorder: V46903**

In Date: 01/28/2012  
Close Date: 02/07/2012

Meter Reading: 26,848.00

**Problem?**

uneven tire wear. front drivers side tire wearing on outside, needs to be rotated.R14

**Task performed:**

TRAVEL TO STATION CHECKED TRUCK ORDERED  
NEW TIRES.

Parts

NO PARTS USED

Quantity

**Workorder: V47200**

In Date: 02/09/2012  
Close Date: 02/10/2012

Meter Reading: 27,770.00

**Problem?**

replace front tires

**Task performed:**

REPLACE FRONT TIRES.

Parts

NO PARTS USED

Quantity

**Vendor?** BOULEVARD TIRE CENTE





10/17/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10182237

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

**Workorder: V47833**

In Date: 03/08/2012  
Close Date: 03/16/2012

Meter Reading: 29,172.00

**Problem?**

FRONT CAB AC NOT WORKING, Sta 14

**Task performed:**

1. HAD TRUCK COME TO SHOP - TROUBLESHOOT BLOWER INOP - REMOVED PANELS - TOOK AMP DOWN ON BLOWER - BLOWER START UP HOLD HIGH DRIER - REMOVED BLOWER CASE - R&R BLOWER AND RESISTER - REASSEMBLED - CHECK OK. RECOVER, VAC AND CHARGE A/C CHECK OK.  
2. FOUND SIDE # PLATES FADED - INSTALLED RED & # STICKERS.

Parts

Quantity

3626414C1BLOWER MOTOR RESISTOR

1

3674285C1BLOWER MOTOR

1

H6054USE CV TYPE SEALED BEAM

1

**Workorder: V47752**

In Date: 03/05/2012  
Close Date: 03/19/2012

Meter Reading: 29,049.00

**Problem?**

R14 right front scene light lense coming off. Rear screws broke through. r 14

**Task performed:**

INSTALLED NEW LENSE TRAVEL TO STATION.

Parts

Quantity

6811813493LENS CLEAR 68-1181349-3

1

**Workorder: V48027**

In Date: 03/17/2012  
Close Date: 03/20/2012

Meter Reading: 29,760.00

**Problem?**

missing oil dip stick R14

**Task performed:**

WENT TO SHOP FOR PARTS - WENT TO 14 - REPLACED DIPSTICK - CHECK OIL LEVEL - CHECK OK. REPAIRED FLAT TIRE ON SERVICE TRUCK.

Parts

Quantity

NO PARTS USED



10/17/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10182237

**INTERNATIONAL 4400 ADVANCED LIFE SUPPORT**

**Workorder: V48652**

In Date: 04/13/2012

Close Date: 04/30/2012

Meter Reading: 31,280.00

**Problem?**

B INSPECTION R46

Task performed:

Parts

Quantity



10/17/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10182237

**INTERNATIONAL 4400 ADVANCED LIFE SUPPORT**

1. B-INSPECTION.
2. B-INSPECTION.
3. FOUND LRI TIRE AT 55 PSI - SPRAYED TIRE AND STEM - FOUND STEM LOOSE AT RIM - REPAIRED LEAK - AIRED TIRE TO 110 PSI CHECK FOR LEAKS - CHECK OK.
4. INSTALL LED TIRE MONITORS - REMOVED REAR WHEEL LUG NUTS, INSTALLED HOSE KITS - REMOVED OLD SENSORS AND REPLACED - REMOVED OLD SYSTEM SCREEN CHECK OK - R&R WIPER BLADES - FILL WASHER BOTTLE.
5. FOUND GROUND LIGHTS LOOSE AND MTS. DAMAGED - REMOVED LIGHTS AND MTS. STRAIGHTENED MTS - REMOUNTED LIGHTS - CHECK OK.
6. FOUND BODY GROUNDS HAVE STAR WASHERS - REMOVED ALL WASHERS AND CLEANED GROUNDS AND REINSTALLED.
7. CHECK FOR COOLANT LEAKS - PRESS TEST CAP AND SYSTEM - FOUND CAP BAD REPLACED CAP FOUND CLAMPS LOOSE TIGHTENED CLAMPS REMOVED AIR CLEANER AND EGR PIPE, EXC. COOLER CHECK OK. REASSEMBLED FILLED AND CHECK OK.
8. REPLACE ENG BELTS - R&R A/C AND ENGINE BELT.
9. CHECK P.S LEAK - FOUND HOSE CLAMPS LEAKING AT RESERVIOR - DRAINED R&R F IILTER - REPLACED CLAMP TIGHTENED ALL OTHER CLAMPS - FILLED CLEANED AND CHECK FOR LEAKS - CHECK OK.
10. FOUND PAT. DOOR SHOCKS AND MTS. LOOSE - TIGHTENED ALL SHOCKS AND MTS. - CHECK OK - REPAIRED AND GLUED DOOR SEAL ON REAR DOOR - CHECK OK.
11. INSTALL NEW NUMBER PLATES - APPLIED RED VINYL TO SIGNS.
12. FINISH APPLYING NUMBERS, VINYL AND CAMPAIGN STICKERS TO PLATES - INSTALLED NUMBER ON WINDSHIELD - CHECK OK.
13. Q & A INSPECTION.
14. FOUND BACK-UP CAMERA BACKWARDS ON SCREEN - REMOVED CAMERA MOVED IMAGE MAGNETIC PLUG - REINSTALLED AND ADJUSTED CHECK OK.
15. CHECK AIR HORNS - CHECK AND ADJUSTED AIR HORNS - CLEANED WORK AREA.

1847727C1BELT	1
1878042C91FUEL FILTER 2008 HORTON	1
2506656C124316 WIX CAB A/C FILTER	1
2507061C1PS RESV GASKET	1
46870AIR FILTER	1
5774457744XD OIL FILTER	1
91-22WIPER BLADE	2
AMH-1AMH-1 VALVE EXTENSION	1
F6DZ-8100-A9C3Z8101B RADIATOR CAP 10238 STANT	1
K060705BELT HORTON	1
L PLACARD INSERTLARGE PLACARD INSERT CARD	4
RWTG1234LED PRESSURE CAP	6
S PLACARD INSERTFRONT AND BACK INSERT CARD	1
SAHSVS2510STRAP	1
VMLT1808D2503221C1 FILTER POWER STEERING	1



10/17/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10182237

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

### Workorder: V49555

In Date: 05/22/2012

Meter Reading: 34,186.00

Close Date: 05/25/2012

#### Problem?

REPLACE REAR TIRES R46

#### Task performed:

REPLACE REAR TIRES R46.

#### Parts

216568BRIDGESTONE 255/70R22.5

#### Quantity

4

Vendor? BOULEVARD TIRE CENTE

### Workorder: V49648

In Date: 05/26/2012

Meter Reading: 34,855.00

Close Date: 06/01/2012

#### Problem?

Lower rear compartment door will not stay latched. R 46

#### Task performed:

ADJUSTED REAR DOOR LATCH

#### Parts

NO PARTS USED

#### Quantity

### Workorder: V50579

In Date: 07/03/2012

Meter Reading: 37,955.00

Close Date: 07/10/2012

#### Problem?

The back air condition of front cab is not working. Will not go on at all. No fan no air. R46

#### Task performed:

REAR CAB AIR INOP/BREAKER TRIPPED/DRAWS 0.4 AMPS ON 15 AMP ???? TESTED OK WILL MONITOR.

#### Parts

NO PARTS USED

#### Quantity

### Workorder: V50903

In Date: 07/17/2012

Meter Reading: 39,089.00

Close Date: 07/18/2012

#### Problem?

ON CALL A/C 10-7 R 46

#### Task performed:

PATIENT COMPARTMENT A/C INOP/ DISCHARGE LINE BLOWN AND COMPRESSOR DEFECTIVE/REPAIRED LINE AND REPLACED COMPRESSOR HAD TO REUSE CLUTCH NONE IN STOCK ALSO NO DRIER IN STOCK.

#### Parts

5790COMPRESSOR A/C

#### Quantity

1



10/17/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10182237

**INTERNATIONAL 4400 ADVANCED LIFE SUPPORT**

**Workorder: V50702**

In Date: 07/09/2012

Meter Reading: 38,507.00

Close Date: 08/08/2012

**Problem?**

C INSPECTION R 46

**Task performed:**

1. C-INSPECTION AND TIGHTEN ALL COMPARTMENT SCREWS.
2. REPLACE ALL CAB DOOR AJAR SWITCHES.
3. INSTALL REAR BRAKE SHOES, SPRING KIT AND DRUMS ADJUST ALL BRAKES.
4. INSTALL AIR DRYER KIT.
5. INSTALL FRONT AND REAR SHOCKS. HAD TO DISCONNECT AIR BAG LEVEL VALVE AND REATTACH.
6. WIPER BLADES.
7. R/REAR STROBE LIGHT REPLACE.
8. TIGHTEN ALL CAB STEP HANDLES.
9. TEST DRIVE.
10. Q.A. INSPECTION.
11. CHECK A/C FOUND COMPRESSOR WEAK AND BAD VALVE REPLACE COMPRESSOR, DRYER, EXPANSION VALVE. EVACUATE AND RECHARGE A/C.

**Parts**

**Quantity**

065624AD-IP DRIER	1
1501450007750USE 0775145	2
1878042C91FUEL FILTER 2008 HORTON	1
2506656C124316 WIX CAB A/C FILTER	1
3553628C3SHOCK REAR WPB	2
3578105C2FRONT SHOCKS	2
3579984C1DOOR SWITCH	4
3611894C9103-0805 A/C COMPRESSOR 4347	1
3660853C22512331C1 EXP VALVE NAV	1
3670134C1ACCUMULATOR ASSY INT.	1
3757REAR DRUMS 3757X 3647X	2
50R03ZCRLIGHT LED RED TIR 6	1
5774457744XD OIL FILTER	1
6819634283068-1963428-30 LENS CLR	1
91-22WIPER BLADE	2
E-600013-3052 NUT	1
HP-31DBATTERY 950CCA HP-31D	1
K022105PURGE VALVE AD-IP-IS	1
RWTG1234LED PRESSURE CAP	4
XK4034707QPMHD SHOE KIT 3/8 BEAM	2

**Workorder: V51169**

In Date: 07/27/2012

Meter Reading: 39,132.00

Close Date: 09/14/2012

**Problem?**

COOLANT LEAK R46

**Task performed:**

COOLANT LEAK REPAIRED LEAK AT COOLANT TANK.

**Parts**

**Quantity**

NO PARTS USED



10/17/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10182237

**INTERNATIONAL 4400 ADVANCED LIFE SUPPORT**

### Workorder: V51195

In Date: 07/30/2012

Meter Reading: 39,132.00

Close Date: 09/14/2012

#### Problem?

ON CALL COOLANT LEAK

#### Task performed:

RAN A/C AND CLEANED CONDENSER FANS AND REPAIRED COOLANT LEAK.

#### Parts

#### Quantity

3610318C2RADIATOR HOSE

1

ALA00350-50 EXTENDED LIFE COOLANT GAL

3

### Workorder: V51485

In Date: 08/09/2012

Meter Reading:

Close Date: 09/14/2012

#### Problem?

cover for one of the exterior outlet broke off. R46

#### Task performed:

1. CHANGED COVER INSTALLED NEW PLUG ON CORD TO SHORTLINE.

#### Parts

#### Quantity

091-3YWCOVER KUSSMAUL AUTO EJECT

2

### Workorder: V51708

In Date: 08/20/2012

Meter Reading: 40,622.00

Close Date: 09/17/2012

#### Problem?

ON CALL SMOKE IN REAR OF RESCUE R 46

#### Task performed:

TRACED OUT PROB FOUND WINDOW SOLENOID SHORTENED OUT REMOVED UIT AND INSTALLED NEW ONE.

#### Parts

#### Quantity

NO PARTS USED

### Workorder: V52099

In Date: 09/03/2012

Meter Reading:

Close Date: 09/20/2012

#### Problem?

left high beams out R 46

#### Task performed:

HEADLIGHT OUT, REPLACED. STRECHER NOT LATCHING REPLACED STRECHER LOCK.

#### Parts

#### Quantity

090-0278STRECHER BAR NEW

1

9007H9007 BULB ASSY

2



10/17/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10182237

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

### Workorder: V52054

In Date: 08/30/2012

Meter Reading:

Close Date: 09/21/2012

#### Problem?

Drivers side headlight is out

#### Task performed:

REPLACED HEADLIGHT AND REPAIRED WIRES.

#### Parts

NO PARTS USED

#### Quantity

### Workorder: V52061

In Date: 08/31/2012

Meter Reading:

Close Date: 09/21/2012

#### Problem?

left headlight out, also coolant low says add

#### Task performed:

COLLANT LEAK REPAIRED COOLANT LEAK AND TESTED.

#### Parts

NO PARTS USED

#### Quantity

### Workorder: V52388

In Date: 09/14/2012

Meter Reading:

Close Date: 09/25/2012

#### Problem?

Front (Cab) Air Conditioning inop. Fan will not blow air. Rear AC working fine. R46

#### Task performed:

REPLACED CAB BLOWER AND TESTED.

#### Parts

3674285C1BLOWER MOTOR

#### Quantity

1

### Workorder: V52498

In Date: 09/19/2012

Meter Reading:

Close Date: 10/01/2012

#### Problem?

The front driver side wheel well has a yellow reflector that has fallen off the truck. It is not an emergency light but rather an OEM part. R46

#### Task performed:

INSTALLED NEW LIGHT ON HOOD. REAR LIGHT LENS BROKEN REPLACED UNIT.

#### Parts

3561965C1LIGHT

91553943GUAGE

#### Quantity

1

2



10/17/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10182237

**INTERNATIONAL 4400 ADVANCED LIFE SUPPORT**

**Workorder: V52756**

In Date: 10/01/2012  
Close Date: 10/04/2012

Meter Reading: 44,874.00

**Problem?**

Air condition in front cab dose not work. R46

**Task performed:**

1. INSTALL TWO NEW THERMISTORS IN A/C SYSTEM CHARGE SYSTEM FOUND WIRING PROBLEM CORRECTED.
2. ASSIST IN A/C TROUBLESHOOTING.
3. INSTALL NEW INVERTER FOR PRIVACY WINDOWS.

Parts	Quantity
10006527WINDOW INVERTOR	1
3622764C32606229C92 THERMISTER	2

**Workorder: V52880**

In Date: 10/05/2012  
Close Date: 10/16/2012

Meter Reading:

**Problem?**

Amber clearance lamp out (Top left side of box) Need coolant for the station. R46

**Task performed:**

DROPPED OFF COOLANT AT STATION.

Parts	Quantity
NO PARTS USED	

**Workorder: V53079**

In Date: 10/15/2012  
Close Date: 10/17/2012

Meter Reading: 45,932.00

**Problem?**

ON CALL LOW COOLANT

**Task performed:**

COOLANT LOW - ADD 1/2 GALLON COOLANT - CHECK FOR LEAKS NONE FOUND - CHECK FOR STORED CODES NO FOUND - UNIT IN SERVICE.

Parts	Quantity
NO PARTS USED	





10/17/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10182237

**INTERNATIONAL 4400 ADVANCED LIFE SUPPORT**

**Workorder: V53091**

**In Date:** 10/15/2012

**Meter Reading:** 46,052.00

**Close Date:** 11/01/2012

**Problem?**

**B INSPECTION R 46**

**Task performed:**

1. B-INSPECTION.
2. REMOVE UPPER KING PIN CAPS AND INSTALL NEW 90 DEGREE ZERKS FROM STRAIGHT ZERK.
3. TROUBLE SHOOT BAR LIGHT AND VENT INOP.
4. SERVICE DRYER.
5. SEARCH FOR VENT MOTOR, CHECK WIRES BROKEN OFF MOTOR RE-SOLDER WIRES, MOUNT IN NEW SPOT.
6. FINISH REPIAR VENT MOTOR RE-MOUND.
7. TROUBLE SHOOT PATIENT COMP. LIGHTS GOING ON/OFF BY THEMSELVES. ALSO THE AIR RIDE IS GOING UP AND DOWN BY IT SELF.
8. CONTINUE TROUBLESHOOT LIGHT AND AIR BAY PROBLEM.
9. TROUBLE SHOOT LIGHT AND AIR BAG PROBLEM. FOUND BAD CONNECTION AT INPUT MODULE 12 FOR REAR DOOR SENSE.
10. REPAIR SHARPRES DRAW, DID NOT HAVE THE RIGHT SLIDES MADE ONE OF OURS WORK, ORDER SLIDES.
11. REMOVE R/R/I WHEEL, TIGHTEN VALVE STEM, CHECK FOR LEAKS.
12. TIGHTEN ALL COOLANT HOSE CLAMPS.
13. REPLACE LEFT FRONT UPPER COVER MARKER LIGHT AND REAR LIGHT BAR LIGHT.
14. CHECK CAB A/C LOW ON FREON CHECK FOR LEAK. NOE FOUND. RE-CHARGE SYSTEM.
15. Q.C. VEHICLE AFTER REPAIRS.
16. REPLACE ALL PATIENT COMP. CABINET HOLD OPENS.
17. REMOVE BLOWN AIR COMPRESSOR AIR INTAKE LOOSE. INSTALL NEW HOSE AND OPERATE UNIT.
18. REMOVE TIRES AND INSTALL NEW TIRES TO CORRECT VIBRATION PROBLEM AIR TIRES TO SPECS. ROAD TEST.
19. R&R TIRES, TAKE ON ROAD TEST FOR VIBRATION.
20. TIGHTEN ALL COMPARTMENT HOLD OPEN MOUNTS.

**Parts**

**Quantity**

065624AD-IP DRIER	1
10006527WINDOW INVERTOR	1
1501450007750USE 0775145	3
1878042C91FUEL FILTER 2008 HORTON	2
5632-1212 IN PAIR DRAWER SLIDES	2
5774457744XD OIL FILTER	2
78R539018-2699 A/C FILTER	1
91-22WIPER BLADE	2
CLR9185209186-1500-20 MARKER LT.AMBER LED	1
HLD3999GSS1715UV 30LB STRUT GAS	4
K022105PURGE VALVE AD-IP-IS	1
KR-CCL-1-WPCATHODE LIGHT WATERPROOF	1
RWTG1234LED PRESSURE CAP	4
XK4034707QPMHD SHOE KIT 3/8 BEAM	2



10/17/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10182237

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

**Workorder: V53619**

In Date: 11/07/2012  
Close Date: 11/09/2012

Meter Reading: 46,925.00

**Problem?**

low coolant

**Task performed:**

LOW COOLANT/ UNKNOWN/ TOP OFF COLLANT  
PRESSURE TEST NO EXTERNAL LEAKS NEED TO  
BRING TO SHOP TO CHECK EGR COOLERS.

Parts

Quantity

NO PARTS USED

**Workorder: V53466**

In Date: 11/01/2012  
Close Date: 11/30/2012

Meter Reading:

**Problem?**

missing passenger side windshield wiper R 46

**Task performed:**

REPAIRED WIPER ARM AND REPAIRED WIPER  
SWITCH.

Parts

Quantity

91-22WIPER BLADE

2

**Workorder: V53881**

In Date: 11/19/2012  
Close Date: 12/26/2012

Meter Reading: 48,286.00

**Problem?**

Plexiglass from R1 compartment door (inside patient compartment) broken.

**Task performed:**

1. REPLACED COMPARTMENT DOOR GLASS.
2. AIR LEAK - REPAIRED AIR LEAK ON REAR MAIN TANK.

Parts

Quantity

NO PARTS USED

**Workorder: V53882**

In Date: 11/19/2012  
Close Date: 12/26/2012

Meter Reading: 48,286.00

**Problem?**

Right upper strobe light cover broken at screwin attachment points.

**Task performed:**

REPLACED LIGHT AND REPAIRED WIRING.

Parts

Quantity

NO PARTS USED



10/17/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10182237

**INTERNATIONAL 4400 ADVANCED LIFE SUPPORT**

**Workorder: V53994**

In Date: 11/26/2012

Meter Reading: 48,923.00

Close Date: 12/26/2012

**Problem?**

The yellowrear cross bar emergency light is out r46

**Task performed:**

Parts

Quantity

REPAIRED SHORTED WIRE IN LIGHT BAR.

NO PARTS USED

**Workorder: V53970**

In Date: 11/24/2012

Meter Reading:

Close Date: 01/03/2013

**Problem?**

right rear brakes smell like something is burning. R 46

**Task performed:**

Parts

Quantity

CHECKED BRAKES OUT FOUND NO PROBLEM.

NO PARTS USED

**Workorder: V54075**

In Date: 11/29/2012

Meter Reading:

Close Date: 01/03/2013

**Problem?**

The cap for the left side rear emergency lights came off

**Task performed:**

Parts

Quantity

REPLACED LENS AND REPAIRED WIRES.

NO PARTS USED

**Workorder: V55104**

In Date: 01/16/2013

Meter Reading: 52,014.00

Close Date: 01/22/2013

**Problem?**

Replace all tires [Labor only]R-46

**Task performed:**

Parts

Quantity

REPLACE ALL TIRES (LABOR ONLY) R46

NO PARTS USED

**Vendor?** BOULEVARD TIRE CENTE



10/17/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10182237

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

### Workorder: V54566

In Date: 12/21/2012

Meter Reading: 51,750.00

Close Date: 01/25/2013

#### Problem?

There is a hole on the rubber pass thru insulator between the front cab and traesport cab and the rescue is still leaking antifreeze R46

#### Task performed:

RESEAL HOLE IN RUBBER TUBE.

#### Parts

NO PARTS USED

#### Quantity

### Workorder: V54652

In Date: 12/27/2012

Meter Reading: 52,014.00

Close Date: 02/01/2013

#### Problem?

C INSPECTION R 46

#### Task performed:

1. C INSP
2. C INSP
3. REPLACE VALVE CORES IN TWO TIRE VALVES ALSO REPLACED TWO BAD PRESSURE SENSORS.
4. REMOVE MODIC COMPARTMENT GLASS AND MATCH UP REINSTALL.
5. RECOVER A/C SYSTEM.
6. REPLACE PATIENT COMPARTMENT SHOCKS.
7. INSTALL BOTH SYSTEM BELTS.
8. CHECK AIR LEAKS.
9. WENT ON THE ROAD TO REPAIR COOLANT LEAK- REPAIRED LEAK- FILLED RAD- RETURNED TO SHOI
10. DIAGNOSE AND REPLACE 110V A/C CONDENSOR FANS.
11. SERVICE AIR DRYER.
12. REPLACE REAR BRAKE SHOES AND DRUMS.
13. SERVICE TRANSMISSION.
14. DIAGNOSE A/C CONTROL HAND FAULT REPLACE RECALABRATE DOOR MOTOR.
15. REMOVE REAR BUMPER FROM R31 AND INSTALL ON R46.
16. REMOVE PASS THROUGH SEAL AND REPLACE WITH ARE SEAL MATERIAL.
17. REPAIR WIRING ON R2 GROUND LIGHT.
18. INSTALL BELT TENSIONER AND AUX BELT.
19. REPLACE HOSE CLAMP ON ESR COOLER PRESSURE TEST AND TEST DRIVER.
20. Q.A INSPECTION.

#### Parts

065624AD-IP DRIER 1

15-40B15W40 MOTOR OIL NON SYN 30

1501450007750USE 0775145 2

1847727C1BELT 1

1878042C91FUEL FILTER 2008 HORTON 1

216568BRIDGESTONE 255/70R22.5 6

2506656C124316 WIX CAB A/C FILTER 1

29526898 29548988 TRANS FILTER ALLISON 1

3542575C2VENT MOT0R 1

3542606C12611234C1 VENT ACTUATOR 1

3757REAR DRUMS 3757X 3647X 2

38504TENSIONER HORTON ADD ON A/C 1

50-2204FAN KIT DANHARD CONDENSER 1

5774457744XD OIL FILTER 1

78R539018-2699 A/C FILTER 1

AMH-1AMH-1 VALVE EXTENSION 1

DOOR 822 7/8 X 7 1/2 DOOR HORTONS 1

E-600013-3052 NUT 1

GASK-BEL0110002439 WINDOW BELLOWS 6 IN WIDE 6

HLD3999GSS1715UV 30LB STRUT GAS 2

K022105PURGE VALVE AD-IP-IS 1

K060705BELT HORTON 2

RWTG1234LED PRESSURE CAP 4

XK4034707QPMHD SHOE KIT 3/8 BEAM 2

#### Quantity



10/17/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10182237

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

### Workorder: V55331

In Date: 01/27/2013

Meter Reading:

Close Date: 02/04/2013

#### Problem?

air dump is not working properly and while going code 3 with lights on a warning is sounding advising to set parking break

#### Task performed:

TRAVELED TO STATION FOUND TRUCK WOULD NOT DUMP DOME LIGHTS WOULD NOT WORK COMPARTMENT LIGHTS INOP- NEED NEW INPUT MODULE.

#### Parts

#### Quantity

10007828HORTON INPUT MODULE

1

AMH-1AMH-1 VALVE EXTENSION

1

### Workorder: V55485

In Date: 02/01/2013

Meter Reading: 52,717.00

Close Date: 02/07/2013

#### Problem?

air dump inop

#### Task performed:

1. SWAP MODULE FOR COMPARTMENT WITH R72 AND REINSTALL BOTHMODULES.
2. REMOED CPU FROM R-73 REPROGRAMMED CPU INSTALLED INTO 46. REPAIRED WIRING HARNESSES AND CHECKED OPERARION.

#### Parts

#### Quantity

10008530KNEEL MODULE HORTON

1

### Workorder: V55667

In Date: 02/09/2013

Meter Reading:

Close Date: 02/14/2013

#### Problem?

strobes on the rear and side of the box portion of the truck are not working properly. The large strobes are staying solid and not strobing. R46

#### Task performed:

PROGRAMMED INTERPLEX FOR FLASH PATTERN.

#### Parts

#### Quantity

NO PARTS USED

### Workorder: V55831

In Date: 02/19/2013

Meter Reading: 53,772.00

Close Date: 02/20/2013

#### Problem?

Rear a/c inop R-46

#### Task performed:

RECHARGED A/C AND REPAIRED LEAK.

#### Parts

#### Quantity

NO PARTS USED



10/17/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10182237

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

## Workorder: V55922

In Date: 02/22/2013

Meter Reading: 54,223.00

Close Date: 02/25/2013

### Problem?

cab a/c inop

### Task performed:

GO TO ST 46 DIAGNOSE A/C SYSTEM TAKE TO SHOP AND REPLACE THERMASTAT EVALUATE AND RECHARGE A/C SYSTEM.

### Parts

### Quantity

3622764C32606229C92 THERMISTER

2

## Workorder: V54653

In Date: 12/27/2012

Meter Reading: 52,014.00

Close Date: 03/12/2013

### Problem?

REPAIR COOLANT LEAKS

### Task performed:

1. REMOVE EGR COOLER CROSSOVER TUBE TO VERIFY FAULTY COOLERS AND ORDER.
2. REMOVE BOTH EGR COOLERS.
3. INSTALL L/S EGR COOLER AND EGR VALVE ALL COOLER HOSES.
4. INSTALL R/S EGR COOLER REFILL COOLANT SYSTEM. CHECK FOR LEAKS.
5. INSTALL R/S FENDER AND INNER FENDER. PRESSURE TEST COOLING SYSTEM. SCAN AND CLEAR CODES TEST DRIVE.

### Parts

### Quantity

1876262C96EGR COOLER INT SIDE USE 4307362R91

1

1878918C2EGR VALVE

1

7090595C91COOLER EGR KIT 330MM EXH SIDE OLD 1876

1

ANTICOOLANT ANTIFREEZE GAL

5

CORECORE CHARGE

1

F6DZ-8100-A9C3Z8101B RADIATOR CAP 10238 STANT

1

## Workorder: V55986

In Date: 02/25/2013

Meter Reading: 54,396.00

Close Date: 03/15/2013

### Problem?

R headlight is out and we have none in stock. r 46

### Task performed:

1. REPAIRED COOLANT LEAK AT TANK.
2. READJUSTED REAR DOORS THAT WERE HARD TO OPEN.

### Parts

### Quantity

9007H9007 BULB ASSY

1

G5095 IN STORZ GASKET BLACK MAX

4



10/17/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10182237

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

### Workorder: V56604

In Date: 03/24/2013

Meter Reading: 57,211.00

Close Date: 04/10/2013

#### Problem?

Diesel key on R46 is bent need a replacement

#### Task performed:

Parts

Quantity

DROPPED OFF SPARE KEY.

NO PARTS USED

### Workorder: V54759

In Date: 01/02/2013

Meter Reading: 52,014.00

Close Date: 04/11/2013

#### Problem?

replace bumper

#### Task performed:

Parts

Quantity

NO PARTS USED

### Workorder: V55309

In Date: 01/26/2013

Meter Reading:

Close Date: 04/22/2013

#### Problem?

The dump is non functional. We have to dunnp the truck manually R-46

#### Task performed:

Parts

Quantity

PARTS WERE MADE.

NO PARTS USED

### Workorder: V57361

In Date: 04/30/2013

Meter Reading: 60,421.00

Close Date: 05/01/2013

#### Problem?

instauill striker streacher r-46

#### Task performed:

Parts

Quantity

1. CHANGED OUT STRETCHER TO NEW STYLE STRYKER. INSTALL HOOK. INSTALLED MAGNETIC DISCONNECT AND ADJUSTED RELEASE POLE.
2. ASSIST IN REPLACING OLD STRETCHER - ADJUSTEDLOCK AND MAGNETIC DISCONNECT.

NO PARTS USED



10/17/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10182237

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

**Workorder: V57647**

In Date: 05/10/2013  
Close Date: 05/10/2013

Meter Reading: 60,479.00

**Problem?**

OCS B inspection R46

**Task performed:**

Parts

Quantity

B inspection  
changed oil and fuel filters

NO PARTS USED

**Vendor?** OIL CHANGE SERVICES

**Workorder: V58476**

In Date: 06/17/2013  
Close Date: 06/17/2013

Meter Reading: 64,508.00

**Problem?**

rear a/c inop

**Task performed:**

Parts

Quantity

TRACED OUT PROBLEM FOUND CONDENSER FANS  
INOP- REPAIRED RELAY FOR FANS AND TESTED.

NO PARTS USED

**Workorder: V58889**

In Date: 07/06/2013  
Close Date: 07/19/2013

Meter Reading: 66,009.00

**Problem?**

Air leak when truck is turned off. R46

**Task performed:**

Parts

Quantity

1. TRACED OUT AIR LEAK AND FOUND AND REPAIRED.
2. READJUSTED AIR BAGS THAT WERE OUT OF ADJUSTMENT.

NO PARTS USED

**Workorder: V59057**

In Date: 07/13/2013  
Close Date: 07/19/2013

Meter Reading: 66,449.00

**Problem?**

small air leak R 46

**Task performed:**

Parts

Quantity

1. CHECKED FOR AIR LEAKS FOUND NONE AT THIS TIME.
2. ADJUSTED REAR DOOR LINKAGE.

NO PARTS USED





10/17/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10182237

**INTERNATIONAL 4400 ADVANCED LIFE SUPPORT**

**Workorder: V57219**

**In Date:** 04/23/2013

**Meter Reading:**

**Close Date:** 08/01/2013

**Problem?**

DIESEL KEY FOR R46 BROKEN/NEED REPLACEMENT

**Task performed:**

Parts

Quantity

NO PARTS USED

---



10/17/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10182237

**INTERNATIONAL 4400 ADVANCED LIFE SUPPORT**

**Workorder: V59169**

**In Date:** 07/17/2013

**Close Date:** 08/08/2013

**Meter Reading:** 66,567.00

**Problem?**

C Inspection R46

**Task performed:**

Parts

Quantity



10/17/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10182237

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

1. C-Inspection.	1501450007750USE 0775145	2
2. C-Inspection continued.	1878042C91FUEL FILTER 2008 HORTON	1
3. Inflate all 6 tires to 110 psi install missing l/r inflator, hose. Replace 4 TPMS Blinkers.	2506656C124316 WIX CAB A/C FILTER	1
4. Repair O2 wrench make custom length screw to attach cable.	370001ASEAL 35066	2
5. R&R cab aux a/c filter.	3757REAR DRUMS 3757X 3647X	2
6. R&R patient a/c filters.	46870AIR FILTER	1
7. Tighten screws on hold open support bracket in fwd med cabinet remove and replace shelf in order to tighten screws for hold open in rear med cabinet.	5774457744XD OIL FILTER	1
8. Remove air pack bracket on compt L-2 door. Hole stripped. Drill and install nutserts to secure bracket.	607141-05USE 61H01 COPMPARTMENT LIGHT	6
9. Raise vehicle on lift. Drain 2 qts of trans fluid.	78R539018-2699 A/C FILTER	1
10. Wire broken off red door warn light. R&R door panel. Extend wiring harness to red light. Test light assy. Reassemble panel and light assy.	AMH-1AMH-1 VALVE EXTENSION	1
11. R&R lens R&R bulb on l/s drivers door white light.	CHR1612340-4024 HUB COVER - FRONT AXLE 2004 RESC	2
12. R&R and file and shim striker block for rear double door medical cabinet.	GPX13ULTRA VIOLET LIGHT SHORT	1
13. Remove drag link. Clean and inspect tapered hole and tapered stud clean threads reinstall and tighten.	GUI1R11216GY1R11216 AIR BAG INT.	2
14. R&R u-v light.	H35SN12BULB	2
15. Build up air pressure. Soap air system to find all baks found baky fittings and leaking air bag.	RWTG1234LED PRESSURE CAP	4
16. Diagnose why 2 rear loading lights don't work. Disassemble rear light bar r&R lenses r&R 2 bulbs.	S1818COUPLING	1
17. Start R&R of 6 ground lights.	XK4034707QPMHD SHOE KIT 3/8 BEAM	2
18. Finish R&R of 6 ground lights. Had to cut off existing connectors and install new connectors to fit new lights. Heat shrink all connections.		
19. R&R 2 rear suspension air bags and fittings.		
20. R&R fan clutch fitting at brake valve R&R fitting on governor.		
21. Start diagnosis and repair of both car a/c not cold.		
22. Continued diagnosis and repair of both cab a/c not cold. Check fan clutch grevation. Check temp drop across condensor. R&R freon and fill to factory amount. Road test both car units now proper temp.		
23. R&R wheels and tires and hub caps. R&R rear brakes and drums adj brakes. Check air chambers for leaks with brakes applied road test. Measure stroke length applied and off both exactly.		
24. Electronic trans oil level says still high. Check dipstick raise vehicle on hoist. Drain 1 quart trans fluid. Recheck shift display - now ok.		
25. Jack up vehicle remove front tires, drums and hubs wash all old grease from hubs, bearings and spindle.		
26. Finish above job. Assemble all clean parts. Install oil type seals install oil type hub cover fill with oil adj brng preload adj frt brakes.		
27. Q.C. truck.		



10/17/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10182237

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

**Workorder: V59617**

In Date: 08/06/2013  
Close Date: 08/19/2013

Meter Reading: 66,720.00

**Problem?**

10182237 Rescue truck is making a high pitch noise from the engine. Just came back from PM as well.

**Task performed:**

1. REPAIRED ALL HOSES ON TURBO AND ROAD TESTED.
2. REPLACE HEADLIGHTS AND REPAIRED SHORT.

Parts

Quantity

9007H9007 BULB ASSY

2

**Workorder: V60128**

In Date: 08/27/2013  
Close Date: 08/27/2013

Meter Reading: 68,346.00

**Problem?**

will not start, at jog and La chalet. R-46

**Task performed:**

1. travel to Jog and La chalet rd, check out for no start, transmission push pad had two stars and a wrench showing on display, check battery's, starter, and wiring, hook up laptop, had codes for no power to TCM for transmission, check fuse for trans, when fuse removed and reinstalled truck would start, followed unit back to sta-46, driver stated would no shift out of 1st gear on the way back to sta., continue to check out unit, could not find problem, called c/shop per Steve R unit will be towed and spare sent down to sta. travel back to s/shop.

Parts

Quantity

NO PARTS USED

**Workorder: V60286**

In Date: 09/05/2013  
Close Date: 09/06/2013

Meter Reading: 68,346.00

**Problem?**

Install N.Y. hook brackets

**Task performed:**

- INSTALLED BRACKETS.

Parts

Quantity

5269LPVM-5 SM MOUNT

2



10/17/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10182237

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

### Workorder: V59246

In Date: 07/22/2013

Meter Reading: 68,346.00

Close Date: 09/10/2013

#### Problem?

Request to have windows tinted during PM.

#### Task performed:

REPAIRED ON DO-440-071813-22729

Parts

NO PARTS USED

Quantity

### Workorder: V59951

In Date: 08/21/2013

Meter Reading: 67,823.00

Close Date: 09/13/2013

#### Problem?

front A.C. in R46 not working. Not blowing any air. E46

#### Task performed:

NO CAB A/C TRACED OUT PROBLEM FOUND BAD CONNECTION ON BLOWER MOTOR REPAIRED AND RETESTED.

Parts

NO PARTS USED

Quantity

### Workorder: V60476

In Date: 09/13/2013

Meter Reading: 68,811.00

Close Date: 09/30/2013

#### Problem?

medical supply drawer latch is broken, the drawer slides open when brakes are applied. 3rd drawer from the bottom. if you are sitting to close it hit you in the head.

#### Task performed:

1. REPAIRED MED DRAW THAT WAS BROKEN AND TESTED.
2. REPAIRED FOLD DOWN STEP IN REAR OF TRUCK.

Parts

NO PARTS USED

Quantity

### Workorder: V61053

In Date: 10/07/2013

Meter Reading: 70,876.00

Close Date: 10/09/2013

#### Problem?

no cab a/c and coolant leak

#### Task performed:

1. RECHARGED A/C AND TESTED WAS BLOWING COOLER. COOLANT LEAK-REPAIRED LOWER HOSE THAT WAS LEAKING.

Parts

NO PARTS USED

Quantity



10/17/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10182237

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

**Workorder: V61041**

In Date: 10/06/2013  
Close Date: 10/10/2013

Meter Reading: 70,876.00

**Problem?**

air conditioning is only working when the vehicle is in motion

**Task performed:**

- CHECK A/C REPLACE BAD COMPRESSOR AND DRYER.
- COOLANT LEAK - EGR HOSES LAKING AT CLAMPS - TIGHTEN CLAMPS AND TOP OFF COOLANT RESOVIOR.

Parts	Quantity
22230-000-30BREAKER CIRCUIT 30A	4
3611894C9103-0805 A/C COMPRESSOR 4347	1
3670134C1ACCUMULATOR ASSY INT.	1

**Workorder: V60994**

In Date: 10/04/2013  
Close Date: 10/21/2013

Meter Reading: 70,548.00

**Problem?**

power door locks not working, patient compartment will automatically lock and can only be unlocked with key.

**Task performed:**

- LOCKS INOP, TRACED OUT PROBLEM FOUND BAD FUSE REPLACED AND TESTED.

Parts	Quantity
NO PARTS USED	

**Workorder: V61312**

In Date: 10/17/2013  
Close Date: 11/01/2013

Meter Reading:

**Problem?**

rear tires are close to the wear bars r46

**Task performed:**

- WILL HAVE NEW TIRE INSTALL ON REAR OF TRUCK

Parts	Quantity
NO PARTS USED	

**Workorder: V61589**

In Date: 10/28/2013  
Close Date: 11/08/2013

Meter Reading:

**Problem?**

Temperature light coming on. Temperature readings upwards of 200 deg F. r46

**Task performed:**

- CHECKED TRUCK AND ROAD TEST FOR HEATING AND TESTED OK.
- AIR LEAK CHECKED FOR AIR LEAKS AND FOUND NONE AT THIS TIME.

Parts	Quantity
NO PARTS USED	



10/17/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10182237

**INTERNATIONAL 4400 ADVANCED LIFE SUPPORT**

**Workorder: V62560**

**In Date:** 12/07/2013

**Close Date:** 12/13/2013

**Meter Reading:** 74,216.00

**Problem?**

REPAIR A/C

**Task performed:**

DIAGNOSE CAB A/C NOT COLD. FOUND EVAP INLET THERMISTOR BAD ON LAPTOP DISCHARGE SYSTEM FOR EVAP THERMASTORS. EVACUATE AND RECHARGE SYSTEM.

Parts

Quantity

3622764C32606229C92 THERMISTER

1



10/17/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10182237

**INTERNATIONAL 4400 ADVANCED LIFE SUPPORT**

**Workorder: V62260**

**In Date:** 11/25/2013

**Close Date:** 12/16/2013

**Meter Reading:** 73,564.00

**Problem?**

B inspection R46

**Task performed:**

Parts

Quantity





10/17/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10182237

## INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

1. B INSP.
2. BATTERIES FAILED BATT TEST- REPLACE BATTS- ALSO BATT SLIDE TRAY LOCKING LATCH FROZEN- PENETRATE AND FREE UP TO WORK PROPERLY.
3. TIRE INFLATION KITS L/REAR ON HAD 1/2 A KIT INSTALLED-INSTALLED MISSING PIECES.
4. BATT COVER AND STEP. BATT COVER/STEP RATTLES LOAD- READJUST ALL FOUR LATCHES.
5. DOOR ALARM CHECK OUT PROBLEM-FOUND FLIP/DOWN COMPT DOOR UNDER REAR ENTRY WOULD NOT LATCH PROPERLY- STATIONARY LATCH WAS BROKEN AND WAS BARELY CONTACTING YOUR LATCHMECHANISM- FIND A PIECE OF MATERIAL IN WELD SHOP AND MAKE UP NEW STATIONARY LATCH- MOUNT AND ADJUST- NOW OK.
6. INSTALL NEW WIPER BLADES.
7. REAR LT-BAR CENTER OF LT BAR OVER/UNDER LED LT ONLY HALF WORKS- DISASSEMBLE LT BAR TO GET CTR LED FIXTURE- REMOVE AND INSTALL NEW FIXTURE- REASSEMBLE LT-BAR TEST-NOW OK.
8. GROUND LTS. GROUND LT UNDER DRIVERS DOOR-INOP- REMOVE OLD- INSTALL NEWER STYLE LED GROUND LT MODIFY WIRING TO INSTALL NEW STYLE LT FIXTURE.
9. CAB STEP LONG STEP ON RT SIDE IS VERY LOOSE AND RATTLES FOUND FOUR BOLTS BROKEN AND TWO UNDER STEP BRACKETS BENT UP FROM HITTING SOMETHING- REMOVE BRACKETS AND USING PRESS AND BARS STRAIGHTEN OUT AS BEST AS POSSIBLE AND REINSTALL- REDRILL HOLE LOCATIONS AND INSTALL NEW BOLTS.
10. SQUEELING- ENG AREA CHURPPING/SQUEEZING NOISE FROM L/SIDE OF ENG REMOVE A/C BELT-START ENG AND RECHECK- NOISE GONE- CHECK OUT A/C COMPRESSOR CLUTCH- SEEMS OK- CHECK IDLER AND TENSIONER PULLEYS DIDNT FEEL SMOOTH- REPLACED BOTH AND BELT- START ENG RECHECK NOISE GONE.
11. FRT TIRES REMOVE FRONT TIRES TO HAVE NEW TIRES MOUNTED FROM OUTSIDE VENDOR- REINSTALL FRT TIRES AND SET PRESSURES TO PORPER LEVEL.

01-0286361211LAMP ASSY LED AMBER/AMBER	1
0128042000PULLY TENSION	1
15-40B15W40 MOTOR OIL NON SYN	30
1878042C91FUEL FILTER 2008 HORTON	1
2506656C124316 WIX CAB A/C FILTER	1
38504TENSIONER HORTON ADD ON A/C	1
5774457744XD OIL FILTER	1
607141-05USE 61H01 COPMPARTMENT LIGHT	1
91-22WIPER BLADE	2
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTEF	3
HP-31DBATTERY 950CCA HP-31D	3
K060705BELT HORTON	1



10/17/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10182237

**INTERNATIONAL 4400 ADVANCED LIFE SUPPORT**

### Workorder: V62588

In Date: 12/09/2013

Meter Reading: 74,216.00

Close Date: 12/23/2013

#### Problem?

Replaced two tires.

#### Task performed:

REPLACED TWO TIRES.

#### Parts

NO PARTS USED

#### Quantity

Vendor? BOULEVARD TIRE CENTE

### Workorder: V62855

In Date: 12/20/2013

Meter Reading: 75,266.00

Close Date: 12/31/2013

#### Problem?

Hard starting after sitting a while A/C intermittent L/R cab door window inop

#### Task performed:

1. ASSIST IN REPAIRS. DRAIN OIL AND REFILL REPLACED FILTER.
2. TROUBLESHOOT POWER WINDED PROBLEM. DRIVERS DOOR MODULE BAD. ORDERED PARTS.
3. REMOVE AND REPLACE THERMESTERS CHARGE A/C SYSTEM AND TEST FOR OPERATION IS GOOD NOW.

#### Parts

15-40B15W40 MOTOR OIL NON SYN  
 3622764C32606229C92 THERMISTER  
 5774457744XD OIL FILTER

#### Quantity

30  
1  
1

### Workorder: V61507

In Date: 10/24/2013

Meter Reading:

Close Date: 01/06/2014

#### Problem?

front tires need to be replaced. 4 rear tires getting replaced today.

#### Task performed:

REPAIRED ON V61312.

#### Parts

NO PARTS USED

#### Quantity

### Workorder: V63121

In Date: 01/03/2014

Meter Reading:

Close Date: 02/06/2014

#### Problem?

driver side rear scene light damaged and cover is broken off. R46

#### Task performed:

1. REMOVED AND REPLACED LIGHT, AND TESTED.
2. REPAIRED ALL SLIDE OUT STEPS THAT WERE HARD TO PULL.

#### Parts

90R00FRR900 SERIES LED W/O FLANGE - RED

#### Quantity

2



10/17/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10182237

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

### Workorder: V63439

In Date: 01/16/2014

Meter Reading:

Close Date: 02/06/2014

#### Problem?

LEAKING COOLANT(REDFLUID)

#### Task performed:

PRESSURE TESTED SYSTEM AND FOUND WATER PUMP LEAKING- REMOVED AND REPLACED.

#### Parts

#### Quantity

1842665C93WATER PUMP DT570

1

ALA00350-50 EXTENDED LIFE COOLANT GAL

6

### Workorder: V64072

In Date: 02/08/2014

Meter Reading:

Close Date: 02/12/2014

#### Problem?

DRIVERS COMPARTMENT AC IS OUT

#### Task performed:

1. check cab a/c, found compressor not coming on, check for power at compressor, no power, replace high side pressure switch, still no compressor, remove freon had 2lbs 4 oz, replace thermister's recharge a/c compressor comes on and cools to 29deg.

#### Parts

#### Quantity

3546241C1SWITCH A/C PRESSURE INT.

1

3622764C32606229C92 THERMISTER

1

### Workorder: V64404

In Date: 02/20/2014

Meter Reading: 80,982.00

Close Date: 02/27/2014

#### Problem?

Replace rear tires R46 Boulevard Tire

#### Task performed:

REPLACE REAR TIRES R46 BOULEVARD TIRE.

#### Parts

#### Quantity

NO PARTS USED

Vendor? BOULEVARD TIRE

### Workorder: V64559

In Date: 02/26/2014

Meter Reading:

Close Date: 03/10/2014

#### Problem?

when the truck is first started air comes out cold. by the time we get to call or out of house with pt air is warm. Shut truck off start a/c is cold. By the time we get to it blowing warm again R46

#### Task performed:

ROAD TESTED TRUCK AND A/C WAS BLOWING COLD CONNECTED LAPTOP AND CHECKED A/C OPERATION AND WAS ALL WORKING.

#### Parts

#### Quantity

NO PARTS USED



10/17/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10182237

**INTERNATIONAL 4400 ADVANCED LIFE SUPPORT**

**Workorder: V64730**

In Date: 03/06/2014

Meter Reading:

Close Date: 03/12/2014

**Problem?**

A/C still is not working. It will blow for 10 minutes than start blowing warm. Truck has to be turned off for and turned on for it to blow cold for another 10 mintues. R46

**Task performed:**

1. A/C BLOWER INOP- REPLACED BLEND DOOR MOTORS BROKEN CAMS.
2. HARD START OIL LEVEL OVERFILLED- FUEL IN OIL- DROPPED OIL AND FITLER REPLACED WITH 30QTS.
3. DPF CLOGGED- REGENED SYSTEM. WOULD NOT GET UP TO TEMP- REPLACED DPF.
4. TROUBLESHOOT AND REPLACE D.P.F- ASSIST IN TROUBLESHOOT CODES.

Parts

Quantity

15-40B15W40 MOTOR OIL NON SYN	30
2593986C1DPF GASKET	1
2593998C1DPF GASKET	1
3542606C12611234C1 VENT ACTUATOR	2
5774457744XD OIL FILTER	1
DPFCLEANED UNIT	1

**Workorder: V64240**

In Date: 02/15/2014

Meter Reading:

Close Date: 03/19/2014

**Problem?**

Cover for power outlet on the outside of the truck has been broken off. R46

**Task performed:**

1. REPAIRED AIR LEAK AT REAR AIR TANK.
2. REPLACED COVER FOR 110 OUTLET.

Parts

Quantity

NO PARTS USED

**Workorder: V65207**

In Date: 12/09/2013

Meter Reading: 74,216.00

Close Date: 03/26/2014

**Problem?**

Replaced two tires.

**Task performed:**

REPLACED TWO TIRES.

Parts

Quantity

NO PARTS USED

Vendor? BOULEVARD TIRE



10/17/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10182237

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

**Workorder: V65222**

In Date: 03/26/2014

Meter Reading:

Close Date: 03/26/2014

**Problem?**

rear tires are close to the wear bars r46

**Task performed:**

Parts

Quantity

REAR TIRES ARE CLOSE TO THE WEAR BARS R46.

NO PARTS USED

Vendor? BOULEVARD TIRE

**Workorder: V65140**

In Date: 03/23/2014

Meter Reading:

Close Date: 04/09/2014

**Problem?**

A/C still not working in the cab. R46

**Task performed:**

Parts

Quantity

REPAIRED ON WORK ORDER 65318.

NO PARTS USED

**Workorder: V65318**

In Date: 03/31/2014

Meter Reading:

Close Date: 04/30/2014

**Problem?**

Air in front cab usually blows cold for only about 10 minutes then starts blowing warm. We have to keep shutting the truck off and starting again to get cold air. Then again in about 10 minutes.

**Task performed:**

Parts

Quantity

COULD NOT REPRODUCE A/C CONCERN.

NO PARTS USED



10/17/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10182237

**INTERNATIONAL 4400 ADVANCED LIFE SUPPORT**

**Workorder: V65570**

**In Date:** 04/09/2014

**Close Date:** 04/30/2014

**Meter Reading:** 85,018.00

**Problem?**

C inspection R46

**Task performed:**

Parts

Quantity



10/17/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10182237

### INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

1. FINISH CONDENSER REPLACEMENT- REPLACED O-RINGS CHECK OK.
2. REASSEMBLE TRUCK AND DIAGNOSE A/C ISSUE
3. REPLACE A/C COMPRESSOR AND THERMOSTAT AND TEST DRIVE TRUCK TO BLEED AIR OUT OF SYSTEM AFTER HIGH PRESSURE PUMP REPLACEMENT AND TOPPED OFF OIL.
4. PERFORM C SERVICE.
5. CONTINUED/COMPLETED C SERVICE.
6. REPLACED LIGHT POLE BRACKETS ON FRT BUMPER (BENT/CRACKED).
7. REPLACED WIPER BLADES.
8. ADJUSTED ALL LATCHES ON BATTERY DOOR. (LOOSE/RATTLING).
9. REATTACH O2 WRENCH AND CABLE TO COMPARTMENT WALL AND INSTALL NEW VELCRO
10. ADJUST COOLANT HOSE CLAMPS AWAY FROM COMPRESSOR INTAKE HOSE (CHAFFING) AND HOSE FROM MOVING BACK AND FORTH.
11. PAINTED BOTH FUEL TANK CAPS.
12. REATTACHED HOLD DOWN BRACKET IN O2 COMPARTMENT (STRIPPED) LUBED AND ADJUSTED ALL DOOR LATCHES, HOLD OPENS ON CAB AND BODY.
13. REPLACED BRAKE PEDAL PAD. (WORN OUT).
14. REPLACED REAR CAB A/C FILTER.
15. SERVICE P/S.
16. REPLACED BELTS.
17. TROUBLESHOOT 110V A/C FAN INOP. (BLOWER FAN).
18. CONTINUED TO TROUBLESHOOT 110V A/C BLOWER INOP. TRACED PROBLEM FAULTY FAN MOTOR MODULE ASSEMBLY TORE EVEN BOX, CHANGED OUT FAN ASSEMBLY REASSEMBLED AND TESTED. 110V A/C IN NOW OPERATING AND COOLING NORMALLY.
19. REPLACED PATIENT COMPARTMENT A/C FILTERS.
20. REPLACED CLAMP ON COOLANT HOSE BEHIND TRBO. (LEAKING)
21. SERVICED 4 WHEEL BRAKE JOB.
22. CONTINUED/COMPLETED 4 WHEEL BRAKE JOB.
23. SERVICED AIR BRAKE DRYER.
24. CHECK HARD START/ NO START- REMOVED AIR CLEANR ASSEMBLY AIR TUBES BREATHER TUBE HARNESS.
25. CHECK HARD START CONT REMOVED VALVE COVER- RAN ENGINE- HIGH PRESSURE PUMP INOP- REMOVED TURBO HOSE FUEL LINES.
26. CHECK HARD START CONT REMOVED FUEL SUPPLY LINES AND FILTER ASSEMBLY ENG HARNESS AND PUMP ASSEMBLY.
27. CHECK HARD START CONT REPLACED HIGH PRESS, OIL PUMP REPLACED FUEL LINE

065624AD-IP DRIER	1
1501450007750USE 0775145	3
1812348C1FUEL LINE SLEEVE INT	4
1842626C951842626C96 OIL RAIL MANIFOLD SEALS	1
1847727C1BELT	1
1873906C1SEAL FUEL FILTER HSG	1
1875784C921875784C93 ICP SENSOR	1
1878042C91FUEL FILTER 2008 HORTON	1
1882259C931882259C94 HIGH PRESSURE OIL PUMP	1
1893940C911893940C93 OIL LINE HIGH PRESS PUMP	1
2284075MOTOR BLW PRO AIR MEDTEC/HORTON	1
2505695C1BRK PEDAL PAD	1
2506656C124316 WIX CAB A/C FILTER	1
3533425C3FUEL LINE FITTING INT.	1
3591094C1FUEL FITTING	1
3611894C9103-0805 A/C COMPRESSOR 4347	1
3622764C32606229C92 THERMISTER	1
3670134C1ACCUMULATOR ASSY INT.	1
3757REAR DRUMS 3757X 3647X	2
5774457744XD OIL FILTER	1
78R539018-2699 A/C FILTER	1
8201L17-3428 ESTER OIL E7	1
91-22WIPER BLADE	2
B-1104 CLAMP	2
K022105PURGE VALVE AD-IP-IS	1
K060705BELT HORTON	1
KSMA2124703QFRONTBRAKE KIT RUMPER AND 4DR RE:	2
VML/T1808D2503221C1 FILTER POWER STEERING	1
XK4034707QPMHD SHOE KIT 3/8 BEAM	2



10/17/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10182237

**INTERNATIONAL 4400 ADVANCED LIFE SUPPORT**

GROMMETS.

28. CHECK HARD START CONT INSTALLED BRKTS-  
FUEL LINES FILTER ASSEMBLY.

29. REPAIR COOLANT CROSS OVER PIPE- REMOED  
HOSE CLAMPS AND REINSTALLED PIPE SEURED  
PIPE TO MOUNT BRKT CHECK OK.

30. CHECK HARD START CONT REMOVED INJ  
HARNES AND VALVE COVER GASKET HIGH  
PRESS OIL RAIL- R&R SEALS- INSTALLED RAIL  
HARNES VALVE COVER AND TUBE, AND ALL  
OTHER PARTS- STARTED AND RAN.

31. REPLACE CONDENSER- START CONDENSER  
REPLACEMENT.

**Workorder: V66190**

In Date: 05/02/2014

Meter Reading: 85,264.00

Close Date: 05/07/2014

**Problem?**

pat a/c inop

**Task performed:**

REPLACE PAT A/C COMPRESSOR AND DRYER  
LEAK AT FITTING RECRIPPED HOSE STILL LEAKED.

**Parts**

**Quantity**

071601A07-0602A DRIER A/C 7118

1

559103-6537 MANIFOLD COMP 5779

1

577903-3673 COMP USE 5591 MANIFOLD

1

**Workorder: V66254**

In Date: 05/05/2014

Meter Reading: 85,264.00

Close Date: 05/07/2014

**Problem?**

repair a/c line

**Task performed:**

REPLACE PAT A/C HIGH SIDE LINE AND FITTING-  
REPLACED A/C COMPRESSOR THE DAY BEFORE  
AND FOUND THE LEAK ON HIGH SIDE HOSE.

**Parts**

**Quantity**

08-3001Q8 SPLICE

1

08-6932QAC FITTING

1

09-1017Q8 CRIMP GRAY HOSE

5

**Workorder: V67112**

In Date: 06/10/2014

Meter Reading: 88,572.00

Close Date: 06/17/2014

**Problem?**

A/c inop

**Task performed:**

A/C INOP LOW REFRIGERANT. NEED TO BRING TO  
SHOP TO LOCATE LEAK IS WORKING NOW.

**Parts**

**Quantity**

NO PARTS USED





10/17/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10182237

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

### Workorder: V66593

In Date: 05/19/2014

Meter Reading:

Close Date: 06/23/2014

#### Problem?

Blows HOT AIR in the front compartment. Problem with the AC.

#### Task performed:

repaired a/c blower motor.

#### Parts

NO PARTS USED

#### Quantity

### Workorder: V67535

In Date: 06/28/2014

Meter Reading: 90,073.00

Close Date: 07/01/2014

#### Problem?

Patient a/c inop

#### Task performed:

FOUND NO ALARM GOIMF OFF, FOUND ABS LIGHT ON.

#### Parts

NO PARTS USED

#### Quantity

### Workorder: V67612

In Date: 07/01/2014

Meter Reading: 90,073.00

Close Date: 07/01/2014

#### Problem?

Cab a/c inop

#### Task performed:

REPLACED A/C COMPRESSOR, DRYER AND EXPANSION VALVE. VACUUMED SYSTEM AND RECHARGED.

#### Parts

3611894C9103-0805 A/C COMPRESSOR 4347

3660853C22512331C1 EXP VALVE NAV

3670134C1ACCUMULATOR ASSY INT.

#### Quantity

1

1

1

### Workorder: V66981

In Date: 06/04/2014

Meter Reading:

Close Date: 07/09/2014

#### Problem?

LED light on the back driver side not working

#### Task performed:

ck, truck found all lights working .

#### Parts

NO PARTS USED

#### Quantity



10/17/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10182237

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

### Workorder: V67321

In Date: 06/18/2014

Meter Reading:

Close Date: 07/09/2014

#### Problem?

passanger side scene light is broken.

#### Task performed:

found no lights broken on box.

#### Parts

60R00FRR600 SERIES RED LED W/O FLANGE

#### Quantity

2

### Workorder: V68497

In Date: 08/07/2014

Meter Reading:

Close Date: 08/13/2014

#### Problem?

Vehicle needs rear tires. Wear bars visible on right side, soon to be visible on left side.

#### Task performed:

#### Parts

NO PARTS USED

#### Quantity

Vendor? BOULEVARD TIRE CENTE

### Workorder: V68235

In Date: 07/28/2014

Meter Reading: 92,291.00

Close Date: 08/29/2014

#### Problem?

Back driver side scene light not working E46

#### Task performed:

Repaired rear spot light that was out and tested.

#### Parts

NO PARTS USED

#### Quantity

### Workorder: V68711

In Date: 08/15/2014

Meter Reading: 93,885.00

Close Date: 08/29/2014

#### Problem?

steering wheel not aligned with wheels r46

#### Task performed:

1. Road tested truck. Found no problem with steering wheel.

2. o2 leak repaired leak at fitting at bottle

3.Repaired rear door latch that was hard to open.

#### Parts

NO PARTS USED

#### Quantity



10/17/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10182237

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

### Workorder: V69064

In Date: 08/29/2014

Meter Reading:

Close Date: 09/05/2014

#### Problem?

A/C stoped working in the front cab. R46

#### Task performed:

#### Parts

#### Quantity

trace out a/c found bad fuse on blower motor rewired and repaired.

NO PARTS USED

rear cab a/c inop found bad connection.

### Workorder: V68989

In Date: 08/27/2014

Meter Reading: 94,994.00

Close Date: 09/09/2014

#### Problem?

Oil is over full range.

#### Task performed:

#### Parts

#### Quantity

OCS changed oil

NO PARTS USED

### Workorder: V69997

In Date: 10/08/2014

Meter Reading: 97,921.00

Close Date: 10/08/2014

#### Problem?

cab a/c inop, R-46

#### Task performed:

#### Parts

#### Quantity

1. hook up laptop found code for thermostiter, evecaute and replce both thermostiters, recharge system, ok

3622764C32606229C92 THERMISTER

1

### Workorder: V69258

In Date: 09/09/2014

Meter Reading: 95,549.00

Close Date: 10/14/2014

#### Problem?

map light broken

#### Task performed:

#### Parts

#### Quantity

1. A/C inoperable. Installed high pressure switch.

3546241C1SWITCH A/C PRESSURE INT.

1

2. Installed new map light.

LF18TS-LEDMAP LIGHT LED 18 IN

1

QL97SFCAAAMBER QUAD LIGHT

1



10/17/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10182237

**INTERNATIONAL 4400 ADVANCED LIFE SUPPORT**

### Workorder: V69352

In Date: 09/13/2014

Meter Reading: 95,814.00

Close Date: 10/14/2014

#### Problem?

Driver side rear flasher light and ground lights. R46

#### Task performed:

Repair broken wires on light and tested.

#### Parts

NO PARTS USED

#### Quantity

### Workorder: V68843

In Date: 08/21/2014

Meter Reading: 94,994.00

Close Date: 10/15/2014

#### Problem?

B inspection R46 by OCS

#### Task performed:

B inspection  
oil and filter change

#### Parts

1878042C91FUEL FILTER 2008 HORTON

2506656C124316 WIX CAB A/C FILTER

5774457744XD OIL FILTER

#### Quantity

1

1

1

Vendor? OCS

### Workorder: V69797

In Date: 09/30/2014

Meter Reading: 97,301.00

Close Date: 10/29/2014

#### Problem?

Unkown problem with R46. While parked in the bay a loud bursting type sound was heard in the bay. Something had burst on R46, poss. the air brakes line.

#### Task performed:

1. Found 110 A/C was not working due to blown line.  
2. Repaired air leak at air bag fitting.

#### Parts

NO PARTS USED

#### Quantity



10/17/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10182237

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

**Workorder: V70727**

In Date: 11/05/2014

Meter Reading:

Close Date: 11/05/2014

**Problem?**

front air is blowing warm R-46

**Task performed:**

check cab a/c, found compressor not coming on, evacuate system, had correct amount of freon, vac. and recharge system, hook up laptop no codes, found outer thermister out of range reading 0 and inner reading 79, 2 new thermisters were installed on oct. 8, 2014, evacuate and replace both thermisters again, recharge and a/c clutch now comes on

Parts

Quantity

3622764C32606229C92 THERMISTER

1

**Workorder: V70151**

In Date: 10/09/2014

Meter Reading: 98,474.00

Close Date: 11/06/2014

**Problem?**

R46 front tires

**Task performed:**

r46 front tires

Parts

Quantity

NO PARTS USED

Vendor? BOULEVARD TIRE CENTE

**Workorder: V70541**

In Date: 10/29/2014

Meter Reading: 99,792.00

Close Date: 11/10/2014

**Problem?**

The AC in the cab is not working. The AC was fixed a few weeks ago. But broke again. R46 station 46.

**Task performed:**

1. Diagnose cab A/C. Disassemble cab auxiliary A/C unit. Replace missing hardware. Replace filter. Test for 12V. None. Found breaker tripped. No new breaker. Switched with another. R & R dash A/C filter. Road test vehicle.

Parts

Quantity

2506656C124316 WIX CAB A/C FILTER

1

78R539018-2699 A/C FILTER

1



10/17/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10182237

**INTERNATIONAL 4400 ADVANCED LIFE SUPPORT**

### Workorder: V70649

In Date: 11/02/2014

Meter Reading:

Close Date: 11/18/2014

#### Problem?

check air suspension for leak(s) and/or sticky pressure relief valve(s). Suspension losing air pressure. R46

#### Task performed:

Checked for air leaks and found none at this time

#### Parts

NO PARTS USED

#### Quantity

### Workorder: V71056

In Date: 11/19/2014

Meter Reading:

Close Date: 11/26/2014

#### Problem?

R46 oil is too high which is affecting performance

#### Task performed:

1. found oil level 2" above normal, drain and refill oil to correct amount, replace oil filter, road test, runs rough, hook up laptop found active code for #5 injector, have crew swap into spare

2. remove air cleaner and hoses, cables, etc., remove valve cover, oil rail manifold and injectors, found # 1 injector hold down clamp bolt stripped, had to drill and use easy out to remove hold down clamp bolt, replace oil rail manifold seals, replace ICP sensor, replace all injectors, and # 1 injector hold down clamp, reinstall all equipment, start engine and clear code for #5 injector, road test, recheck for codes, ok runs good

#### Parts

15-40B15W40 MOTOR OIL NON SYN

1841843C94HOLD DOWN INJECTOR

1842626C951842626C96 OIL RAIL MANIFOLD SEALS

1875784C921875784C93 ICP SENSOR

5010561R925010561R93 INJECTOR

5774457744XD OIL FILTER

#### Quantity

30

1

1

1

6

2

### Workorder: V71333

In Date: 12/02/2014

Meter Reading: 101,975.00

Close Date: 12/02/2014

#### Problem?

Air leak

#### Task performed:

Check for air leak-found needs rear air bags R/R bags ,adjust suspension, and test for leaks and operation-it's good.

#### Parts

GY1R11216AIR BAGS

#### Quantity

2



10/17/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10182237

**INTERNATIONAL 4400 ADVANCED LIFE SUPPORT**

**Workorder: V71361**

In Date: 12/03/2014

Meter Reading:

Close Date: 12/18/2014

**Problem?**

rESCUE WAS IN SHOP YESTERDAY FOR DUMP BUT IT IS STILL AN ISSUE

**Task performed:**

Repaired on WO# 71369

Parts

Quantity

2505183C91LEVELING VALVE

2

**Workorder: V71366**

In Date: 12/03/2014

Meter Reading:

Close Date: 12/18/2014

**Problem?**

Scene lights on the back of R46 is loose. Missing two screws out 4.

**Task performed:**

Rear light bar scene light L/side missing scews-rear back up light inop-install (4) screws and secure. Remove blown bulb and install new bulb

Parts

Quantity

NO PARTS USED

**Workorder: V71807**

In Date: 12/22/2014

Meter Reading: 102,795.00

Close Date: 12/29/2014

**Problem?**

rear a/c inop

**Task performed:**

Traced out problem found bad connections on condensor fans

Parts

Quantity

NO PARTS USED

**Workorder: V70971**

In Date: 11/17/2014

Meter Reading: 104,137.20

Close Date: 01/06/2015

**Problem?**

lens on rear light below r 46 sign on passenger side is loose. Screws missing

**Task performed:**

Repaired on WO#71366

Parts

Quantity

NO PARTS USED



10/17/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10182237

**INTERNATIONAL 4400 ADVANCED LIFE SUPPORT**

**Workorder: V71034**

In Date: 11/18/2014

Meter Reading:

Close Date: 01/06/2015

**Problem?**

The AC on the Rescue 46,pPatient compa/ area is producing condensation. Making the floor wet causing medical equipment damage

**Task performed:**

Parts

Quantity

Repaired on WO# 71366

NO PARTS USED

**Workorder: V71256**

In Date: 11/29/2014

Meter Reading:

Close Date: 01/06/2015

**Problem?**

Rear emergency light lense is missing screws and is falling off.

**Task performed:**

Parts

Quantity

REPAIRED ON W/O #71366

H4651CVH4651CVC1 HEAD LAMP HIGH BEAM CRYSTAL \

1

H4656CVH4656CVC1 LOW BEAM CRYSTAL VISION

3

**Workorder: V71284**

In Date: 11/30/2014

Meter Reading:

Close Date: 01/06/2015

**Problem?**

The Rescue truck Air Dump System is loosing air when the truck is turn off.

**Task performed:**

Parts

Quantity

Repaired on wo#71369

NO PARTS USED





10/17/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10182237

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

**Workorder: V71369**

In Date: 12/03/2014

Meter Reading: 102,381.00

Close Date: 01/20/2015

**Problem?**

C inspection R46

**Task performed:**

- "C" inspection
- 110 AC inop-diagnose fault found hi pressure line blown off-remove for new line-install new line-vaccum system fans high reassistance. Remove, install new fans and remove dryer accumulator-parts on order.
- Cross bens chassie support bolts loose-check and retorque bolts.
- Air leak-found cab leveling valve and patient box leveling valve leaking. Remove valves, install new valves and air line fittings adjust valve and secure.
- Remove 110 AC compressor and accumulator-install new compressor, rewire,install new accumulator, vacuum unit charge unit and operate.
- QA inspection
- Coolant leak-found lower radiator hoseclamp loose-secure. Fill coolant to proper level-pressure test-no leak at this time.
- L-2 compartent tool holders, SCBA bracket and door panel loose, worn to damage-secure, drill and tap and install components.
- Stair chair comp door rain guard damage-straighten out guard, sand/grind sharp edges.
- Windshield wiperblades, bug solvent/fluid-remove install new wiper blade, add solvent and water to resevo
- Outside 110v plug wired polarity reverse-remove plug and rewire to proper polarity and test.
- UV bulb blown-remove and install new UV bulb
- Window L/R side mirror bracket broken-remove window bracket and install new replacment support.
- Front shocks leaking-remove and install new shock absorbe

**Parts**

**Quantity**

1878042C91FUEL FILTER 2008 HORTON	1
23-5094DANHARD ACCUMULATOR	1
2506656C124316 WIX CAB A/C FILTER	1
2507385C1CAB AIR LEVEL VALVE INT	1
2509068C91MIRROR MOUNT UPPER	1
2509070C91MIRROR BRACKET UPPER R/H	1
3578105C2FRONT SHOCKS	2
489537HOSE & FITTINGS	1
50-215050-2105 DANHARD COMPRESSOR	1
50-2204FAN KIT DANHARD CONDENSER	1
5774457744XD OIL FILTER	1
91-22WIPER BLADE	2
FREIGHTSHIPPING CHARGES	1
FRT V27624FREIGHT CHARGE	1
GPX13ULTRA VIOLET LIGHT SHORT	1

**Workorder: V72120**

In Date: 01/08/2015

Meter Reading:

Close Date: 01/28/2015

**Problem?**

AC condinsation leaking into treament area wetting equipment.

**Task performed:**

Unclogged drain and cleaned condensor.

**Parts**

**Quantity**

NO PARTS USED



10/17/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10182237

**INTERNATIONAL 4400 ADVANCED LIFE SUPPORT**

**Workorder: V72142**

In Date: 01/09/2015

Meter Reading:

Close Date: 01/28/2015

**Problem?**

Noise coming from underneath Patient compartment while driving

**Task performed:**

Parts

Quantity

1. Road tested truck and did not find or heard any noise.

NO PARTS USED

**Workorder: V72207**

In Date: 01/11/2015

Meter Reading:

Close Date: 02/09/2015

**Problem?**

Rear driver side scene light is 10-7.

**Task performed:**

Parts

Quantity

Repaired bad connection on light and tested.

NO PARTS USED

**Workorder: V73786**

In Date: 03/10/2015

Meter Reading:

109,933.00

Close Date: 03/10/2015

**Problem?**

replace rear tires

**Task performed:**

Parts

Quantity

replace rear tires

NO PARTS USED

Vendor? ELPEX



10/17/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10182237

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

**Workorder: V73385**

In Date: 02/24/2015

Meter Reading:

Close Date: 03/30/2015

**Problem?**

Officer window will not roll down. AC in the crew cab does not work.

**Task performed:**

1. Trouble shoot EGR leak, check to see if leaking internally confirm leak, check trouble codes, pressure check, system coolant for leaks ect. Also W/pump leaking.
2. EGR cooler.
3. Water pump R&R.
4. A/C compressor pump down and check for leak and charger system.
5. Repair window.
6. Kit HVAC thermister.
7. IGN swithc.
8. Coolant tank sensor, check and replace bad.
9. Q/A unit and verified unit due for B- inspection.

**Parts**

**Quantity**

1842665C93WATER PUMP DT570	1
1878918C2EGR VALVE	1
2587324C1LEVEL SENSOR	1
3545580C1IGN SWITCH	1
3611894C9103-0805 A/C COMPRESSOR 4347	1
3622764C32606229C92 THERMISTER	1
4307362R91KIT EGR COOLER COLD SIDE OLD 1876262C	1
7090595C91COOLER EGR KIT 330MM EXH SIDE OLD 1876	1

**Workorder: V73593**

In Date: 03/03/2015

Meter Reading: 109,201.00

Close Date: 04/29/2015

**Problem?**

B inspection R46

**Task performed:**

1. Start "B" Service
2. Check out oil leak, clean and check, found oil pressure sw, leaking, replace with new.
3. Check out lights on back of truck, scene light out, check, power ground connection found light out, replace
4. Clean and check all ground lgiths, repaired wires to light on right side step, door open light on.
5. Check lights on left side out, found wires to lights broken, repair wires, clean lights, retest ok.
6. Remove all tires on rear, remove brake drum and shoes. Replace all brakes on rear and spring and drum complete. Also needs all tires on rear, found nails in two tires.
7. Switch out truck with driver only.

**Parts**

**Quantity**

1839415C91OIL PRESSURE SENSOR	1
1878042C91FUEL FILTER 2008 HORTON	1
2506656C124316 WIX CAB A/C FILTER	1
3757REAR DRUMS 3757X 3647X	4
5774457744XD OIL FILTER	1
H35SN12BULB	1
XK4034707QPMHD SHOE KIT 3/8 BEAM	2



10/17/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10182237

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

## Workorder: V73743

In Date: 03/08/2015

Meter Reading:

Close Date: 04/30/2015

### Problem?

back up Camera will not stay on R46

### Task performed:

Parts

Quantity

1. Repaired bad connection on back of display.

NO PARTS USED

## Workorder: V73764

In Date: 03/09/2015

Meter Reading:

Close Date: 04/30/2015

### Problem?

Driver side Head light out. No replacement bulbs available at station. R46

### Task performed:

Parts

Quantity

1. Replaced headlight.

9007H9007 BULB ASSY

2

## Workorder: V73889

In Date: 03/16/2015

Meter Reading:

Close Date: 04/30/2015

### Problem?

MDC on R46 broke from bracket, needs to be reinstalled with new hardware.

### Task performed:

Parts

Quantity

1. Unit sent to shop.

NO PARTS USED

## Workorder: V73386

In Date: 02/24/2015

Meter Reading:

Close Date: 06/30/2015

### Problem?

Every time the truck is shut down or started, the modem reboots. This is creating a with the trptix and the MDC's connection. The triptix is not able to charge in the front cab.

### Task performed:

Parts

Quantity

NO PARTS USED



10/17/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10182237

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

**Workorder: V73112**

In Date: 02/12/2015  
Close Date: 09/08/2015

Meter Reading: 108,157.00

**Problem?**

side door handle broken

**Task performed:**

replace door latch

replace starter rope on saw

Parts

Quantity

10008146HND5948 HANDLE RH HORTON

1

506258102PARTNER STARTER PULLEY

1

**Workorder: V74563**

In Date: 04/10/2015  
Close Date: 09/08/2015

Meter Reading:

**Problem?**

Front ac blows warm. It works for 10 minutes then blow warn. Shut truck on and off repeat. Front cigarette lighter outlet does not work. Plug in tablet it appears to be charging , it does not.

**Task performed:**

Parts

Quantity

NO PARTS USED



# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

Asset: (10182237) 2010 - HORTON 4400 Advanced Life Support Vehicle

10182237

**CSHOP-2015-1136**

Comments: **R46 C INSPECTION**

Date Opened 6-11-2015

Date Finished

6-19-2015

Meter 1 Reading:

118,305

**TASKS PERFORMED**

**Q PARTS**

PM SERVICE C RESCUE

1	FILTER; 24316 WIX CAB A/C FILTER
1	FILTER; 57744XD OIL FILTER
1	FILTER; FUEL FILTER 2008 HORTON

**CSHOP-2015-1137**

Comments: **R46 REPAIRS FROM INSPECTION**

Date Opened 6-11-2015

Date Finished

6-25-2015

Meter 1 Reading:

118,305

**TASKS PERFORMED**

**Q PARTS**

WASHER RESERVOIR

WIPER BLADES

COOLING SYSTEM

TURN SIGNAL LIGHTS

HEADLIGHTS HIGH BEAM

TRANSMISSION

SUSPENSION

CROSS MEMBER

AIR SYSTEM

WINDOW REGULATOR

FAULT CODE

STROBE LIGHTS

DOOR

CAB VENT

DOOR PANEL

UPHOLSTERY

CAB-INTERIOR ACCESSORIES

HEATING AND VENTILATION

A/C FILTER SCREENS

AIR CONDITIONING

1	WASHER; WASHER PUMP W/GROMMET
2	WIPER; WIPER BLADE
1	BULB; INTERIOR DOME BULB
2	SPRING; SPRING WASHER HEADLITE
2	BULB; H9007 BULB ASSY
2	LIGHT; LOCK RING HEADLITE
30	MOTOR; 15W40 MOTOR OIL NON SYN
2	BRAKE; GY1R11216 AIR BAG INT.
1	LAMP; LAMP MARKER INT. DOOR PANEL
1	ASSEMBLY; BEAM ASSY DOOR LEFT REAR
2	LIGHT; AMBER QUAD LIGHT
1	LAMP; LED TURN SIGNAL LAMP
2	SLIDE; 12 IN PAIR DRAWER SLIDES
1	LIGHT; ULTRA VIOLET LIGHT SHORT
1	NONSTOCK; A/C VENT
1	COMPRESSOR; 03-0805 A/C COMPRESSOR
2	FILTER; PANEL FILTER
1	FILTER; 18-2699 A/C FILTER

**CSHOP-2015-1637**

Comments: **LFT FRONT STROBE OUT R46**

Date Opened 7-8-2015

Date Finished

7-9-2015

Meter 1 Reading:

118,350

**TASKS PERFORMED**

**NO PARTS USED**

TRAVEL TO BE CHARGED TO WORK ORDER  
LIGHTING SYSTEM

**Asset Work Order History 10182237**

**CSHOP-2015-1899**

Comments: **RIGHT HI BEAM INOP R46 POWER DOOR LOCKS ONLY OPEN WITH KEY CAB DOORS**  
Date Opened 7-22-2015 Date Finished 8-14-2015 Meter 1 Reading: 118,350

**TASKS PERFORMED**

**Q PARTS**

TRAVEL TO BE CHARGED TO WORK ORDER  
HEADLIGHTS HIGH BEAM  
DOOR LOCKS

1 LIGHT; HEADLIGHT CUP  
1 SPRING; SPRING WASHER HEADLITE  
1 SWITCH; T/S SIGNAL SWITCH 3587009C92  
1 BULB; H9007 BULB ASSY  
1 MODULE; OUTPUT MODULE HORTON  
1 LIGHT; LOCK RING HEADLITE

**CSHOP-2015-2507**

Comments: **R46 PAT A/C RRO TIRE EXCESSIVE WEAR**  
Date Opened 8-24-2015 Date Finished 9-2-2015 Meter 1 Reading: 118,350

**TASKS PERFORMED**

**NO PARTS USED**

FRONT TIRES  
AIR CONDITIONING

**VENDOR?** EARL COLVARD BOULEVARD TIRE

**CSHOP-2015-2652**

Comments: **R46 NO START**  
Date Opened 9-1-2015 Date Finished 9-4-2015 Meter 1 Reading: 124,907

**TASKS PERFORMED**

**Q PARTS**

BATTERY

3 BATTERY; BATTERY 950CCA HP-31D  
3 BATTERY; BATTERY EPA TAX \$1.50 PER BATTERY

**CSHOP-2015-2801**

Comments: **R46 OIL OVER FULL**  
Date Opened 9-9-2015 Date Finished 9-10-2015 Meter 1 Reading: 125,699

**TASKS PERFORMED**

**Q PARTS**

EXHAUST SYSTEM  
OIL  
DOOR LOCKS ELECTRIC

1 GASKET; DPF GASKET  
1 GASKET; DPF GASKET  
1 EXHAUST; CLEANED UNIT  
1 FILTER; 57744XD OIL FILTER  
30 MOTOR; 15W40 MOTOR OIL NON SYN

**CSHOP-2015-297**

Comments: **R46 PAT COMP A/C NOT WORKING**  
Date Opened 4-27-2015 Date Finished 5-1-2015 Meter 1 Reading: 112,760

**TASKS PERFORMED**

**NO PARTS USED**

TRAVEL TO BE CHARGED TO WORK ORDER  
AIR CONDITIONING

**Asset Work Order History 10182237**

**CSHOP-2015-3028**

Comments: **PT COMPARTMENT AC NOT WORKING. BRINGING UP TRUCK TO SHOP THIS MORNING PER CONVERSATION WITH THE SHOP.R46**

Date Opened 9-22-2015 Date Finished 9-22-2015 Meter 1 Reading: 126,807

**TASKS PERFORMED**

**Q PARTS**

FILTER	1	FILTER; FUEL FILTER 2008 HORTON
AIR CONDITIONING	1	NEWPART; HOSE & FITTINGS
	1	DRYER; 07-0602A DRIER A/C 7118
	1	CAP; 9C3Z8101B RADIATOR CAP 10238 STANT
	1	MANIFOLD; 03-3673 COMP USE 5591 MANIFOLD

**CSHOP-2015-3145**

Comments: **R46 CAB A/C INOP AND 12 V CHARGER INOP**

Date Opened 9-29-2015 Date Finished 10-14-2015 Meter 1 Reading: 128,777

**TASKS PERFORMED**

**NO PARTS USED**

AIR CONDITIONING

**Service Requests:**

09/29/2015 A/C / 19: LOOSE / REPAIR  
A/C IN CAB DOES NOT WORK. FUSE FOR 12V CHARGER IN CAB DOES NOT WORK

**CSHOP-2015-3451**

Comments: **R46**

Date Opened 10-15-2015 Date Finished 11-10-2015 Meter 1 Reading: 131,323

**TASKS PERFORMED**

**NO PARTS USED**

TRAVEL TO BE CHARGED TO WORK ORDER  
OIL  
ENGINE AND ACCESSORIES  
LIGHTING SYSTEM  
SAFTEY-EMERGENCY EQUIPMENT

**Service Requests:**

10/15/2015 LIGHTS / 19: LOOSE / REPAIR  
THE PASSENGER SIDE HIGH BEAM IS NOT WORKING WHILE EMERGENCY LIGHTS ARE ACTIVATED OR WHEN IN USE AT NIGHT.

10/23/2015 SERVICE REQUEST / 19: LOOSE / REPAIR  
THE FRONT CHARGER ON RESCUE 46 IS NOT WORKING.

11/02/2015 OIL / 17: INSUFFICIENT LUBRICANT / REPAIR  
OIL LEVEL IS HIGH IN ACCORDANCE TO DIP STICK READING



**Asset Work Order History 10182237**

**CSHOP-2015-396**

Comments: **R-46 AIR CONDITIONING NOT WORKING**

Date Opened 5-1-2015 Date Finished 5-8-2015 Meter 1 Reading: 112,760

**TASKS PERFORMED**

**Q PARTS**

DIAGNOSE ELECTRICAL  
AIR CONDITIONING

1 ACTUATOR; 2611234C1 VENT ACTUATOR  
1 INTERNATIONAL; 2606229C92 THERMISTER

**CSHOP-2015-4022**

Comments: **R46 RRO TIRE FLAT**

Date Opened 11-17-2015 Date Finished 11-17-2015 Meter 1 Reading: 132,210

**TASKS PERFORMED**

**NO PARTS USED**

FRONT TIRES

**VENDOR?** EARL COLVARD BOULEVARD TIRE

**CSHOP-2015-4656**

Comments: **R46**

Date Opened 12-28-2015 Date Finished 12-31-2015 Meter 1 Reading: 136,417

**TASKS PERFORMED**

**NO PARTS USED**

TRAVEL TO BE CHARGED TO WORK ORDER  
TIRE  
REAR TIRES

**Service Requests:**

12/26/2015 TIRES / 44: WORN / EXCHANGE - NEW  
DRIVER OUTSIDE REAR TIRE IS BALD AND SLIPPERY ON THE ROAD. TIRE MAKE GOODYEAR G661HSA 255/70R22.5

**CSHOP-2015-4728**

Comments: **R46 BROKE DOWN REPAIRED ON ANOTHER TICKET**

Date Opened 12-31-2015 Date Finished 1-15-2016 Meter 1 Reading: 137,918

**TASKS PERFORMED**

**Q PARTS**

AIR SYSTEM

1 GOVERNOR; GOVERNOR D-2

**CSHOP-2015-835**

Comments: **R46 STRETCHER HOOK NOT SECURE**

Date Opened 5-27-2015 Date Finished 5-28-2015 Meter 1 Reading: 112,760

CLEAN, LUBE AND ADJ.LOCK LINKAGE,LATCH ASSY, AND STRIKER ON

**TASKS PERFORMED**

**Q PARTS**

OIL  
VALVE STEM  
SAFTEY-EMERGENCY EQUIPMENT  
DOOR

1 SWITCH; SWITCH COMPARTMENT DOORS

**Asset Work Order History 10182237**

**CSHOP-2016-103**

Comments: **R46 BREAKDOWN ON LANTANA EAST OF TURNPIKE**

Date Opened 1-8-2016 Date Finished 1-15-2016 Meter 1 Reading: 137,918

**TASKS PERFORMED**

**Q PARTS**

TRAVEL TO BE CHARGED TO WORK ORDER  
COOLING SYSTEM  
DOOR

6 FLUID; 50-50 EXTENDED LIFE COOLANT GAL

**Service Requests:**

01/07/2016 DOOR / 19: LOOSE / REPAIR  
DRIVERS SIDE SECOND DOOR WILL NOT OPEN FROM INTERIOR OR EXTERIOR.

**CSHOP-2016-1032**

Comments: **OVERHEATING R46**

Date Opened 3-3-2016 Date Finished 3-10-2016 Meter 1 Reading: 142,851

**TASKS PERFORMED**

**Q PARTS**

COOLING SYSTEM

-1 BELT; BELT  
1 BELT; BELT  
1 THERMOSTAT; 1842130C3 THERMOSTAT DT466  
-1 NEWPART; FAN CLUTCH  
1 NEWPART; FAN CLUTCH

**Service Requests:**

03/03/2016 SERVICE REQUEST / 12: BROKEN / EXCHANGE - NEW  
TEMP WARNING LIGHT

03/03/2016 SERVICE REQUEST / 12: BROKEN / EXCHANGE - NEW  
EXTENSION CORD RESCUE 46. CHARGER

**CSHOP-2016-1250**

Date Opened 3-16-2016 Date Finished 3-20-2016 Meter 1 Reading: 143,839

**TASKS PERFORMED**

**NO PARTS USED**

ELECTRICAL

1 SWITCH; SWITCH BATTERY MASTER 300A  
-1 SWITCH; SWITCH BATTERY MASTER 300A

**CSHOP-2016-1460**

Date Opened 3-28-2016 Date Finished 4-13-2016 Meter 1 Reading: 146,239

**TASKS PERFORMED**

**Q PARTS**

BODY EXTERIOR

3 INSERT; LARGE PLACARD INSERT CARD  
2 INSERT; FRONT AND BACK INSERT CARD

**Service Requests:**

03/27/2016 BODY / 19: LOOSE / REPAIR  
SCRATCH IN PAINT ON OUTSIDE OFFICER SIDE TOP REAR OF TRUCK, FOUND DURING TRUCK CHECKOUT.

**Asset Work Order History 10182237**

**CSHOP-2016-1581**

Date Opened 4-4-2016 Date Finished 4-8-2016 Meter 1 Reading: 145,707

**TASKS PERFORMED**

**NO PARTS USED**

TRAVEL TO BE CHARGED TO WORK ORDER  
TIRES & WHEELS

**Service Requests:**

04/03/2016 STEERING / 19: LOOSE / A  
FRONT LEFT AND RIGHT TIRES SHOWING SIGNS OF WEAR AND TEAR ON THE OUTSIDE OF TIRES.

**CSHOP-2016-1887**

Comments: **R46**

Date Opened 4-21-2016 Date Finished 4-27-2016 Meter 1 Reading: 147,617

**TASKS PERFORMED**

**Q PARTS**

TRAVEL TO BE CHARGED TO WORK ORDER  
AIR SYSTEM

1 REGULATOR; 1462369 O2 REGULATOR

**Service Requests:**

04/21/2016 SERVICE REQUEST / 18: LEAKING / X  
RESCUE 46 IS HAVING A PROBLEM WITH THE MAIN O2 REGULATOR LEAKING. IT IS A FAST LEAK. WE NEED A REPLACEMENT ASAP.

**CSHOP-2016-2075**

Comments: **ON-CALL R46 OVERHEATING**

Date Opened 5-2-2016 Date Finished 5-2-2016 Meter 1 Reading: 147,801

**TASKS PERFORMED**

**NO PARTS USED**

COOLING SYSTEM

**CSHOP-2016-2129**

Comments: **R46**

Date Opened 5-3-2016 Date Finished 5-6-2016 Meter 1 Reading: 147,801

**TASKS PERFORMED**

**Q PARTS**

PM SERVICE C RESCUE

1 FILTER; 24316 WIX CAB A/C FILTER  
1 FILTER; 57744XD OIL FILTER  
1 FILTER; FUEL FILTER 2008 HORTON  
30 MOTOR; 15W40 MOTOR OIL NON SYN  
1 FILTER; AIR FILTER

**Asset Work Order History 10182237**

**CSHOP-2016-2133**

Comments: **COOLING SYSTEM LEAK PM FOLLOW UPS**

Date Opened 5-3-2016 Date Finished 5-13-2016 Meter 1 Reading: 147,801

**TASKS PERFORMED**

**Q PARTS**

GROUND LIGHT BODY	4	LIGHT; LED GROUND LITE CLEAR
EQUIPMENT MOUNTING BRACKETS	7	FLUID; COOLANT ANTIFREEZE GAL
DOOR LATCH	1	BULB; BULB
COOLING SYSTEM	1	BULB; H9007 BULB ASSY
PARK-CLEARANCE LIGHTS	2	HOSE; P/S HOSE 3/4
HEADLIGHTS HIGH BEAM	1	GASKET; PS RESV GASKET
LIGHTING SYSTEM	1	FILTER; 2503221C1 FILTER POWER STEERING
TIRES ALL	1	FLUID; P/S FLUID
REAR SPRING	1	NEWPART; SHOCK ABS REAR CAB
RESERVOIR	2	BRAKE; BRAKE DRUM RUMPER FRONT
CAB & BODY MOUNT	2	BRAKE; FRONTBRAKE KIT RUMPER AND 4DR RESCUE
FRONT BRAKE PADS-SHOES	1	DRYER; AD-IP DRIER
AIR DRIER	1	VALVE; PURGE VALVE AD-IP-IS
DOOR WEATHER MOLDING		
DOOR		
INTERIOR TRIM-MOLDINGS-UPHOLS		
SEAT FRONT		

**CSHOP-2016-2326**

Comments: **R46 A/C**

Date Opened 5-16-2016 Date Finished 5-23-2016 Meter 1 Reading: 148,428

**TASKS PERFORMED**

**NO PARTS USED**

TIRE  
A/C COMPRESSOR

**VENDOR?** DAN CALLAGHAN ENTERPRISES

**Service Requests:**

05/16/2016 A/C / 12: BROKEN / INSPECT  
PATIENT COMPARTMENT AC IS COMING OUT HOT

**CSHOP-2016-2345**

Comments: **R46**

Date Opened 5-16-2016 Date Finished 5-26-2016 Meter 1 Reading: 148,809

**TASKS PERFORMED**

**Q PARTS**

ELECTRICAL	1	SWITCH; 19-1045 MASTER SWITCH 175 AMP
------------	---	---------------------------------------

**Service Requests:**

05/14/2016 DOOR / 19: LOOSE / 3  
DOOR LOCKING/UNLOCKING BUTTONS ON DOORS WILL NOT OPERATE THE MECHANISMS THAT LOCK THE DOORS.  
OUTSIDE BLACK BUTTON ON DRIVERS SIDE IS INOPERABLE AS WELL.

05/20/2016 SERVICE REQUEST / 19: LOOSE / Q  
THE BATTERY POWER TO THE RESCUE REMAINS ON REGARDLESS OF THE POSITION OF THE BATTERY SWITCH.

05/20/2016 SERVICE REQUEST / 19: LOOSE / REPAIR  
TRUCK WILL NOT START DUE

**Asset Work Order History 10182237**

**CSHOP-2016-2674**

Date Opened 6-4-2016 Date Finished 6-4-2016 Meter 1 Reading: 149,733

**TASKS PERFORMED**

**NO PARTS USED**

DIAGNOSE ELECTRICAL

**CSHOP-2016-2685**

Date Opened 6-6-2016 Date Finished 6-6-2016 Meter 1 Reading: 149,894

**TASKS PERFORMED**

**NO PARTS USED**

TRAVEL TO BE CHARGED TO WORK ORDER  
COOLING SYSTEM

**CSHOP-2016-2813**

Comments: **R46 ALTERNATOR LOCKED UP, MELTED BELT AND UNIT DRIVEN HOT**

Date Opened 6-13-2016 Date Finished 6-24-2016 Meter 1 Reading: 149,906

**TASKS PERFORMED**

**Q PARTS**

FAN CLUTCH  
EGR COOLER  
OIL  
CHARGING SYSTEM  
AIR CONDITIONING

1 PULLEY; IDLER PULLEY  
1 PULLEY; IDLER PULLEY BOLT  
1 COOLER; COOLER EGR KIT 330MM EXH SIDE OLD 1876261C98  
1 COOLER; KIT EGR COOLER COLD SIDE OLD 1876262C96  
1 VALVE; EGR VALVE  
1 NEWPART; FAN HUB  
1 NEWPART; PULLEY FANHUB  
1 MOUNT; 4949PA/4962 320 AMP UPGRADE SADDLE MOUNT  
1 BELT; BELT  
1 NEWPART; FAN CLUTCH  
-1 NEWPART; FAN CLUTCH  
1 BELT; BELT  
1 HOSE; HOSE A/C COMP-CONDENSOR

**CSHOP-2016-3071**

Date Opened 6-27-2016 Date Finished 7-4-2016 Meter 1 Reading: 150,452

**TASKS PERFORMED**

**NO PARTS USED**

ENGINE AND ACCESSORIES

**Service Requests:**

06/25/2016 ENGINE / 19: LOOSE / R  
THE ENGINE IS MAKING A KNOCKING NOISE AND STARTED TO SMOKE GREY SMOKE AFTER RUNNING FOR A LONG PERIOD OF TIME.

**CSHOP-2016-312**

Date Opened 1-22-2016 Date Finished 1-22-2016 Meter 1 Reading: 138,690

**TASKS PERFORMED**

**NO PARTS USED**

COOLING SYSTEM

**Asset Work Order History 10182237**

**CSHOP-2016-322**

Comments: **ON-CALL R46 USING COOLANT**

Date Opened 1-23-2016 Date Finished 1-29-2016 Meter 1 Reading: 138,940

**TASKS PERFORMED**

**Q PARTS**

COOLING SYSTEM

2 VALVE; 8211237 HEATER VALVE

**Service Requests:**

---

01/23/2016 ENGINE / 19: LOOSE / REPAIR  
POSSIBLE ENGINE COOLANT LEAK. COOLANT TANK WAS FULL THIS MORNING. THIS AFTERNOON A RED LEVEL 4 ENGINE LIGHT CAME ON. ENGINE COOLANT LEVEL WAS CHECKED AND SHOWED HALF FULL. THERE WAS NO COOLANT FOUND ON BAY FLOORS WHILE SITTING IN THE BAY.

---

**CSHOP-2016-3609**

Comments: **R46 PAT A/C INOP**

Date Opened 7-28-2016 Date Finished 7-29-2016 Meter 1 Reading: 152,465

**TASKS PERFORMED**

**NO PARTS USED**

CHARGING SYSTEM  
AIR CONDITIONING

**Service Requests:**

---

07/28/2016 BODY / 17: INSUFFICIENT LUBRICANT / ADJUST  
AUTO EJECTORS DO NOT EJECT SHORELINE FROM THE RESCUE

---

**CSHOP-2016-3632**

Date Opened 7-30-2016 Date Finished 8-2-2016 Meter 1 Reading: 152,837

**TASKS PERFORMED**

**Q PARTS**

AIR CONDITIONING

3 A/C; FREON LB

**Service Requests:**

---

07/29/2016 A/C / 18: LEAKING / W  
THE A/C IS NOT FULLY COOLING THE CAB. AIR IS BLOWING OUT BUT IT IS SEMI COLD.

---

**CSHOP-2016-387**

Comments: **B INSPECTION R46**

Date Opened 1-26-2016 Date Finished 1-27-2016 Meter 1 Reading: 138,940

**TASKS PERFORMED**

**Q PARTS**

PM SERVICE B

1 FILTER; 57744XD OIL FILTER  
1 FILTER; 24316 WIX CAB A/C FILTER  
1 FILTER; FUEL FILTER 2008 HORTON  
30 MOTOR; 15W40 MOTOR OIL NON SYN

---

**Asset Work Order History 10182237**

**CSHOP-2016-3907**

Date Opened 8-9-2016 Date Finished 8-9-2016 Meter 1 Reading: 153,603

**TASKS PERFORMED**

**NO PARTS USED**

TIRE

**VENDOR?** DAN CALLAGHAN ENTERPRISES

**CSHOP-2016-397**

Comments: **R46 REPAIRS FROM PM**

Date Opened 1-26-2016 Date Finished 2-3-2016 Meter 1 Reading: 138,940

**TASKS PERFORMED**

**Q PARTS**

WIPER BLADES	2	WIPER; WIPER BLADE
CATALYTIC CONVERTER	1	PUMP; WATER PUMP DT570
WATER PUMP	30	MOTOR; 15W40 MOTOR OIL NON SYN
SYSTEM TEST	1	VALVE; EGR VALVE
ANTIFREEZE	1	COOLER; KIT EGR COOLER COLD SIDE OLD 1876262C96
DRAIN COCK	1	COOLER; COOLER EGR KIT 330MM EXH SIDE OLD 1876261C98
BY-PASS HOSES	1	COOLER; COOLER EGR KIT 330MM EXH SIDE OLD 1876261C98
EGR COOLER	1	FILTER; 57744XD OIL FILTER
COOLING SYSTEM	30	MOTOR; 15W40 MOTOR OIL NON SYN
OIL	1	NEWPART; MAP LIGHT ASSY
OIL FILTER	1	LIGHT; MAP LIGHT LED 18 IN
DOME LIGHTS	1	LIGHT; DOME LIGHT ASSY
HEADLIGHTS HIGH BEAM	1	COVER; OVAL AUTO EJECT COVER
CONNECTOR	1	FUSE; FUSE 15 AMP NEW #BR315
WIRING	2	STROBE; TURBOTUB STROBE
AUTO-EJECT	4	BRAKE; HD SHOE KIT 3/8 BEAM
DIAGNOSE ELECTRICAL	2	BRAKE; REAR DRUMS 3757X 3647X
REAR BRAKE PADS-SHOES	1	BULB; H9007 BULB ASSY
REAR BRAKE DRUMS	1	INTERNATIONAL; CONTAINER
AIR SYSTEM	1	INTERNATIONAL; CONTAINER
DOOR	3	FILTER; PANEL FILTER
CAB VENT	1	FILTER; 18-2699 A/C FILTER
DOOR HANDLES INSIDE-OUTSIDE	1	LIGHT; LOUVER AC HORTON UV LIGHT
CABIN AIR FILTER		
HEATING AND VENTILATION		

**CSHOP-2016-4299**

Comments: **USE FOR PM FOLLOW UPS ALSO**

Date Opened 9-1-2016 Date Finished 9-2-2016 Meter 1 Reading: 155,698

**TASKS PERFORMED**

**Q PARTS**

WIPER BLADES	2	WIPER; WIPER BLADE
AIR CONDITIONING	1	ASSEMBLY; ACCUMULATOR ASSY INT.
	1	COMPRESSOR; 03-0805 A/C COMPRESSOR
	1	INTERNATIONAL; 2606229C92 THERMISTER

**Service Requests:**

09/01/2016 A/C / 12: BROKEN / REPAIR  
A/C ISSUE THE REAR AC UNIT IN THE CAB OF THE TRUCK TURNS OFF AND ON. THE OIL LEVEL IN THE TRUCK IS READING OVER FULL

**Asset Work Order History 10182237**

**CSHOP-2016-4300**

Comments: **B-INSPECTION WITH OIL CHANGE**

Date Opened 9-1-2016 Date Finished 9-7-2016 Meter 1 Reading: 155,698

**TASKS PERFORMED**

**Q PARTS**

PM SERVICE B

1 FILTER; 57744XD OIL FILTER  
1 FILTER; FUEL FILTER 2008 HORTON  
30 MOTOR; 15W40 MOTOR OIL NON SYN

**CSHOP-2016-4430**

Date Opened 9-12-2016 Date Finished 9-12-2016 Meter 1 Reading: 156,475

**TASKS PERFORMED**

**NO PARTS USED**

LIGHTING SYSTEM

**Service Requests:**

09/11/2016 BODY / 19: LOOSE / REPAIR  
REAR PASSANGER SIDE TURN SIGNAL LIGHT IS LOOSE AND IS MISSING SCREWS, IS BARLEY HANGING ON JUST BY ONE SCREW

**CSHOP-2016-4820**

Comments: **PATIENT A/C INOP**

Date Opened 10-7-2016 Date Finished 10-14-2016 Meter 1 Reading: 159,361

**TASKS PERFORMED**

**Q PARTS**

TIRE  
AIR CONDITIONING

2 VALVE; VALVE CORE  
4 A/C; FREON LB

**VENDOR?** DAN CALLAGHAN ENTERPRISES

**Service Requests:**

10/06/2016 ENGINE / 17: INSUFFICIENT LUBRICANT / INSPECT  
ENGINE OIL LEVEL SI HIGH; THE LEVEL ON THE WORD "RANGE" ON THE DIP STICK IS ON THE LETTER "N".

**CSHOP-2016-5040**

Comments: **R-46 FRONT TIRE NEEDS TO BE CHECKED OUT.**

Date Opened 10-24-2016 Date Finished 10-24-2016 Meter 1 Reading: 160,126

**TASKS PERFORMED**

**NO PARTS USED**

TIRES & WHEELS

**Service Requests:**

10/24/2016 TIRES / 19: LOOSE / REPAIR  
BAD TIRES PASSENGER FRONT TIRE HAS LARGE CUT IN SIDEWALL



**Asset Work Order History 10182237**

**CSHOP-2016-5198**

Comments: **R46**

Date Opened 11-1-2016 Date Finished 11-2-2016 Meter 1 Reading: 160,904

**TASKS PERFORMED**

**Q PARTS**

SAFTEY-EMERGENCY EQUIPMENT

1 SLIDE; 12 IN PAIR DRAWER SLIDES

**Service Requests:**

---

11/01/2016 HAZARD / 18: LEAKING / REPAIR  
HAZARDOUS ISSUE. THE INTERIOR PATIENT COMPARTMENT HAZARDOUS MATERIALS DRAW (WITH NEEDLES AND GARBAGE) IS BROKEN AND COMPLETELY SLIDES OUT; DUMPING OUT CONTENT OF CONTAINERS.

---

**CSHOP-2016-5308**

Date Opened 11-14-2016 Date Finished 11-30-2016 Meter 1 Reading: 163,716

**TASKS PERFORMED**

**NO PARTS USED**

COOLING SYSTEM  
AIR SYSTEM  
AIR CONDITIONING

**Service Requests:**

---

11/12/2016 A/C / 19: LOOSE / REPAIR  
A/C ISSUE - REAR CAB A/C NOT WORKING.

11/22/2016 A/C / 19: LOOSE / REPAIR  
A/C ISSUE CAB A/C DOES NOT WORK

---

**CSHOP-2016-5606**

Date Opened 11-30-2016 Date Finished 12-7-2016 Meter 1 Reading: 164,403

**TASKS PERFORMED**

**Q PARTS**

INSTRUMENTS-GAUGES-WARNING &  
AIR CONDITIONING

1 BLOWER; MOTOR BLOWER REAR CAB UNIT HORTON

**Service Requests:**

---

12/03/2016 A/C / 19: LOOSE / REPAIR  
A/C NOT WORKING.

---

**Asset Work Order History 10182237**

**CSHOP-2016-5810**

Date Opened 12-13-2016 Date Finished 12-29-2016 Meter 1 Reading: 166,344

**TASKS PERFORMED**

**Q PARTS**

TRAVEL TO BE CHARGED TO WORK ORDER	1	THERMOSTAT; 1842130C3 THERMOSTAT DT466
COOLING SYSTEM	1	CLAMP; CLAMP T-BOLT AIR INTAKE
REPAIR FROM PM - AIR INTAKE SYS	1	CLAMP; CLAMP T-BOLT AIR INTAKE COLD SIDE
REAR BRAKE PADS-SHOES	1	TUBE; TUBE AIR INTAKE COLD SIDE
AIR CONDITIONING	2	BRAKE; HD SHOE KIT 3/8 BEAM
	2	BRAKE; HD SHOE KIT 3/8 BEAM
	2	BRAKE; REAR DRUMS 3757X 3647X
	2	BRAKE; REAR DRUMS 3757X 3647X
	2	ACTUATOR; 2611234C1 VENT ACTUATOR
	1	INTERNATIONAL; VENT MOTOR
	1	INTERNATIONAL; 2606229C92 THERMISTER

**Service Requests:**

12/12/2016	DECALS / 19: LOOSE / REPAIR VEHICLE SIGNAGE - YELLOW REFLECTIVE TAPE ON REAR RIGHT SIDE OF PATIENT COMPARTMENT FALLING OFF. NEEDS TO BE REPLACED.
12/12/2016	SERVICE REQUEST / 19: LOOSE / REPAIR SERVICE REQUEST - ON BOARD OXYGEN SUPPLY SYSTEM SLOW LEAK. CAN NOT DETECT LEAK LOCATION.
12/13/2016	LIGHTS / 19: LOOSE / REPAIR VEHICLE LIGHTS NOT WORKING - LIGHTS ARE NOT WORKING ON FRONT BUMPER LIGHT POLE LEFT AND RIGHT SIDE.

**CSHOP-2016-5872**

Comments: **C-INSPECTION**

Date Opened 12-16-2016 Date Finished 12-20-2016 Meter 1 Reading: 165,278

**TASKS PERFORMED**

**Q PARTS**

PM SERVICE C RESCUE	1	FILTER; 57744XD OIL FILTER
	1	FILTER; FUEL FILTER 2008 HORTON

**CSHOP-2016-6018**

Date Opened 12-27-2016 Date Finished 1-6-2017 Meter 1 Reading: 166,406

**TASKS PERFORMED**

**NO PARTS USED**

INTAKE MANIFOLD  
AIR CONDITIONING

**Service Requests:**

12/22/2016	ALARMS / 15: FOREIGN MATERIAL / DEALER REPLACED BREATHER FILTER AND CAC HOSE POS ALARM SIGNALS TEMP RUNNING ABOVE 230 F. R46 ALSO PRESENTED WITH STRONG BURNING SMELL.
12/24/2016	A/C / 18: LEAKING / REPAIR A/C ISSUE - BOTH A/C UNITS IN FRONT CAB BLOWING WARM/HOT AIR.

**Asset Work Order History 10182237**

**CSHOP-2016-633**

Comments: **R46**

Date Opened 2-8-2016 Date Finished 2-19-2016 Meter 1 Reading: 140,634

**TASKS PERFORMED**

**NO PARTS USED**

BODY EXTERIOR

**Service Requests:**

02/08/2016 SERVICE REQUEST / 18: LEAKING / REPAIR  
AFTER THE TRUCK HAS BEEN RUNNING THERE IS AN ODOR OF SOMETHING BURNING OUTSIDE OF THE VEHICLE.  
NO WARNING LIGHTS ARE DISPLAYED AND THERE ARE NO ABNORMAL READINGS ON THE DASHBOARD.

**CSHOP-2017-146**

Comments: **SEVERE BELT NOISE CAB A/C COMP RAPID CYCLING 3 REAR TIRES WORN OUT**

Date Opened 1-7-2017 Date Finished 1-10-2017 Meter 1 Reading: 166,406

**TASKS PERFORMED**

**Q PARTS**

AIR SYSTEM	1	2IH; 2IH
AIR CONDITIONING	1	9IP; 9IP
	1	9IP; 9IP

**CSHOP-2017-1686**

Date Opened 3-20-2017 Date Finished 4-5-2017 Meter 1 Reading: 174,932

**TASKS PERFORMED**

**Q PARTS**

DIAGNOSE ELECTRICAL	3	1AD; BATTERY 31 SERIES
---------------------	---	------------------------

**Service Requests:**

03/19/2017 LIGHTS / 18: LEAKING / REPAIR  
REAR EMERGENCY LIGHT ON THE PASSENGER SIDE NOT WORKING ON R 46

**CSHOP-2017-1840**

Date Opened 3-27-2017 Date Finished 3-30-2017 Meter 1 Reading: 174,282

**TASKS PERFORMED**

**Q PARTS**

A INSPECTION	1	2IH; FUEL FILTER
FAN BELT	2	MAC; NON-CHLOR BRAKE CLNR
OIL	1	BELT; BELT HORTON
AIR SYSTEM	1	FIL; NAPAGOLD OIL FILTER
AIR CONDITIONING	1	NBH; V-RIBBED BELT

**Service Requests:**

03/27/2017 AIR RIDE / 18: LEAKING / REPAIR  
AIR RIDE ISSUE - AIR LEAK FROM DRIVER SIDE ENGINE COMPARTMENT.

03/29/2017 ENGINE / 17: INSUFFICIENT LUBRICANT / REPAIR  
ENGINE; OIL LEVEL IS HIGH; OIL LEVEL IS UP TO THE LETTER "A" OF RANGE ON THE DIP STICK

**Asset Work Order History 10182237**

**CSHOP-2017-1896**

Date Opened 3-30-2017 Date Finished 4-5-2017 Meter 1 Reading: 174,932

**TASKS PERFORMED**

**NO PARTS USED**

---

LIGHTING SYSTEM  
AIR SYSTEM

**Service Requests:**

03/30/2017 LIGHTS / 18: LEAKING / REPAIR  
LARGE YELLOW FLASHER NOT WORKING (BACK OFFICERS SIDE)

---

**CSHOP-2017-2006**

Date Opened 4-5-2017 Date Finished 4-5-2017 Meter 1 Reading: 174,959

**TASKS PERFORMED**

**NO PARTS USED**

---

BRAKE CHAMBER  
AIR CONDITIONING

**CSHOP-2017-2095**

Date Opened 4-10-2017 Date Finished 4-20-2017 Meter 1 Reading: 175,360

**TASKS PERFORMED**

**NO PARTS USED**

---

PM SERVICE B

**CSHOP-2017-2102**

Comments: **REPAIRS FROM PM**

Date Opened 4-10-2017 Date Finished 4-20-2017 Meter 1 Reading: 175,360

**TASKS PERFORMED**

**Q PARTS**

---

DOOR LATCH	1	2IH; OIL COOLER GASKET
WIPERS-WASHER	7	9OC; SYN 15W40
ENGINE AND ACCESSORIES	1	2IH; 2IH
PARK-CLEARANCE LIGHTS	1	2IH; OIL COOLER TUBE ASSY
AUTO-EJECT	2	2IH; ORING
DOOR LOCKS	1	2IH; SEAL
DOOR PANEL	2	9IP; BULB
HEATER CONTROL VALVE	2	9IP; BULB
AIR CONDITIONING	2	INTERNATIONAL; 2606229C92 THERMISTER
	1	FIL; NAPA CABIN AIR FILTER

---

**Asset Work Order History 10182237**

**CSHOP-2017-2598**

Date Opened 5-3-2017 Date Finished 5-3-2017 Meter 1 Reading: 176,468

**TASKS PERFORMED**

**NO PARTS USED**

ENGINE AND ACCESSORIES

**Service Requests:**

05/03/2017 OIL / 20: LUBE/OIL SOAKED / REPAIR  
ENGINE OIL APROX HALF INCH ABOVE MAX LEVEL

**CSHOP-2017-2794**

Comments: **INSTALL NEW TIC CHARGER AND TIC GET PARTS FROM WAYNE**

Date Opened 5-11-2017 Date Finished 5-12-2017 Meter 1 Reading: 177,224

**TASKS PERFORMED**

**NO PARTS USED**

FIRE FIGHTING EQUIPMENT  
COOLING SYSTEM

**CSHOP-2017-2863**

Date Opened 5-15-2017 Date Finished 6-19-2017 Meter 1 Reading: 180,438

**TASKS PERFORMED**

**Q PARTS**

FUEL SYSTEM  
AIR CONDITIONING

2 2AW; T RING  
1 2AW; VIB  
1 2IH; RETAINER NUT  
1 NONSTOCK; FREIGHT CHARGE  
1 2IH; GRILLE  
1 2IH; THERMISTORS  
1 1FD; HEAD LIGHT RETAINER

**Service Requests:**

05/15/2017 A/C / 12: BROKEN / REPAIRED  
A/C BLOWS HOT AFTER RUNNING FOR 15 TO 20 MINUTES IN FRONT CAB OF R 46

05/18/2017 OIL / 12: BROKEN / REPAIR  
ENGINE OIL ABOVE MAX LEVEL

**CSHOP-2017-3007**

Date Opened 5-22-2017 Date Finished 5-26-2017 Meter 1 Reading: 178,714

**TASKS PERFORMED**

**Q PARTS**

BODY EXTERIOR

1 9IP; CLAMP EXH SHIELD  
2 2IH; CLAMP EXHUAST

**Service Requests:**

05/22/2017 MUFFLER / 18: LEAKING / REPAIR  
MUFFLER BAD: 3 OF THE 4 BRACKETS HOLDING THE COVERING AROUND THE MUFFLER HAS BROKEN OFF. THE COVERING COULD FALL OFF AT ANYTIME. OIL LEVEL IS STARTING TO GET HIGH AT THE LETTER "E" ON THE WORD RANGE ON THE DIP STICK.

**Asset Work Order History 10182237**

**CSHOP-2017-3124**

Date Opened 5-27-2017 Date Finished 5-30-2017 Meter 1 Reading: 179,156

**TASKS PERFORMED**

**NO PARTS USED**

COOLING SYSTEM  
FAULT CODE

---

**CSHOP-2017-3237**

Date Opened 6-2-2017 Date Finished 6-5-2017 Meter 1 Reading: 179,607

**TASKS PERFORMED**

**NO PARTS USED**

VEHICLE RECOVERY OPERATION  
TRAVEL TO BE CHARGED TO WORK ORDER

---

**CSHOP-2017-3373**

Date Opened 6-8-2017 Date Finished 6-8-2017 Meter 1 Reading: 179,927

**TASKS PERFORMED**

**NO PARTS USED**

TRAVEL TO BE CHARGED TO WORK ORDER  
COOLING SYSTEM

---

**CSHOP-2017-3429**

Comments: **ON-CALL R46 OVERHEATING**

Date Opened 6-9-2017 Date Finished 6-9-2017 Meter 1 Reading: 179,927

**TASKS PERFORMED**

**Q PARTS**

ENGINE COOLANT TEMPERATURE SE

1 2IH; 060E THERMOSTAT

---

**CSHOP-2017-3464**

Date Opened 6-12-2017 Date Finished 6-12-2017 Meter 1 Reading: 180,438

**TASKS PERFORMED**

**NO PARTS USED**

COOLING SYSTEM

**Service Requests:**

06/11/2017 ENGINE / 18: LEAKING / REPAIR  
COOLANT LEAKING AND HAS TO REFILLED SEVERAL TIMES THROUGHOUT SHIFT ON R 46. PUDDLE OF COOLANT NOTED ON BAY FLOOR

06/11/2017 OIL / 18: LEAKING / REPAIR  
ENGINE OIL ABOVE MAX LEVEL ON R 46

06/11/2017 A/C / 18: LEAKING / REPAIR  
A/C BLOWS HOT IN CAB OF R 46 AFTER 10 TO 15 MINUTES OF RUNNING

---

**Asset Work Order History 10182237**

**CSHOP-2017-355**

Date Opened 1-17-2017 Date Finished 1-17-2017 Meter 1 Reading: 166,883

**TASKS PERFORMED**

**NO PARTS USED**

REAR TIRES

**VENDOR?** DAN CALLAGHAN ENTERPRISES

**CSHOP-2017-3587**

Comments: **C-INSPECTION**

Date Opened 6-16-2017 Date Finished 6-20-2017 Meter 1 Reading: 180,523

B-SER.

**TASKS PERFORMED**

**Q PARTS**

PM SERVICE C RESCUE

30 9IP; 15W40 MOTOR OIL NON SYN  
1 FIL; NAPAGOLD OIL FILTER  
1 FIL; NAPA GOLD FUEL FILTER

**CSHOP-2017-3624**

Comments: **REPAIRS FROM PM**

Date Opened 6-19-2017 Date Finished 6-20-2017 Meter 1 Reading: 180,523

NEED O-RING FOR OIL PAN PLUG

**TASKS PERFORMED**

**NO PARTS USED**

OIL PAN-GASKET

**CSHOP-2017-3765**

Comments: **PREP TO SEND TO REMOUNT REMOVE ALS DECAL AND SUNPASS TRY NOT TO DESTROY IF POSSIBLE**

Date Opened 6-26-2017 Date Finished 6-26-2017 Meter 1 Reading: 180,542

**TASKS PERFORMED**

**NO PARTS USED**

SCBA BRACKETS

SAFTEY-EMERGENCY EQUIPMENT

**CSHOP-2017-414**

Comments: **R-46 VIDEO SCREEN NOT WORKING**

Date Opened 1-19-2017 Date Finished 2-9-2017 Meter 1 Reading: 169,153

**TASKS PERFORMED**

**Q PARTS**

AIR SYSTEM

SAFTEY-EMERGENCY EQUIPMENT

INSTRUMENTS-GAUGES-WARNING &

-1 9IP; MONITOR VOYAGER 10008120  
1 9IP; MONITOR VOYAGER 10008120  
1 9IP; MONITOR VOYAGER 10008120

**Service Requests:**

01/18/2017 SERVICE REQUEST / 19: LOOSE / REPAIR  
SERVICE REQUEST VIDEO CAMERA SCREEN DOES NOT WORK

**Asset Work Order History 10182237**

**CSHOP-2017-466**

Comments: **R46 SIDE DOOR NOT WORKING**

Date Opened 1-23-2017 Date Finished 1-25-2017 Meter 1 Reading: 167,901

**TASKS PERFORMED**

**Q PARTS**

BODY EXTERIOR  
CAB-INTERIOR ACCESSORIES

1 9IP; 9IP

**Service Requests:**

01/21/2017 DOOR / 19: LOOSE / REPAIR  
VEHICLE DOORS SIDE PATIENT COMPARTMENT DOOR WILL NOT OPEN PROPERLY WHEN SHUT

01/22/2017 DOOR / 19: LOOSE / REPAIR  
VEHICLE DOORS: OFFICER SIDE PATIENT COMPARTMENT INNER LATCH IS NOT WORKING/OPENING. DOOR MUST BE OPENED FROM THE OUTSIDE

**CSHOP-2017-5080**

Date Opened 8-29-2017 Date Finished 8-29-2017 Meter 1 Reading: 180,452

**TASKS PERFORMED**

**NO PARTS USED**

TOWING HITCH

VENDOR? SISTERS TOWING

**CSHOP-2017-698**

Date Opened 2-1-2017 Date Finished 2-2-2017 Meter 1 Reading: 168,561

**TASKS PERFORMED**

**NO PARTS USED**

CAB-INTERIOR ACCESSORIES

**Service Requests:**

02/01/2017 WINDOW / 19: LOOSE / REPAIR  
WINDOW/GLASS - DRIVER SIDE FRONT WINDOW IS NOT OPERATING. WINDOW IS IN THE DOWN POSITION AND WILL NOT GO UP.

**CSHOP-2017-845**

Comments: **R46 OVERHEATING**

Date Opened 2-9-2017 Date Finished 2-16-2017 Meter 1 Reading: 169,331

TRUCK OVER HEATING

**TASKS PERFORMED**

**Q PARTS**

ANTIFREEZE

8 9OC; 9OC  
1 9IP; 1842130C3 THERMOSTAT DT466  
1 9IP; 1842130C3 THERMOSTAT DT466



**Asset Work Order History 10182237**

**CSHOP-2017-935**

Comments: **R46 A/C BLOWS HOT**

Date Opened 2-14-2017

Date Finished

3-21-2017

Meter 1 Reading:

173,397

**TASKS PERFORMED**

**NO PARTS USED**

---

AIR CONDITIONING

**Service Requests:**

---

02/14/2017

A/C / 19: LOOSE / REPAIR

A/C BLOWS HOT AFTER TRUCK HAS BEEN RUNNING FOR OVER 10 MINS. ON R 46

---

**RADIO-2016-394**

Date Opened 6-29-2016

Date Finished

8-16-2016

Meter 1 Reading:

154,197

**TASKS PERFORMED**

**NO PARTS USED**

---

TRAVEL TO BE CHARGED TO WORK ORDER  
ANTENNA

**Service Requests:**

---

06/29/2016

RADIO / /

REPLACED BACKUP RADIO ANTENNA CONNECTOR (PL 259)

---

**RADIO-2016-413**

Comments: **REPLACED PAGER.**

Date Opened 7-6-2016

Date Finished

7-6-2016

Meter 1 Reading:

150,634

**TASKS PERFORMED**

**NO PARTS USED**

---

TRAVEL TO BE CHARGED TO WORK ORDER  
RADIO

**Service Requests:**

---

07/05/2016

SERVICE REQUEST / /

RESCUE 46 DRIVER OPERATOR PAGER HAS BLANK LINE THROUGH DISPLAY. STILL ABLE TO SEE CALLS ON PAGER, BUT DIFFICULT AT TIMES.

---

**RADIO-2017-346**

Date Opened 6-26-2017

Date Finished

6-26-2017

Meter 1 Reading:

180,523

**TASKS PERFORMED**

**NO PARTS USED**

---

RADIO

**Service Requests:**

---

06/26/2017

RADIO / /

REMOVAL OF RADIOS AND MDC MOUNT. TRUCK ITS GOING FOR REMOUNT.

---