

10/17/2017
12:20:39PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10156323 2004 TORO 420TX Trencher,Compact,Dingo

Workorder: 456414

Problem: PRE-DELIVERY INSPECTION

Meter Reading: 0	Labor	Parts
In Date: 09/15/2004	Hours	Description
Close Date: 09/15/2004	Quantity	
- Pre-Delivery Inspection	2.00	
Parts Charge: 0.00	Labor Charge: 100.00	

Workorder: 632433

Problem: P.M. & HOSE LEAK

Meter Reading: 61	Labor	Parts
In Date: 01/06/2006	Hours	Description
Close Date: 01/26/2006	Quantity	
- Pm Service	5.00	4788303 AIR FILTER KIT KOHLER
- Service Hydraulic System		10W30 MOTOR OIL
- Shop Supplies		SPRK/PLUG BKR5EIX-11
		SHOP SUPPLIES
		86-3010 HYD.FILTER TORO 3500D
		10W30 MOTOR OIL
		10W30 MOTOR OIL
		3031 FUEL FILTER 1/4" FRM G1 WIX 33031
		1348 OIL FILTER FRM PH3614 WIX 51348
Parts Charge: 69.70	Labor Charge: 50.00	

Workorder: 643801

Problem: LEAKING FILTER

Meter Reading: 103	Labor	Parts
In Date: 08/09/2006	Hours	Description
Close Date: 08/14/2006	Quantity	
- Repair Leaking Hyd Filter.Add Fluid.Wash Off Unit.	2.50	SHOP SUPPLIES
- Jppark/Shop.		15/40 OIL
- Shop Supplies		
Parts Charge: 6.76	Labor Charge: 50.00	

10/17/2017
12:20:39PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10156323 2004 TORO 420TX Trencher,Compact,Dingo

Workorder: 649659

Problem: P.M./ATTACHMENT COUPLING LEAKS (TAPE AROUND LEAK)

Meter Reading: 123		Labor		Parts	
In Date: 12/07/2006	Close Date: 01/19/2007	Hours	Description	Quantity	
- Pm Service		9.00	272490 PRE FILTER B/S FITS 394018	1.00	
- Hyd Service			3031 FUEL FILTER 1/4" FRM G1 WIX 33031	1.00	
- Remove & Install New Hyd Lines For Aux Eqpt			86-3010 HYD.FILTER TORO 3500D	1.00	
- Test Run			1348 OIL FILTER FRM PH3614 WIX 51348	1.00	
- Shop Supplies			10W30 MOTOR OIL	2.00	
			237-79 O-RING	2.00	
			100-4701 NIPPLE	1.00	
			237-65 O-RING	2.00	
			105-8394 COUPLER	1.00	
			227-80 O-RING	2.00	
			104-6134 COUPLER	1.00	
			SHOP SUPPLIES	1.00	
			105-8395 NIPPLER	1.00	
			10W30 MOTOR OIL	2.00	
			4788303 AIR FILTER KIT KOHLER	1.00	
Parts Charge: 487.42		Labor Charge: 27.50	Commercial Charge: 139.21		

Workorder: 832886

Problem: PM

Meter Reading: 123		Labor		Parts	
In Date: 01/17/2008	Close Date: 02/06/2008	Hours	Description	Quantity	
- Pm Service		9.50	10W30 MOTOR OIL	2.00	
- Service Trailer			3031 FUEL FILTER 1/4" FRM G1 WIX 33031	1.00	
- Wiring Harness For Lights Dragging On Ground Damaging Wires, Repaired Wiring & Secured To Trailer			86-3010 HYD.FILTER TORO 3500D	1.00	
- Nitro Tires			58856 SEAL	2.00	
- Test Run			SHOP SUPPLIES	1.00	
- Shop Supplies			1348 OIL FILTER FRM PH3614 WIX 51348	1.00	
			BKR5E SPARK PLUG 7938	2.00	
			4788303 AIR FILTER KIT KOHLER	1.00	
Parts Charge: 50.95		Labor Charge: 30.00			

10/17/2017
12:20:39PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10156323 2004 TORO 420TX Trencher,Compact,Dingo

Workorder: 838369

Problem: BATTERY DEAD

Meter Reading: 172	Labor	Parts	
In Date: 05/12/2008	Hours	Description	Quantity
- Charge And Ck Old Battery No Good. Fill And Charge	2.50	BATTERY	1.00
- New Batt And Isntall Ck Charge		SHOP SUPPLIES	1.00
- Test Run			
- Shop Supplies			
Parts Charge:	139.09	Labor Charge:	30.00

Workorder: 933673

Problem: P.M.

Meter Reading: 202	Labor	Parts	
In Date: 02/06/2009	Hours	Description	Quantity
- Pm Service	6.50	3031 FUEL FILTER 1/4" FRM G1 WIX 33031	1.00
- Hyd Service		86-3010 HYD.FILTER TORO 3500D	1.00
- Wash		1348 OIL FILTER FRM PH3614 WIX 51348	1.00
- Shop Supplies		10W30 MOTOR OIL	2.00
		15/40 OIL	2.00
		SHOP SUPPLIES	1.00
		BKR5E SPARK PLUG 7938	2.00
Parts Charge:	35.96	Labor Charge:	390.00

Workorder: 943684

Problem: Transition Prep Charge

Meter Reading: 202	Labor	Parts	
In Date: 09/24/2009	Hours	Description	Quantity
- Transition Prep Charge	2.00		
Parts Charge:	0.00	Labor Charge:	120.00

10/17/2017
12:20:39PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10156323 2004 TORO 420TX Trencher,Compact,Dingo

Workorder: 1005052

Problem: will not start / pm service

Meter Reading: 219 In Date: 05/14/2010	Close Date: 05/28/2010	Labor Hours	Description	Parts	Quantity
- Pm		8.50	1348 OIL FILTER FRM PH3614 WIX 51348		1.00
- R/R Battery Test			BP92 TERMINAL #2 STANDARD		1.00
- Lube And Service Trencher Attachments			CS2RV RED CABLE 2 GAUGE		3.00
- R/R Starter And R/R Battery Cables			BP91 TERMINAL #2 STANDARD		1.00
- Shop Supplies			CS2L BLACK CABLE 2 GAUGE		3.00
			BATTERY		1.00
			10W30 MOTOR OIL		2.00
			SHOP SUPPLIES		1.00
			3031 FUEL FILTER 1/4" FRM G1 WIX 33031		1.00
			STARTER		1.00
	Parts Charge: 405.53	Labor Charge: 510.00			

Workorder: 1105499

Problem: pm service

Meter Reading: 238 In Date: 05/25/2011	Close Date: 05/26/2011	Labor Hours	Description	Parts	Quantity
- Pm Service		6.00	1348 OIL FILTER FRM PH3614 WIX 51348		1.00
- Hydraulic System Service			3031 FUEL FILTER 1/4" FRM G1 WIX 33031		1.00
- Replace Asset Numbers			10W30 MOTOR OIL		2.00
- Shop Supplies			86-3010 HYD.FILTER TORO 3500D		1.00
			SHOP SUPPLIES		1.00
			4788303 AIR FILTER KIT KOHLER		1.00
	Parts Charge: 38.47	Labor Charge: 360.00			

10/17/2017
12:20:39PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10156323 2004 TORO 420TX Trencher,Compact,Dingo

Workorder: 1205298

Problem: pm service

Meter Reading: 0	Labor	Parts
In Date: 06/06/2012	Hours	Quantity
- Pm Service	6.50	86-3010 HYD.FILTER TORO 3500D 1.00
- Ign. Service		10W30 MOTOR OIL 2.00
- Hyd Service		207 ALUMINUM PAINT 1.00
- Replaced Hour Meter		BKR5E SPARK PLUG 7938 2.00
- Spray Paint (Parts Only)		43583 SLEEVE SCAG 2.00
- Shop Supplies		33971 FUEL FILTER 1/4" GAS/DIESEL 1.00
		1348 OIL FILTER FRM PH3614 WIX 51348 1.00
		SHOP SUPPLIES 1.00
		HOUR METER 1.00
Parts Charge:	218.20	Labor Charge: 390.00

Workorder: 1305806

Problem: PM / See Request

Meter Reading: 6	Labor	Parts
In Date: 06/11/2013	Hours	Quantity
- Pm	6.50	SHOP SUPPLIES 1.00
- Free Up And Lube Parking Brake Labels And Wheel Lock Levers		NAPAGOLD FUEL FILTER 1.00
		10W30 MOTOR OIL 2.00
- Free Up And Lube Lock Cyl		PH3614 OIL FILTER WI 1.00
- Ign Service		SPARK PLUG 2.00
- Shop Supplies		
Parts Charge:	19.10	Labor Charge: 390.00

10/17/2017
12:20:39PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10156323 2004 TORO 420TX Trencher,Compact,Dingo

Workorder: 1400071

Problem: won't stay running / won't start

Meter Reading: 26	Labor	Parts
In Date: 01/03/2014	Hours	Description
Close Date: 02/26/2014		Quantity
- Diagnose No Start Complaint Repair Wire Harness (Open)	18.50	MUFFLER CLAMP 1.00
- R&R Cab Clean And Adjust		NUT 4.00
- Drain Fuel Tank To Inspect Fuel For Water Contamination		CYLINDER HEAD KIT 1.00
- Replace Exhaust Sys		O-RING 1.00
- Drill And Extract Broken Exhaust Manifold Stud, (Not Removable) Replace Left Side Cylinder Head		CYLINDER HEAD GASKET KIT 1.00
		STUD 2.00
- R&R Engine To Gain Access To Engine Cylinder Head		EXHAUST GASKET 2.00
- Clean Eqpt Of Oil And Grease		INTAKE MANIFOLD GASKET 1.00
- Shop Supplies		Freight Charge 1.00
		SHOP SUPPLIES 1.00
		MUFFLER ASSY 1.00
Parts Charge:	762.79	Labor Charge: 1,110.00

Workorder: 1406380

Problem: pm service

Meter Reading: 32	Labor	Parts
In Date: 06/30/2014	Hours	Description
Close Date: 07/14/2014		Quantity
- Pm Service	6.00	SHOP SUPPLIES 1.00
- Fix Body Repair Fiber Glass Hood		NAPA 10W30 QT 2.00
- Wash Eqpt		GLOS BLK 1.00
- Shop Supplies		TRAILER WIRE 8.00
		NAPAGOLD FUEL FILTER 1.00
		REPAIR KIT 1.00
		NAPAGOLD OIL FILTER 1.00
Parts Charge:	53.08	Labor Charge: 360.00

Workorder: 1412526

Problem: wont start

Meter Reading: 33	Labor	Parts
In Date: 12/15/2014	Hours	Description
Close Date: 12/19/2014		Quantity
- Install New Battery And Adapt Mounts	2.00	BATTERY 1.00
- Clean Terminals On Starter And Battery Cable		SHOP SUPPLIES 1.00
- Add Fuel And Stabilizer		
- Shop Supplies		
Parts Charge:	107.65	Labor Charge: 120.00

10/17/2017
12:20:39PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10156323 2004 TORO 420TX Trencher,Compact,Dingo

Workorder: 1506734

Problem: pm service

Meter Reading: 39 In Date: 07/07/2015	Close Date: 07/13/2015	Labor Hours	Description	Parts	Quantity
- Pm		4.50	SPARK PLUG		1.00
- Ign Service			NAPAGOLD FUEL FILTER		1.00
- Shop Supplies			10W30 MOTOR OIL		2.00
			NAPAGOLD OIL FILTER		1.00
			SHOP SUPPLIES		1.00
			SPARK PLUG		2.00
Parts Charge:		19.34	Labor Charge:	270.00	

Workorder: 1510431

Problem: keeps blowing fuses/ wont start

Meter Reading: 39 In Date: 10/15/2015	Close Date: 10/27/2015	Labor Hours	Description	Parts	Quantity
- Trace Down Broken Wire To Fuel Solenoid		1.50	SHOP SUPPLIES		1.00
- Shop Supplies					
Parts Charge:		2.00	Labor Charge:	90.00	

Workorder: 1511342

Problem: replace hydro couplings on attach/ cylinder leaks

Meter Reading: 49 In Date: 11/05/2015	Close Date: 11/18/2015	Labor Hours	Description	Parts	Quantity
- Replace Hydraulic Hose And Coupler And Send Out Cylinder Tube Rebuilt.		2.50	SHOP SUPPLIES		1.00
- Shop Supplies			CYLINDER REPAIR		1.00
			HOSE MADE		1.00
			fitting		1.00
Parts Charge:		493.58	Labor Charge:	150.00	

10/17/2017
12:20:39PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10156323 2004 TORO 420TX Trencher,Compact,Dingo

Workorder: 1606773

Problem: pm/ no power/ wont stay running

Meter Reading: 49	Labor	Parts	
In Date: 07/05/2016	Hours	Description	Quantity
- Pm	7.00	SPARK PLUG	2.00
- Ign Service		NAPA 10W30 QT	2.00
- R&R Carb And Clean And Rebuild Drain Fuel Tank And Install Fresh Fuel		IGN SWITCH	1.00
- Ck For Intermittent Cutting Out-Out Put Ign Switch		NAPAGOLD FUEL FILTER	1.00
- Shop Supplies		NAPAGOLD OIL FILTER	1.00
		SHOP SUPPLIES	1.00
Parts Charge:	53.99	Labor Charge:	420.00

Workorder: 1707344

Problem: Transition Prep Charge

Meter Reading: 49	Labor	Parts	
In Date: 07/26/2017	Hours	Description	Quantity
- Transition Prep Charge	2.00		
Parts Charge:	0.00	Labor Charge:	0.00

Total Parts Charges: **2,963.61** Total Labor Charges: **4,967.50** Total Comm. Charges: **139.21**